GREENE LAW FIRM

2004 JAN 16 PM 1: 58

ATTORNEYS AT LAW WEDGE INTERNATIONAL TOWER 1415 LOUISIANA, SUITE 3200 HOUSION, TEXAS 77002


Odd K 1002 le 462

FACRIMER: 713-547-0506 E-MAIL: GREENELAWI@ACL.COM

TRURPHONE: 713-547-0500

December 11, 2003

Ms. Kathleen C. DeMeter, Director Office of Defects Investigation Safety Assurance National Highway Traffic Safety Administration 400 Seventh Street, S.W. Washington D.C. 20590



Dear Ms. DeMeter:

I am representing the family of Johnny Hudson in a wrongful death case against Ford Motor Company based on a defective accelerator assembly unit in a 2001 year model Ford Super Duty truck with a 7.31 diesel engine. The style of the case is: Cause No. 02-137: Sendy Hudson, et al, vs. Joseph Todd Pearah, et al. In the 3rd Judicial District Court: Henderson County, Texas.

As part of the discover in the case, Ford has produced multiple boxes of documents that they have produced to you in response to your PE03-044 investigation. Additionally, Ford produced a copy of its response to your letter requesting information from Ford, which was written by James P. Vondale, Director, on December 2, 2003.

Although I have not had the opportunity to completely review all of the documents and material produced by Ford. I would like to point-out a few glaring oversights in Ford's response. First and foremost, Ford refers to my particular litigation on page 16 of their response. Ford conveniently omitted the fact that the driver of the vehicle gave a sworn statement on the day of the accident that when he attempted to make the left hand turn, the truck would not respond when pressure was applied to the accelerator. Rather than going forward, the truck only "eased" into the oncoming lane and caused the accident. I am attaching the driver's statement to this letter for your file, as well as the service invoice from a Ford dealership that discovered the defective accelerator.

A brief perusal of Ford's response reveals that Ford is attempting to minimize the overall breadth of the inquiry and limit the focus to only "adjustable accelerators" because Ford has discovered a problem with adjustable pedals. However, I would ask that your agency conduct a thorough investigation into the fixed accelerators as well and not allow Ford to hoodwink your agency into limiting the scope. In my case, the 2001 Ford truck had a "fixed" accelerator that was unquestionably discovered to be defective. Whether it was

GREENE LAW FIRM, P.C.

ATTORNEYS AT LAW

December 11, 2003 Page #2 of 2

because of some component or sensor failure or whether it was because of an improper installation, the end result was an unreasonably dangerous situation. In addition to the Ford truck in my case, I accidently discovered another truck that had the same occurrence (lack of throttle response) that was discovered by a Ford dealership about a month prior to the accident in my case. The truck had a fixed pedal as well. I am attaching the service ticket hereto for your file. It certainly does not appear that the issues with the accelerators are limited to the "adjustable pedals".

In addition, I also discovered on the Internet that Ford has acknowledged a similar problem in Ford vans built during June and July of 2003 with 7.31 diesel engines. The website where I noticed the issue is: http://www.intellidog.com/dieselmann/bulletin.htm. I printed the information from the web-site and am attaching it hereto. It appears that Ford has not limited the scope with the vans to only "adjustable" pedals. Did Ford disclose this fact to you in their disclosure statement?

Finally, I find it totally irresponsible for Ford Motor Company to make the representation that a vehicle that does not respond when a driver attempts to accelerate is not an "unreasonable risk to motor vehicle safety". Any situation in which a driver is unable to accelerate poses an unreasonably risk to injury not only to the driver of that vehicle, but to other motorists as well. The situation is akin to a vehicle that is stalled on the highway. Every day, motorists throughout the county encounter driving scenarios in which a vehicle that does not respond would create an very unreasonably risk. For instance, if a motorist is attempting to enter a freeway here in Houston and the vehicle fails to respond, that motorist is in danger of getting hit from behind. There are many highways throughout the Country in which there are absolutely no shoulders in which a motorists could go to get out of the way of danger. Further, any vehicle that is stranded on a shoulder creates an unreasonable risk itself. While I was reading the Houston Chronicle this morning. I noticed where a person was killed when his vehicle stalled. The article is attached hereto. Finally, it is obvious that an unreasonable risk is created when a motorist attempts to make a left-hand turn and the vehicle only idles forward (rather than proceeding as usual). However, Ford takes the contrary and unfathomable position that a defective accelerator does not pose a danger or unreasonable risk to motor safety.

I appreciate your time and attention to this matter. If you need any additional information from me, please do not hesitate to contact me directly.

Very truly yours,

GREENE LAW FIRM, P.C.

Troy L. Greene

JUVENILE STATEMENT FORM

State of Texas	···· § ,	in the Justic	e.Court
County of Benders	9 9	Precinct No	Place 1
My name is:	6	in the sty of " 6.0	tem yours of
in Henderson	County, Texas. I	have 12 yes	ra of education and do
read, write and understand the	English languaga, 1 have been w	igh elineval yet to beman	its, persuent le Section
51.09, Texas Femily Code,	by Magistrate. Su.C. 7	Treat IPS	# ✓ . in the city
of Athona	11 end	Count	, Texas at <u>4540</u>
o'clock F. M., on the	7 day of 4	100	_ = 201 2
PROMISES OF PERSUASION	AS THEY HAVE BEEN EXPL ARILY, WITHOUT BEING IN N, MAKE THE FOLLOWING ST	duged by any com Tatements in Writh	PULSION, THREATS. IG:
- L Was CARRY	y from mos	k in my	mies truck
guina to his	have I wa	5 12 11	HWY PAR
- TUCK OK to	Michaelé Coure	Kool, and	t looked
to see ito	y an me	& forming	act the
HOY and He	ere was a c	Par matin	La tura
then I book	ul farmant s	La Ma	and the form
and there	Jest a Roll Vien	obush 11	connection
aked 50 T			when I
dua du		· · · · · ·	William J.
Signature of Magistrate	4.01	· Ş. W.	Signature of Juvenile
Date Signed		$-\frac{6}{7}$	102
Judge Madecus Re Addam Name of Magistrate (Print or Type Justice of the Peace, Pct. # # 8, Athene Benders	Place 1		Oate Signed
Part II. Juverille Statement Form Revised August 1995		•	- 1 . 2

000047

einent (Conunued) reaks and year to occul

Sue Tarrant Judge Hilton Ho Name of Magistrate (Print or Type)

Justice of the Peace, Pot. # 6 Place 1.
Athens _____ Henderson County, Texas

Port E. Juvenile Statement Form Revised August 1805

000008

Man killed after stalled car hit

A Houston man was killed when a pickup hit his cor, which was stalled in a moving lane on the West Loop North.

Zeng Gao, 35, of the 9500 block of Strend was sitting in the front right passenger seat in the freeway's 1860 block near Manustant lets Turnday. Hempsteed late Tuesday.

Another Houston man, 43, step in the car, was taken to Monorial Hormann Hospital. The pickup was driven by a Richmond man. 22.

State

Officials look into body mix-up

AUSTIN - Travis County officials are investigating how the medical examiner's office accidentally released the wrong body to a funeral home, which cremated the remains.

The mix-up occurred last week, when funeral home officials went to pick up the hody of Paul Williams, 38, of Coder Park, who had been hit by a train. They were mistakenty given the body of Rayford Floyd, 30, who died in a cer wreck. The funeral home then cremated Floyd's

body, thinking it was the body of Williams.

în 1995, a marilar mistake generated new protocols at the medical examiner's office. This is the first mix-up since.

The mistake was recognized Saturday morning, when workers from a mortusary service hired to pick up Ployd's body for a Burnet County funeral home arrived and saled for his remains.

UT-Arlington on probation

FORT WORTH -- The University of Texas at Arlington has been placed on probation because its revised mission statement was automitted late.

Interim UT-Arlington President Charles Sorber called the situation "a buremovable nightness" and criticized the Atlanta-based Southern Association of Colleges and Schools, which secredits schools in 11 states.

An official with the Texas Higher Eduention Coordinating Board, which was supposed to submit the musico statement, said he send if Reseasy morning before the association's afternoon vote.

Despite the probation, UT-Artington re-mains accordited.

From staff and wire reports



833-467-9993

she sees her gift in your kand. E's a little box with a pretty bow. And incide is a velocity jewelry box. And her heart starts to race...



713.700.0110 Holdey Hours SF 78-830 = 9x 10-8 = 9xs 12-

COM- 1 nt and andria. rest. d The lambo

oliers.

oma bo ·

re De-

a wit-

er the ملاعه ع

eday.

r used

enda to ijown.

deral





Motorcaft

1108 B. PALESTINA (908) 675-5763 ATHEMS, TEXAS 76781

Exalty Mich OTHER CALLS SEVEN COST CONTROL OF FOR JAME CALLS CALLS ATT OR PERFECT AND 5407 01/20/63 Seed u Shop FDC8138258 9399 10616 107-Z02 HITE/ F T # W 2 1 F 2 1 F D 2 6 2 5 8 receipt of the · *** 91716/95 90 J. 73 ENGINE - DIESEL
ENGINE WORT ACCEL & TIMES, ONLY IDLES
TEST WORT ACCEL ONLY IDLES CK ENG LIGHT DOMES ON KOED PASS
CONT CODE POSE;
TEST FOLKS TO SEMBOR AND IDLE VALIDATION PID SCHETIMES
DOM'T MATCH **WARRANTY** REPLACE FAD ED ACCEL PEDAL SEBENBLY RETENT KOED PAGE CONT CODE PAGE DEBUREPTION--UMIT PRICE-TO 8 1 1737-9F834-8A PENT & BONE FIRM JUB . 1 TUTAL PARTE JUB 4 : TOTAL LABOR & PARTS ## 2 84FD7455 BALGES/IMSTRUMENTS TECH (8):2348

GDOMGTER INDD. WILL SHOW SPEED BUT HE MILES

ROAD TEST FOLAD SPEEDO WORKS WORMAL TRIPM NOER AND GDOMEYER

INDP HEESBOARY TO REPLACE CLUSTER

REPLACE IMSTRUMENT CLUSTER MENRER-LA ----UNIT PRICE-PARTS # 2 JDB # 2 TOTAL PARTS JOS 🔹 2 TOYAL LABOR & PARTS SAFETY BELT INSPECTI RECREL 01821 SEATBELT RECOLL 01821 A. 3 INSP INSPECTION REPLACE SP UW 3+11F07@1821 TECH(S):2348 DEBCRIPTION -UNIT--PRICÉm 3 BEL A BALE TO . JOB . 3 TOTAL PARTS JUB & 3 TOTAL LABOR & PARTS TOTALB TOTAL LABOR...
TOTAL PARTS...
TOTAL SUBLET...
TOTAL B. G. B... TOTAL MISC CHE TOTAL SAVOTOE + CUSTOMER SIBUSTUME



17165624

INVOICE

JIM BASS SEAL HONDA-MAZDA

JANUAR & MRIS
JANUAR & MRIS
JANUAR & MRIS
JANUAR & MRIS
MRIT ACL. AT TIMES

MRIT ACL. AT TIMES

MRIT ACL. AT TIMES

(915) 948-4621		ES FE-3 NES REPLACED ACCELATION PEDIAL NES 42 1005 NOT GREATE PROPERTY CLEMEN COMES & NETEST PULL 1000 TESTED		
		PMCS	JES # 1 THISAL PRATS	
			1 TOURL LABOR & PARTS	
FOCS7	8096	JOB # 1 MON MANNAMY DESCRIPTION - CUSAGER	78996 78896 1874L - 1050	
Andrew Property	20166	TROMECLAN CHOTHECATION		
		1221 JNES E. HICERIA	GJ07	
MASON, TX		TOTALS.	TOTAL LABOR TOTAL PARTS	
		ANALOGY OPERATOR IS RETRIVED TO THE BASS MAINTRACES. WHI MAY RECEIVE A SURVEY HIM FUND OR HOMON CONCERNEDS. THIS SERVICE VISIT. PLEASE TAKE THE TIME TO ANSWER IT.	TOTAL SHELET Total 6.0.6	
dynamic Indol		SO HE HAVE BETTER SERVE YOU. HE WANT YOU TO BE HIRST SATISFIED. IF FOR MAY NEASON HOW MAE NOT, "PLEASE" GIVE US A CALL & 949-4621.	POTAL MESC CHS. THEAL MISC DISC THEAL TAX	
LARRY W. GREGORY	1353 7295	HARD THE REAL PROPERTY AND THE PARTY OF THE	TOTAL INVOICE \$	
	1 272 38.668	HOME MAZIA ME GENNYTEED 12 MINTES ON 12,400 MILES, HERCHER CHES FIRST GARTS & LAUGE), NO COMMUTEE ON USE 19815, LAUGE CHLY REPLIES ME SUMMAREED 99 DAIS OR 4,000	o [.]	
WENTER PLANS	HEAVY TRUCK/F250 CRI	ST MINES, MINESPER ONES FIRST DECEMBER LITT REPORTS ARE		
1 F T N W Z I	F B 1 E A 9 4 4 1 7			
Cours /	\$1000.00	CUSTOMER STOCKING		
Carlina			高高百	
	Regard Mountain			
06/01/02	06/01/02		- III 34	
	OEACH PAI			
STATE OF THE PERSON NAMED IN COLUMN 1	Property (State of State of St			
	5 <u>1100</u> 1 1000 001		·.	

100.00

2003 Econoline Remains at Idle and/or Trouble Code P0221:

Some vans built during June and July 2003 with the 7.3 engine may remain at idle regardless of accelerator pedal position. This condition may be intermittent and the check engine light may be illuminated. If a P221 trouble code is in the computer, replace the accelerator pedal assembly with P/N XC2Z-9F836-AA. If there is no code, or the condition persists after pedal replacement, follow normal diagnostics. Use a scan tool to monitor AP voltage and IVS mode/state. IVS should switch from OFF to ON before AP reaches 1.6 volts. Broadcast Message 0999.