EA04-006 FORD 5/13/2005 ATTACHMENT J BOOK 11 OF 11 PART 1 OF 6

174.85	1	7704 *	NA.	CA	31801
168.04	1.9	3262 *	NA.	ŤΧ	31801
110.84	1	3624 *	NA	NC	31801
167.56	2.1	4498 °	NA	אַד	31801
200.85	2.9	1491 *	NA.	TX	31601
112.87	1	4656 *	NA	ťΧ	31701
101.89	0.8	4946 *	NA.	FL	31601
199.36	2.1	4572 *	NA	TX	31.801
141.07	1.1	7749	NA	CA	31801
424.24	3.6	2695	NA NA	CA	31801
269,18	3.2	2631 *	NA.	TX	31601
158.59	1.5	5458 *	NA.	ÇA	31601
130,43	12	9233 *	NA.	Wi	31801
176	2	4350 *	NA.	NY	31801
132,73	1,2	2406 *	NA.	TX	31401
162.45	1.5	2561	NA.	TX	31801
163,52	1.2	7988 *	NA.	ĆÁ	31801
247.3	3.1	978 *	NA.	NC	31801
209.44	2.7	2779 *	HA.	g.A	31801
118.64	1	243 *	NÃ.	Ğ	31801
177.62	2	4605 *	NA.	TX.	31801
325.67	4.7	4288 *	NA.	Τχ	51801
201,98	22	1175 -	NA.	ထိ	31601
308,12	21	8190 *	NA NA	MC	31801
27B,21	3.7	3162 *	NA.	~~	31801
106,23	0.8	2872 -	NA.	Mi	31801
237.88	2.0	4647 *	NA.	ΤX	31801
430		5374 *	NA.	FL	31801
300.52	4.1	4492 *	NA.	TX	31801
101.21	0.8	2631 *	NA ·	ΤX	31801
148.71	1.5	20422	NA.	NEA	A1801
186.25	1.5	20422	NÅ.	NM	31601
165.26	1.8	20422 1	NA.	NM	31601
315.29	4	20422	NA.	NM	31801
114.27	6.9	3144 *	NA.	60	31801
141.49	1.5	802B ·	NA.	MO	31601
78.56	0.5	7879 *	NA.	ar.	31601
B2.84	0.7	1014 *	NA.	NC	31601
218.91	2.5	4584 1	NA.	IN	31801
218.78	27	2388 *	NA.	ОK	31801
107,01	1.1	475 *	NA.	90	31501
154.4	1.7	385 *	NA.	ĞĂ	31601
216.74	1.9	7883 *	NA NA	ČĀ	31801
321.06	4.1	1468	NA.	ΤX	31801
367.87	4.8	2417	NA NA	ΤX	31801
238.23	1.5 2.8			TX	
230.23	2.5	4672 *	NA.	1.0	31801

NA

FL

31601

31601

31801

31801

31601

31601

31801

31601

31601

31(0)1

31801

31801

31801

31801

31801

31801

31801

31801

31801

31801

31801

31801

31801

31801

31401

31801

31801

31801

31801

31801

31801

31801

31801

31601

31801

31601

31801

31801

31601

31501

31801

31801

31801

31501

31801

31601

4645 "

1.5

147.58

94.58	1	352 °	NA	GA.	31801
195.76	21	4551 *	NA	ŤΧ	31801
120.98	1.1	4416 *	NA	TX	. 31801
217.89	1.3	2030 *	NA	ОК	31501
162.10	1.7	2446 *	NA.	TX	31801
297.93	3.3	7791 "	NA.	CA	31801
194.4	9.2	8042 *	NA.	TX	31601
132.6	1.3	4645 *	NA	PL.	31801
503.80	5.1	4473 *	NA	TX	31801
124.63	1.3	9480 *	NA.	ND	31801
110.83	0.0	3042 *	NA	, TX	31801
201.75	1.1	193 *	NA NA	GA	31801
80.5	0.5	6637 '	NA NA	OR	31601
185.07	1.7	3134 *	NA 1		31501
218.07	2.5	243 *	NA	GA	31501
345.60	4.3	2441 *	NA NA	TΧ	31601
131.67	1.2	2413 *	NA.	TX ·	31801
202.3	2.1	7022 *	NA ·	ÇA	91501
179.60	1.9	2413 *	NA.	TX	31801
154.15	1.5	4845 *	NA	л.	31601
322.47	3.8	2441 *	NA.	TX	31601
117.69	1	2413 '	NA NA	TX	31601
124.48	1.5	4520 *	NA	Ϋ́X	31601
150.84	1.6	3182 *	NA	ထ	31601
214.21	3	5788 *	NA.	TN	31601
144,63	1.5	4500 *	NA.	TX	31501
108.6	t	4433 *	* NA	, TX	31801
547.79	4.5	3140 *	NA.	CO	31801
22.6	8.6	1754 *	NA.	CA	31601
335.6	4.3	20307 *	NA.	NM	31601
144.00	1.4	2923 *	NA.	TX	31601
338.27	4.2	3820 *	NA.	TN	31801
141.17	1.3	6497 *	NA.	GA	31801
155	1.8	4073 *	NA.	MD	31601
187.73	1.5	6017 1	NA.	ſL	31601
168	1.7	5592 *	NA.	CA	31601
105,7	0.9	26389 *	NA.	AZ.	31001
221.58	2.1	5547 *	NA.	CA	31601
98.4	0.8	9217	NA.	MN	31601
164.26	22	3228 *	NA	ΚY	31601
249.6	2.5	7894 *	NA	CA	31601
102.2	0.8	2511 1	NA.	TX.	31851
309.09	4.3	8373 *	NA	ΤX	31501
115.75	0.9	8170 *	NA.	co	3160:
254.68	3.6	1891 *	NA	AL.	31501
205.33	1.6	7900 *	NA	CA	31601

361.64	4.8	8947 *	NA,	TX	\$1 6 \$1
107,74	0.9	2831 *	NA.	· TX	31601
348.58	4.5	6947 *	NA.	. TX	31661
300,68	3.9	664 *	NA.	TX	31601
127	12	2292 *	NA.	OН	31801
192,42	1.7	7616 *	NA '	CA	31801
112.87	1.5	4410 *	NA.	TX	31501
278.14	3,5	4033 *	NA.	FL	31601
120.42	1.4	951 *	NA.	NC ·	31801
120.42	1.4	951 *	NA	NÇ	31901
108.63	0.0	4402 *	NA.	TX	31501
106.6	0.9	2868 1	.NA	ОK	31601
387.54	4.3	4622 *	NA .	FL	31901
101.87	0.3	296 '	NA.	GA	31801
204,4	2.f	243 *	NA.	GA	31601
101,94	1	1075 *	NA.	NC	31501
119.2	1.8	5225 '	NA	GA	31801
126.08	1.7	\$706 *	NA	TN	31901
80.27	0.5	5406 *	' NA	CA	31501
121.8	1.3	4119 *	NÅ.	NC	31801
178.8	1.8	20 19 *	NA NA	CA	31601
89.51	0.7	1462 *	NA	ML	31801
255.18	4.2	6549 *	NA.	MB	31501
112,6	1.2	\$577 *	NA.	LA.	31601
116.50	1	18579 *	NA	GA	31501
198.73	23	6142 *	NA,	(L	31801
85.29	0.0	1584 *	NA.	CA	31901
271	5	1346 *	NA.	PA	31501
207.67	2.9	9356 *	NA.	MN	31801
104.11	0.8	2413 "	NA.	ťχ	31801
389.8	4.8	467 *	NA.	QA.	31801
156.47	1.5	2446 *	NA	TX	31601
213,32	2.5	240 *	NA.	₽ A	21601
307.57	2.4	7894 *	NA	CA	31801
136.56	1.4	7745	NA.	ÇA	31601
217.61	2.2	6414 °	NA	CA	31801
290.4	3.4	20305 *	NA.	AZ	31801
762.75	9.7	2478 '	N,A	ťΧ	31801
264.4	3.2	6667 *	NA	CA	31801
121.64	1	5486 *	NA NA	CA	31601
66.2	0.3	2960 "	NA.	OK	31801
206	3.8	echs .	NA	AR	31801
328.01	4.2	2417 '	NA.	TX	31801
106.6	9.0	2987 *	NA	OK	3:601
111.96	9.0	4437 *	NA	ΤX	31501
112	C.D	2486 *	NA	TX	31901

102.74	0.8	423 "	NA	CA .	31501
165.1	1.7	7916 *	NA	ÇA	31861
228.49	3.1	1618 *	NA	TX	31801
208.81	3.6	1167 *	NA	Æ	31801
366.66	5.2	4440 *	NA NA	TΧ	31401
127	1.3	915 *	NA .	NC	31801
147.3	1.9	3584 *	NA NA	VA	31801
267.29	4.3	5242 °	NA	ťχ	31801
120.98	1.3	20420 *	NA NA	NM	31501
196.05	2,1	7775 *	NA	CA	31501
210.13	2.8	4510 *	NA NA	Æ	31501
134.1	1,1	7781 °	NA.	· HI	31801
127.63	1.2	7913 *	NA	ĊA	31501
332.07	4.2	3620 *	NA	TN	31601
318.5	4.1	4443 -	NA	TX	21501
192.98	2.2	4416 *	NA	TX	31501
358.59	4.8	6182 *	NA	TX	31801
129.25	1,5	68 12 *	NA NA	M	31501
157	1.8	3080 *	NA	Ϋ́X	31501
148.8	1.6	7283 *	NA	OR	31801
201.19	3.1	1073 -	NA	5C	31801
185.75	1.9	3991 "	NA .	MA	31801
145	1.8	7283 *	NA	OR	31801
122.29	1.3	985 *	NA.	NG	31801
76.62	0.4	3188 *	NA.	60	31601
146.55	1.2	7800 *	NA	CA	31801
174,4	1.8	5661 "	NA.	TN	31801
125.92	1.3	1818 *	NA	TX	31601
245.4	3.4	5582 *	NA.	TN	31801
91.68	0.6	9225 *	NA.	SD	31601
381.64	4.8	6947 *	NA.	TX	31801
349.67	4.2	214 *	NA	GA	31601
122.23	1.1	4547 *	NA NA	TX	31601
109.65	1.2	1821 *	NA	VA	31901
121.48	1,1	2091 *	NA	TΧ	31901
137.7	1	7884 *	NA	CA	31901
129.55	0.8	386 '	NA.	CA	31801
114.43	9.0	2967 *	NA	MI	31601
169.07	2	6521 *	NA.	LA.	31601
A.E8	0.7	4283 *	NA	TX	31501
126.78	1.2	7767 *	NA.	CA	31601
144.87	1.4	4437 *	NA	TΧ	31501
239.96	3.1	3262 *	NA.	ΤX	31801
323.7	4.1	6042 *	NA,	TX	31601
187.4	2.6	8494 -	NA.	MS	31501
304	6.5	1200 *	NA.	FL	31801

. . .

NA

NA

ŢΧ

31801

31801

154.62

139.99

2488 *

937 *

1.8

2

106.65	0.9	2511 *	NA NA	TX	31501
130,66	1.2	5584 *	NA	CA	37801
332.8	4.3	5901 1	NA.	TN	31601
391.65	4.3	5100 "	NA.	140	31601
103,51	0.0	6084 *	N/A	MO	31801
81.93	6.5	223 *	NA	GA.	31861
109.67	2	5471 1	NA.	CA	31601
189.8	22	2265 *	NA	OH	31601
84.48	0.7	3063 *	NA	ŤΧ	31601
227,55	3	2816 *	NA	OK .	21801
111.52	0.9	68 *	NA	MD	31801
362.68	4.3	4863 *	NA.	FL	31801
338.68	4.2	2441 1	NA	TX	31601
110.14	1	3553 1	NA	ŤΧ	31601
652.13	2.0	2561 *	NA.	TX .	31801
194,78	2.2	4687 *	NA	TX	31501
184.8	2.2	1860 *	NA	VA	31801
152,48	2	3584 *	NA.	VA	31501
70.91	0.4	312 *	NA.	GA	91801
107.68	4.0	4527 *	NA.	TX	31801
272,08	3.1	6639 * `	NA.	CA	31801
190,48	4.7	7713 °	NA NA	CA	\$1801
147.58	1.5	4845 *	NA.	PL	31801
163.6	8.0	2458 *	NA.	ΤX	31501
114.71	1	4615 *	NA.	TX	31801
318,77	3.0	4977 *	NA	FL	31801
312.67	4.1	6042 *	NA.	TΧ	31501
118,04	1.1	4361 *	NA	MO	31501
208.91	2.6	4448 *	NA.	TX	31801
87.67	0.7	8375 *	NA.	ID	31861
108,74	0.6	3786 *	NA	AZ	31801
272.00	3.6	2945 *	NA.	MB	31801
373,21	3.9	7021 *	NA	CA	21601
165.08	1.4	6278 °	NA	MO	31801
295.48	4.2	779 *	NA.	TX	31601
323.7	4.1	1472 *	NA	TX	31901
62.4	0.5	4920 "	NA NA	PL.	\$1801
145	1.5	3542 *	NA	NC	31801
176.7	2.1	2411 -	NA.	ָאַל	31801
108.53	1	20238 *	NA	· W	31801
124.74	1.4	1076 *	NA	NC	81801
271.57	4.Z	157 -	NA	NG	31601
180.44	2	8566 *	NA.	OR	31801
164.2	1.8	389 *	NA	'FIN	31801
215.80	2.7	4148 *	NA	NM	31801
271.48	3.6	4148 *	NA	NM	31501

120.30	1.1	2453 *	NA	TX	\$1801
161	2	4055 "	NA	B A	31601
74.8	0.4	4283 *	NA.	Τx	31801
202.06	3.5	4590 *	NA.	13	31801
69,48	0.6	3177 *	NA.	60	31801
1129	1	382 '	NA.	TX	31501
249.94	4.3	2823 *	NA.	TX	21801
139.52	7.4	8145	NA.	MÓ	31801
167.02	1.5	7005	NA	CA	31801
80.02	0.7	464 *	NA.	MT	31801
182.5	2	480 *	NA.	GA	31801
160.67	2	4924 *	NA	FL.	31801
145.48	1.5	4845 *	NA.	FL	31801
300.54	3.9	6192 *	NA	TX	31801
1773.86	1.8	4917 -	NA	FL	31501
130.53	1.4	4821 *	NA.	FL	31901
841.22	3.4	4506 *	NA.	ÍĀ.	81801
330.94	4.1	4443 *	NA.	TX	31501
281.12	3.8	7773 *	NA.	ÇA	31801
182.54	2	5592.	NA.	AL.	21601
130.83	1,5	\$412 °	NA.	Ã	31801
256.01	3.9	7583	NA.	ĀR	31801
142.26	1.4	365	NA.	GA	31801
151.50	1.5	4241 *	NA.	TX	31801
240.18	2.9	20428	NA.	NM	31801
272,51	. 33	1778 *	NA.	Ĉ	31801
259.77	3.5	7018 *	NA.	GA	31801
137.20	1.4	8772	NA.	TX	31801
602.87	. 6.8	7180 *	NA.	NE.	31501
103,84	0.9	2955	NA.	οκ	31601
326.8	4	2459	NÅ	Ťχ	31801
91	0.7	1596 '	NA.	. 12	31801
230,2	2.5	7848	NA.	Ĉ.	31801
130.21	1.8	193 *	NA.	SA.	31801
130.21	1.5	193	NA.	GA.	31801
233.05	3.4	193	NA NA	GA.	31801
101.38	0.0	1019	NA.	TX	31501
549.7¢	6.3	2914	NA.	ŤŔ	31801
155.13		7478	NA.	TX	31801
	1.6				
130.4	1.1	243 *	NA Na	GA.	31501
184.18	1.3	5466 '	NA.	씂	31801
189.34	2.2	7977 *	NA.	ŢΧ	31501
444.79	3.7	7863 *	NA.	Ç.	31501
345.04	42	20400 *	NA	AZ	31001
348.58	4,5	6047	NA.	TX	31601
323.7	4.1	1472 *	NA.	TX	31631

224,07	2.5	5009 *	NA.	MQ	\$1601
198.78	1.5	7620 *	NA	CA	31501
317	4	1472 "	NA.	TX	31601
114.86	1	2091 1	, NA	ťΧ	31651
112.9	0.9	7987 *	NA.	TX	31601
316.26	4	225 1	NA.	AL.	31601
117.1	1	8965 °	ALA.	M9	31801
97.1	0.7	8478 *	NA.	QK .	31801
134.2	1.3	4421 *	NA.	TΧ	31601
110,87	1	2486 *	NA,	TX	31801
112.61	0.0	2934 *	NA	MI	31501
259.48	3,1	2417 1	NA.	TX	31651
103.32	0.4	1354 *	NA	VA	31801
244	3	e 033 .	NA.	AR	31801
134,64	1.0	6018 '	NA	AR	\$1801
247.8	2.6	7987 *	NA NA	TΧ	31801
126.04	1.1	6521 *	NA .	LA.	31801
330.94	4.1	4496 *	NA.	TX	31501
340.90	4.3	2417 *	NA.	TX	31601
216.92	2.5	2446 1	NA 	TX	31801
20.03	D.7	6521	NA.	<u> </u>	31801
323,57	4.1	4817 *	NA.	TX	31801
310.61	1.7	2677 *	NA.	GA.	31801
140	1.4	765 *	NA.	· CA	31801
124.60	0.9	017B *	NA	MO	31801
92.4	0.7	* 6105	NA NA	TX	31501 31501
95.8	0.8	6064 ° 4437 °	MA	TN	31 60 1
111.80	0.9	5985 *	NA NA	TX	31801
130,72	1.2	4511 *	NA NA	MS	31801
115,96 235,39	' 1	1412 1	NA NA	TX CA	31601
103,24	0.6 0.9	4894	NA NA	FL	31601
180.42	2	4482 *	NA NA	TX	31801
105	0.6	2485	NA NA	ŤX	31801
118,21	1.9	9880 *	NA NA	NH	31801
161,82	1.9	7482 *	NA AN	778	31801
159.0	1.5	250	NA NA	λĹ	31601
252,67	27	7791 *	NA NA	ĈĀ	31601
160,17	1.3	30e *	NA	GÃ	31601
185,60	1.8	7482 *	NA.	TX	3:801
344.2	4.1	2556	NA.	73	31901
120,64	1.3	2530 *	NA.	ΤÂ	31801
152,85	1.4	1884 *	NA.	ĊÂ	31801
226.67	2.0	4463 4	NA NA	ΤX	31801
99.55	0.0	3282 *	NA NA	ΤX	31801
60.92	0.5	6531 *	NA NA	ĽÃ	31801
VV. BE		 ,	1171		D1007

876.62	4.8	3756 *	NA.	WI	31801
170.05	2.3	4840 *	NA.	F L	31801
110.5	0.0	4838 *	NA	PL	31501
218.67	2.5	2688 *	NA	KY	31501
97.78	0.6	7800 *	NA	CA	31601
133.95	0.9	7712 *	NA.	CA	31801
99.4	0.6	3867	NA.	ΤX	31601
	1.4	243 '	NA.	άÂ	31601
152.8 166.11	1.7	12577 *	NA.	100	31801
			NA.	Ň	31801
220.5	. 25	7882		TX	31801
90.1	9.0	4474 *	NA NA		
260,67	24	3238 1	NA	TX:	31801
102,57	0.8	4511 *	NA	TX	31801
209.72	1.4	994 *	NA.	NC	31801
251,32	3.2	847 ^	NA	WA	31801
100.2	0.5	4245 *	NA.	, NC	31801
104,5	0.6	2753 *	NA	LA.	\$1501
151.07	2	4496 "	NA.	TΧ	31801
155.79	1.7	4718 *	NA	IN.	\$1501
116.5	1	2816 *	NA.	NJ.	31801
278.02	2.9	5476 °	NA.	CA	31801
298,37	9.7	3620 *	NA	TN	31501
382.6	2.2	751 °	NA.	CA	31801
89.46	0.5	2413 *	NA	TX	31801
400.69	5	643 *	NA	TX	31501
113.6	0.0	6556 '	NA.	AW.	31501
100.00	0.6	4424 *	NA	TΧ	31801
181.8	1.5	2505 *	NA.	ĞÄ	31501
119	1.	2486 *	NA.	TX	31901
381.4	3.9	427 '	NA.	ΤΧ	31801
483.26	8.6	2975	NA.	MI	31501
		7883	NA NA	CA	31801
141.69	1.1	6375 *		iD.	31801
101.24	0.8		NA NA		31801
341.46	3.5	4522	NA NA	FL	31901
147.97	1.2	7597 *	NA.	CA.	
202.0	3.6	1472 *	NA.	ŤX.	31901
147,79	1.2	9217 *	N.A.	MN.	31501
145.79	1.5	6844 *	N/A	TΧ	31801
245,64	2	2890 *	NA.	M	31801
520.97	5.8	20554 *	NA.	NJ.	31601
111/99	0.9	4427 *	NA NA	TX	31801
145.74	1	2551 '	NA.	ÇA	21601
173.14	2	1266 *	NA.	FL.	31601
125.02	1.4	P90 "	NA	NC	31801
198.77	2	B71 °	NA.	8C	31601
181.60	2	2417 *	NA	TX	31601

185.57	2	6724 *	NA	VA.	31601
88,91	0.7	4922 *	NA.	PL.	31801
246	. 2	7820 *	NA	GA	31801
248.32	27	8867 *	NA	ÇA	31801
236.23	2.6	4872 *	NA.	ŤΧ	31601
168.8	1.9	2285 '	NA.	QH .	31801
223,67	1.1	4404 *	NA.	TX	31801
111.38	9.9	1182 1	NA.	60	31871
312.33	4.2	17 *	NA.	MD	31601
81.06	0.6	\$295 *	NA.	PA	31601
176.31	1	58R2 *	MA	AL.	31601
199,15	2.1	3130 "	NA	CO	21801
236.79	2.8	4843 *	NA	FL	31801
115.8	0.0	EDB * .	NA	GA	31601
178.71	1.5	3713 °	NA	NY	\$1901
· 191.25	2.2	2572 *	NA.	ΤX	31801
373	4,5	2586 *	. NA	ΤX	31901
117.54	1	4943 *	NA.	FL.	31501
109.35	0.8	1864 *	NA	CA	31601
351.65	4.5	2075 *	NA.	MI	31801
98.57	0.8	1014	NA.	NC	31801
145.04	1.4	7892 *	NA	NV.	31501
117.48	1	4437 *	NA	TX	31901
215.49	2.4	1365 *	NA.	PA	31801
344.89	4	20351 *	NA.	NM	31501
169.89	1,5	1349**	NA.	PA	316 0 1
B3.71	0.7	4410 '	NA.	ΤX	31601
1459.9	13.9	2048 .	NA.	MQ	31501
111.52	1	2574 *	NA.	TX	31601
108.48	0.9	4410 '	NA NA	TX	21601
97.85	0.8	8068 .	NA.	MA	.31801
160.27	1.5	1954 *	NA.	CA	31601
121.50	1.2	5802 *	NA	KY	31801
88,44	0.6	2830 *	NA.	MO	31631
412,13	6.1	3902 *	NA.	AL,	31801
220.8	2.6	2384 *	NA	TX	31601
382.84	4	20301 '	NA	AZ	31801
181.56	1.8	7752 *	NA.	CA	31601
191.21	2.1	4557 *	NA.	TX	31601
227.86	28	2531 *	NA.	TΧ	31601
276.07	2.1	5478 *	NA	CA	31801
200.00	2.5	7016 "	NA.	TX	31601
113.6	. 1	3043 .	NA 	NY	31801
324.2	4.3	6329 1	NA,	AL.	31801
179.91	. 2	1019 *	NA.	TX	31801
146.69	1.5	4871 *	NA	₽L	31901

127.19	1.2	4574 *	NA.	OR	31601
142,45	1.1	1246 *	NA.	· KJ	31801
428.28	3.0	3021 *	NA.	CA	31901
103.17	0.0	4402 "	NA.	TX	31601
219.15	2.6	4511 *	NA.	TX	31901
117.78	1.1	4410 *	NA.	TX	31651
181.49	1.8	1071 *	NA.	NG	31801
340.51	4.1	3204 *	NA	CO	31601
118.74	1.2	9005 *	NA	M	31801
425.35	4.2	1678 1	NA.	íŁ	21801
376.02	4.5	8287	NA.	UT	81601
216.25	2.5	4005 *	NA.	IN	31601
197	2	3573 *	NA	GA	31601
141.88	1.2	163B 1	NA	IL.	· 31801
164.2	1.6	389 *	NA	TN	31601
115.62	1.2	4868 *	NA	FL	31801
147.48	1.6	5714 *	NA	7N	81601
160.35	1,7	1265 *	NA.	FL	31881
104.11	0.6	2413 *	NA.	TX	31601
207.19	2.4	20428	NA.	NM	31601
287.42	2.8	4487 '	NA.	ŤΧ	31601
176.05	1.8	4572 "	NA.	ΤX	31501
108.48	1.2	10431 *	NA	PA	81801
381.67	5.1	1500 *	NA	AZ	\$1801
331.00	4.3	4850 *	NA.	FL.	31801
200.26	26	1987 *	NA.	IL .	31601
117	1	2370 -	HA	OH	31801
118.51	1	2415 *	NA	TX	21801
124.40	1.4	4370 *	NA	· NC	31801
188.83	1.7	B471 *	NA.	ÇA	31801
125.53	1.2	4039 "	NA.	PĻ.	31601
268.88	1.4	150 *	NA	SC	81861
164.62	2.1	4843 *	NA	FL	81801
106.19	0.9	7947 *	NA	TX	31661
165.24	2	9868 °	NA	M	31501
177.05	1.3	7820 '	NA.	CA	\$1651
135.46	1.3	2811 *	NA	TX.	81801
184	2.5	7457 *	NA	WV	31851
106,48	C'B	4544 1	NA.	ŢΧ	31801
2t6.61	1.6	5476 *	NA.	CA	31801
142	1.3	10093 *	NA	TX.	31801
274.95	3.5	3037 *	NA	FL	\$1801
76.4	0.4	4474 "	NA.	7X	31601
176.31	1.8	20402 *	NA	AZ.	31801
174.62	2	1969 *	NA	WV	31601
196.63	1.8	1016 *	NA.	ŤΧ	31631

241.65	. 26	" סלוב	. NA	CO	21801
819.73	4.1	4498 *	NA NA	TX	31601
161.29	ŒΒ	20360 *	NA	AZ	31601
130.14	1.3	5686 "	NA.	KY	31801
139.96	1.3	4437 *	NA.	ΥX	31501
179.92	1.5	7777 °	NA.	CA	31601
115.62	1.1	427 *	NA.	TΧ	31801
339.21	42	7160 *	NA NA	NE	31801
382.5	3.3	7921	NA.	CA.	31801
0	Þ	4044 "	NA.	FL	31801
205.16	1.9	\$613 °	NA	CA	31801
D	0	2611 *	NA.	TX	\$1801
153.75	1,2	7777 *	NA.	CA	31801
93.8	0.6	3139 *	NA.	60	31801
840.49	. 4	6518 °	NA.	CA	31801
237.52	1.7	5497 "	NA.	CA	31801
121.79	0.8	20623 *	NA	NJ	31801
192.99	1.7	20360 *	NA.	AZ	.31801
199.7	2.3	.4611 *	NA.	TX	31801
141.48	1.5	2635 *	NA	ΤX	31801
82.4	0.5	4820 *	NA.	FL	31801
261.74	3.5	4860 '	NA .	R,	31801
159,6	1.4	751 *	NA.	CA	31801
448.72	8.2	1167 *	NA	FL.	31901
108.8	1	6498 *	NA.	LA	31001
448.72	6.2	1187 *	NA.	FL.	31601
120.83	1.1	3973 '	NA.	FL.	31501
147.50	1.5	4513 '	NA.	TX	31601
208.83	26	4982 *	NA.	FL.	21501
109.67	0.8	1016 *	NA.	5G	31501
179.41	23	4846 *	NA.	₽L	31801
335.0	4.0	8888 *	NA	TX	31801
120.66	1.3	4908 *	NA.	FL.	31501
148.4	1.4	7957 *	NA	TX	31801
129.13	1.\$	3567 *	NA	TX	51801
122,08	1.1	2417 *	NA.	TX	31801
112.43	0.7	4963 *	NA	PL	31801
120.96	1	2441 *	NA.	TX	31601
343.44	4.6	3620 *	NA.	ΤX	31801
61.22	0.7	3827	NA	TX	31801
304.46	4.2	2515 *	NA.	TX	31801
186,76	2.3	1730 '	NA.	GA	31601
148.4	1.4	7967 *	NA.	ΤX	31801
355.41	4.5	3048 *	NA.	TX	31801
76.4	0.4	2413 *	NA.	ΤX	31801
145.0	1.5	1923 *	NA.	OH	31 6 0 7

117.78	1.1	4544 *	NA	ΤX	31601
86	0.7	2466 *	NA	TX	31801
274.25	4.1	6398 *	NA	LA	31901
304.2	3.6	\$192 °	NA.	TΧ	31801
188.01	1.8	1864 *	NA	CA	31001
108.23	1	4500 *	NA	TX.	31601
200.58	2.1	5350 *	NA	CA	31801 ·
143.38	.1.3	1864 *	NA	CA	31801
120,83	1.5	855 *	NA.	ac	\$1801
349.36	4	5009 °	NA	MO	31001
263,56	3.8	1109 "	NA.	NC	31601
104.84	9.0	2040 *	NA.	WY	· 31601
102.4	9.0	5875	NA	AR	31801
241.48	2,1	8645 *	NA	WA	31801
106.63	1	650S *	NA ·	i.a	31401
132.46	1.5	250 *	NA .	QA.	31801
132.45	1.5	269 *	NA NA	GA.	31601
151	1.7	9044 *	NA .	ME	31601
108.6	0.0	839 *	NA	9C	31601
100.05	21	2488 *	NA.	TΧ	31801
164.2	1.B	930 *	NA.	\$C	31601
336.24	3.1	3567 "	NA.	D .	31801
228.60	2.4	3148 -	NA.	CO	31601
150.24	1.2	7819 *	NA.	CA	31801
160.56	4.5	543 *	NA.	TX	31801
307.4	3.8	4790 *	NA	FL.	31601
152.52	1.4	2929 *	NA.	М	31601
172.13	1.7	648 *	NA.	6C	31601
406.0	7.3	4584 *	·NA	FL	31801
191.98	1.5	7799 *	NA.	CA	31801
79.75	0.5	1708 *	NA.	W	37801
163,02	1.7	B645 *	NA.	WA	31401
191.54	1.6	5488 *	NA NA	CA.	31801
80.74	0.7	6443 *	NA	LA	31501
251.1B	3.3	4463 *	NA	TX	31801
411.6	4.9	647 *	NA.	GA	31601
100.93	0.7	1864 *	NA.	CA	31801
330.94	4.1	4443 *	NA.	TX	31501
100.51	9.0	6444 *	ŅA	₩	31801
194.88	2.6	5029 °	NA .	AR	31601
144.8	1.5	4814 *	NA.	FL	31801
288.95	23	5445 *	NA	GA	31801
103	Q.8	4560 *	NA	X	31601
292.95	3.5	4590 "	NA	TΧ	31501

TECH_TXT1

VERIFY WOR KOEC PO221 PPT QC18 TQC18 REPLACE FAULTY ACCELERATOR REDAIL ADJUSTABLE CLEAR CODES AND RETEST

CHECKED BBP SENBOR OK EEC TEST NO CODES SENBOR WORKS INTERMITTENLY REPLACED ACCLERATOR PEDAL ASSEMBLY WITIME NO SUTS

DIAG ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG

RUN ENGINE PERFORMANCE TESTS, INSPECT LINKAGE, REPLACED PEDAL ASSEMBLY, CLEARED CODES, ROAD TEST

IDLE VALIDATION SWITCH OPEN | EEC (QUICK TEST) DIAGNOSIS

16570 EEC TEST FOR CHECK ENGLIGHT HAS CODE PO221 PINPOINT TEST FE1 FE2 CALLED AND TALKED TO HOT LINE THEY RECOMENDED INSPECTING WIRE HARNES FOR THROTT PERFORM COMPLETE DEGLE DIAG PERFORMED DIAGNOSTICS AND REPLACED ACCEL PEDAL RETEST OK.

16977 ORDER THE FOOT FEET ASY, 1428 TOOK FOOT PEED ASY OUT OF TRUCK ON LOT AND INSTALLED IT IN CUSTOMERS TRUCK, THROTTLE NOW OK, PUT OLD ASY IN CUSTOMERS BNG PERF DIAG, PPT TEST, REPL PEDAL

12766 CK POR NO THROTTLE RESPONSE. PERFORM PERFORMANCE DIAGNOSTIC SHEET STEPS 1 14 RETREIVE CODE P0221 THROTTLE SWITCH B CIRCUIT PERFORMANCE, TESTEC TEST REPLACE AP SENSOR

RÉPLACE PÉDAL AND BENSOR OPEN CIRCUIT

SCAN TEST CODE PO221, CHECK PIDS PERFORM PINPOINT TEST DIAG ACCEL PEDAL ASSEMBLY REPLACE ACCEL PEDAL ASSEMBLY, CLEAR CODE AND RETEST OK, NO PUBLISHED TIME KOEO, INJECTION CONTROL PRESSURE TEST, LOW ICLE TEST, REPLACED ACCEL PEDAL ASSY

1 DIESEL DIAG, CODE 221 PEDAL LOW CIRCUIT, PIN POINT TEST DEFECTIVE PEDALISM, RAR PEDAL ASSY DROVE WI CUST TRUCK OK

12540 CC42 PREFORMED DIESEL DIAG FOR CODES P0122 P0221 PIN POINT ("ESTED AND REPLACED THE ACCEL, PEDAL CLEARED CODES RETESTED OK

RAN DIAG TEST. FOUND TO SENSOR IN THE ACCELERATOR ASSY TO CORRECT. IN AND IN FUEL PEDAL ABSY TO CORRECT

18889 FAULTY ACCELERATOR PEDAL 6006F.3P1.1F1X1.1F2.1F7.2F8.1F9.3F10.1F11.2F12.3F13.1F14.1F16.6F17.8P16.6F19.2: 2480F.4 VERIFIED CONCERN DIAG PID TEST CODESPO221 PC VIERNIED CONCERN RPL PEDAL INOP

20743 42 WAR TESTED THE FUIL ACCARDAL IS INCH. RER AND REPLACED FEDAL AND ROAD TESTED OK

11792 SENSOR FAILURE MITIME 1,5 HR\$ NO OP\$ FOR REPARK, DIAG TEST, PG221 RIR AND REPLACE AP PEDAL ASSY.

14152 ROAD TEST PERFORMANCE CHART STEPS 1 14 PM POINT TEST REPLACED TO SENSOR OUT OF RANGE RETEST PASSED

MT8F838 REPLACED ACCEL.PEDAL ASSY

REPLACED THROTTLE ASSY, PETEST OK

PINPOINST TEST MONITOR PIDS REPLACED PEDAL ASSEMBLY

11642 42 PF656 ROAD TEST, FOUND ACCEL PEDAL DOES NOT RESPOND AT TIMES, SEE DIAG. SHEET, PINPOINT CODES, RAI AND REPLACE PEDAL ASSY, CLEAR CODES, ROAD TEST

PE83-844 32238

8199 THROTTLE PIOP WARR CHECKED DUT THROTTLE PEDAL SHOTED RAR PEADAL ASSY RETESTED OK

TESTED, REPLACED THROTTLE PEDAL ASSY.

RAN PERF DIAG 1 14 ON WISHEET RETRIEVED CONT CODE PO221 RAN PINPOINT AND PID MONITOR INTERMITTANT NO SIGNAL NECESSARY TO REPLACE PEDAL ASSEMBLY PEDAL ASSY RAD DIAG AND INSTALL NEW PEDAL ASSY

PERFORM DIAS AND FOUND IDLE VALIDATION SWITCH MALFUNCTION REMOVE AND REPLACE IDLE VALIDATION SWITCH

DI PERFORMANCE DIAG.CHECK COOLANT, CLEAN FUEL, CILLEVEL, INTAKE RESTRICTION, KOEO PASS, CONTINUOUS DTC P0122, KOEO INJECTOR BUZZ TEST, FUEL PRESSURE RIGHT FUEL PEDAL ASSEMBLY BAD ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

CONFIRMED CONCERN PERFORMED DIESEL DIAG 1 14. FOUND ACCEL PEDAL OPEN CIRCUIT, INSTALLED NEW PEDAL ASSEMBLY, ROAD TEST NORMAL.

MONITOR PIDS RAN PINPOINT TESTS WINGS THROTTLE POSITION SENS OR NOT OPERATING PROPERLY REPLACE PEDAL ASY

16190 41 VERIFY CUSTOMER CONCERN, PERFORM DIESEL PERFORM ANCE DIAGNOSTIC SHEET STEP 1 TO 5, USING NGS PERFORM KOED, PASSED, RETRIEVED CLEAR CONTINUO: ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

22165 TESTOROVERAN EED TEST, NO CODES IN SYSTEM, RETESTOROVE, HOCKED UP RECORDER & MADE RECORDINGS FOR INTERMITTANT CONCERN. IDLE VALIDATION SWITCH 18965 TESTOROVE, HOCKED UP NGS & RAN KOED & KOER TESTS, POZZ1, RAN PINPOINT TEST & REPLACED AP SENSR, CLEARED CODES & RERAN ETST & TESTOROVE FOR GUALITY TESTED AND TRACED TO BAD PEDAL SENSOR AND REPLACEDAND RETESTED TO CORRECT

VERIFIED CONCERN REPLACED THE THROTTLE POSITION SENSOR ASSEMBLY .

43614 WARIA VERIFIED CONCERN. EEG TEST HAD CODE POSSI MONTORED PIDS AP 1Y5, PIN POINT TEST FE1. FOLLOWED PIN POINT TEST REPLACED ACEILERATOR PEDAL, ROAD NEC DIAG KOED, KOER P1111, KOEC POSSI PERFORM PPT & PID DATA MONITOR. FOUND ERRATIC SWITCHING OF IDLE VALIDATION SWITCH REPLACE PEDAL ASSY HAD TO GET PARTEST DRIVE VERIFIED CONCERN CHECKED TESS NONE CHECKED CODES WITH WOS CODES FOR TP RANGE CIRCUIT HOW LOW RESIS PERFORMED PCED PINPOINT TESTS TPEDALS EEC SYSTEM TEST ROADTESTED AND MONITORED CHECKED REPLACED PEDAL ASSY

14200 PEDAL ASSY W PERFORMANCE TEST 1 10. ALL P1111, EXCEPT ON SWITEST, AND RETREIVE CODES, P0221, TP CODE. (NBTALL PEDAL ASSY FOR TP CODE. RETEST.

MEC TEST ROAD TEST MONITOR TEST PRIPORT TEST CODE P0221 WIRING SHORTED AT STEERING COLINUM SHAFT AND MOUNT ACES DASH REPAIRED CIR 477 SHORTED RETEST P

PERFORMED DIAGNOSTIC INSPECTION USING MGS TESTER. CODE POZZI IN SYSTEM. PERFORMED PINPORT ELECTRICAL

1 INSTALLED SOP ON, KAN NGS. CLEARED DTCS. P0221, INSTALLED ACCELERATING PEDAL ASSY, ROAD TESTED, RAN QUICK TEST, FIXED

ENG PERFORMANCE DIAGNOSIB, REPLACE ACCID, PEDAL ASSY AND RETEST

PALLTY PECAL SENSOR ASSY ENGINE PERFORMANCE DIAGNOSTICS 7.3. IX TURBO ENGINE DIAG

PERFORMED DIESEL DIAG WORKSHEET ALL TEST PASS TO KOED CODE PO220 MONETORED PIDS FOUND THE T P INTERMITY OPEN PERFORMED

13884 25 W5544 PERFORMED TEST 1 14 FOUND DTC PO221 MONITOR AP FOUND D'A AT TIMES REPLACED PEDAL ASSEMBLY RETEATED CK AT THIS TIME

THROTTLE. INSTALL BREAK OUT BOX, YOUTAGE INCREASED AND MATCHED NOS INGLICATE WIRING AT LEFT SHOCK TOWER AND UNDER DASH NEAR STEERING SHAFT. REPLACE DIESEL BY BY PERFORMANCE DIAG, KOEC PO122, PO221, POUND INTER MENTENT FAILURE IN PEDAL ASSY, NEC TO REPLACE PEDAL ASSY, ROAD TEST OK, NOTE: VEHICLE HAS AFTER PERFORM PN POINT, REPLEXCITER RING RETEST ROAD TEST.

24083 TP SENSOR 28 W CHECK VEHICLE FOR NO ACCEL OVER 30MPH, PERFORMINGS BELFTEST PASS, MONITOR PIDS FOR TP AND AP TP INOP, REMOVE ACCEL PEDALS FROM ST RAN EEC TEST CODE P0221 DCL DISPLAY PID MONITOR ROAD TEST PINPOINT TEST MT TIME TO REPLACE PEDAL AND SENSOR ASSEMBLY RETEST PASSED TEST DROVE RUNS NOT PERFORM BEC TEST NO COOKS PRESENT IN SYSTEM FOUND LOW OR NO THROTTLE R

PREFORMED PERFROMANCE DIAG PERFORMED PRIPOINT TESTREPLACED ACCELERATOR PEDAL

QUICK TEST, PO123 CODE, PINPOINT, FAULTY ACCEL PEDAL ASSY, REPLACE ACCEL PEDAL, ROAD YEST, O.K.

PERFORMANCE WHILE DRIVING DIAG KOEC POZZY ALL OTHER TEST PASS POUND OPEN IN INTERNAL ACCEL, PEDAL SWITCH REPLACED ACCEL PEDAL ASSY ROADTEST AND RETEST 14100 EEC TEST, DIAG PREFORM SHEET, OCL DIEPLAY, PIMPOINT, FOUND AP OUT OF SPEC, REPLACE AP RETEST, IS

VERIFIED CONCERN PERP DIESEL DIAG MEM CODE PO122 KOEC SELF TEST PASS KOED INJ SELF TEST PASS KOER SELF TEST PASS PINPOINT TEST FOR MEM CODE MONITOR PIDS 35573 TECH NO. 40 MIL COMES ON INTERMITTENTLY AND ENGINE WILL ONLY IDLE. INSTALLED NGS AND PERFORMED EEC TESTS NKOED PASS, NKOER PASS, NCONT PO221. RAN CX PERFORMED EEC DIAG PINPOINT TEST FOUND ACCEL PEDAL NOT OPERATING PROPE

THROTTLE POSITION SENSOR OPEN CIRUCIT TEST DROVE 2 MILES, VERIFY CUSTOMER CONCERN, PERFORMED DIAG SHEET STEPS #1 14. FOUND DTC P0221, REMOVED & TEST T F INOPERATIVE EBC (QUICK 1651) DIAGNOSIS

APP SENSOR CAUSE OF NO POWER 6006F F17 2460F ROAD TEST VEHICLE VERIFIED CONCERN INTERMITTENT NO POWER PERFORM DIESEL PERFORMANCE DIAG VISUAL INSPECTIK DASIS CONCER 15/12 CHECK WIRING AND REPAIR GREY WHITE WIRE AT TLEFT OF FRONT SHOCK YOWER AND SECURE REPALCED ACCEL PEDAL

RAN DIAG TEST CODE P0221 PINPOINT TEST REPLACED THROTTLE SWITCH PEDAL ASSY CLEAR CODES

BELF TEST, PIN POINT TEST. CHECK FUEL PRESSURE, REPLACE THROTTLE PEDAL ASSEMBLY

DIAG.7.3 TURBO OPP.PINPOINT TEST.FOUND TP SENSOR SAD.REPLACE PEDAL SENSOR ASSY.ROAD TEST.OK.BASIC.9836.041.42.

ECC TEST VEH CODE FOR FLIEL PEDDLE FOUND REPLACED FUEL PEDDLE CLEARED CODE TEST ORIVE ALL OK

CONFIRM, TEST DRIVE AT TIMBREXCELERATER PEDAL INOP AND SETS A PO221 WOULD ONLY HAPPEN ONCE TO TECH, CAN REPRODUCE IN SHOP, CHECHED ALL WIRES OK CONNEC

OPEN IN PEDAL ASSY ENC (QUICK TEST) DIABNOSIS

WILL NOT ACCELL ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG CHECK CONCERN AND INSPECT FOUND BAD ACCEL PEDAL, REPLACE PEDAL AND RECHECK ALL O.K.

RESTRICTED ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

REPLACE ACCELERATOR PEDAL ASSEMBLY

ACCEL, PEDAL ASSY. ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG.

10627 AP BESS 42 W PERFORM PERFORMANCE DIAGNOSTICS STEPS 1 THRUS PERFORM PINPOINT TEST SERIES CORSER AP AND CLEAR CODES

11548 SOMET 16. C K FOR ACCEL PEDAL INOP AT TIMES TEST DROVE VEH VERIFIED PROBLEM.RETURNED TO SHOP PERFORMED ENGINE PER DIAG. FOUND CODE PO122.REPLACED TEST DROVE AND CONFIRMED CONCURM, PERFORM QUICK TEST WITH WIDS AND FOUND CODE P0221, PERFORM PINPOINT TESTS AND MONITOR

EEC TEST, PO123, PID MONITOR SHOWS ACEL PEDAL GOESTO 4.76 VOLTS JUST OFF IDLE, PINPOINT TO PEDAL SE NSOR, REPLACED SENSOR, CLEAR CODE AND RETEST. REINSTALL

EEC TEST, CODE P0221, REPLACED ACCELERATOR PEDAL ASSY
VERFIED CONCERN NO THROTTLE RESPONSE INTERMITTENTLY RUN CASIS NO SSM OR TSES APPLY RUN TEST ON WDS RETRIEVED CODE P0221 RUN WEEP TEST ON TP SENSOR R
TEST SYSTEM CODE P0221 MONITOR PIDS NO RESPONCE FROM ETC TESTED AND REPLACED ETC. 050 P0221 42

1 VERIFY CONCERN PERFORMED DIESEL DIAG, WORK SHEET AND REPL. FUEL PEDAL ASSY. RETET ROAD TEST OK NOW

AP SENSOR INTERMITTANT MGS DIAG, POZZI KOEC PIH KOEC PIH KOEC PIH KOER, REPLACED THE AP SENSOR A

RAN EEC TEST PINPOINT MONITOR ROAD TEST INSTALL PEDAL ASSY RETEST IN TIME TO INSTALL PEDAL ASSY WPI

1884S CONDITION 42 BASE PART 97835 VERIFY CUST. CONCERN PERFORM PERFORMANCE SHEET FOUND FAILED. PEDAL ASSY NOT ALLOWING VEHICLE TO COME OFF IDLE. REPLACE 21847 FAULTY ACCELERATION PEDAL PERFORM DIESEL. DIAGNOSIS PO221 FOUND ACCEL PEDAL ASSEMBLY FAULTY REPLACE PEDAL RETEST.

HOCKED UP NOW AND MONITORED PID DATA WHILE TEST DRIVEN; DICCOLLD NOT GET TRUCK TO ACCERATE UP; RAN PERF DIAG; HAD DTC P0221; DID PINPOINT TEST FE1 ADN PE: M TIME TO REPLACE SWITCH FOR ACCEL FEDAL DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

RAN EEC TESTS ON WOS. FOUND IDLE VALIDATION SWITCH CODE RAN PINPOINT TESTS LISING DATALOGGER MONITOR, IVS PID WOULD NOT RESPOND TO PEDAL MOVEMENT, REPI PERFORMED DIAGNOSTICS, REPLACED ACCELARATOR PEDAL DUE TO OPEN SERISON CINCLIT

TED,OK.

INOP ENGINE PÉRFORMANCE DIAGNOSTICS 7.3L DI TURBO ÉNGINE DIAG

PEDAL ASSEM REPLACE ACC PEDAL ASSEM

BAD PEDAL ABSY

INOP 800Y CHASSIS ELECTRIAL (BCE) TEST

ILDE VALIDATION SWITCH SHORTED ROAD TEST TO VERIFY CONCERN, NGS START UP, NGS ERC TEST PO122, PO221, DOL DISPLAY, PINPOINT TEST DOS. REPLACE ACCEL PEDAL AS AP SENSOR GOING OPEN INTERMITTENTLY REPLACE AP SENSOR PEDAL ASSY.

CHECKED CUSTOMERS CONCERN VERIFIED THE SYSTEM FOUND THE PEDAL ASSY. INOPERATIVE REMOVED AND REPLACED THE PEDAL ASSY. REINSTALLED ALL PARTS RE EEC TEST LAMP ON PINPOINT TEST PEDAL ASSEMBLY OPENDOL DISPLAY VOLTAGE DROP TO .13 TOO LOW REPLACE P EDAL ASSEMBLY CLEAR AND RETEST PASS ROAD TEST OK TESTED BUIC SYSTEM PERFORMED NGS ROAD TEST AND REPLACED AP SENSOR

REPL ACCELERATOR PEDAL ASSY

CK ENGINE LIGHT ON ENGINE PERFORMANCE DIAGNOSTICS 7.3L, DI TURBO ENGICIAG REPLACE ACC PEDDLE SENSOR CHECKED PARTS PRIOR TO MAKING REPAIR FOR DI COVER/ 2008 VEHICLE CLITS OUT WHEN DRIVING AND ACCELL, PEDAL INOP. RAN NGS SELF TEST KOEO PASS, CONT. CODES P0122, RAN PINPOINT TEST DOS. MONITORED DOL DISPLAY AP VERIFIED CONCERN TESTED HARNESS FOR OPENS JIONITORED PEDAL ASSENSLY POUND BAD PEDAL ASY REPLACED ASSY RECHECKED GOOD AT THIS TIME

ROAD TESTED CHECK ENGINE LIGHT ON NGS EEC TEST PO122 P0221 H MANUAL PINPOINT TEST DCL DISPLAY 0.2 PAILED QCS 5VOLTS R AND R GAS PEDAL ASSY RETESTED P1000 F 1 PERFORM DIESEL DIAG 1 14 POUND HARD FAULT P0221 STORED IN MEMORY PERFORM PINPOINT TEST RAR AP ASSY RETEST ROAD TEST

CUST STATES PUSH ON ACCEL DOES NOCHECK AND REPLISHECTRIC THROTTLE PEDAL ASSY RE ROAD CHECK CHECK FO

12817 PERFORMANCE DIAGNOSIB, ROADTEST WITH NOS AND MON ITOR PIDS, REPLACE AP JREYEST

PERF, TEST PIDS THAT REPLACE ACCEL PEDAL RETESTED

RUN TEST ON ENG AND REPLACED ACC PEDAL

PERFORMED COMPUTER SYSTEMS DIAGNOSTICS FOR FAULT CODES TEST EEC, PO221, MONITOR PIDS, DIESEL DIAG, PINPOINTS AND REPLIED LE VALIDATION SWITCH PÉDAL ASSY, RE

PERFORM ENGINE PERFORMANCE DIAG, & PPT QC 15 & 19 FOR CODE P0221, REPLACE ACCELERATOR PEDAL ASSEMBLY

1844 VERIFIED CONCERN, WOS TEST, PO221 TP (9) SITCH PERFORMANCE, TP SWITCH EAD, REPLACED ACCEL, ERATOR PEDAL, W ADJUSTABLE PEDALS.

TP RANGE OFF THROTTLE DOEBN'T RESPOND, CKD AS PER SHOP MANUELMSAID. TO REPLACE PROCESSOR, INSPECTED WIRES PER HOTLINE NPF REPLACED PEDAL ASSY RETRIEVE CODES P0221, PERFORM PINPOINT TESTS F. OR ACCELERATION PEDAL FAULT, INSTALL NEW ACCELE MATOR PEDAL ASSEMBLY, CLEAR CODES, RETEST. PASS.

7.3 OF PERFORMANCE DIAG PINPOINT & REPLACE PEDAL ASSY RETESTION.

AP PEDAL, DIAG 1 6 PLASH CODE P0221,RR ACCEL PEDAL.

REPROGRAM POM SERVICE BAY DIAGNOSTIC SYSTEM (SBOS) START UP TEST

NOP ENGINE PERFORMANCE DIAGNOSTICS 7.5L DITURGO ENGINE DIAG

CK FOR ENGINE WILL NOT ACCELERATE TEST DRIVE AND FOUND NORMAL OPERATION AND CUSTOMER STATED ONLY HAPPENED ONCE A DAY MAYBE 2 TIMES TOTAL CK FUEL PSI., 19821 DESELL EEC TEST, NGB DCL DISPLAY, PINPOINT TEST, MONITOR AND RECORD PIDS. KOBO SELF TEST, KORR SELF TEST, REPLACED ACCEL PEDAL SWITHC ASSEMBLY RETE

SUBLET TO HAL BURNS OK ACCEL PROAL STUCK & CRUISE CONTROL WENT OUT, HAD ADJUSTED IN MEX

WOS SELF TEST REPLACE APP SENSOR OPEN

VERIFIED CONCERN, RAN PARTIAL PERFORMANCE TEST, CODE 0221, RAN PINPOIN TEST, QC13,QC17, REPLACE ACCELERATION PEDAL PER TEST QC15, RETEST, TEST DRIVE, ALL PA

D60 42 9F836 BAD PEDAL ASSMIREPLACED PEDAL ASSEMBLY

CHECK OUT ENGINE LIGHT COMES ON AND PEDAL WILL NOTRESPOND, PERFORM PERFORMANCE DIAG, CODE P0221 REP LACE PEDAL ASSY (OPEN CIRCUIT)

OPEN CIRCUIT BEC (QUICK TEST) DIAGNOSIS

OUT PINS INSPECT WIRING AT C133 FOAMD WIRING RUBBING ON SHOCK TOWER. CIRCUIT 356 367 REPAIR WIRING 2 INSTALL CONVOLUTE TUBING AND REPOUTE HARNESS ROAD 1. REPLACE ACCEL PEDAL/SENSOR ASY.

RAN BEC TESTS RAN DATA LOGGER ACCELERATOR PEDAL NOT IN SPECS REPLACED.

INSTALL NEW PEDAL WITH SENSOR

25000 ROAD TEST EEC TEST PO221 MONITOR AND RECORD TO COLDISPLAY PIMPOINT TEST FOUND FAILED TO REPAL ACED ROAD TEST OK

1 RAN ALL DIEBEL PERFORMANCE TESTS, REPLACED ACCELLERATOR PEDAL AND BRACKET

EEC TEST, P0102 RECORD AND MONTOR PIDS, PERFORM PINPOINT TEST, REPLACE AP SENSOR, RETEST AND ROADTEST.

13431 APP 5W HOOK UP WOS AND PERFORM KORE TEST. AND RETREIVE DTCS P0221 P0380 P1211 P1249 P1249 DISPLAY AND MONITOR PID DATA AND APP SW STAYS AT HOLE BUT CC 28 3PN 9F836 PERFORM VISUAL INSPECTION OF ENGINE, CHECK FOR CLEAN FUEL, CHECK OIL LEVEL AND CONDITION, CHECK FOR INTAKE RESTRICTION, PERFORM KOSO, RETRIED AP THROTTLE SWITCH ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

PERVIORM DESEL DIAGNOSIS, CODE POIZS TP OUT OF RANGE REPLACE ADJUSTABLE THROTTLE AND TP ASSY.

73 DI TURBO E400 ADAJSTABLE PEDALS RUN ENGINE PERFORMANCÉ TEST 1 2 3 4 5 6 7 9 10 11 12 14 PERFOM PINPOINT TEST AND

1995 VERIFIED THE CONCERN, PERFORMED PERFORMANCE DIAG AND FOUND CODE P0221 FOR TP SENSOR FAILURE ORDERED NEW TP SENSOR IVO 1049, 9756 R R THE FOOT FEE BEC TEST NO CODES OPEN SPOT IN TPS AT TIMES REPLACED 8.0. THROTTLE CONTROL

D36 9F836 42 ROAD TEST VEH. VERIFIED CONCERN, PERFORM DIESEL, ENG. PERFORMAN DIA 680 TEST SYSTEM, CODE P0221 TP SENSOR, RANGE PERF.

EEC TEST CODE P0122 PINPOINT TEST PID MONITOR REPLACED ACCELLERATOR PEDAL.

DIESEL DIAGNOSIS REPLACE ACCELERATOR PEDAL ASSEMBLY

ENGINE PERFORMANCE DIAGNOSIS, REPLACED ACCELERATOR PEDAL

RAN PERFORMANCE SHEET 1 8 A.S.C.D 9 10 A.B FOLIND CODE PA122 CHECKED TP SENSOR, FOUND SHORT REPLACED ACCELORATOR PEDAL 1

CODE PO221 MONITORED PIDS PERFORMED PP TESTS REPLACED ACCELERATOR PEDAL ASSEMBLY CLEARED CODE RETEST VEHICLE OPERATES PROPERLY

TRUCK WILL NOT ACCEL HOOK UP WOS AND PULL CODES, F0221 MONITOR FIDS. REMOVE AND REPLACE ADJUSTABLE ACCEL PEDAL ASSY. AND CLEAR CODES, TRUCK RUNS FINE REPLACE PEDAL ASSY.

NGS TEST 6000F F1 F1X1 PARS F2 PARS F6 PARS F7 PARS F6 PARS F12 PARS. PINPOINT TEST SHOWS INTERMITANT SHORT ON ACCEL PEDAL REPLACE PEDAL ROAD TESTED OK 7.3 C/ PERFORMANCE DIAG PINPOINT & REPLACE THROTTLE PEDAL ASSY

REPLACED AP BENSOR.

MC12274,7,3LAUTO,F350,DUALLY, C C43,6F635 PEDAL ASY CONCERN CHECK ENGINE LIGHT IS ON TRUCK HAS NO POWER AT IDLE CONCERN VERIFED NO POWER AT IDLE RAN DIESE RUN CODES FOUND PC123 RUN PINPOINT TEST-REPLACED ACCEURATOR PEDAL CLEARED CODES,ROAD TESTED ALL OK

25848 MT9F638 .7 REPLACED SOP ACCELERATOR PEDAL ASSEMBLY, CLEARS D CODE AND RETESTED PASSED.

THAT SYSTEM INJURIES FRONT SPLASH SHIELD MT TO INSTALL BRAKE OUT BOX TEST AP A IVS CIRCUITSPIN POINT TO T.P.A REPLACE ASSEMBLY

COMPLETED DIAG ACCEL PEDAL HAS OPEN IN SWITCH REPLACED ACCEL PEDAL ASSY ROAD TEST GOOD AT THIS TIME 73517

12372 ACCELERATOR PEDAL TEST BEC SYSTEM KOED KOER DCL. NO CODES RAN DASIS CALLED HOT LINE PINPOINT TEST PSDAL FOUND INTERMITTENT CORN IN PEDAL. ASSEMBL'
5769 BASE WARRANTY PERFORM DIESEL PERFORMANCE. DIAGNISTICS RETRIEVE PCM MODULE CODE YKOED P1111 CONT POZ21 KOER P1111 INJECTOR P1111 CONTRIBUTION P11
27874 VERIFIED CONCERN. TESTED BEC KOED KOER CODE P0221. PP TESTS IN PCED. PINPOINTED CONCERN TO AP SENSOR, MONITORED AP SIGNAL USING GEN STAR. VERIFIED \L

INOP REPLACED ACCL, PEDAL ASSY

OUT OF SPECE EEC (QUICK TEST) OKASHOSIS

1 MT YIME FOR NO LABOR OPERTAION REPLACED ACCEL PEDAL SENSOR ASSEMBLY

7820 9F836 TIME TO CK FUEL OIL CK AIR EXCHRIT RESPICTION OK TIME TO RUN KORO KOER DCL P0221 RAN PINPOINT TE ST FE1 FE7 REPLACE PEDAL ASY ERATIC ER TEST RAD D. REPLACE PEDAL ABSY ENGINE PERFORMANCE DIAGNOSTICS 1.3L DI TURBO ENGINE DIAG

12065 PERFORM DIESEL PERFORMANCE DIAG CONTINIOUS CODE P0221 BOER P1531 RUN PIN POINT TEST REPLACE TP PEDAL ASSEMBLE

10899 ACCELARTION POSITION SENSOR RAN PERFORMANCE DIAGNOSTIC TESTS 1 TO 14 RETRIEVED CODE P0122 IN MEMORY FOUND ACCL POSITION SENSOR JUMPING FROM .55% 22962 WF 00 3 34 97695 48 VERTIED CUST CONCERN, QUICK TEST FOPUND CODE P0221, REPLACED PEDAL ASSY, CLEARED CODES, TEST DROVE OK.

14020 BF830 PEDAL42 DOES NOT OPERATE PROPERLYT ROAD TISST AND VERIFY CUSTOMERS CONCERN DIESEL ENGINE DIAG. SEE ATT.SHEETS KOED CONT.PO221 KORD DEMAN ENGINE PERFORMANCE DIAG REPLACED ACCELERATOR PEDALE

HARD TO START PERFORMED HARD START DIAG PERFORMED PINPOINT RER AP PEDAL CLEARED DTC CHARGED BATTERIESTARTED VEHICLE FINE

BHÓP M TIMÉ TO DIAGNOSE & REPLACED THROTTLE PEDAL ASSEMBLY, NO LABOR

TRUCK STALLS AT THE LIGHT'S MITTING TO REPLACED PEDALS

FOUND VEHICLE REPORTE THROTTLE AND PEDAL ASSY. CRETEST, DCL DISPALY TEST ALL FASS, MONITOR PID CK CK,D AND REPLACE THROTTLE AND PEDAL ASSEMBLY
EEC CHECKED, DID PINPOINT & DIAG. FOUND IQUE TRACKING SWITCH INTERNAL LOCSING CONNECTION INTERNALLY INSWITCH, NEED T REPLACE & RETEST. INSTALLED ACCEL PEDAL
RAN EEC TESTS,DID PINPOINT TESTS FOR CODES,FOUND ACCEL PEDAL INCP,REPLACED PEDAL ASSEMBLY, RETESTED OK.

30605 C 97435 CC 42 80037 0.2,F1 0.1,12580D1 0.2,12650D45 0.2 0.9 PLAG 108 CONCERN CUTS OUT INTERMITTENTLY, CAUSE PERFORMED DIAGNOSTICS, RAN CODES P0221 WAS RET TEST DRIVE TO VERIFY CONCERN, HOCKED UP NGS, RECIEVED CODE P0221, CONSULTED PCED POLLOWED APPROPRIATE PPT, DISCONNECT

SCAN TEST FOR CODE PO221 PERFORM DIAG FOUND TP SENOR FAULTY REPLACED PEDAL ASSY OK

SEC DIAG ON DIESEL TO FIND PO221 HARD FAULT. PINPOINT TEST AND PID MONITOR TO FIND AND REPLACE PEDAL ASSEMBLY WITH ADJUSTABLE PEDALS.

1 REPLACED PEDAL AND SWITCH ASSY.

EEC CIÁB KOEO, KOER P1111, KOEC P0221 PERFORM PPT & MONITOR PIOS FOUNDSTICKING IDLE VALIDATION SWITCH REPLACE PEDAL ASSY CLEAR CODES RETEST
NOS DIAGNOSIS MONITOR PIDS WATCH ETC TRANSITION VOLTAGE TEST SENSOR CIRCUIT AND SENSOR FOUND SENSOR INTERMITTENLY OPEN REPLACE PEDAL AND SENSOR ASSI
CHECK AND REPLACED ACCELERATOR PEDAL ASSY AND CLEARED CODES., INTERMITTANT MALIFUNCTION IN AP SENSOR, ROAD TEST, CHECK OASIS, WDS HOOK UP. PERFORM STE
RAN PERFORMANCE DIAG. GOT CODE P0122, RAN VARIOUS TEST, TEST WIRES TO POM, RECLACE ACCELERATOR PEDAL, REYEST, OK

RENTAL FOR WARRANTY WORK DONE LINE A 1 DAY

34954 CHECKED FOR NO POWER EEC TEST CODE PO221 PINPOINT TEST REPLACED ACCELERATOR PEDAL ASSEMBLY RETEST

27305 BASII WARRANTY CC 42 PP 9F836 INTERMITTENT INOP PERFORM DIBSEL PERFORMANCE DIAGNOSIS RETRIEVE PCM MODULE CODE YKOEO P1111 CONT P0221 KOER P1111 I 73 DI TURBO BIOD RUM BING PERFORMANC ETEST 1 2 3 4 8 6 7 8 PERFORM PINPOINT AND PID MONITOUR TEST CONT CODE P0221 NO CLOCK TIME COMPUTERS DOWN AGAIN OPEN CIRCUIT ELECTRONIC TRANSMISSION DIAGNOSIS DIAGNOSIS DIAGNOSIS

VERIFY CONCERNITEST AND REPLACE THROTTLE PEDAL ASSY ROAD TEST AND FOLIND CHAFFED WIRE AT STRUT BOLT REPAIRED

20041 BASE WARRANTY CC 42 FP BESS NO POWER IDLE ONLY RETRIEVE PCH MODULE CODE NKOEO P1111 CONT P0221 DCL DISPLAY IRP 9 ICP 450 ROAD TESTINGS MONITOR PINTESTED ENGINE PERFORMANCE. REPLACED ACCELERATOR PEDAL ASSY.

PERFORMED ENGINE PERFORMANCE DIAG 1 19 REPLACED ACELERATOR FEDAL ASSY, FOR KOED, KOED, KOED, PO221, TEST DROVE VEHICLE NO OTHER PROPLEMS FOUND

RAN PERFORMANCE PASSED ALL TESTS ROAD TESTED FOR 16 MILES AND CUPLICATED CONCERN 1 7ME RAN DATA LINK TEST AT THIS TIME AND APP VOLTAGE STAYED AT 2 56 Y ROAD TEST AND RUN TEST WITH WDS. CODES PO221 THROTTLE SWITCH & CIRCUIT. PERFORMANCE PINPOINT TEST QC13 TO QC 19 REPLACE ELECTRONIC THROTTLE CONTROL PER DIAG. CODE PO221. FAILED TPS. REPLACED RISTERT ROADTEST OK AT THIS

10239 WP 00 \$ 38 9F836 42 FOUND GAS PETADEL STUCKING AT TIMES, REPLACED PEDATEL, TEST DROVE, OK,

9169 RAN PERFORMANCE DIAG 1 TO 14, HAD CODE PO221, REPLACE ACEL PEDAL ASSY, CLEAR CODES & ROAD TEST O K

SHORTED WIRES AT LEFT FRONT FINDER WILL AND TP SENSOR BAD RUN WIDS DIAG. GOT CODES P0221, P1211 REPARED WIRES AT LEFT FINDER WELL BY SHOCK REPLACE THRTC AP SENSOR INOP CK W WOS AND SEC TEST AND REPLACED A PEDAL SENSOR NO LABOR OPS IN SUITS WHY MT USED

CIAG PERFORMED ALL NECESSARY TESTS CODE PO21 REPLACED PEDAL ASSESSIBLY RETESTED AND ROAD TESTED WITH MGS EVERYTHING ELSE OK AT THIS TIME, TRUCK HAS P

ACCLERATOR PEDAL STICKING REMOVED AN ROS RETEIVED CODE FOUND ACCLETOR PEDAL STICKING REMOVED AN

RAN NOS DIAGNOSTICS AND RETRIEVED CODE PO221 MADE PIN POONT TESTS AND FOUND THROTTLE ASSEMBLY TO SE FAULTY REPLACED ASSEMBLY AND RETEST ALL OK SEC YESTED CODE PO122 PINPOINT TESTED FOUND ACCEL PEDDEL BAD REPLACED RETESTED OK AT THIS TIME DIAG AND REPAIR

RAN PERFORMANCE SHEET 1 6 A,B,C,D,8 16 A,B,11 14,FOUND CODE P0122,REPLACED ACCELORATOR PEDAL ASSY,TEST DROVE DK,8844. 1 ENGINE PERFORMANCE 1 14 CODES P0122, P0221, REPLACE ACCEL PEDAL

23681 TP SENSOR 42 ROAD TEST HOCKED UP WOS RETREVIED CODES 0221 PERFORMED PIN PT TESTS PERFORMED PLEL PRESSURE TESTS (60PSI) PERFOREMD POWER BALANCE SHARED FOR THE PERFORMANCE DIAG 1 M PID DATA MONITOR I NOTALLED BREAK OUT BOX PINPOINT TEST REPLACED A CCELERATOR PEDAL ASSY RETESTED AND ROAD TESTED ALL OK PERFORMANCE DIAG 1 14 DTC P0221 PINPOINT TEST P ID DATA MONITOR REPLACED PCM RETEST DTC P0221 INSTALLED KNOWN GOOD PEDAL ASSY CK REPLACED PED AL ASSY ENGINE PERFORMANCE DIAG 1 14 CALLED HOTLINE INS. PECTED AND TAPE WIRES AT SHOCK TOWER DISCONNECT AFTERMARKET EXHALIST BREAK REPLACED PEDAL ASSY RETERMININGS DTC'S CODE P0122, REPLACE AP BENEOR AND RESET PCM, RETEST - AFTER REPAIRS, ALL OK, PART ON DOS STATUS, NECESSARY TO PURCHASE FROM BOS HOWARD I INSTALL ACC PEDAL WITH SENSOR

1 RAN DIESEL EEC TEST KOEO PASS KOEOC PO221 KOER PASS, RAN PINPOINT TEST AP SENSOR INT. (NOP. REPLACED ADJUSTABLE

RAN EEC FOUN TP LOW INPUT RUN PINPOINT FOUND FALLED TP SENSOR AND ACCEL PEDAL ASSEMBLY, REPLACED BOTH AND RETEST ALL OK.

20510 42 CHECK TRUCK AND FOUND ACCELERATER PEDAL WOULD ONLY WORK AT TIMES RUN PERFORMANCE DIAGNOSTIC TESTS 1 14.FOUND CODES 503 AND 0231,NECC TO REF. TESTED. REPLACED THE ACCLERATOR PEDAL POSITION BENSOR, OK, WHEN RETESTED.

1 NGS TESTED FOUND ACCEL PEDAL FAULTY, REPLACED ADJUSTABLE ACCEL, PEDAL.

13435 ACCELERATOR PEDAL INTERMITENT TEST DROVE AND VERIFIED CONCERN. PERFORMED DIESEL DIAGNOSIS SHEET STEPS 1.7. RECEIVED CODE P0221 FOR AP SIGNAL INTERPREPARATION DIESEL PERFORMANCE DIAG. KODO PASS,KORO P0221,P01211,KOER PASS,PERFROMED WIRE REPAIR. UPON ROAD TEST FOUND ACCELERATOR PEDAL, NOT RESP. CK ENGINE FOR NO POWER VERIFY RUN PERFRANCE DIAG 6005F 19 ENGINE HAS A INTER T.P FAILER RER PEDAL ASSEMBLY & REPLACE 7.3 D.I LASOR 6005F 19 DOES NOT OPERATE PROPERLY REPLACE ACCELERATOR PEDAL ASS

TEST DROVE TO CONFIRM CUSTOMER CONCERN PIN POINT TESTED THE PROBLEM TO THE PEDAL ASSEMBLY ASSEMBLY AND RETESTED TO CONFIRM PROPER OPERATIONS THE PEDAL ASSY, REPLACED PEDAL ASSY, REPAIRED LOOSE PIN CONNECTOR UNDER DASH TO PEDAL ASSY.

KOBO PO211, INJ BLIZZ: PASS, PUBL PRESSURB; OK, CYL CONTROL TEST: OK, KOBR: PASS, INTAKE RESTRICTION OK.

1 CHECK CODES RECIVED PO221 PREFORMED PINPOINT TEST CALLED HOT LINE REPORT#2FCF8004.FQUIND AP BILLINGS BAD FIRMOVED PEDAL FROM NEW TRUCK AND INSTALLED 12840 SEC TEST PINPOIT TEST PID.MONGOR TP SIGNAL INTERMITANT REPLACE FUEL PEDAL AND RETEST CK EEC CODE P0221

ENGINE PERFORMANCE TEST, PINPOINT TEST ON ACCID, PEDAL SENSOR, REPLACED ACCEL, PEDAL ASSY, RETEST,

DOES NOT OPERATE PROPERLY ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

PERFORMANCE WHILE DRIVING DIAG KOEC P0122 P0221 KOEC P1111 KOEC P1111 ALL OTHER TEST PASS PRIPO INT REPLACED ACCELERATOR PEDAL ASSEMBLY.CLEAR CODES.RETESTED.SYSTEM PASS.ROAD TESTE WDS DIAGNOSIS CODE P0122 P0221 REPLACE FAULTY A CELERATOR PEDAL CLEAR CODES AND RETEST.

MIL ACTIVATED LACKS POWER AT TIMES VERIFIED INTERMITTANT PERFORM ENGINE PERFORMACE DIAG STEPS 1 12 CODES KOSO PASS COTN P0221 P034C PERFORM PINPOINTS PITHFOTTLE PEDAL ASSY TESTED RIR REPLACED FAILED THROTTLE PEDAL ASSY

65 TEST DROVE AND VERIFIED, WOULD NEVER STALL COMPLETELY JUST RETURN TO IDLE, PERFORMED ALL. SELF TESTS POSSIBLE WITH THE NGS AND EVERY. THING PASSES, RUCC 28, 9F836 NGS SETUP AND EEC TEST, PC221 IN CONT. MEMORY, EEC PINPOINT TEST, DCL DISPLAY, ROAD TEST MONITOR AND RECORD, IVS SENSOR VOLTAGE DROPPING OUT IN RESPONSE FROM TPS IN PEDAL CODE PO123. PERFORM EEC TEST AND ALL OTHER TESTS NECESSARY, REPLACE PEDAL ASSY. ADDITIONAL TIME TO R. FROM STK UNIT.
YIKOEO PASS CONT PO221 KDER PASS PINPOINT NGS DCL DISPLAY AND ROAD TEST MONITOR PIDS. ACCID. PEDAL AT TIME HAS NO CHANGE IN YOUTAGE CHANGE IN TIME TO REPL

RAN ENGINE PERFORMANCE TESTS 1 20. REPLACED ACC ELERATOR PEDAL ASSEMBLY,

MO 7614, 7.\$L DI, 4R100 AUTO, CC 26, CASUAL PART 2C3Z 9F836 DA ACCEL PEDAL ASSY VERF CUST CONCERN. PERF DIESEL PERFORMANCE DIAG SHT. PERF TESTS 1 THRU 5. TEST 9229 NG8 HOOK UP, PERFORM NG8 KOEO, KOER, PERFORM NG8 MONITOR PIDS ROAD TEST, FOUND TP SENSOR TO BE OUT OF RANGE. TIME TO REMOVE AND INSTALL ADJUSTABL ACCELERATOR PEDAL ASSEMBLY FAULTY TEST DROVE AND VERIFIED COMPLAINT. EEC TESTED, RECEIVED CODE PO221, ROAD TEST AND MONITOR ACCELERATOR PEDAL PID, FOUND PIZZ1. PERFORM PINPOINT TEST AND FOUND ACCELERATOR PEDAL SENSO R TEST DRIVE PINPOINT TEST EEC TEST FOUND GAS PEDAL FAULTY REPLACE GAS PEDAL RETEST OK

ACCEL PEDAL ASSAY CODE PO21 PERFORM WOS PIN TEST DOL DISPLAY DOL MONITOR REC REPLACE ACCEL PEDAL ASSAY CLEAR CODES RETEST 97636 26 TEST DROVE VEHICLE HAS POWERINGS PERFORMANCE TESTS CODE IN MEMORY 0221 FAILED PEDAL ASSEMBLY OPEN CIRCUIT ENGINE DIAG, REPLACED TP SENSOR

BEC TEST PIN POINT TEST RAR TP PEDAL ASSM

PERFORM ELEC TRANS DIAG, PRIPORT TEST PO221, PRIPORT TEST, FE 1, FB 4, RESISTANCE OUT OF LIMITS, FAULTY

ENGINE PERFORMANCE TESTS. FOUND CODES P0221 P0122. PINPOINT TEST., DOS DOS, REPLACE BAD AP SENSOR.

DIAG. CODE PO470,P0221. ROAD TEST, PERPORMED DIESEL DIAG. REPLACED EBP SENSOR AND ACCEL, PEDAL, ROAD TEST.

5866 PEDAL AGBINGLY CC 46 EEC TEST AND RECIEVED CODE PO221 CHECK AND REPLACE PEDAL AGBINGLY AND REAGGINGLE ROAD TEST AND RETEST AND FOUND NO CODES BL

23391 NGS HOOK UP KOEC CODE PO221 PINPOINT TESTS PER H MANUAL INTERMITTANT CONCEINS WITH T.P. SENSOR AT ACCEL. PEDAL WAS ABLE TO VERIFY ORDERED REPLACE VERIFIED CONCERN AND FOUND ACCELERATOR PEDAL, IDLE VALIDATION SWITCH NOT RESPONDING, PID MONITOR APP GOOD, CHECK CKTS, IDLE VALIDATION SWITCH CAUSE OF CICE, ON EEC TEST CODE PO122 ACCELERATOR MONITOR TEST PRIPOINT TEST COMPONENT TEST OPEN CIRCUIT AP SENSOR REPLACED SENSOR RETEST.

ROADTST VERIFY EEC TST AND FOUND CODES P0221 CK PIDS PINTST OC13 OC18 A P PID ON REMOVE AND REPLACE PEDAL ASSY ROADTST RETST AND CODES PASS

HESITATES AND WONT ACCELLERATE RPL ACCELERATER PEDAL ASSY.

NGS SCAN, MONITOR PIDS, REPLACED PEDAL ASSY 1

RAN PERFORMANCE TEST 1 14, RECIEVED CODES P0123 & P0221 REPLACED GAS PEDAL ASSEMBLY AND RETEST OK.

KEY ON ENGINE OFF KOEO CHECK TEST

BEC TEST, PINPOINT TEST, DCI, MONITOR TEST, N. 98 TEST, REPLACE AND ADJUST ACCELERATOR PEDAL, REPROGRAM POM, RETEST

REPLIPEDAL ASBLY

DIAG. POUND FAULTY THROTTLE POSITION SENSOR REPLACED THROTTLE POSITION SENSOR UNDER DI POWERSTROKE WARRANTY 100.00 DEDUCT

DIAG USING NGS RUN PERFORMANCE SHEET FOUND A P ASSEMBLY OUT OF RANGE RUN PPT REPLACE A P ASSEMBLY CLEAN SYSTEM

EEC TEST FOR CODE P0221, PINPOINT TEST PER CODE, POLIND FALLTY PEDASTAL ASSEMBLY, REMOVE AND REPLACE ASSEMBLY FOR CONCERN. RECHECK AND ROAD TEST

ERRATIC OPERATION BEC (QUICK TEST) DIAGNOSIS . MT TIME TO REFL PEDAL ASSSY, COMPONENT \$F658.

EEC TEST CODE PORZI PIN POINT TEST REPLACE TO SENDSOR OK

RAN EEC TEST CETAIN CODES P0221 AND P1631, PIN POINTED AND REPLACED ACCE. PEDAL AND IVS SENSOR, CLEARED CODE AND RETEST PASSED.

TESTED KOEO FOUND P\$221 DID PINPOINT TEST FOUND TP SENSOR INOPERATIVE, REPLACED TP SENSOR THROTHE PEDAL ASSY AND RETESTED VEH TESTED OK AT THIS TIME DIAGNOSE & REPLACE TP & PEDAL

NO LIGHT ON, RUN DISL DAIG TEST, ALL OK, ROAD TEST LIGHT CAME ON, AND NO POWER, REPLIN DISL DIAG TEST, POUND CODE, #P0122 REPLICE PEDAL ASSY, CLEAR CODES, RÉRU COULD NOT VERIFY CONCERN, CODES P0122 AND P0221, PIN POINT TEST, INJECTOR BELF TEST, OUTPUT ST ATE SELF TEST, PINPOINT TEST, REPLICE ACCELERATT OR PEDAL ASS NGS SCAN, PINPOINT TEST, RR PEDAL ASSY. 1

INTERMITTANT CHERATION PEPORMED DIESEL PERFORMANCE SHEET MY TIME TO REPLACE THROTTLE PEDAL

1 VERIFIED CUSTOMERS CONCERN FOUND CODE PO221 IN MEMORY FOLLOWED PRIPORT TEST FOUND AP BENSOR GOING OPEN AT

WD6 STARTUP, KOED P0/22/PINPOINT TEST, RPL ACCEL PEDAL ASSY RETEST, CLEAR CODE AND ROAD TEST.

ENGINE WON'T RETURN TO IDLE ON ACCELERATION, CK ALL WIRING PROMACCELERATION, OK, ACCELERATOR POSITION SENSOR OPEN, REPLACE PEDAL ASEMBLY.

VERIFIED CONCERN RUN CASIS NO INFO PERFORMED DIESEL PERFORMANCE DIAG CHECK OIL OK CHECKED FUEL CONTAMINATED

SECTESTING CODES CHECK DASKS FOR SYMPTOMS, CALL HOTLINE (REPWZEGF5014) CHECK FOR CHAFED WIRING AND REPLACE ACCELER. ATOR PEDAL ASSEMBLY

9532 MIL ON, WDS CHECKS, PO221, PINPOINT TEST, NEEDS AP SWITCH, ORDERED. 77, INSTALL NEW AP SENSORA ND RETEST EEC P1000 NO MIL. ROTEST.OK

PERF DIAG., ALL OK ROAD TEST FOUND TPS INT OPEN REPLACED TPS

EEC TESTED, RETREIVED TROUBLE CODE PO221, RAM PINPOINT TEST, FOUND PEDAL SENSOR ASSEMBLY BAD, REPLACED ASSEMBLY, RAN PINAL QUICK TEST, ROAD TESTED OK.

ÉNGINE PERFORMANCE DIAG CODÉ PS221. CONTACT CABIS AND HOTLINE PERFORM SSN 15412.R À I ENGINE HARNESS AND COMPARTMENT

ACCELERATOR PEDAL SWITCH SHORTED INTERNALLY REPLACED A P SWITCH, TEST DROVE OK

RD. TEST,..INTERMITTANT NO ACELL, NGS, MONITOR PIDS, FOUND OPEN ACELLERATOR PEDAL AT TIMES... PPT, REPLACED ECCELERATOR PÉDAL AND TPS GWITCH, RD. TEST. GOOD DOES NOT OPERATE PROPERLY — EEC (QUICK TEST). DIAGNOSIS

RUN PERFORMANCE DIAGS CODE 0221 CONT RUN PARAME TER IDS PERFORM PINPOINT TESTS REPLACE ACCEL PE. DAL ASSY ROAD TEST OK

NGS TEST CODE PO221, PINPOINT TEST OC13 ROAD TEST MONITERING PIDS FOUND PEDAL TP OUT OF RANGE REPLACE PEDAL ASSY CLEAR CODES ROAD TEST OK

DEPECTIVE PEDAL ASSY. TEST EEC CODE P0221 INTERMITTEN PRIPOINT CHECKED AND REPLACED PEDAL ASSY ROADTEST.

MIL OFFIXOED PASS/KOED POZZI/(KOER PASS) PART ORDERED/ACCEL PEDAL ASSY) TEST EEC WINGS(PASSKOED POZZI/(KOEC PASSKOER) DCL DISPLAY(PASS) PINPOINT TST (NPF EEC CHECKED CODE FOR IDLE TRACKING SWITCH, DID PINOINT TO FIND INTER, OPEN, NEED TO REPLAE ACCEL PEDDLE ASSEMBLY & RETEST, INSTALLED PEDDLE ASSEMBLY & RETEST. INSTALLED PEDDLE ASSEMBLY & RETEST.

EEC TEST AP SENSOR NO SIGNAL PINPOINT TEST. MONITOR PID CATA REPLACED ACELLERATOR PEDAL ASSEMBLY REFEST OK.

7845 FUEL PEDAL ABBY 9F836 42 M TIME 5.3 VERIFY IDLE AT TIMES ONLY PERFORM DIESEL PERF DIAG ÉEC CONT CODE PO221 FOLLOW PPT CK, CALL T SCH LINE NO OTHER CONF EEC TEST DI22. PINPOINT TEST DD_NGS MONITOR OF SYST NECC TO REPL ACCEL PEDAL FOR OUT OF RANGE INT., CK WIRING

HOCK UP TO NGS PERFORM DISSEL ENGINE TESTS, CHECK FOR CODES FOUND CODE PO221, CHECK WIRING TO TP AND IDLE VALIDATION

TEST BEC CODE 0221

AP SENSAOR CASSY BAD REPLACED

PEDAL ABSEMBLY

EEC (CLUCK TEST) DIAGNOSIS, EXTRA TIME TO REPEAT FINAL QUICK TEST, PRI POINT TEST. PEDAL ASSEMBLY NOT WORKING CORRECTLY, PART ON

7755 4465 F1 ENGINE PERFORMANCE DIAG TESTS PER PCED, KOEC POSD3, KOEO PASS, KOEO BUZZ TEST PASS, KOER ON DEMAND PASS, DCL DISPLAY, RECORD & MONITOR PIDS,

EEC TEST P0221 REPLACED PEDAL GWITCH ASSEMBLY ANDRETEST PERFORM ENGINE PERFORMANCE DIAG REPLACE ACCEL PEDAL ASSY

INÓP

ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

EEC (QUICK TEST) DIAGNOSIS

TECH 1692, PERFORMED 7.31, DI TURBO PERFORMANCE WHILE DRIVIN DIAG SHEET, PINPOINT TEST, FOUND TP SENSOR IN THE FOOT PEDAL ASSEMBLY INTERMITTENT OPEN, PART ENGINE PERFORMANCE DIAGNOSTICS, REPLACED PEDAL ASSY.

HOCKED UP WIRE, NO CODES IN SYSTEM AT THIS TIME, PERFORMED DIAG. PER H MANUAL (PC ED) DIAG. PROBLEM IN ACCELERATOR REA ACCELERATOR PEDAL ASSEMBLY. INSTAL DIAG AND OVERLAYED CIRCUIT AND ORDERED PEDAL ASSY AND REPLACED PEDAL ASSY.

RAN ENGINE PERFORMANCE TESTS RAN PINPOINT TESTS FOR CODE 231. REPLACED ADJUSTABLE THROTTLE PEDALASSEMBLY, CODE 42.

14194 42 CK OUT POUND INTERMITTENT CK ENGINE LIGHT ON AND WOULD NOT ACCELL RAN DESEIL PERFROMANCE TEST FOUND ERRATIC OPERATION ACCELL PEDAL REPLACET ROAD TEST & INSPECT FOR CONCERN. EEC TEST PASS CODES, OK VERIFIED CONCERN...ACCEL SENSOR PEDAL INOPERABLE REMOVED AND REPLACED ACCEL SENSOR PEDAL...VERIFIED CONCERN FIXED

REPLACE ETC CLEAR CODES SYSTEM OK

VERFIED CONCERN PERFROME ENGINE PERFICIAL TEST REPLACED ACCELL, PEDAL ASSEMBLY CORRECTED

PIRF SEC TEST USING NGS POZZI PID MONITOR FAIL REPLACED THROTTLE PEDAL QUE TO INTERMITENT OPEN CIRCULT RETEST PASSED

1 ROAD TEST TO CONFIRM, TEST EEC, NO CODES, MONITOR PIDS AND PINPOINT TEST, REPLACE ACCELERATOR PEDAL AND RETEST.

REPLACED THE ACCEL PEDAL ASSY CLEARED ALL CODES

37064 RUN CHAGNOSTIC CHECKS AND FOLAD 0603 AND C221 CODES IN CONTINUOUS AND KOEO, ERASE CODES AND RUN PINPOINT CHECKS, ORDER NEW TIP ASSEMBLY, NEED TO 9F536 CC42. EEC TESTED FOUND CODE FOR ETC SYSTEM FAILLIRE, DIAGED PER, PCED, FOUND PAULT IN AP SENSOR, REMOVED AND REPLACED.

15594 THROTTLE POSITION SENSOR W VERIFIED CUSTOMER CONCERN PERFORMED DISEBS, PERFORMANCE DIAGNOSTICS VISUAL ENGINE INSPECTTION OK SUFFICIENT CLEAN F. 9F896 CC42 EEC TESTED, KOGO P1111, CONT P0221, KOGO P1111, PINPOINT TESTED, REPLACED ACCEL PEDAL, RETESTED ALL PASSED,

PROFORMED KÖRÖ,CONT CODES PO221 PERFORM PROPOINT TESTE MEPLACE PEDAL AND SENSOR ASSY OPEN

EEC VITESTS KOEO PASSED, KOEC POZZI, KOER PASSED MONITORED PIDS WITH NGS PINPOINT TESTS DIAGNOSED AND REPLACED ACCEL

TRESTED AND REPL SENSOR

20776 THROTTLE POBITION BENSOR W DEISEL PERFORMANCE DIAGNOSTICS VISUAL ENGINE INSPECTION OK SUFFICIENT CLEAN FLIEL PRESENT ENGINE OIL LEVEL OK INTAKE REF WOS, PRIPORIT, REPLACED TP SWITCH AND RETEST

REPLACED PEDAL ASY, VEH BACK TO SPECS

12289 VERIFIED CUST CONCERN PERFORMED EXCC TEST. RECIVED DTC FOR TIP OUT OFD SELF TESA TIRANGE PERFORMEDINGS MONITOR AND RECORD. PERFOR DIPINPOINT TES.

1. RAN CODES AND TRACED PINPOINT TESTS TO AND REPLACED THROTTLE PEDAL ASY, WITH ADJUSTABLE PEDALS.E.

PEDAL ASSEMBLY CHECK REPLACED PEDAL ASSEMBLY

PERFORMED ENGINE PERFORMANCE DIAG 1 19, NEPLACID ACCELERATOR PEDAL ASSY, FOR KOEO, KOEO PO221, TES T. DROVE VEHICLE, NO OTHER PROBLEMS POUND.

REPLACE PEDAL AND SENSOR ABBY

ROAD TESTED AND EEC TESTED. PO221 PRESENT. MONITOR PIDS. RENEWED DEFFECTIVE FUEL PEDAL ASSY PER PINPOINT TEST RESULTS.

TPS CHECKED FOR CODES AND POUND PO221 PINPOINT TEST AND REPLACED GAS PEDAL, P0221 P054 P0545.

10843 ENGINE DIAGNOSES REPLACED THE ACCELERATOR PEDAL ASSEMBLY M T 1.5

PINPOINT AND REPLACED PEDAL ASSEMBLY DIAG NO CODES SET UP AND MONITORED PIDS FOUND AF OUT OF SPEC REPLACED PEDAL ASSEMBLY AND RETESTED, EVERYTHING EL 22870 FAULTY ACCELERATOR PEDDAL 6008F.2F1.1F1X.1F2,1F7,2F4.1F3.3F10,1F11,2F12, 3F13.1F14.1F16.6F17.5F18.5F16.2, 2450F.4 VERIFIED CONCERN DIAG PID TEST PO221 PIN PION ACCEL, PEDAL FAILED, COOR PO221 ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

VERIFIED INTERMITTANT NO THROTTLE RESPONSE, PERFORMED DIT TEST, CODE 0220 IN MEM, REPLACED PAILED ACCEL PEDAL, QUALITY TEST CK.

FAULT CODE PO221 , NEED TO REPLACE BLECTRONIC THROTTLE CONTROL ASSEMBLY & RETEST REPLACED ELECTRONIC THROTTLE & ROAD TEST WITH CUSTOMER CLEAR CODES EEC PINPOINT MONITOR ROAD TEST FOUND PROAL ASSY SHORTED RIR PEDAL ASSY

20922 WARR T 414 PERFORMED DISSEL CIAG 1 14 FOUND TP SENSOR INOP HAD TO RIR GAS PEDAL ASSEMBLY RETESTED OK AT THIS TIME ALSO FILLED OUT DIAG SHEET QUALITY

EEC (QUICK TEST) DIAGNOSIS

FAILED AP SENSOR INT TIME ABNORMAL DIAGNOSIS TIME OF INTERMITTENT FALLT.

ENGINE PERFORMANCE DIAGNOSTICS 7.3% DI TURBO ENGINE DIAG

17024 WF 00 5 55 97635 42 RAN QUICK TEST FOUND CODE P0221. REPLACED GAS PETADEL, GLEARED CODES, TEST DROVE OK.

DIAGNOIS WIDS HAS CODE PO221 PIN POINT THAT REPLACE PEDAL ASSEMBLY RETEST CLEAR CODES ROAD TEST 1 ECC TESTED RETRIVED CODE P0123 PIN POINT TEST TRACED TO ACCELERATOR PEDAL REPLACED PEDAL ROAD TEST RETEST CORRECTED

24482 42 SFB38 VERIFIED CHECK ENGINE LIGHT ON VEHICLE AT TIMES WILL ONLY IDLE BEGIN PERFORMANCE SHEET VISUAL OK OIL OK FUEL OK UBTAKE RESTRICTION OK KORO P EEC TEST DOLTEST REPLACE PEDAL ASSEMBLY PER HOT LLINE

VERIFY CHECK ENGINE LIGHT ON VIBH HAS CODES FOR PO238 AND OVERBOOST CODE P1211 AND HIGH ICP P RESSURE VEH HAS AFTERMARKET PCM AND MISSING GROUND STSA. ACC PEDAL ABBEM REPLACE ACC PEDAL ASSEM

EBC & TEST, PERFORM PIN POINT TEST, REPLACE TP SEMBOR, TEST DRIVE OK, RETEST OK

DIAGNOSE CODE P0221, PIMPOINT TEST, NECESSARY TO ROAD CHECK AND MONITOR IVS, FOUND INT OPEN, REPLACE ACCLERATOR PEDAL, RETEST, PASS

GAS PEDAL NOT RESPONDING. CHECKED FOR CODES FOUND PO21 PINPOINT TEST AND FOUND TP SENSOR OUT OF SPEC FE1 TO FE7, MT TIME TO REPLACE GAS

ACCULL PEDAL DIAG, ROAD TESTS, REPLACE PEDAL ASY

TEST WITH WOS CODE PO221 PEPLACED THROTTLE PEDAL ASSEMBLY QUE TO BAD T.P.SENSOR

MOP

ENGINE PERFORMANCE DIAGNOSTICS 7.3L D. TURBO ENGINE DIAG

EEC (QUICK TEST) DIAGNOSIS

RAN EEC TEST AND FOUND CODE P221. PINPOINT TEST GE1 CHECKED PEDAL SWITCH IT SHOWED OFF ALL THE TIME.

AP SENSOR INTER, FALURS, PERF DIAG, KOEC PASS, KOER PASS, KOEC PC221, INJ EL PASS, CCT PASS, PINPOINT TEST, REPLACED AP ASSY, CLEARED, ROAD TEST, RETEST 14503 VERIFIED THE CONCERN ON TEST DRIVE. PERFORMED DIESEL DIAG SHEET STEPS 1 6. FOUND CODE P0221 FOR AP SENSOR 8+ MALIFUNCTION: PERFORMED PINPOIN TITEST EEC TEST REPLACCEL PEDAL ASSY

REPLACED ACCELERATOR CARLE., ROAD TEST, WOS HOOK UP, PERFORM STEPS 1 8 1999 DI PERPORMANCE DIAGNOSIS SHEET, RETRIEVE DTC P0221, PERFORM PINPOINT TESTS F 1 VERIFY CONCERN PERFORMED DISSEL DIAS, WORKSHEET AND REPL ACCELERATION PEDAL ASBY, ROAD TEST RETEST OK NOW

ÉEC TÉST METRUEVED CODE POZI 1. PINPOINT TÉST SHOW BAD PEDAL ASBEMBLY, REPLACE PEDAL ABSEMBLY, RE TEST, OK.

WFF TEST SYSTEM, ORDERED AND REPLACED PEDAL ASM WITH SENSORS, TEST DROVE, OK NOW.

REPLACED THOTTLE PEDDLE

TESTED COULDN'T VERIFY BUT REPLACED THROTTLE PEDDLE ASSYRIA

ACCELERATOR PEDAL INOP ENGINE DIAG TESTS, REPLACED ACCELERATOR PEDAL

OPEN CIRCUIT

EEC (QUICK TEST) DIAGNOSIS

1296 VERUPIED NO THROTTLE RESPONSE. CHECK CASIS. WOS DIAG CODTC PASS, CMDTC PC221, PINPOINT TEST TP SNSR CKTS OK.

21084 CHECK OUT, VERIFY CK ENGLITE ON, PERFORM 7.3L DI DIAGS, KORG P0225, PERFORM FUEL BYSTEM TESTS , ALL FUEL TESTS PASS, PINPOINT TESTS FOUND TH SENSOR 8 VERIFY CHECK CASIS PERFORM DIT PERFORMANCE DIAG VISUAL CHECK SICK KOED TEST PASS KOED TEST POZZA KOED INJ TEST PASS CHECK

CIAGNOSE AND REPLACE PEDAL.

REPLACE PEDAL ASSY

VERIFIED CONCERN, PERFORMED DIESEL DIAG. FOUND FAILED PEDAL AND SENSOR ASSY, REPALCED, OK NOW

DIAGLHAD THROTTLE AT TEST TIMELESC CHECK SYS,CODE P0221,MONITOR AP VOLTAGE WHILE WIGGLE HARNESS OK AT THIS TIME,HOOK UP BREAK OUT BOX,CHECK AP VLTAGE A NGS FOR CODE FOUND CODE P0221 MONITORED PIDDS FOUND TP INOP INSTALLED NEW AP ASSEMBLY MADRE CONNECTIONS AND CHECK OPERATION OF ADJUST PEDAL STARTED TEST EEC CODE POORT, PRIPORT TEST AND FIND INTERMITTINT TO SENSOR, REPLACE TO SENSOR ASSY AND RETEST, PASS.

15273 TP SENSOR FAILURE 5005 F 0.2 F1 0.1 F1X1 0.1 F2 0.1 F6 TO F14 1.5 F16 0.5 F17 0.5 12850045 0.3 D80 0.3 D81 0.5 TOAL 4.2 HRS SUFFICIENT CLEAN FUEL AND OIL LEVEL OK INTA CK ENGINE LITE ON, NO POWER ON ACCERLATION ROAD TESTED VERIFIED CONCERN, PERFORMED DIESEL PERFORMANCE TESTS, FUEL PRESSURE 63 PSI, BOOST 17 PSI, RECIEN TEST DROVE ENGINE DEFAULT TO JULE INTERMIT NOS TEST NO CODES FARTHER DIAG FINDS FAULTY JULE VARIATION SWITCH TPS ASSY

EEC SYSTEM DIAG, MONITOR ROAD TEST, PINPOINT TESTS, REPLACE THROTTLE PEDAL PER HOTLINE(9F836).

PER3-844 32243

TP SENSOR SHORTED OPEN 7.31, D) 4XX AUTO RUN PERFORMANCE DIAG.1 14,PINPOINT TEST CODE POZZY, REPLACE FUEL PEDAL ASSY, CLEAR CODES, RETEST, ROAD TEST, OK PEDAL ASSEM

ENGINE PERFORMANCE DIAGNOSTICS 7.31 DI TURSO ENGINE DIAG

ROAD TEST, NO RESPONSE FROM AP AT TIMES, MIL PLASHES, RAN ENG PERF DIAG, HARD FAULT AP CODE, REPLACED AP ASSELBLY, ROAD TEST, DK.

SAST WAS UNABLE TO VERIFY NO THROTTLE RESPONSE AT THIS TIME, CONNECT SCANTOCK AND PERFORM KIDD TESTS, UNABLE TO PERFORM ON DEMAND TESTS PLIE TO INSTAPREFORM DIAG WIDS FOUND AP CODE PO123 PINPOINT TEST INSTALL BREAKK OUTBOX, TEST ALL CURCUITS ALL OK ROAD TEST MONITOR AP SIG FOUND INTERMITTANT REPLACE
ENGINE PERFORMANCE DIAGNOSTICS 7.SL DI TURBO ENGINE DIAG

VERIFIED AND REPLACE TROTTLE

13802 SENSOR FAILURE 6008F-2F1.1F1X1.1,2480A.2 VERIFY CONCERN,DIAG,PID, PINPOINT TRST R R AND REPLACE ADJUSTABLE ACCEL PEDAL. CLEAR CODES,RETEST AND ROAD TI

PERFORMED KOEC CONTITIEST CODE P0270 PINPOINT TEST PE 1 PERFORMED KOER SWITCH TEST CODE P0221 ENTER PIDS TEST IVS READS ON RE 7 DISCONNECT IVS CONNECT REPLACED DUE VALIDATION SWITCH

VERBFIED RAN ENGINE PERFORMANCE 1 THRU? CODE P 0221 PINPOINT TEST CC13 QC19 REPLACED ACC PEDAL ASSEMBLY CLEARED CODES AND TEST DROVE OK

TESTED REPLACED THE ACCLUMATOR PEDAL ABSENSLY OK WHEN METESTED

RAN NOR DOL TOTS TRACE FAULT TO BAD TO SENSOR REPLENTIRE ADJ PEDAL ASY MT NO LABOR OF

28430 ROAD TESTED WAS UANBLE TO GET THROUTLE PEDAL TO BE INOP CUSTOMER STATE AT TIME DRIVING DOWN ROAD ENG WOULD RETURN TO IDLE TO UANBLE TO GIVE AN EEC (QUICK TEST) DIAGNOSIS

CHECK CODES POZZI, POZZI FORIND PRIPORT TEST, FOUND ACC PEDAL POSS SENSOR AT FAULT, REPLACED APP RETEST ALL PASS TEST DRIVE ALL CK NOW CONCERN VERIFIED CUSTOM STATED THAT RPM WOULD NOT GO ABOVE IDLE AND CK ENGINE LIGHT CAME ON HOOK UP NOS AND RUN EEC V QUICK TESTS, P0122 IN MEMORY TS C CONCERN VERIFIED, CUSTOM STATED THAT RPM WOULDN'T GO ABOVE IDLE & CK ELIGHT CAME ON, RUN QUICK TESTS, RUN PINPOINT TEST, REPLACE ACCEL, PEDAL ASSY. AS PEI PERFORMED DIAGNOSIS AND FOUND FAULTY ACCELERATOR PEDAL.

7817 PROFESS DESEL PERFORMANCE DIAG KOED TEST. CODE 8221 FUEL CONTAMINATION PASS INTAKE RESTRICTION PASS PINPOINT TEST, FAILED PEDAL ASSEMBLY REPLACE RAIN PERF TEST THROUGH STEP 10 B REPL PEDAL ASSY RETEST PASS

SATIME FOR ABNORMAL DIAG DUE TO INTERMITTENT CONCERN. INSTALLED NEW EPR SENSOR

TESTED AND REPLACED PEDAL AND SENSOR

SEC (QUICK TEST) DIAGNOSIS

VERIFIED CONCERN, CHECK POR CODES REPLACED ACCELERATOR PEDAL ASSEMBLY, RECHECKS OKAY

TECHNICIAN REPLACED AUTO PEDAL ASSEMBLY AND RET EST OK

12382 42 CK OUT FOUND ENGINE WOULD NOT ADOBLE AT TIMES RAN DESEIL PERFROMANCE TEST FOUND ERRATIC OPERATION ACCELL PEDAL REPLACED PEDAL RETEST ALL OK CHECK ENGINE LIGHT ON PEC (QUICK TEST) DIAGNOSIS FOUND ACCEL PEDAL DROPS SIGNAL, REPLACED ACEL PEDAL AND SNS ASY, RETEST CK

PERFORMED DIAG FOUND CODE PO221 PERFORMED PIN POINT TESTS PERFORMED WIRING PIN POINT TESTS AS PER MANUAL CHECKED RES

TESTED FOUND CODE 321 REPLACED THROTTLE PEDAL ASSEMBLY ROAD TESTED OK

4503 CONDUCT PERFORMANCE SHEET AND FOUND CODE P0221 PINPOINT TEST FOR CODE AND REPLACE THE A P. SWITCH PEDEL ASY.CLEAR CODES AND RETEST. RAN. CASIS AN 17/18 9F836 WAR ROADTEST MILLIGHT ON AND LOSS OF PEDAL RESPONSINGS SELF TEST 1 FAULT IN SYSTEM P0221 PINPOINT TEST ON AP CIRCUIT FOUND LOSS OF SIG RTN O.C. 14/15 ACCELERATOR PEDAL ASSY 6005F,F1,2,6 14,16 18,1X1,9F636 PERFORMANCE DIAG.,CODE 0221,PINPOINT TEST, RAR FAULTY ACCELERATOR PEDAL ASSY.ROADTEST, RETEST. MGS TRETED, RETRIEVED CODE 122, PERFORMED, PINPOINT TESTS. FOUND FAULT IN ACCEL PEDAL. REPLACE PEDAL AND ROAD TEST.

EMERGENCY REPAIR VEH LOST THROTTLE CUSTOMER INSTALLED PART UNDER WARRANTY

PUEL PEDAL FAILURE, PERPORNED DIRREL CHARNOSTICS, TIME NEEDED TO REMOVE AND REPLACE PEDAL AND BENSOR ASSY...

VERTIED CUSTOMER CONCERN RETREIVED CODE POIZ2 PERFORMED PINPOINT TEST REPLACED ADJUSTABLE PEDAL ASSEMBLY AND RETESTED OK AFTER REPAIRS TRUCK HAS NO THROTTLE; THROTTLE SWITCH NOT WORKING PROPERLY: RER SWITCH

FAULTY PEDAL ASSY PERFORMED EEC TEST FOR LOW 1015, CODE P0221 PRESENT, PERFORM DC2, RECORDER MONITOR WITH MGS. IDLE VALIDATION SWITCH
10224 CBUT BTATES WHEN ACCEL VECH GOES SACK TO IDLE INSPECTED AND CONFIRMED XX PERFORMED EEC TEST AND FOUND OK XX CHEKÇED AND FOUND APP OK XX CHECK
1804 TRK LOSING THRUTTLE RESPONSE INTERMITTENTLY, TEST POED FOLIND THROTTLE ASSY DEFECTIVE, REPL. ROAD TEST, OK.

REPLACE THROTTLE PEDAL ASSY

6404 42 ROAD TEST, COULD NOT VERIFY CONCERN, PERFORMANC E TESTS 1 9, CODE PRZ21 CONT. MEMORY, PINPOINT TEST, REPLACE THROTTLE PEDAL ASSY, RERUN NGS TE 57 T P SENSOR HOCK UP TO NGS PERFORM DIESEL ENGINE TESTS, NO CODES IN SYSTEM, ROAD TEST WITH NGS AND MONITOR PIDS, FOUND T P

PERFORM DIAG, PIN PT YEST, REER ACCEL PEDAL ASSY RECK OK

VERFY CONCERN MILLIGHT ON KOEC P0221 FOLLOW PINPOINT STEPS FE1 FE7 RE

TECH 1892, PERFORMED 7-SL DI TURBO PERFORMANCE WHILE DRIVING DIAG SHEET, FOUND TP SENSOR INOP, REPLACED THE FOOT PEDAL ASSEMBLY, WITH ADJUSTABLE PEDALS NGS SYSTEMS TEST PIMPOINT TEST REPLACE GAS PEDAL SENSOR

1 PERFORMED DIESEL DIAG WORKSHEET ALL TEST PASS TO KOER CODE POSS1 MONITORED PIDS PASS PERFORMED PINFOINT TEST

1985 PERFORMANCE WHILE DRIVING DIAG. CODE PO122, ALL OTHER TEST PASS. FOUND ACCEL PEDAL INTERNAL. FAILURE, REPLACED ACCELERATOR PEDAL ASSEMBLY ROADTE REPLACED ACCEL PEDAL ASSY MEC (QUICK TEST) DIAGNOSIS

MT TO DIAG DIESEL BYS AND REPLACE PEDAL ASSY

TP SENSOR OPEN CIRCUIT INTERMITTENT, DIESEL OMG STARY UP. KKOEO TEST PO221, PINPOINT TEST PO221, CANT USE 12540045 AND 12850081 WITHOUT 12650D. NGS MONITOR F CHECK AND REPLACED PEDAL ASSY

10365 PERFORMANCE WHILE DRIVING DIAG, KOBO, KOBN, CYLINDER CONTRIBUTION, INJECTION BUZZ TEST, ICP TESTS, CRANKCASE PRESSURE TEST, EXHAUST AND FUEL INLET # REPLACED ACCELERATOR PEDAL ASSEMBLY.

FILIN PERFORMANCE CHECKS P0221 CHECK WIRING HARNESS FOR SHORT FORM PEDAL TO PCM REQUIRED SHORT LOOSE FIN CONNECTOR AT PCM REPLACED ASSEMBLY

, MIN POINT TEST, INGS MONITOR ROADTEST, ACCELERATOR PEDAL, HAVING INTERMITANT OPEN INSENSOR, REPLACE AS WHOL ROAD TEST, QUICKTEST, PID DATA DISPLAY. 5312 CONDUCT PERFORMANCE SHEET EVALUATION AND ORDER A NEW AP SWITCH INSTALL A NEW ACCEL PROFE ASY OR AP SWITCH CLEAR CODES AND RETEST. DIAG AND RPL GAS PEDAL ASSY

42 PERFORM DI DIAG STEPS 1 14 CHECK AIR, PUBL, OIL OK RAR IVS SENSOR AND RETEST OK PASS

\$2220 DIAGNOSIS TRANS ERATTIC SHIFTS JOUICK TESTED KOEC PO731, PINPOINT, FOUND STATTIC TP SIGNAL REPLACED ACELL PEDAL ASSY RETESTED OK 23905 TP SENSOR 25 W ROAD TEST VEHICLE LOOSES ACCEL SIGNAL, PERFORMINGS SELFTEST HAS CODES POLZZ PIZZ 1, FOR TP SENSOR, PERFORM PINPOINT. TEST, MONITOR PI AP SWITCH PASS DIAGNOSIS 1 14 REPLACED AP SWITCH

AIP SESS ACCELERATOR PEDAL SPR WADES RUN DIAG STEPS 114, REPLACE ACCELERATOR PEDAL

FALLTY ACCELERATOR PEDAL DIESEL DIAGNOSIA STEPS 1 14 AND REPLACED ACCELERATOR PEDAL

RUN DIAG TESTS, REPLACE PEDAL ASSY

9566 VERIFY MIL & LACK OF POWER PERFORM DESEL PERFORMANCE CHASNOSIS PER PC ED KOED KOER P0122 P0221 "AP IV SWITCH, CK KCP, CK BOOST, CK PUEL AIR EXHALIST : PERFORMED DIESEL DIAG SHEET, 1,2,3,4,5,6 AND 9 FOUND TP OR PEDAL ASSEMBLY OPEN REPLACED ASSEMBLY ANDRETESTED

PERFORM DIAG TESTS, REPLACE PEDAL ASSY

RAN PART OF PERFORMANCE DIAG SHEET DTC P0221 THROTTLE SWITCH B CIRCIT PERFORMANCE WENT PC ED MANUAL DTC SENT TO PINPOINT REPL ACCE. PEDAL ASSY INTER (CUSTOMER & DEALER/TECH COMMENTS ARE REQUIRED FIELDS OF ENTRY. SHORT IN HARNES RER WIRING HARNESS AND TRACE FOR OPEN IN HARNESS TO APADLE VALIDATION.

REPLACE ACC PEDAL ASSEM PEDAL ARGENI

RAN BINGINE PERFORMANCE DIAGNOSIS, CODE 0221 PRESENT, FOLLOWED PINPOINT TESTS, REPLACED ACCELERATOR PEDAL ASSEMBLY, ROAD TEST CONNECTED TO SERVICE BAY DIAGNOSTICS, RETREIVED CODE POZZI, INDICATING AN IDLE VALIDATION SWITCH, REPLACED IDLE VALIDATION SWITCH LOCATED ON THE FUEL PEDA VERIFIED CUSTOMERS COMPLAINT PULLED CODE PIZZ1 WIRING CONEUTOR HARNESS ERATIC SIGNAL RETURN ON ACCEL PEDAL REPLACED PEDAL CHECK WIRING VOLTAGE.39.41

4016 42 CK OUT FOUND ENGINE CUTTING OUT ON ACCELL TIME TO RUN DESEIL PERFROMANCE TEST FOUND ACCELL PEDAL ERRATIC OPERATION REPLACED PEDAL RETEST ALL O VERIPHID CUSTOMERS CONCERNIPHIFORMED INSPECTION AND PIN POINT TEST, FOUND THAT THE GAS PEDAL ASSY IS FAILING, REPLACED AND RECHECK, OK. 10750 41 VERIFY CUSTOMER CONCERN, PERFORM DIRSEL PERFORM ANCESHEET STEP 1 TO 5 AND PULL CODE PD221, PERFORM PINPOINT TEST AND FOUND TO SENSOR, INCP AT PERFORMED DIESEL PERFORMEANCE DIAG 14 PULLED CODES MONITORED PIDS REPLACED ACCELERATOR PEDAL CLEARED CODES RETEST VEHICLE OPERATES PROEPRLY INTERMITTENT OPEN CIRCUIT - DIESEL DIAG START UP KOEG TEST POZZI PINPOINT TEST CODE 221 NGS MONITOR TEST TO WATCH AP SIGNAL & IDLE VALIDATION SWITCH REPL VERBY COMPLAINT OF NO THROTTLE PEDAL PERFORM DIESEL PERFORMANCE CHART FOUND CODE 122 FOLLOW: PINPOINT TEST TFOR THIS CONDITION REPLACE. THROTTLE PED , OC CHECK VERIFY NO DTCS AND NO CHECK ENGINE LITE ON, ACCRLL PEDAL WORKS AT ALL TIMES.

EEC (QUICK TEST) DIAGNOSIS

DEPECT THROTTLE POSITION SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

- 1 CHECKED FOR CODES WITH WOS HAD CODE PO122 FOR TP SENSOR TEST DROVE AND MONITORED SENSOR FOUND SENSOR
- 1 PERFORMINGS TEST, CODE POZZI, PIN POINT TEST, DIAG AND REPLACCELORATOR ASSY

RUM TEST PRZZI ACCEL PEDAL CODE REPLACE ACCEL FEDAL ASSEMBLY, CLEAR CODE, ROAD TEST OK VIRRIFIED, WIDS HOOKLIP, DOLLDISPLAY, PINPOINT TES IT, FOUND THROTTLE POSITION OPEN, RER PEDAL ASSY ALL OK ENGINE PERFORMANCE, KOEO, PINAL, QUICKTEST, KOER, INJECTOR TEST, ICP, LOW IDLE, CRANKCAGIE PRESS, CYLINDER CENTRI, EXHAUST RESTRICT, SOOST PRESS, FUEL CONTAMIN, RAN DIAG, FOUND LOSS OF TP MIGNAL. 20200 NGS HOOK UP PERFORMANCS DIAG. SHEET CONTINUOUS CODE P0221 PINFORM TESTS PER IN MANUAL FOUND ACCEL, PEDAL SENSOR INTERMITTANT ORDERED: PART CUS RUN WOR DIAG. FOUND CODE, P0221, PINPOINT TEST, FOUND ACCEL PEDAL ABBY NOT WORKING PROPERLY 6FAMB 42 CC M O 6263 VERIFIED CONCERN, NGS SELF TEST EEC SYSTEM, CODE P0122, PIO MONITOR ROADTEST, FOUND AF SIGNAL CHANGING, PINFOINT CAUSED BY ACCELERATOR SOLENOIDE ACTUATOR. REMOVED AND REPLACED ACCELERATOR SOLENOIDE ACTUATOR TEST IT AND EVERYTHING WAS OK, AT THIS TIME. DEFECTIVE ACCEL PEDAL ASSY, PERFORMED DIESEL DIAG AND REPLACED ACCEL PEDAL ASSY, CLEANED CODES, ROAD TEST, RETEST, PASS. WIDS DIAGNOSIS P0221 PINFOINT TESTS QC13 QC16 PID MONITOR REPLACE PEDAL ASSY, MITMAE NO SLTS CLEAR CODE & RETEST PASS PEDAL ASSEMBLY OPEN CIRCUIT DIESEL DIAG START UP KOED TEST POZZI PINPOINT CODE 221 REPLACE TP ASSEMBLY RETEST FASS 8395 TEST DROVE AND COULD NOT CONFINAL USING NOS CHECKED CODES AND COULD FIND NONE IN CONT. MEMORY, KOSO AND KOER TEST ALL PASS, TEST DROVE WHILE MO! PERFORM DIESEL DTO 0221 REPLACED PEDAL ASSEMBLY ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG CODES POSOS POSSS1; KOEO TEST PASS; NURCTOR TEST PASS; 1 PERFORMED ENGINE PERFORMANCE DIAG SHEET #1 10,000E P0221, RAR INTERMITENT PAILED THROTLE PEDAL ASY, PERFORMED QUALITY REPLACED PEDAL ASSY. ENGINE HAS NO THROTTLE PERFORM NOS DIAG. CODE PO221 FOLLOW PPT. IDLE VALIDATION SWITCH IS ERRATIC, R & R PEDAL ASSY AND RETEST ERASE CODE. REPLACE ACCEL PEDAL SENSOR CK DIES WHILE DRIVING PERFORM ENGINE PERFORMANCED DIAG 512P6 1 2 3 4 5 8 7 P0221 PINPOINT TEST AND REPLACED THRTTLE PEDAL ASSY RETERDT INSPECT FOR NO ACCS), EEC TEST, CODE P021, MONITOR PIDS PIDS OK, PINPOINT TEST, PPT LEADS TO PCM THAT HAS SEEN REPL. REPLACED PEDAL ASSEMBLE(TP SENSOR) CLI

ENGINE PERFORMANCE CLAGNOSTICS 7.3L DI TURBO ENGINE DIAG

17294 TEST DROVE, TRUCK HAS NO POWER AT TIMES PERFORMED EEC TEST, NO CODES PERFORMED PIN POINT TEST, BAD ACCELRATOR PEDAL, RR ADJUSTABLE PEDAL, RETES ACCELERATOR FEDAL, SENSOR ASSY DEFECTIVE INTERNAL SHORT DIAGNOSE, FOUND CODES FOR PEDAL SENSOR ASSY REPLACE PEDAL ASSY, RETEST ROAD TEST OK

REPLACE ACCEL PETAL AGGY, AND RETEST SYSTEM PASSED, ROAD TEST VECHICLEWORKING PROPERLY, MITIME ASK OF 3 TO RUN PIN POINT TEST NA1 &

RAN PERFORMANCE SHEET ALL PASS CODES CHECKED PID POUND IDLE VALIDATION SWITCH INTERMITTENTLY NOT TURNING ON NO CODE SRT REPLACED IVS PER PINFOINT TEST
REC TEST POISS PINPOINT TEST REPLACE ACCELL PEDAL SENSOR OPEN REPLACE ASSEMBLY M YIME NO OPERATION RETEST P1000

13862 CHECK OUT, VERIFY DOBENT WANT TO ACCEL AT TIMES, PERFORM 7.5L DI DIAGO, PERFORM FUEL SYSTEM TESTS, ALL FUEL TESTS PASS, PRIPOINT TESTS, ALL CODES P11
1 EEC TEST REPLACED AP SENSOR CLEARED COORS

DEFECTIVE PEDAL ASSY CC42 ADDRESS CONCERNIDIAGI PERFORM DISSELDIAGI 1 14 REPLACE ACCELERATOR PEDAL ASSY TEST DRIVE

OPEN CIR SELF TEST CODE PO221.TEST PEDAL ASSY FOUND OPEN CIRREPLACE PEDAL

CK BEC SYSTEM, YKOEC POZZI, PLAPOINT TEST, MITME TO REPLACE GAS PEDAL SENSOR ASSY FOR CK ENGINE LIGHT ON CONCERN

TEST & DIAG., P1111 10 P0221 PINIONT YEST TO TP WITH ACELL PEDAL BENSOR .. REPLACE & ROAD TEST & RETEST.. ALL PASS CODES, MT TO REPL SENSOR

INSTALLED SOP PEDAL ASSEMBLY. RETESTED SEC V KOED PASSED, KOEC PASSED, KOER PASSED, SEE PREVIOUS RO FOR DIAGNOSTIC TIME AND

17363 W8644 PERFORMED TEST 1 14 FOUND OTC P0221 PERFORMED PIN POINT TEND INTERMITTENT OPEN IN PEDAL SWITCH REPLACED PEDAL ASSEMBLY RETESTED OK AT THIS T

INOP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

CONNECTED TO WOS FOUND CODE FOR TP SENSOR REPLACED THROTTLE PROAL FOR REPAIRS TESTED ALL CK.

8417 ROADTEST VERIFY VEHICLE WILL, NOT MOVE MIL ON, PERFORM ELECTRONIC TRANS TEST, RECIVED PO221 PINPOINT TEST FOUND THE SENSOR BAD. PERFORM PINPOINT TEST ROADTEST TO VERIFY CONCERN, SEC TEST, FOUND COOS PO221. PERFORMED PINPOINT TEST FOR CODE, REPLACED FAULTY PECAL AND SENSOR ASSEMBLY. CLEARED CODE AND MIL WAS ON RAN BELF TEST KOEC PO224 503 RAN PINPOINT TEST FOUND THROTTLE PEDAL SWITCH OPEN INTERNALLY REPLACED THROTTLE PEDAL ASSY CLEARED CODES ROAD.

VERIFIED ENGING LOGGES POWER, FEELS LIKE VEHICLE TURNS OFF TEST DROVE WITH CUSTOMER VERIFIED SYMPTOM WOT SENSOR SHOWED TO BE AT IDLE AT WOT REPLACED I VEHICLE WILL NOT ACCELERATE, FOUND THROTTLE SENS OR FAILED, REPLACED PEDAL ASSY AND ROAD TEST.

TECHNICIAN COULD NOT VERBY CONCERN TECHNICIAN REPLACED PEDAL ASSEMBLY
TESTED SYSTEM OTC'S PERFORMED PINPIONT TESTS REPLACED ACCELL, PEDAL, RETESTED & ROADTESTED OK

RAR PEDAL ASSEMBLY, TEST DROVE UNABLE TO HEAR ANY CLICKING NOISE

VERIFY, EEC TESTED, PINPOINT TESTS. FOUND IVS SWITCH OUT OF NAMOS, REPLACED ACCELERATOR PEDAL ASSY, ROAD TEST, RETEST OK

CHECK ENGINE LIGHT IS ON DIES. COMPLETED EEC TESTS WITH NGS TO VERIFY COMPLAINT REMOVED AND REPLA

13855 REPLACED IVE OF REPLACED THOTTLE IVE ROAD TEST CK. HAVE SOP PART ON ORDER IVE FOUND PCM UPDATE PART NUMBER 20SF 12A650 DE REPROGRAMED PCM

JULY TEST WINGS KOED GOT CODE 0221, RUN PINPOINT TEST REPLACCEL PEDAL ASSY RETEST P. 1000

COMPRISED CONCERN RANINGS TEST AND TESTED TPIRA INGE SENSOR INDP, RIPEDAL ASSY AND TPISENSOR RIPESTED GOOD

FLIEL PEDAL AT PAULT DIAGNOSE CONDITION, REPLACED FUEL PEDAL CIK

DEFECTIVE ACCELERATOR PEDAL ASSY BEC (QUICK TEST) DIAGNOSIS

PCM AND THROTTLE BODY REPLACED.

PEDAL ASSY FAILURE, TIME NEEDED TO REMOVE AND REPLACE PEDAL ASSY., NO APPLICABLE LABOR OPERATION

ECC AND PINPOINT TESTS NOS DISPLAY REPLACED PEDAL AND SENSOR ASSEMBLY AND RETESTED

CIESSI, PERFORMANCE DIAG, 1 14 PINPOINT TEST, REPLACE ACC. FEDAL ASSEMBLY RERUN CLUCK TEST CLEAR CODES, REPROGRAM PCM

INSPECT & DIAGNOSIS & REPLACE THE IVE PEDAL ASSEMICLEAR CODE POSS IN TIME TO REPLACE IVE PEDAL

3873 PRIOR DIAG HER SE VI NEC TO REPLACCEL PEDAL POS SENSOR ASY RECD WRONG PART NEC TO REORDER X WHEN ATTEMPT TO HERE SELF TEST FOUND NO COMMUNICAL VERIFY COMPLAINT OF NO THROTTLE RESPONCE FOLLOW PINPOINT TEST REPLACE THROTTLE PEDAL THIS IS A ADJUSTABLE PEDAL.

SCAN AND RETREIVE CODES PROM BLECTRONIC CONTROL SYSTEM/2221 PROM. ASSEMBLY CIRCUIT CONCERN. ENTER PPT OC 18 & CONCLUDE REPLACE PEDAL ASSEMBLY, CLEARUN NOS TEST POZZ1 MONITORED AP INTERMITTENTLY OPEN REPLACE GAS PEDAL ASSY RETESTED PROBLEM SOLVED

CEC TESTED REPLACED ACCUL, PEDAL ASSEM, MITME NO SLITS

VERIFIED CONCERN PERFORMED EEC TESTS FOUND CODE POZZ1 AP SIGNAL FAULT PERFORMED PID MONITOR FOUND AP SIGNAL REMOVED AND REPLACED ACCUSTABLE ACCELEF THROTTLE PEDAL ASSEMBLY INOP — EEC (QUICK TEST) DIAGNOSIS, EXTRA TIME TO REPEAT FINAL QUICK TEST, PINPOINT TEST, REPLACE THROTTLE PEDAL ASSEMBLY TESTED REPLACED ACCEURTATOR PEDAL.

14611 WARRANTY BEC TESTED, COOR P0221. ROAD TESTED AND MONITOR ED PIDS, PINPOINT TESTED, FOUND TO SENSOR INTERMITTENTLY OPEN. REA ACCELERATOR PEDAL ASY 12956 RAN EEC TEST RAN KEY ON TEST CODE PO123 RAN CYLINDER CONIBUTION TEST RAN GOOST TEST RAN FUEL P51 IN 807H HEADS RAN FUEL PLIMP PSI TEST RAN LOW 106L PERFORM DRIVABILITY DIAGNOSTICS & PP TESTS PE1 PS4. NEEDS PEDAL PEDAL IS DS6...ORDER PEDAL, INSTAL PEDAL WHEN IT COMES IN.

18390 42 INSPECT FOR CUSTOMERS COMPLAINT, CHECK KOEC ON DEMAND AND FOUND CODE P0221, ACCEL PEDAL, USING PINPOINT TEST CHECK SYSTEM ALL WIRES AND CONNITRATED REPLACED GAS PEDDLE

WD8 KOEO P1511 KOEC P0221 KOER P1111.

PINPOINT REPLACE FUEL PEDAL RÉPROGRAM

POM & RETEST, OPEN CIRCUIT IN PEDAL

PERFORMED DIAGNOSTICS AND REPLACED ADJUSTABLE ACCEL PEDAL DUE TO OPEN CIRCUT

23765 DIESEL ENGINE PERFORMANCE DIAG. PINFIONT TEST FOR CODE PO221. REPLACE ACCEL PEDAL ASSEMBLY (ADJUSTABLE PEDAL) CLEAR CODE AND ROAD TEST RETEST E ECC TEST CODE FOR P0221 TP RANGE PERFORMANCE BAD REPLACED TP THROTTLE. PEDAL RETEST CLEARED CODE ALLOK

ACCELERATOR PEDAL, OPEN CIRCUIT OF SIAS DIAG 1.9 FLASH CODE POZZI, OPEN CIRCUIT APIRR ACCELLERATOR PEDAL

PERFORM DIESEL ENGINE PERFORMANCE DIAGNOSIS REPLACE ACCELENATOR PRESSURE SWITCH ROAD TEST

.....EEC TEST.RETRIEVED DTC PO221,PINPOINT TEST. REPLACED PEDAL ASSEMBLY,RETEST OK.,....

TEST DRIVE TRUCK WAS RUNNING OK TURNED CORNER PLIT PEDAL TO PLOOR TRUCK STARTED TO ACELL THEN WENT TOIDLE WHILE AT FULL CHECK ENGINE LIGHT CAME ON DID
DEPECTIVE PEDAL ASSEMBLY WIDS DIAG. ELECTRICAL PPT, REPLACED PEDAL ASSEMBLY TO REPAIR.

CK EEC.PP TEST TO FAULTY PEDDLE SWITCH REPLACE AND RETEST, OK. PART DIS

BEC TESTS KOEO P1111 KOEC P0221 KOER P1111 RD TEST PID MONITOR INSPECT WIRING FROM AP SENSOR TO FOU OK DIAG BY FAULT REPLACE ACCEL PEDAL ASSY RETESTS TESTED SYSTEM, FOUND BAD TO BENSOR, ORDERED SENSOR, REPLACED SENSOR, RETESTED SYSTEM, SYSTEM PASSED

WDS SETUP AND TEST KOED PASS CONTPOIZS PINPOINT TEST DOL MONITOR RD TEST R & R ASSEMBLY RETEST REPROGRM PCM

TEST ENGINE CONTROL SYSTEM M TIME TO REPLACE ACCEL PEDAL

CAL EMERGENCY BREAKDOWN TOWING INVOICE

MY R AND R SWITCH

DIESEL DIAG HAD CODE 20221, PIN POINT TEST AND REPLACE ETC CONTROLLRETEST

20149 PROAD TEST AND THE CHECK ENGLIGHT DOES COME ON AND THE ENG WILL ONLY IDLE.EEC TEST AND THERE IS A CODE OF PO221.GO THROUGH THE PINPOINT TESTS AND ROAD TESTED SEC TESTED GOT CODE PO221 RAN PINPOINT TESTS NEEDS AXCELL PEDAL REPLACED #45 REPLACED ACCEL PEDAL

SELF TEST KOED GOT CODE 0221 RUN PINPOINT TEST REPL ACCELL PEDAL ASSY, CLEAR CODE AND RETEST KOED P 1111

1 WOS DIAGNOSTICS AND PIMPOINT TESTS ALL GOOD AT THIS TIME, HAS CODE POZZ1 IN MEMORY, PIMPOINT TEST STEP KET SAYS TO REPLACE

PROAL ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

THROTTLE POSITION SENSOR INOP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

ACCL PROAL SHORTED

CHECK TRANSMISSION WILL NOT SHIFT, ENGINE WILL NOTACCELERATE, DIESEL DIAG STEPS 1 14, ERC TEST CODE POIZS, PINPOINT TESTS, ACCELERATOR PEDAL ASSEMBLY FAUL. DIAGNOSE CHECK ENGINE LEIGHT ON AND THROTTLE RESPONCE INTERMITTENT RAN BEC TEST POZZ1 TP PERFORMANCE PERFORM

PERFORMED BEC TEST, RETRIEVED GODES KOSO PASS, KORR P0125, KORC P0123, PERFORMED PINPOINT TEST DD1 DD8, REPLACED ACCELERATOR PEDAL ASSY AND RETESTED WITH NGS, REPLACED ACCELERATOR PEDAL, RETEST O.K.

ACCEL PEDAL ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURGO ENGINE DIAG

ROAD TEST RUN PERFORMANCE DIAG TESTS FILL OUT DIAG SHEET CODE POZZI IN MEMORY PINPOINT TEST & REPLACED TP SENSOR

CHECKED OVER AND REPLACED ACCELL PEDAL ASSEMBLY

TEST ELECTRONICS, REPLACE ACCELERATOR PEDAL

1640 ACCELERATER PEDAL 26 WR VERIFY CONCERN AND IRAN PERFIDIAGITEST SCOSE \$005F1 18, HAD MEMORY CODE P0221, RAN PINPOINT TEST AND LED TO INOP PEDAL ASSEMBLY PERFORM SECITED FOUND CODE P012D RUN PINPOINT TEST DO FINAL CLICK TEST REPLACE ACCELERATOR PEDAL ASSEMBLY

NOP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DITURBO ENGINE CIAG

6576 TP 55NSOR CLIT OF RANGE AFTER A PEW MILES 6005F 0.2 F1 0.1 PIXL 0.1 P2 0.1 P6 TO F14 1.4 F16 0.6 F17 0.6 12850045 0.3 D61 0.6 M.T 0.3 TOTAL 4.1 HRS SUFFICIENT CLEAN FI AP SWITCH MALFUNCTIONING. PERFORMED KOED NO CODES.PERFORMED KOER NO CODES.PERFORMED INTAKE AIR RESTRICTION.FUEL CONDITION,ICP TEST, PIU DATA

CHECK ENGINE LIGHT IS ON EEC (QUICK TEST) DIAGNOSIS

TECH HOCKED TO WOS CONFIRMED TRUCK RACING TO FULL THROTTLE THEN DROPPING INSPECTION OF CONNECT ORS ALL OK HOCKED TO WOS RAN KOED CODE P1023 KOER I VERTIED COMPLAINT ECC TEST P0221 TP RANGE IRRATICREPLACED SENSOR AND PEDAL ASSY RETEST OK

NGS TEST CODE POZZI, PINPOINT TEST AND FOUND FAULTY THROTTLE ASSY, REPLACE AND RETEST P1111

PERFORMED INTO TEST ROADTEST, INSPECT WIRING & CO. MIN AT ACCELERATOR PEDAL, OK, PNPNT MONITOR AP & 1. VS PIO WHILE MOVING PEDAL IVS INTERMITTENLY REAL OS OPP.

MIL WAS ON RAN EEC KOEC POZZI KOER POZZI KOED POZZI RAN PRIPOINT TEST FOUND THROTTLE BENSOR OPEN INTERNALLT REPLACED THROTTLE PEDAL ASSY CLEARED COD.

PEDAL EEC (QUICK TEST) DIAGNOSIS

INTERNITERIAL BAD INPUT FROM ACCEL PETAL ASSY, REPLACED ACCEL PETAL ASSEMBLY YEST DRIVE OKAY B.

RUN DOL DIAG TEST, ROAD TEST, FOUND T P SENSOR FAILING AT TIMES, NO PART

PERFORMED DESEL PERFORMANCE DIAG MONITORED PIDS KOEG KOER PPTEST PULLED CODES REPLACED ACCELERATOR PEDAL CLEARED CODE RETEST VEHICLE OPERATES PI 86 NOTED AP OUT OF RANG CODE IN MEMUSED NGS TO LOCKAT AP PID WILL NOT COME DOWN TO LOW READING. WITHOUT SNAPPING PEDEL A FEW TIMES SUSPECT SENSOR ST PASSED VISUAL RISPECTION BIDZ P1111 MONITORED DATALIST V PWR 11.5 RMP 1851CP 820 FUEL 1.5 PASS GLO W PLUG TEST PERF DIAG INTAKE REST 2 IN FUEL PRESSURE RIGHT ROAD TESTED TO VERIFY PROBLEM, ECC TEST CODE P0220 THROTLE SWITCH MALFUNCTION PERFORMED PINPOINT TEST FE1 THRU

CHÉCKED FOR CODES POZZ1 DID PINPOWIT TEST TP BAD REPLACED ACCEL PEDEL ASSY ROALITESTED OK RECHECKED NO CODES

PERFORMED DIAGNOSIS REPLACED THROTTLE PEDAL ASS Y RETEST OK NOTE DISCONNECTED AFTERMARKET TRAILER WIRING TH AT WAS TAPPED INTO 5 VOLT THROTTLE PEDA SYSTEM CHECK AND PIN POINT DIAG FOUND THROTTLE POSITION SENSOR BAD REPLACE T POSITION SENSOR AND ROAD TEST

18843 PEDAL FAILURE 6000F.2F1.1F2.1F7.2F3,1F9.3F10.1F11.2F12.3F13.1 F14.1F16.6F17.5F18.5F19.2,5638A.2 VERIFY CONCERN.DIAG, PID TEST, PINPOINT TEST 9 R AND REPLACE AP PERFORMED COMPUTER TEST KORO P1111,KORO P0221,KORO P1111 PERFORMED PINPOINT TESTS DIAG AND REPLACED THE FAULTY

PERFORMANCE DIAGNOS PUZZI, PON POINT TEST F1 THRU F4, REPLACE THROTTLE PEDAL SENSOR ASSY 97506 WAS ERATTIC, CLEAR CODE, RETEBT PASS 0

FALED PEDAL ASSEMBLY CODE PO221 HOOKED UP NOS CODE PO221, REPLACED ACCELERATOR PEDAL ASSY, CLEARED CODE TEST DROVE PASS.

WOS, PINPOINT, REPLACE TP

DOES NOT OPERATE PROPERLY KEY ON ENGINE OFF KOED CHECK TEST

PERFORMED DIAGNOSTICS FOUND INTEGRITY OF TRANSMISSION TESTING GOOD AT THIS TIME FOUND PAULT IN ACCELERATOR SWITCH REMOVED AND REPLACED ACCELERATOR DIAGNOSE AND REPLACE ACCELERATOR PEDAL ASSY.

VERLIFED COCKERN FOLIND CODE 220 PINPOINT TEST AP SENSOR INTERNAL FALILT RELACED AND RECHECKED OK

PERFORM DIAG CHECK FOR CODES FOUND PEDAL POSITION WOULD NOT CHANGE REPLACE PEDAL ASSY CLEAR CODES AND RECHECK

1 CHECK AND REPLACCED BROKEN ACCELLERATOR FEDAL 1

PERFORMED ÉEC BYSTEM TEST, REPLACED GAS PEDAL ASSEMBLY

CODE PO221, PERFORMANCE DIESEL DIAGNOSIS CHECK AND REPLACE ACCELERATOR PEDAL ASSY AND ROAD TEST

PERFORM ENGINE PERFORMANCE DIAG. REPLACE ACCEL PEDAL ASSEMBLY

ACCELERATOR PEDAL CEFECTIVE

LIDIAG SYSTEM FOUND PEDAL GOES OPEN AT TIMES REPLACED PEDAL

BBC TEST CODES POS21 LOW TPB SENSOR LOW YOLTAGE HAR TPS SENSOR REPLACE SET TO FACTORY SPECTS ROAD TESTED OK

NGS TEST, CHECK PID DATA, HOCK UP NGS AND MONITOR ROAD TEST CONTACT HOTLINE, PERFORM PIN POINT TESTS, CHECK PCM, HARNESS TEST AND FOUND ADJUSTABLE THROTTLE PEDEL ASSEMBLY FROM PREVIOUS DIAG BY 1185.

* TESTED WITH NGS, FOUND CODE FOR TP SENSOR, REPLACED SENSOR, CLEARED CODES AND RETEST O.K.

PECAL ASSEM REPLACE ACC PEDAL ASSEM

VERIFY CK ENGINE LAMP ON, AND NO RESPONSE FROM ACCELLERATOR PEDAL, PERFORM DIESEL ENGINE PERFORMANCE DIAG SHEET STEPS 1 TO 14 AND REPLACE PEDAL RETES VERIFY CONCERN PERFORM WOR BEC SELF TEST, CODE PO123, ETC. PERFORM PPT FOUND ETC SENSOR BAD, DISCONNECT PEDAL ADJUSTER CASLE, REMOVE PEDAL ASSY INST

LIGHT ON BEC (QUICK TEST) DIAGNOSIS

EEC TEST, RETEST, PINPOINT, DCL, MONITOR, REPLACED ACCEL, PEDAL ASSEMBLY

NOAD TESTED, SECT TESTED CODE 0221, MONITORED MOS AND REPLACED THEPEDAL ASSEMBLY, RETESTED AND CLEARED CODES

ENGINE PERF TEST 7.3L DEGREE PINPOINT TEST ON ACCELERATOR PEDAL CODE PO122 RAIR ACCELERATOR PEDAL & RETEST SYMPTOM STILL PRESENT CONTINUE PPT RAIR PC

7384 EFECTEST PINPOINT TEST REPLACED ACCELERATOR PEDAL SWITCH ASSEMBLY RETEST TO VERIFY REPAIR

BAD ACCEL ASM JUMPS OFF IDLE REPLACE ACCEL ASM

DEFECTIVE ACCULERATION PUBLIC ASSIY ENGINE PERFORMANCE DIAGNOSTICS 7.31 DITURBO ENGINE DIAG

COMPLETE PERFORMANCE CHART AND REPLACE DUE VALIDATION SWITCH

T TEST OC13 19.RPL ACCELERATOR PEDALIS SCTRICI PERFORMED PIO MONITORING TESTING, CLEAR DTC, ROAD TEST, OK.

VERLIFIED TO SENSOR WORKING INTERMITTANTLY, TEST DRIVE AND FOUND ACCELL PEDAL NOT WORKING, REPLACED ACC FEDAL AND RECHECKED OK. CANNOT VERIFY ANY ABNOL

TEST AND REPLACE PEDAL AND SENSOR ASSY

1 BEC TESTED: CHECKED REPLACED ACCEL PEDAL ASSEMBLY AND CLEARED MEMORY. DI ENGINE WARRANTY

EEG TEST, PINPOINT TEST, WIGGLE TESTED WIRING, REPLACED THROTTLE PEDAL ASSEMBLY, RETEST, AND ROAD TEST

PERFORM CODE P0221 A PINOP PINITEST IVS STICKS INTERNITANIT REPLACED ACCELL PEDAL ROAD TEST AND RETEST.

PEDAL ASSY ERRATIC OPERATION: SEC (QUICK TEST) DIAGNOSIS

CHECK ENGINE LIGHT ON DIAGNOSED EEC BYSTEM CODE POIS3 PINPOINT TEST REPLACED ACCEL PEDAL FOR BENSOR RETESTED OK

ACCELERATOR PEDAL ASSY INOP INCAD TESTED VEHICLE AND VERIFIED CUSTOMER CONCERN, CHECKED AIR FILTER, PERFORMED DIESEL DIAGNOSTICS TEST, BOOST SLOW

PRRATIC OPERATION OF SEMBOR TEST SYSTEMREFLACED SEMSOR RETEST SYSTEM

CHECKED CODES ON NGB PERFORMED PINPOINT TEST CHECKED CASIS AND TSB MESSAGES CALLED HOTLING CHECKED MESSAGE 18412 NO CHAFFING FOUND. REPLACED ADJUS' INSPECTED & PERFORMD TRANS DIAG INFO, PERFORMED EEC TEST KGED,KOER & KOEC, PLUID FULL & CLEAN. CLEARED CODES & RE ROAD TEST. TRANS OPERATION O K AT THIS REPLACED THROTTLE PEDAL SENSOR

CHECK OUT COMPLETE AND DIAS TO ACCEL,PEDAL SAO, REPLACE COMPLETE, ALSO FOUND OIL LEAK AT TURBO AND OILPUMP, REPLACE BOTH RECHECK OK

DIAGNOSE EEC SYSTEM RETENT PIN POINT TEST DIAGNOSE IGNITION REMOVE AND REPLACE PEDAL AND SENSOR ASSEMBLY

THE TED WITH NOS, RECEIVED CODE PO125 TESTED AND REPLACED ACCELERATOR PEDAL TP SENSOR SHOWS 5. CHECK OF IDLE.

FOUND AP SIGNAL CROPS AT 0 AT TIMES, INSTALL BOS AND MONITER, VERIFIED WIRING AP; RECK, OK, ROAD TEST, OK.

REPLACE ACCEL PEDAL ASSY

PROAL ASSEMBLY INTERNIT INCP. EEC (QUICK TEST) DIAGNOSIS

CHECKED FOR TRUCK NOT ACCELERATING, CHECKED CODES, FOUND CODE FOR ACCELERATOR PEDAL POSITION, CHECKE D PARAMETERS, AF VOLTAGE DROPPED, REPLACED ACCEPTAGE TO VERIFY FOUND INTITIOSS OF POWER ON ACCELL PERFOR TESTS 1.14 REPLACED ACCELL, PEDAL ASSY RETEESTED PASSED ROAD TESTED OK NOW

PERFORM BYS TEST NECC TO REPLACE ACCELERATOR PEDAL.

RAN DIESEL PERFORMANCE DIAGNOSIS FOUND BAD POTENTIONETER REPLACED TO CORRECT FOUND CODE P0221

RAN EEC TEST CODE PUZZI DEL DISPLAY PID MONITOR ROAD TEST PINPOINT TEST LET TIME TO REPLACE PEDAL AND SENSOR ASSEMBLY RETEST OR TEST DROVE RAN NORMAL N. CODE PUZZI, REPER TO R.O. 342136 FOR DIESEL ENGINE PERFOR MANCE DIAG REPLACED ACCELLERATION PEDAL ASSY, CLEARED CODES, ROAD TEST CK, EEC TEST PASS.

ROAD TEST VEHICLE ONLY IDLES AT TIMES AT ANY ACCELERATOR POSITION PERFORM DIESEL DIAGRR ACCELERATOR PEDAL ASSEMBLY CLEAR CODES ROAD TEST.
REPLACE ACCELARATOR PEDAL AND SENSOR REMOVE PROMISTOCK UNIT TO FIX CUSTOMERS CAR

DIAG, EEC CHECK SYETEM, FOUND CODE POIZZ A TY CODE, ROAD TEST WITH NGS TO MONITOR PIDS, TY PID IVS NOT OPERATING PROPERLY, REMOVE NAD REPLACE PEDA SESS 42 ROAD TEST FOR CONCERN AT TIMES ENGINE WOULD IDLE ONLY AND CHECK ENGINE LIGHT COMES ON AFTER A MINUTE OR SO TRUCK RUNS NORMAL PERFORMED DISSECTION OF RESPINSE FROM ACCELLERATION NOS DIAG CODE POIZZ. PID MON

VERIFY CONCERN PERFORMED WAS CONTINUOUS ON DEMAND ENGINE RUN CONTINUOUS CODE PIZZI | DUE VALIDATION SWITCH PINPOINT TEST: ORDER ACCELERATION PEDAL ERC TEST, PINPOINT TESTS, REPLACED THROTTLE PEDAL ASSYMBLY (TP SENSOR) RECHECKED OK

SCC TEST PASS CODES MONITOR PIOS FOUND IVS OPEN REPLACE FUEL PEDAL AS NEEDED ROAD TEST

10917 ACCELORATOR BAD 9F836 PERFORMED DIESEL DRIVABILITY, DIAGNONI, CODE PO12 2 IN CONTRIQUE, RAN PINPOINT TEST, MONOTORED PIDS REPLACED ACCELORATOR PETAL
CK FOR VEH STALLING ON ACCEL FROM STOP: RAN DIESEL DIAG: PINPOINT CODE P0221; REPLACED PEDAL ASSEMBLY; RECHECK OK.

9370 PREFORM PREFORMANCE DIAG SHIBIT STEP 1 VISUAL OK STEP 2 CLEAN FUEL OK STEP 3 CK OIL OIL OK STEP 4 INTAKE RESTRICTON NONE STEP 5 KOED NO CODES STEP 5 R
FOUND CODE P 0122 ACCEL, PEDAL FALLT OPEN CIRCUIT AND NO ONE IN THE VALLEY HAS PART, NEEDS TO BE S.O.P. CAR TEST DRIVE TO VERIFY 3 TO 5 MILES AND CUTS DUT 3 TH
OPEN IN PEDAL ABBY, 28 GF835 MILES OUT 13641 RUN ENGINE PERFORMANCE DIAG. STEPS 1 14 ROAD TRATED TO DUPL REPLACE PEDAL ASSY, RETESTED AND ROAD TESTED
RAN ESC TESTS, DIO PINPOINT TESTS FOR CODES, FOUND ACCEL, PEDAL INOP REPLACED PEDAL ASSEMBLY, RETESTED OK.

TECH INSPECTED & FOUND TRANS WORKING GOOD UNTIL THE THROTTLE PEDAL RESPONSE STOPPED IN TIME TO REPLACE ACCEL PEDAL ASSY AND CLEAR CODES PO251

MITME TO PERFORM PINPOINT TESTS, QC13 AND QC19, FOUND ACCELERATOR PEDAL NOT OPERATING PROPERLY, ORDER, CUSTOMER CHOSE TO PULL YEHICLE OUT OF SERVICE ROADTEST BEC TEST PO221 PO940 PINPOINT TESTS REPLACE AP SENSOR PEDAL ASBY, & LAT GENSOR MITME NO SUTS RETEST BEC PASS P1111

DISSEC DIAG CODS P0221 PRINCINT ICLE VALIDATION SWITCH STICKING REPLACE THROTTLE PEDAL ASSEMBLEY ROAD TEST

24611 WARR, VERIFIED CONCERN ECC TESTED PO221. CHECKED WIRING ON LEFT SHOCK TOWER ALL OK PIN TESTED FOUND ACCERLATOR PEDAL AT FAULT. REPLACED ACCEPLATOR VERIFIED CONCERN OF CHECK ENGINE LIGHT ON, PERIFORMED DRIVE TESTS FOUND CODE PO221. REPLACE AP SENSOR AND RECK, CK.

VERIFY MIC ON, NOACCELERATOR PEDAL RESPONSE, RE TRIEVED CODES POZZI , PPT FE 1 NO FEZ NO FEZ YE S, REPLACED ACCELERATOR PEDAL CLEARED CODES AND RETEST INTERNATIFIC OPEN IN SWITCH

RD TEST, CONDITION YARIPIED, CONNECTINGS AAND RETRIEVE CODES, PO221.CONT, KOER SWITCH MONITOR TEST, RUN PIN POINT TESTS REPLACE ACCEL PEDAL ASY ADJUSTASI.
OPEN IN ACCEL PEDAL EEC (QUICK TEST). DIAGNOSIS

HESITATES ON TAKE OFF BEC (QUICK TEST) DIAGNOSIS

1 VERIFIED CONCERN EEC TEST P0221 TP OUT OF RANGE RER AND INSTALLED NEW THROTTLE PEDAL ASSY RE EEC TEST ALL PASS ROAD

CHAR, EEC CHECK SYSTEM, NO CODES, MONITOR PIOS, FOUND AP SIGNAL INTERMITTEN, POUND PEDAL ASSY FAILED, ORDER PARTS, REMOVE AND REPLACE PEDAL ASSY, RECHEC VERIFIED COMPLAINT EEC TEST CODE PO221 MONITOR PIOS POUND INTERMITTENTLOSS OF AP SIGNAL REPLACED PEDAL ASSY, RD TEST AND MONITOR OK, RETEST NO CODES RD TEST VERIFIED COMPLAINT EEC TEST CODE PO221 FOR IDLE VALIDATION - SWITCH CHECKED CONNECTIONS TO AP SWITCH ON PEDAL CK. RD TEST AND MONITOR - PIDS FOUN ROAD TEST VERIFY NO REPORT FROM ACCELERATION REPLACE PEDAL ASSEMBLY RETEST OK

PERFORM DI DIAG CODE PO222 PERFORM PIN POINT TEST OPEN CIRCUIT IN ACC PEDAL REPLACE ASS PEDAL AND CLEAR CODES.

OFFICE COLD FOR THE PROPERTY OF A SECONDECT PERTAINS AND ASSESSED OF THE PROPERTY OF A REPORT OF A REP

EEC TEST P1311,NGS TEST AND ROAD TEST TO MONITOR PIDS AT TIMES NO THROTTLE RESPONSE,REMOVE AND REPLACE THROTTLE PEDAL AND SWITCH ASSEMBLY AND TEST DRINGPECTED, FOUND THROTTLE LINGUAGE FAILURE REPLACED ASSEMBLY, TESTED, OPERATION NORMAL

DIAG COOR (221) PINPOINT AND REPLACED AP SWITCH SET UP AND MONITORED FIDE ON TEST DRIVE TRUCK HAS FULL BOOST

DIAGNOSIS OF NO POWER ON ACCELERATION INTERMITTENTLY PERFORM EEC SELF TEST CODE PIZZY PERFORM PINPOINT TESTS PERFORM NGS RECORDER MONITOR ROAD."
TEST DROVE WITH CUSTOMER CUSTOMER WAS NOT ABLE TO DUPLICATE CONCERN CONTINUOUSLY FOUND IT TO GO YO IDLE.

DIAGNOSE AND REPLACE GAS PEDAL ASSEMBLY CLEAR RECODE AND READ TESTED

SEC TESTED, NO FAULT CODES, PIOS TESTED, FOUND AP SENSOR NOT WORKING INTERMITTENTLY, R&R AP SENSOR MT TIME DUE TO NO LABOR OP. AVAIL.

ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG

CHÉCK AND REPLACE GAS PEDAL ASSY WPI

PART WAS LEFT OFF ORIGINAL CLAIM 127681.

MITIME TO REPLACESLERATOR PEDAL ASSY REPLACE GAS PEDEL ON VEHICLE

REPLACE ACCE PEDAL ABBY

6272 ENGINE INTERMITTENT STAYS AT IDLE PERPORMANCE DIAG CHECKED ENGINE PUEL OIL LEVEL AND INTAKE RESTRICTION ALL OK KOSO ON DEMAND YEST PASS RETRIEVE C RUN PERFORMANCE TEST CODE 0221, AP ASSY FAULTY. INSTALL NEW THROTTLE PEDAL, CLEAR CODES & ROAD TEST.

ENGINE PERFORMANCE TEST, REPLACE ACCEL FEDAL AND SWITCH

D42 42 9F636 VERIFIED CONCERN, VISUAL INSPECT, ELEC DIAG, REPLACED PEDAL A98Y AND THAT DRIVE, RETEST NO CODES

SEC YESTS KOSO P1111 KOSC P0221 KOSR P1111 DCL PID MONITOR RD TASTS REPLACE AP ASSEMBLY DUE TO INTERMITTANT FAULT. RETEST DRIVE UNABLE TO REDUPLICATE C

ACCELERATION PEDAL PEROFINED WDS DIAGNOSIS PIN POINT OCL REPLACED AP SENSOR CHECKED P

PEDAL ASSEM

ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

DIAG NO EQNING ACCEL ENTER PIDS APIVS NO IVS OPERATION RAN KOEO CODE PO221 TESTED ACCELERATOR IVS SWITCH INOP REMOVE AND REPLACED SASS PEDAL ASSYMICAL VERIFY CONCERN. RAR A PEDAL ASSEMBLY, DONE TESTED OKAY NOW.

GAS PEDAL REPLACE PEDAL

PEDAL ASSEMBLY OPEN CIRCUIT DIESEL DIAG START UP. KOÉO TEST POZZI, PINPOINT CODE POZZI, KGS MONITOR RD TEST TO WATCH IDLE VALIDATION SWITCH & TP SENSOR.

PEDAL PAULTY ACCOLERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE

FAILTY ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG

DIAG USING NGS., PULLED CODE POZZO, RUN PPT, REPLACE AP PEDAL, RETERT

ROADTESTAD VEHICLE VERIFIED CONCERN PERFORMED. DIESEL DIAGNOSTIC SHEET FOR DRIVARIUTY CONCERN POZZ1 ACCELERATOR PEDAL POSITIONER PINPOINT TEST. YOUR

TP SENSOR CPRN CRICUIT IN SENSOR ESC (QUICK TEST) DIAGNOSIS

PEDAL ABBEM REPLACE ACC PEDAL ABBM INOP
CHBCK NO POWER ON ACCEL, RUN ENGINE PERFORMANCE DIAGNOSTICS, CODE P0221, PINPOINT TEST WITH PID MINITOR ON ROAD TEST, CONCERN CODE: 629

COMPUTER TESTED REPLACED GAS PEDAL ASSEMBLY

REPLACE PEDAL ASSEMBLY REQUEST MYME NO LABOR OF

14 STALLS 6005F 6006F12 1286006 D45 D61 D62 3.4 PERFORM DIESEL DIAG TEST PERFORM QUICK TEST PERFORM RETEST INJ TEST ICP TEST CYL CONT TEST INGS 90AD TEST ING CO200 DIAG., REPLACED ACCELL PEDAL AND

PERFORMED DESEL ENGINE PERFORMANCE DIAG PERFORMEDICOED KORR PULLED CODE MONITORED PIDS REPLACED ACC ELERATOR PEDAL ASSEMBLY CLEARED CODE RETEST FAILURE OF PEDAL ASSEMBLY. TECH REPLACED THE PEDAL ASSEMBLY, RECHECKED OK, MITIME TO REPLACE PEDAL NO OP CODES

7093 TP SEASON NOT WORKING PROPERLY, 125500, DXT, D45, 67258 DIAG ENGINE DOESN'T ACCELERATE PROPERLY, FOUND CODE PO123 IN KOEO CONTINUOUS, PERFORMED PIN CHECK ENGINE LOSS OF POWER AND CHECK ENGINE LIGHT CAME ON, RAN PARTIAL PERF. TEST ## #14 KOEO P1111.PMPOINT TEST QC18 GC18.REPL ACCEL PEDAL ASSY PER TST (DIESEL PERF DIAG 1 14 MONITORED PIDS WHILE DRIVING IN PARKING LOT LOSS OF ACCELERATOR PEDAL SIGNAL (INTERMITTEN) REPLACED A.P. ASSEMBLY W ACJUSTABLE PEDAL

INOPERATIVE ÉEC (QUICK TEST) DIAGNOSIS

CCDGG DIESEL ENGINE DIAGNOSIS. REPLACED ACCELERATOR PEDAL SENSOR.

DIESEL PERFORMANCE TESTS CODE PO221 REMOVE REPLACE INJECTOR VARIABLE SPEED CONTROL SWITCH ACCELERATOR PEDAL ASSEMBLY

DIAG. PP TEST, CK VOLTS TO TP SEN. 1.5 REPLACED SENSOR MT FOR REPLACE.

PERFROM DIAGS, NECC TO REPLACE PEDAL

CC28 OPEN CIRCUIT EEC DIAG PO221 PERFORM PID MONITOR RECORD INVESTIGATION TEST LEADS TO REPLACE AP ASSEMBLY MITIME NO OPS RETEST PASS

VÉRRIPIED CONCERN. PERFORMED WIDS SELF TEST. RETRIEVED CODE P0221. PERFORMED PINPOINT TÉST FOUND CHAFFED WIRE AT LEFT FRONT SHOCK TOWER, REPAIRED WIRE

TRUCK HAS NO POWER EEC (QUICK TEST) DIAGNOSIS

ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE

ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURSO ENGINE CIAG

REPLACED PEDAL ABSY

CK OUT ON WOS CODES P0221 T.P. IDLE TRACKING SWITCH FAILING INSTALL NEW CONTROL ASSY, CK FOR & RE PROGRAM UPDATE IN PCM, CLEAR DTC'S & RE TEST OK

19960 INTERMITTANT OPEN IN ACCEL PETAL SENSOR 26 \$7636 NOTE DIAG FOR LINES 4,8, AND C PERFORM LINES 1 THOUGH 14 DI TURBO PERF. SHEET KOCM PO221 ALL OTHER PA

PE83-844 32251

VERIFY ENGINE IT. BS ONLY CK ENG LIGHT IS ON KOBO PO122 AP INFT LOW REPTO PINPOINT TEST DPS DIAG AND REPLACE (FAULTY) AP CLEAR CODES AND VERIFY REPAIR KOBO I VERIFIED RAN EBC TEST TO PINPOINT TEST RAN ALL TEST FOUND CODES POLLOWED CODES TO PEDAL INTERMETTANT FAULT, REPL PEDAL

DOES NOT OPERATE PROPERLY | EEC (QUICK TEST) DIAGNOSIS

ENGINE HAS NO POWER AT TIMES INJECTION CONTROL PRESSURE REGULATOR REPLACE

VERIFIED CONCERN NO RESPONSE TO ACCELLERATE EEC SYSTEM DIAG AND PF TEST OTC P0221 MONITOR PIOS NO SINGLA OUT OF GAS PEDAL REPLACED PEDAL ASSY CLEAR CC PREFORM DIEBEL DIAG TEST 1 14 FOR ACC. PEDAL WILL NOT WORK AT TIMES PREFORM SEC YEST WAS NO CODES

REMOVE AND REPLACE FAILED THROTTLE PEDAL ASSY

PINPOINT TEST DIAG VERIFY CONCERN HOOK UP NGS CLEAR AND RETRIEVE PROSSER REPLIPER PINPOINT TEST DID NOT REPAIR FOUND THROTTLE PEDAL STICKING REPLIESSES PEDAL 42 WOS DIAGNOSIS KOED PASS, KOED PASS, KOED POZZI DATALOGGER DISPLAY PINPOINT TEST REPLIACED ACCELERATOR PEDAL ASSY WITH ADJUSTABLE PET 19983 42 CC M O 5465 NGS 261. TEST REC SYSTEM, CODE 1221, INSTALLED BREAK OUT BOX 1

7433 42 9F836 28 12K973 ROADTEST VEHICLE UNABLE TO VERIFY STALLING BUT VERIFIED TRUCK HEBITATING AND BUCKING AT TIMES BEGINE PERFORMANCE SHEET VISUAL OK CHECK AND REPLACE THROTTLE BEDAL ABOY STICKING AND OPERATION REPLACE PEDAL ASSY

CHECK ENG CODES, CONT P0221, KOSO PASS, PINPOINT TEST, RD TEST WINGS AND MONITOR PIDS, RIR ACCEL PEDAL ASSY.

13841 VERIFY CONCERN SECITEST PO221 CONTINAS KOSO PASS KOSO PASS KOSO PASS KOSO PASS KOSO MONITOR AS TEST DROVE FROM STOP IVS 887UCK ON IDLE RENEW PEDAL ASSY CLEAR CO ACCELERATOR PEDAL SENSOR FAULTY SECITESTED, NECETVED CODE PO221, MONITORED PID DURING ROAD TEST, AND POLLOWED PINPOINT TEST. REPLACED ACCLERATOR PED FAILED PART \$7835 VERIFY, DIAG. PIN TEST REPLACE \$7235 PEDAL ASSY RETEST.

OFRIGE 28 VERIFIED CONCERN, APPLIED HOS POZZI ACCELERATOR PEDAL CIRCUT, PREFORMED PIN POINT TESTS PER MANUAL AND POLIND FAULTY

GO TO SYMMPTON CHART RUN EEC NO CHECK ENGINE LIGHT, RUN CODE P0123 PPT 001 YES 4.4 VOLTS D2 YES 0.0 VOLTS REPLACE AP PEDAL ASSY

161 PER CUSTOMER CONCERN THROTTLE ASSY IS BROKE AGAIN CUSTOMER CAME TO PICK UP VEHICLE AND APP. BENBOR BROKE OFF ACCELERATOR PEDAL ASSY AS HE. WENT STATES ACCELARATOR BROKE LOOSE WENT TO FLOOR WENT TO DRIVE HOME GAS PEDAL WENT TO FLOOR AND IRPUS WENT UP. INSPECTED ACCELERATOR PEDAL AND FR RAN WOS DIAG & PINPOINT TEST.FOUND INTERMITTANT CONCERN IN ACCELERATOR PEDAL SENSOR REPLACED PEDAL & SENSOR ASSEMBLY RETESTED, NO CODES.ROAD TESTED PERFORM DIAG WORKSHEET, FOUND CODE POIZE, PERFORM PINPOINT TST, REPALCE AP SENSOR, RETEST ALL. OK.

CHKO FOR CODES PINPOINT TEST R AND R PEDAL ASSY RETIST

ROAD TEST RETRIEVE CODES PASS, KOED PASS, KOED PASS, KOED PASS, MONITOR PIDS 1P OUT OF RANGE AT TIMES, PIN POINT TEST.

VEH STARTS BUT HAS NO THROTTLE KEY ON ENGINE OFF KOSO CHICK TEST

NGS DIAG, AND REPLACE PEDAL ASSY

16925 OPEN IN 1 P SENSOR WARR CODE 28 PERFORM DIESEL CIAGNOSIS CHECK PUBLICK CHECK OIL OK CHECK INTAKE FOR RESTRICTION NONE PERFORM KCEO TEST. PASS HIS INOP.

COMPLÉTED ENGINE PERFORMANCE TESTS 1 14 FROM DIAG SHEET. RECEIVED CODE PO123 AND PERFORMED PINPOINT TESTS POR ACCEL REPLACED ACCELERATOR PEDAL AND F SENSOR FAULT MONITORED ENGINE FUEL AND ELECTRICAL SYSTEMS, FOUND THROTTLE PEDAL SENSOR IS NOT RESPONDING CAUSING LACK OF

EEC TEST PINPOINT TEST COOK PO221. REPLACED FAULTYPEDAL ABBY, RETEST & ROAD TEST OK

DOES NOT OPERATE PROPERLY EEC (QUICK TEST) DIAGNOSES

PEDAL SENSOR OPEN AND INJECTOR HARNESS SHORTED 7:3 DI PERF DIAG STEPS 1 66 9 12 REPL PEDAL ASSY ADJUSTABLE PEDALS RIR RT VALYE COVER REPL INJ HARNESS RET. EEC (QUICK TEST). DIAGNOSIS

2121 ACCEL PEDAL SEE PARTE(BOBBY) SEE BOBBY IN PARTS

1360 CK FOR LACK OF ACCELERATION INSPECT, ROAD TEST TO VERIFY CONCERNING PEDAL RESPONSE, PERFORMED KOED PO!22, PERFORMED PINPOINT TESTS. RAR ACCELERATION CHECKED CONCERN PINPOINT TEST MEPLACED THROTTLE PEDAL SENSOR RETEST

REPLACE ACCELERATOR PEDAL ASSY

SFISSIN ORDERED THROTTLE PEDEL ASSY REPLACED THROTTLEROADS FOR 8 MILES UNABLE TO DUPLICATE CUST CONCERTO ACCESS WIGGLE TEST HARNESS ROAD TEST OVER I NOS FOUND FAULTY PEDAL ASSY, REPLACE ASSY.

FAILED AP SENSOR ENGINE PERFORMANCE DIAGNOSTICS 7.3L DITURBO ENGINE DIAG

CHECKED BYSTEM REPLACED ACCLERATOR PEDAL, TEST DROVE OK

NGS TEST, PINPOINT TESTS, FOUND OPEN IN AP SENSOR, RAR SENSOR

PERFORM EEC DIAGNOSIS. REPLACE ACCEL PEDAL ASSY AND REPAIR WIRING AT LEFT PRONT FENDER,C159, ACCEL PEDAL BIAS AND LODGE

NGS TEST, FOUND CODE P0221 REPLACE PAULTY ACCIDE PEDAL NIT IS FOR LABOR OF FOR ACCELL PEDAL

CEC DIAG CONT P0221 PIN POINT TEST ROAD TEST WITH NGS NEEDS AP SENSOR REPLACED PEDAL ASSEMBLY RETEST OK

TECH INSPECTED & FOUND THE PEDAL THROTTLE PEDAL FAULEY CAUSING ENGINE LIGHT A NO PEDAL RESPNSE REPLACED THE ACCELERATOR PEDAL MITME TO REPLACE PEDAL SESSION 42 DIAG TRANS PRESSURE TEST LEG TEST FOUND CODE POZZI PIN POINT TEST REPLACE TO SENSOR AND GAS PEDAL ASSY RETEST SYSTEM

AP SENSOR OUT OF RANGE PERFORMANCE TESTS ALL OK, MONITORED AP PID, RAR AP SENSOR, RETEST

19962 ACCELERATER PEDAL 25 WIT VERIFY CONCERN AON RUN PERFIDIAGITEST 6006F 6006P1 12. HAD MEMORY CODE P0221, RAN PINPOINT TEST AND LED TO PAOP ACCELERATO DIAGIFOUND CODE P0122 P.P. TEST FOUND PEDAL ASS READING INACCUATS, NECC TO REPLACE PEDAL ASSY.

WDS TEST CODE P0221 DATA PINPOINT TEST REPLACE INJECTOR VARIABLE CONTROL SWITCH ACCELERATOR PEDAL ASSEMBLY RETEST DIAG, REPLACE GAS PEDAL ASSEMBLY

RAN DIBBEL DIAG SHEET P1111 10 P0122 SEE SHEET FOR NUMBERS PINPOINT DIAG AS PER HIMANUAL REPLACE PEDAL ASSEMBLY AND RETEST P1111 10 P1111KOER P1111 CYCL PULLID COORS TO OUT OF RANGE P0221

14964 TECH 9, RAM ENGINE AND VERIFIED CONCERN. CHECK ENGINE LIGHT IS ON AND THERE IS NO THROTTLE RESPONSE. CONNECTED NOS TESTER AND RETREIVED FULT CODE ENGINE PERFORMANCE DIAGNOSIS, REPLACED ACCELERATION PEDAL

CHAGNOSE SEC CODE P0221, PINPOINT TEST, NECESSARY TO MONITOR AP IVS PID. FOUND IVS ERRATIC, NECESSARY TO REPLACE OPEN PEDAL ASSEMBLY, RETEST PASS VERIFIED CONCERN, EEC TESTED, ROAD TESTED WHILE MONITORING PIDS, DIAG AND REPLACED ACCELERATOR PEDALSWITCH ASSEMBLY, RETEST, CK.

NECESSARY TO PERFORM ALL EEC TEST AND REPLACE ACCELERATOR PEDAL SWITCH

MO 11112, 7.3L DI, 4R100 AUTO CC 28, CASUAL PART 9R36 ACCEL PEDAL ASSY VERF CHIST CONCERN. PERF DIESE, PEPDRMANCE DIAG, PERF TESTS: THRU 6 FND ALL OK. TEST 7 F ACC PEDAL DOES NOT WORK PARTTIME SEC TEST CODE PO22! PINPOINT TEST FEI FES IVS OUT OF RANGE REPLACED ACCELL PEDAL CLEAR CODES ROAD TEST OK DIG FROM FOF VERIFIED CONCERN. EEC TEST FOUND CODE PO22!, PINPOINT TEST FOUND POSITION SENSOR FOR ACCELERATOR PEDAL FAILING REMOVED AND REPLACED PEDAL, CLEARED CO-CPN CRICUIT REPLACE PEDAL ASSY. ENGINE PERFORMANCE DIAGNOSTICS. 7.5L DI TURBO ENGINE. DIAG

ENGINE WILL NOT RUN AT TIMES TESTEEC (CHICK TEST) DIAGNOSIS.

PLEO. SYSTEM CIAG. CEC TEST, REPLACED GAS PEDAL ASSEMBLY (DIS), RETESTORIVE

VERIFIED CONCERN DIAGNOSED TRANS FOUND COOR PAZA1 CHECKED SYSTEM FOUND FEDAL ASSEMBLY SHORTED NEEDED MT TIME TO REPLACE PEDAL ASSYDUE TO NO LABOR RAN ENGINE PERFORMANCE TESTS 1.20, REPLACED PED DAL ASSEMBLY.

15816 TEST DROVE AND WAS UNABLE TO VERIFY CONCERN. NGS EEC SELF TEST, KORO PASS, CONT PO221, PO122 INJECTOR ELCTRICAL PASS, KORR PASS, CYL. CONT. PASS, GLO. BEC. IV DIAB. PIN POINT TEST REPLACED FLIEL PEDAL

ENG PERFIDIAG, REPLIACCEL PEDAL

FUEL PRESSURE TEST 63 PSI EEC CONT POZZI PRIPOINT TEST FEI FEI NO VOLTAGE INCREASE ON IVS PID REPLACE AP SENSOR CLEAR CODES TEST DRIVE OK

RUN TEST 19 RAR TP ASSEMBOLY UNIT HAS ADJUSTABLE PEDALS ROAD TEST AND CLEAR MEMORY

ACCEL PEDAL ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

DEFECT ACCELERATOR PEDAL ASSY ENGINE PERFORMANCE DIAGNOSTICS 7.3L OI TURBO ENGINE DIAG

CHECKED FOR NO THROTTEL RESPONSE FOUND CODE P0220 AP BENSOR BAD, REMOVE REPLACE A P SENSOR

DIAG FOR THROTTLE INOP, FOUND 00221 FOR AP IVE CIRCUIT INOP FIN POINT TEST FEI FE3...REPLACE AP SENSOR

ENGINE PERFORMANCE TEST FOUND CODE PO221 PINPOINT TEST FE1 FE4 REPLACED AP PEDAL. THIRD TIME AF PEDAL HAS FAILED...

ENGINE PRAFORMANCE TEST 1 14 FOUND COOKS P0220 P0221 PINPOINT TEST PE1 FE3..REMOVE REPLACE A P PEDAL

USED NGS TO TEST SYSTEM.FOUND CODE P0221, PERFORMED PINPOINT TEST PER PCED.FOUND SHORTED ACCELERATOR PEDAL ASSEMBLY, R&R ASSEMBLY, TEST DROVE AND REMONTORED PIDS TSEST CK FUEL DID PERFORMANCE DIAG SHEET 1 THRU 14 PINPOINT ACCELERATOR PEDAL BAD REPLACED

ROAD TESTED WEH SEC TESTED KOED PARS KOER PASS CONT \$122 PERF THROTTLE POSITION SENSOR DIAG REPLACED THROTTL PEDAL REPLACED ACCELERATOR PEDAL ASSY

PERFORMINGS TEST FOUND TPS CODE POZZI. PERFORM PINPOINT TEST REPLACE TPS SENSOR FOOT PEDAL VARIFIED CONCERN IS FIXED CLEAR CODES

1 NRC TO EEC TEST, NO CODES, SWITCH TEST, GODE P0221, NEC TO REPLACE FAULTY THROTTLE SWITCH RETEST.

MEC TESTICODE POZZILNOS MONITOR ROAD TEST, PINPOINT TESTS, REPLACED ACCELERATOR PEDAL SENSOR ASSEMBLY,

CHECKED FOR TP PROBLEM. RAN KOEO KOBOCC OSTAINED CODE PO221. RAN PINPOINT TESTS, MONITOR PIDS. ROAD TESTED AND COULD NOT GET CO DE TO RESET. REPLACED RUN PERFORMANCE CHART, ALL PRESSURES & RUEL FLOW IN SPEC. RPL BAD THRUTTLE PEDAL ASSY, TEST DRIVE, RETEST SYSTEM, ALL PASS CODES.

18815 ACCELERETOR PEDAL. TEST DROVE TO VERIFY THE CONCERN. CONFIGNED, NGS TEST TO DIAGNOSE, PILLED THE CODES FOUND P0122 AND P0221 ACCELERETOR PEDAL NEED V DIAGNOSE, PILLED THE CODES FOUND P0122 AND P0221 ACCELERETOR PEDAL NESS. (BAD SWITCH PEDAL NESS.) (BAD SWITCH PEDAL NESS.) (BAD SWITCH PEDAL NESS.)

CC 42 9F836, 10368 M D. VERIFIED CONCERN, MGS DIAG. CODE P0221, PID MONITOR ROAD TEST FOUND AP VOLTAGE DROPING OUT, PIN POINT TEST TROVE DIAG CONCERN CHECKED CODES WITH MGS P0221 MONITOR PID ACCELERATOR PEDAL SENSOR HAS OPEN R R PEDAL ASSEMBLY

EEC VIDIAG, SELF TEST, CODE PO221, FUEL PUMP TEST (85 PBI), NGS DCL DISPLAY DIAG, NGS RECORD MONITOR, PINPOINT YEST, REPL. ACCEL. FEDAL ASSY...ROAD TEST, RETEST

TEST DRIVE AND PERFORM DIAGNOSIS AND PREPOINTS AND FOUND IVS NON FUNCTIONAL, REPLACED THROTTLE PEDAL ASSEMBLY. AND TEST DRIVE

CK ENGINE LIGHTON TEST POR CODES PO221, PAPCINT TEST, REPLACED ACCELLERATOR PEDAL A

EEC TEST, CODE P0221 EC PASS EOLER PINPOINT TEST, DCL DISPLAY NGS ROAD TEST MONITOR CHECK HARNESS FOR CPENS OR SHORTS NONE FOUND CONTACT. HOTLINE REVERIPED CHECK ENGINE LIGHT ON, PERF, WOS DIAGNOSO RETRIVE AND CLEAR CODES, KOER DATTALOGGER AND MONITOR ROAD TEST, PERF, PINPOINT TEST FE1 FE4. FOUND IF ROADTEST, PERFORM PRELIMINARY CHECKS, OKAY, TEST EEC, KOEO PASS, KOEO INJECTOR TEST PASS, KOEC PO221, GOTO PP TEST, FAULTY AP SENSOR, NOTE EQLIPPED WOIT IRUN PERFORMANCE DIAG CODE P0221 PO470 PIN PORT TEST REPLACED ACCELERATOR PEDAL ASSEMBLY REPLACED ESP SENSOR.

OPEN CIRCUIT REPLACE PÉDAL ASSY

EEC TEST, REPLACE GAS PEDAL ASSY

EBC TEST, PIN POINT TEST, REPLACE ACCELERATOR PEDAL & SENSOR ASSY, RETEST.

(MIXOBO PASS CONT PO221 KOER PASS PINAPOINT INSIDED DISPLAY AND ROAD TEST, MONITOR PIOS INTERMITTANTLY. IDLE VALIDATION GOES TO 0Y. MITIME TO REPLACE ACCELE PERPORMED DIAG CHART. TEST 1.4 OK. FUEL PRESSURE 60 PSLO RESTRICTION KOEO AND KOEO BUZZ P1000. RETRIEVE P0221, KOER P0221, P6DAL ASSY OPEN. REPLACED PEDAL ASSIGNEED AND VERIFIED COMPLAINT, RAN SELF TEST DIAGNOSIS WITH WIDS AND RECEIVED CODE P0221. FOLLOW PCED MANUAL REPLACE ACCELERATOR PEDAL CLEARED CODES 25465 ACCELORATOR PETAL BAD BF636 DIAGNOSIS DIGSEL ORIVABILITY CONCERN, CODE P0122 IN CONTINOUS, RAN PINPOINT TEST, MONOTORED PIDS REPLACED PETAL ASSY. CLEVENGINE PERFORMANCE STEPS 1.12 REPLACE PEDAL ASSEMBLY PEDAL ASSEMBLY OPEN SHORTED

INSPECTED AND TRACED TO THROTTLE PEDAL FAILED. INSTALLED NEW PEDAL ASSEMBLY AND RETEST. OK.

ENGINE PERFORMANCE TEST STEPS 1 2 3 4 5 9 PINPOINT TEST PO122 REPL THROTTLE PEDAL SENSOR ASSY

CHECK CODES POUND CODE FOR BAD TP BENSOR P0221 REPLACE TP SEASOR ROAD TESTED RECHECK CODES CLEAR 1

SOP PERFORMED PINPOINT TESTING, FAULT ACCELERATOR FEDAL ASSEMBLY REMOVED AND REPLACED ACCELERATOR PEDAL ASSEMBLY CLEARED

GENSOR INOP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG

INOP ENGINE PERFORMANCE DIAGNOSTICS 7:3L DI TURBO ENGINE DIAG

TECH PERFORMED NOS TEST, DTC PO123, PINPOINT TESTS, REPLACED ACCELRATOR PEDAL ASSEMBLY, RETEST, NO OTC. OK AT THIS TIME.

PERFORMED DIAG SHEET RAN PINPOINT, CALLED HOTLINE INSTALLED NEW FUEL HEDAL ASSEMBLY, ROAD TEST

TEST DROVE, VERIFIED CONCERN, PERFORMED TESTS, REPLACED ACCELERATOR PEDAL ASSEMBLY, RETEST, OK.

22874 42 PERFORM KOEO, KOER & PID TESTS, CODE P. C221 CON T. MEMORY, REPLACE ACCEL PEDAL PER. HOTLINE, RER UN NGS TEST, CLEAR MEMORY & VERIFY REPAIR.

RAN NOS TEST CODE ACCELERATOR PEDAL CIRCUIT LOW INPUT RAN PINPT TEST THROTYLE PEDAL BAD REPLACED PEDAL RAB QUICK TEST TEST DROVE.

ENGINE PERFORMANCE TEST, NECC TO REPLACE ACCEL PEDAL AND TP SENSOR, RETESTED

PCM QUICK TEST PIN POINT TEST FAULTY ACCELERATOR PEDAL POSITION SENSORREPLACE SENSOR AND PERPORM FINAL QUICK TEST

5825 TIME TO CK FUEL OIL OK CK AIR EXHOST. RESTRICTION OK RAN KOBO KOER OCL P0221 RAN. PINPOINT TEST FE1 FE7 TIME TO REPLACE ACCEL PEDAL CLEARD ALL CODES RO

BEC TEST CODE F0231, OPEN CIRCUT AT PEDAL ASSY. ORDERED NEW ADJUSTABLE ACCEL PEDAL ASSY INSTALLED PEDAL ASSY TEST DROVE OK

THROTTLE PEDAL SHORTED EEC TEST RECIEVED CODE ROAD MONITOR TEST FUEL PRESSURE TEST PHYTEST REPLACED THROTTLE PEDAL RETEST CLEAR ROADYEST.
38 PULLED THE ACELLERATOR OUT OF TRUCK RAIN PERFORMANCE SHEET PULLED CODE P0221 THEN REPLACED THE ACELLERATOR AND RETEST DROVE ALL IS FINE...

1 ENG PERFORMANCE DIAG VISUAL INEP-FUEL OIL LEVEL/INTAKE REST RICTION PASS, KOEO PASS, CONTINUUS CODES PO221, KOEO INJ. 61,6

WOS DIAG, START UP, SELF TEST, D.C.L. DISPLAY, PINPOINT TEST AND REPLACE PEDAL ASSY, ADJUSTABLE PEDAL ASSY, CLEAR AND RETEST.

VERFIED CONCERN CHECK ENGINE ON AND NO ACCEL RUN ENGINE PERFORMANCE TEST 1 8 AND 9 MONITOR ACCEL PEDAL SENSOR WITH PIDS ON NGS FOUND INTERMITTENTLY (

REPLACE TRIGAS PETAL SENSOR — ENGINE PERFORMANCE DIAGNOSTICS 7-31 DI TURBO ENGINE DIAG

14886 CC 42 9F838 } RUN THE PERFORMANCE SHEET 1.7 AND FOUND THE CODES POLZ2,P0221 IN CONTINIOUS.THIS IS A THRODLE PEDDLE ASSEMBLY. REPLACED THE PEDDLE ASS TEST DROVE TO VERIFY AT TIMES WOULD NOT ACCELLERATE. RAN ENG. PERFORMANCE TEST 1.8A B 14 SC CODE 0221, PINPOINT TEST F1 F7 REPLACED ACC. PEDAL ASSY RECHECK RUN BEC TEST CODE P0122 AND P0221 RUN PINPOINT TEST DD5 AND CD6 REMOVE AND REPLACE BTC ASSY CLEAR CODES AND ROAD TEST

CHECK AND REPLACE AP BENSOR

PERFORMED DIESEL PERFORMANCE DIAGNOSIS, FAIL REPLACED ACCELERATOR PEDAL ASSEMBLY DUE TO INTERMITTENT OPERATION.

1 PERFORMED DIESEL DIAG WORKSHIET PER ATACHED CODE PO221 MONTORED PIOS ALL OK PERFORMED PINPOINT TEST FOUND THE

DIAGNOSED FOUND PEAL ASSY CAUSING CONCERN R AND R PEAL ASSY RETIEST OK

RAN PRET 1 14, PETEST, PIONONT, ACC PEDAL LOSES SIGNAL AT TIMES. REPLACED ACC PEDAL POWER RETEST. CK.

29572 THROTTLE INOP, RAN NGS SELF TEST P0122. MONITORED DOLDISPLAY AP .38V, WILL NOT INCREAS WITH TP MOVEMENT, RAR THROTTLE PEDAL RETEST, CK.

ACCELLIRATOR PEDAL TEST DRIVE PERFORM DIESEL PERFORMANCE DIAGNOSIS TESTS 1 6 RECIEVED CODE P0122 PERFORM PINPOINT TESTS AS PER SHOP

PEDAL MALPUNCTIONING. PERFORMED KORO NO CODES PERFORMED BUZZ, PERFORMED KOER, PERFORMED ICP, INLET RESTRICTION, EXHAUST RESTRICTION,

MITTIME TO DIAG MAND REPLACE PEDAL ASSEMBLY

30396 PERITORIA DIESEL DIAGS KOEC POZZ1 PINPOINT TEST REPLACE ACCEL PEDAL ASSY RETEST ROAD TEST

9F836 CC 42 M Q 20366 VERRIFRED CONCERN, NGS DIAG CODE PO121, PIO DATA MONITOR, PINPOINT TEST FOUND THROTTLE PEDAL INTERMITENTLY DROPPING

18377 PERFORMANCE WHILE DRIVING DIAG, KOED, KOER, INJECTOR BLECTRICAL TEST, CYLINDER CONTRIBUTION ICP TESTS, CHANKCASE PRESSURE TEST, BOOST TEST, EXHAULT RAN EEC TEST, REPAIRED WIRE AND REPLACED ACC PEDAL.

PERFORMED THE NECESSARY TEST AND REPLACED THE TP SENSPR

NGS AND MONITOR PID FOUND IVS VOLTAGE INTERM INSPECTED HARNESS OK REPLACED PEDAL ASSY AND RETEST OK

REPLACE THROTTLE PEDAL ASSY.

1 TEST DROVE DUPLICASTED CONCERN, USED NGS MONITERED KOED AND KOER TESTES FOUND DTC PO221 FOR PEDAL A P SWITCH.

DIESEL DIAG, STEPS 1 14, CONTINUOUS MEMORY CODE PO221, PINPOINT TEST FE1 2,3,4, DIRECTED BY PPT TO REPLACE ACCELERATOR PEDAL ASSY, RETEST, ROADTEST, CONCERN OI VENIFIED CONCERN PERFORMED DIÈSEL DIAG DTC PO212 RNR ACCELL PECAL RETESTED CONCERN CORRECTED

7901 CC 42 9F836 I RUN MY PERFORMANCE DIAG SHEET 17 AND POUND CODES P0122,P0221 IN CONTINIOUS.! CLEARED ALL CODES AND REPLACED THE THRODILE PEDDIE ASSEME

ENGINE PERFORMANCE DIAGNOSTICS 1.3L DITURBO ENGINE DIAG

6772 (BF836) COND COCE (42) TK 3826 7.3L 4R150 434 (1) DIAGNOSIS COMBO EEC. TEST (2) PRIPOINT TEST (3) REPLACED ADJUSTABLE ACCELERATOR PEDAL ASSY, PERFORMED EI SESSECC 25 M OS264 VERRIFIED CONCERN, SELF TEST EEC SYSTEM CODE P2221 PIN POINT TEST INSTALL B.O.B. PIN OUT AP CATS PID DATA DISPLAY

OPEN CIRCUIT CC28 #8F635 DIESEL DIAG.P0221.PID MONETOR TEST DRIVE,PRIPOINT TEST.REPL GAS PEDAL

5544 (9C596) CC 42 7.3L DI VERIFIED CONCRN. PREFORMED DIESTIL PREFORMANCE DIAG. FOUND NORAMI. OIL LEVEL AND NO INTAKE RESTRINCTION, FOUND CODE PO221 IN COUT REPLACE ACCELERATOR PEDAL ASSY

BELF TEST, PPT TEST, MONITOR, REPL PEDAL, RETEST

ENGINE PERFORMANCE TEST, REPLACE ACCEL PEDAL SENSOR

INSPECTION POR CONCERN, RAN EEC TEST CODE P0221, MONITORED P1D DATA, REPLACED ACCELERATOR PEDAL, ASSEMBLY

CONNECTED TO WOS FOUND THROTTLE PEDAL INOP, REPLACED THROTTLE PEDAL FOR REPAIRS, TESTED, ALL OK.

PERFORMANCE DIAG. PINPOINT TEST, PO221, ACCELERATOR PEDAL FAILS, REPLACED ACCELERATOR PEDAL ASSEMBLY, RECHECKED, OK NOW.

COMPRIMILEAKS FLUID UNDER DASH ACCELERATOR PEDAL SOLENOID LEAKING REPLACED PEDAL ASSY

PERFORMANCE TEST 1 14 REPLACED PEDAL ASSY IN UNIT SHORTED

TP SENSOR OPEN CIRCUIT

ACCELERATOR PEDAL IVS THROTTLE SWITCH B CIRCUIT FAILURE PERFORM TESTS PER DIESEL ENGINE PERFORMANCE SHEET, DTC POZZ1 REPLACE ACCELERATOR PEDAL ASSY,

REPLACED FUEL PEDAL ASSY

13308 IDLE VALIDATION SWITCH RAN QUICK TEST FOR COLLOTC PO221 IVS OUT OF RANGE FOLLOWED PPY FE1. THRU FE7 LEAD TO REPLACEING GAS PEDAL IVS ASSY, R.R. IVS ASSY.

VERIFY CONCERN FOR DASH LITE ON AND ACCELL,CODE P0221 PRESENT,NECC TO REPLACE IDLE VALADIATION SWITCH

APP SENSOR OPEN CIRCUIT CONNECT WOS NO VOLTAGE CHANGE AT APP SENSOR REPLACE APP EBROOR RETBET OK AT THIS TIME

NGS TEST NO CODES NGS KORD AND KOER INJECTOR SELF TEST NO CODES BOOST PRESSURE TEST 16 1 2PGI 2400RPM EXHAUST BACK PRESS 28% CYC CONTRIBUTION PASS CHI VERFIED CONCERN, HOCKED UP WOS AND PERFORMED SELF TESTS AND RETREIVED DTCS FOR TP TOO HIGH LOW. MONITORED DATALOGGER AND REPLACED TPS ASSEM, #9F836 ROAD TESTING WIS DIAG NO CODES, ROAD TEST W WOS, FUEL PRES TESTING, DIAG & REPLACE ACCEL PEDAL ASSY. ROAD TEST OK

ELECTRONIC DIAG PO22: PINPOINT TEST REPLACED INTER ENGINE COOLANT SENSOR

1 PERFORMED ENGINE PERFORMANCE DIAG FOUND CODES FOR AP REPLACED AP

TP SENSOR SHORTED PERFORMED DIESEL PERFORMANCE DIAGNOSTICS TP SENSOR SHORTED REPLACED THE TP PEDAL ASSY, TO CORRECT CONCERN

30605 120600 DT D45 DX1. A HRS YESTED WITH NGG GOT P0221 PINPOINTED TO BAD TP ASSEMB, PEPLACED TP ASSEMB AND 1897 DROVE TRUCK WORKING FINE.

DIAG AND REPLACED FUEL PEDAL ABSY

CIAS PEDAL ASSEMBLEY

REPLACED GAS PEDAL ASSENDLEY

DI DAIG 1 14, PINPOINT TEST, RR THROTTLE PEDAL ASSYM, ROAD TEST OK

PERFORMED ENGINE DIAG TESTES AND REPLACED ACCEL PEDAL

WIRING HARRESS CHAFFING ON FRAME AT SHOCK TOWER SHORTED ACCELATOR PEDAL ASSY, 7.3L DI AUTO RUN PERFORMANCE DIAG.1 14 PINPOINT TEST CODES(F1531,P0221), CHECKED CODES, HAD CODES FOR THROTTLE PEDAL. CHECKED SYSTEM, FOUND BAD PEDAL ASSEMBLY, REMOVED, AND REPLACED THROTTLE PEDAL ASSEMBLY, ROAD TESTED, OK.

ILDE VALIDATION SWITCH SHORTED, ROAD TEST TO VERIFY CONCERN. NGS EEC TEST P0122.P0221, DCL DISPLAY, PINPOINT TEST DD AND FE, REPLACE SWITCH, EEC RETEST AND CONFIRM CONCERN, PERFORM PERFORM SENSOR FAILING, MAKE ACCESS TO & REPLACE PEDAL AS

HAND START INDISTART DIAGNOSTICS 7.3L DITURSO ENGINE D GAS PEDAL ABSEMBLY INOP

HARD START NO START DIAGNOSTICS 7.3L DITURBO ENGINE D RAS PEDAL ABBENELY INCP

14890 WF 36 36 6F536 42 RAN QUICK TEST, FOUND GOOR P1211 T P SWICH FAILTHROTTLE PEDAL DID PINPOIN T TEST FOUND INTERMINTENT OPEN SHORT WHILE DEPRESSING PED D35,42,9F856 BEC TESHED HAD CODE FOR TP SENSOR CHECKED OVER AND PINFOINT TEST AND FOUND OPEN IN 8+ WIRE TO SENSOR REPLACED ACCEL.

ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG INTERMITTENT OPERATION

COKED OUT ADN REPALCED THE

SYSTEM CHECK OUT PERFORM DISSEL GIACKOSE AND PERFORM ESC TEST PO122 PO221PMPIONT TEST CIRCUIT YEST BLECTRICAL TEST REPLACE TO SEASOR CLEAR CODE RO VERIFY CONCERN, CK FOR CODES WITH NGS, CODE P0221, RUN WOS TEST, PINPOINT TEST, FOUND BAD FUEL PDEAL SWITCH, REPLACE ASSY, RETEST OK.

EEC TEST CODE P0221 R R SENSOR/PEDAL ASSY

PEDAL ASSY SHORT TO GROUND REPLACED PEDAL ASSY TO CORRECT THE PROBLEM

DIAG KOSO POZZI RE FITO PIN POINT TEST E1 MONITOR MS PID REPALCE FAULTY ACCELL PEDAL MT TIME NO GPS TO REPALCE PEDAL

ESC TEST, REPLACE ACCEL PEDAL ASSY

THROTTLE PRIDAL ASSEMBLY REPLACE NO SLO INOP

11682 9F836 42 NGS TEST P0820 TP(B) RANGE MALF ORDERED NEW TP ASY, INSTALLED NEW PEDAL ASSY TESTED OK

PERFORMED EINIGHTE DIAGNOSTICS VISUAL ENGINE INSPECTION, BUFFICENT CLEN FULL CHECKED ENGINE OIL, INTAKE RESTRICTION, PEPLACED THE PDS AND SNS ASSEMBLEY. T

EEC TEST, REPLACE ACCEL PEDAL SENSOR

10525 THROTTLE SWITCH ON PEDAL WARRINGS TEST CODE PO221 PIN PONT TEST OC 1 THRU QC 19 REPLACE PEDAL RETEST TEST DROVE 9F836 CC 42

5109 PROSECC 42 TEST DROVE AND CHECKED BEC. BYSTEM REMOVED AND REPLACED ACCELORATOR PEDAL ASSEMBLY RETESTED SYTEM AND TEST DROVE. CHECK ENGINE LK THROTTLE RESPONCE INTERMITTENT. REPLACE THROTTLE ASSEMBLY DUE TO MITME IN FORD.

22676 ROAD TEST AIL LIGHT ON NO POWER ON ACCEL DIESEL PERFORMANCE DIAG SHEET KOED PASS P0221 KOER P1501 CYLINDER CONTRIBUTION TEST PASS INJECTOR SELF." VERIFY CHECK CASIS KOSO TEST PASS KOSO TEST PO221 KOER TEST PASS CHECK FUEL PRESSURE BOTH HEADS AND PUMP VERIFY 65 PS;

25754 (9F826) CC 42 7.8L DI VERIFIED CONCERN. PREFORMED DIESEL PREFORMANCE DIAG FOUND CLEAN FUEL, OIL LEVEL WITHIN SPECS AND 4 IN OF INTAKE RESTRICTION. FOUN

DIAG. MITIME TO REPLACE PEDAL. BINGING PERFORMANCE DIAGNOSTICS. 7.3L DI TURBO ENGINE. DIAG RAN EEC TESTS ON WOS. P0123, AP CIRCUIT OPEN, RAN PINFOINT TESTS USING DATALOGGER MONITOR. FOUND PEDAL ASSEMBLY OPEN REPLACED PEDAL ASSEMBLY, CLEARED (202 42 CHECK TRUCK ACCELERATER PEDAL DOES NOT WORK AT ALL CHECK CONNECTERS AND PEDAL IS FILIGED IN. RUN PERFORMANCE DUAGNOSTIC TESTS 1 14 AND FOUND (

CHECK DIESEL ENGINE PERFORMANCE PINPOINT TEST DCL MONITOR REPLACED ACCELERATOR PEDAL DIAG, VERIFY PROS, EEC CHECK SYS, NO CODES, MONITOR PIDS, IDLE VALIDATION SWITCH NOT OPERATING INTERMITTENLY, CHECK CASIS, CALL HOTLINE, HOTINE SAID CHECK HARNI

FALLED TO SENSOR AND PEDAL ASSY. TEST DIAGNOSE AND REPLACED TOS AND PEDAL

9F856 42 ROAD TEST FOR CONCERNAT TIMES WHEN ON ACCEL ENGINE WOULDN'T RESPOND. EEC TEST CONT. CODE P0221 MONITORED AP, IVS AND VREF WITH NGS FOUND AP RE 13225 6005F .2 F1 .1 F2 .1 F6 .1 F7 .2 F8 .1 F8 .3 F10 .1 F11 .2 F12 .3 F13 .1 F14 .1 F16 .5 F17 .5 F18 .5 F19 .2 043208 2.1 MT 3.9 TO REPLACE OF 638 AND CIRC.REPAIR.TOTAL 9.7 ENG.PERF NGS BEC TEST POZZI, PIO DATA DISPLAY, MONTOR AND RECORD, AND PLAYBACKDATA, INJECTOR ELECTRICAL TEST, INSPECTION CONTROL PRESSURE TEST, LOW IDLE STABILITY VERIFY ENGIONLY IDLE ENGIPERFOMANCE DIAGLES TO PINPOINT TEST APC OS IVS AP CONNECTOR OK REC TO PINPOINT TEST FEI MONITOR #5 PID REPLACE FAILY ACCEL PEDDAL 28,97836 REPL THROTEL PEDAL ASSY PER 8 M CHECKED CODES & NO CODES PRESENT AT THIS TIME

2 PERFORM DIESEL DIAG STEPS 1 19, NO MIL, ALL TESTS PASS, ROAD TEST TO FIND ERRATIC SIG RTN FROM TP SENSOR, REPLACE ACCEL PEDAL ASSY & RETEST & ROAD TEST V 59 ACCELLERATOR PEDAL DEFECTIVE.INOP, RAM PERFROMANCE SHEET, DIAGNOSSO THE ACCEL, PEDAL TO BE DEFECTIVE, THEN REPLACED THE PEDAL ASSY AND ADJUSTED TH ACCEL MODULE AND PEDAL ASSEMBLY PRESENTED COROVE VEHICLE VERIFIED CONCERN. ACCEL PEDAL INOP. USED NGS RAN ON DEMAND SWITCH SELFTEST, DTCS INDICATED ACCELERATOR PEDAL OPEN GRICUIT DODE 0221 9F836 PERFORMANCE DIAG 1 6 CODE 0221,RR ACCELERATOR PEDAL CUEAR CODES ROAD TEST TO VERIFY REPAIR OK 13048 ACCEL PEDAL ASSEMBLY INOP AT TIMES, 126500, DX1, D45, MITIME 0.3 DIAG ENGINE IDLES AND CK. ENGINE LIGHT COMES ON FOUND CODES PC122 AND PC221 IN KOEO CO! REMOVE AND REPLACE ACCELERATOR PEDAL, CLEAR CODES AND ROAD TEST OK

SERVICE BAY DIAGNOSTIC BYSTEM (SSDS) START UP TEST

INOP MT DIESEL DIAGNOSIS FIN POINT TEST REPLACE GAS PEDAL SENSOR ASSY

MIL ACTIVATION VERIFIED PERFORM STEPS 1 17 PERFOR DIAG CONT. DTC PRO21 VIEW DCL DISPLAY NPF AT THIS TIME ROADTEST W WDS DATLOGGER VEHICLE LOSSES POWER TP 1 WDS TESTED, KORC PO122, PO221, REPLACED FOOT PEDAL, TP SENSOR SHORTED, RETEST ADJUST PEDALS.

TEST DROVE VEHICLE FOR CONCERN,CHSCKED FOR CODES,CODE P0221 THROTTLE FEDAL,PIRRYDRAMED PINPOINT TEST,RAN PIDS ON THROTTLE PEDAL,PINPOINT TEST ADVISED YEARING PERFORMANCE DIAG, PINPOINT TEST, REPLACE ACCELERATOR PEDAL SENSOR ASSEMBLY, MT TIME TO REPLACE SENSOR NO LABOR OPERATION.

PERFORM (SEC TEST. FOUND BAD ACCELLERATOR PEDAL REPLACED PEDAL AND RECHECK

PINPOINT TEST INTERNATITIENT OPEN IN THROTTLE PEDALOTTLE NON RESPONSIVE, EEC TEST PO221, TP SENSOR, CHECKED AND VERIFIED CHECK ENGINE LIGHT ON AND THROFOSE 20756 TP SENSOR 26 W CHECK VEHICLE FOR CUTS OUT NO ACCCEL PERFORMINGS SELFTEST HAS NO CODES. PERFORM FUEL PRESSUR E TEST ALL PASS, MONITOR, PIDS AND FORECK ENGINE LIGHT WAS ON FUN QUICK TEST, FUN THRU PPT PEI FOUND AND REPLACED ACCEL PEDAL INOP. RERUN QUICK TEST ALL P1111

WIRING ASSEMBLY REPAIR

WOS TEST, RAN PERFORMANCE DIAG TEST 1 14 AND RECIEVED CODE PROZZ1, PERFORM PINPOINT TEST, DIAG AS FAILED T.P. SENSOR, REMOVED AND REPLACED PEDAL ASSEMBL'
PERFORMED ENGINE PERFORMANCE DIAGN 1 19:REPLACE DIAGNET PEDAL ASSY FOR KOED, KOED, KOED, FOZZ1, NO OTHER PROBLEMS FOUND.

25508 RAN BILLY TEST PO221, KOEO PASS, ACCEL PEDAL INOP AT TIMES. RAN PINPOINT TEST AND COL DISPLAY AP OK, IVS SAYS OFF WHEN ACCEL RER ACCEL PEDAL ASSEMBLY.
7623 VIEN BURGES AND HESITATES WHILE DRIVING TEST DROVE VEH. VEH SURGES AT LOW AND HIGH SPEEDS, RAN ALL KOEO TESTS, SYS PASS. RAN ALL KOER TESTS, SYS PASS.
NGS TEST, PO221, REPLACED TP PEDAL ASBY, NETEST, PASS.

CEL EEG (QUICK TIEST) DIAGNOSIS

EEC TEST PO221 MONITOR PIDS ON TEST DRIVE RER PEDAL ASSY AS NEEDED

RUN TESTS, REPLACED ACCEL PEDAL ASSEMBLY

ROAD TEST FOUND NO POWER STEP ON GAS PEDLE NO ACCELERATION NGS TEST FOUND CODES P0238 P0221 P1211 PREFORMANCE FEUL PRESSURE AT THE LEFT HEAD. FUEL PRIVATE TO GRO RER BENECK AND RE TESTED OK

8878 CHECK BAGINE LIGHT ON AND ENGINE HESITATES PERFORMANCE DIAG CHECKED ENGINE FUEL OIL LEVEL AND INTAKE RESTRICTION ALL OK KOSO DEMAND TEST PASS RET

NEC TO INSPECT AND PERFORM QUICK TESTS, FOUND CODE PO221 INTERMITANT OPEN IN THE PEDAL ASSY, NEC TO REPLACE PEDAL ASSY AND RETEST, CK NOW

PAILED AP SENSOR

PIN POINT TEST DIAGNOSIS

PARTS HAVE BEEN SPECIAL ORDERED

OFRIS 42 PERFORMANCE TEST, MEPLACED ACCELERATOR PEDAL ASSEMBLY.

RUNN EEC TEST FOUND THROTTLE POSITIONING BENBOR BAD REMOVE AND RELACK SENSOR REPEAT FINAL QUICK YEST CLEAR CODES

PERFORMANCE DIAGNOSTICS, REPLACED ACCELERATOR PEDAL ASSY

ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE

RUN OBD11 SYSTEM TESTS, P0221 IN CONTINIOUS MEMORY, PERFORM PINTESTS. TEST AND REPLACE ACCELERATOR PEDAL ASSEMBLY, PER INOP AT TIMES WONT ACCELERATE EEC CK AND PINPOINT TEST FOUND ACCELETATOR PEDAL ASSY OPEN CKD AND NECC TO REPLACE THE ACCELERATOR PEDAL ASSY RECKD AND CLEAR OTCS

SP838 28 BEC TEST RETRIEVED CODE P0221 PINPOINT BLECTRICAL OPEN CIRCUIT IN PEDAL TP. REPLACED PEDAL ASSEMBLY ADJUSTABLE. FINAL OU

FALTY THROTLE TO BENBOR NESSARRY TO REPLACE PEOLE ASSEMBLY INSTALLED NEW THROTLE PEOLE ASSEMBLY ROAD TEST AND RE CHECK NORMAL OPERATION AT THIS TIME ORDERED FOR CHECK ENDINE LITE ON, CODE P0271. REPLACE PEDAL AND RECHECK, OK.

28725 CHECK FOR CHECK ENGINE LIGHT COMES ON AND ACCEPATOR PEDAL QUITS WORKING HOOKED TO NOS RAN SEC TEST SYSTEM PASS PID DATA MONITOR ROAD TESTED VICEO TEST AND RUN DOLDISPLAY. REPLACE ACCELERATION PEDAL ASSEMBLY.

BOAN AND RETRIEVE CODES FROM ELECTRONIC CONTROL SYSTEM/PO221 PIN TEST PASS, INSPECT CONNECTORS & WIRES PASS, APPLY REPLACE A P WITH SPECIAL ORDER PART AP SWITCH 9F538 DIAG 1 6, PERDRIME PINPOINT TEST ON AP SWITCH, RR SWITCH, TEST DRIVE OK

CC 28 9PH 97895 PERFORMED VISUAL INSPECTIONS NOS SETUP, PERFORMED PERFORMANCE DIAG STEPS1 14 PER DIAG SHEET, RECIEVED CODE P0221, PERFORMED PINPOINT TEST 25895 CHECK OUT, VERIFY WONT ACCEL AT TIMES, PERFORM 7.3L DI DIAGS, KOEC P0122, PINPOINT TESTS, PERFORM FLIEL SYSTEM TESTS, ALL FLIEL TEST PASS. PINPOINT TEST PARK ON NOS. GOT CODE FOR THROTTLE POSITION SENSOR BAD. RER TPS ASSY.

DIEBEL DIAGNOSIS

DIAG SYSTEM WITH DESIL DIAG AND REPALCEPART

ACCELERATOR PEDAL SENSOR ERRATIC WHEN PINST POWERED... DIAGNOSIS AUTO TRANSJOKING CODES, INSTALLINGS AND MONITOR PIDS, FOUND AP CIRCUITS OUT OF RANGE.P 21726 ACCELERATOR PEDAL 28 WR VERIFY CONCERN AND RUN PERF DIAG TEST, 6005F 6009F1 18. HAD MEMORY OF P0221, RUN PRPOINT TE ST AND LED TO INOP PEDAL ASSEMBLY ACCELERATOR PEDAL ASSEMBLY RAN EEC, TEST, CODE P0221 PRESENT, MONITORED WITH NGS. POUND A P PID TO GO TO ZERO, INTERNAL OPEN IN 5WIYCH, INST.

22563 FUEL PEDAL ASSEMBLY 25 WR VERIFY CONCERN AND RUN PERF DIAG TEST 8006F 8005F1 19. HAD MEMORY CODE POZZ1, RUN PINPORT TEST AND LED TO INOP FUEL PEDAL VERIFIED BY ROUND GOOD TO CODE POZZ1 KOEO IN GLEC SELF TEST PAS INSPECTED, WOS HOCKLIP, KOEO ON DEMAND, POZZ1, PINPORNT TEST, CIRCUIT TEST, REPLACED TP AND RETESTED AND TEST DRAVE

2 PERFORMED THE BEG DIAGNOSTS AND FOUND DATA CODE PO221FOR THE CALE VALIDATION SWITCH. REPLACED THE PEDAL ASSY AND

FUN NGS TEST, CODS P0122, TEST & REPLACE ACCELERATOR PEDAL ASSY.

RAN NGS TEST ACCELERATOR PEDAL BENSOR LOW INPUT RAN PRIPT TEST. REPLACED THROTTLE PEDAL REYEST

ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG

BINDING BEC (QUICK TEST) DIAGNOSIS

PERFORMED EEC TEST PID MONITER FOUND ADJUSTABLE ACCELERATOR PEDAL NOT OPERATING PROPERLY, REPLACED PEDAL ASSEMBLY, RETESTED OK NOW.

EEC TEST, CODE PO122, PO221, REPLACE PEDAL, RETEST.

ROAD TESTED, ENGINE PERFORMANCE DIAGNOSTICS, REPLACED PEDAL ASSY.

97826 42 ROAD TEST FOR CONCERNS AT TIMES THERE WAS NO RESPONSE WHEN TRYING TO ACCELL AND CHECK ENGINE LIGHT COMES ON PERFORMED DIESE. DIAG FUEL PRESS REPLACED PEDAL AND BENSOR ASSY CLEARED DTC RETEST OK ROAD TEST OK

1 FOUND ENGINE LIGHT ON LIBED NOS TO DIAGNOSE CODE F0221 USED PID MONITOR ON ROAD TEST TO PIN POINT TO A BAD ACCELARATOR

15815 BASE WARR.....CC:42.....FP:TP SENSOR TEST DRIVE TO VERIFY CONCURN VEHICLE BUCKS AND JERKS WHILE DRIVING PERFORM DIESEL DIAG PERFORMANCE STEPS 1.19 IC.
USED NGS AND MONITERED MEMORY, KOEO.KOEN TESTES DTC FOR A P SWITCH, MONITERED PIDS, DUPICATED LOSS OF SIGNAL, COMPLETED

INTERNATION AP AVECIRCULT MAILURES, KOEO PASS, KOEO PASS, KOEO PASS, INDI EL PASS, INDI EL PASS, VERIFY INTERNITTENT FAIL URE. NO RESPONSE FROM AP, REPLACED ADJUL KOEO PASS KOEC POZZI KOER PASS ELC TESST PINPOINT ROADTESWT MONITOR APP PID AND IVS PID DROP OUT INTERNITTENTLY REPLACE AP SENSOR ASSY RETEST PABACK ORDER THURSDAY OR FRODAY, INSTALL SOP RETEST, VERIFY REPAIR

PERFORM NO START DIAGRICOSTING AS PER SHEET, PINPOINT, NO VILET ISTALL BREAK OUT BOX FOUND ACCELERATOR PEDAL POTENTIOMETER

16914 126960 D1 D1X1 D45 D61 1.5 TESTED WITH NGS RECEIVED CODE P0221 RADD TESTED TO MONITOR AP REPLACED TP SENSOR.

ENGINE PERFORMANCE DIAG REPLACED ACCELERATOR PEDAL

9F838 42 CC M C 7186 VERIFIED CONCERN, MG8 6ELF TEST EEC SYSTEM, CODE P0122, PID MONETOR ROADTEST AP PID, AP VOLTAGE DROPPING CUT ON

NECESSARY TO REPLACE PETAL ASSEMBLY & MAP SENSOR OK NOW

INSPECTED AND TESTED RETRIVED CODE PO221 FOR TP SESCR REPLACED AND RETESTED OK

IDLE VOLIDIATOR SWITCH EEC (QUICK TEST) DIAGNOSIS

NGS TEST, DC. DISPLAY, INSTALL BOS AND CHECK WIRING FROM PCM TO TP SENSOR, OK. PINPOINT TESTS, TP SENSOR ERRACTIC, INTERMITTANTLY OPEN, REPLACE TP ASSEMBLE SECTEST KOSO DTC PO221 PINPOINT AND REPLACE PEDAL ASY REPOAD TEST ALL NORMAL.

GAS PEDAL ASSY ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG.

6826 CHECK OUT, VERIFY CK ENGLITE COMMO ON, PERFORM 7.31, DI DIAGA, KDEC PO122, PINPOINT TESTS, PERFORM FUEL SYSTEM TESTS, ALL FUEL TESTS PASS. PINPOINT TEST, COOR PO221 PINPOINT TEST, DIESEL ENGINE PERFORMANCE TESTS PER ATTACHED SHEET, REPLACE AP SENSOR AND PEDAL ASSY REPLACE PEDAL AND SENSOR ASY

1 DIAGNOSE DEPECTIVE PEDAL GENSOR ASSY REPLACE RETEST OK COAS

AP SWITCH MALFUNCTIONING. PERFORMED SBDS DIAG, NO CODES, PERFORMED FILE TEST, PERFORMED PID DATA DISPLAY, TEST DROVE WHILE MONITORING.

1 KAN ALL DIESEL PERFORMANCE DIAGNOSTICS, PINPOINT TEST, REPLACED ACCELL PEDAL ASSY, RETESTED OK

REPLACE TO SENSOR

18707 SP636 ENGINE PERFORMANCE DIAG.TO VERIFY CONCERNOF LOSS OF POWER.6005F TO.2 KOED 6005F1 PO122,P1212 PINAL QUICL TEST 6005F1X1 TO.1 INJECTOR CONTROL P ENGINE WOULD NOT ACCELERATE, PERFORMED EEC TEST KOED P1111 KOEC P0221 KOER P1111, PINPOINT TEST LEAD TO AP SWITCH, REPLACED ACCELERATOR CABLE.

RAN NGSJOCL TOTA TRACED TO BAD BENSOR ON PEDAL REPL PEDAL ASSY RETAIT

1 PERFORMED SEC TESTS, COOES PO221 IN CONTINUOUS, KOSR P1531 WITH NO THROTTLE PEDAL MOVEMENT, REPLACED THROTTLE PEDAL ASSEMBLY DIAGNOSED AND REPLACED ACCELERATOR PEDAL.

NGS TESTED FOLAD THROTTLE POSITION SENSON SAD REPLACED PETAL ASSEMBLY ADJUSTED PEDAL RETEST AND ROADTEST TAD

RAN NGS TESTS RETRIEVE, KOGO, KDER, INJECTOR BUZZ, AND CYL. CONTRIBUTION. GAVE CODE POZZI FOR THE TP RANGE PERF. REMOVE AND REPLACE ACC PEDAL RETEST ALL I TEST ENGINE CONTROL SYSTEM MITIME TO REPLACE ACCEL. PEDAL

ACCELERATOR PEDAL IN OP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

REPLACE ACCEL PEDAL POSITION SENSOR

DOES NOT OPERATE PROPERLY SEC (QUICK TEST) QUAGNOSIS

CK ACCELERATION RUN TEST OBDII REPLACED TP

PETAL ASSEM ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI YUNGO ENGINE DIAG

6218 PERFORMED POWERSTROKE PERFORMANCE DIAGNIOSTICS, PERFORMED PINPOINT TESTS FOR CODE P0221 IN MEMORY, ORDERED ACCELERATOR PEDAL, REPLACED ACCELERATOR PEDAL, RAN DIAG RAN PINPOINT TEST REPLACED PEDAL ASSY HAD ADJUSTABLE RETEST TRUCK RITINSPECTED, AT TIMES JUST FOR A \$500ND HAD NO THROTTLE, RAN DIAG 64-EET 114. PASSED, MONITOR PIDS AP SENSOR AT PART THROTTLE WOULD GO TO 0 THEN BACK AGAIN 1200 CK ENGINE LIGHT COMES ON WARR DIESEL DIAG 1 6 CODE 0221 REMOVE PCM TEST CKTS REPLACE THROTTLE PEDAL ASSY ERASE CODE RD TEST & RETEST. HAD DAVE FOR TAST CKTS REPLACE THROTTLE PEDAL ASSY ERASE CODE RD TEST & RETEST. HAD DAVE FOR TAST CKTS REPLACE THROTTLE PEDAL ASSY ERASE CODE RD TEST & RETEST. HAD DAVE FOR TAST CKTS REPLACE THROTTLE PEDAL ASSY ERASE CODE RD TEST & RETEST.

PERFORMED ALL PERFORMANCE DIAGNOSTICS AND ONLY FOUND THE THROTTLE POSITION SENSOR OUT OF RANGE, PERORMED PINPOINT OPEN OR INTERMITTENT OPEN IN THOT

TRUCK WOULD NOT RUN HAD TO REPLACE THROTTLE PEDAL

CHK BNG. LIGHT ON AND WILL CKLY IDLE AT TIMES, RAN PART OF PERFO SHEET OTC POZZITP(S)RANGE PERF, USED POED MANUAL PIN TEST FEI DOES IVS PIP READ ON NO GO TO I NIKOGO PASS CONT POIZZ KOER PASS PINPOINT NGS DOLDISPLAY AND ROAD TEST MONITOR PIDS ACCE PEDAL WONT COME OFF IDLE. MITIME TO REPLACE ACCEL PEDAL, OPEN I DIAGNOSE EEC, RISTEST, PINPOINT TEST, NGS DOLDISPLAY, NGS MONITOR RECORDER, REPLACE ACCELERATOR PEDAL ASSEMBLY, D.K. AT THIS TIME.

CHECKED FOR CODES WITH NGB, CODE POZZI PERFORMED PINPOINT TEST QC13 QC19. TEST FAILED, ISINTALLED ACCELERATOR PEDAL ASSEMBLY, CLEARED CODE AND TEST DROVE PEDAL ASSEMBLY, CLEARED CODE AND TEST DROVE.

2959 VERIFIED CONCERN RUN CONT, KOED INJ BUZZ, KOER, AND CYL CONTITESTS CODE P0221 POLLOW PINPOINT STEPS TO BAD ACCELERATOR PEDAL REPLACE ACCELERATOR PEDAL REPLACED ACCELERATOR PEDAL REPLACE ACCELERATOR PEDAL REPLACE ACCELERAT

INSP, FOR ENGINE LACKS POWER ACCELERATOR PEDAL ABBIENOLY ADJUSTABLE REPLACE

CC 42 9FB36, 14785 M C, VERIFIED CONCERN, NGS DIAG. CODE P0221. DATA MONITOR AP AND IDLE VALDATION SWITCH, AP SIGNAL IRRATIC, PIN POINT

7900 ACCEL PEDAL ASSEMBLY BAD, 12850D, DX1, DIS, ACCEL PEDAL OR MITME 0.2 DIAG CK ENGINE LIGHT. FOUND CODE PO221 IN KOEO CONTINUOUS, PERFORMED PINPOINT DV

INOPERATIVE SERVICE BAY DIAGNOSTIC BYSTEM (3808) START UP TEST

OR CLEAR CODES RETEST OK NOW

9855 CHECK OUT, VERIFY WONT ACCEL AT TIMES, PERFORM 7.3L DI DIAGO, PERFORM FUEL SYSTEM TESTS, ALL FUEL TESTS PASS, KOEC PO221, PINPOINT TESTS FOUND TP SENS DIAGNOS CK CODIES MONITOR PIGS REPLACE TP SENSOR RETEST

RUN ENG PER FTEST REPAIR CODE PO221 REPLACE PEDAL ASSY CLEAR CODES RUN PINPOINANT TESTO

DIAG. FOUND ACCEL PEDEL BENSOR REPLACE PEDEL ASSY AND RETEST

24210 TEST DRIVE AND VERIFIED CUST CONCERN PERFOR ENGINE PERFORMANCE DIAG. PERFORM KOED TEST FAIL PC221 REPLACE FUSI. PEDAL AND TEST DRIVE AND PERFORMANCE DIAGNOSTICS STEPS 1 THRU 12 R&R ACCEL PEDAL ASSY; CLEAR CODE AND ROAD TEST "NOTE CROERED PART ON I 1889 PREFORM R T AND VAIR. C C 1 TIME RAN CASIS AND PREFORM SSN 15412 AND CALL HOT LIND TALK TO MIKE ZEXDBO18 CASE FAND RECHECK WIRING FROM GAS PEDIL TO FRAN TEST, POUND TO SWITCH AT FAULT, REPLACED

VERIFIED CONCERN PERFORMED DI DIAGNOSIS CODE POZZI REFLACED FAULTY GAS PEDAL RETEST ROAD TEST OK

17626 FAULTY ACCELERATOR PEDDAL 6005F.2F1.1F1X1.1F2.1F7.2F8.1F8.3F10.1F11.2F12. 3F13.1F14.1F16.6F17.3F18.5F19.2, 2450F.4 VERIFIED CONCERN DIAG PID TEST CODES P0122: 8HORTED REPLACE PEDAL ASSEMBLY

MT CHECKED CONCERN, PINPOINT TEST, REPLACED PEDAL ASSEMBLY AND RETEST

DOES NOT OPERATE PROPERLY ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

VERIFY, PIMPOINT TEST, INTERMITTANT OPEN IN PEDAL SWITCH, REPLACE PEDAL ASSY.

13324 PEDAL ASSEMBLY TEST DROVE OK FAN NOS HAD CODE PO221 PERFORMED PINPOINT TESTS MONITORED FIGS REPLACED ACCEL PEDAL ASSEMBLEY REICH OK

CONDITION CODE 48 SEC (QUICK TEST) DIAGNOSIS EXTRATIME TO REPEAT FINAL QUICK TEST PIN POINT TEST. DIAGNOSIS REPLACED LEFT FRONT AND RIGHT FRONT!
ROAD TESTED TO VERBY CONCERN.EEC TESTED, MONITORED PIOS TO PINPOINT, TEST. MT PERFORMED DIAG PER HOTLINE INSTRUCTION. MT REPLACED THROTTLE PEDAL AND SET 5770 OPEN IN AP SWITCH NOT CHANGING STATES REPLACE ACCELERATION FEDAL ASSY & RE 10057 INSPECTED AND TESTED VEHICLE FOR THE ENGINE HESITATION, UNDER ACCELERATION, RAN PERFORMANCE TESTS TO DIAGNOSIS. PMPOINT TESTING RESULTED IN FINDING 3105 INSPECTED AND TESTED VEHICLE FOR HAVING A HESITATION, RAN PERFORMANCE TESTS, PINPOINT TESTING RESULTED IN FINDING THE THROTTLE POSITION SENSOR INTE

CK ENGINE LIGHT CAME ON

DIAGNOSE, CODES P1221, RAR ACCELL PEDAL ASSY

MGS EEC TESTED PINPOINT TESTED WIRING OK CONNECTIONS OK REPLACED PEDAL ASSY CLEARED CODE

REPLACE ACCELERATOR PEDAL ASSEMBLY

RANGEC TEST AND RETRIEVED CODE PO 221 MADE MIN POINT TESTS AND FOUND ERATIC OPERATION OF IVS SWITCH, REPLACED THROTTLE PEDAL ASSEMBLY RETEST AND TEREPLACED THROTTLE PEDAL

CK ENGINE LIGHT ON

ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE CIAG

OPEN CIRCLIT TO SENSOR

42 ROAD TEST, CKD, EEC SYSTEM, DO PINPOINT TESTS, REPLACED ACCEL, PEDAL AND RETEST AND ROAD TEST. OK

PERFORMED EEC TEST, CODE PO221 IS PRESENT, PID MONITOR DISPLAY AND RECORD INDICATE A REPLACED PEDAL AND RETESTED, PASSED, ERASED CODE.

DIAGLEEC TEST, RIP PEDAL ASSY, TESTS OK.

ERRACTIC

EEC (QUICK TEST) DIAGNOSIS

11260 OPEN IN AP SENSOR PERF EEC TEST ROAD TEST MONITOR AND NGS RECORDE FOUND CODE P0123, PERF FIN POINT TEST AND REPLAC AP SENSOR ON ACCELERATOR PEDI ROAD TESTED VERIFIED CONCERN TESTED EEC KOEO PASS CONT. P0221 KOER PASS CHECKED PID MONITOR DATA PERFORMED NGS REPLACED THROTTLE PEDAL ASSY. CLEARE: 7442 42 CK CUIT FOUND CK ENGINE LIGHT ON AND WOULD NOT ACCELL RAN DESEIL PERFROMANCE TEST FOUND ERRATIC OPERATION ACCELL PEDAL REPLACED PEDAL ASSY RE 15988 42 VERPLY CUSTOMERS CONCERN RUN ENGINE PERFORMANCE TEST CODE P0220 PINPIONT TEST PET FES REMOVE AND REPLACE ACCELERATOR PEDAL CLEAR CODES RET WIDS START UP KOEO PO122 P0221 DATALOG TEST PINPOINT ACCELERATOR PEDAL NEPLACE RETEST AND CLEAR CODE REPROGRAM

PERFORMED ENGINE PERFORMANCE DIAG 1 18/8EPLACED ACCELERATOR PEDAL ASSY FOR KOBO, KOBO, KOBO, P0221 TES T DROVE VEHICLE, NO OTHER PROBLEMS FOUND.

MT NO SLO AFTER EXTENSIVE ROAD TEST, FOUND AP VOLTAGE DROPS TO 37 VOLTS AND VEHICLE (DLES UNTIL ACCELERATOR PEDAL IS RELEASED. R & R ACCELERATOR PEDAL PROP

6806 TEST ELEC ACCELERATOR DOES NOT RESPOND AT TIMES REPLACE ACCEL AND SENSOR ASSY

ROAD TYEST, DIESEL PERFORMANCE TEST CODE P0221 REPLACE AP BENSOR RETEST CLEAR CODES TEST ORIVE

SEC TESTIPASS CODES) NGS MONITOR ROAD TEST, PRIPOINT TESTS, REPLACED ACCELERATOR PEDAL ASSEMBLY.

RO TEST VEHICLE VERIFIED CONCERN PERFORM CLICK TEST KOED KOER KOED PRZZI PIN POINT TEST PEI TO PES PERFORMED MONITOR

VERIFIED CUSTONER COCNERN. CODE PO221. FOUND LIGHT ON AND NO ACCEL RESPONSE. PÉRIFORMED DIAG TEST 1 14 FOUND CODE 221 PERFORMED DIAG PINPOINT TEST FOUND PERFORMED DIAG SHEET REPLACED ACCEL PEDAL

NGS CAGNOSIS, PINPOINT TEST, POWER SALANCE TEST, CYLINDER CONTRIBUTION TEST, REPLACED ACCEL PEDAL ASSEMBLY NECESSARY TO RAI FROM A STOCK UNIT AND RETE CK ENGINE LIGHT ON VIEW WILL NOT EEC IQUICK TEST). DIAGNOSIS

9967 ACCELERATOR PEDAL ASSY 8006F, F1.2,6 14,16 19,1X1,9F896 PERFORMANCE DIAG., PINPOINT TEST, RER ACCELERATOR PEDAL ASSY, WITH ADJUSTABLE PEDALS. RETEST.

CC42 9F836 D35,42,9F836 PEFFORM 6SC T65T,PM POINT TEST,MCNITOR T65T,REPLACE ACCEL, PEDAL ABBM,CODE P0221,QUALITY CHECK BY CS.
21032 CC42 9F836 KDEO PASS,CONT P0221,ER PASS 6005F 2 F1 .1 F1X1 .1 F2 .1 F6 .1 F7 .2 F6 .1 6005P5 .3 F10 .1 F11 .2 F12 .3 F13 .1 F14 .1 8005F16 .5 F17 .5 F18 .5 F18 .2 12650D1 .3 TL PAILED THROTTLE CK WITH NGG T65TER AP 6WITCH FAILED REOPLACED AP SWITCH AND ROAD TEST CK

PERFORMED HOTLINE RECOMMENDED REPAIR TO CHECK WIRING HARNESS ON LEFT FRONT SHOCK TOWER FOR CHAMING, WIRING DK, CUSTOMER WILL RETURN FOR FURTHER RE NOS POZZ! KOSO PASS MONITOR PIDS FOUND ACCEL PEDAL SENSOR OUT OF RANGE REPLACED ACCEL PEDAL, AND SENSOR ASSY TEST DROVE MONITOR PIDS RECKED CODES ME NOS TEST KOSO PASS MEM POZZ! MONITOR AND RECORD IVS CHANGES FROM ON TO OFF ON ROAD AND DROPS TO IDLE CKED HARNESS AND CONNECTORS OK, REPLACED ACCEL CASS PERSON, CKED HARNESS OK, REPLACED POWER ADJUST ACCEL PEDAL ASSY R KOSO OD PASS OM POZZ! P1670 KOER PASS PINPOINT CONTACT HOT LINE ADVISED CHECK WIRIS CHARING WIGGLE WIRE HARNESS NO FAULT FOUND INSPECT POM AP + C133 CON HOOK UP TO NOS PERFORM DIESBL ENGINE TESTS, FOUND CODER POZZ!, PERFORM PINPOINT TEST AND CHECK WIRING, FOUND

DEFECTIVE VALIDATION TPS SWITCH E.E.C. TESTS PERFORMED, FOUND STORED CODES, POZZI, PIN POINT TEST REPLACED ACCELERATOR PEDAL WITH SWITCH.

CHECK OUT ROAD TEST FOUND ENG STOP PULING RAWINGS TEST COD PO221 RAW PINPOINT TEST OPEN CURCET IN RANG SEMER B, VOLT RAWIELE, TEST FOUND SHORT IN THROU, VERIFY CK ENG LIGHT ON REF TO PINPOINT TEST AND CONFIRM LIGHT ON AH2 KOED PASS CONT PO221 REF TO PINPOINT TEST FE1 MONITOR IVS PID READING ON GO TO FE7 DISK. 21837 42 DNOP WARR ROAD TEST, MIL OFF, NOS SET UP, EEC TEST KOED P1111 KOEC N. C KOER P1111 NGS REC MON ROAD TEST PUSE PRESS TEST LEFT AND RIGHT HEAD PINP NAM PERFORMANCE CHART MONITOR PICE FOR ROAD TEST. REPLACED THROTTLE PEDAL ASSEMBLY, GAVE TO QUALITY CONTROL MANAGER TO TEST. O.K.

FROM DASH WHEN THIS HAPPENS ADVISE. DIESEL ENG PERFROMANCE DIAG KOEO PASS KOEC POZZ1 KORM PASS FOUND ACCELERATOR PEDAL TO BE INTERMITENTLY FAULTY FO PERFORMED ENGINE DIAGNOSTICS, REPLACED FAULTY PEDAL ASSY.

18892 FAULTY ACCELERATOR PEDAL 6005F.2F1.1F1X1.1F2,1F2.1F8.1F8.1F8.1F10,1F11.2F12, 3F13,1F14,1F15,5F10,2F10,5F10,2, 2450F, A VERIFIED CONCERN DIAG PID TEST CODES F0221 FI

18795 RUN A ENGINE PREFORMANCE CHT AND FOUND CODE PO 221 NEEDS A THROTTEL PEDDEL ASSY NO PARTS ORDER PARTS 441 48...REMOVED LIGHE VALIBATION SWITCH FRO 12029 VERIFY CHECK ENGINE LIGHT ON W94 FOUND PEDAL NOT RESPONDING HOOK UP NGS AND PULLED CODE P0221 TP SENSOR FAILURE KORO ON DEMAND SELF TEST PASS IF 21569 FAULTY ACCELERATION PEDAL BOOK 251.1F1X1.1F2.1F7.2F8.1F9.3F10.1F11.2F12.3F13.1F14.1F10.8F17.2F10.6F10.2 2450F 0.4 VERIFIED CONCERN DIAG PID TEST CODE P0221 RA 9F836 28 VERIFIED CONCERN CODE 0221. PINPORNT TEST PEDAL ASSEMBLY OPEN CIRCUIT. REPLACED PADAL ASSEMBLY ADJUSTABLE. OPERATES

1836 SEMBOR OPEN VERIFIED CONCERN NECC TO TEST. EEC DTC KORC POZZI KORD POZZO PINPOINT TEST. ISOLATED TP SENSOR NECC TO REPLACCELL PEDAL TO REPAIR RETURN PERFORMANCE SHEET 1 & A.B.C.D 9 10 A.B. FOUND ACCELORATOR PEDAL HAD SHORT REPLACED PEDAL ABBY, 1

36206 9°636,42 PERPMD KOED,KOER AND DOLIDIAG USING WDS, RECEIVED CODE P0221,PERPLO PP. TESTS,RIEFLACED FAULTY ACCELERATOR PEDAL ASSY,RETSTD.OX.
42 KOED TEST: P0123 CODE FOR ACCELERATOR PEDAL. RUN PPT REPLACE ACCELERATOR PEDAL. ROAD TEST OX. ADJUSTABLE PEDAL.

1 REPLACED ACCELERATRO CABLE ASSEMBLY.

FAULTY ACC PEDAL RUN SEC TEST, PO221 RUN PINPOINT TEST AND DOLIDISPLAY, FOUND FAULTY

NGS TEST REPLIGAS PEDAL WITH TP NO TEST CLEAR ALL DITS

6916 ACCELL PEDAL DEFECTIVE RAN PERFROMANCE SHEET (PARTIAL) AND DIAGNOSED THE PEDAL ASSY TO BE DEFECTIVE, PO221, AND VERIFIED, REPLACED THE PEDAL ASSY, AND VERIFIED CLIST COMPLAINT OF PEDAL BEING INCP. REMOVED AND REPLACED PEDAL AND RETESTED OK NOW.

PERFORMED DIAG TEST AND AP AND IVS PASSED CALLED HOTLINE TALKED TO ALTOLD ME TO REPLACE AP ORDERED DIS BACK ORDER HAD TO REMOVE AP FROM ANOTHER VEILDIESEL DIAG. PINPOINT TEST, REPLACE ACCELERATOR PEDAL ASSY AND RETEST.

29904 \$F886 TIME TO CK FUEL OIL OK CK AIR AND EXCHIST RESTRICTION OK RAN KOEC F0221 P1780 P1746 P1746 P1716 KOEC ALL, SAME CODES KOER SAME CODES CLEARE 28859 CK FOR NO THROTTLE RESPONSE ROAD TREST HOCKUP NOS PERFORM EEC TEST P0221 PERFORM PID DATA PERFORM PINPOINT TEST REPLACE ADJUSTABLE ACCELERATE INCP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

10069 PACEL ASSY PAPECTIVE RAN PERFECTIVE SHEET, PULLED CODE P0221 AND I THEN PERFECTIVE DIN PIONT TEST, DETERMINED THE ACCELL PEDAL WAS DEFECTIVE SEP-1 PERFORMED KOED NO CODES, PERFORMED KOER NO CODES PERFORMED PUBLICONDITION KP. DUE STABILITY EXHAUST RESTRICTION.

31436 EEC TEST PIDS VIEW PINPOINT TEST REPLACE ACCEL PEDAL ASSEMBLY

1929 BASE WARRANTY CC 42 FP SF838 INTERMITTENT INOP PERFORM DIESEL PERFORMANCE DIAGNOSTICS RETRIEVE PCM MODULE CODE NICCO P1111 CONT P0221 KOER P111 PERFORMED ENGINE PERFORMANCE DIAGNOSIS AND RECEIVED CODE P0221, PERFORMED PIN POINT TEST, FOUND ACCELERATOR PEDAL

DIESEL DIAG DTC P0122 PINPOINT TESTS REPLACE ETC(0F636)

EBC (QUICK TRUT) DIAGNOSIS POTENTIONETER ASSEMBLY THROTTLE POSITION SENSOR (TP)

NGS TESST KOED PASSED CODE,CONT CODE PO221; WENT TO PRIPOINT TEST, POUND INTERM OPEN CIRCUIT IN IPEDAL SENSOR; REPLACE AACCEL PEDAL & SENSOR ASSY & REC. SELFTEST, PINPOINT TEST, REPLACE PEDAL THROTTLE POSITION SENSOR, RETEST OK

ACCELERATOR PEDAL 9F835 OPEN CIRCUIT CODE P0221 PERFORMED DIAQ 1 S.RR. ACCEL PEDAL, CLEAR CODES, ROAD TEST TO VERIFY REPAIR OK

6287 9C536,42 PERFMD KOBO, KOER AND OCLIDIAG USING NGS, RECEIVED CODE P0221 PERFMD PP TESTS REPLACED PAULTY ACCELERATOR PEDAL ASSY RETSTD, OK

82174 REDUEST MITINE NO LABOR OF IN BOOK 1.0 C K FOR NO ACCEL RAN CODES FOUND CODE FOR A 17 SENSOR PERFORMED PINPOINT TEST ON VEH FOUND ACCEL PEDAL INC. FOUND ACC PEDAL BAD, REPLACE, CLEARED CODES, TEST ORIVE AND RETEST.

1 VERIFIED CONCERN AND PERFORMED DIAGNOSIS AND EEC TEST P0122 P0221

PERFORMANCE TEST 1 12,000E P0221,PINPOINT TESTED AND REPLACE THROTTLE PEDAL ASSEMBLY, TP SENBOR HAD OPEN CIRCUIT.CC 28 QUALITY CONTROL CHECK BY 9047 MILLI 1969 ACCEL PEDAL ASSEMBLY INOP. 12580D, DX1, D45, M TIME DIAG ENGINE ONLY IDLES, NO ACCELERATION, AND CK ENGINE LIGHT ON, CODE PO122 IN KORD COINT, PERFORMED DIAGNOSE W NGS, FOUND PO221 REPLACE ACCEL PEDAL

PERPORMIEED CYSTEM TEST DOLDISHLAY AND PID MONITOR RACD TEST PERFORMED PIN POINT TEST AND REPLACED PEDAL ASSEMBLY

VERIFIED PROBLEM. BINGING WAS SURGING ON ACCELARTION GOING DOWN THE ROAD, CHECKED ON COMPLITER FOR DICKONE RECORD, PASSED TEST, MONITORIO PROPILED FOR THROTTLE PEDAL ASSEMBLY VERIFIED COMPLAINT, CHECKED DTC SPOZZI, TROUBLESHOOT AND FOUND THROTTLE PEDAL ASSEMBLY BAD REPLACED PEDAL ASSEMBLY

ESC TEST CODE PO271. OFEN CIRCUT AT ACCEL PEDAL SENSOR, SURVICE ENGINE LIGHT ON AND NO POWER, REPLACE ACCEL PEDAL ASSY, ROAD TEST OK

PERFORM GAS PEDAL ASSEMBLY REPLACED COMPONET TEST DROVE REPAIR VERIFIED TESTED FINE AFTER REPAIR

PERFORMED DIESEL DIAG. AND REPLACED ASSELL. PEDAL ASSEMBLY, AND ROAD TEST AND RETEST OIL.

PERFORMED DIESEL DIAG, RECIEVED CODE P0221, PERFORMED PINPOINT TEST, TRACE TO OPEN CIRCUIT IN AP. REPLACED AP, AND ROADTEST, OK NOW,

SHORTED TP SENSOR BEC (QUICK TEST) DIAGNOSIS

18609 18018 NO LITÉ ON ROAD TEST TO VERIFY, OK, DO PERFORMANC E CIAGNOIS, 1) VISUAL INSPICK, SIGNIFF CLEAN FUEL, OK, 3) CK ENGINE CIL, OK, 4) INTAKE REST. OK, 5) PERFOR M INC. 28 SPN 97639 FERFROM DIRECT DIAGNOSIS PER DIESEL WORKSHEET, REPLACE TP SENSOR, RETEST, OK.

25936 WARR VARIFIED CUSTOMERS COMPLAINT EEC TESTED POZZI PIN TESTED FOUND ACC PEDAL FAULTLY REPLACED PEDAL ASBY RETESTED ALL OK ROAD TESTED ALL OK

PERFORMED DIESEL PERFORMANCE DIAG, 1 14, PID MONITOR ROADTEST, PINPOINT TESTS, PERLACE THROTTLE PEDAL ASSY WITH ADJUSTABLE PEDALS, CLEAR CODES, ROAD TE HARNESS RUBBED THROUGH ON HYDRO BOOST LINE. PERFORMED DIESEL DIAGNOSIS, 1 14,000 BF P0221, PINPOINT TESTED REPAIRED HARNESS, HISTALLED SHIELD, CLEARED CODI 15001 NGS TESTED PCM, RECIEVED CODE 2221, PERFORM PRIPOINT TEST DO1 ON THROTTLE SWITCH PERFORMANCE. CHECK VREP, HAVE 5 VOLTS, CHECK AF GROUND, FOUND GC WENT SYMPTOM CHART 7 PERFORMED TEST 1 7 OF PERFORMANCE DIAG WORKSHIET FOUND P0128 WAS PRESENT IN CMDTC PERFORMED.

CHECK ENGINE LIGHT ON AND IT WILL NOT ACCELERATE CONNECT NOS AND PERFORM QUICK TESTS, PINPOINT TESTS FOUND THROTTLE POSITION SENSOR OUT OF RANGE, NEC*
CONFIRMID COMPLAINT, TECH FOUND ADJUSTABLE PEDAL ASSEMBLY DEFECTIVE, REPLACED PEDAL ASSEMBLY AND CLEARED CODES ROAD TESTED TRUCK LIGHT IS OFF A LL IS OVERIFY COMPLAINT, TECH FOUND ADJUSTABLE PEDAL ASSEMBLY DEFECTIVE, REPLACED PEDAL ASSEMBLY AND CLEARED CODES ROAD TESTED TRUCK LIGHT IS OFF A LL IS OVERIFY COMPLAINT, TECH FOUND ADJUSTABLE PEDAL ASSEMBLY AND CLEARED CODES ROAD TESTED TRUCK LIGHT IS OFF A LL IS OVERIFY COMPLAINT, TECH FOUND ADJUSTABLE PEDAL ASSEMBLY AND CLEARED CODES ROAD TESTED TRUCK LIGHT IS OFF A LL IS OVERIFY COMPLAINT, TECH FOUND ADJUSTABLE PEDAL ASSEMBLY AND CLEARED CODES ROAD TESTED TRUCK LIGHT IS OFF A LL IS OVERIFY COMPLAINT, TEST, CODE POZZI "PERFORMACED DOLL TEST MONITOR ROAD TEST. PINPOINT TEST, THROTTLE POSITION SENSOR INTERMITTENLY OPEN, REPLACED THROUGH THE PROPERTY OF THE PROPERTY OF

ENGINE PERFORMANCE DIAG. KEY ON ENGINE OFF KOED CHECK TEST, EXTRA TIMEREPEAT FINAL QUICK TEST, KEY ON ENGINE RUNNING KOER CHECK TEST. DCL DISPLAY TEST. F. 14048 NO RESPONE FROM THE THROTTLE PEOAL (PERFORMED ROAD TEST AND) VERIFIED CUST CONCERN I RAN THRU PERFORMANCE SHEET STEPS 1 THRU 14 1 FOUND CODE P. REC TEST REPLACED ACC ASSEMLY RETEST.

OID ENG. PERP. TEST 1 THRU 14. FOUND CODES POIZE AND POZZ1 IN MEMORY, PINPOINT TEST. FOUND NO PAULT, TEST DROVE WHILE WATCHING PIDS. FOUND ACCELERATOR PED-16286 C K FOR BERV ENGINE SOONS LIGHT ON/RAN. CODES FOLIND CODE FOR THE TP SENSOR/PERFORMED PIN POINT TEST ON VEH, FOUND ACCEL PEDAL INOP AT TIMES/REPLAND CUICKTEST PEMPOINT MONITOR ROAD TEST REPLACE PEDALAND RETEST.

VERIFIED CUSOTMER CONCERN FOUND THROTTLE POSITION SENSOR FAILING, REPLACED SENSOR AND THROTTLE ASSEMBLY AND RETEST...OK NOW. 1826

1 EEG TEST REPLACED PEDAL ASSEMBLY

13657 PERFORMED CHESS, SINGINE PERFORMANCE DIAGNOSIS, KOED TEST RECEIVED CODE P0220... INJECTYOR ELECTRICAL TEST PASSED, KOER TEST PASSED, PINPOINT TEST 14576 ACCELERATOR PEDAL ASSEMBLY 28 WR VERIFY CONCERN AND RUN DIAG TEST, 12550D 12550D X1 12550D45 12650D81 AND R350B, HAD CODE P0221, RUN PINPOINT TEST AN 17472 VERIFIED CONCERN, TESTED SEC KOEO KOER COOS P0221, VERIFIED NO THROTLE RESPONSE, MONITORED IVS 3 AP PIDS, VERIFIED AP SIGNAL COES NOT CHANGE AT TIME RAN STAR TEST, RESCIEVED COOS P0123, PERFORM PIN POINT TEST FOR ACCEL PEDAL SENSOR & WRING, RER ACCEL PEDAL ASSEMICLEAR CODES AND RETETS OK

THROTTLE ASSY INCP MTSFS36 NO LBR REPL THROTTLE ASSYSTIKUP VEH FLIGHT RECORDS FOR DIAG

RAN PERFORMANCE TEST 1 14 AND RECIEVED CODES P0123 & P0221 DIAG PROBLEM AS BAD PEDAL ASSEMBLY, REMOVED AND REPLACED THE PEDAL ASSEMBLY AND CLEARED COL.
BAND ACCELERATOR ABBY ELECTRONIC TRANSMISSION DIAGNOSIS DIAGNOSIS

6894 FAILED THROTTLE PEDAL ASSY, CC 42,9F896 VERIFIED CONCERN, PERFORM 2002 DI PERFORMANCE DIAG, 1)VISUAL ENGINE INSPECTION PASS, 2)8UFFICIENT CLEAN FUEL PAI

CHECKED AND REPLACED PEDAL ASSY

THROTTLE PEDAL OUT OF RANGE | EEC (QUICK TEST) DIAGNOSIS

11742 CONFIRMED CUSTOMER CONCERN OF NO THROTTLE RESPONSE AND CHECK ENGINE LIGHT ON AT THIS TIME PERFORMED EEC TEST RETRENED CODE P0221 FOR APP CONSESSION ACCEL PROMINED FROM THE TIME PERFORMED FROM THE PROPERTY OF THE PROP

28 SF838 PERFORMANCE TEST 1 THRU 16 AND 1 THRU 14 ROAD MONITOR TEST FUEL 1 ST HEAD AND SECOND HEAD 80 PSHINLET RESTRICTION TEST

INSPECT, RAN KOEGIC, KOEG, OBTAINED CODE POIZS, POS46, RAN PRIPOINT TEST POIZS, ACCESS PIOS AND MONITOR, NEED THROTTLE PEDAL ASSEMBLY ANS RECHECK REPLY
X REPLACED PEDAL SWITCH

NOP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DITURBO ENGINE DIAG

SKINSPECT WOS DIAG KOEO PASS KOER P0221 DCL DATA DISPLAY FOUND AT TIMES THROTTLE WILL NOT WORK NO ACCELL REPLACED ELECTRNIC ADJUSTASLE GAS PEDAL ASSE 2002 FAULTY ACCELERATOR PEDDAL 60097.3F1.1P1X1.1F2.1F7.3F1,1F9.3F10.1F11.2F12, 3F13.1F14.1F18.0F17.3F18.2F18.2 2480F.3 VERIFIED CONCERN DIAG PID TEST CODE P0221 P CONCERNS STATED BY CUST AND CHARACTERISTICS FOUND IN VEHICLE LEAD TO MALP. TPS. R R TPS AND TEST DROVE, PART TAKEN FROM

PERFORMED DIESEL PERFORMANCE DIAG PULLED CODE MONITORED POIDS PEROFINAD PPTEST SREPLACED ACCELERATORPEDAL CLEARED CODE RETEST MIL LIGHT STAYS OF HOOKUP NGS RETRIEVED CODES 0125,0221 PERFORM PCED PINFORM TEST FE1 FES DOI DO2 INSTALL BREAKOUT BOX AND TEST REPLACED BAD ACCELERATOR PEDAL

INOP ENGINE PERFORMANCE DIAGNOSTICS 7.3L DITURSO ENGINE DIAG ACELL PEDAL HAS OPEN CIRCUIT COOR P0122 PERFORMED DIAG 1 6 COOR P0122/REPLACED ACELL PEDAL, ROAD TEST OK

REPLACE T P SENSOR CLEAR CODES RECHECKS FINE

verfied concern performed engine performance diag test replaced accell pedal assembly corrected

CHECK JUST IDLE AT TIMES COMPUTER TEST ROAD TESTED PIN POINT TEST INSTALLING PEDAL ASSEMBLY

HOCKED TO WOS CHECKED FOR CODES, TP RANGE SENSOR PERFORMANCE CODE, HAN PINPOINT TESTS ON TP CIRCUITRY REMOVED AND REPLACED ACCELERATOR PEDAL ASSE 7675 ACCELERETOR PEDAL, NGS TEST TO DIAGNOSE, PULLED THE CODES FOUND 2 P0122 AND P0221 ACCELERETOR PEDAL DISFECTIVE, R& R THE SAME, CLEARED THE CODES AN 97136 42 529 6656 M TIME FOR NO LABOR OPERATION TO INSTALL PART EEC TESTED MONITORED ON ROAD TEST WITH NGS PULLED CODE P0221 PIN POINT TESTED TO FAILED TPS.
INOP INTERNAL.

BEC (QUICK TEST) CLASHOSIS

13816 OPEN IN THROTTLE POSITION SENSOR CODE 28. WARR PERFORM DIESEL DIAGNOSIS CHECK AIR PILITER OK CHECK OIL OK CHECK EXHAUST OK CHECK AIR PERFORM KOEC NGG TESTED POZIT FID DATAMONITOR INJECTOR ELECTRICAL TEST, NJECTOR CONTROL PRESS TEST, LOW IDLE STASMILITY TEST CHECK PUEL PRESSURE 60PS) CYLINDER CONTREC V DIAG., SELF TEST, CODE POZZI, NGS DCL. DISPLAY DIAG., NGS RECORD MONITOR, PERFORMANCE DIAG. 1 THROUGH 14, PINPOINT TEST, THERE WAS NO DTC AT PIRST, ROAD TEST 11933 EEC TESTED FOUND POLSS CHECKED PUBES FOUND TO SE OK PINPOINT TESTED FOR CODERAR PCM. CONNECTOR TO TEST WIRING CIRCUIT FOUND CONNECTOR WITH PULL PERFORM DIAGNOSIS PINPOINT POZZI POSMA PISMA REPLACE ACELLERATOR PEDAL.

DIAGNOSE DRIVEASILITY CONCERN NOS TESTS CODE P0221 TP FALLED REPLACE DEFECTIVE ACCELERATOR

DIESEL DIAG REPLACE TPS RETEST OK

1 REPLACED ACCELERATOR PEDAL AGREMBLY AND CLEARED CODES, ROAD TEST

INOP RR ACCELLERATOR

1 RANIALL DEGEL PERFORMANCE TESTS AND ORDERED ACCELL, PEDAL 7 10 RÉPLACED ACCELERATOR PEDAL ASSY WI ADJUSTABLE PEDALS

PERFORM DISSEL PERFORMANCE TEST 1 THRU 14 REPLACE THROTTLE PEDAL WITH POWER ADJUST CLEAR CODES RETEST

ACCERATOR PEDAL EEC TESTED, REPLACED ACCELERATOR PEDAL

ROADTESTED, NO SUP CONFRMED, SECTEST AND PRIPOUNTIEST FOR DTC P0221, MT TIME TO REPUBLICATIONACIAC CITAL PEDAL ASSIY, RETEST, CK.

TEST EEC, NO CODES. PIN POINT CONCERN, MONITOR MIDS & DISPLAY, REPLACE AP SWITCH, IRRATICY OPE, RATION, ROAD TEST, RETEST, MITIME IS FOR NO LABOR OP IN BOOK F. PERFORMED CIEBEL CHAIRPART, REPLACED PEDAL ABBY DUR TO INTERNITIENT, RETEST OK.

PERFORM DIAG REP ACCEL PEDAL IMOP

THROTTLE PEDAL ASSEMBLY PAILED ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE

28 IF698 PERFORMANCE TEST 1 THRU 10 AND 1 THRU14 CODES PO221 PIN POINT R AND R GAS PEDAL ASSEMBLY RE TEST CLEAR CODES OK

QUICK TEST, CODE POZZI, PINPOINT, FAULTY PEDAL SENSOR, REPLACE PEDAL ASSY

12783 VERIPIED LAMP ON INSTALLIED NGS AND PERFORMED KOEC KOER PID DATA MONITORED, RETRIEVED CODE P0221 PINPOINT TESTED FOLIND THROTTLE PEDAL INOP AT TIMACCELERATOR PEDAL OPEN CIRCUIT \$536 DIAG 1 6 CODE P0221 REPLACE PEDAL CLEAR CODES, ROAD TEST TO VERIFY REPLACE

6780 ROAD TEST VEHICLE ENGINE SEEMS TO HESITATE OR WAS AND CHECK ENGINE LITE IS ON USING WOS RETRIVE CONTICODE PO123 RUN KOEO PASS RUN KOER PASS RUN E PERFORMANCE TEST PO221 PINPORT TEST REPLACE AC PEDAL WITH ADJUST

ACCELERATOR ASSY BAD ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG REPLACE ACCELERATOR ASSEMBLY

IV8 SWITCH ON PEDAL SHORTED ROAD TEST TO VERIPY CONCERN, NGS START UP, NGS SEC TEST P0122, P0221, DCL DISPLAY, PINPOINT TEST FE, REPLACE ACCEL PEDAL ASSY. RESTAUS SEC KORR P0476 DCL DISPLAY PIN POINT REPLACED ESP, SENSOR RETEST STILL P0476 PIN POINT KB TEST AGAIN REPLACED PCM STILL P0476 HOT LINE WAS TOLD BY I PERFORM SEC DIAGNOSIS PINPOINT TEST REPLACE ACCELERATOR PEDAL ASSY.

LIDE VALIDATION SWITCH SHORTED ROAD TEST TO VERIFY CONCERN, MGS START UP, MGS EEC TEST P0122, P0221, DCL DISPLAY, PINPOINT TEST DD AND FE. REPLACE ACCEL PEC VERIFY AND DIAGNOSE CHECK ENGINE LIGHT ON SCAN FOR CODES P0221 STORED THROTTLE POSITION OUT OF RANGE, PERFORMED PINPOINT TEST AND FOUND TP SENSOR OPE DEFECTIVE SENSOR

BEC (QUICK TEST) DIAGNOSIS

NGS TEST PINFOINT NO FAULTS FOUND ALL SYSTEMS PASS MITIME TO REPLACE PEDAL ASSEMBLEY

REPLACE PECIAL ARRESMLY

15622 RUN DIT TEST CODE P0221,REPLACE ACCELRATOR, HAD TO REMOVE CABLES AND INSTALL ON NEW PEDAL.

INTRIPNAL ENGINE PERFORMANCE DIAGNOSTICS 7.5L DI TURBO ENGINE DIAG REPLACED PEDAL ASSY

AIR, FUEL, OIL, OIC (OCKOEO, BUZZ PASS, CONT POZZ1, PO12Z, PUBL PRESSUR E 57 60, KOER PASS, JCP 1250, LOW ICP 490, CRANKCASE 1 2, CONTRIBUTION PASS, ESP 29.6, BOOST 18.MONITOR 1. RER THROTTLE ASSEMBLY, CLEAR CODES, AND TEST OR IVE.

(Y) KOED PASS KOER PASS KOEC PO221 RUN WDS, MT TO REPLACE ERRATIC ACCEL PEDAL

ENGINE PERFORMANCE DIAGNOSIS, REPLACED ACCELERATOR PEDAL

ACCELERATOR PEDAL SENSOR INOP INTERESS NO LIST OPS REPLACE ACCELERATOR PEDAL SENSOR INOP PROIFF RECESSARY TO PICK UP PART FROM ANOTHER DEALER TO CC. ELECTRONIC TRANSMISSION DIAGNOSIS. DIAGNOSIS

VERIFY EEC TEST PPT TO AND RR GAS PEDAL ASSY RECK OK

VERUFIED CONCERN, RAN ENGINE PERFORMANCE TESTS 1 14, MEMORY CODE 0221, KORD CODE P1111, KORR CODE P1111, CCT CODE P1111, RAN PINFOINT TEST, FE1 FE7, CCDE PTEST DIAG P0221 PINPOINT TEST AND TO SENSOR OK ACCL PEDAL RPL SENSOR WITH PEDAL ASSY RETEST ROAD TEST ALL PASS

MITIME TO REPL PEDAL ASSY
PERFORM TEST REPLACE AP SENSOPR RETEST

TEST DRIVE DID NOT VERIFY, EEC TEST PULL CODES PINPOINT TEST MONITOR PIDS IDLE VALIDATION SWITCH OPERATION STICKING PEDAL ASSEY REPLACE PEDAL ASSEY AND CLIVENIFIED CONCER STALLED WHILE CRIVING RECITEST HARD FAULT CODE P0221 TP RANGE PINFOINT TEST FOUND FAULTY GAS PEDAL TP ACQUMULATOR REPLACED GAS PEDAL FINSPECT & COMPLETE DISSELDIAGNOSIS, RETRIEVED CODES P0221 & P0221, PINPOINT TEST POUND PAULTY INS SWITCH REPLACED SID INS SWITCH (COMPLETE GAS WITCH SIZE OF SIZE OF

6646 C.K. FOR BERY ENGINE SCONLIGHT COMING ON. VERIFIED PROBLEM, RAN CODES FOUND P0221, PERFORMED PINPOINT TEST ON VEH FOUND ACCEL PEDAL INOP AT TIMES REINS TRANSITION OUT OF MANGE INCAD TEST VEHICLE TO VERIFY CUSTOMER CONCERN, NGS START UP, NGS EBC TEST P0221, DCL DISPLAY, PINPOINT TEST FE. REPLACE ACCEL P. AP SENSOR IN PEDAL MALFUNCTIONS. BEC. (OUTICK TEST). DIAGNOSIS

20503 4496 PT KORC PO221, KORO PASS, KORO BUZZ TEST, PASS, KORR ON DEMAND TEST PASS. ENGINE PERFORMANCE DIAG TESTS FER POED, REPLACED SAD ACCELLERATOR EEC TEST, PIN POINT TEST, MONTIOR PIDS, RIPLACED 1,P PEDAL ASSY, HAS POWER ADJUSTING PEDAL, RETEST OK, ROAD TEST OK, RECHECKED FOR CODES NONE.

PEDAL AND SENSOR ASSY EEC (QUICK TEST) DIAGNOSIS

1 PERFORMED PERFORMANCE DIAG SHEET KOED PASS CONT POZZ1 KOER PASS CIL CONT TEST PASSED PINPOINT TESTED THE CONT CODE RAN NGS FOR DIAG. REPLACED AP SWITCH ASSEMBLY AS PEDAL SWITCH WAS OUT OF RANGE CLEAR CODES AND TEST DROVE AFTER REPAIRS.

SENSOR INOP REPLACE ACCELERATOR PEDAL ASSEMBLY EECO TEST, PINPOINT TEST AND DOLLMONITOR TEST

INOP EEC (QUICKTEST) DIAGNOSIS

12711 ECC TESTED FOUND AP CODE REPLACED PEDAL ASSEMBL TO TURN OUT CHECK ENGINE LIGHT

VERIFIED CONCERN RAN HOS DIAG REPLACED ACCELL PEDAL ASSY RETEST SYSTEM OK

8379 42 INOP COMP PREFORMED DIAG SERVICE CODE: PO221 PREFORM TESTS QC13 TO 18 R ACCELERATOR PEDAL CLEAR CODE ROAD TEST RETEST SYSTEM PASSED 544 VERFIED CONCERN PERFORMED DIAG TEST 1 6 REPLACED ACCELL, PEDAL ASSEMBLY

13397 (SPB36) CC 42.7.3L DI VERIFIED CONCERN. PREFORMED DIESEL FREFORMANCE DIAG FOUND CLEAN FUEL, INTAKE RESTRICTION 4 IN. NO CODES IN KOED BUCCODE PO221 IN I VERIFIED CUSTOMER CONCENT. PERFORMED DIAG TEST 1.14 FOUDN VALIDATION SWITCH INOP AND CODE 221 AND 603. PERFORMED PIN POINT TEST FOUDN VALIDATION SWITCH RAN PERFORMANCE SHEET, RAI POM & FUSE BOX,CK WIRE HARNESS FROM POM TO FUSE BOX,CK WIRE HARNESS FROM FUSE BOX TO PEDAL ASSY, REPAIRED WIRE, REP; ACED TH RAN DIESEL DIAG PERFORMANCE SHEET P1111 10 PO221 KOER P1111 SEE SHEETPINPOINT DIAG AS PER H MANUAL REPLACE PEDAL ASSEMBLY AND RETEST P1111 P10 P1111 KOEF TEST ESC SYSTEM REPLACED FUEL PEDAL AND SENSOR

RUN EEC TESTS DTC PO221, CK ETC VOLTAGE, MONITOR IVS OUTPUT DROPS OFF, PER HOTLINE CHECK FOR CHAFINS HARNESS AT FOUR

12017 TP SENSOR SHORTING OUT AFTER DRIVING FOR A WHILL 6005F 0.2 F1 0.1 F1X1 0.1 F2 0.1 F6 TO F14 1.4 F16 0.6 F17 0.6 12860046 0.3 D61 0.5 MT 0.3 TOTAL 4.1 HRS TF SUFFICIE 18377 CHECK ENGINE LIGHT ON GOT CODE FOR IDLE VALIDATION SWITCH TESTED SWITCH FOUND TO BE BAD. SWITCH ON D89 BACK ORDER WILL HAVE TO ORDER ACCELERATOR AND SENSOR

NOS TEST, FINAL TEST, KOEC & KOER, TEST, PINPOINT YEST FOUND ACCELERATOR PEDAL ASSY, INTT. INCP, REPLACED ASSY,

EEC TESTED, DIAGNOSED BAD TP SENSOR REPLACED TP SEMISOR AND RETESTED OK NOW.

THROTTLE PEDAL REPLACE THROTTLE PEDAL ASSEM

ENGINE LOOSES POWER UNDER ACCELL PERFORMED 7.3 DIESAL ENGINE PERFORMED TEST ESC TEST PO122 PO221 IN MÉMORY

AND PINPOINT TESTS, NECESSARY TO REPLACE ACCELERATOR PEDAL ASSY, CLEARED CODES, ROAD TESTED OK, RETESTED ECCING FURTHER CODES. PERFORM DIAG REP ACCEL, PEDAL OPEN SENSOR

14811 \$F636 TME TO CK FUEL OIL CK AIR BOHAUST XESPICTION ALL OK RAN KOED KOER DCL P0221 TME TO RUN PINPORT TEST FE1 FE4 REPLACE ACCEL PEDAL SEATIC OPIRATIO EEC TEST, DATALOG IDLE SENSE POSITION INTERMITTENT, PIN POINT TEST BATTERY POS AND GIGNAL NETURN TO SWITCH TEST OK, R & R A P SENSON, ACCELERATOR ASSENSELY 117 INSPECT VERIFIDIAL ON, PERFORM EEC TEST CONTINIOUS CODE P0221 PERFORM KOED SELF TEST PASS PERFORM KOER SELF TTEST PASS PERFORM SOLE SELF TEST PASS PERFORM SOLE ALL P. RAN NGS RETIRIEVE, KOED, KOER, INJECTOR SUZZ, AND CYL. CONTRIBUTION, GAVE CODE P0221 FOR TP PERF RANGE. REPLACED ACCEL PSDAL ASSEMBLY AND CLEARED CODE, 42 ACCEL PEDAL SWITCH NOT WORKING PROPERLY, CAUSING MIL, TO CO ME ON, VERIFY CONCERN, TEST PCM WITH WOS, CMOTO P0221, DO PPOINT WITH GUIDED DIAGNOSTIC, CHK (CC)2 ERRATIC, \$P\$506, LIGHT ON, P0221 PASS PASS INTIME ON PEDAL NGS TEST, DCL TEST, PIN POINT TEST, REPLACED ACCELERATOR PEDAL (ADJUSTABLE), ROAD TEST ACCELERATOR PEDAL INOP

MT9F636 NO LER CY PEDAL INOP

MT9F636 NO LER CY PEPLACE ACCELERATOR CABLE ASSY

CHECK ENGINE LIGHT ON AND WILL NOT ACCELERATE TEST EEC SYSTEM DOLD ISPLAY REPLACED ACCELERATER PEDAL ASSY RETEST EEC SYSTEM

ERRATIC OPERATION OF PEDAL ASSY ENGINE PERFORMANCE DIAGNOSTICS 7.3L DI TURBO ENGINE DIAG

13843 RAN NGS TEST, COOK 0221 PRESENT, TEST THROTLE PEDAL SENSOR, SIGNAL IS ERRATIC, REPLACED PEDAL ASSEMBLY, RETEST CLEAR OTCS GMAINT

RIT PULLED CODE POX21 FOUND FAILED ACC, PEDAL REPLACE PEDAL RETESTED OK

RAN DIEBEL DIAGNOSIS HAD CODE FOR TPS RAN PINPO INT TEST FOUND TP ASSEMBLY BAC HAD TO REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PEDAL ASSEMBLY TRUCK HAD ADJUSTABLE FEDAL (SINSING REPLACE P ART OF PART OF PART OF PART OF P ART OF PART OF P ART OF PART OF P ART OF P AR

10589 7000F F2 7247A 126500 046 3450F 2.6 TESTED WITH NGS RECEIVED CODE P0221 TESTED MLP OUT OF RANGE REPLACED ACCEL PEDAL AND MLP

10366 ACCELERATOR PEDAL 26 WR VERIFY CONCERN AND IRUN PERF DIAG TEST, 6005F 6005F1 19, HAD CODES P0221 IN MEMORY, RUN PINPO INT TEST AND LED TO INOP ACCELE CHECK FOR CODES KOBO P1000 KOBO P220 KOBR PASS RUN PPT FOR AP IVS SWITCHES AND FOUND INTERMITTENT AP SWITCH, REPL ADJ PEDAL ASSY AND RETEST, ALL PASS RUPPERFORMED SECT TEST P0221 WAS PRESENT CONT. PERFORMED PP TEST FIX POUND IVE SHOWED ON TROUGH TRAVEL, WAS INSC TO REPLACE

ADJUSTABLE ACCELERATOR PEDAL 9F028 PERFORMANCE DIAG 16,000E PO221,PERFORMED PIN POINT TEST,RR ADJUSTABLE ACCELERATOT PEDAL, ROAD TEST TO VERIFY REAF

VEHICLE HARD TO PULL NO POWER BEC (QUICK TEST) DIAGNOSIS

34618 ACCELERATOR PEDAL ASBY 6005F,F1,2,614,18 19,1X1,9F636 PERFORMANCE DIAG.,CODE 0221,PINPOINT TEST, FOUND FAULTY ACCELERATOR PEDAL ASSY.R&R PEDAL ASSY. 5 M TIME FOR EXTRA DIAG TIME AND REPAIR TIME TECH INSTALLED NEW THROTTLE PEDOLE ASSY RETEST ALL OK AT THIS TIME ROAT TEST SMI...

IMPROPER OPERATION 99604 CC42 DIAG AND PINPOINT TEST, FOUND MOTOR ON PEDAL TO BE INCP. REPLACED MOTOR AND RETESTED.

....EEC TEST AND DIAGNOSIS RETRIEVED DTC PO221 PINPOINT TEST AND DIAGNOSIS, REPLACED PEDAL ASSEMBLY CLEARED DTC

INSTALL ADJUSTABLE PEDAL ASSEMBLY AND SWITCH

2500 TP SENSOR CK AND FOUND TP SENSOR CAUSING PROBLEM, REMOVED AND REPLACED SENSOR AND PEDAL ASSEMBLY CLEARED CODES TEST DROVE OK.

CHECK OUT PERFORM PINPOINT TEST. REPLACE TP PEDAL REINSTALL OK

18042 07436 42 8008F,0.2; F1,0.1; F1X1,0.1; F2,0.1; F3,0.1; F3,0.2; F6,0.1; F9,0.3; F10,0.1; F11,0.2; F12,0.3; F13,0.1; F15,0.3; F16,0.6; F18,0.2; 2450F,0.3 CORRECTION: PERFORMED C

ROAD TESTED VERIFIED CONCERN PERFORM SEC SYSTEM DIAG AND PP TEST POSS! TP SENSOR PERFORMANCE NO CLEAR AND RETEST NO DTC PPT TP SENSOR 'NOP INTERMENT. DIAG PERFORMED ALL SCC TESTS NO CODES SET UP AND MONITORED PIDS FOUND AP PID OUT OF SPEC REPLACED PEDAL ASSESSMBLY

9188 O K VEH FOR ENGINE SURGING, TEST OROVE VEH VERIFIED PROBLEM.RAN CODES ON VEH FOUND CODES FOR TP SENSOR PERFORMED PINPOINT TEST ON VEH FOUND ACCE 7 PEDAL ASSY BAD DIAG AND TRACED PROBLEM TO ACCELORATOR ASSY, RE PLACED ASSY AND RETEST VERIFY REPAIR

SHORTED ACCELARATOR PEDAL REPLACE ACCELARATOR PEDAL

RCAD TEST, COMPLIETE 7.SL DIT PERFORMANCE DIAGNOSTICS. PINPOINT TEST KOUC P0221, REPLACE AP ABBY, CLEAR PCM, POST ROAD TEST, RETEST. PASS CODES ALL TESTS, UPEDAL ENGINE PERFORMANCE DIAGNOSTICS 7.SL DI TURBO ENGINE DIAG

TO CYLINDER HEAD FITTING LOOSE FINAL ROAD TEST OK

ACC PEDDAL ASSEMBLY BAD TEST DRIVE SEC TEST KOEC P0122 PERFORM PPT QC5 Y QC6 Y REPLACE PEDAL ASSY RETEST TEST DRIVE QUALITY REVIEW

WIRING REPAIR COMPRESSION PRESSURE TEST DIAGNOSIS

9557 42 PERFORMED DIESEL DIAG SHEET STEPS 6,6,7,9 KOEO P0125 P0476, INSTALLED SOP ACCELERATOR PEDAL SENSOR AND RETESTED, ALL PASS KOER P1111 12650D DX1 D45 D51 MT9F836 CHECK AND FOUND ENGINE LIGHT ON SO RAN TST AND FOUND PO221 TP OUT OF RANGE SO PIDMONITOR AND FOUND ACCS AND AP NOT

ENGINE PERFORMANCE DIAGNOSTICS 7.3L DITURBO ENGINE DIAG

5020 42 EEC TEST PID MONTOR PIN POINT TEST REPLACE ACCELATOR PEDDLE ASSEMBLY

PERFORMED DEISEL DIAG 1 14 CODE PO123. PINPOINT TEST AND ACCELERATOR PEDAL ASSEMBLY HAS AN INTERNAL FAILURE REPLACED PAILED ACCELERATOR PEDAL. RECHECKI PZZ1 SHORTED PERFORMACE TESTS PINPOINT TESTS REPLACED TO SENSOR

VERIFIED CUSOTMER CONCERN VEH WILL START BUT NOT ACCELERATE MILLON AT TIME KOEO, ER, PO122 PERFORMED EBC TEST DOL DISPLAY PINPOINT TEST TP SENSOR VOLTS A 9063 OPEN SENSOR VERIFED PERFORMANCE NO ACCELL CHECKED EBC AND FOUND OTC PO231 PINPOINT TEST. FOUND OPEN ACCELL, PEDAL SENSOR NECC TO REPL. SENSOR VE. CPARTIFISM COODE 25 INST NDS PERF EBC TEST, PO221 RO TEST MONITOR PIDS TP SENSOR INTERMITTANT OPEN CKT. PPTTEST TPSENSOR INFINITE RESISTANCE.

183 ACCEL PRIDAL NOS TEST TO DIAGNOSE. PLLLED THE CODES FOUND PO122 TP LOW IN PUT. PIN POINT TEST FOUND THE ACCELERATOR PEDAL DEFCTIVE NO WORK PROPERLY INCP EEC (QUICK TEST) DIAGNOSIS

9F656 42 EEC DIAG AND PPT FOR P6221. PIO DATA DIAG TP ERRATIC REPLACE POWER PEDAL ABSY AND REYEST PAGE

PERD DIAG AND FUEL TESTS PO221 MONITOR PIDS AND FOUND THAT AF SENSOR IS INTERMITTENT REPLACE AP SENSOR RETEST

ROAD TEST NECTO PERFORM RETRIEVE CLEAR CONTIONOUS CODES POR PRISENT PERFORM PID DATA FOR AP SENSOR SENSOR FALLING AT PARTIAL THROTTLE NECTO REPINTERMITT SHORT PERFORM PEDAL ASSY BACK ORDERED

ACC PEDAL INOP PERFORM ALL BECTREST AND PPITEST P0221 REPLACE ACC PEDAL ASY CLEAR CODES WITH ADJ PEDALS

8669 SFESS TIME TO CK FUEL OIL CK AIR AND EXHOST RESTRICTION OK RAN PERFORMACE DIAG KOED P1111 KOED P0122 KOER P1111 RAN PINPIONT TEST DDS DDS REPLACE ACK PERFORM HARD START DESEL DIAGNOSTIC GUIDE ALSO PERFORM A ENGINE COMPRESSION TEST, TEST DEC DO & ER ON DEMAND, A INJECTION BUZZ TEST NECESSARY TO POLI 37Z (6PK36) CC 42 REMOVED PEDAL DUE TO PEDAL BEING ON DOS AND RESISTALLED PEDAL IN CUST TRUCK SEE RO (914899) REINSTALLED NEW PEDAL WHEN PEDAL CAME OFF O NOG REPLACULATOR PEDAL ASSY SENSOR RETEST

9F838,CC 42 LIGHT ON P0221 P1000 P1000 EBC TEBT,OCL TEBT,PINPOINT TBST,MONITOR ROAD TEST P0221 TP RANGE PERF, CHECK CKT O.K.,CHECK TP AP BENSOR ERRATIC,RBR 20836 SF636,42 7.3L 12850D,DX1,D45,9836A7 OR M TIME DIAG & EEC TEST FOR NO ACCELL, RETREIVED CODER P0122, P0221, T.P SENSOR FAILURE, PERFROMED PIN POINT TEST ALL

11209 OPEN 26 TIME TO DIAGNOSE RUN KOED DTC AND KOER (0221) TIEM TO RUN PERFORMANCE SHEET AND ALL YEST (FUEL PRESSURE, INTAKE RESTRICTION, INJ BUZZ TEST, IN ENGINE PERFORMANCE DIAGNOSTICS 7.9L DI TURBO ENGINE DIAG CHECK ENGINE LIGHT ON

1 TEST WITH NGS ELECTRICAL PINPOINT TEST REPLACE ADJUSTABLE PEDAL ASSEMBLY RETEST OK

6851 CC 42 AP SENSOR TECH 513 (2.1) 12650D 0.2.126500X1 0.1,12650D45 0.3,12650D80 0.1,12650D81 0.5,MT 0.9 REPLACE ACCEL PEDAL ASY IN VEHICLE. CHECK AND ADVISE ON CH NO RESPONSE FROM THROTTLE ASSEMBLENGINE PERFORMANCE DIAGNOSTICS 1.3L DI TURGO ENGINE DIAG

TEST DRIVE HESITATES CK ENGICIR ON RUN TEST REC PO125 CODE REVER PPT DD1 PID AP SLOWLY DEPRESS ACC PEDAL VOLTAGE VOLAGE READY WENT TO 4 7 VOLTS PPTDD2 [RAN BNOINE PERFORMANCE CHART, CHECKED AND REPAIL CED ACCEL PEDAL ASSEMBLY, CLEARED CODES AND ROAD TESTED OK MITIME DUE TO PUBLISHED LASOR TIMES WOULD CLOSE OFF IDUE AT 19636 CK AND REPLACE ACCELERATOR PEDAL ABASY AND RETEST, COULD NOT DUPLICATE ENGINEESUSPECT IDUE VAL SWITCH HAD SOMETHING TO VERIFY, PULLED CODES, PINPOINT THET ACCELERATOR PEDAL CIRCUIT, FOUND INTERNETTANT OPEN IN AP SENSOR, REPLACED SENSOR, RETEST OK

ROAD TEST; HOOKED TO NGS; RAN REC TEST, CODE P0112; FOLLOWED PINPOINT YEST; CK SENSOR ON DCL DISPLAY; RPLC FUEL PEDAL ASSY; CLEAR CODES; RETEST

PEDAL ASSY TESTED CHECKED SYSTEMS RR REPLACED FAILED THROTYLE PEDAL ASSY

TESTOROVE & VERIFIEDCONCERN CHICERAN ECC WORDIOS PO221 PRESENT MONITORED PIDS & WIRRING PINPOINT TEST, REPLACED ACCEL PEDAL ASSMITEST DROVE & RETEST EEC TEST PIN POINT TEST RAR TP SENSOR

TECH HAS VERLINED CONCERN TECH ROADTESTED, FOUND THROTTLE DID NOT RESPOND NORMALLY, PERFORMED EEC TEST FOUND P0221 AP RANGE PERF MALF PERFORMED

ACCELATOR PEDAL INOP COOR POZZ1 PERFORM WDS FIN TEST REPLACE ACCELATOR PEDAL CLEAR CODE RETEST (42) THE ACCELERATOR PEDAL SENSOR WAS INCO AT TIMES (DESSE) (N 4201) INSPECT FOR THE BAGINE ONLY IDLING AT TIMES WHILE DRIVING ... EEC TESTED KOEO P THROTTLE BODY CODE PORM PERFORM WITH PIN TEST DC. DISPLAY OCL MONITOR RECORD REPLACE THROTTLE BODY PERFORM KIN SYSTEM TEST RETEST

12078 LOST POWER WARK PERFORM PERFORMANCE SHEET AND GOT GODE POLZE TO SENSER TO HIGH, PERFORM PINPOINT TEST FOR CODE AND DIAG THAT TO SENSER IS FAUL COMPLETED ENGINE PERFORMANCE TEETS 1 14 FROM DIAG SHEET, RECEIVED CODE PO221 AND FOLLOWED PINPOINT TESTS FOR THROTTLE REPLACED ACCELERATOR PEDAL AN

DEFECTIVE PEDEL ASSY CC 42 ADDRESS CONCERN DIAG PERFORM DIESEL DIAG 1 14 REPLACE ACCELERATOR PEDAL ASSY SCAN FOM, PERFORM PRIPORT TEST, RER THROTTLE ASSEMBLY, RETEST, TEST GLOWPLUG SYSTEM, FOUND BAD CONNECTION AT RELAY AND RELAY LOGSE. TIGHTEN RELAY AND REPLACED ADJUSTABLE ACCELERATION, PEDAL ASSEMBLEY ENGINE PERFORMANCE DIAGNOSTICS 7,3L OI TURSO ENGINE DIAG

EMG. PERF TEST 1 14,P/P TESTS QC13 PID ON QC 19 PID OFF REPLACE ACEL PEODLE ASSY.

MIT TIME TO REPLACE ACCELERATOR PEDAL AND SANBOR ASSY WPI

PEDAL ASSY TESTED SYSTEMS PERFORMED DCL. R.R. REPLACED FAILED PEDAL ASSY RETRIST OK

WDS SYSTEM CHECK REPLACE THROTTLE PEDAL ASSEMBLY RETEST AND ROADTEST OK

TIP HAS INTERMITTANT OPEN CKT HAS ADJUSTABLE PEDALS PERFORM EEC TEST RECIEVED GODE POZZI PERFORMED PINPOINT TESTS REPLACED TO IV SENSOR & PEDAL CLEARE 18518 18824 ROAD TEST TO VERUFY, DID NOT VERIFY, DO PERFORMAN OR DIAGNOIS, 19/18UAL INSP, DK, 2)SUFF CLEAN FUEL SYCK ENGINE OIL OK, 4)INTAKE REST. OK, 5)PERFORM KOEF 12724 111 I BROUGHT THE VIRHICLE INTO THE SHOP AND CHECKED OUT THE CODES IN THE PCM, THEY ARE ALL TRANSMISSION RELATED SO I GOT OFF THE RO. 111 STAR TESTER

THROTTLE ABSEMBLY FAILED SINGINE PERFORMANCE DIAGNOSTICS 7,3L DI TURGO ENGINE DIAG PERFORMED ENGINE PERFORMANCE DIAG 1 18.REPLACED ACCELERATOR PEDAL ASSY, FOR KOEG, KOEG, PO221.TES T DROVE VEHICLE, NO OTHER PROBLEMS FOUND 18 PSIT LIRES

QEC (DUICK TEST) DIAGNOSIS NOPERATIVE

CHECK WITH TESTER AND SCOPE AND REPLACE TO SENSOR ASSY

EAC (OUTCK TEST) DIAGNOSIS OPEN CIRCUIT

RAN EEC TEST AND RETRIEVED CODES PO122 AND P0221 MADE PRI POINT TEST AND FOUND THROTTLE PEDAL ASSEMBLY TO BE FAULTY REPLACED ASSEMBLY AND RETEST ALL C RAN DRIVEABILTY DIAGNOSTICS AND RETRIEVED CODES P0122,0755,0743 P0221 AND P1747. MADE ALL PIN POINT TESTS AND FOUND THROTTLE PEDAL TO SE FAULTY, REPLACE

,
\cdot
TECH_TXT2
INSTALL NEW THROTTLE PEDAL ABBY HOT LINE SAID IF HARNESS WAS OK TO REPLACE PEDAL ASSY ROAD TEST ALL OK AT THIS TIME
IS TRUCK
98Y. FOUND WIRING FROM CONNECTOR TO 42 PIN CONECTOR, DK. TESTED CONTROL UNIT, FOUND SHORT TO GROUND WITH CONTROL CIRCUIT FOR IVS. FIN. REMOVE ADJUST
AE POR PART REPLACEMENT
·
D REPLACE ACCELER ATOR PEDAL RETEST AND ROAD TEST.
\cdot
I, RECHECK EEC. CK,
PERS-D44 32267
AEA1-Aid seen.

T RESTRICTION, KOER TEST, ICP PRESSURE, ICP AT IDLE, CRANKCASE PRESSURE TEST, CYLINDER CONTRIBUTION TEST, EXHAUST RESTRICTION, BOOST PRESSURE TEST, PINPON

P SKNSOR STICKING AT TIMES, REPLACED ACCELERATION PEDAL AS PER ASSEMBLY, CLEAR CODES, ROAD TEST RETEST OK.

ROVE 6 MONITERED PIDS FOR CLIAILTY 22176 16965

TESTED TRUCK CONCERN CORRECTED
T FROM ANTORER DEALER PART WAS DOS
TEST DRIVE NO CODES RETRIEVED VEHICLE NOT CUTTING OUT THROTTLE RESPONDING PROPERLY

R QC TECH 972

ED ACCELERATOR PEDAL ASSEMBLY.
MARKET MODIFICATIONS AND ADDITIONS.

ALLED, POST ROAD TEST ALL OK.

31

E DRIVING REPLACED FAULTY ACCELLERATOR PEDAL CLEARED CODE AND ROAD TEST OK
FAULT WHEN CONCERN OCCURRED, INSTALLED BREAKOUT BOX AND PERFORMED PINPOINT TESTING AND, FOUND NO PROBLEMS, REPLACED ACCELERATOR PEDAL AND RE TESTI

SSEMBLY, RETEST, TEST DRIVE 10 MILES TO VERIFY REPAIR

3N OK

ME3-844 32288

TCH INSTALL VALIDATION SWITCH TEST AND RETEST AND TEST DRIVE OK

DROVE ONCE MORE VEH O.K.

. REAR DRIVESHAFT, HAD BEEN REMOVED FOR TOWING

LEM APPEARS TO BE SOLVED AT THIS TIME.

CE PEDAL ASSY REASSEMBLE TEST ORIVE

OK

TG . CLEARED CODE AND

87


ETESTED THE SYSTEM FOUND OK

'GRICAN FIND NO REASON FOR CLAIM TO REJECT. PLEASE EXPLAIN.
OT AP CONNECTOR OK. REPLACE ADJUSTABLE THROTTLE PEDAL ASSEMBLY, RETRET OK.

VEROAD TESTED OK

STEBT OK CCC E29 CC 42

PEB3-844 32289



ON 28

PECS PRIPOINT TEST AP SENSOR CIRCUITS OK REPLACE ADJUSTABLE ACCEL PEDAL ASSEMBLY CLEARED CODES AND RETEST P1111 CK TEST DROVE SEVERAL MILES OK ASSEMBLY ADD TIME FOR ADJUSTABLE PEDALS, ROAD TESTED MONITORING APRIGANL, VERIFIED REPAIRS, CLEARED CODES.

TEST P1111

VOLTS TO 5.0VOLTS REPLACED ACCL POSITION SENSOR

ROAD TEST AND FOUND FEDAL SENSOR INOP AT TIMES, STICKS FIN POINT TEST AND FOUND WIRING CK, SENSOR FAULT REPLACED PEDAL ASSEMIL (SENSOR) ADJUSTABLE. CLE.

THE ASSM. RETESTED, OK AT THIS TIME.

INED ACCELERATOR PEDAL ASSY AT FAULT. CORRECTION REWOVED AND REPLACED PEDAL ASSY, RETEL STED OK AT THIS TIME PREFISIO

EMBLY RETEST TO VERIFY REPAIR. ETRIEVE DTC P0221, PERFROM PINPOINT TESTS FE1 FE4, PERFORM PD DATA MONITOR, RE TEST SYSTEM FASS

INTERMITTENT LOSS OF POWER AND IDLE ONLY REPLACE FAULTY ADJUSTABLE ACCEL PEDAL ASSEMBLY CLEARED CODES AND RETEST P1117 ENGINE PERFORMS NORWALLY OF

ACCEL PEDAL ASSEMBLY CLEARED CODES AND RETEST P1111 ENGINE PERFORMS NORMALLY OK

YOUTS REPLACED ACCELERATOR PEDAL ASSY DAL ASSEMBLEY AND CLEARED CODES

ILE PEODLE REYEST AND

ULL BOOST

PEB3-644 32271

INTERNAL OPEN IN TO SENSOR REPLACED PEDAL ASSEMBLY CLEARED CODES ROAD TEST. RETEST

CLEARED CODES ROAD TESTED TO VERIFY REP AIRED STED AND ROAD TESTED TO VERIFY REPAIR \$7,00 FREIGHT COST \$20.95

DIESEL W ELECTRIC ADJUSTABLE PED.

LARATOR PEDAL SENSOR INTER MITENTLY OPEN. REPLACED ACCELORATOR PEDAL ASSEMBLY. RETESTED AND VERIFIED REPAIR. SPECS. REPLACED PEDAL AND RETESTED ALL DIKAY.

ION

TEST OK AT THIS TIME

G ACCEL PEDAL ASSY ID.OK.

T MITIME FOR UNSUPPORTED LABOR OPERATION FOR REPLACING PEDAL ASSY

RYTHING LOCKS JUST MINE, RAN CASIS AND FOUND NOTHING, STARTED LOCKING AT PIDS AND TEST DRIVING AND FOUND THAT THE ACCELERATOR FEDAL IS GOING TO GFF AND ENSOR ASSY, CLEARED DTC, RETEST, PASS

ACE PEDAL ASSEMBLY, RETEST PASS

6 PMD COOK P0122, AS PER PPT DOS THRU REPAIR EPAIR WIRINS PINCHED AT SHOCK TOWER MBLY, CLEAR CODES, ROAD TEST RETEST OK.

PE83-844 32272

PERFORMANCE DIAG TEST AND RICHT AND REAGGINGLE AND RETEST AND ROAD TEST 527
T AND MONITOR APPROPRIATE PIDS ALL WORKING FINE AT THIS TIME RETEST PASS
LL WORKING FINE.

ANALL OK, ROAD TEST, AL ALL OK. IEMBLY, CLEAR CODES, OKAY.

D, CODE 28, MILES OUT \$1454, Q.C. BY DONALD.

*) PERFORM NGS MONITOR ROAD TEST ISOLATE A RESTED, OK.

PEB3-044 32273

9 CONCERN PIDS REACTED NORMAL DURING DIAG. FOUND WIRES 381 RD 570 BK WH 350 GY RD 1 INCH. FROM PCM CONNECTOR DAMAGED, PROBABILLY AT FACTORY. REPAIR OR RU LER COST 55.86 PLUG SHIPPING ASSY, CLEARED KAM & RETEST, PASS, ROAD TESTED VEHICLE TO VERIFY REPAIRS. , R AND R FOOT PEDAL ASSEMBLY, WITH ECTOR AND ADJUSTER GABLE. DIPEDAL ASSY RETEST ALL OK . ERASE CODES AND ROA DITEST, RECHECK FOR CODES AND RETURN TO SERVICE, HAD TO SET PART FROM NORTHWEST FORD AND STERLING TRUCK CENTER, FORDS POCS WEF 3 H20 KOSO T887 P1111 CONTINOUS CODES PO221 KOSO INJECTOR ELECTRICAL TEST P1111 PUEL PRESSURE AT RIGHT HEAD 67PSI PUEL PRESSURE AT LEFT HEAD 66PSI TANDE US CODES PO221 KOED INJECTOR ELECTRICAL SELF TEST P1111 PLEL PRESSURE AT RIGHT HEAD 67 PSI FUEL PRESSURE AT LEFT HEAD 68PSI TANDEM FUEL PUMP PRESSURE 7(PEDAL ASY CLEARED CODE AND ROAD TESTED PROSLEM CORRECTED SE OK CCEL PEDAL RETEST AND ROAD TEST. PEC3-644 32274

LA RETEST PASS
"INSPECTED BY # 414 20999
L PRESSURE R 6 65 L 6 66 EUEC PUMP PRESSURE 66 INLET RESTRICTION C KOER P1111 ICP TEST 1210 LOW IDLE STABILITY 485 CRANKCASE PRESSURE COYL CONT. TEST P1111 I
RAP AND PLASTIC COVER NOT A WARRANTY ISSUE
R. CHECK DASIS FOR ANY TSBS OR SSMS. PERTAI NING. FOUND SSM FOR WIRE CHAPFING AGAINST THE SHOCK TOWER, WIRES WERE OK WE HAD NO AP SENSOR'S IN STOCK. (IT TEST SYSTEM PAGE
CLEAR CODES AND RETEST.
VOLTAGE AT PIN 80 CIRCUIT 386,FOUND WIRE BARE AT HARNESS BRACKET PRIOR TO \$176 PCM REPAIR BARE WIRE,CLEAR CODE,ROAD TEST,CODE P0221,REMOVE AND REPLACE 3 CHECK ON PIDS OK TEST DROVE TO VERIFIED REPAIRED
ASS KOEO INJ TEST OK FUEL PRESSURE TEST AT BOTH HEADS OK KOER TEST OK ICP AND LIS TEST OK CYLINDER CONTRIBUTION TEST OK EXHAUST TEST OK BOOST TEST OK BAL ASSY, ROAD TESTED
PER3-844 32278

k.

IN MEMORY, IS RELATED TO THROTTLE SENSOR, WOULD CAUSE FAULT DESCRIBED, ALSO HAD PO478 AND P1249 CODES, ARE RELATED TO WASTEGATE AND EXHAUST CONTROLS ES.
EST. SY AND REPLACED CUBARED CODES AND RETEST INTIME REQUESTED FOR REPLACING PEDAL ASSY (SPR36) DUE TO NO LABOR OPPS FOUND LAST RO WIRE WAS REPAIRED THIS (
R PASS MEM P1/221 TP B RANGE OUT DIAG AND ITES ED PER SHOP MANUAL RÉPLACED THROUTLE PEDAL ASY REROAD TESTED AND RECHECKED OK AT THIS TIME INSTALLED SOF
ERATOR PUDAL ASSEMBLY AS PER PINPOINT TESTE, CLEAR CODE AND TEST DRIVE, RPM DROPPED TO IDLE ABAIN AFTER TWO MILES AND THEN WENT SACK TO NORMAL ACCESS A E AFTER 2 MILES AND THE WENT BACK TO NORMAL PERFORM WISQLE TEST ON HARNESS. FOUND CIRCUIT SHORTING OUT INTERMITENTLY ON LEFT FRONT SHOCK TOWER. REPA- S
•
IRING HARNESS AT THE POINT WHRREIT GOS THROUGH THE COWELFO SHORTS NONE FOUND ALL OK NOW. TERNAL ACCEL PEDAL SENSOR ASSYR AND I NEW PEDAL ABBY WITH ADJ PEDAL BRASE FAULT AND ROADTEST TO VERIFY REPAIR OK
UND LOGSE PIN IN APP CONNECT OR XX SECURED AND REPOUTED WIRING CLEAR OF PEDAL XX FOUND STILL LOGSING SIGNAL TO PCM PERFOMRED PIN POINT TEST AND PEDAL
F, CLEAR MEMORY & VERIFY REPAIR
PER3-644 32276

I, DEDAL ASSEMBL, NO LABOR OP.

MBLY, RETERT PASS

AN FUEL TEST, FUEL PRESS AND AT RIGHT HEAD, ALL TESTS PASSED EXCEPT KOEC CODE POZZ!, REPLACED ACCELERATOR PEDAL ASSEMBLY, MITIME NEED TO REPLACE PEDAL

MALLY AT THIS TIME

CERN CLEAR CODES AND ROAD TEST ALL CHECKS OUT OK.

CONTRIBUTION, ISOLATE AP IN SWITCH PAULTY, ACCESS & REPLACE & RESET KAM & ROAD TEST, OK & RETEST EEC PASS.

OPEN

T THAT GOES THROUGH FIRE WALL OPEN GROMET AND REPAIR OPEN CIR AND RETEST. THAT IS ALSO WHAT WITHING IS FOR

NL SWITCH, RECHECKED OPERATION, OK. I OK THEN ROAD TESTED OK

ĸ

INSTALL ROAD TEST RETEST OK.

ACE PEDAL ASSEMBLY RETEST PASS AL OPEN CIRCIUT

PE83-844 32277

NSOR & ADJUST & CALIBRATE FOOT FEED
DES NOW HAS PO221 AND PO122 COOR IN MEMORY REPLACED ACCEL PEDAL ASSY. CLEAR CODES AND ROAD TEST ALL, WORKING FINE RECHECK FOR CODES PASS
SWITCH TO INTERNITANTLY SHOW NO CHANGE REPLACED ACCELERATOR PEDAL ASSIY WITH ADJUSTABLE PEDALS. CLEARED CODES AND TEST OROME. RETEST ALL PASS, PRICE
PARDED CODES AND ROAD TEST, CK.
ST AND DROVE PROBLEM FIXED
S RECHECKED NOW WORKING FINE
E ACCEL PEDAL ABBY, RETERT.
ACCELERATOR PEDAL TP SENSOR ASSMICLEAR CODE ROADTEST CHEKC OPERATION,OK RECHECKED, NOW CK.
TEST REPAY SELF TEST ALL PASS ADJUSTABLE PEDALS
CHECKED GOOD AT THIS TIME
PEB3-844 32278

CAUSE FOUND SHORTED CIGAR LIGHTER ELEMENT X REPLACED LIGHTER AND FUSE RECK OK NOW X PER SFICK FOR PCM UPDATED CALIBRATION FOUND 1 AVAILABLE. TECH PER ME. RATOR PEDEL ASSY RETESTED VERIFEID REPAIR. Y CLÉARED CODE AND RETESTED, OK. NT ON ACCEL SWITCH REPLACED AND RETES T. VE VEHICLE EQUIPED WITH ADJUSTABLE PEDAL ASSY. REVISED PCM CALIB. MIL OFF, TECH 117. EC SYSTEM OK AT THIS TIME GE PERFORMANCE MONITOR PIDS ON DCL PERFORMED PIN POINT TEST SAID TO REPLACE ADJUSTABLE PEDAL ASSEMBLY FOR ACCELERATOR REPLACED PEDAL RETESTED CLEAR BABIC 9F836 CC 42 PE63-844 32279

· · · · · · · · · · · · · · · · · · ·	•
T FEET, CLEARED THE PO221 MEMORY CODE, ROAD TEST AND THE ENGINE RAN PINELECTEST AND THERE ARE NO CODES.	
TY, REPLACED PEDAL ASSEMBLY AND RETESTED	
ED ALL CIK.	
COOSS TEST DRIVE TO VERIFY REPAIR.	
RESTRICTION OK KOTO TEST CODE FOR TP. SENSOR AND RETEST OK FUEL PRESURE TEST AT BOTH. HEADS OK KOER TEST SYSTEM PASS ICP AND US TEST. OK CYU	NDER CONTI
SENSOR VOLTAGE AT .8V THEN AT .4V WITHIN 1 SIN AP FAILURE OPEN IN SENSOR REPLACED ADJUSTABLE GAS PEDAL ASSEMBLY RETESTED TO CONFIRM REPAIR	
WITH PEDAL DEPRESSED, RAR ACCEL PEDAL REC K OK. ED	
ROPERLY	
CED THROTTLE PEDAL ASSEMBLEY AND READJUST PEDAL HIGHT, CLEARED CODE AND ROAD TESTED RECHEC P1111 ALL CLEAR DONE TECH: 23 8 PSI INURT FUILL RUIST () AIR IN FUEL K KOUR PASS KOP 170 LOW IDLE STAB 490 KOER CYL TEST PASS EXH REST 29,4 BOOST 15 PSI PPT P0221 CK V REF ORD OK SIGNAL	L WIRE OK RI
AL REFERÊ NOE WIRE	
ROFORMANCE CONCERNIFOUND NO OTHER CODES, ROAD TEST TO VERIFY REPAIR	
R PSDAL ASSY (SP836)	
PE63-844 32288	

.

- .

•

٠.

ø

.

NEW, CLEAR DTC.
et ok B, Clear Codes, Clear Codes, Ro Test ok
om per shop manual repair complete
RIMAL NOISE.
TABLE PEDAL OK AT THIS TIME . FOND AP IV9 BAD. ORDRERED & INSTALLED PART, RECHECKED & ROAD TEST, RECHECKED & ALL OK EEC TEST FOUND P1600.
•
CELERATOR PEDAL AND RECHECKED OPERAITON, OK.
PEB3-844 322#1

.

.

	IGH1

LI ASSY, RECHECK, CK.

GES OR TSSS PERTAINING TO CONCERN FOUND SSM M6412 PERTAINING TO POSSIBLE WIRE CHAFING CALISING CONCERN INSPECTED WIRE HARNESS AT UPPER PORTION OF LEF

ROSE REPLACED PEDAL ASSY RETEST OK

"CLEARED CODES, TEST DIROVE AFTER REPAIR

E PREFORM PIN POINTTEST SE1 THRU SE12 REPLACE PUEL PEADLE RETSET OK TE GOES ON, NOT PUEL LITE AS PER WRITEUP ITS WRONG, PERFORM 7.3 DIT TESTS SHEET AND CODES PO122 TP LOW INPUT PERFORM PINPOINT TESTS STEP OUS TO DOS AND RE

STOR PEDAL ROAD TESTED ALL OK ECC TESTED ALL OK

"PA55.

LE CLEAR GODES AND RETEST PASS, ROAD TEST, OK.

X, OK,

SWITCH, REMOVED AND REPLACED PEDAL ASSY, RD TEST OK


HIVE OK

ERATOR PEDAL ASSEMBLY CLEARED CODES RETEST SYSTEM CK

PERS-844 32282

0221 RIPLACED ACCEL PEDAL 9F636 INTERMITTENT POOR CONNECTION CODE X2 CLEARED CODES ROAD TESTED AND RECHECKED OPERATION XONCERN MASIC 9P830 CC 42 FOR THE MENTIONED REPAIR DONE DUE TO NO OPS FOUND REPLACE PEDAL ASSEMBLY, RETEST PASS Y RECHECKED PASSED TESTDRIVE IS OK VEHICLE REPAIRED AND FINE AT THIS TIME SAFE TO ORIVE CM AND PEDAL EXHAUST TEST INT TEST "VEHICLE OPERATES PROPERLY ID TO SENSOR, CLEAR CODE, TEST DRIVE, RETEST, OK, NO OTHER CONCERNS FOUND AT THIS TIME, OC14.CUSAR CODES, RETEST JE AND RETEST LISENSOR OUT OF RANGE AT TIMES, REPLACE PEDAL ASSEMBLE PROBLEM FIXED. HOUGH PET OPEN IN ACCEL PETAL GENSOR REPLACE PETAL ASSY, RETEST AND ROAD TEST

PE83-844 32283



Name of the control o
NID CLEAR CODES P(221
ar Codes. Test or: Ve to verify repair.
TOK.
VALIDATION SWITCH CIRCUIT, MONETORED TO SENSOR AND IDLE VALIDATION SWITCH WITH NGS TESTER AND OPERATED ACCELERATOR PEDAL, AT FIRST THE SENSORS DID NOT
ID PO122, AS PER PHYPOINT TESTS NECC TOGET PART OUTSIDE ES, RETESTS PINE AT THIS TIME.
P AVAILABLE .
LLOK, PERFORMED PP TESY TO AND REPALCED INTERMITTANT BAD ACCELERATOR PEDAL POSITION BENSOR AND PEDAL ASSEMBLY, RETESTED ALL PASS, TEST DROVE ALL OX
\cdot
ESTED SYSTEM NORMAL OPERATION FOUND AT THIS TIMES
HROTTLE PEDAL.
des, road test again all check fine at this time QC by FP NTER.), road test, retest
TB3-844 12285

.

OBLEM FOUND
PEDAL ASSY, REPLACED ACCELERATOR PEDAL ASSY AND RETESTED OK.
CRONIZED PEDALS, ROADTEST AND RETEST, OKAY

SS SY. 3 RETESTED WORKING PROPERLY, QUALITY CHECKED JND. 4RED CODES TEST DROVE AFTER REPAIR

IAO TEST RE TEST PININ PEDAL ERATIC

8T AS PER SHOP MANUEL REPLACED ACCEL PEDAL ASSY CLEARED CODES RETESTED MONITORED VOLTAGE WORKING PROPERLY
AND NO CODES FOUND AT THIS TIME, TECH 298
< OK

PE83-844 32268

PECT PUEL, FUEL PUMP PRESSURE AT PUMP, AND LEFT AND RIGHT HEAD, KOEO, KOEO, CODES PO221, PO240, ALL OTHER TESTS PASS, PIMPOINT, REPLACED ACCELERATOR PEDV **FATALLING NOT VERIFIED** D NO PROBLEMS AT THIS TIME. TECH 298 MED DRIVE CYCLE AND NOTED NO ACCELERATION INTERMITTANTLY PERFORMED SEC, TEST KOSO POZZI KOSO P1111 KOSR P1111 PERFORMED PINPOINT TEST PER POWERTRAD STIDG FOUND ACCEPATOR PEDAL INTERNALY SHORTED CAUSING PREFORMCE CODTION, REPLACED ACCEPATOR PEDAL AND TESTED AGAIN TO VERIFY REPAIRS, TRUCK RUNS, NOT COME ON PIOS IVS AND AVP UNRESPONSIVE PPT AND CHECKED OPERATIONS, OK. ROAD TESTED, CK. PEB3-844 32287

ORTED GAS

ROAD TEST RECHECK ALL A P PUNCTIONS ARE NORMAL AT THIS TIME. M O 9241, COND CODE 42.

OK.

IAD TEST RETEST OK

ME.

221, KOERC P0221. INJECTOR BUZZ, CYLINDER CONTRIBUTION, EXHAUST RESTRICTION, KCP LOW IDLE, INJECTOR BUZZ, FUEL PRESSURE, RESTRICTION AND AIR RESTRICTION PASSET.

ABE PRESBURE TEST EXHAUST RESTRICTION TEST BOOST PRESSURE TEST INTAKE RESTRICTION TEST. FUEL PRESSURE TEST LEFT + RIGHT HEAD REPLACE. ACCELERATOR PED.

. PREFORMED PRIPORT TEST JK FOR PO221 FOUND THROTTLE PEDAL INTERALY SHORTED. REPLACED. PEDAL AND TESTED AGAIN TO VERIFY REPARIS, TRUCK. RUNS AND DRIVE

CODE AND RETESTED, PASS.
P ACCELRATER PEDAL, ROADYEST TRUCK AND CLEAR CODES.

LIDATION SWITCH IS NOT OPERATING PROPERLY, FOUND PIN PUSHED OUT HARD SHELL CONNECTOR, PUSHED PIN BACK IN, REMOVE AND REPLACE PEDAL ASSY, POOR CONNECTION

TEST OK REPLACED FAILED PEDAL ASSEMBLY CLEARED CODES AND RE ROAD TEST OK, TRUCK IS OPERATING NORMAL AFTER RETEST ALL PASS CODES P1111
S,PIN POINT TESTED IVS SWITCH,PAILLED,REPLACED SWITCH AND RETESTED, CONCERNISTILL PRESENT DASH ACCES,FOLIND SHORT ON CIRC.8129,WIREING REPAIRE ON CIRC.81
NTRIBUTIONTET, GLOW PLUG MONITOR TEST, CHECK HIGH PRESSURE AT SYSTEM LEVEL PPTS ACCEL, PEDAL ASSEMBLY AND SWITCH ERRACTIC. REMOVED AND REPLACED ACCE
PPLACE ACCEL PEDDAL

WITH NGS TO MONITOR ENGINE PIDS OK, 4E HIGHT, TEST DROVE... Q.C.TESTED BY K.D. 66) THAT THE

DIACCEL PEDAL ASSEMBLY, CLEAR CODES AND ITEST DRIVE, RETEST, OK.

PE63-644 32288

D PEDAL ASSY INOP AT TIMES REPALCED PEDAL ASSY RETEST MITIME FOR UNSUPPORTED LABOR OPERATION FOR REPLACING PEDAL ASSY BLY,CLEARED CODES AND TEST DROVE.

ST O

WHEN C ONCERN IS VERIFIED, REPLACE PEDAL ASSEMBLY FOR CONCERN, POST ROAD TEST ALL OK.

Y, CLEARED CODES AND RETEST OK.

. RETEST OK, CLEAR CODE

PUMP, ALL, WITHIN SPEC, RAN ALL, ENSINE PERFORMANCE TESTS, ALL WITHIN SPEC, RAN ROAD MONTOR TEST, MONTORED PIDS WHILE DRIVING, FOUND PID FOR AP FLUCTUATE

BRAKE PEDAL

DICCOE REPLACED ACCELL PEDAL ASSEMBLY 99836 POOR CONNECTION INTERMITTENT CODE X2 ROAD YESTED AND RECHECKED SYSTEM

E

ACCEL PEDAL PINPOINT TESTED ACCEL PEDAL GIRCUIT FOUND ACCEL PEDAL ASSEMBLY BAD REPLACED ACCEL PEDAL ASSEMBLY RETESTEDOK ROAD TESTED OK

TIME. DELETE MVALID LABOR OPERATION

EST NO CODES

CE ACCEL PEDAL ABSY, CLEAR CODES AND RETEBT.

PE63-844 32288

· · · · · · · · · · · · · · · · · · ·
INPOINT TEST AP CIRCUIT CODES. TEST DRIVE TO VERIFY REPAIR. (L. PASS. TEST DROVE ALL PASS. ERASED ALL CODES.
LIBAR CODIEST DRIVETO VERIEY REPAIR. 0221 ROAD TEST WIDS MONITOR PIDS AP PID GOES OPEN WHILE DRIVING REPLACED ACCELLERATOR PEDAL CLEARED CODE AND ROAD TEST OK
21 PINPOINT TEST FOUND AP SENSOR READING LOW 33V OUT OF SPEC REPLACED PAILED ADJUSTABLE PEDAL ASSY CLEARED CODES AND REPROGRAMMED POW TO LATEST LEV
BOOST 16 PSI CHECK ENGINE LIGHT ON RETRIEVED. CODE PO221 PERFONR NGS MONITORED ROAD TEST FOUND. TO VIRRATIC PERFORM BCE DIAG TO CHECK HARNESS. PERFOR BTABLE ACCELERATOR PEDAL ASSY, RETEST, 1855
y, retest. Clear codes. Road Test.
MES. REPLACE PEDAL ASSY. CLEAR CODES, RETEST AND ROAD TEST.
BILITY 550 PASS 5005F6 TO 1 BOOST PRESSURE 14PSI PASS 6005F12 TO 3 EXHAUST TESTRICTION PASS 5005F11 TO 2 PIN POIN TEST ACCELERATOR SWITCH OPEN CIRCUIT REPLACE
PE93-044 32290

.

.

LERATOR PEDAL AND RETESTED EEC. TEST DROVE OK.
ESPACHDING
OPERLY, RPELACED AP SENSOR AND RETEST DROVE OK,
FID TEST ALSO AFTER REPAIRS

CLEAR CODES, TEST DRIVE AND

OT CLAER REPLACE PCM CODE PO221 WOULD NOT CLEAR CALL HOTLINE CURT SSM 18412 CHK CHAFFING WIRE LT UPPER SHOCK TOWER TESTACCEL PEDAL INTERMITTENT OPEN CIRCUIT. RETEST AND ROAD TEST PASS

E TO VERIFY REPAIR.

EDAL CLEAR CODES RETESTION QUALITY CHECKED BY JUH

TP SENSOR, CLEAR CODES AND TEST DRIVE, RETEST, OK.

Y, CLEAR CODES AND RETEST.

D CLEAR CODES OK ROWIS4724 T9072 IN BOOK IS WRONG 133 SHOD SE 135 RECHECK AFTER R.T. REPLACED PEDAL ASSEMBLY AND RETEST OK

E3 RAR AND REPLACE ACCELERATOR PEODAL RETEST AND ROAD TEST

AY TEST REPLACED GAS PEDAL ASSEMBLY VISOR ASSY.
(TEST OK.
POT. THE TPS WAS REMOVED FOR REPLACIMENT. SYSTEM WAS THEN RETESTED TO VERFLY REPAIR.
FOR REPLACIMENT. SYSTEM WAS THEN RETESTED TO VERFLY REPAIR.

PE03-844 32291

ST DROVE ALL OK

AL ROAD TEST OK D CODES ROAD TESTED RETESTED OK !TEST ALL OK "EST OK AFTER REPAIR

ASSEMBLY.

SY AND RETEST FOUND LIGHT OFF AND

ΞST.

IEO CONCERN, VEHICLE WOULD DIE WHILE DRIVING, TIME TO PERFORM DIESEL DIAG, KOEO SYS PASS, KOEO BUZZ SYS PASS, KOER CYL, BAL PASS, GLOW PLUG PASS, CONT P022

DAD TEST AND DIAGNOSIS

2M FASS KOEO PASS

. PEDAL ASSY, RETEST DOL OK

ETEST OK

VE RPL ETO FOR INTERMITTEN FAULT RETEST

REPLACE RECHECK OUT OK

ACE (FAULTY) ACCEL PEDAL (FET) REF CLEAR CONT PASS RECK (OK) M TIME REPLACE ACCEL PEDAL (NO OPERATION)
Y FOR INTERMITANT TP FALLURE, RETEST AND ROAD TEST

XUND

PLACE ACCELERATO RIPEDAL RETERT AND ROAD TEST.

PEB3-044 32292

NEW TRUCK HAD WRONG STYLE REINSTALLED BOTH SWITCHS AND MADE SURE THE CORRECT ONE WAS ORDERED FOR THIS TRK. AS PER RP......48 48..GOT CORRECT PART AND ATE SELF TEST PASSED KOER SELF TEST PASS KOER GLOW PLUS SELF TEST PASS CYLINDER CONTRIBUTION SELF TEST PASS PAR THROTTLE POSITION SENSOR PEDAL ASSEMBLED FOR THE TO VERIFY REPAIR.

TEST DROVE QUOTESTED BY K.D.

CHILE AND INSTALL INTO THIS VECHILE

UN PINPORT TEST FET CLEARD CODES REITEST ALL CODES CAME BACK BUT P0221 WILL ACCEL NOW TIME TO ROAD TEST WILL SERLY PULL OD LIGHT ON TIME TO RUN TRANS
XI PEDAL CLEAR CODES REITEST ROAD TEST VERIFY REPAIR

"LACED THE PADAL AND TEST DROVE...

UELICP AND EEP PRESSURES WITHIN EXPECTE. RANGES PINPOINT TEST REPLACE ADJUSTABLE ACCEL, PEDAL ASSEMBLY CLERAED CODES AND RETEST P1111 TEST DROVE AFT

HECK OK

O K NO MORE CODES PRESENT.

EAGE 22100 TO 22108 CLEAR CODE, TEST DRIVE, RETEST, OK.

SHOWING CORRECT VOLTAGE IN CERTION POSITION, REPLACED ACCELARTER, PEDAL SWITCH ASSEMBLY

PASS 7 KDBO INJECTOR BLECTRICAL TEST PASS, SAIFUEL PRESS TEST AT THE RIGHT HEAD 65 PSI, 68) FUEL PRESS TEST AT THE LEFT HEAD, 65 PSI, OK, 9) PERFORM KOER ON DEMA

PEE3-844 32293

ST AND RETEST

ES RETESTED O.K

NSOR, VOLTAGE READS 0, CIRCUITS O.K. INSTALL. NEW ACCELERATOR PEDAL ASSEMBLY, CLEAR CODE AND RETEST, SYSTEM PASS. TECH 572

ST, OK NOW OK AT THIS THIS OK

OR OP.
OK I REPLACED THRACCEL PEDAL ABBY CLEAR CODES ROAD TEST AND RETEST SEC SYSTEM P1111 SYSTEM PASS.

EM, RETESTED AND TOST DROVE. TRUCK DID NOT LOCKE POWER, CONCERN PIXEFD ORE VEH OIK NO WORK CODES VEHS ACCELS FINE.

ELERATOR PEDAL ASY. CLEARED CODES. ROADTESTED OK. RETESTED OK. NO INSTALL NEW PEDAL AND CLEAR CODES, TEST DRIVE TO VERIFY REPAIR. GAS PEDAL ASSEMBLY, AND TIME FOR ADJUSTABLE PEDALS.. CLEARED CODS, ROAD TESTED MONITORING AP SIGNAL. VERIFIED REPAIRS.

SES, RETESTICK.

RESTRICTION PASS SPERFORM KOBO ON DEMAND TEST PASS SPRETRIEVE CONTINUOUS CODES P0221, PERFORM PINCINT TEST, PINPOINT TO THROTTLE PEDAL ASSY, REPLACED

THE CONCERN, RECOMMEND REPLACE THROTTLE PEDAL ASSEMBLY. E. TEST DRIVE, RETEST, OK.

. CLEARED CODES

MBLY LACE ACCELERATOR PEDIDAL RETEST AND ROAD TEST.

AND SENSOR ASSEY ADJUSTED PEDAL

MBLY YFP...

PE83-044 32284

AND ACCELERATOR PEDAL

CTOR BUZZ TEST PASS CHECK EXHAUST RESTRICTION NONE CHECK TANCEM PUMP PRESSURE SORS OK PERFORM KOER TEST PASS PERFORM CYLINDER CONTRIBUTION TEST PIN SWITCH EXRATIC, REMOVED AND REPLACE IDLE VALIDATION SWITCH ASSY AND ROAD TESTED AND RETESTED OK,
ACCEL, PEDAL ABSY, (INTER, CIRCUIT & MALURE IN ASSY.), REPROGRAMMED PON, RETEST HASACELL TROUB. IF IDLE FALLS BELOW 1000 RPM VERY BOOST, PUMP PRECODE PO135 PINPOINT TESTED FOUND BAD ACCELLERATOR PEDAL POSITION SWITCH REPLACED POSITION SWITCH REPLACED

YOR AP PEDAL BWITCH REPLACE.

OR PEDAL ASSEMBLY CLEARED CODE AND RETESTED OK

THEFT PASS INSTALLED FLIEL PRESSURE GAUGE AND CHECK FUEL PRESSURE FOULD OK AT 65 PSI BOTH HEADS PERFORM PINPOINT TEST FOR CODE P0128 DIAG AND FOUND AP F

ETEST AND ROAD TEST

CLOISPLAY AGAIN PIN POINT FOUND AP SENSOR VOLTAGE JUMPS BETWEEN 94 TO 1.19 WHILE ACCEL REPLACED ACCEL PEDAL ASSEMBLE RETEST & ROAD TEST, OK REQUEST M.

1AL ASSY, EEC RETEST AND FINAL ROAD TEST ROAD TEST OK

BPLACE PEDAL ASSEMBLY.RETEST PAS

BACK ORDER TILL 6 14 02 PER DOES 11

SSEMBLY, RERAN TEST, ROAD TEST.

PER3-844 32285

LEAR ALL CODES RETEST TEST DRIVE OK SECHECKED AFTER ROAD TEST OK REPAIR.

ONCE MORE NO MORE CODES VEHIOR AT THIS TIME. REDAL ASSY, RETERT AND ROAD TEST

), CLEARED COOSS & REPUN SYSTEM TESTS, PASSED ALL TESTS.

M FOR PO221 FOUND THROOTLE PEDAL SHRTED CAUSING NO ACCERLER TION, REPLACED THROTTLE PEDAL AND PREFORMED FINAL QUICK TO VERIFIY REPAIS, TRUCK RUNS AND RETEST FOUND CODE GONE AND POWER ROTTLE PEDAL ASSY.
ROTTLE PEDAL ASSY.

VELOK INTAKE RESTRICTION OK KORO TEST CODE 221 ERASE AND RETEST OK FUEL PRESSURE TEST AT BOTH HEADS OK CYLINDER CONTRIBUTION TEST OK EXHAUST RESTRIC

IN CLEARO CODES RETERT P1111

OVE IN TANDOM WITH BRAKE PEDAL, CLEAR AND RETESTED ROAD TEST SYSTEM PASS.

AND AT THE ETC (ELECTRONIC THROTTLE CONTROL) ALL PASS, CHECK FUEL PRESSURE AT BOTH HEADS (PASS 70 PSI) PERFORM INJURIECTRICAL TEST PASS, RUN CASIS, NO AD RERAM NGG TESTS AND QAVE NO CODES AFTER REPAIR.

USTABLE THROTTLE PEDAL AP SWITCH CLEAR CODES, RECALIBRATE PCM TO LATEST LEVEL PER SSM 15608, CLEAR CODES RETEST KOED PASS KOER P1000 N° TIME CLAIMED TO I

OK.

PEB3-844 32298

ASSEMBLY AND CLEAR CO DEG. TEST DRIVE TO VERIFY REPAIR. CAU TEST CK.
-AUR OK
METEST, DIAG. SHEET ATTACHED TO HARD COPY.
GINE PERFORMANCE DIAGNOSIS FOR LOSS OF POWER CONCERN, NO CODES FOUND AT THIS TIME, FUEL PRESSURE OK AND BOOST PRESSURE OK AT THIS TIME. OIL QUALITY AT
REPLACE PUEL PEDAL BENSOR ASSY CLEAR CODES AND ROAD TEST OK
ED CODES TEST DROVE ONCE MORELYEM O K.
INIT RUNS WELL MILES OUT 5628
30 AND TEST DROVE CHECKS OK AT THIS TIME
LONG RIFED REPAIR RETEST AND RD TEST
OVÉ ALL CHECK OKAY AT THBI TIMEOC BY FP
ST VERITY REPAIR OK
E, WHITE OUT AT BODY, REPAIR WIRLING CLEAR COORS & RETEST, NECESSARY TO REPLACE ACCELARATION PEDAL & CLAER COORS & RETESTED G RESET KAM # CASA.
PEB3-844 32297

.

.

R CODES, ROAD TEST, ESC TEST AGAIN, PASS CODE, P1000, ALL O.K. AT PRESENT TIME.

KCASE PRESSURE, CYL, CONTRIBET, EXHAUST RESTRICTION, AND BOOST PRESSURE) TIME TO REPLACE ACELL PEDEL TIME TO CLEAR CODES TEST DRIVE AND RETEST

ES WHILE MOVING INTO GEAR TEST DRIVE TO VERIFY CONCERN HOCK UP WIDS RETRIEVE CODE PO 202 AP SENSOR OUT OF SELFTEST RANGE RECORD AND MONITOR PIDS FOR INSTALL A NEW ACC PEDAL ASSEM CLEARED CODE AND RETEST PASS P111

DO WITH IT

EDJSYSTEM PASSED.

L MONITOR AND

ALBRAS PCM TO THE LATEST CALIBRATION. TEST DRIVE TRUCK.

DCONNECTION, TESTS OK.

TED OK, ROAD TESTED OK.

2D COOKS RETEST

) KOSO INJECTOR SLECTRICAL TEST PARS, SAIFUEL PRES 6 TEST AT THE RIGHT HEAD 65 PSI, 68) FUEL PRESS TEST AT THE LEFT HEAD 65 PSI, 6) PERFORM KOER ON DEMAND PASS, 1 AND PO221 (THE PO221 IS AP 6 SENOR CODE RAN FE 1 PINPOINT TEST THROUGH FE 4 CONCLUSION ACCERATOR PEDAL BAD (ORDERED PART REMOVED) ACCERATOR PEDAL AND I

O BOOST

ILES OF 11519 AND CROSS REF. RO # 74900. 30 PEDAL AND RETEST ALL

PE03-644 32298

CUST_TXT

CUSTOMER REPORTS VEHICLE WILL NOT REV. BY THE GAS PEDAL, JUST STARTS AND IDLES, DRIVESHAPT REMOVED BY TOWING COMPANY CHECK ENGINE LIGHT

CUSTOMER STATES WHEN STEPPING ON GAS VEHICLE WONT ACCELERATE ((TEC 115))

AT TIMES CHECK ENGILIGHT WILL COME ON SOMETIMES WHEN TAKING OFF PROM A STOP THERE WILL BE NO THROTTLE RESPONSE

WONT GO OVER 5 MILES PER HOUR

CUSTONER STATES YELLOW CHECK ENGINE LIGHT HAS BEEN COMING ON, ENGINE CUTS OUT WHEN THIS HAPPENS, CHECK AND ADVISE

CUSTOMER STATES: NO ACCEL BOGS DOWN.

ENGINE IDLES BUT HAS NO THROTTLE RESPONSE AT TIMES

CUST STATES INTERMITICK ENGINE LIGHT COMES ON WHEN THIS HAPPENS VEHICLE HAS NO RESPONCE FROM ACCEL PEDAL

CUST STATES VEH HAS NO THROTTLE RESPONSE AT TIMES ADVISE

LOOKING POWER ENGINE LIGHT COMING ON

ENGINE STALLS

CHECK ENGINE LIGHT ON AT TIMES, CUSTOMER SAID ENGINE WOULD NOT ACCELERATE WHEN LAMP WAS ON

CUSTOMER STATES THAST THE ENGINE WON'T ACCELERATE UNDER HEAVY LOAD

CLIENT STATES CHECK ENGINE LIGHT COMES ON AND GOES OFF WHEN LIGHT COMES ON VEH, YER HAS NO PULL

BERVICE ENGIEN LIGHT COMES ON & MOTOR WILL CUT OFF AT STEADY SPEED OR A STOP ALSO WHEN PUSHING DOWN THROTTLE AT TIME MOTOR WILL ONLY STAY AT IDLE

CUSTOMER STATES HESITATION WHILE ACCELERATING WILL NOT GO

CHECK ENGINE LIGHT IS ON (WHEN LIGHT IS ON, VEHICLE ACCELERATOR IS INOP)

CHK ENG AMBER (MIL) C 8 AT TIMES WHEN APPLYING ACCELLERATOR WONT ACCELLALSO WILE ORIVING AND ACCELL GOES TO TOLE

#29 C 8 ENG. (DIBBBL) CK, ENG. LITE ON

C S WHILE DRIVING VEH THROTTLE WILL NOT RESPOND AND GO TO AN IDLE

CHECK ENGINE LIGHT CALLE ON, ENGINE OUT RESTARTED

CUST STATES THROTTLE STICKING

DS0 ACCEL PEDAL DDGS NOT RESPONS

PEB3-844 32288

CHECK FOR THROTTLE DOES NOT WORK UNTIL ACCELRATOR PEDAL IS PUSHED UP AND DOWN REPEATEDLY CHECK ENGINE LITE COMING ON WHILE DRIVING WITH NO POWER, WITH STOP WILL NOT ACCEL

CUST STATES DIES WHILE DRIVING, WHEN LET OFF ACCELERATOR

COMMER REPORTS THAT INTERR WHEN DISTANCE VEHICLE LOOSES FOWER OR CLITS OUT DIAGNOSE & REPORT

CUST, STATES CHECK ENGRAT LAMP ON AND OFF WHEN ON NO ACCELERATOR CONTROL

C & THAT THE ENGINE LIGHT IS COMING ON & OFF AND ENGINE HAS NO POWER WHEN THE CHECK ENGIE IS ON

CUSTOMER STATES LOSS OF POWER

MFCZ CUSTOMER STATES VEHICLE WON'T ACCELERATE THAN STARTS TO DE OUT AFTER HE PUTS IT IN NEUTRAL IT \$

AT TIMES CHICKING LIGHT COMES ON AND OFF WHEN LIGHT IS ON WILL NOT ACCELERATE

AT TIMES VEH WILL NOT ACCEL, PUT INTO NEUTRAL AND BACK INTO DRIVE THEN IT WILL GO ADVISE

SERVICE ENGINE SOON LIGHT ON , NO RESPONSE PROMACCEL PEDAL. TURBO DIESEL. TOW IN

CUST STATES VEH WONT ACCELERATE AT TIMES JUST STAYS AT IDLE

CUST STATES SET LT COMES ON AND WHICH IT DOES VEH WONT ACCELERATE WHEN PEDAL PUBLICD ONLY IDLES!

LOOSES POWER WHEN DRIVING AND LACKS ACELERATION.

CUST STATES CHECK REASON VEHICLE SEEMS TO BE BUCKING CRUISE SPEEDS APPROX 40 46MPH.....CHECK AND ADVISE

DEG O ACCELERATOR PEDAL CLITTE WORKING AT TIMES WHEN DRIVING

CHECK ENGINE LIGHT ON AND WONT ACCELERATE

CUST STATES TAHT TRUCK CUTS OFF WHEN DRIVEING CK ENGLIGHT ON

CUST STATES VAC IT WILL START BUT WONT REV UP ENOUGH TO TAKE OFF

CHRCK ENGINE LIGHT COMES ON INTERMITTENTLY

CUST STATES THAT THE SES LITE IS ON AND WONT MOVE FORWARD OR REVERSE EXCEPT AT IDLE

CUSTOMER STATES THAT HE HITS THE GAS AND THE TRUCK WON'T MOVE

OCCASIONALLY LOSES POWER WHILE DRIVING DOES NOT STALL SERMS TO HAVE NO RESPONSE TO ACCELERATOR PEDAL PRESSURE,

INSTALL BOP REF#\$4889

INTERMIT NO ACCEL

CUSTOMER STATES THAT CHECK ENGINE LIGHT IS ON.

529 CK.W ACCOUL PEDAL BARELY APPLIED ENGISTARTS SURGING SEE GARRETT

E29 CUST STATES SERV ENG LIGHT STAYING & WILL NOT ACCEL AT TWES CHECK

CUSTOMER STATES: VEHICLES RPAIS WILL NOT RAISE WHEN IN PARK OR NEUTRAL CAN HOLD PEDAL TO FLOOR NO CHANGE (CHECK ENGINE LIGHT WILL COME ON NOT ONNOW)

WON'T ACCEL UNLESS PEDAL KICKED

OWNER STATES CHECK ENGINE LIGHT IS ON DASH WHILE DRIVING AND WHEN THIS HAPPENS CANNOT ACCELERATE...

DAZ CLIST STATES WILL NOT ACCEL 011500

CUSTOMER STATES THAT INTERNATTENTLY WHILE DRIVING ENGINE LOSES ALL POWER IF YOU PUSH GAS PEDAL NOTHING HAPPENS

CUSTOMER STATES NO THROTLE RESPONSE AT TIMES

CHECK ENGIN LIGHT COMES ON AND ENGIN LOSES POWER USUALLY WHEN SLOW TO TURN OR STOP.

CLIST STATES CK ENGINE LIGHT IS ON AND VEHICLE WILL NOT ACCELERATE

WILL NOT ACCELL WILL ONLY DUE

CUST STATES AFTER VEHICLE SITS AWHILE AND THEN START THE CHECK ENGINE LIGHT WILL COME AND IT WILL NOT ACCELLERATE

NO ACCEL STEOP ON GAS NOT GETTING POWER AT TIMES LIKE GETTING NO FUEL

WE ESP WHILE DRIVING CHECK ENGINE LIGHT WILL COME ON AND THROTTLE WILL NOT RESPOND WILL RUN AT IDLE ONLY WILL PICK UP IF TURNS CRUSS ON WORKS OK IF LETS 5

CUST STATES SERVICE ENGINE LITE ON

CISIENG STALLS AND LACKS POWER CHECKIENG LIGHT ON IN DASH AND WAIT TO START LIGHT COMES ON WIDRINNG.

MILLIGHT COMES ON AT TIMES

CUST STATES THAT THE TRUCK WILL START AND MOVE IN GEAR BUT IT SEEMS LIKE GAS PEDAL IS NOT ATTACHED.

CUST STATES THAT THE VEHICLE KEEPS CUITING OFF

CUST STATES CHECK ENGINE LIGHT ON WHEN IT COMES ON TRUCK DIES OUT

CHECK ENDINE LIGHT COMES ON WHILE DRIVING, ENGINE WILL NOT RUN ABOVE IDLE, CAND SHUT DOWN AND WILL BE OK FOR AWHILE

CLUSTONER STATES CHECK ENGINE LIGHT ON LACK OF POWER. INTERMITTENT NO THROTTLE RESPONSE WITH VEHICIVE IT GAS NOTHING HAPPENS CHECK ENGINE LIGHT COMES ON INTERNAL ENGINE LIGHT WILL COME ON ; WHEN PUSHED ON ACCELL, PEDAL THERE IS NO RESPONSE CK FOR TRUCK WILL NOT ACBUL WHEN STEPPING ON ACEU. 8.O.P WHEN COMING TO A STOP, CHECK ENGINE LIGHT COMES ON AND RAS NO THROTTLE C S THAT THE CHECK ENGINE LIGHT IS COMING ON ALSO IS LOSING POWER PLEASE CHECK VEHICLE RETURNS TO IDUE GONING DOWN ROAD CUST STATES WHEN TRUCK IN DRIVE INTERM WHEN HOT DOES NOT ACCEL D35 ENGINE WONT ACCELERATE AT TIMES, WONT RESPOND TO PEDAL AT TIMES D36 WILL NOT ACCELERATE FROM A STOP AT TIMES CUST STATES VEHICLE WOULD NOT MOVE FROM A STOP, NO POWER SHIFTED ALL THE WAY DOWN TO FIRST GEAR AND THEN IT WOULD GO CUST STATES ON BLIGHT ACCELERATION ENG HAS FULL THROTTLE ACCELERATOR QUITS WORKING WHILE DIVING AND SURGES O S ENGINE HAS NO THOTTLE RESP. AT TRIES TRIK WONT ACCULAND YOU HEAR A CLICKING SOUND. CUSTOMER STATES THAT THE CHECK ENGINE LIGHT COMES ON AT TIMES, ENGINE BOGGS DOWN AND WILL NOT ACCEPT CHECK ENGINE LIGHT COMES ON SOMEMES AND WHEN IT DOSE YOU CAN PUSH DOWN ON THE THROTTLE AND IT WILL

C & CEHCK SINGINE LIGHT WILL COME ON WHEN THIS OCCURS, VEHICLE WILL NOT MOVE HAS NO POWER 528 CK ENGINE LIGHT ON AND HAS NO POWER WHAT SO EVER. CHECK FOR CHECK ENGINE LIGHT COMES ON AND THROTTLE WONT RESPOND E28 CUSTOMER STATES CHECK ENGINE LIGHT CAME ON WHILE DRIVING AND VEHICLE LOST POWER. DOES NOT RESPOND W 1502 CLISTOMER STATES THE ENGINE WILL NOT GO OVER 4 MPH. CK ENGINE LIGHT IS ON. CUSTOMER STATES THE ENGINE WONT ALWAYS RESPOND TO THE THROTTLE LOSS POWER WHEN DRIVING AND DASH LIGHT WAS ON ENGLIGHT WAS ON CUST STATES VEHICLE LOSES POWER AND ACCEL PEDAL DOES NOTHING IF ALLOWED TO IDLE ENGINE WILL RUN OK QUST STATES VEH HAS NO THROTTLE RESPONSE AT TIMES TRUCK WILL DIE WHEN ACCL. ON HARD FROM STOP CUST STATES THERE IS NO THROTTLE RESPONSE AT TIMES, SOP IN E29 QUST STATE OK ENGINE LIGHT ON WILL NOT ACCEL CUSTOMER STATES CHECK ENGINE LIGHT ON TWICE HAS DIED AT STOP TRYING TO ACCL. CUSTOMER STATES NO THROTTLE WHEN ACCEL. E29 CHECK ENGINE LIGHT WILL COME ON AND ENGINE WILL HAVE NO POWER THE LIGHT WILL GO OFF THEN IT HAS POWER AGAIN. CK ENG LIGHT IS ON AND UNIT WILL NOT ACCEL

C S CHECK BYGINE LIGHT ON
VEHICLE CUTS OUT WHEN DRIVING
ENORE STAY AT HIGH RPM BUT WON,T MOVE
CUSTOMER STATES CHECK ENGINE LIGHT ON AND NO THROTTLE
CHECK TRUCK WILL TRY TO SHUT DOWN WHEN SLOWING DOWN AND MAKING A TURN WILL CUT OUT BUT START RUNNING AGAIN 050
CUST STATES PUSH ON ACCS, DOESN'T GO SOMETIMES
C S DIES WHILE DRIVING AT LOW SPEEDS SEEMS TO JUMP INTO GEAR
STALLS ON ACCS, LENATION
TRUCK WILL, NOT MOVE OVER IDLE SPEED
CHECK ENGINE LIGHT IS ON LOSS POWER ON ACCSL.

PEB3-844 22381

CK ENG RUNS & QUITS CK ENGINE LIGHT COMES ON AT TIMES AND TRK WILL ALMOST STALL SEE NOTES CK ENGLIGHT COMES ON NO ACCELERATION CUSTOMER STATES THE CHECK ENGINE LIGHT COMISSION AND THE VEHICLE LOSES ALL POWER NO ACCELERATION INSPECT CHECK ENGINE LIGHT IS ON THROTTLE PEDAL DOES NOT RESPOND WHEN PURHED ON BEE ED CUSTOMER STATES CHECK ENGINE LIGHT ON E29 VECH HAS NO THROTTLE CUSTOMER STATES CHECK ENGINE LIGHT STAYS ON AND ENGINE WILL NOT ACCEL WHEN DEPRESSING ACCEL PEDAL ENGINE LIGHT COMES ON THEN ENGINE DOES NOT WANT TO GO BEEMS LIKE NO RE ACTION FR CK ENGINE WILL NOT ACCELERATE DBD VEH WONT ACCELERATE WHEN GAS PEDAL DEPREBBED BOP HERE CK ACCELLERATOR PEDAL BTUCK AND CRUISE CONTROL WENT OUT CUSTOMER STATES CK ENGINE LIGHT IS ON CUST STATES CHECK ENGINE LIGHT WILL COME ON, STATES WHEN DOES, WONT TAKE FUEL, STATES HAVE TO KEEP FOOT CK. ENGINE LIGHT IS ON WHILE DRIVING CK. AND ADVISE CHECK OUT THROTTLE CABLE BROKEN....W CS CHECK ENGINE LIGHT COMES ON AND PEDAL WONT RESPOND LOSES POWER PROM 65 TO 66 MPH DROPS TO AROUND 50 MPH THEN PICKS BACK UP VEH HERITATES WHEN DRIVING AT SPEEDS OVER SEMPH CHECK ENGINE LIGHT COMES ON WHILE DRIVING NO ACCEL: IDLE ONLY CUSTSTATES SERVICE ENGINE LITE ON WONT ACEL CUSTOMER STATES VEHICLE WONT MOVE AND CHECK ENGINE LIGHT COMES ON AT TIMES (HAS TO TURN TRUCK OFF AND RESTART FOR VEHICLE TO MOVE) CUSTOMER STATES THERE IS NOT RESPONSE IN ACCEL PEDAL CHECK AND ADVISE CUST STS WHEN TRUCK WAS IN PARK AND PUT INTO DRIVE TRUCK HAD NO THROTTLE RESPONSE CUST STATES CK ENGINE LITE COMES ON AN STARTED LOOSING POWER. EZE CO THE CHECK ENGINE LIGHT COMES ON, AND THE THROTTLE WIL NOT RESPOND. WHEN PRESSED, NOTHING HAPPENS GAS PEDAL INCP, VEHICLE IDLES BUT DOES NOT ACCELERATE \$100 DEDUCTIBLE CHECK ENGINE LIGHT TRUCK WILL NOT ACCU. WITH OUT BURGING TEST DRIVE AND ADVISE ACCLERATOR PEDAL PUSH AND ENGIFALLS HAVE TO WORK WITH PEDAL TO GET IT TO OPERATE. OK ON CRUISE ENGINE GOES TO IDLE ABO STAYS AT IQLE SOMETIMES (PRESSING ON THE ACCELERATOR DOES NOTHING WONT ACCEL AT TIMES NO RESPONSE FROM THROOTLE CHECK TROTTLE WILL NOT ACCELERATE WHEN DEPRESSED INT STATES CHECK ENGINE LIGHT ON WHEN DRIVING, WON'T ACCELL, ENGINE LIGHT COMES ON AND HAS NO POWER WILL NOT ACCEL, AS SOON AS LIGHT GOES OUT, TRUCK WILL ACCEL 042 CUSTOMER STATES THAT AFTER COMING TO A STOPE OF LIETTING OFF OF ACCELERATOR WHIEL DRIVING ENGINE ONLY IDLES CHECK REPAIR WATER IN FUEL WARNING LITE COMES ON AND HAS NO POWER C 8 ACC PEDAL NOT WORKING D&O ENGINE MESTITATES SURGES WHEN ACCELERATING TRUCK WILL NOT ACCELERATE CUST STATES ENGINE HAS ON POWER AT TIMES VEH LOOSE'S POWER WHILE ORIVING CUST STATES THROTTLE REVS VERY HI RED LINES CHECK ENGINE UGHT ON E29 CUSTOMER STATES CHECK ENGINE LIGHT IS ON, VEH HAS NO POWER AT IDLE.

CHECK ENGINE LIGHT ON, CUTS OUT

CUSTOMER STATES THAT VEH DOES NOT RESPOND TO FOOT FEED INTERMITTANTLY

ASSISOP TO SENSOR AND ACCELERATOR PEDAL ASSEM, HERE FOR LINEWA

CUSTOMER STATES THAT GES LIGHT IS ON, AND THROTTLE IS INOP INTERMITTENTLY DURING OR AFTER SLOWING DOWN, PLEASE CHECK

PRESS ACCELLERATOR VEN ONLY IDLES MOST OF TIME

ENGINE LIGHT COMES ON AND WILL NOT GO FOWRAD . WILL NOT MOVE

"DID ACCELERATOR PEDAL DOES NOT RESPOND AT TIMES, WHEN THIS HAPPENS LITE ON DASH COMES ON.

CK, ENGINE LIGHT IS ON

O.R. CHECK ENGINE LIGHT WAS ON WHEN THIS WAS ON ENGINE WOULD NOT ACCELERATE IN GEAR OR PARK

QUETOMER WISHES TO LEAVE TRUCK FOR TEST DRIVE. DIAG TO ASSURE PARTS ORDERED ARE CORRECT.

CUST STATES CHECK ENGINE LIGHT COMING ON INTERMITTANTLY & AT TIMES ENGINE LOOSES ALL POWER WHILE DRIVING & YOU CAN PUSH ON GAS & NOTHLING HAPPENS

CHECK ENGINE LIGHT ON WONT ACCELERATE

E20 CUST STATES CK ENGINE LIGHT COMBS ON AND TRUCK STALLS WHILE DRIVING

DIAG. ENGINE DIES OUT GOING DOWN ROAD

D42 CLISTONIER STATES AT TIMES VEHICLE WILL NOT ACCEL, WILL ONLY IDLE

AMBER ENGINE WARNING LIGHT ON

DEC ONE TIME AT STOP BIGN VEHICLE WOULD NOT MOVE WHEN ACCEL HAD TO SHUT OFF AND RESTART AFTER FLOORING ACCEL PEDAL

CK FOR CRANK NO START BLEW WHITE SMOKE FROM TALL PIPE SMELLS LIKE RAW FUEL PREVIOUS TO THAT IT STOPED ACCELLERATING YOU HAD TO WORK PEDEL TO GET IT

C 2 BING IDLES BUT WONT RUN BAYS CAN WIGGLS WIRES AT GAS PEDAL SENSOR AREA AND WILL RUN

CUST STATES TRUCK STALLS AT LIGHT

CUSTOMER STATES WHILE DRIVING WILL COME TO A STOP INTERMITTE NTILY AND WILL PUSH ACCELLORATOR TO TAKE OFF AND VEHICLE

CHECK ENGINE LIGHT ON

C & VEHICLE HAS AN ENGINE MISS WHEN A C IS ON

DED ENGINE WILL STOP ACCELERATING INTERMITANTURY CHECK AND ADVISE

CHECK FOR NO RESPONSE FROM ACCELERATOR.

CHECK ENGINE LITE ON ALSO ON ACEL HAS NO POWER

CK FOR START VEH PUSH ACCEL AND NOTHING HAPPENS

CLIST, STATES WHEN UP TO SO COMPHITIK, ACTS LIKE WANTS TO DIE OUT BEEMS LIKE NOT GETTING FUEL

CHECK ENGINE LAMP IS ON AND NO ACCELERATION WHEN ON

CUTS OUT WHEN DRIVING CHECK AND ADVISE...

MEL LIGHT ON AND NO THROTTLE

CUSTOMER STATES CHECK ENGINE LIGHT COMES ON WHEN LIGHT SOMES ON VEHICLE LOSES POWER AND ACTS LIKE IT WANTS TO CUT OFF

QUET REQUESTS A RENTAL CAR FOR ONE DAY

CUST STATES WHEN DRIVING THE TRUCK LOOSES POWER LIKE THE GAS PEDAL IS INOP YOU CAN FLOOR IT ADM THE TRUCK WILL NOT EVEN REV UP

CHECK ENGINE LIGHT COLLES ON WHEN DRIVING, WHEN ON THE ENGINE LACKS POWER ON ACCEL

PUSH ACCELERATOR PEDAL AND NOTHING HAPPENS. AFTER A PERIOD OF TIME IT WILL GO

CUST STATES AT TAKES WHEN SHIFTED INTO ORIVE SERVICE ENGINE SOON LIGHT COMES ON AND VEHICLE DOES NOT MOVE....CHECK AND ADVISS...

CLIST STATES GARS PEDAL INOP AT TIMES FRELS LIKE LETTING OFF GASS.

CHECK ENGINE LIGHT ON AND VEHICLE HAS NO ER ON ACCELERATION. SEES BLOW BY OR LEAK ON TURBO Y PIPE

LACK OF POWER ON ACCELERATION CHECK ENGINE LIGHT ON IDLES HI ROUGH FAN CLUTCH WILL, NOT ENGAGE CUTS ON OFF ÉVÉRY 2 5 SEC

THERE IS A CK ENGINE LIGHT COMING ON

BOGS DOWN WHEN ACCLE CUSTOMER BAY IT IS VAPOR LOCKING

CISICHECK ENGINE LIGHT ON LACKS POWER HAS TO KEEP FOOT ON ACCELERATOR ON ACCEL OR AT IDLE TO KEE

CLISTOMER STATES AFTER HARD STOPPING. THEN APPLING PUBLING RESPONSE. 10 SECOND DELAY THEN GOES.

D42 CLISTOMER STATES THAT GAS PEDAL HAS NO PRESSURE

DIAG CHECK ENGINE LIGHT ON AND WHEN PRESSING ACCEL IT DOES NOT MOVE

C & THAT THE TRUCKS CHECK ENGINE LIGHT IS ON, WHEN YOU PRESS GAS PEDOLE NOTHING HAPPENS

WILL NOT ACCEL OR TAKE GAS.

CUST SAYS WHEN DRIVING ACTS LIKE DOWN SHIFTS AND THEN BLICKS AND SURGES, HAPPENS WARM OR COLD, ADVISE

CHECK ENGINE LITE ON HAVE TO PUMP ACCELARATOR AT TIMES CHECK ENGINE LIGHT COMING WHEN CEPRESS ACCEL PEDAL HAS NO RESISTANCE CUSTOMER STATES CHECK ENGINE LIGHT COMES ON AND WHEN IT DOES LOOSE THROTTLE CUST STE VECH START AND RUNG CK ADV CHECK ENGINE LIGHT IS ON AND AT TIMES WHEN ACCELERATI ING OR DRIVING IT HAS NO ACCEL. WHEN LIG WON'T ACEL PROPERLY, RPMS FLUXUATE EZSIDIAG SES LIGHT COMES ON AND VEH HAS LOST POWER UNDER ACCLERATION FROM STOPS. BURGES WHILE DRIVING WHILE DRIVING THE RPMS DROP DOWN TO IDLE AT TIMES NO RESPONCE FROM THROTTLE MOST OF THE TIME CHECK ENGINE LIGHT IS STAYING ON. AT TIMES THE VEH FEELS LIKE IT IS NOT GETTING GAS D21 ENGINE STALLS WHILE DRIVING INSTALL SOP CHECK ENGINE LIGHT COMES ON AT TIMES. LACK OF POWER ON ACCELARATION WHEN THE LIGHT IS ON CC D50 CUST STATES AFTER 12 DAY OF DRIVING VEH WILL HAVE NO THROTTLE RESPONCE, PUSH ON GAS, NOTHING HAPPENS CISITHE CHECK ENGINE LIGHT IS ON THE ENGINE HAS NO POWER CIK ADVISE. CHECK ENGINE LIGHT COMES ON ACCELERATOR PEDAL GOES DEAD SEE GENE IN PARTS CLITTING OUT WHILE DRIVING EMISSION LIGHT IS ON AND TRUCK HAS HESITATION. CISITHE ENG. WILL ALL OF A SUCCENILOSE POWER AND THE ACCELERATOR WILL NOT RESPOND... ACCECLERATOR PEDAL NARD TO PUSH D50 TECH 4

E29 C 9 TRANS NOT ENGAGING WHEN YELLOW ENGINE LIGHT IS ON

CUSTOMER STATES TRUCK HAS LOW THROTTLE PEDAL RESPONSE

CUST STATES CHECK ENGINE LIGHT ON

C & ELIGBRION CONTROL LIGHT ON AND TRUCK IS RUNNING ROUGH AND ENGINE IS. KILLING ON HIM

CUST STATES WHEN ACCEL NO POWER WILL NOT ACCEL CK ENGINE LIGHT ON AT TIMES

CUST STATES CK ENGINE LIGHT IS COMING ON INTERMITTANTLY ALSO WHEN LIGHT COMES ON CUST STATES WHEN ACCELLING WOULD NOT SPEED UP

OK ENGINE INTERMITTENTLY WONT ACCELERATE

CUST STATES WHEN ACCELEARTING VEH HEBITATES

C S INTERMITANTLLY LOOSES GAS PEDAL FUNCTION

CK ENGINE LITE ON VEHICLE WILL NOT GO OVER 2 MPH_RPMS WILL NOT CHANGE IF PRESSING ACCELERATOR TO PLOOR ... IF YOU TURN VEHICLE AND BACK ON SEVERAL CUSTOMER STATES THROTTLE WILL NOT RESPOND NO THROTTLE

DIAG STALLING OUT

829 CC CHECK ENG. LITE WILL COME ON AND THEN GAS PEDAL WILL NOT WORK

CISICHECK ENGINE LITE COMES ON, WHEN ON TRUCK WILL IDLE BUT NO RESPONSE PROMICAS PEDAL PUMP 3 TIMES LITE GOES OUT AND DIK

TRUCK WILL NOT ACCELERATE

QUISTOMER REPORTS CHECK ENGINE LIGHT COMES ON WHILE DRIVING AND ENGINE LOOSES FOWER WHEN TRYING TO ACCEL.

DSI CLIST STATES CHECK ENGLIGHT ON WHEN IT DOES CUST HAS NO ACCELERATION ALSO AT TIMES JUST WHILE DR

CK ENGINE LIGHT ON AND SOMETIMES HAS LACK OF POWER ON ACCELLERATIO

THERE IS NO RESPONSE WHEN THE ACCELERATOR PEDAL IS DEPRESSED SOMETIMES.

DEG WHILE DRIVING CHECK ENGINE LIGHT COMES ON AND ENGINE WONT ACCELERATE AT ALL, SHUT OFF ENGINE, AND WILL RESTART AND RUN FINE UNTIL CK ENGINE, LIGHT COM-ENGINE CLITS OUT WHEN DRIVING

CRANKS AND IDLES CHECK ENGINE LIGHT COMES ON AND WILL NOT GO WHEN LIGHT GOES OFF ITS OK

CUST STATES CK ENGINE LIGHT IS AND ENGINE LOSS OF FOWER

PERS-844 32304

CK ENGINE LIGHT ON GAS PEDAL NOT RESPONSIVE (ADVISE) CUSTOMER STATES NOTHING HAPPENS WHEN YOU MASH ACCEL CUST STATES TRANS WILL NOT PULL OUT OF O D RPMS DROP. CLIST STATES FUEL PEDAL WILL NOT ACCELERATE CUSTOMER STATES CK ENGINE LT COMES ON DRIVING STATES LOGSES POWER DRIVING ADVISE CUST STATES CHECK ENGINE LIGHT IS ON, INSPECT AND ADVISE, VEHICLE HAS LOW POWER. POSICE WHILE DRIVING AT TIMES, THE GAS PEDAL BECOMES INOP INSTALL SOP PART CHECK ENGINE LIGHT WILL COME ON SHILE DRIVING AND ENGINE WILL BOG AND NOT ACCELERATE CLISTOMER STATES THAT VEHICLE CHECK ENGINE LIGHT IS ON. (SOP) CUST STICEL ON , TRUCK WONT ACCEL. CUSTOMER STATES THE SESILIGHT HAS COME ON, WHEN THIS HAPPENED THERE BEEMED TO BE NO ACCLERATION... HESITATES WONT ACCELERATE CLIRTOMER STATES: ENGINE SURGE WHILE DRIVING CCC D50. ENGINE BUCKS AND JERKS AND SURGES WHILE DRIVING - ENGINE LIGHT COMES ON WHEN IT DOCS THIS CK ENGINE LIGHT ON AND CUSTOMER STATE THAT WHEN STEPPING ON THROTTLE TRUCK WON'T GO E28 CHECK ENGINE LIGHT COMES ON AND NO POWER ON ACCEL. VEHICLE WILL NOT ACCELERATE

OWNER STATES WHILE ACCEL THEN LET OFF GAS PEDAL CHECK ENGINE LIGHT COMES ON THEN WILL NOT ACCEL, CHE

CUST STATES WHILE DRIVING ENGINE WILL NOT ACCELERATE PROPERLY..

CHECK ENGINE LIGHT, LACK OF POWER

CHK CEL COMES ON AND NO RESPONSE FROM ACCEL PEDAL

VEHICLE LACKS POWER

CK ENGLIGHT COMES ON AT STOP AND WHEN SLOWING DOWN AT TIMES, WAS RUNNING VERY ROUGH AT TIME LIGHT.

NO THROTLE RESPONDE

TOWED TO SHOP BY CLISTOMER...CS CHECK ENGINE LIGHT COMES ON AND VEHICLE WONT MOVE.

C 8 INTERMITTENTLY ON ACCELERATION FROM STOP TRUCK EXHIBITS SEVERE LACK OF POWER AND CK. ENGINE LIGHT COWES ON

CUSTOMER STATES AFTER ORIMING FOR A WHILE THE PUEL PEDAL IS IN OP AND THE CHECK ENGINE LIGHT COMES

CUSTOMER STATES: CHECK ENGINE LIGHT CCC 629

CHECK CUSTOMER CONCERN THAT WILHIOUT LOOSES POWER WHILE DRIVING, JUST GOES TO IDLE.

CUSTOMER STATES THE THROTTLE IS NOT RESPONDING AT TIMES.

WHEN PUBLING ON GAS PEDAL HAS NO EFFECT RPMS DONT GO UP SEEMS TO HAPPEN WHEN WARM

NO POWER & CK ENGINE LIGHT ON.

CHECK OUT THE VEH IS SURGEING VERY BAD IDLE OK STARTS OK BUT SURGES ON ACCEL WOSE

LOSES POWER AT CRUISE

DIESAL ENGINE LIGHT STAYING ON AND NO POWER STEP ON ACCEL NOTHING UNTIL LIGHT GOES OUT, INT DOMES ON.

INT SEVERE LOBE OF POWER NO ACCEL & STALLS ON HAY INT.

CLIST STATES SERVICE LIGHT COMES ON AND VEH LOOSES ACCEL PEDAL WHEN LIGHT GOES OUT RUNS NORMAL

CHECK ENGINE LIGHT ON E29

CUSTOMER REPORTS THE VEHICLE WILL NOT CRUISE AT A CONSTANT SPEED, WITH OUT BUCKING AND JERKING...WILL DRIVE SMOOTH IF

WONT ACCELERATE AT TIMES

CUSTOMER STATES THE CELIVILL COME ON INTERMINTANTLY, WHEN CELIS ON THERE IS NO THROTTLE RESPONSE

CHECK FOR AT TIMES WHEN AT A STOP THE CHECK ENGINE LIGHT WILL COME ON AND WHEN CUSTOMER TRYS TO ACEKY THE PEDAL WILL MOVE NORWALY BUT THE VEHICLE'S

CUSTOMER STATES THAT AT TIMES WHEN GIVING GAS VEHICLE DOES NOT RESPOND

E28 (DIESEL) CHECK WHILE DRIVING SERVICE ENGINE SOON LIGHT CAME ON WOULD NOT ACCELL WITH THE GAS PEDAL BUT WOULD

CHECK THE CUSTOMER STATES THAT THE THROTTLE PEDAL DOESN'T SEEM TO WORK AT TIMES WHEN FIRST ACCELERATING AND THE EMMISSIONS LIGHT IS ON

CEL IS ON, WHEN GO TO ACCELERATE THE TRUCK DOES NOTHING CUSTOMER REPORTS THE TRUCK WILL IDLE BUT NOT ACCELARATE, CHECK ENGINE LIGHT WILL COME ON CUSTOMER SPOKE TO TECH RE CONCERNS CK WHEN PUSH THROTTLE DOESN'T DO ANYTHING CUSTOMER STATES VEHICLE WILL NOT ACCELL AT TIMES WITH PETAL PUSHED DOWN AND WILL LOCKE ALL POWER USE SPO 02144005 NO RESPONSE TO ACCELERATOR, WILL IOLE CLISTOMER STATES CHECK ENGINE LIGHT COMING ON SOMETIMES NO POWER ON ACCEL, HAVE TO PUMP GAS GET VEHIC WHEN TURNING ENG WOULD ACCEL ON ITS OWN CHECK ENGINE LIGHT & ON AND THERE IS NO ACCLERATION AND WHEN LIGHT IS DEFIT RUNS. FINE CK ENGINE LIGHT COMES ON CUST STATES WHEN STEP ON GAS PEDEL NO RESPONCE CHECK ENGINE LIGHT ON VEHICLE HAS NO POWER AND CHECK ENGINE LIGHT IS ON. WILL START AND RUN OKAY FOR A PEW MINUTES, THEN CUTS OUT AND WHEN CHY ENGLIGHT COMES ON IT HAS NO POWER WHEN LIGHT GOES OFF POWER RETRUPNS CLISTOMER STATES CHICK ENGINE LIGHT CAME ON AND WHILE DRIVING VEHICLE ACTS LIKE IT IS GOING TO STALL. CUST STATES THE CHECK ENGINE LIGHT IS ON WHEN IT IS ON THE ACCU HAS NO RESPONSE GOES OFF AND OK REPAIR AT TIMES CUST STATES GETTING NO THROTTLE RESPONSE CODE DISC CUSOTMER STATES INTERMITTENT ENGINE LITE AND NO POWER...CAN PRESS DOWN PEDAL AND VEHICLE STAYS AT I CUST STATES: EMBINE WILL NOT RESPOND TO THROTTLE AT TIMES, ADVISE CUSTOMER STATES CHECK ENGINE LIGHT IS ON WHEN PUT IN DRIVE THE VEHICLE WILL NOT MOVE INSTALL PARTS COMES ON AND OFF, HAS 3.4 TIMES SINCE PCM REPLACEMENT, WHEN IT COMES ON VEHICLE HAS ACCELERATION AT ALL (NO POWER) CUSTOMER STATES WHEN STARTS IN MORNING CHK ENGINE LIGHT COME ON VECHILE WILL JOLE BUT WILL NOT MOVE CHK AND CLIST SAYS CHECK ENGINE LIGHT IS ON CUSTOMER STATES ENGINE DRIOPS TO IDLE WHEN TURNING CORNERS THEN WHEN TRIES TO ACCELERATE DOESN'T ACCEL HAS TO STEP ON CLIST STATES CHECK ENGINE LIGHT ON WHEN PUT INTO GEAR AND TRY TO ACCEL THE THROTTLE RPMS DON'T RESPOND MAINTENANCE SERVICES REPAIR FOR NO THROTTLE RESPONSE CK ENGINE LAMP IS ON NO ACCELERATION DIESEL. CUSTOMER STATES AFTER DRIVING FOR ABOUT 20 MIN THE SERVICE ENGINE LIGHT WILL COME ON EN CLISTOMER STATES THAT THE TRUCK LOSES THROTTLE CONTROL CUSTOMER STATES: WHEN PUSHING THE GAS PEDAL THE ENGINE WILL NOT REV NO POWER, CHECK ENGINE LIGHT COMES OK. E29 CHECK ENGINE LITE IS ON CUST STATES NO RESPONSE PROM ACCELL PEDAL C 5 WHILE DRIVING IN THIS WEEK BND WITH CRUSSE CONTROL ON AND COMING DOWN A MOUNTAIN, WHEN CUSTOME CUST STATES TRUCK KEEPS STALLING OUT LIKE NOT GETTING GAS, CHECK ENGINE LIGHT IS COMING ON CHECK AND ADVISE CUSTOMER STATES LACKS POWER, FEELS LIKE NO THROTTLE RESPONSE E29 CK ENGINE LIGHT COMES ON WHILE DRIVEING THEN ENGINE WILL HOT ACCELERATE REPAIR CHECK ENGINE LIGHT COMES ON AND ENGINE WILL LOSE THROTTLE CHECK ENGINE LIGHT COMES ON WHILE DRIVING NO THROTTLE RESPONSE THE GAS PEDAL IS NOT WORKING AT TRACES WITERATTENTLY CHECK ENGINE LIGHT COMES ON AND TRUCK LODGE THROTTLE RESPONSE. TRUCK WILL NOT ACCELERATE, SOP HERE TO CORRECT. CLESTORIER STATES MIL LIGHT IS ON REPAIR FOR ENGINE LIGHT IS ON WHILE DRIVING CUST STATES ENGINE LIGHT IS ON INTERMIT. WHEN LIGHT IS ON TRUCK IDLES FINE BUT HAS NO POWER ON ACCELERATION. CLIST STS ACCEL PEDAL INOP DIESEL CHECK ENGINE LIGHT IS ON (WHEN LIGHT IS ON, ACCELERATOR SOMETIMES WILL NOT WORK) CUSTOMER STATES THAT SERVICE ENGINE SOON LIGHT IS COMING ON., SINGINE HAS IND POWER ON TAKE OFF... CUST STATES TRUCK WILL NOT MOVE WHEN ACCLERATOR IS PUSHED

CUSTOMER REQUESTS TO INSPECT FOR THE FOLLOWING CONCERN: CUSTOMER REPORTS THE CHECK ENGINE LIGHT IS ON, ALSO CHECK ENGINE LIGHT COMES ON ESSIGNED LIGHT STAYING ON CONSTANTLY, CHECK ENGINE LIGHT ON CONSTANTLY, CHECK ENGINE LIGHT ON WONT ACCL

E29 AMBER CK ENGINE LIGHT IS ON
CUSTOMER STATES CK ENGINE LIGHT COMES ON HESTITATION
ENGINE BOOGS DOWN WHILE DRIVING CHECK ENGINE LIGHT COMES ON AND GOES OFF
DSD CUSTOMER REPORTS WHEN PRESSING ACCELERATOR PEDAL TRUCK WONT MOVE, CHECK AND ADVISE
CUSTOMER STATES VEHICLE HAS NO POWER, INTERNITTEN CONDITION
CS THAT THE CHECK ENGINE LIGHT ON AND VEH HAS NO THOTTLE RESPONSE
CUSTOMER STATES OK ENGINE LIGHT ON AND VEH HAS NO THOTTLE RESPONSE
CUSTOMER STATES TRUCK CUTS OFF AND CHECK SINGINE LIGHT COMES ON
CUST STATES THAT THE VEHICLE WILL NOT ACCELERATE AND THE CHECK ENGINE LIGHT IS COMING ON ADVISE
WIST SOP GAS PEDAL ASSEMBLY
OWNER REPORTS THAT WHEN DRIVING VEHICLE LOOSES POWER DUADNOSE & REPORT TOWED IN

CUST REPORTS AT TIMES (HAPPENED TODAY) IN GEAR TRYING TO ACCEL RPMS WOULD NOT GO UP FELT LIKE NO THROTTLE CK ENGLIGHT CAME ON CUSTOMER STATES ENGINE LOSE POWER AND THE CHECK ENGINE LIGHT IS ON, TOWED IN CHECK ENGINE LIGHT ON, HIT THE GAS AND NO ACCELL STARTED JULY 4TH DEC NO THROTTLE, GOES TO IDLE AND CANT GET THROTTLE BACK, HAVE TO KEEP POPPING PEDAL CHECK ENGINE LIGHT COMES ON AT STOPS AND THE ACCELERATOR DOES NOT WORK

WILL NOT MOVE CURTOMER STATES THAT WHEN VEH IS IN GEAR THAT IT WILL NOT MOVE (INTERMITTEN) AND THE CHECK ENGINE II BLE. THROTTLE WOP AT TIMES.

C S TRUCK ONLY IDLES, WON T DRIVE DOWN ROAD. CUSTOMER STATES THROTTLE PEDDLE WOP CUSTOMER STATES CHECK ENGLIGHT CAME ON AND PEODLE NOT RESPONDING VEHICLE WILL NOT ACCELL MILLITY COMES ON THROTTLE INCP CUSTOMER STATES THAT THE VEHICLE WILL NOT THROTTLE UP , RPWS DROP. CHECK KINGING LIGHT IS ON AND THE TRUCK WILL NOT ACCE. CHECK AND ADMISE CLIETCAKER STATES THAT PROMIDLE TO TAKE OFF IT WONT GO WHEN PUSHING THE PEDAL NO POWER THEN STARTS TO GO C 8 THAT THE CHECK ENGINE LIGHT WILL COME ON AND VEHICLE WILL NOT MOVE CAN PRESS GAS BUT WILL GET NO CIS FRIDAY NIGHT AT CONSTANT SPEED WOULD IDLE PAST THEN DROP OFF BOUT USE CRUISE IT DOES FINE CUSTOMER STATES THE GAS PEDAL WONT RESPOND CUSTOMER STATES WAS DOING SOME TOWING AND CHECK ENGINE LIGHT CAME ON AND LOST ACCERATOR REPONSE, STEP ON GAS AND NO GO, CUSTOMER STATES WHEN LETTING OFF THROTTLE AND STARTS TO PUSH THROTTLE DON'T WORK THEN PUSH AGAIN IT DOES CUST STATES CHECK ENGINE LIGHT ON HAVE NO THROTTLE WHEN LIGHT IS ON IF LIGHT OUT, OK CUST SYATES CK FOR NO ACCELARATION, PLEASE ADVISE CUSTOMER STATES CHECK ENGINE LIGHT IS ON. CHECK AND REPORT. NO POWER ON ACCELERATION INTERMITTANTLY VEHICLE STALS AND LOOSES POWER INTERMIT CHECK ENGINE LIGHT ON, NO THROTTLE RESPONSE

ENGINE STARTE UP PINE, BUT WILL NOT ACCELLERATE PROM STOPS QUET STATES CK ENGINE LIGHT ON AND NO THOTTLE RESPONSE SERVICE ENGINE LIGHT COMES ON AND YOU CAN GIVE THE TRUCK GAS SUT IT COESNIT RESPOND AT ALL LIKE THE PEDAL IS NOT CONNECTED AND THEN YOU WAIT A FEW MORE CHECK AND ADVISE CHECK ENGINE LIGHT IS ON AND AT TIMES ON ACCELERATION WILL NOT MOVE FOR WARD WITH THROTTLE INPUT LIKE TRANS NOT ENGAGED, RPMS DO NOT I CLIS BAYS TRANS INDICATOR LIGHT ON DASH IS COMING ON WHEN THIS HAPPENS, TRUCK WILL NOT MOVE. CHECK ENGINE LIGHT COMES ON SPECIAL ORDER GAS PEDAL IN. ENGINE IDLES BUT WILL NOT ACCEL AT ALL CHECK ENGINE COMES ON WHEN VEHICLE IS AT IDLE ONLY NOT WHILE DRIVING. ADVICK THIS LT COMES ON STAYS ON HAS HESITATION AT ACCELLOSS OF POWER CUST STS CHECK ENGINE LIGHT COMES ON AND VEHICLE LOOSES THROTTLE RESPONSE SLUGISH AT TIMES POOR ACCLEERATION SEE STEVE CHECK ENGINE LIGHT ON AT TIMES LOW SPEEDS WHEN TURNING DROPS SPEED SERVICE ENGINE LIGHT IS ON WHEN THIS HAPPENS THE ACCLERATOR WIL C S AT TIMES WHEN STARTING THE ENGINE THE ENGINE LIGHT WILL REMAIN LUMINATED IN THE DASH LONGER THAN THE LISUALL CAT STATES OK KING LIGHT IS ON AT TIMES HAS NO THROTTLE ON STRT WE DIZ INSTALL SIG THROTTLE PEDAL SWITCH

THE THROTTLE HAS NO RESPONCE, AND THE CHECK ENIGNE LIGHT IS COMES ON AT THE SAME TIME CUSTOMER STATES CK ENGLIGHT STAYS ON

CHECK ENGINE OR SERVICE ENGINE SOON LIGHT ON.

C/S CHECK ENGINE OR SERVICE SOON LIGHT IS ON.

C S PUEL SHUTS OFF WHILE RUNNING

ACCELERATOR PEDAL (NOP INTERMITTANTLY, OCCURES MOST TIMES WHEN COLD, STARTED 2 WEEKS AGO, SEE DON H

CK WONT ACCELERATE

ENGINE HAR BEEN CUTTING OUT

HAS NO POWER ON ACCELERATION

C & ENGINE LIGHT IS ON

NO POWER ON ACCELL, HAS NEW OIL AND AIR AND FUEL FILTER

CHECK ENGINE LIGHT IS COMING ON AND THROTTLE RESPONSE IS ERRATIC

CLISTOMER REPORTS JUST AFTER START UP COLD START UP FOR THE MIRST 15 SECONDS OR SO THERE IS NO REACTION FROM THE ACCELL PEDAL NO ACELL PLEASE CHECK AL

KOEC

CUSTOMER STATES ENGINE LITE COMES ON ... VEHICLE LOSES ABOUTY TO ACCELERATE ... STAYS AT IDLE ...

KOEO . CHECK ENGINE LAMP ON, CUTTING OUT WHILE DRIVING CUSTOMER STATES CHECK ENGINE LIGHT IS ON WHEN LIGHT COMBS ON HAS NO ACCELLERATION

CHECK ENGINE LIGHT ON THROTTLE PEDAL INOP

CLIST REPORTS AT TIMES CHECK ENGINE LIGHT COMES ON & NOTE AT STOPS ON ACCEL PUSH ON PEDAL & NO RPM. INCREASE WILL NOT ACCEL

REPLACE SOP SENSOR

CHECK AND ADVISE TRUCK DIED WHILE DRIVING , HAB ING THROTTLE RESPONSE

DS6 ENG LOCISES POWR WARM OPP AND ACC INOP IRRATIC OPP

(POWERTRAIN ENGINE) OTHER ENGINE TROUBLES

CHECK WHY ENGINE LIGHT IS ON

CUST STATES ENGINE LIGHT COME ON

DRIVEASELITY IGNITION SYSTEM & TUNE UP QUET STATES VEHICLE HAS NO POWER

CUSTOMER STATES STARTS TO ACCELERATE THEN VEHICLE GOES BACK TO AN IDLE.CUSTOMER ALSO STATES WORKS. PINE WITH CRUISE CONTROL.

CK ENGLITE ON:NO THROTTLE RESPONSE REPAIR AS NECESSARY

CUSTOMER STATES: CK THROTTLE IB STICKING

CHECK AND ADMISE ACCELERATOR PEDAL DIONT ACCELERATE HAD TO DEPRESS OR PUMP 2 5 TIMES AND SURGE BETWEEN 25 30 MPH

CUSTOMER STATES THAT TRUCK WILL NOT ACCELERATE AT TIMES

CUST STATES CK ENG LIGHT STAYS ON, AND NOTHING HAPPENS WHEN ACCEL PEDAL IS PUSHED CUST STATES CHECK THROTTLE NOT WORKING PROPERLY GUEST STATES CHECK ENGINE LIGHT (ML) IS ON. DIAGNOSE AND ADVISE. NO OTHER SYMPTOMS PRESENT. CHECK ENGINE LIGHT ON ACCELERATION VEHICLE DIED TWICE OK ENGINE LIGHT ON WHEN DIED CUSTOMER STATES POOR MILEAGE. CHECK WILL NOT ACCELL UNLESS PUT IN PARK THEN BACK IN DRIVE. CUSTOMER STATES VEHICLE WILL NOT ACCELL UNLESS PUT IN PARK THEN BACK IN DRIVE.

INTERNETT WHEN STEPPING ON GAS PEDAL TRUCK WONT MOVE SEE TIM
CONCERN: C 8 TRANSMISSION WARNING LIGHT COMES ON DASH INTERNETTENTLY AND WHEN IT IS ON THE VEHICLE WILL NOT MOVE OR ACCELERATE AT ALL. IF YOU TURN EAGING OF VEH HAS NO POWER VEH TAKES A WHILE BEFORE IT WILL HAVE A LOT OF POWER
VEHICLE WILL NOT MOVE, WIGGLES AND IT WALKS, ENSINE SYMBOL IS ON.
C 8 CHECK ENGINE LIGHT IS ON

CUST STATES DEPRESS GAS PEDAL AND VEHICLE WONT ACCELERATE SOP IN TECHHASS CUST REPORTS WHILE DRIVING ENGINE LOSS OF POWER & ASILITY TO CONTROL THROTTLE ACTION CUSTOMER STATES WHEN PULLING TRAIL CHACK ENGINE LIGHT COMES ON VEHICLE WILL QUIT PULLING

C S THAT YEHICLE HAS NO THROTTLE PEDAL INTERMITTENTLY. C S THAT VEHICLE WOULD JUST IDLE WHEN TRYING TO ACCELERATE.
CHECK TRAINS TAKES TOO LONG TO BHIFT
E28 CUST STATES WHEN STARTED CHECK ENG LIGHT ON 8 WHEN ACCEL HAS NO ENG POWER. LIGHT GOES OUT & ENG WORKS, WHEN AY LIGHT SAME THING HAPPENS
E29 CK, ENGINE LIGHT ON AND ENGINE HAS NO PWR?
DSC CK, ENGINE LIGHT ON AND ENGINE HAS NO PWR?
DSC CK, ENGINE LIGHT ON AND MO ACCELERATION INTERMITTENT
THE CHECK ENGINE LIGHT ON AND MO ACCELERATION INTERMITTENT
THE CHECK ENGINE LIGHT STAYING ON CHECK AND FIX OR ADVISE.
CHECK ENGINE WILL NOT ACCELERATE AT TIMES CHECK AND RÉPAR
CK WHEN MASS ACCELERATORY PEDAL WILL NOT GO
CHECK DIESEL, ENGINE FOR DIED IN TRAINET
VEH CRAINS AND RUNS WILL NOT TAKE GAS HAD TV PUT IN YESTERDAY AND RAN FINE BEFORE TOOK IN SHOP
CLIST STATEB CK FOR NO THOTTLE AT TIMES

CK ENGINE LIGHT CAME ON 1 TIME

AT TIMES VEHICLE WILL NOT ACCELERATE WHEN LEAVING A STOP

INSPECT, CUSTOMER AT TIMES PRESSES ACCEL PEDAL AND ENGINE WILL NOT ACCE., CHECK ENGINE LIGHT IS ALSO ON.

VEHICLE DIES WHILE DRIVING, ADVISS

CUSTOMER STATES THAT THE VEHICLE WILL NOT MOVE WHEN THE PEDAL IS DEPRESSED, SOP IS HERE.

DISTOMER STATES THAT THE VEHICLE WILL NOT MOVE WHEN THE PEDAL IS DEPRESSED, SOP IS HERE.

DISTOMER STATES THAT THE VEHICLE WONTR ACCEL DISTOM STOPS, HAVE TO WAIT ABOUR 13 14 SECONDS SEFORE WILL GO

C.S. EMMISSION LT WILL COME ON AND WONT ACCEL. DISTOMER TO WAIT ABOUR 13 14 SECONDS SEFORE WILL GO

LOSS OF POWER CHECK ENGINE LIGHT HAS COME ON TECH 118

REPAIR FOR THE VEHICLE HAVING NO THROTTLE RESPONSE INTERMITTANTLY, CUSTOMER HAS TO MOVE SHIFT LEVER SACK AND FORTH TO ENGAGE VEHICLE POSITION OF MENTONS TO ACCELERATE TRUCK WILL NOT MOVE AT TIMES. RPMS STAY ON 700 ***SEE KIM***

DIAG...THE TRUCK DOES NOT ACCELERATE INTERMITTENLY LINLESS YOU HIT THE PEDE A FEW TIMES...THERE IS A LIGHT THAT STAYS ON DURING THIS SEE LANCE.

WATER IN FUEL LIGHT COMES ON, WHEN COMES ON VEHICLE GOES TO ICLE AND HAS NO THROTTLLE RESPONSE

CUSTOMER STATES THAT THE CHECK ENGINE LITE IS ON

CUSTOMER STATES CHECK ENGINE LIGHT IS ON HAS NO POWER AND DIES OUT

229 CHECK ENGINE LIGHT COMES ON A IT WONT ACCELLIGHT GOES OFF & IT ACCELLS

CK. ENGINELITE ON, VEHICLE DOES NOT MOVIL

CHECK TRUCK IS DRING WHILE DRIVING, CHECK ENGINE LIGHT IS COMING ON, IT WILL RESTART EVERY TIME, (

CK ENGINE FOR GOING DEAD.

CHECK ENGINE LIGHT COMES ON WHEN HOT

CUSTOMER STATES CHECK ENGINE LIGHT ON

GUSTEBUEN BTATES INTERMITTANTLY LOGSES THROTTLE RESPONCE & CHECK ENGINE LIGHT COMES ON ADVISE

CUSTOMER BIATES THE VEHICLE HAS LOST ACCELERATION WAS DIAGNO SED AS ACCELERATOR SOLENOID ACTUATOR IN SALMON RIVER

CLISTCIMER STATES THAT SUIS LIGHT IS ON AND WONT RUN ABOVE AN IDLE

CHECK EMISSION LITE ON VEHICLE HAS LACK OF POWER.

CLISTOMER STATES SOMETIME WHEN STARTING OR TAKEING OFF WHEN STEPPING ON THROTTLE PEDAL NOTHING HAPPENS SOMETIMES YOU HAVE TO RESTART OR STEP ON PEL

CUST REPORTS VEH INTERNITYENTLY WILL DIE OUT AND HAVE NO RESPONSE PROMITHE THROTTLE, CHECK AND REP

CHECK ADJUSTABLE THROTTLE PEDAL HAVE TO PUBH PEDAL SIDEWAYS FOR GAS

ENGINE HAS NO RESPONSE WHEN PRESS ACCEL PEDAL , THEN SEIDAS TO CATCH — TURBO CHISEL — YOW IN

CLIST STATES INSTALL SOP TO SENSOR, ORDERSO BY JAY AM PLEASE DIESEL

AM PLEASE DIESEL SERV ENG SOON LIGHT COMES ON SEE ATTACHED B.H. FORD RECIET

GUEST STATES CHECK ENGINE LIGHT KEEPS COMING ON WHEN IT IS ENGINE HAS NO POWER

DRIVER REPORTS ENGINE HAS NO THROTTLE RESPONCE AT TIMES, PLAY WITH THROTTLE AND IT MAY START WORKING SPO

VEHICLE HAS NO THROTTLE RESPONDS FINE.

CUSTOMER STATES THE CHECK ENGINE LIGHT COMES ON , WHEN LIGHT COMES ON THE THROTTLE IS INCP, WHEN LIGHT GOES OFF YOU CAN RESUME NORMAL ACCELERATION

CK DIES WHILE DRIVING

CHECK ENGINE LIGHT COMES ON AND VEHICLE WILL NOT ACCELERATE WHEN IT HAPPENS -

VEHICLE WON'T ACCELERATE

CK ENGINE LIGHT ON , WHEN LIGHT IS ON CANNOT SET RESPONSE WHEN PRESS ON ACCEL PEDAL

CUSTOMER STATE ENGINE HAS NO POWER AT TIMES DIES AT A STOP

ACCELERATOR PEDAL ERRATIC NO RESPONSA.

VEHICLE WAS TOWID IN WILL START AND IDLE BUT AN ATTEMPT AT ACCELERATING LACKS, POWER OR WILL NOT AC

CUST BAYS NO POWER AND STALLS OUT

CK ENGLIGHT ON ACCEL NOT RESPONDING

DEG ENGINE IDLES BUT WILL NOT ACCELERATE

CUSTOMER STATES CHECK ENGINE LIGHT ON

021 CLIST STS WHEN ACCELERATING VEHICLE STALLS OUT

CK ENGINE LIGHT COMES ON AND VEHICLE LOOSES THROTTLE

CHECK INGINE LITE ON, SOP HERE

CUST STATES OD LITE FLASHING AND ONLY MOVES IN 4WD

CLISTOMER STATES SERVICE ENGINE LIGHT ON, LOBS OF POWER ON ACCEL DIESEL, INSTALL SOP PEDAL ASSY.

OWNER STATES CK ENGINE LIGHT ON WONT ACCEL AT TIMES

CUSTOMER STATES CHECK ENGINE LIGHT IS ON

C B CHECK ENGINE LIGHT COMES ON AND THE TRUCK WONT ACCELLERATE

CHECK ENGINE LIGHT TROUBLES

CUST STATES LIGHT ON FOR TRISANS AND UNIT WON.T. MOVE

CHECK ENGINE LIGHT IS ON VEHILCE LOSES POWER UNDERACCELORATION

CUST STATES HE HAS NO THROTTLE AT TIMES CHECK ENGINE LIGHT COMES ON WHEN THIS HAPPENS

ENGINE LOOSES POWER AT HIGHWAY SPEED

WRECKERED TO SHOP UNIT WONT ACCELERATE ABOVE TOLE

PERS-844 32918

OSO CUSTOMER STATES VERY LITTLE RESPONSE OUT OF THROTTLE CHECK ENG LAMP ON HESITATES BUCKS JERKS FROM STOPS

CUSTOMER STATES THAT WHEN AT A CRUSE SPEED THERE IS A CLICKING NOISE DOES NOT DO WHEN CRUSE IS SET

CK EMISSIONS LIGHT COMES ON AND TO THROTTLE

CLIST STATES CHECK ENGINE LITE ON \$ NO POWER VEHICLED WHILE DRIVING RESTARTED OK CK & ADV

DIS CUSTOMER REPORTS WHEN LETTING OFF DAS CAR JERKS IS WORSE AT LOWER SPEEDS. TEST DRIVEN IW CUSTOMER BY SERVICE FOREMAN.

DOES NOT ACCELERATE NOTHING HAPPENS

CLISTOMER STATES MILL ON THE TRUCK DOES NOT SHUT. OFF WHEN ACCELERATE NOTHING HAPPENS

CHECK ENGINE LITE IS ON

CHECK ENGINE LITE IS ON

CHECK ENGINE LIGHT WILL COME AND WHEN LIGHT IS ON DON'T HAVE ANY THROTTLE RESPONSE

CHECK ENGINE LIGHT ON BRIGHE SOGS

CUST STATES ENG. LIGHT IS ON AND THROTTLE DOES NOT RESPOND WHEN TAKING OFOFF FROM A STOP

CHECK ENGINE LIGHT COMES ON AND VEHICLE DIES LIGHT GOES OFF AND VEHICLE RUNS OK

GAS PEDAL INOP

CUSTOMER STATES VLACK OF POWER PLEASE CHECK AND ADVISE
REPAIR FOR WHEN COMING TO A STOP CHECK ENGINE LIGHT COMES ON AND NO THROTTLE RESPONCE
QUISTOMER REPORTS CHECK ENGINE LIGHT CAME ON AND ACCELERATOR PEDAL HAS NO RESPONSE
C 8 THISING WILL NOT ACCEL.
CHECK ENGINE LIGHT IS COMING ON OFF

CHECK ENGINE LIGHT IS ON WONT COME OFF IDLE AT TIMES RESTART SEEMS TO WORKFINE FOR AWHILE DESCUSTOMER STATES THAT ENGINE CRANKS AND RUNS BUT WONT ACCELERATE STAYS AT IDLE CHECK ENGLIGHT COMING ON AND LOOSEING ALL ACCEL RESPONSE UNTIL LIGHT GOES OFF.

CS THAT CHECK ENGINE LIGHT COMES ON & WHEN ON, FUEL PEDAL DOES NOT RESPOND PLEASE CHECK ENGINE STALLS & WILL NOT ACCELERATE.

VEHICLE WILL NOT TAKE FUEL AFTER RELEASE OF PEDAL (DECEL) CLELIGHT COMES ON, VEHICLE CUTS OFF CUST PULLS OVER VEH. RE STARTS. E28 CUSTOMER STATES CHECK ENGLIGHT ON AND GAS PEDOLE NOT RESPONDING SETWIEN 1200 AND 2200. CUST STS WHEN FIRST TURNNING ON VEH SURGES UP AND DOWN CUSTOMER STATES THE ENGINE WILL NOT RESPOND TO THE TROTTLE ERB TOWING, ONLY IDLES, WONT ACCELERATE EMISSIONS LIGHT IS ON E29 CKENGINE LIGHT COMES ON AND LOSES POWER CK GAS PEDAL DOES NOT WORK CLISTICALER STATES THAT GAS PEDAL GOES TO IDLE WHILE DRIVING IS TIMES TODAY) AT DIFFERENT TIMES ON SURFACE STREETS AND ON NOT RESPONSIVE WHEN PUT PEDAL TO FLOOR ENGINE LIGHT COMES ON AND ACCLERATOR LOSES RESPONSIVENESS. CHECK ENGINE LIGHT ON NO RESPONSE TO THROTTLE MOVEMENT AT SPEED TO CHECK ENGINE LIGHT COMES ON AND WONT ACEL WHEN TURNING CORNER. EMPL 6577 CUST, STATES ENGINE LIGHT COME ON, GIVE IT GAS AND IT JUST IDLES, WATERY SLACK FLUID COMES OUT ON TA NO THROTLE RESPONSE

* INTERMETTEN GOES TO TAKE OFF WONT GO. THEN BEEMS TO GO, ENGINE DOESN'T REV

WHEN CHECK ENGINE LITE COMES ON VEH WONT ACCLERATE. WHEN LIGHT GOES OUT ITS OK

REPAIR NO THROTTLE RESPONSE INTERMITENTLY CHECK FOR BETWICE ENGINE SOON LIGHT STAYS ON AND AT TIMES VEHICLE HAS LACK OF POWER CHECK ENGINE LIGHT 18 ON, ACCEL PEDAL WILL STOP WORKING WHILE DRIVING AND LINABLE TO ACCEL. CHECK ENGINE LIGHT ON INTERMITTENT AND NO THROTTLE RESPONSE INTERMITTENT PER CLISTOMER INTERMITTENTLY WHILE DRIVING AND LETTING OFF ACCEL THE CHECK ENGLIT WILL COME ON AND VEH WONT ACCEL, RIPMS STAY FLAT, KEEP PRESSING ACCEL AND LIGHT CLIST, STATES SERVICE ENGINE LIGHT IS ON VEHICLE HAB NO ACCELERATION CLIST STATES CK ENGINE LIGHT COMES ON WHILE ORMING AND ENGINE WILL NOT ACCLERATE UNTIL LIGHT GOES O VEH WILL NOT MOVE POSS TRANS TOWED IN DIAGNOSIS OF DIEBEL ENGINE CONCERNS INCLUDES HOCK UP OF EQUIPMENT & MINOR COMPONET DISASSEMBLY CHECK AND ADVISE FOR ERRATIC ACCELERATOR PEDAL COMES ON WHEN COME TO STOP AND TAKE OFF, LOSES POWER WHEN LIGHT IS ON. VEHICLE QUITS RUNNING AT TIMES CHECK ENGINE LIGHT STAYS ON D21 AT TIMES WILL NOT ACCELLERATE SES LITE COMES ON CHECK FOR LACK OF POWER AND CHECK INGINE LIGHT ON AT TIMES ON ACCELL FRIME WILL NOT INCREASE ON ACCOL, CHECK ENGINE LIGHT COMES ON (E28)CK, ENGINE LIGHT IS ON, AND HAS NO POWER WHEN TRIES TO ACCELERATE. VEHICLE NOT ACCELERATING C 8 WHILE DRIVING AT HAY. SPEED VEHICLE FEELS LIKE FUEL IS CUTTING OUT, HAVE TO STEP ON ACC. TO PICK UP SPEED & STOP IT FROM DOING IT 003 CUST STATES THE CHECK ENGINE LIGHT IS ON AND WHEN HE ACCELERATES TRUCK DOEST RESPOND. E29 CUST STATES CE LIGHT COMES ON AND THEN ENGINE WILL NOT ACCELERATE ABOVE IDLE CUSTOMER STATES CHECK ENGINE LIGHT COMES ON SEE ADVISOR. CUSTOMER STATES ENGINE RACES AND THEN DROPS TO IDLE CONTINUES TO SURGE PLEAF DIAGNOE AND ADVISE ENGINE CUTS OUT WHILE DRIVING NO RESPONSE FROM THROTTLE AT TIMES AT INTERSECTION ATTEMPTED TO ACCELERATE WOULD NOT MOVE JIGGLED ACCEL PEDAL FINALLY MOVED WHEN ENGINE IS 18T STARTED VYOU PRESS ON GAS AND ENGINE WONT REV. CANNOT ACCEL UNTILL IT WARMS UP CK ENDINE SPITS AND SPUTTERS, PUBLION FUEL PROAL AND ACTS AS THOSH NOT PUBLING PEDAL, STOP ON SIDE OF ROAD, MOVE AROUND PEDAL OK FOR SHORT TIME CUSTOMER STATES HAS NO POWER VON ACCEL VERIFY CONCERN PERFORM INITIAL DIAG KOEO KOER, INJECTOR BUZZ CUSTOMER STATES THAT VEHICLE SURGES AT 40 MPH. CIS TRUCK WONT TAKE OFF JUST (DLES DEC REPAIR FOR THROTTLE HAS NO RESPONSE AT TIMES WHEN STEPPING DOWN ON PEDAL AND CHECK ENGINE LIGHT HAS BEEN ON AT TIMES. CLIST STATES SERVICE ENGINE SOON LIGHT COMES ON WHEN CRUISE CONTROL ON THEN WONT ACCELERATE, ALSO WONT ACCEL FROM STOP AT TIME OR WHEN LET UP ON AC CUSTOMER STATES THAT ACCELERATOR IS STICKING, SOMETIMES AT STOPS AND ACCELERATING WILL NOT GO JUST IDLES AND ALSO AT WHEN THE TRUCK IS WARMED UP AND YOU ACCELERATE NORMALLY THE ENGINE GOES TO AN IDLE AND THE CHECK ENGINE LIGHT COMES OR WEH FALLS ON ITS FACE ON ACCELERATION FROM REST AND AT FWY SPEEDS TRUCK WILL NOT ACCOLORATE SOMETIMES VEHICLE WILL ONLY DUE CUSTOMER CAN PRESS THE ACCELERATOR AND THE VEHICLE ONLY IDLES INVOKEM PLUCTUATION) CLISTOMER STATES THAT YOU CAN DEPRESS ACCEL AND ENGRIC WON TREV, VEHICLE WILL JUST LOLE, IN GEAR, INTERMITTENT, QUET STATES THE CHECK SINGING LIGHT CAIN ADVISE REPAIR NOTE THE CAR AT TIMES WILL HAVE SURGE OR HISTITATION

PE63-644 32312

NEW HAS NO POWER

VEHICLE WILL NOT ACCEL AT TIMES NO THROTTLE RESPONCE WORSE HOT

CLIST STATES CHECK ENGINE LIGHT KEEPS COMING ON CHECK AND ADVISE

CLISTOMER STATES THAT WHEN WHEN VEHICLE IS FIRST STARTED AND PLIT INTO GEAR IT DOES NOT MOVE MUST MANUALLY PUT

CK ENGLIGHT ON ACCEL PEDAL NOT RESPONSIVE PARTS HERE ENGINE UGHT COMES ON ACCELERATOR PEDAL INOP AT TIMES DIESEL.

DIAG AND ADVISE CUST STATES INTERM WHEN ACCELERATING WHEN PUSHING GAS FEDAL NOTHING HAPPENS S O PARTS IN FOR WHEN GIVES GAS VEH WILL NOT MOVE CUSTOMER STATES CHECK ENGINE LIGHT IS ON,DIES. CK NO POWER CUSTOMER STATES CHECK ENGINE LIGHT ON PUTTING THE GAS TO THE PLOCE THERE IS NOTHING THERE. CUSTOMER STATES CHECK ENGINE LIGHT IS COMING ON ERRATIC HAS NO POWER LIKE ITS NOT GETTING ANY PUEL. WHECK ENGINE LIGHT COMES ON STAYS ON QUST STATES LIGHT INTER ON ALSO STATES WHEN LIGHT ON RUNS POOR AND NO POWER CHECK FOR INTER, CHECK ENGINE LIGHT WILL COME ON AND THERE WILL BE NOT THROTTLE RESPONDE COMES ON, VEHICLE LOSES POWER, WILL NOT RUN PROPERLY. CUST STATES CK ENGINE LIGHT OK AND VEH HAS NO THOTTLE RESPONSE CUST STATES CHECK ENGLIGHT IS ON PLEASE ADVISE CHECK ENGINE LIGHT IS ON CK POR CK ENGLIGHT ON AND NO ACELL WHEN LIGHT IS ON CURTOMER STATES CHECK ENGINE LIGHT ON STEPED ON ACCL IN GEAR NO REV 17 NO MOVE CUSTOMER STATES THAT THE ENGINE WILL NOT REV AT TIMES WHEN DEPRESSING THE ACCELERATOR LACK OF ACCEL AT TIMES CHECK OUT CLISTOMER STATES PEDAL STICKS SOMETIMES CK ACCEL JUMPS OFF IDLE

WHEN PULLING AWAY FROM A STOP VEHICLE DOESN'T HAVE ANY THROTTLE RESPONSE WILL JUST IDLE AWAY

WHEN ENGINE STARTED, CHECK ENGINE LIGHT COMES ON AND VIDUOLE WILL NOT MOVE

CK ENG LIGHT ON & CUSTOMER STATES YEHICLE HAS NO THROTTLE RESPONSE C & CHECK ENG LIGHT ON AND MAKES A KNOCKING NOISE BETWEEN 15T AND SHD GEAR.

ENGLITE ON PUSH ACCELPEDAL AND NOTHING HAPPENS

CHECK ENGINE LIGHT COMES ON AND VISHICLE WON'T ACCELERATE

ENGLITE ON PUSH ACCEL PELAL AND THEN THERE IS NO RESPONSE FROM THE PEDAL WHEN AT A STOP. ONCE THE CEL CAME ON WHEN CELLISHT COMES ON AT TIMES AND THEN THERE IS NO RESPONSE FROM THE PEDAL WHEN AT A STOP. ONCE THE CEL CAME ON WHEN CLIST SAYS VEH IS LURCHING, WHEN LEAVING RED LIGHT, CUST SAYS ITS ACTS LIKE ITS NOT GETTING FUEL NO THROTTLE RESPONSE NO THROTTLE RESPONSE WHEN ACCEL PUSHED INTERMITANLY VEH HAS NO ACCELERATION PROMIPEDAL TOWED INTO SHOP WONT MOVE CUSTOMER STATES: WHEN ACCEL TURSO HAS NO KICKILOSS OF POWER) & SMOKES REAL BAD, PLEASE CHECK & ADVISE

OB 816 LOCGES POWER, BANGS INTO GEAR CHECK ENGINE LIGHT COMES ON

OTHER TRANSMISSION TROUBLES
CLISTOMER REPORTS CHECK ENGIEN LIGHT STAYS ON. INTERMITTANTLY WHEN YOU STEP ON THE THROTTLE THE ENGINE DOES NOT RESPOND, CHECK AND REPORT.
ENGINE RUNS ROUGH AT SLOWER SPEEDS(25MPH) RPM GASE BOUNCING UP AND DOWN,
ENGINE WILL IDLE DOWN AT STOPS AND HESITATES ON ACC WHEN ENGINE IDLES DOWN CHECK ENGINE LIGHT WILL COME ON AND THEN GO OUT
TOW IN CRANKS NO START CUSTOMER STATES THAT ON HIS WAY HOME FROM PT COLLINS THE VEHICLE WOULD SURGE AND THEN DIE, BUT

CHECK ACCEL WON'T GO AT TIMES

CK ENGINE LIGHT ON AND NO POWER ON ACCELERATION

CONCERN; TRUCK WILL NOT ACCELERATE

WHILE DRIVING ENG SOCIES OUT & LOCKES POWER ON REACCEL, & ON 1ST START UP AFER SITTING ENG WON'T ACCEL

EMISSION LIGHT ON TRUCK SHLTS OFF

CHECK ENGINE LIGHT FLASHED ON AND VEHICLE LOST ALL POWER IN THE THROTTLE

PEB3-844 32313

CUSTOMER STATES THE CK ENGLIGHT IS COMING ON WHEN LIGHT IS ON WHEN HE TRYES TO ACCEL IT TAKES ABOUT 10 SEC FOR THE GAS PEDAL IS UNRESPONSIVE SOP HERE

CK ENGINE LIGHT ON LOSS OF POWER

CORRECT C STS THAT 3 TIMES IN LAST DAY WHEN HE HAS PRESSED THE ACCELERATOR DOWN THE VEH, DID NOT RESPOND AND DIDN'T UNTIL ABOUT THE SRD TIME HE PRESSED

CHECK ENGINE LIGHT ON OCCASIONALLY NO D10

CHECK BINGING LIGHT IS ON AND WILL NOT ACCOUNT

CUSTOMER STATES INTERM THERE IS NO RESPONSE WHEN TRYING TO A CCEL, PUSH ON THE PEDAL AND NOTHING HAPPENS

VEHICLE WILL NOT RESPOND WHEN ACCELERATOR IS PUSHED

CHECK VEHICLE GAS PEDAL WILL NOT WORK INTERAL ENGINE RUNS FINE AND IDLES. BUT CUSTOMER STATES HE CAN PRESS GAS PEDAL DOWN AND IT DOES NOTHING

CHECK FOR MAINTENANCE LIGHT, OR CHECK ENGINE LIGHT ON WHEN FIRST STARTED AFTER SETTING A WHILE THE VEHICLE WILL

CUSTOMER STATES VEHICLS WILL NOT ACCOLERATE AT TIMES

DAS TRUCK WONT ACCELERATE AT TIMES WHEN ACCELERATOR PEDAL IS DEPRESSED.

CHECK VEHICLE WILL DIE OUT WHEN ACCELERATING FROM A STOP

CUST STATES ENGINE DES AND TACH GOES TO ZERO

GIS PAUSES AND CUTS OUT ON ACCEL, IÉ GOING UP HILL PUEL LIT E COMES ON

DSG C S THAT WHEN COME TO STOP AND PRESS GAS

C 8 GAS PEDAL OUTS OUT CK AND ADVISE

CHECK TRANS DROPS OUT OF GEARLIF PUT IN NEUTRAL ENGINE WONT REV (IT STAYS AT IDLE) WAIT 6 MIN & TRUCK SEEMS OK. CK TRUCK HAS NO POWER ON ACCELERATION INTERLETAN PROBLEM

E29 CHECK ENGINE AMBER (MIL) CHECK ENGINE LIGHT ON

CUSTOMERS STATES THE CHECK ENGINE LIGHT IS COMING ON THROTTLE HAS LACK OF RESPONSE.

CUSTOMER STATES THE CHECK ENGINE LIGHT WILL COME ON AND THE VEHICLE WILL LOOSE ALL POWER.

THE CHECK ENGINE LIGHT COMES ON AND THE THROTTLE DOES NOT RESPOND.

CLIST STATES VEHICLE WILL NOT ACCELERATE FROM STOP, REVIEW HISTORY

CK HESITATION TAKEOFFS

CHECK ENGINE LAMP IS ON AND WHEN ACCELERATE AT TIMES ENGINE DOES NOT RESPOND AT ALL

CUSTOMER STATES THERE IS NO ACCERATOR RESPONSE LOW SPEEDS AND LIGHT ACCEL

THROTTLE PEDAL INTERMITTENT DEAD

ENGINE CLITS OUT WHEN LETTING OFF GAS PEDAL ACTS LIKE DEAD THROTTLE

AFTER DRIVING ABOUT 1 MOUR CHECK ENGINE LIGHT CAME ON AND THEN ENGINE WOULD NOT REV UP WHEN PUSHING ACCELLERATOR DOWN

E29 C 6 BRRVICE ENGINE BOON LIGHT COMES ON AT TIMES AND VEHICLE WONT ACCRLURATE

WONT ACCEL AT TIMES THEN OKAY AFTER FEW SECONDS ADVISE DED

DATI SOMETIMES LOSES THROTTLE RESPONSE TOLE CHLY ENGILIGHTCOMES ON HAS ADJUSTABLE PEDALS

POOR THROTTLE RESPONSE.

CUSTOMER STATES CHECK ENGINE LIGHT ON VEHICLE LOSES POWER WITH LITE ON

CUST \$18 NO POWER

OWNER STATES THAT THE CK ENGINE LIGHT IS ON SEEMS TO DIE OUT AT AN IDLE AFTER WARMED UP (CLISTOMER REPLACED

CIS HAS A MISS NOT ELATED TO WARK OR COLD CHECK ENGINE LITE CAM ON SIMEPLY, WENT OUT.

CUST STATES NO RESPONSE AT TIMES WHEN PRESSING ON GAS PEDAL

CHECK THROTTLE OPERATION.

NO RESPONSE FROM THROTTLE AT TIMES, CK ENGINE LIGHT COMES ON , DIED WHILE DRIVING DOWN H WAY , SURGES WHILE DRIVING TURBO DIESEL

PEB3-844 32314

PART WAS LIKPT OFF ORIGINAL RO 137681

CISINUST HAVE CAS PEDAL REPLACED IN VEHICLE CHARGE TO NEW CAR DEPT. PER BILL LIEB.

CLEET STATES INTERMITANTLY THE VEH WILL NOT DO ANYTHING BUT IDLE STEPS ON GAS FEELS A JOLT THEN NOT

ENGINE HAS NO THROTTLE RESPONSE AT TIMES.

CHECK ENGINE SURGES FROM 0: 50 MPH

E29 CLISTOMER STATES CHECK ENGINE LIGHT COMES ON AND HARDLY MOVES AT TIMES

WCULDN'T ACEL

EMPL 6577

D42 CUSOTMER STATES CK ENGINE LAMP COMING ON VILLICLE LOST ALL POWER AND WOULD NOT MOVE

CLIST STATES CK ENGINE LIGHT IS ON AND VEH HAS NO THROTTLE RESPONSE AT TIMES

CUST STATES THAT VEHICLE LOOSES ACCELERATION AFTER DRIVING FOR AWILE. VEHICLE HAS TO IDLE FOR A FEW MINUTES SEFORE ACCELERATING

CHECK ENGINE LITE ON WHEN LEAVING STOP SIGN CUSTOMER HAS TO PUMP GAS PEDAL 3.4 TIMES BEFORE VEHICLE WILL MOVE.

ENGINE CUTS OUT AT 45 50 MPH HIGHWAY SPEEDS

CHECK ENGINE LIGHT IS ON

CUST STATES OK ENGINE LIGHT IS ON AND VEH HAS NO THROTTLE RESPONSE AT TIMES.

CUST STATES CK FOR NO RESPONSE ON ACCEL ADVISE

CUST STATES INT ENGINE HAS NO THROTTLE RESPONCE... C50

CUSTOMER STATES START VEHICLE PLIT IN DRIVE PUBH GAS TO PLOOR VEHICLE WILL JUST IDLE FORWARD PUMP GAS 7 8 TIMES ALL OF A SUDDEN VEHICLE WILL RESPOND NOR

QUIST WOULD TAKE OUT OF O DITO GET VEH TO GAIN POWER TRAVELER WAIT CK ENH LIGHT ON ENG STARETO TO LOOSE POWER ON ACCEL HESITATES.

CUST STATES SERVICE ENGINE SOON LIGHT ON AND VEH HAS NO THOTTLE RESPONSE

GUSTOMER STATES THE CHECK ENGIE LIGHT WILL COME ON WHILE DRIVING AND THEN THERE IS NO RESPONCE FROM THE ACCELERATOR.

CHECK ENGINE LIGHT COMES ON AT TIMES AND WHEN LIGHT COMES ONVEHICLE WILL NOT ACCELERATE

CHECK ENGINE LIGHT ON

WHILE DRIVING VEH FEELB LIKE IS GOING TO STALL.

CUST STATES CK ENGINE LIGHT ON TRUCK STALLS

C.S.CK ENGINE LIGHT COMES ON AND TRUCK OUTS OUT(\$29)

OWNER STATES THE SERVICE ENGINE SOON LIGHT IS COUNTY ON, CHECK AND ADVISE.

ENGINE REVS UP & DOWN WHEN TRY TO ACCEL

CLIST, STATES CHECK ENGINE LIGHT ON LOSS OF POWER.

C 8 THAT WHILE GOING DOWN THE ROAD ENGINE IS REVING BUT TRUCK QUITS GOING ALSO THE CHECK LIGHT IS ON

CHK ENGLIGHT ON INTERMITTENT WHEN ON NO RESPONSE FROM ACCELERATOR

529 CHECK AND REPAIR CHECK ENGINE LIGHT COMES ON WHEN DRIVING

CUST STATES CHECK ENG. LIGHT COMES ON TRUCK HAS NO POWER

CK ENGLIGHT ON

CHECK ENGINE LIGHT ON

BASK ENGINE DIES WHILE DRIVING CUST PUTS INTO NEUTRAL ENGINE RESTARTS ON IT S OWN DS0

CUST STATES THE VEHICLE HAS BEEN DIRING AND THE CK ENGINE LIGHT HAS BEEN COMING ON

C 5 AT ACCELERATION TRUCK HAS NO POWER PEELS LIKE TRANS NOT SHIFTING ON TIME

CHECK VECH LOST POWER, NO PEDAL RESPONSE

CUSTOMER STATES CHECK ENGINE LT IS ON

CK ENGINE LIGHT IS ON LOST THROTTLE

(E29) CHECK ENGINE LIGHT STAYS ON SCHETUMES

ACCEL PEDAL IS INOP WHILE NOT REV ENGINE 3 38...TOWED IN

CUSTOMER STATES WHEN STEPPING ON FUEL PEDAL VEHICLE WILL NOT ACCELERATE AT TIMES

CK. ENGINE LIGHT COMES ON WHEN THIS HAPPENS TRUCK GOES TO IDLE & WILL NOT ACCLERATE UNTILL

CHECK ENG LIGHT ON

CUST STATES CHECK ENGINE LIGHT IS ON VEHICLE WILL NOT MOVE

CK FOR CK ENGINE LIGHT ON WHEN PUSHING FUEL PEDAL NO GO

FORD WARRANTY INSPECT FOR UNIT QUIT ON ROAD, HAS NO THROTTLE RESPONSE, CHECK ENGINE LIGHT ON.

DESSE SAYS AT TIMES NO ACELL PROM THROTTLE PEDAL

INTERMITTANT CHECK ENGINE LIGHT, ENGINE DROPS TO IDLE SPEED, STAYS AT IDLE TRYING TO ACCELERATE, HAS NO POWER.

CUSTOMER STATES THAT THERE IS NO RESPONSE FROM THROTTLE WHEN YOU STEP ON GAS PEDAL STATES THAT YEHICLE SEEMS TO BE AT AN

DIZ CUSTOMER REPORTS TRUCK WONT ACCELERATE FOR 30 BECONDS AND THEN PICKS UP AGAIN ALSO CUSTOMER STATES WHEN DEPRESSING BRAKE PEDAL TO DISENGAGE

CUSTOMER REPORTS CHECK ENGINE LIGHT STAYS ON AT TIMES AND ENGINE HAS NO THROTTLE RESPONSE WHEN LIGHT IS ON.

CHECK BUSTNET LITE IS COMING ON AND WHEN IT DOES THE ENGINE LOOSES POWER

THE SERVICE ENGINE SOON LIGHT IS COMING ON AND THERE IS NO THROTTLE RESPONSE WHEN PEDAL IS DEPRESSED WITH LIGHT ON.

WHEN DRIVING AT LOW SPEEDS OR COASTING THE TRANSAISSION WILL NEUTRALIZE.

CUST STATES ENGINE IDLES, WILL NOT ACCELERATE

CUSTOMER REPORTS THROTTLE ASSY IS SROKE AGAIN

CLIST STATES WHILE DRIVING ACCELARATOR PEDAL BROKE LOOSE AND WENT TO FLOOR CAUSING ENG TO REVE UP 3000 RPM

CHECK ENGINE LIGHT ON & OFF, WHEN ON, NO RESPONSE AT ACCELERATOR PUBH TO FLOOR NOTHING THERE. VEHICLE TOWED IN LIGHT WAS ON THEN WENT OFF WHEN STA

CHECK ENGLIGHT COMING ON AND GAS PEDALIS INOP.

CUSTOMER STATES VEH DONE WANT TO TAKE FUEL

CK FOR CK ENGINE LIGHT ON AND WHEN PUBHING FUEL PEDAL VEHICLE SOMETIMES WILL NOT MOVE

CUST BAYS THAT THAT THE VEHICLE WOULD START BUT NO ACCELERATE, COULD NOT GO, CHECK AND ADVISE, HAD TOWED IN, CUST NEEDING TO HEAD OUT TODAY.

BURGES WHEN DRIVING

CUST REPORTS CHECK ENGINE LIGHT COMING ON

CK WILL NOT PULL OFF

CIS THET WHEN ACCEL IS BARLEY TOUCHED AT A STOP, THE ENGINE RAPS UP HIGH THEN GOES DOWN AND THE CHIC ENGILIGHT GOES ON

CUSTOMER STATES THE THROTTLE LOOSES RPMS, LIKE NOT STEPPING ON THROTTLE.

CHECK ENGINE LIGHT

CHECK TRANS SEEMS TO IDLE UP & TAKE OFF BY ITSELF SOMETIMES A DELAY ALSO

629 PER CUST, WHEN WARM OUTSIDE AFTERNOON AND ENGINE IS WARM THE CHECK ENGINE LIGHT COMES ON AND THERE IS A LOSS OF POWER.

CHECK ENGINE LIGHT ON.

VEH FUEL PEDAL DOESNY WORK.ENG DOESNY RESPOND TO DEPRESSING IT

CK FOR LACK OF ACCELERATION

C & VEHICLE WILL JERK TAKING OFF UNDER LIGHT ACCELERATION

DSG ACCELERATOR PEDAL WILL NOT RESPOND AT TIMES (SOP HERE)

ECCEL PEDAL INOP INTERMINT PEDAL ASS RETEST

THROTTLE INOP.

C.S. VEHICLE WILL NOT ACCELERATE AT TIMES WHEN SLOWING DOWN OR TURNING

CUSTOMER STATES CHECK ENGINE LIGHT ON AT TIMES AND LACKING POWER JUST BEFORE SHIFT.

CK ENGINE LIGHT COMES ON AND ACCELERATOR INOP WHEN LIGHT COM

ENGINE STARTS WONT ACCELERATE CHECK ENGINE LAMP COMES ON

CUSTOMER STATES ON DECELL AND WHEN STOPPING, CK ENGINE LIGHT COMES ON ANOTHERE IS NO RESPONSE FROM ACCELLERATOR

CUST STATES THERE IS NO POWER NO ACCELERATION, REPORT, YOU STEP ON GAS AND VEHICLE DOES NOT MOVE

PE83-644 32316

PRI CC THE TRANSMISSION WILL NOT MOVE AT TIMES

CHECK ENGINE LIGHT ON AND VEHICLE LOBES POWER WHEN LIGHT IS ON

E28 CUSTOMER STATES SERVICE ENGINE LIGHT IS ON ENGINE HAS NO POWER AND WATER IN FUEL INDICATOR IS

CK ENGLIGHT ON, LOSS OF POWER

CUST BTATES CHECK ENGLIGHT ON WILL NOT ACCEL.

GUSTOMER STATES ENGLIGHT POPS ON NO ACCEL AND RPMS RACE ADVISE.D13

CHECK ENGINE LITE ON

CS THAT THE CHECK ENGINE LIGHT IN PLEASE REPORT

CHECK AND ADVISE CUST STATES THAT CHECK ENGINE LIGHT IS ON AT ALL TIMES, LAST TWO DAYS WHEN VEHICLE IS AT A STOP IT WILL NOT ACCELERATE, ONLY IDLES, MUST PI

D21 CLIST STATES THAT THE ENGINE STALLS WITH ACCELLERATION AT TIMES, PLEASE CHECK

EMBBION LIGHT IB ON AND TRUCK WONT GO UNLESS RPMS ARE HIGH

CUST BTATES VEHICLE WILL NOT MOVE WHEN PUT INTO GEAR.

CUSTOMER STATES VEHICLE HAS NO THROTTLE AT TIMES ENGINE JUST IDLES HAS STALLED ONCE

DOND CUSTOMER STATES THROTTLE RESPONSE JUST DIES WHILE DRIVING KEEP PUSHING GAS PEDAL AND IT STARTS WORKING

CHECK DIESEL FOR NO EXCELLERATION

CHECK CAUSE OF CHECK ENGLIGHT ON

WILL NOT ACCELL AT TIMES WHEN ACCEL DEPRESSED.

CLISTOMER STATES CHECK ENGINE LIGHT COMES ON, ENGINE HAS NO THROTTLE RESPONSE.

CK ENGINE THROTTLE IS STICKING.

LACK POWER ON ACCELERATION

CUSTOMER STATES TRANS LIGHT COMES ON AND SLIPS

CK ENGILIGHT IS COMING ON AT TIMES WHEN THIS COMES ON ENGIDOESNY HAVE POWER, IF CRUISE IS ON AND LIGHT COMES ON IT STAYS AT THE SAME SPEED.

CHK ENGINE LIGHT COMES ON AND NO THROTTLE RESPONSE

CUSTOMER SAYS AT TIMES ENGINE WILL ONLY IDLE, WILL NOT REV

CUST STATES CHECK ENGINE HUGHT WAS ON AND TRUCK HAD NO POWER.

CK ENGLIGHT STAYS ON

CK ENGINE LIGHT COMES ON AND ENGINE WONT ACCELL, WITH LIGHT ON

ENGINE CUITS RUNNING WHILE DRIVING AT TIMES

CHECK ENGINE LIGHT ON AND ENGINE WILL NOT ACCELERATE FROM STOP

CUSTOMER STATES THROTTLE IB INOP UNTILL REACHES HALF WAY

CUSTOMER STATES INTERMITTENTLY QAS PEDAL IS INOP WHEN APPLIED........

CUSTOMER STATES ACCELLERATOR IS INOP INTERMITTENTLY

CUSTOMER STATES ENGINE WILL ONLY IDLE AT TIMES

CUSTOMER STATES CHECK ENGINE LIGHT IS ON WHEN LIGHT ON AND SHIFTING INTO DRIVE TRUCK WILL NOT MOVE

AT A STOP SIGN WILL ACT LIKE IT DIES PUSH PEDAL DOWN AND NOTHING HAPPENS WONT MOVE PUT IN NEUTRAL THEN GAS WILL, GO

CUSTOMER STATES VEH WILL NOT TAKE FUEL AT TIMES WHEN LETTING OFF ACCELERATOR AND REAPPLING VEH WILL RETURN TO IDLE

SERVICE ENGINE SOON LIGHT ON COMES ON 10 20MPH LIGHT ON ENGINE IDLE

TRUCK WILL NOT ACCELERATE WHEN FOOT FEET IS MASHED, SOP

WHEN HITTING A SMALL BUMP IN ROAD CHECK ENGINE COMES AND LODGES POWER((CHECK HISTORY))

CUSTOMER STATES ENGINE HESITATES WHEN STEPPING ON ACCELERATOR SOMETIMES

AT TIMES, WHEN AT A STOP LIGHT, TRANS DOES NOT RESPOND ACCELERATING OFF THE LINE AT FIRST. HAVE TO PUT INTO NUETRAL AND PUMP GAS PEDAL AND BACK INTO DRIV CHECK TING LIGHT WILL STAY ON AT TIMES, AFTER STARTING AND AT STOP, NO ACCELERATION.

CHECK ENGINE LIGHT IS ON, VEHICLE HAS NO ACCELERATION AND NO RESPONSE WHEN LIGHT IS ON

CK ENGINE LIGHT IS ON AND TRUCK WILL NOT ACCELERATE FROM STOPS

CHECK ENGAGE LIGHT COMES ON AND THROTTLE IS NON RESPONSIVE LASTS A FEW SECONDS OR UNTIL TRUCK IS RESTARTED.:NTERMITTANT

CHECK ENGRIG WHEN THE CHECK WINGING LIGHT COMES ON THE ENGINE WILL CREEP FORWARD ONLY IDLE SPEED.

CUST STS AT STARTUP CHECK ENGLIGHT COMES ON AND STAYS ON, WILL PUT INTO 18T GEAR, GEAR WILL CHANGE BUT WILL HAVE LACK OF POWER.

CHECK ENGINE LIGHT IS ON

CHECK ENGINE LIGHT COMING ON, WHEN THIS HAPPENS, THERE IS NO RESPONSE FROM ACCELERATOR PEDAL AND TRUCK WILL NOT MOVE SEE 98348 TECH 245 CAR LACKS FOWER AND HAS CELLON MAPPENS AT LOW SPEEDS

CUSTOMER STATES THAT CHECK ENGINE LIGHT IS ON AND HAS NO EXCELERATION.

INT. STEP ON PEDAL AND THERE IS NO RESPONCE, STAYS AT ICLE

D35 APTION COME STOP TRY TO ACCEL CHECK ENGINE LITE COMES ON AND WILL NOT ACCEL

OWNER STATES THE CEL IS ON AND WHEN HITTING THE GAS PEDAL THE TRUCK DOES NOT RESPOND

CHECK ENGINE LIGHT ON

CK ENISS LIGHT ON A ENGINE WONT THIN ABOVE IDLE ALSO FOOR FUEL MILEAGE

CUSTOMER STATES EMISSION LIGHT CAME ON AND ENGINE VERY SLUGISH WHOULD NOT GO OVER 10 MPH

CUST 6AYS VEH ACCELSRATES SLOWLY CHECK ENGINE LAMP COMES ON AND THEN THE VEHICLE WILL

CUST STATES THE CHECK ENGINE LIGHT COMES ON, STATES POOT PEDAL GOES INOP., HAPPENS INTERMITTANTLY, NO PATTERN

E29 WILL GRANK WONT PULL NO POWER REPORT FOR MORE INFO

SOMETIMES WHEN TRY TO ACCELORATE HAVE NO PEDAL RESPONSE

CUSTOMER STATES EMISSIONS LIGHT IS ON AND ENGINE WONT RESPOND TO THROTTLE PEDAL, CHECK.

CK ENGINE WHILE GO TO IQUE WHILE DRIVING FOOT PEDEL HAS NO EFFECT CONDITION LAST FOR 1MIN THEN IS OK BUT HAS HAPPEND 10 TIMES IN LAST 2 WEEKS

INSP WHILE AT FREEWAY SPEEDS ACCLERATER AT TIMES THERES NO RESPONCE AT ANY SPEED CHECK ENGINE LIGHT COMES ON STAYS ON

GOING DOWN ROAD. LET OFF OF ACCELERATION, ACCELERATE AGAIN AND WILL NOT ACCELERATE.

CUSTOMER STATES CHECK ENGLIGHT ON

WHEN THE CHECK ENGINE LIGHT IS ON YOU CAN PUSH THE ACCELERATOR PECAL TO THE FLOOR AND THE ENGINE WILL NOT RESPOND JUST SITS THERE AT HOLE

C S CK. ENGINE LIGHT COMES ON WHEN COLD START NOT ALLOWING ENGINE TO REB. UP FOR APROX. 3 MIN.

CLIST STS THE ENGINE HAS A HESITATION DOCS NOT HAVE THE CRUISE ON ALSO MAKES A NOISE.

WONT ACCEL AT TIMES SEE BJ

CHRCK FOR VEHICLE JERKS WHEN CRUSING

NO RESPONSE AT TIMES WHEN TRYING TO ACCELERATE

CUST STATES CK ENGINE LIGHT IS ON AND NO RESPONDE ON ACCEL CORZE

HEST(TATES ON ACCEL, CHECK ENGINE LIGHT IS ON

AFTER BRAKES ARE APPLIED ENGINE GOES TO ICLE AND WILL NOT REV

CUST STATE WHEN AT STOPS THE CKIENG LIGHT WILL, COMP, ON AND WHEN ACCEL THE VECH WILL JUST IDLE THE

BERVICE EMBINE LIGHT

CHECK BARINE LIGHT WAS ON, YEACLE HAD NO THROTTLE RESPONSE AND WOULD NOT MOVE, NOW IT DOES, IT WAS TOWED IN...ADVISE

NO ACCELERATION FROM A STOP

CHECK ENGINE LIGHT COMES ON ATTIMES CISINO RESPONSE TO THROTTLE INPUT, WONT ACCELERATE AND

CUSTOMER STATES CHECK ENGINE LIGHT ON COMES ON WHEN DRIVING ON HIGHWAY ENGINE WILL HAVE NO POWER

C 8 CHECK ENGINE LIGHT IS ON, AND ACCELLORATOR IS INOP

CUSTOMER STATES ON TAKE OFF VIEW SEEMS TO GO DEAD LIKE TRANS IS SUPPING MUST PUT DOWN INTO 2ND THE BACK INTO DRIVE TO GO .

529,CK SAGINE LIGHT COMES ON AND HAS NO POWER ON ACCELLERATION.

CUST STATES CHECK ENGINE LIGHT STAYING ON AND DOES NOT RESPOND WHEN ACCELLERATING

BERVICE ENGINE LIGHT ON

CHECK ENGINE LIGHT CAME ON

CUST STATES CK ENGLIGHT COMING ON AND OFF WHILE DRIVING INSPECT

CHECK ENGINE LIGHT COMES ON, VEHICLE WILL NOT ACCELERATE, LIGHT GOES OFF, VEHICLE ACCELERATES, ADVSIE

CHECK VEHICLE WON'T ACCELERATE
E29 CHECK ENGINE LIGHT COMES ON AND GOES OFF WHEN LIGHT IS ON ENGINE HAS NO POWER.
CHECK ENGINE LIGHT IS ON SOMETIMES THE ACCLE. PEDAL WILL NOT DO ANYTHING

D50 INTERMITTENTLY HAS NO ACCELERATOR PEDAL RESPONSE.

E29, SERVICE ÉNGINE LIGHT ON, RPMS STAY AT AN IDLE, WILL NOT INCREASE

CUSTOMER STATES INTERMITTANTLY WHEN WARMED UP HAS NO THROTTLE RESPONCE CHECK ENGINE LIGHT COMES ON TURN OFF & RESTART

CHECCK WHEN STARTING TRUCK WILL NOT ACCELL HAVE TO TRIE THREE TIMES TO GET IT TO ACCELL CHECK ENGINE LIGHT WAS ON

CUSTOMER STATES UNIT HAS NO POWER CEL IS ON DIEB OUT AT TIMES

050 PER CUST. CK POR NO THROTTLE RESPONSE.

CUSTOMER STATES VEHICLE WILL NOT ACCELERATE FROM A STOP AT TIMES WHEN STEPPING BACK ON PEDAL AFTER B.

CUSTOMER STATES POWER PEDALS RACHET, CHECK TO SEE IF NORMAL CONDITION,

7777

CUST STATES CHECK ENGINE LIGHT COMES ON AND GOES OFF, WHEN LIGHT COMES ON WHILE DRIVING, VEHICLE DIES, HAPPENS OVER BUMPS A LOT OF THE TIME OUSTOMER STATES THAT VEH, IS RUNNING ROUGH

DAY CHECK ENGINE WARNING LIGHT COMES ON AND MEHICLE LOSES POWER AND WILL NOT GO INTERMITTENTLY, ADVISE

CX BNGINE LIGHT ON AND AY TIMES CUST TRYS TO ACCUAND ENGIS AT IDLE AND WONT ACCU. ROB DID VERIFY

TRANS WILL NOT PULL AND TRANS LIGHT STAYS ON

CUSTOMER STATES INTERMITTANTLY THROTTLE PEDAL HAS NO RESPONSE AVISE.

CUSTOMER STATES THAT CHECK SING, LIGHT COMES ON WHEN SITTING AT A STOP AND PRESS GAS PEODLE AND VIEW, WILL NOT MOVE THEN

CHECK ENGINE LIGHT COMES ON AND ACCELERATOR PECAL IS INOPERATIVE WHEN DEPRESSED, HAPPENS AT SLOW RP

ENGINE WILL NOT ACCELERATE

CUST STATES 3 TIMES NOW THE TRUCK HAS HAD NO THROTTLE RESPONCE

CHECK ENGINE IDLES ROUGH

WILL ONLY DUE AT TIMES INDIRESPONSE FROM ACCEL PEDAL

CHECK ENGINE LIGHT TROUBLES

CUSTOMER STATES ENGINE HAS NO THROTTLE RESPONSE, THE CHECK ENGINE LIGHT COMES ON AND THEN IT STALLS.

C.S. THAT THE VEH IS SURGING WHILE DRIVING ADMEE

C 8 WHEN ACCELLERATOR PEDAL PRESSEDING POWER

CUSTOMER STATES CHECK ENGINE LIGHT ON AFTER TRANS ACT UP

EMMISSION LIGHT ON

CHECK ENGINE LIGHT COMES ON

REPORTS VEH WILL NOT ACELERATE DASH LITE AND ON

SINGINE BURGES AT LOW SPEEDS

DIAG AND ADVISE CUST STATES ACCELERATOR HAS PRESSURE BUT IN OPERATIVE......(895)

CUSTOMER STATES THAT THE CHECK ENGINE LIGHT IS ON.

CUSTOMER STATES: AMBER CHECK ENGINE LITE COMES ON WHEN ON TRUCK WILL NOT ACCELERATE AT ALL.,

CUST STATES CK ENGLIGHT AND EXTREME LACK OF POWER ON ACCEL INTER HASHT HAPPEDNED TODAY BUT DID LAST NIGHT

DOS CUSTOMER STATES CK ENGLIGHT WILL COME ON AND THEN ACC PEDAL WILL NOT RESPOND

CUS SAYS TRUCK HAS NO ACCELERATION WITH PEDAL. CAN GAIN SPEED WITH CRUISE CONTROL

CLISTOMER STATES DIES ON ROAD AND CEL COMES ON SOP HERE

C 6 AFTER RUNNING FOR A WHILE IT OUTS DOWN TO AN IDLE MAY BE THE GAS PEDAL

CUST STATES WHEN ACCLEORATING ENGINE SPEED DOES NOT CHANGE WILL NOT GO ABOVE IDLE

WILL NOT ACCEL FROM STOP

CUST STATES OK ENGINE LIGHT COMES ON AND GAS PEDAL WONT ACCELERATE O S CHECK ENGINE LIGHT COMES ON AT TIMES., WHEN LIGHT PRESENT ACCELERATOR WILL, NOT RESPOND WHEN DPRESS, PEDAL CHECK CODES ECT... CUSTOMERS SAYS SOMETIMES HE COESN'T HAVE ANY THROTTLE RESPONSE

E28 CUSTOMER STATES CK ENGINE LIGHT IS ON,ALSO HAS NO POWER & SOMETIMES WILL NOT MOVE AT ALL
CUS SAYS STARTED OVER WEEKEND, WHEN PUTTING INTO GEAR, CK ENG LIGHT COMES ON AND ACCEL PEDAL HAS NO RESPONSE.
ENGINE WILL NOT REVUP OR PULL AT TIMES
ENGINE SURGES WHEN PEDAL IS DEPRESSED
CUSTOMER STATES WHEN TAKING OFF FROM A STOP CAN PUBLICOWN ON GAS PEDAL VEHICLE WONT MOVEOR ACCELORATE FOR ABOUT IS SECONDS
CUSTOMER STATES WHEN TAKING OFF FROM A STOP CAN PUBLICOWN ON GAS PEDAL VEHICLE WONT MOVEOR ACCELORATE FOR ABOUT IS SECONDS
CUSTOMER STATES WHEN TAKING ON AND TIMICE WOULD NOT THROTTLE UP FROM IDLE

C 8 2 3 TAMES A DAY THE CK ENQ LT WILL COME ON WHEN ON VEH WILL NOT ACCEL ENG WILL NOT BUILD RPMS

CLIST STATES TOLD NEEDS TPS LAST VISIT SOP HERE

CUST STATE OK ENGLIGHT IS ON

PUEL PEDAL WILL NOT TAKE FLIEL AT TIMES

CHECK SERVICE GOON ENGINE LIGHT ON

MILLAMP ON CHECK AND CORRECT

CHECK ENGINE LIGHT IS ON

CHECK ENGINE LIGHT ON

CUST STATES CK ENGLITE ON NO THROTTLE RESPONSE FROM PEDAL. HAS HAPPENED TOW OR THREE TIMES

CUISTOMER SAYS THAT EMISSIONS LIGHT COMES AND GOES OFF, WHEN ON SEEMS LIKE IT IS CUITING THE FLEL OFF, WHEN YOU TRY TO PUT THE PEDAL TO THE FLOOR SEEMS

CLISTOMER STATES CHECK ENGINE LIGHT COMES ON, VEHICLE WILL NOT ACCELERATE AT THAT TIME

CHECK ENGINE LIGHT ON

E29 CH5CK ENGINE LIGHT ON

CUSTOMER STATES THAT THE CHECK ENGINE LIGHT KEEPS COMING ON ON OCCASION, AND EVERY TIME IT DOES THE

CUSTOMER STATES THROTTLE RESPONCE IS INTERMITTENT

DURING IDLE WHEN YOU PUSH DOWN ON THROTTLE NO RESPONCE.

CLISTOMER STATES ENGINE LIGHT COMES ON AND VEHICLE HAS NO POWER AND WILL NOT ACELL E29

\$29 CHECK ENGINE LIGHT COMES ON DEACC. THEN NO POWER

E29 CHECK ENGINE LIGHT IS ON VEH DIDES NOT MOVE WHEN GAS IS PRESSED.

CK ENGLIGHT IS QUAND WONT ACCELERATE

E29 CUSTOMER STATES THE SERVICE ENGINE LIGHT COMES ON, WHEN IT DOES THE TRUCK WILL NOT MOVE

CO 050, NO RESPONSE FROM GAS PEDAL

CUST STATES NO PWER ON RE ACCEL AFTER BACKING AND DECEL NO THROTTLE AFTER SITTING AT IDLE AT A STOP

CUSTOMER STATES THERE IS NO THROTTLE RESPONSE AT TIMES. THIS AM HE WAS DRIVING AND ALL WAS DK. ALL THE SUDDEN THERE WAS

CUST STATES VEHICLE WILL LOSE POWER WHEN DOWNSHIFTING AT INTERMITENT TIMES AT 55 TO 75 ON HWY AFTER

CUSTOMER STATES VEHICLE LOSES POWER WHILE DRIVING, HAVE TO PUMP THE PUEL PEDAL TO GET IT YO RESPOND

DET ENGINE WILL NOT ACCLERATE WHEN YOUTRY TO GO

GAS PEDAL STICKS OFF AND HAS HAPPEND 5 TIMES

AT TIMES CUST, WILL ACCEL, BUT TRUCK HAS NO POWER AND RPMS DO NOT REV. 3 36 (DEISEL) HAS AUTO PEDALS 3 36

THROTTLE PEDAL IS INCP AT TIMES

AND ACCELERTAOR INOP CANNINGT ACCEL

RAR ACCELERATOR PEDAL

ADVISE CUST STATES CELION AND DOES NOT WANT TO ACCELL

CUST STATES THAT THE ENGLIGHT COMES ON THEN WHEN PUSHING GAS PEDAL NOTHING HAPPENDS NO POWER...

UNIT WILL NOT ACCEL PROMIDLE (80P)

PE83-844 32328

CHECK ENGINE LIGHT IS ON, NO ACCELERATION, NO SHIFTING

CHECK ENGINE LIGHT COMES ON, LACKS POWER UNTIL IT HITS AN INCLINE

CUSTOMER STATES WHEN COMING TO STOPS WILL NOT ACCEL AWAY RUNS ROUGH PARTS IN

CK ENGINE LITE ON

CUSTOMER STATES THAY CHECK ENGINE LIGHT IS ON HAS LOW IDLE, ALSO NO PADEL, APPLY THE GAS AND NOTHING

WHEN COMING TO A STOP ENG. LIGHT WILL COME ON AND WILL NOT ACCELRATE ENGINE WILL STAY AT IDLE AT TIMES

CHECK ENGINE WILL NOT ACCELERATE.

MIL LIGHT IS COMING ON ON ACCELLERATION.

REPORTS CHECK FOR CHECK ENGINE LIGHT COMING ON AND GOING OFF, THROTTLE WHEN HOT WILL, NOT RESPOND LAS T 2 3 DAYS STARTED APPROX 1 WEEK AGO.

D21 CUST STATES ENGINE CUT OUTS...NO ACCEL.

CHECK ENGINE LIGHT CAME ON, AND VEHICLE WOULD NOT SHIFT

CHECK ENGINE LIGHT STAYS ON

CUSTOMER STATES THE VEHICLE WILL NOT ACCEL AND THE CHECK ENGINE LIGHT IS ON.

CK BYGLIGHT ON AND HAS NO POWER WHEN ACCEL.

CK BNG LIGHT ON AND VEHICLE HAS NO POWER YOU CAN HIT GAS AND WONT MOVE ALL AT TIMES

CUSTOMER STATES ENGINE HESITATES AND SURGES PROM 30 50 MPH WHEN TRYING TO MAINTAIN A CONSTANT SPEED...JERENY HAS TEST DRIVEN ALREADY WITH CUSTOMERS

GAS PEDAL NOT WORKING NO POWER ON ACCEL GOES TO IDLE

CK ENGINE LIGHT IS ON, AT THIS TIME WILL NOT ACEL WHEN LIGHT GOES OFF WILL ACELERATE

CHECK EMOINE LIGHT FLASHED AND HAD NO POWER PICKED BACK UP A NO IS OK

VEHICLE HESITTATES, STALLS AT TIMES

CK ENGINE LAMP COMES ON ACCS, PEOOLE WILL NOT REACT

ENGINE HAS NO POWER

CUST STATES THE CHECK ENGINE LIGHT IS ON AND THE VEHICLE RESITATES WHEN YOU ACCELERATE INTERMITT.

CLISTOMER STATES VEHICLE WONT ACCEL HAVE TO PLAY WITH ACCEL FEDAL SEE DEWAYNS IN PARTS

CUSTOMER STATES THE VEHICLE WILL NOT ACCELERATE.

C.S.NO ACCLERATION AT TIMES

CHECK ENGINE LIGHT COMES ON THEN HAS NO POWER ON ACCEL

C STATES CHECK ENGINE WON'T PULL OUT FROM STOPS SEE NOTE D36

CHECK ENGINE LIGHT ON

CK ENGILITE COMES ON INTERMITT, WILL NOT ACCELL HAS NO POWER QUET STATED CPSYS

CHECK ENG. LIGHT ON, AND VECH WILL NOT MOVE

CK ENGINE LIGHT COMES ON AND ENGINE WONT ACCELERATE WITH LIGHT ON

CHECK ENGINE LIGHT IS ON WONT PLLL AT TIME!

STATES THAT CK ENGINE LIGHT COMES ON WHILE DRIVING AND VEH LOOSES POWER AND WILL CUT OFF AND DIE HIT

CUBTONER STATES TRUCK HAS NO THROTLE RESPONSE IDLE ONLY CHECK AND ADVISE

INSTALL SPO THROTTLE PEOAL ASSY...

CUSTOMER STATE CHECK BINGING LIGHT COMES ON WHILE DRIVING AND WHEN LIGHT IS ON ACCELERATOR PEDAL. INOP ONLY THING ENGINE WILL DO IS IDLE TRANS. STOPS PULLING WHILE DRIVING, AFTER CHIFTING INTO NEUTRAL AND BACK IT WILL RE ENGAGE. TRANS LIGHT ON DASH COMES ON

CUSTOMER REPORTS ENGINE WON'T RESPOND TO ACCELERATOR INT. ACTS LIKE ITS GETTING NO FUEL WHEN YOU STE

CLISTOMER STATES CHECK ENGINE LIGHT ON E29 DOES NOT WANT TO ACCELERATE

WHEN IDLING, IF YOU WANT TO ACCEL, IT WILL NOT RESPOND AT TIMES \$36

DEC CUSTOMER STATES AT TIMES ENG. WON'T ACCELERATE JUST IDLES REPORT

CHECK ENGINE LIGHT (5 ON AND VEHICLE WILL NOT GO OVER 5 MPH.

SPO HERE REPACEMENT PART

USE SPO 02143007

PE03-844 32321

CUST STATES INT. WHEN PUT INTO GRAP OR ACCELL VEH DOES NOT MOVE CUST, STATES CHK, ENG. LIGHT ON AND VEH, NOT RESPONDING AT ACCLERATION CK ENGINE LIGHT ON

E29 CUSTOMER STATES SERVICE ENGINE LIGHT IS ON AND ENGINE HAS NO POWER. TRANS IS SUPPING SLAMS INTO GEARS. WP CHECK ENGINE LIGHT COMES ON AND WHEN IT DOES UNIT WILL NOT REV UP OR MOVE REPAIR TO MOVE STARTS PLT IN GEAR WILL NOT ACCELL. CHECK ENGINE LIGHT ON VEH RUNNING ROUGH AND CUTTING OUT...CC 621 CHECK ENGINE LIGHT COMES ON WONT ACCEL RESTART RUNS OK SHORT TIME. ENGINE LIGHT IS ON. NO ACCELERATION DUE TO ENGINE LIGHT ON ACCELERATOR NOT RESPONDING CUST, WENT TO ANOTHER DEALER, SAID ACCELERATOR SENSOR BAD THROTTLE INOP WHILE ON TRIP SOP IN WHEN CHEEN CHEEN LIGHT (S ON NO POWER OM ACCLÉERATION WHEN LIGHT GOES OFF POWER RETURNS CUSTOMER STATES INTERM NOTHING HAPPENS ON ACCEL, VEHICE JUST NEUTRALS, CHECK ENGINE LIGHT IS ON CHECK ENGINE LIGHT ON HESITATES ON TAKE OFF CC: EXPREPORTS CHECK ENGINE LIGHT IS ON, SAD LOSS OF POWER DURING ACCELERATION ENGINE WILL NOT ACCEL CUSTOMER HAS TO FEATHER PEDAL TO GET ENGINE TO ACCEL, INTERMITTENT PROBLEM CUBT STATES CK ENG LIGHT IS COMING ON EXCEL, PEDAL WONT RESPOND AT TIMES CHECK ENGINE LIGHT IS ON

CUST STATES AFTER ENGINE IS WARM AND TURNED OFF WHEN RESTARTING VEH TAKES 5 SECONDS BEFORE VEH WILL MOVE DISC CK ENGINE AT TIMES WELL NOT GO GIVE IT GAS SLO, PHERE GAS PEDAL ALLEN HAS PART CUSTOMER STATES VEHICLE RUNS BUT HAS NO POWER CHECK AND ADVISE EMISSION LIGHT COME ON & VEHICLE WON CHECK ENGINE LIGHT COMING ON CUSTOMER STATES CHECK ENGINE LIGHT IS ON AND HAS NO ACCELLARATION, INSTALL SPECIAL ORDER PART, CUSTOMER STATES CHECK ENGINE LIGHT ON AND NO RPINS WHEN HITTING THE GAS PEDAL STAYS AT 600 RPM E29 CHECK ENGINE LIGHT AND WILL NOT ACCELERATE CK ENGINE LIGHT COMIES ON AND WHEN THIS GAS PEDAL QUITS WORKING E39 STATES CHECK ENGINE LIGHT COMES ON AND WHEN THIS HAPPENS GAS PEDAL QUITS WORKING E39 STATES CHECK ENGINE LIGHT COMES ON AND WHEN THIS HAPPENS GAS PEDAL QUITS WORKING E39 STATES CHECK ENGINE LIGHT COMES ON INTERMENTLY WHEN THIS DUPLICATES VEHICLE WONT ACCELERATE CEL ON AT TIMES.....WILL NOT ACCELERATE

CUSTOMER STATES ACCELERATOR HAS NO RESPONSE SVC ENGINE LIGHT IS ON

DSC CUST STATES SOMETIMES AT STOPS AND AFTER DECEL THERE IS NO RESPONSE FROM ACCELERATOR PEDAL WILL NOT ACCELERATE C STATES THAT THE CHECK ENGINE LIGHT IS ON CUSTOMER HAS NOTED THAT ON SEVERAL OCCASSIONS, THE ENGINE HAD NO POWER CHECK ENGINE HAS NO ACCELERATOR

ENGINE LOST ALL POWER, WONT ACCELRATE WHEN THROTTLING UP.

OTHER ENGINE TROUBLES.

CST STATES CK ENG LIGHT IS ON PEDAL WILL GO ALL THE WAY TO THE FLR BUT VEH WILL NOT MOVE. CK ENGINE LIGHT COMES ON AND ENGINE KEEPS DYING

CHECK ENGINE LIGHT IS ON AND VEHICLE DOES NOT ALWAYS ACCELERATE.

CUST STATES THE VEHICLE SURGES AT TIMES

CK SES LIGHT COMES ON VEHICLE LOOSES POWER

PEB3-844 32322

E29 CUSTOMER STATE CK ENGLIGHT COMES ON AND THEN ACC PEDAL DOES NOT RESPOND CUSTOMER STATES THAT THERE IS A CHECK ENGINE LIGHT IS ON AND THE THROTYLE IS NON RESPONDING AT TIMES REPAIR AS NEEDED C.S. CHECK ENGINE LIGHT ON, ENGINE WILL NOT ACCELERATE. CORRECT VEIL NOT RESPONDING WHEN ACCELERATOR IS PRESSED. CHECK ENGINE LIGHT COMES ON, GAS PEDAL QUITS WORKING WHEN LIGHT IS ON VEHICLE WOULD NOT ACCELERATE OR TAKE FUEL CUST STATES CK ENGINE LIGHT IS ON AND HAS NO PEDAL RESPONSE AT TIMES VEHILAÇÃO POMER WONT ACCELERATE ÇK ENGINE LIGHT ON RUNNING BAD, CHECK ENGINE LIGHT COMING ON DAZ CUST STATES SOMETIMES TRUCK HAS NO THROTTLE CHECK ENGINE LIGHT COMES ON WHILE DRIVING CUS BAYS ENGIDOES NOT HESPOND WHEN DEPRESSING ACCELERATOR. CHECK ENGINE LIGHT COMES ON AT STOP, MUST PUMP GAS TO GET VEHICLE TO ACCEL FROM A STOP. CHECK ENGINE LT. ON WHEN TRUCK WILL ONLY IDLE CHECK ENGINE LIGHT IS ON AND WONT MOVE ANY PARTER THAN AN IDLE ENG HAS NO POWER WHEN ACRILLERATE IDLES OK ONLY CHECK TRANS LIGHT ON WONT MOVE EMISSION LIGHT COMES ON AND WILL NOT TAKE FUEL AT THIS TIME SOMETIMES ENG. DOES NOT RESPOND WHEN ACCEL IS PRESSED. D42 AT TIMES WHILE DRIVING OR AFTER START UP THE ACCEL ENGINE STAYS RUNNING BUT NO THROTTLE RESPO

CHECK FOR NO ENGINE POWER.

CUSTOMER STATES EMISSIONS CONTROL LIGHT COMES ON & ENGINE WILL, NOT ACCELLERATE INTERMITTANTLY JUST IDLES ADVISE CHECK ENGINE LIGHT COMES ON AND TRUCK WILL NOT ACCEL. IDLES AND RUNS FINE BUT WILL NOT GO AT ALL CK ENGINE LIGHT ON AND WONT ACCELEATE WILL ONLY JOLE QUST STATES THE DASH ENGINE WARNING LIGHT COMES ON VEHICLE WONT ACCEL, WHEN LIGHT IS ON TOW IN 829 AMBER CK ENG LIGHT ON AND BING WONT ACCEL INTERMITTEN PROBLEM CHEK AT TRAFF ENDIN GOES TO IDLE WONT MOVE UNLESS PEDAL HIT SEVERAL TIMES THEN WILL MOVE CHECK ENGINE LIGHT COMES ON AND GOES OFF WHEN LIGHT IS IN THE ACCELLERATOR PEDAL SEEMS TO BE INOP INSTALL SPECIAL ORDER PART ACCEL PEDEL SENSOR USE SP0 02168014 CISITHE TRUCK WONT RESPOND TO THE GAS PEDAL AND THE CHECK ENGLIGHT WILL PLASH ON AT THE BAME TIME (D50) THE ENGINE WOULD LOSE POWER, AMD WOULD NOT WANT TO RUN (PARTS IN) OWNER STATES THROTTLE WILL NOT RESPOND WHEN LEAVING FROM STOPS AND WHEN CRUSING FEELS LIKE IT GOES TO IDLE NO CHECK ENGINE LIGHT ON CHECK ENGINE LIGHT COMES ON AND ACCELERATOR PEDAL WILL NOT RESPOND CUSTOMER STATES CHECK ENGINE LIGHT ON ENGINE HAS NO POWER WHEN THIS OCCURS. CHECK ENGINE LIGHT IS ON, GAS PEDAL WILL NOT RESPOND AT ALL AT TIMES CUST STATES WHILE DRIVING ACCEL PEDAL GOEB DEAD CAS TRUCK DONESN'T ACCELERATE AT TIMES

CK ENG WHEN EMISS LIGHT COMES ON WONT LET YOU ACCIED. BUT IF HIT HAVE CRUISE ON AND HIT ACCED WILL ACCED.

DIESCL ENGINE IDLE BPEED WILL NOT RESPOND AT TIMES AND WILL SO DOWN TO IDLE NO MATTER WHERE PEDAL POSITION IS, HAS HAPPENED 3 TIMES IN LAST COUPLE WEEKS ENGLIGHT CAME ON AND ENG WOLLDN'T MOVE TWO TIMES

CK ENGINE LIGHT COMES ON AND OFF VEH WILL NOT RUN PROPERLY WHEN THIS HAPPENS

INTERMITTANT NO THROTTLE RESPONSE SEEMS OK ON CRUISE

CHECK ENGINE LIGHT IS ON ADVISE

CUSTOMER STATES AND VEHICLE HAS BAD HESITATION LUNDER A LIGHT ACCELERATION, CHECK AND ADVISE

CUSTOMER STATES VEHICLE YES TATES ON TAKE OFF, CHECK AND ADMISE

PERS-844 32323

ENGLIGHT CAME ON WOULD NOT ACCELL.
CHECK ENGINE LIGHT COMES ON CUTS OFF ON ACCEL E29
ADJUSTABLE FEDALS INDP(SOP)
WHEN DRANGE INDICATOR SHAPED LIKE AN ENG. LOSE OF POWER WONT ACCEL RUNS GOOD WHEN LIGHT OFF

CUST STATE OK ENG LT IS ON WONT ACCELERATE CUST HAD TO PUMP GAS PEDAL TO MOVE VEHICLE
C S VEH HESSITATES AND WILL NOT ACCEL CUST MOVES CONC AT GAS PEDAL AND VEH RUNS FIRE CHECK AND ADVISE
CUSTOMER STATES CHECK ENGINE WILL NOT ACCEL AT TIMES CHECK & ADVISE
CUSTOMER STATES CHECK ENGINE WILL NOT ON
GAS PEDAL INOP AT TIMES.
CUST STATES ENGINE LIGHT COMING ON AND VEHICLE WOULD NOT PULL ENGINE WOUSLD RUN LET SIT FOR AWHRE W
629.....OWNER REPORTS CHECK ENGINE LIGHT ON
CUSTOMER STATES THAT CHECK ENGINE LIGHT ON
CUSTOMER STATES THAT CHECK ENGINE LIGHT ON
CK ENGINE LIGHT CAME ON, HEARD LOUD POP LIKE BACKFIRE, VEHICLE WOULD NOT ACCEL.
C S AT TIMES WHEN STATE UP VEHICLE CHECK ENGINE LIGHT WILL COME ON AND VEHICLE WILL NOT ACCELERATE
CK ENGINE LIGHT ON

AT TIMES WHEN STOPPING THEN TRYING TO TAKE OFF VEH WILL NOT MOVE WITH FOOT ON ACCLERATOR PEDAL VEH JUST IDLES WHEN THIS HAPPENS THE CHECK ENGINE LIGHT IS ONLIGHT IS ONLIGHT POWER THEN POWER BACK AFTER 10 SECOND.

CLISTOMER SAYS ENGINE WILL ONLY IDLE SOMETIMES

ENGINE HESITATES ON ACELERATION WILL NOT TAKE FUEL AT ALL SOMETIMES

CHECK ENGINE LIGHT TROUBLES

CUSTOMER STATES WHEN ENGINE RUSHING , WHEN PUT IN GEAR WHEN TOUCHING ACCELERATOR PEDAL RPM GO UP TO 3000.

CHECK ENGINE LIGHT IS COMING ON AND GAS PEDAL WILL NOT RESPOND, ENGINE WILL NOT REV UP.

D365 CUSTOMER STATESCHECK ENGLIGHT ON NO ACCEL CHECK AND AEWYSE

CHECK VEC WILL DE WHILE DRIVING AND WILL RESTART OK

CHECK ENGINE LIGHT ON AND ENGINE WILL NOT ACCELERATE

CK ENGINE LIGHT ON VEH WILL NOT MOVE WHEN LIGHT ON

CHECK ACCELERATOR PEDAL, CUSTOMER STATES IT IS VERY SENSITIVE TO THE TOUCH

CUST. STATES NOT FUNNING CORRECTLY

CHECK FOR THE VEHICLE WHEN THE CHECK LIGHT COMES

CUST STATES ON CRUISE TOOK OFF CRUISE NO POWER WILL IDEL OK BUT GAS PEDAL HAS NO RESULT ADVISE BUT WITH CRUISE OK

INTERMITTENTLY WHEN ACCELERATING FROM A STOP VEHICLE WONT MOVE.

CLICKING SOUND UNDER HOOD WAS TOWED

CLICKING FROM ACCELERATOR WILL NOT ACCELERATE WAS TOWED

CLISTOMER STATES THROTTLE DOES NOT RESPOND AFTER VEHICLE IS STARTED

CUST STATES VEHICLE WONT ACCEL AT TIMES WHEN CHECK ENGLIGHT COMES

CUSTOMER STATES CHECK ENGINE LIGHT ON AND TRUCK STALLS OUT AT TIMES WHILE DRIVING

ENGINE LIGHT COMING ON AND VEHICLE LOSSES ALL POWER.

CUST STATES WHEN VEHICLE IS WARRED UP, CHECK ENGINE LIGHT COMES ON AND VEHICLE HAS NO THROTTLE. VEHICLE IS SLUGGISH

THE CHECK ENGINE LIGHT IS ON, 336 YESTERDAY, WHEN THE CUSTOMER CAME TO A STOP 2 TIMES YESTERDAY HE WOULD HIT GAS NOTHING WOULD HAPPEN, 338DIESEL.

CUST STATES CK ENGLIGHT ON AND WHEN LIGHT IS ON TROTTLE HAS NO REPONSE ACCELERATOR DOES NOT WORK

CLIST STATES THAT VEHICLES WHILE VEHIS (IN TRANSIT, AND ACCEL PEDAL CAN BE DEPRESSED TO GET IT TO START UP AGAIN, NOW YER DIES AS IT COMES TO A STOP.

CUST STATES CHECK ENGINE LIGHT COMES ON, VEH WONT ADVANCE AND WONT REV, LIGHT GOES OFF EVERYTHING OK, WHINING NOISE COMING

CHECK ENGINE LIGHT COMES ON LACK OF POWER ON ACCELERATION GAS PEDAL HAS NO PRESSURE

WHEN ACCELERATOR IS PRESSED VEHICLE DOES NOT MOVE

CORRECT FOR THE CHECK ENGINE LIGHT CAME ON WHILE DRIVING AND THE VEHICLE HAD NO THROTTLE RESPONSE CUST STATES THAT CHECK ENGINE LIGHT IS ON AND PEDAL WONT RESPOND CHECK ENGINE LIGHT ON AND WONT ACCEL E26 CUSTOMER STATES;CHECK ENGINE LIGHT COMES ON AT TIMES AFTER STARTING, WHEN LIGHT COMES ON VEHICLE CHK ENGINE LIGHT ON IDLES BUT NO FOOT FEED RECK VEH ACT LIKE IT HAS POWER TECH 9644 MILES 13,242 DATE 6 27 02 RD 254614 CK CHECK ENGINE LIGHT HAS BEEN COMING ON ADVISE CLET STATES WON'T MOVE AT TIMES WHEN PUSHING ACCELERATOR SOP HERE DORS NOT ACCELORATE NO POWER D41 CUSTOMER REPORTS TRANSMISSION LIGHT COMES ON AND TRANS WILL NOT GO INTO GEAR AT TIMES. LISTON THOW, 8008 9016 MOST LISTON ACCEL. CHECK ENGINE LIGHT COMING ON INTERNITTENLY, WHEN LIGHT IS ON, VEHICLE HAS NO ACCELERATION CUSTOMER REQUESTS CHECK THE GAS PEDAL FOR BEING INOP **950NO ACCELERATION WHEN PEDAL DEPRESS** VEC WILL NOT TAKE FUEL AND CHK ENGLIGHT ON CLIST STATES CK ENGLIGHT IS ON WHEN DRIVING AND WILL NOT ACCELL AND THEN THE OVER DRIME LIGHT WILL FLASH CUSTOMER STATE AT TIMES WHEN PRESSING ACCELERATOR PEDAL NOTHING HAPPENS ENGINE FOLE ONLY AT TIMES ON STARTS THE CK ENGINE LIGHT COMES ON AND VEHICLE WONT MOVE THE LIGHT GOES OUT AND THEN TRANS ENGAGES CHECK ENGINE LIGHT COMES ON WHEN YOU PRESS ON THE BRAKE THAT IS WHEN THERE IS NO ACCELERATION. AFTER ABOUT FIVE MINUTES, THE LIGHT WILL GO OFF, AND EVEL D41 CUSTOMER STATES ENGINE SURGES LIKE IT HAS A MISS WHILE DRIVING CUST STATES SES LIGHT COMES ON WHEN IT DOES VEH WONT ACCELERATE JUST (DUES NO FUEL FEED ON ACCL AT TIMES, PEDAL?? CHECK ACCRILLERATOR FED TRUCK WONT MOVE WHEN DEPRESSED CK ENGLITE ON WONT ACCEL AT TIMES, WONT REV UP AT TIMES ON ACCEL FROM A STOP AND CHECK ENGINE LIGHT COMES VEH CHECK ENGINE LIGHT COME ON & VEH LOSES POWER E29 WP ENGINE MISS, SURGE CUSTOMER STATES CHECK ENGINE LIGHT ON E29 (EAS) CK CHECK ENGINE LIGHT COMES ON AND WONT ACCELERATE FROM A STOP E29 CK ENGINE LIGHT ON WILL NOT ACCEL CUST STATES TRUCK HESITATES ON ACCELERATION

AT TIMES WILL DEPRESS ACCERATOR AND NOTHING HAPPENS
CHECK ENGINE LIGHT IS ON AND VEHICLE MISSES AND RUNS ROUGH
CHECK ENGINE LIGHT ON NO ACCEL AT TIMES ENGINE RUNS GREAT
CHECK NO POWER ON ACCEL
D36 C & DIESEL ENGINE INTERNITTENLY CK ENG LIGHT WILL COME ON AND VEHICLE DOES NOTHING WHEN PRESS ACCELERATOR
ENGINE SURGES WHILE DRIVING

SERVICE ENGINE LIGHT COMES ON AND TRUCK MAS NO POWER
D50 C 8 INTERNITTENT NO RESPONSE PROM ACCELERATOR
CUST SAYS AT TIMES WHEN TRYING TO ACCELL THERE IS NO RESPONSE AND NOTHING HAPENS, INTERMITTENT PROBLEM, CUST
CHECK ENGINE LIGHT COMES ON AND ENGINE NO RESPONSE, CHECK AND ADVISE.
CUST STATES CAR WILL NOT MOVE. CHECK ENG LIGHT IS ON. SOP ON ORDER — CK AND ADVISE.
CHECK ENGINE LIGHT IS ON AND WONT ACCELERATE \$29
E29 CC THE CHECK ENG LIGHT IS COMMING ON INTERMITANTLY AND ON ACCEL, VECH WILL NOT RESPOND
C50 O — WILL NOT ACCELERATE

PER3-644 32325

ENIGNE WILL NOT REV UP WHEN STEPPING ON POOT PEED.

CUST STATES WILL NOT ACCELERATE AT TIMES, THEN ALL OF A SUDDEN TAKES OFFICE AND ADVISE HAPPENS EVERY DAY 3 OR 4 TIME

DED CLISTOMER REPORTS TRUCK STOPS ACCELERATING SQUETIMES, CHECK AND ADVISE

CUSTOMER BAYS THAT TRUCK HAS NO POWER ON HARD ACCEL

CUSTOMER STATES THE VEHICLE JUST IDLES, DOE NOT GO WHEN YOU PRESS THE ACCELERATOR.

CUST, STATES AT STOPS THE TRUCK WILL NOT MOVE WHEN ACCELERATOR IS PUSHED ON APMS STAY THE SAME THEN

CLIST, STATES CHECK ENGINE LIGHT ON AND ENGINE WILL BE FUNNING FINE BUT DROPS DOWN TO IDLE AND HAS NO ACCELL.

CHECK ENSINE LIGHT ON, WAITING FOR CLIST TO CALL TO SEE IF ANY FURTHER CONCERNS WITH VEH, VEH WAS TOWED IN

C/8 CHECK ENGINE LIGHT IS ON.

CUST STATES NO RESPONSE FROM ACCELERATOR PEDAL, MAINLY WHEN WARMED UP

E20 CHECK ENGINE LIGHT STAYS ON

CKFOR LOSS OF POWER AT HWY SPEED

1829 CK ENGINE LIGHT ON WILL NOT ACCEL

CHECK ENGINE LIGHT ON

CUSTOMER STATES THERE WAS LOW POWER THEIN VEHICLE LOST FOWER AND WAS TOWED IN.

CHECK ENGINE LIGHT COMES ON AT TIMES

C S AT TIMES ACCELERATOR PEDAL NOP, VEHICLE TOLES OK BUT WONT MOVE, CAN PRESS ACCELERATOR, SEVERAL TIMES & WILL WORK...S.O.P.

(E20)CK, ENGINE LIGHT IS ON.

"#20 CHECK ENGINE LITE IS ON AT TIMES.

CUSTOMER STATES CHECK ENGINE LIGHT ON

CHECK VEHICLE THROTTLE PEDAL STICKS (LDSS OF ACCELERATION) TECHISIOS SOP HERE

VEHICLE WILL START AND IQUE BUT WILL NOT ACCEL.

CUBT STATES WHEN ACCELERATING FROM A STOP THERE IS NO RESPONSE FROM GAS PEDAL CUSTOMER DROPS INTO N & BACK TO D AND OK CK ENGINE LIGHT ON

EZE CHECK ENGINE LIGHT LIGHT IS ON CUST STATES WHEN THEY PUSH THE GAS PEDAL THE VEH WILL NO GO OR

E28" CHECK ENGINE IS ON, AT COLD START VEHICLE HAB NO RESPONSE BARLEY MOVES, ON ACCELARATION.....

BER ENG BOOK LIGHT COMES ON

CHECK AND ADVISE CLIST STATES THE VEHICLE WILL LOSE POWER AND NOT RESPOND TO THE FLIEL PEDAL AND THE CHECK ENGINE LIGHT IS ON CODE E28

CHECK ENGINE AT TIMES WILL NOT ACCEL RUNS FINE GOES NO WHERE

CHECK ENGINE LIGHT ON (DOESN'T WANT TO GET UP & GO WHEN ON GAS PEDAL)

ENGINE HAS LOSS OF POWER WHEN PUT INTO DRIVE OR REVERSE THE TRUCK WONT MOVE AT TIMES

CUST STATES THE VEH WILL NOT ACCEL, BUT DOES ENGAGE INTO GEAR.

CUST STATES IN LUKEWARM STAGE IDLES UP DOWN INSTALL SOP

CUST REPORTS TRUCK GOES INTO NEUTRAL WHEN ACCEL AFTER LOOSING ENGIPOWER. READ WRITE P SHEET FOR MORE INFO

CUST STATES AT TIMES THE THROTTLE DOES MOTHING

CHECK ENGINE LIGHT ON AND WILL ONLY LOVE

DAZ GLEST STATES VEHICLE WILL NOT ACCELERATE INTERMITTENTLY.

C 5 AT TIME TRUCK WONT ACCELERATE AT TIMES HAS TO POP GAB PEDAL 050

TOWER IN, WHILE DRIVING AT ABOUT SOMPH VEHICLE ACTED AS IF IT WERE IN NUETRAL AND WOULD NOT MOVE, DID NOT STALL AND RPMS STAYED AT AN IDLE.

CUST STATES CHECK ENGINE LIGHT ON ENGINE WILL NOT GO OVER 500 RPM

OSO CUST, STATES ENGINE CUTS OUT WHEN OPERATING ACCELERATOR PEDAL

CUST STATES WHEN TRYING TO ACCEL AT TIMES VEH WILL NOT MOVE AT ALL BEEMS TO JUST GO INTO NEUTRAL

CUSTOMER STATES OHK ENGINE LIGHT APPLY PEDAL NOTHING HAPPENS FOR FEW MONTHS LACK POWER , SEEMS LIKE

CHECK ENGINE LIGHT ON AND JUST IDLES AT TIMES

INTERNAL ACCELERATOR DOES NOT HAVE ANY RESPONSE , HAPPENED STIMES YESTERDAY , AND CHECK ENGINE LIGHT ON

CHECK ENGINE LIGHT IS ON

CAST STATES CHECK ENGINE LIGHT IS ON RUNNING ROUGHT DIES ON ACCEL

CUST STATES ON ACEL NO POWER BERVICE SOON LITE CAME ON

CUSTOMER BTATES SERVICE ENGINE SOON LIGHT IS ON GO TO EXCEL WILL NOT - EXCEL UNTIL 30 SECCUMPS LATER

CK ENGLITE IS ON HAS ACCELERATION TROUBLES IF DUE FALLS BELOW 1000 RPM VIRY CONSISTENT (S.O.F.S.) ACCELERATION FROM STOP AFTER DRIVING

CUSTOMER DRIVING ON INTERSTATE, LOSS POWER DID NOT SHUT OFF, SEEMS TO RUN BY PLAYING IN CRUISE AT

CHÉCK ENGINE WILL NOT ACTULERATE STALLS

CHECK ENGINE LIGHT IS ON

WHEN COLD AND PUTS INTO GEAR AND STARTS DRIVING LOBES ALL POWER AND BLK SMOKE COMES OUT OF EXHALIST IT WONT STALL BUT YOU HAVE TO SIT UNTIL. IT WARMS UP NO RESPONSE FROM THROTTLE WHEN PUSHING ON GAS PETAL.

CUSTOMER BAYS ENGINE WILL ONLY IDLE SOMETIMES

CHECK ENGINE LIGHT IS ON AND NO POWER WHEN ACCELERATING.

W CHECK ENG LIGHT COMES ON THROTTLE INOP

VEHICLE STALLS AT COMPLETE STOPS FEELLS AS IF IT ISN'T GETTING GAS.

CUST STATES TRANSMISSION IS SLIPPING

D50 REPAIR FOR NO THROTTLE RESPONCE AT TIMES

CUST STATES CK ENGINE LIGHT ON WHILE DRIVING AND AT TIMES WHILE DRIVING HWY SPEED VEHICLE LODGES EVERYTHING BUT (DUE

WICHECK ENGLIGHT GOES ON NO THROTTLE!

CUSTOMER STATES WHILE DRIVING VEHICLE CUTS DUT HAS TO PULL OVER LOSES. ACCELERATION, KICKS BACK IN AND GOES AGAIN. WHEN WARM

WHILE DRIVING ENGINE LOOSES ALL POWER BUT STAYS MUNNING ALSO CHECK ENGINE LIGHT IS ON ADVISE E29

CUST STATES VEHICLE WILL NOT ACCELEARATE INSTALL S.O.P PEDAL ASSY

CUST STATES CHECK ENGINE LIGHT CAME ON

\$29 CK, \$MBINE LIGHT ON AND ENGINE WOULD NOT RESPOND TO ACCELERATOR ONCE

OWNER STATES CHECK ENGLITE ON AND VEHILCE SUCKS BADLY

CHECK ENGINE LITE...WONT ACCELL

CUSTOMER STATES VEHICLE BLICKING WHILE DRIVING SEE VICTOR

829 REPAR MIL IS ON BEVERE HEBITATION ACCEL.

DISCUST STATES ENG SURGES ON ACCL AT TIMES WHILE DRIVING AT STEADY SPEEDS, NO CHIK ENG LIGHT ON.

CK AT TIMES WHEN PUSHING ON ACCELERATION, TRUCK WILL NOT MOVE

E29 CUST STATES CK ENGLIGHT ON AND ENGINE STALLS AT IDLE AND ON ACCEL FROM STOPS

CUSTOMER STATES CHECK ENGINE LIGHT ON

CUST STATION VEHICHKIENG LIGHT IS ON

BERVICE ENGINE LIGHT IS ON WONT RUN

C & THAT VEHICLE IS BURGING WHILE DRIVING

CK ENGINE LIGHT ON CUTS OFF WHILE DRIVING

SAYS INT WHILE DRIVE THE CELLUTE IS ON AND STAYS ON UNTIL KILL TRUCK AND ALSO SAYS WHEN ACCEL SAYS WONT DO ANYTHING WONT REV UP AT ALL SHE ROS

CLIST STATES ENGINE LOOSES ALL POWER AT TILES, ENIGNE WILL KEEP PLEANING BUT WONT TAKE ACCEL, DOES HAV

AT TRACE WHEN STEPPING ON FOOT FEED NOTHING HAPPENS, YOU MUST LET ALL THE WAY UP ON THE POOT FEED, PRESS DOWN AGAIN

ENG SPUTTERS AND CHES AT STOPS TECH 123

DOS CUSTOMER STATES THAT INTERMITTENTLY WHEN ACCELERATOR DEP RESSED NOTHING HAPPENS VEH DOES NOT ACCEL

CHECK ENGINE LIGHT COMES ON AT TIMES AND THE TRUCK WILL NOT ACCELERATE

C 6 SOMETIMES YOU PUT VEHICLE IN DRIVE AND IT WILL NOT MOVE (2 X IN 5 DAYS).

C/S CK ENGINE LITE ON

CUST STATES CHECK ENGINE LIGHT IS ON, STATES WHEN SLOW DOWN THEN TRY TO ACCOLURATE, HESITATES, DOESN'T WANT

CUST STATES VEHICLE WONT PULL IN FORWARD GEAR

CUSTOMER STATES CHECK ENGINE LIGHT ON

CUSTOMER STATES NOTHING HAPPENS WHEN SHE FUSHES ON GAS PEDAL LAST WEEK SHE NEEDED TO BACK UP AND WHEN SHE PUT IT IN REVERSE AND PUSHED ON THE PEDAL CUSTOMER STATES VEHICLE SHUTS OFF WHEN DRIVING

CUSTOMER STATES, CHECK ENGINE LIGHT ON & WHILE DRIVING & COMING TO A STOP, ATTEMPT TO ACCEL & NO REV.

DISC WHILE SITTING AT LIGHT VEH WILL NOT ACCEL STAYS AT IDLE CUST MUST TURN VEH OFF AND THEN VEH WILL GOINTO GEAR

OCP E29 CHECK ENGINE LIGHT IS COMING ON

E29 REPAIR MIL IS ON TRUCK WOULDN'T ACCEL FROM A STOP AND O DILAMP IS FLASHING.

PRESS GAS PEDAL; VEC HAS NO RESPONCE; PUT INTO METURAL AND TRY AGAIN IS DIKAY FOR A WHILE HAPPEN IN FORWARD AND REVERSE

CK ENGLIGHT ON AND AT TIMES WHEN ACCEL PUSHING ON ACCEL PEDAL NO REACTION

WILL NOT ACCOLURATE AT TIMES

CK FLEL PEDAL SEALS TO SENSATIVE

QUEST STATES THE CHECK ENGINE LIGHT IS ON, BUT DOES NOT HAVE ANY OTHER SYMPTOMS, DIAGNOSE & ADVISE.

NO POWER ON TAKE OFF

CUST STATES CHECK ENGINE LT. ON ADV.

DIESEL TRUCK CONCERN: DRIVER STATES THAT TRUCK APPARENTLY NEUTRALLED WHILE DRIVING; WOULD NOT ACCELERATE. CHECK ENGINE LIGHT CAME ON.

CHECK ENGINE LIGHT IS ON, INSTALL SOP

INNORMAL DRIVING CONDITIONS VEHICLE WILL MISSISHED AT ANY SPEED.

CUST STATES THAT CHECK ENGINE LIGHT IS ON

CUSTOMER STATES WHILE DRIVING TAKE CRUISE CONTROL OFF VECHILE ACT LIKE WANTS TO STALL CHK AND AV

060 VEH WILL NOT ACCELERATE WHEN PUBLING GAS PEDAL INTERACTENT

CUSTOMER STATES WHEN COMING TO A STOP NO RPMS NO POWER PUTS IN NEUTRAL AND BACK TO DRIVE WORKS OK

C S WHEN PUSH ACCELLERATOR PEDAL SQUETIMES ENGINE DOES NOT RESPOND.

WHEN TRYING TO ACCELERATE THERE IS NO RESPONSE FROM TRUCK HAS TO PUSH PEDAL CONSTANTLEY TILL IT RESPONDS

THE AMBER CHECK ENGINE LAMP IS ON, WHEN DECEMBRATING AND THEN ACCEMBRATING THERE IS NOS RESPONSE IN THE FUEL FEED, CUST PLITS INTO NEUTRAL THE REVS THE !

CUST STATES CK ENGINE LIGHT AS BEEN ON AND OVERDRIVE LIGHT AS FLASHING

D21 CUBTOMER STATES CK UNIT FOR STALLING

CHECK ENGINE LIGHT ON

VEHICLE BARLEY MOVES WHEN GABRING IT WILL JERK, DROVE FROM S.CAROLINA SAT AND HAD TO USE CRUISE TO KEEP GOING ON PREEWAY

SOMETIMES WILL NOT MOVE WHEN PUT IN TO DRIVE, POS

CEL IS ON AT THIS TIME

CUST STATES CK FOR NO THOTTLE RESPONSE

DAY WHEN ACCELERATING TRUCK LOCKES POWER WILL ACCELERATE IF CLIST FEATHERS PEDAL

CUSTOMER STATES CHECK ENGINE LIGHT ON ROAD TESTED, SEC TEST PO122 RECIEVED, RAN PID MONITOR

WICHECK ENGILIGHT ON VEH WONT MOVE WHEN GIVING GAS

CUST STATES INTERMITTANTLY WHILE DRIVING THE ENGINE WILL OUT & SHUT OFF COMPLETELY & WILL RESTART IMMEDIATELY ALSO CHECK ENGINE LIGHT IS ON AND HAS I

CUST STATES INTERMITT VEHICLE LACKS POWER WHEN ACCELERATING

E29 CUSTOMER STATES CK ENGLIGHT ON AND SOMETIMES ACC PROAL WILL NOT RESPOND

E29 CUST STATES THE CHECK ENGINE LIGHT (8 ON.

CUST STATE VEHICLE LOSES POWER THEN TAPS ACCEL THEN VEHICLE WILL RUN

CHECK VEHICLE WILL NOT MOVE AT TIMES WHEN ON AN ACCEL

CUST STATES CHECK ENGINE LIGHT COMES ON

AND STEP ON GAS AND CAR WILL NOT ACCELERATE

CUST STATES THAT ENGINE STALLS WHEN ACCELERATING, NO POWER ADVISE

EZO C S CKLENGINE LIGHT STAYS ON

C & VEHICLE WILL NOT MOVE WITH THROTTLE PRESSURE. ONLY ABEL TO GO ABOUT TEN MPH

CUSTOMER STATES CHECK ENGINE LIGHT ON AND ENGINE HAS NO POWER ON TAKEOFF

CUSTOMER STATES VEHICLE IS MISSING AT DIFFERENT SPEEDS.

PERS-044 32328

CUSTOMER STATES TRANS WENT INTO NEUTRAL AND WOULD NOT MOVE ENGINE REVISED SHE PUT IT INTO LOW AND IT

E20 CHECK ENGINE LIGHT IS ON

C S CHECK ENGINE LIGHT COMES ON, TRUCK WILL NOT RESPOND WHEN PRESSING ACCELERATOR.

E29 CLISTOMER SAYS CHECK ENGINE LIGHT COMING ON

POR CHECK TRANS ON FIRST ACCULISTALLS ENGINEVS BUT NO ENGA UGEMENT ADVISE FOR REPAIRS.

DIESEL. CK ENGINE LAMP ON

LACK OF POWER ON TAKE OFFS

CHECK ENGINE LIGHT ON WAS HARD TO START ON INITIAL A.M. START, CUSTOMER THAT WAS RENTING VEHICLE SAID THEY CHECKED TRANS. FLUID AND IT WAS LOW CHECK. CUST STATES WHILE DRIVING ON THE PRINEWAY THE CAR HAD NO ACC CUST WAS PUSHING ON THE GAS BUT WILL NOT GO BUT THE

CS ADJUSTER FOOT PEDAL WOF H20

ENGINE LIGHT ON DOES NOT ACCEL CORRECTLY, LOOSES POWER

CUSTOMER STATES ADJUSTABLE PEDALS ARE NOT INSTALLED.

CUS TOMER STATES WHEN COASTING FORM HI WAY SPEEDS AND THEN REACCELERATING THERE IS NO RESPONSE FROM THE THROTTLE ,CUSTOMER HAS TO TAP. THE THROTTLE CUST STATES INTERMITTENT THE TRUCK WILL NOT ACCEL CHECK ENGINE LIGHT DID COME ON CHECK AND ADVISE

050 CLISTOMER REPORTS LOSS OF FOWER WHILE DRIVING LOSS OF ACCELERATION FROM PEDAL CHECK ENGINE LIGHT CAME ON ONCE HAS BEEN HAPPAING FOR 1 WEEK EVER.

CUSTOMER STATES ENGINE LOST POWER YESTERDAY WHILE DRIVING THE WOULD NOT ACCELERATE WHEN STEPPING ON CUSTOMER BAYS WHEN PUT INTO GEAR VEHICLE WILL NOT MOVE AT TIMES LIKE LACK OF POWER

D41 ENGINE SURGES

INSPECT ADJUSTABLE GAS PEDAL INOP

CUST STATES VEH DOSNT ACCEL, BUT IDLES

620 CUSTOMER 518 \$16 CHECK ENGINE LIGHT COME ON AND ENGINE HAS NO POWER

CUST STATES THE CHECK ENGLIGHT AS ON

CLIST STATES VEHICLE HAS A HESITATION AND BLICKS DN ACCELERATION...

CHECK ENGINE LIGHT ON

CLIST STATES THE ENGINE DOES NOT GO UPON GIVING IT GAS, KEPT TRYING TO APPLY GAS AND IT FINALLY WENT, NO THROTTLE RESPONSE OR RAISE IN RPMS.

E29 CUST STS CHECK ENGINE LIGHT ON SOP ROKSS190

CUSTOMER STATES CHECK ENGINE LIGHT ON

C 9 EMBSIONS LIGHT (9 ON, NO THROTLE AT ALL, CUSTOMER HAS TO PUT FOOT ON BRAKE, INGUAGE GAS THEN PUT IN DRIVE, SOMETIMES IT WILL GO

NO THROTTLE RESPONCE AT TIMES

CLIST STATES CHECK ENGINE LIGHT IS ON AND AT 10 15 MPH CLIST STEPPED ON THE GAS PEDAL AND VEHICLE DID

CIS INSPECT FOR A LOST OF POWER AND CK ENGINE LIGHT ON

CUSTOMER STATS WHEN PRESSING DOWN ON GAS PEDAL, BUY WILL NOT MOVE,

SEEMS TO HAVE NO FOOT REED POWER

CK FOR CK ENGINE LIGHT ON AND ENGINE LODGING POWER

VEHICLE HAS NO ACCEL FROM A STOP

CUSTONER STATES THE ACCELERATOR PEDAL DOES NOT ALWAYS ENGAGE YOU HAVE TO APPLY PEDAL MULTIPLE TIMES FOR IDLE TO KICK IN, SEE ADVISOR FOR INFO

CUSTOMER STATES CHECK ENGINE LIGHT ON

NO RESPONSE WHEN ACCELERATING AND ENGINE LIGHT IS ON

CHECK ENGINE LIGHT ON

80GGS ON HARD ACCEL DNLY 2 TIMES

CHECK ENGINE LIGHT COMES ON

CIB WHEN BINGING IS COLD THE GAS PEDAL HAS NO RESPONCE YOU CAN PUSH IT DOWN 2 OR 3 TIMES SEPORE IT REACTS.

CHK FOR VECH CRANSK NO START

REMOVE AND INSTALL ACCELERATOR PEDAL (REP:RO#314608)

CUSTOMER STATES CK ENGLIGHT ON 5 NO POWER PROM STOP

MES3-844 32329

CLIALITY CHECK INITIALS: CUST STATES VEHICLE HAS NO POWER AND CHECK ENGINE LIGHT (SON

CHECK ENGINE LIGHT COMES AT TIMES WHEN STARTING, AND WHEN YOU PUSH THE GAS PEDDLE NOTHING HAPPENS

IDLE TOO FAST AT TIMES OR SURGES TAKING OFF

E29 CK ENGINE LIGHT ON, LOSES POWER AT TIMES NO ACELL (NO RPMS)

CLISTOMER STATES CHECK ENGINE LIGHT IS ON

LIGHT ON NO POWER

CUSTOMER STATES WHEN FIRST PUTS IN GEAR HEBITATES BEFORE ENGAGING OR WONT MOVE AT ALL CHECK ENGINE LIGHT 19 ON E28

CUSTOMER STATES CHECK ENGINE LIGHT IS ON

VEH WILL NOT RESPOND AT TREES WHEN THROTTLE PEDAL RESITATES TO PULL OFF

CHECK ENGINE NO THROTTLE RESPONSE

CLIST STATES ENG NOISY WHEN TURBO FAN DILMETAL TO METAL NOISE, NO POWER ACCEL PEDAL FEELS DEAD

CK ENGINE LIGHT IS ON

DIESEL ENGINE WILL NOT ACCELERATE AT TIMES AFTER LETTING OFF ACCEL THEN PRESS AGAIN TO ACCEL, SEEMS DEAD, CAN LET OFF ACCEL & PRESS AGAIN AND GOES CUSTOMER STATES NO THROTTLE CONTROL

CUSTOMER STATES LOSES POWER

CUSTOMER STATES OR ACCELL

TRUCK LOST POWER WHILE DRIVING, COASTED AND FUEL PEDAL WOULD NOT RESPOND. SEE SELDEN

CHECK THROTTLE VEHICLE WILL NOT ACCEL

CHK FOR INT CONCERN UPON ACCESUL RPM DROPS OFF BACK TO IDLIE TYPE SPEED, ACTS AS THOUGH IT WONT PULL REPORT.

CHECK THROTTLE NO ACCIDERATION

W CUST STATES VEHICLE HAS LOOS OF POWER, ACT LIKE THERE IS NO TURBO BOOST ON TAKE OFF

CHECK ENGINE LIGHT GOES ON AND TRUCK LOOSES POWER FOR A FEW SECONDS, THEN THE LIGHT GOES OFF AND REGAINS POWER.

E29'AMBER CHECK ENGLIGHT COMES ON AND STAYS ON, AT TIMES VEH WONT ACCELORATE

E29 CK ENGINE LIGHT IS ON ACCEL VEH WONT GO

HAS NO ACCELERATION.

C S. DOBSHT RESPOND WHEN GOING TO ACCELERATE CHECK ENGLIGHT WILL COME ON INTERMITTENTLY

CHECK ENG. ON, LOST POWER INTERMITTENT LOSS OF CHARGE, NO HIGH IDLE.

CUSTOMER REPORTS NO THROTTE RESPONSE WHEN IN DRIVE...SEEMS OK IN REVERSE OR PARK.

CUST STATES THAT GAS PEDAL WILL NOT REACT WHEN DEPRESSED

CUSTOMER STATES THEIR IS NO RESPONCE PROMINGLE PEDAL UNLESS YOU PUSH DOWN THEN LET UP AND PUSH DOWN AGAIN

CUSTOMER STATES TRUCK INTERMITTANTLY HAS NO THROTTLE RESPONSE ON ACCELERATION

LOSS OF THROTTLE AT TIMES

VEHICLE WILL NOT ACCELERATE

CUST STATES ACCELERATOR IS INTERMITTENLY INOP - ENQUISE WILL DUE BUT NOT ACCELERATE

CUSOTMER STATES CHECK ENGINE LIGHT IS ON LOSES POWER AT IDLE

CLIST STATES THIS VEH HAS NO POWER HARD TO GO 65 70 MPH SEE PULLS A HORSE TRAILER AND STATES THAT THE TRUCK WILL BARRLY PULL THE TRAILER ALSO THE CK ENGI

ENGINE WILL NOT ACC AT TIMES

ENGINE WILL NOT ACCEL BUT IDLES OK DI DIESEL

CUSTOMER STATES WARNING LIGHT ON DASH ABOVE ENGINE LIGHT COMES ON AT TIMES WHILE DRIVING

VEHICLE WILL NOT ACCELERATE WHEN PRESS ACCEL

CUSTOMER STATES NO ACCEL RESPONSE

PER3-844 32338

	580 USA	152637	2 U8A	T21	V44	F7	\$11		
	631 UBA	113486	1 USA	T21	V40	P7	\$11		
	310 USA	171011 EB4	USA	T21	V41	F7	\$11	•	
	712 USA	158518 E72	USA	T21	V40	F7	811	_	
	813 USA	141438	1 U8A	T21	V42	FT	811		
	380 LIBA	174540 E84	UBA	T21	V44	F7	B1 1	4	
	681 USA	113102	1 USA	T21	V41	F7	911		
	612 USA	188018 554	USA	T21	V44	77	51 1		
	670 USA	159642 E54	USA	T21	V44	F7	S11		
	775 USA	171098 554	UBA	T21	V44	F7	3 1†		
	803 USA	121692 E34	USA	T21	V41	F7	611		
	573 USA	153699	2 USA	T21	V42	F7	S11		
3	573 UBA	153080 884	UBA	721	V44	F7	811		
	908 UBA	174477	1 USA	121	V41	F7	\$11	Ø	
ľ	602 UBA	147486	2 UBA	T21	V44	F 7	811	_	
3	734 USA	148022 E84	UEA	121	V44	F7	91 1	•	
_	601 USA .	123453 E84	UBA	T21	941	F7	81:	ě	
Ħ	938 USA	152165 E84	USA	T21	V44	F7	811	_	
32331	304 USA	121213 B84	USA	T21	V44	F7	811		
=	615 USA	123039 E84	ARU	T21	V41	F7	\$11		
	936 USA	152165	1 USA	T21	V44	F7	\$11		
	815 USA	171104 E84	UBA	121	V41	F7	611		
	595 USA	124802 E84	UBA	T21	V42	F7	611		
•	USA	171079	1 UBA	721	V44	F7	\$11		
	219 USA	145025 E84	UBA	T21	V44	F?	811		
	713 USA	182031	2 USA	121	V44	F7	511		

AREA_CO COUNTRY_CO \$LB_DLR_CD TXN_CD CHTRY_BOLD CRT_CD VFG_CD AWS_VL_CD VRT_CD TIS_FLAG

FEE3-644 3233

410 USA	152201	2 USA	T21	V44	PT	511	
281 UBA	152029 684	USA	T2t	V44	F7	811	
936 USA	162777	1 U8A	T21	V41	ř7	S 11	
641 UBA	174468 E84	UBA	721	V41	F7	811	
970 USA	121005	2 USA	T21	V44	F7	511	*
954 USA	124216	2 USA	T21	V43	F7	811	
479 USA	123227 E84	USA	T21	V41	F7	\$11	
600 USA	156543	1 U8A	T27	V44	F7	811	
916 USA	152567	1 UBA	721	V44	F7	S11	
972 USA	192480 €84	USA	T21	V41	F7	511	
303 USA	158011 E84	USA	T21	V44	F7	\$11	
225 USA	123306 E64	USA	T21.	V42	F7	811	
225 USA	123306 E84	U8A	T21	. V44	F?	811	
252 USA	121725	2 UBA	T21	V41	F7	811	
918 USA	172205	1 UBA	121	V41	F 7	911	
504 USA	124224 E72	USA	T21	V44	F7	6 11	2
219 USA	147500 E84	U8A	T21	V44 ·	F7	511	_
703 USA	127044	1 USA	T21	V42	FT	S11	•
903 USA	152054	2 USA	T21	V44	F7	811	•
913 UBA	183009 E84	USA	T21	V44	F7	S11	
954 USA	163080 E84	UBA	T21	V48	F7	511	
97\$ USA	152734 E64	USA	T21	V41	 F7	811	•
830 USA	162718 584	LISA	T21	V44	F7	811	_
972 USA	152467	911 USA	T21	V41	F7	511	
740 USA	147422 E84	USA	T21	V44	F7	S11	
214 USA	152460 E84	UBA	T21	V41	F7	3 11	
581 UBA	124218 E84	USA	T21	V44	F7	811	
636 USA	153334 EB4	USA	T21	V44	F7	811	
602 UBA	148426 E84	UBA	T21	V41	F7	811	
502 USA	147022 E84	USA	T21	V44	F7	811	
561 USA	124224 E84	U&A.	T2:1	V41	1 7	811	
719 USA	162017 E84	USA	T21	V41	F7	911	
724 USA	144415 E64	USA	T21	V41	FT	811	•
870 UBA	123591	1 USA	T21	V44	P7	&11	_
704 USA	121000 E04	USA	T21	V44	F7	811	
713 USA	152031	2 USA	121	V44	F7	\$11	
AZU LAS	124517 E84	USA	T21	V41	ř7	811	42
602 USA	156605	2 USA	T2:1	V41	F7	B11	8
405 USA	152200 E84	USA	T21	V44	F7	811	ă
979 UBA	152023 E84	UBA	T21	V44	F7	811	_
305 USA	124012	2 USA	T21	V42	F7	\$ 11	
918 UBA	158402 E84	USA	T21	V44	F7	811	•
734 UBA	148101 584	USA	121	V44	F7	511	_
484 USA	127490 E94	USA	T21	V42	ř7	811	
337 USA	162067 E84	USA	T21	V42	F7	811	•
731 USA	123045 E72	USA	T21	V44	F7	3 11	-9
		****	•	***		•	

722 USA 141694 2 USA 721 V/4 F7 S11 501 USA 127417 1 USA 721 V/4 F7 S11 501 USA 12608 2 USA 721 V/4 F7 S11 640 USA 12608 2 USA 721 V/4 F7 S11 641 USA 127418 ESA USA 721 V/4 F7 S11 645 USA 127418 ESA USA 721 V/4 F7 S11 646 USA 12608 ESA USA 721 V/4 F7 S11 647 USA 12608 ESA USA 721 V/4 F7 S11 648 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 2 USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 65 USA 12608 ESA USA 721 V/4 F7 S11 66 USA 12608 ESA USA 721 V/4 F7 S11 66 USA 12608 ESA USA 721 V/4 F7 S11 67 USA 12608 ESA USA 721 V/4 F7 S11 68 USA 12608 ESA USA 721 V/4 F7 S11 68 USA 12608 ESA USA 721 V/4 F7 S11 68 USA 12608 ESA USA 721 V/4 F7 S11 69 USA 12608 ESA USA 721 V/4 F7 S11 60 USA 12608 ESA USA 721 V/								
1270 188A 128008 2 UBA 721	732 USA	141604	2 UBA	T21	V41	F7	511	
1806 1806 1806 1806 1806 1721 1806 1721 1806	301 USA	127417	1 USA	T21	V44	F7	911	
BAS LIBA	870 USA		2 UBA		V44	F7	S11	
BAS LIBA	410 UBA	127418 E84	UBÁ	. TZ1	V44	67	B11	
1500 152	843 UBA	121228 E84	USA				511	æ
732 USA 113553 2 USA 721 W1	506 USA					F7	6 11	•
732 USA 113553 2 USA 721 W1			USA		V44	F7		ē
732 USA 113553 2 USA 721 W1					V41		811	ō
					V41	17	511	_
713 USA 152032 2 USA 721 V41 F7 S11 200 USA 172425 2 USA 721 V41 F7 S11 400 USA 174610 1 USA 721 V40 F7 S11 501 USA 123582 E84 USA 721 V44 F7 S11 © 814 USA 162466 E84 USA 721 V44 F7 S11 © 814 USA 144605 1 USA 721 V44 F7 S11 © 814 USA 14505 1 USA 721 V44 F7 S11 © 814 USA 14505 1 USA 721 V44 F7 S11 © 814 USA 14505 1 USA 721 V44 F7 S11 © 814 USA 14505 1 USA 721 V44 F7 S11 © 815 USA 110225 E84 USA 721 V44 F7 S11 817 USA 162460 E84 USA 721 V44 F7 S11 818 USA 124902 E84 USA 721 V44 F7 S11 819 USA 152002 E84 USA 721 V44 F7 S11 819 USA 152002 E84 USA 721 V44 F7 S11 851 USA 152002 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152007 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 851 USA 152006 E84 USA 721 V44 F7 S11 852 USA 152006 E84 USA 721 V44 F7 S11 853 USA 174522 1 USA 721 V44 F7 S11 854 USA 172450 2 USA 721 V42 F7 S11 855 USA 155006 E84 USA 721 V44 F7 S11 856 USA 152006 E84 USA 721 V44 F7 S11 857 USA 152006 E84 USA 721 V44 F7 S11 858 USA 152006 E84 USA 721 V44 F7 S11 859 USA 152106 E84 USA 721 V44 F7 S11 851								
209 UBA 172425 2 UBA 721 V41 F7 811 408 UBA 174610 1 USA 721 V40 F7 811 810 UBA 122582 E84 UBA 721 V40 F7 811 69 814 UBA 182468 E84 UBA 721 V44 F7 811 69 814 UBA 145866 E84 UBA 721 V44 F7 811 69 814 UBA 145866 E84 UBA 721 V44 F7 811 82 1717 UBA 118225 B84 UBA 721 V44 F7 811 83 UBA 152460 E84 UBA 721 V44 F7 811 817 UBA 152460 E84 UBA 721 V44 F7 811 818 128 12860 E84 UBA 721 V44 F7 811 82 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152024 E84 UBA 721 V44 F7 811 83 UBA 152026 E84 UBA 721 V44 F7 811 83 UBA 152026 E84 UBA 721 V44 F7 811 83 UBA 152026 E84 UBA 721 V44 F7 811 84 UBA 152026 E84 UBA 721 V44 F7 811 85 UBA 152026 E84 UBA 721 V44 F7 811 86 UBA 15206 E84 UBA 721 V44 F7 811 86 UBA 15206 E84 UBA 721 V44 F7 811 87 UBA 15206 E84 UBA 721 V44 F7 811 88 UBA 172450 2 UBA 721 V44 F7 811 89 UBA 152162 E84 UBA 721 V44 F7 811		152032	2 USA	T21	V41	F7	511	
406 LISA 174610 1 USA T21 V40 F7 S11 S01 USA 123532 E84 LISA 721 V41 F7 S11 S01 USA 123532 E84 LISA 721 V41 F7 S11 S0 USA 123532 E84 LISA 721 V44 F7 S11 S0 USA 144660 1 USA T21 V44 F7 S11 S0 USA 116225 E84 LISA T21 V44 F7 S11 S0 USA 116225 E84 LISA T21 V44 F7 S11 S11 USA 116225 E84 LISA T21 V44 F7 S11 S11 USA 116225 E84 LISA T21 V44 F7 S11 S13 USA 147315 2 USA T21 V41 F7 S11 S13 USA 12402 E84 LISA T21 V44 F7 S11 S13 USA 125024 E84 LISA T21 V44 F7 S11 S13 USA 152024 E84 LISA T21 V44 F7 S11 S11 S13 USA 15209 2 USA T21 V44 F7 S11 S11 S13 USA 15209 2 USA T21 V44 F7 S11 S11 S13 USA 15209 2 USA T21 V44 F7 S11 S11 S13 USA 152024 E84 LISA T21 V44 F7 S11 S11 S13 USA 152029 2 USA T21 V44 F7 S11 S11 S13 USA 152024 E84 LISA T21 V44 F7 S11 S11 USA 152024 E84 LISA T21 V44 F7 S11 USA S11 USA S11 USA S200 USA S12042 E84 USA T21 V44 F7 S11 USA S1			2 UBA				& 11	
1981 1984 129592 E84			1 USA		V40		811	
918 USA 152498 E54 USA T21 V44 F7 S11							311	•
717 USA 11825 E84 USA T21 V44 F7 S11 417 USA 153490 E84 USA T21 V41 F7 S11 518 USA 147315 2 USA T21 V44 F7 S11 518 USA 147315 2 USA T21 V44 F7 S11 518 USA 15002 E84 USA T21 V44 F7 S11 618 USA 15002 E84 USA T21 V44 F7 S11 653 USA 15002 E84 USA T21 V44 F7 S11 653 USA 15002 E84 USA T21 V44 F7 S11 653 USA 111645 2 USA T21 V44 F7 S11 653 USA 11201 E84 USA T21 V44 F7 S11 654 USA 15201 E84 USA T21 V44 F7 S11 654 USA 15202 E84 USA T21 V44 F7 S11 654 USA 15202 E84 USA T21 V44 F7 S11 655 USA 15203 E84 USA T21 V44 F7 S11 656 USA 174522 1 USA T21 V44 F7 S11 657 USA 176400 2 USA T21 V44 F7 S11 658 USA 176400 2 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA T21 V44								ā
717 USA 11825 E84 USA T21 V44 F7 S11 417 USA 153490 E84 USA T21 V41 F7 S11 518 USA 147315 2 USA T21 V44 F7 S11 518 USA 147315 2 USA T21 V44 F7 S11 518 USA 15002 E84 USA T21 V44 F7 S11 618 USA 15002 E84 USA T21 V44 F7 S11 653 USA 15002 E84 USA T21 V44 F7 S11 653 USA 15002 E84 USA T21 V44 F7 S11 653 USA 111645 2 USA T21 V44 F7 S11 653 USA 11201 E84 USA T21 V44 F7 S11 654 USA 15201 E84 USA T21 V44 F7 S11 654 USA 15202 E84 USA T21 V44 F7 S11 654 USA 15202 E84 USA T21 V44 F7 S11 655 USA 15203 E84 USA T21 V44 F7 S11 656 USA 174522 1 USA T21 V44 F7 S11 657 USA 176400 2 USA T21 V44 F7 S11 658 USA 176400 2 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 15516 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 659 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16216 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA 16267 E84 USA T21 V44 F7 S11 650 USA T21 V44								ā
417 USA 153490 ES4 USA T21 V44 F7 S11 1317 USA 147315 2 USA T21 V41 F7 S11 1318								_
317 USA 14731\$ 2 USA T21 V41 F7 811 213 USA 124802 ESA USA T21 V44 F7 311 713 USA 152026 E94 USA T21 V44 F7 511 405 USA 152020 2 USA T21 V44 F7 S11 663 USA 152020 2 USA T21 V44 F7 S11 817 USA 182408 E84 USA T21 V44 F7 S11 817 USA 182408 E84 USA T21 V44 F7 S11 819 USA 152012 E94 USA T21 V44 F7 S11 820 USA 152012 E94 USA T21 V44 F7 S11 820 USA 174322 1 USA T21 V42 F7 S11 820 USA 172430 2 USA T21 V44 F7 S11 830 USA 172430 2 USA T21 V44 F7 S11 830 USA 152402 E84 USA T21 V44 F7 S11 830 USA 152406 E64 USA T21 V44 F7 S11 841 USA 152402 E64 USA T21 V44 F7 S11 841 USA 153402 E64 USA T21 V44 F7 S11 841 USA 153402 E64 USA T21 V44 F7 S11 841 USA 153402 E64 USA T21 V44 F7 S11 843 USA 15315 E34 USA T21 V44 F7 S11 844 USA 15315 E34 USA T21 V44 F7 S11 850 USA 15262 E84 USA T21 V44 F7 S11 869 USA 15262 E84 USA T21 V44 F7 S11 869 USA 15262 E84 USA T21 V44 F7 S11 869 USA 15263 E84 USA T21 V44 F7 S11 869 USA 15263 E84 USA T21 V44 F7 S11 869 USA 15263 E84 USA T21 V44 F7 S11 869 USA 15263 E84 USA T21 V44 F7 S11 869 USA 15263 E84 USA T21 V44 F7 S11 860 USA 15263 E84 USA T21 V42 F7 S11 860 USA 15263 E84 USA T21 V42 F7 S11 860 USA 15263 E84 USA T21 V42 F7 S11 860 U								
813 USA 124902 E84 USA T21 V44 F7 S11 713 USA 152024 E94 USA T21 V44 F7 S11 603 USA 15209 2 USA T21 V44 F7 S11 817 USA 11545 2 USA T21 V44 F7 S11 817 USA 182408 E84 USA T21 V44 F7 S11 817 USA 182408 E84 USA T21 V44 F7 S11 819 USA 152012 E54 USA T21 V44 F7 S11 820 USA 152012 E54 USA T21 V44 F7 S11 820 USA 174522 1 USA T21 V41 F7 S11 821 USA 172430 2 USA T21 V41 F7 S11 822 USA T21 V44 F7 S11 823 USA 178430 1 USA T21 V44 F7 S11 824 USA 178430 1 USA T21 V44 F7 S11 825 USA 178430 1 USA T21 V44 F7 S11 826 USA 178430 1 USA T21 V44 F7 S11 827 USA 158008 1 USA T21 V44 F7 S11 828 USA 158008 1 USA T21 V44 F7 S11 829 USA 152168 E84 USA T21 V44 F7 S11 820 USA 152162 E84 USA T21 V44 F7 S11 823 USA 153115 E34 USA T21 V44 F7 S11 824 USA 152162 E84 USA T21 V44 F7 S11 825 USA 152162 E84 USA T21 V44 F7 S11 826 USA 152162 E84 USA T21 V44 F7 S11 827 USA 152162 E84 USA T21 V44 F7 S11 828 1530 USA 152162 E84 USA T21 V44 F7 S11 829 USA 152162 E84 USA T21							•	
713 USA 15209 2 USA 721 V44 F7 S11 653 USA 15209 2 USA 721 V44 F7 S11 653 USA 11945 2 USA 721 V44 F7 S11 671 USA 162406 E84 USA 721 V44 F7 S11 672 USA 15209 E84 USA 721 V44 F7 S11 672 USA 152012 E54 USA 721 V42 F7 S11 673 USA 152024 E64 USA 721 V42 F7 S11 673 USA 152024 E64 USA 721 V42 F7 S11 674 USA 174522 1 USA 721 V41 F7 S11 675 USA 176402 E84 USA 721 V41 F7 S11 677 USA 168009 1 USA 721 V42 F7 S11 678 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V41 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 16816 E64 USA 721 V44 F7 S11 679 USA 179 USA 721 V44 F7 S11 679 USA 721 USA 721 V44 F7 S11 679 USA 721 USA 721 V44 F7 S11 679 USA 721 USA								
405 USA 15209 2 USA 721 V44 F7 S11 653 USA 111545 2 USA 721 V44 F7 S11 77 USA 11240 E84 USA 721 V44 F7 S11 77 USA 157 USA 152012 E84 USA 721 V44 F7 S11 77 USA 157 USA 152012 E84 USA 721 V44 F7 S11 77 USA 157 USA 152012 E84 USA 721 V44 F7 S11 77 USA 174522 1 USA 721 V44 F7 S11 77 USA 174522 1 USA 721 V44 F7 S11 78 USA 174522 1 USA 721 V44 F7 S11 78 USA 174522 1 USA 721 V44 F7 S11 78 USA 174522 1 USA 721 V44 F7 S11 78 USA 15800S 1 USA 721 V44 F7 S11 78 USA 152168 E84 USA 721 V44 F7 S11 78 USA 152168 E84 USA 721 V44 F7 S11 78 USA 152168 E84 USA 721 V44 F7 S11 78 USA 15316 E84 USA 721 V44 F7 S11 78 USA 153163 USA 153163 E84 USA 721 V44 F7 S11 78 USA 152162 E84 USA 721 V44 F7 S11 78 USA 152162 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 162168 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 E84 USA 721 V44 F7 S11 78 USA 16218 USA 721 V44 F7 S11 78 USA 16218 USA 721 V44 F7 S11 USA 16218 USA 721 V44 F7 S11 USA 16218 USA 721 V44 F7 S11								
883 USA								
817 USA 182408 E84 USA 721 V43 F7 811 972 USA 192072 E84 USA 721 V44 F7 811 201 USA 127047 E84 USA 721 V42 F7 811 201 USA 174522 1 USA 721 V41 F7 811 303 USA 174522 1 USA 721 V44 F7 811 303 USA 185008 1 USA 721 V42 F7 811 303 USA 185402 E84 USA 721 V42 F7 811 201 USA 185402 E84 USA 721 V44 F7 811 201 USA 185108 E84 USA 721 V44 F7 811 201 USA 185118 Z64 USA 721 V44 F7 811 201 USA 185118 Z64 USA 721 V44 F7 811 201 USA 185118 Z64 USA 721 V41 F7 811 201 USA 185118 Z64 USA 721 V41 F7 811 201 USA 185118 Z64 USA 721 V41 F7 811 201 USA 185118 Z64 USA 721 V41 F7 811 201 USA 185102 E84 USA 721 V41 F7 811 201 USA 185108 S84 USA 721 V41 F7 811 201 USA 185108 S84 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 185108 S81 USA 721 V44 F7 811 201 USA 721 V44 F7 811 202 USA 721 V44 F7 811 203 USA 721 V44 F7 811 203 USA 721 V44 F7 811 204 USA 721 V44 F7 811 205 USA 72462 1 USA 721 V44 F7 811 205 USA 72462 1 USA 721 V44 F7 811 205 USA 72462 1 USA 721 V44 F7 811 205 USA 72462 1 USA 721 V42 F7 811 205 USA 72462 1 USA 721 V42 F7 811 205 USA 72462 1 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811 205 USA 72462 7 USA 721 V42 F7 811								
972 USA 152072 E54 USA 721 V44 F7 S11								
201 UBA 127047 E84 USA 721 V42 F7 S11 380 USA 174322 1 USA 721 V41 F7 S11 UBA 172430 2 USA 721 V44 F7 S11 S03 USA 172430 2 USA 721 V44 F7 S11 841 USA 158008 1 USA 721 V42 F7 S11 841 USA 18402 E84 USA 721 V44 F7 S11 913 USA 182168 E84 USA 721 V44 F7 S11 913 USA 185115 E84 USA 721 V44 F7 S11 USA 119103 1 USA 721 V41 F7 S11 251 USA 132162 E84 USA 721 V41 F7 S11 809 USA 119262 E84 USA 721 V41 F7 S11 809 USA 116228 E84 USA 721 V42 F7 S11 B10 USA 158467 E84 USA 721 V44 F7 S11 B11 USA 152130 E84 USA 721 V44 F7 S11 B12 USA 152130 E84 USA 721 V44 F7 S11 B13 USA 152130 E84 USA 721 V44 F7 S11 B14 USA 152130 E84 USA 721 V44 F7 S11 B15 USA 152130 E84 USA 721 V44 F7 S11 B16 USA 152130 E84 USA 721 V44 F7 S11 B17 USA 152130 E84 USA 721 V44 F7 S11 B18 USA 152130 E84 USA 721 V44 F7 S11 B18 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 152130 E84 USA 721 V44 F7 S11 B19 USA 721 V45 F7 S11 B19 USA 721 V46 F7 S11 B19 USA 721 V42 F7 S11 B19 USA 721 V42 F7 S11 B19 USA 721 V42 F7 S11								77
174522								-
USA								
303 UBA 155009 1 UBA T21 V42 F7 511 641 USA 124402 E84 UBA T21 V41 F7 811 210 UBA 152168 E84 UBA T21 V44 F7 811 913 UBA 155115 E84 UBA T21 V44 F7 811 251 UBA 155115 E84 UBA T21 V41 F7 811 251 UBA 152152 E84 UBA T21 V41 F7 811 869 UBA 116225 E84 UBA T21 V83 F7 808 303 UBA 158467 E84 UBA T21 V83 F7 808 303 UBA 158467 E84 UBA T21 V84 F7 811 251 UBA 152130 E84 UBA T21 V44 F7 811 251 UBA 152130 E84 UBA T21 V44 F7 811 251 UBA 152130 E84 UBA T21 V44 F7 811 868 UBA 152130 E84 UBA T21 V44 F7 811 868 UBA 152131 E84 UBA T21 V44 F7 811 868 UBA 17145 E84 UBA T21 V44 F7 811 868 UBA 17145 E84 UBA T21 V44 F7 811 868 UBA 1714682 1 UBA T21 V44 F7 811 868 UBA 1714682 1 UBA T21 V44 F7 811 868 UBA 1714682 1 UBA T21 V44 F7 811 868 UBA 1714682 1 UBA T21 V44 F7 811 868 UBA 1714682 1 UBA T21 V44 F7 811 868 UBA 171468 UBA T21 V48 F7 811 868 UBA 171468 UBA T21 V48 F7 811 868 UBA 171468 UBA T21 V48 F7 811				T21				
### ### ### ### ### ### ### ### ### ##								
210 UBA 152168 E84 UBA T21 V44 F7 S11 UBA 135115 E84 UBA T21 V44 F7 S11 UBA 119103 1 UBA T21 V41 F7 S11 E81 UBA 119103 1 UBA T21 V41 F7 S11 E81 UBA 152182 E84 UBA T21 V41 F7 S11 E81 UBA 116225 E84 UBA T21 V82 F7 S08 303 UBA 156462 E84 UBA T21 V84 F7 S11 F7 S11 UBA 152188 911 UBA T21 V44 F7 S11 UBA 152188 911 UBA T21 V44 F7 S11 UBA 15218 E84 UBA T21 V44 F7 S11 UBA T21 V48 F7 S11 UBA UBA UBA T21 V48 F7 S11 UBA UBA T21 V48 F7 S11 UBA UBA UBA UBA UBA T21 V48 F7 S11 UBA UBA UBA UBA UBA UBA T21 V48 F7 S11 UBA UBA UBA UBA UBA UBA T21 V48 F7 S11 UBA UBA UBA UBA UBA T21 V48 F7 S11 UBA UBA UBA UBA UBA UBA T21 V44 UBA								en en
913 USA 155115 E64 USA T21 V44 F7 511 251 USA 113103 1 USA T21 V41 F7 S11 251 USA 152162 E64 USA T21 V41 F7 S11 809 USA 152162 E64 USA T21 V82 F7 S08 303 USA 155452 E64 USA T21 V44 F7 S11 F10 USA 152168 911 USA T21 V44 F7 S11 261 USA 152168 911 USA T21 V41 F7 S11 261 USA 15216 E64 USA T21 V41 F7 S11 361 USA 15216 E64 USA T21 V44 F7 S11 609 USA 15115 E64 USA T21 V44 F7 S11 609 USA T21 V44 F7 S11 609 USA 121215 1 USA T21 V44 F7 S11 509 USA 17462 1 USA T21 V44 F7 S11 509 USA 17462 1 USA T21 V44 F7 S11 600 USA 171040 E64 USA T21 V44 F7 S11 600 USA 171040 E64 USA T21 V44 F7 S11 600 USA 171040 E64 USA T21 V45 F7 S11 600 USA 171040 E64 USA T21 V46 F7 S11 600 USA 171040 E64 USA T21 V46 F7 S11 600 USA 171040 E64 USA T21 V46 F7 S11 600 USA 171040 E64 USA T21 V46 F7 S11 600 USA 171040 E64 USA T21 V46 F7 S11								-
USA 119103 1 USA T21 V41 F7 S11 251 USA 152152 E84 USA T21 V41 F7 S11 809 USA 116255 E84 USA T21 V82 F7 S09 303 USA 158462 E84 USA T21 V44 F7 S11 910 USA 152189 911 USA T21 V44 F7 S11 281 USA 152189 E84 USA T21 V41 F7 S11 381 USA 15218 E84 USA T21 V41 F7 S11 381 USA 15218 E84 USA T21 V44 F7 S11 809 USA 15315 E84 USA T21 V44 F7 S11 809 USA 113145 E84 USA T21 V44 F7 S11 809 USA 12121S 1 USA T21 V44 F7 S11 800 USA 12121S 1 USA T21 V44 F7 S11 800 USA 17482 1 USA T21 V44 F7 S11 406 USA 171040 E84 USA T21 V44 F7 S11 600 USA 171040 E84 USA T21 V44 F7 S11 600 USA 171040 E84 USA T21 V45 F7 S11 600 USA 172040 E84 USA T21 V48 F7 S11 600 USA 172040 E84 USA T21 V48 F7 S11 600 USA 172040 E84 USA T21 V48 F7 S11 600 USA 172040 E84 USA T21 V42 F7 S11								
281 U8A 152182 E84 USA 721 V41 F7 S11 809 U8A 116225 E84 USA 721 V82 F7 S09 303 U8A 156462 E84 USA 721 V44 F7 S11 B10 U8A 152189 911 U8A 721 V44 F7 S11 281 U8A 152130 E64 U8A 721 V41 F7 S11 381 U8A 16218 E84 U8A 721 V44 F7 S11 809 U8A 113145 E84 U8A 721 V44 F7 S11 866 U8A 12125 1 U8A 721 V44 F7 S11 866 U8A 12125 1 U8A 721 V44 F7 S11 866 U8A 12125 1 U8A 721 V44 F7 S11 866 U8A 17482 1 U8A 721 V44 F7 S11 860 U8A 171040 E84 U8A 721 V44 F7 S11 860 U8A 171040 E84 U8A 721 V42 F7 S11 860 U8A 171040 E84 U8A 721 V48 F7 S11 860 U8A 171040 E84 U8A 721 V48 F7 S11 860 U8A 1720 U8A 172040 E84 U8A 721 V48 F7 S11 860 U8A 172040 E84 U8A 721 V48 F7 S11 860 U8A 172040 E84 U8A 721 V48 F7 S11 860 U8A 172040 E84 U8A 721 V48 F7 S11 860 U8A 172040 E84 U8A 721 V42 F7 S11 860 U8A 172040 E84 U8A 721 V42 F7 S11 860 U8A								
809 USA 116225 E84 USA T21 V83 F7 S09 303 USA 15545Z E84 USA T29 V44 F7 S11 910 USA 152189 911 USA T21 V44 F7 S11 261 USA 152130 E64 USA T21 V41 F7 S11 361 USA 152130 E64 USA T21 V44 F7 S11 808 USA 15315 E84 USA T21 V44 F7 S11 808 USA T21 V44 F7 S11 806 USA T21 V45 F7 S11 806 USA T21 V48 F7 S11 807 USA T21 V48 F7 S11 807 USA T21 V48 F7 S11								
303 USA 15545Z E84 USA 177 V44 F7 S11 910 USA 162188 911 USA 721 V44 F7 S11 281 USA 152130 E64 USA 721 V41 F7 S11 381 USA 162118 E84 USA 721 V44 F7 S11 808 USA 113145 E64 USA 721 V44 F7 S11 866 USA 121218 1 USA 721 V44 F7 S11 508 USA 17482 1 USA 721 V44 F7 S11 406 USA 171040 E84 USA 721 V48 F7 S11 650 USA 162671 E64 USA 721 V48 F7 S11 650 USA 162671 E64 USA 721 V42 F7 S11 650 USA 123307 2 USA 721 V41 F7 S11								
### ### ### ### ### ### ### ### ### ##								
281 USA 152130 E64 USA T21 V41 F7 811 381 USA 162116 E84 USA T21 V44 F7 811 808 USA 113145 264 USA T21 V44 F7 811 886 USA 121218 1 USA T21 V44 F7 811 508 USA 17482 1 USA T21 V41 F7 811 406 USA 171040 E84 USA T21 V48 F7 811 680 USA 162671 E84 USA T21 V42 F7 811 818 USA 123307 2 USA 721 V41 F7 511								
381 U8A 162118 E84 U8A T21 V44 F7 S11 808 U8A 11\$145 E64 U8A T21 V44 F7 S11 886 U8A 121218 1 U8A T21 V44 F7 S11 508 U8A 17482 1 U8A T21 V41 F7 S11 406 U8A 171040 E84 U8A T21 V48 F7 S11 680 U8A 162671 E84 U8A T21 V42 F7 S11 680 U8A 123307 2 U8A 721 V41 F7 S11								
809 USA 11\$145 264 USA T21 V44 F7 \$11 866 USA 121218 1 USA T21 V44 F7 811 508 USA 17482 1 USA T21 V41 F7 811 406 USA 171040 E84 USA T21 V48 F7 811 680 USA 162671 E84 USA T21 V42 F7 911 62 818 USA 123307 2 USA 721 V41 F7 511							_	
866 USA 121218 1 USA T21 V44 F7 S11 508 USA 174482 1 USA T21 V41 F7 S11 406 USA 171040 E84 USA T21 V48 F7 S11 650 USA 162671 E84 USA T21 V42 F7 S11 65 318 USA 123307 2 USA 721 V41 F7 S11								
508 USA 174482 1 USA 721 V41 F7 S11 406 USA 171040 E84 USA 721 V48 F7 S11 680 USA 162671 E84 USA 721 V42 F7 S11 65 318 USA 123307 2 USA 721 V41 F7 S11								
406 USA 171040 E84 USA T21 V48 P7 S11 680 USA 162671 E84 USA T21 V42 F7 S11 62 816 USA 123307 2 USA 721 V41 F7 S11								
880 USA 162671 É84 USA T21 V42 F7 S11 🚱 818 USA 123307 2 USA 721 V41 F7 S11								
818 USA 123307 2 USA 721 V41 F7 511								
								-
					• • •	• •		•

336 USA

121734

1 USA

721

V42

F7

211

425 UEA	174006	1 USA	T21	V44	F7	811	
801 USA	123514 584	USA	T21	V41	F7	811	
281 USA	182084	1 USA	T21	V44	F7	B11	€
817 USA	147034 E84	V5A	T#I	V44	F7	211	•
936 USA	182181 E84	USA	T21	V44	77	811	
407 USA	124224 E84	USA	721	V44	F7	511	
970 USA	122124 #84	USA	121	V41	F7	Š11	
972 USA	152020	2 USA	T21	V44	F 7	\$11	
856 USA	152405 E84	USA	T21	V44	۴7	811	
281 USA	152055 E84	USA	T21	V44	F7	811	
965 V8A	123648	1 USA	121	V42	F7	811	
713 USA	152023 E84	USA	T21	V41	F7	811	•
417 USA	152152 E84	USA	T21	V44	F7	811	*
972 USA	152012 E64	USA	T21	V44	17	& 11	
513 USA	147004	1 UBA	T21	V43	F7	811	
770 USA	121444 E84	UBA	T21	V41	F7	811	4
908 USA	113058 E84	USA	T21	V42	F7	\$11	
812 USA	147580 E84	ABU	T21	V44	£ 7	811	
530 USA	172504	1 USA	T21	V44	F7	811	
408 USA	152636 272	USA	T21	V41	F7	811	•
945 USA	171074 E84	USA	T21	V44	P7	811	
270 USA	123219 E84	USA	T21	V44	P7	811	
810 USA	172016	1 USA	T21	V44	F7	\$11	
479 USA	123652 E84	USA	T21	V42	F7	811	•
502 USA	147022	1 UBA	T21	V42	F7	811	_
219 UBA	148438 E72	ARU	T21	V44	F7	811	
458 USA	156843	2 USA	**21	V41	F7	811	
863 UBA	124475 EB4	USA	T21	V44	F7	811	
828 USA	121211 E84	ABU	T21	V44	F7	811	
706 USA	121480 E84	UBA	T21	V41	F7	811	
706 USA	121480 £84	UBA	121	V41	P7	811	
281 USA	152054 £84	LISTA	T21	V44	F7	811	
50d USA	152100 EB4	ARU	T21	V44	27	811	
941 USA	121026 E84	UBA	T21	V41	PT	811	G
ARU	121222 \$64	USA	T21	V74	F7	509	-
281 USA	182054 E84	UBA	T21	V44	F7	811	
281 USA	152029 MB4	UŠA	T21	V41	P7	811	
281 USA	152717 E84	USA	T21	V44	F7	511	Œ
936 URA	152783	2 U8A	T21	V41	P7	811	
386 USA	124227 €84	USA	721	V44	F7	911	
805 UBA	171040	2 USA	T21	V41	F7	911	
713 USA	152032	2 UBA	T21	V41	F7	511	-
965 USA	123548	1 USA	T21	V44	F7	811	
972 USA	152002 E84	USA	T21	V44	F7	811	•
229 USA	124442	1 UBA	121	V42	P7	811	_
802 USA	171178 E72	UBA	T21	V41	F7	911	6
	11-4					•	_

...