

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 1 OF 6

BOOK 1 OF 43

Appendix J: Non-Confidential Documents

2001 Exped rr

ID	1
MDL_YR	2001
SORT_INDEX	2
TRANS_CD	TYPE
PLANT_CD	AP
PRODN_DT	10/14/2000
WRTY_START_D	8/7/2001
NAME	LINDSAY LINCOLN-MERCURY, INC.
DOC_NUM	701152
PH_NUM	4778201
WCC_CD	BRC2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	BAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/12/2001
TIS_WSD	3
CLM_KEY	4488042
MILGE	4721
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11520
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN

Tuesday, December 14, 2004

Page 1 of 442

Field27	b
CPSC_CD_6	11001
TECH_TXT1	VERIFIED REPLACED PASSENGER FRONT SEATBELT RECEPTICLE. VERIFIED REPAIR. BUCKLE NOT OPERATING PROPERLY. REQUEST M TIME BECAUSE OF NO LABOR OP
TECH_TXT2	
CUST_TXT	SEATBELT RECEPTICLE DOES NOT HOLD AT TIMES PASSENGER SIDE FRONT
AREA_CD	B12
COUNTRY_CD	USA
SLS_DLR_CD	348140
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	
VIN_CD	5LMFLJ28RX11
LBR_COST	11.70
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEL
DRIVE_CD	T/E
ENG_CD	TWC
Field450	

ID	2
MDL_YR	2001
SORT_INDEX	3
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	7/27/2001
NAME	COURTESY LINCOLN-MERCURY INC
DOC_NUM	11438504
PH_NUM	5477400
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	8AC
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	6
CLM_KEY	6027571
MILGE	8780
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11211
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Field27	b
CPSC_CD_6	11001

TECH_TXT1	1 NEC TO REPLACE SEAT BUCKLES
TECH_TXT2	
CUST_TXT	CS SEAT BELT BUCKLES NOT HOLDING
AREA_CD	718
COUNTRY_CD	USA
SLS_DLR_CD	314032
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VHT_CD	808
TIS_FLAG	
VIN_CD	5UMFLJ28R91L
LBR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
Field50	

ID	3
MDL_YR	2001
SORT_INDEX	21
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/14/2001
WRTY_START_D	5/22/2001
NAME	FORD MOTOR COMPANY (WHQ)
DOC_NUM	1835681
PH_NUM	*
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	33
RPR_DT	8/10/2001
TIS_WSD	4
CLM_KEY	4530748
MILGE	8858
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	86098
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACE PASS. SBLT. RELEASE
TECH_TXT2	
CUST_TXT	
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	364031
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	
VIN_CD	5LMFU2BR11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
Field50	

ID	4
MDL_YR	2001
SORT_INDEX	22
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	11/27/2001
NAME	KUMPF LINCOLN MERCURY, INC.
DOC_NUM	133706B
PH_NUM	7611580
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	8A8
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/14/2002
TIS_WSD	2
CLM_KEY	0520082
MILGE	4262
MTRL_COST	4632
TOT_COST_GRO	93.98
LBR_HRS	0.7
DLR_CD	11058
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACE BUCKLES
TECH_TXT2	
CUST_TXT	CUSTOMER STATES VEHICLE SEAT BELT LATCHES RELEASE BY THEM SELVS BOTH FRONT SEATS.
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	366115
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	
VIN_CD	5LMFL26R11[REDACTED]
LBR_COST	[REDACTED] 1400
VEH_LINE_CD	T1B4
MKT_DERIVED	*
BOD_CAB_STL	T1WD
VER_SERIES_C	T1EL
DRIVE_CD	T1E
ENG_CD	T1WC
Field50	

ID	5
MDL_YR	2001
SORT_INDEX	28
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	9/28/2000
WRTY_START_D	11/4/2000
NAME	FT LAUDERDALE L-M INC
DOC_NUM	232153B
PH_NUM	7792000
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	BAC
CUST_CONC_C	S25
COND_CD	42
RPR_DT	10/2/2001
TIS_WSD	12
CLM_KEY	4223881
MILGE	12013
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11827
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	12013 SAME REPLACE DRIVERS SEAT BELT BUCKLE RELEASES WHILE DRIVING JH
TECH_TXT2	
CUST_TXT	W40 S25 DRIVERS SEAT BELT RELEASES WHEN LOCKED
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	315309
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	
VIN_CD	5LMFU28A11
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
Field59	

ID	e
MDL_YR	2001
SORT_INDEX	28
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/1/2001
WRTY_START_D	10/3/2001
NAME	O. G. WELCH FORD LINCOLN-MERCU
DOC_NUM	7883151
PH_NUM	5243171
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/12/2001
TIS_WSD	3
CLM_KEY	5742183
MILGE	2876
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1018
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SC
Field27	c
CPSC_CD_6	12001

TECH_TXT1	REPLACE PASS FRONT SEATBELT
TECH_TXT2	
CUST_TXT	CHECK PASS SIDE COMES UNLATCHED
AREA_CD	B43
COUNTRY_CD	USA
SLS_DLR_CD	328223
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S06
TIS_FLAG	
VIN_CD	5LMEU27RX11 [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_C	T/EL
DRIVE_CD	T/B
ENG_CD	TWC
Field50	

ID	7
MDL_YR	2001
SORT_INDEX	37
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/16/2001
WRTY_START_D	9/1/2001
NAME	CERRITOS LINCOLN-MERCURY
DOC_NUM	9379001
PH_NUM	8953025
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/8/2001
TIS_WSD	1
CLM_KEY	3884482
MILGE	211
MTRL_COST	29.27
TOT_COST_GRO	20.22
LBR_HRS	25.8
DLR_CD	11907
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	FAULTY RT SIDE BUCKLE SEATBELT BUCKLE DOESNT HOLD.REPLACED PASS SIDE BUCKLE NO RECALL ON VEHICLE
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEAT BELT DOESNT HOLD PER OASIS NO OPEN CAMPAIGN BUT FAILED TEST
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	354015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	
VIN_CD	5LMEU27R51L
LRR_COST	80.56
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_C	T/E L
DRIVE_CD	T/B
ENG_CD	T/WC
Field50	

ID	8
MDL_YR	2001
SORT_INDEX	38
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	2/3/2001
NAME	VISTA LINCOLN-MERCURY
DOC_NUM	8236651
PH_NUM	3489500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/13/2002
TIS_WSD	13
CLM_KEY	7090481
MILGE	15713
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10095
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT1	CUST STATES RIGHT FRONT SEAT BELT FEMALE WILL NOT ALWAYS LOCK INTO CLIP
AREA_CD	B18
COUNTRY_CD	USA
SLS_DLR_CD	354280
TCN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S06
TIS_FLAG	
VIN_CD	8LMEU27R41 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_C	TEL
DRIVE_CD	T/B
ENG_CD	T/WC
Field50	

ID	9
MDL_YR	2001
SORT_INDEX	86
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	5/28/2001
NAME	LEIF JOHNSON FORD TRUCK CITY
DOC_NUM	54890802
PH_NUM	3120800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	5/1/2002
TIS_WSD	12
CLM_KEY	8378838
MILGE	13533
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4483
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	12001

TECH_TXT1	CHECK SEAT BELT LATCHES THEY FAILED SO REPLACED WITH NEW ONES TESTED OUT OK
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SAFETY BELT LATCH HAS RELEASED A FEW TIMES
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	152300
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	Q
VIN_CD	1FMRL17W51L
LBR_COST	40.08
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAF
DRIVE_CD	T/B
ENG_CD	TMN
Field50	

ID	10
MDL_YR	2001
SORT_INDEX	81
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	5/12/2001
NAME	JARRETT-BODIFORD FORD
DOC_NUM	7583602
PH_NUM	7624171
WCC_CD	5R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981202
PART_NUM_CA	AAA
CUST_CONC_C	526
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	7
CLM_KEY	8138907
MILGE	11008
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	481
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	
CPSC_CD_6	12001

TECH_TXT1	REPLACED SEAT BELT BUCKLE PER RECALL 01S21
TECH_TXT2	
CUST_TXT	CUSTOMER STATES R F SEAT BELT NOT HOLDING ADVISE
AREA_CD	813
COUNTRY_CD	USA
SLS_DLR_CD	124449
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	11
MDL_YR	2001
SORT_INDEX	82
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	7/18/2001
WRTY_START_D	8/18/2001
NAME	DUB MILLER FORD INC
DOC_NUM	7636402
PH_NUM	3425811
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	4/29/2002
TIS_WSD	9
CLM_KEY	8252075
MILGE	19279
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4480
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	12001

TECH_TXT1	1 REPL BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	CK FRONT SEAT BELT BUCKLES RELEASE WHILE DRIVING.
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152731
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	0
VIN_CD	1FMRUJ17W31L [REDACTED]
LBR_COST	54.18
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/ND
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	12
MDL_YR	2001
SORT_INDEX	70
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/24/2001
WRTY_START_D	7/28/2001
NAME	SAWGRASS FORD
DOC_NUM	36510503
PH_NUM	8519000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	9/8/2002
TIS_WSD	8
CLM_KEY	7343121
MILGE	11708
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4600
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	C
CPSC_CD_6	12001

TECH_TXT1	SEAT BELT INOP. WILL NOT SECURE REPLACE LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEAT WILL UNLATCH
AREA_CD	954
COUNTRY_CD	USA
SLS_DLR_CD	124009
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRJ17L81
LBR_COST	27.08
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
Field39	

ID	13
MDL_YR	2001
SORT_INDEX	81
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	5/9/2001
NAME	BILLINGSLEY FORD OF LAWTON, IN
DOC_NUM	104891A
PH_NUM	2482300
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	B40
COND_CD	42
RPR_DT	8/17/2001
TIS_WSD	4
CLM_KEY	3245757
MILGE	7384
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1771
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
Field27	c
CPSC_CD_6	12001

TECH_TXT1	CHECKED AND REPLACED BOTH PASS AND DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DIAG DRIVERS SEAT BELT BUCKLE COME UNDONE WHILE DRIVING AND CHECK ALL THE OTHER BELTS
AREA_CD	405
COUNTRY_CD	USA
SLS_DLR_CD	152603
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFQ_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17L81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
Field59	

ID	14
MDL_YR	2001
SORT_INDEX	86
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	6/28/2001
WRTY_START_D	9/9/2001
NAME	GALPIN FORD
DOC_NUM	68718551
PH_NUM	7879800
WCC_CD	BR02
PART_NUM_CA	1LTZ
PART_NUM_CA	7861202
PART_NUM_CA	AAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/16/2001
TIS_WSD	0
CLM_KEY	3525118
MILGE	14
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5698
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	12001

TECH_TXT1	REPLACE SEATBELTS WILL NOT LATCH PROPERLY
TECH_TXT2	
CUST_TXT	
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU17L41L
LBR_COST	9634
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T1B
ENG_CD	T1Z
Field50	

ID	15
MDL_YR	2001
SORT_INDEX	94
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/22/2001
WRTY_START_D	8/31/2001
NAME	OKC AUTO COLLECTION
DOC_NUM	229422A
PH_NUM	7526900
WCC_CD	6RD2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	7/30/2001
TIS_WSD	0
CLM_KEY	2903703
MILGE	5
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	3581
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
Field27	b
CPSC_CD_6	12001

TECH_TXT1	5 TESTED SEAT BELTS AND INSTALLED BOTH LEFT AND RIGHT SIDE SEAT BELT LATCHES R.L.B
TECH_TXT2	
CUST_TXT	825 SEATBELT WONT STAY LOCKED
AREA_CD	406
COUNTRY_CD	USA
SLS_DLR_CD	152208
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L21L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T8
ENG_CD	TN2
Field58	

ID	16
MDL_YR	2001
SORT_INDEX	96
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/4/2001
WRTY_START_D	7/24/2001
NAME	WESTWAY FORD
DOC_NUM	04675001
PH_NUM	0500333
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7361202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	1/24/2002
TIS_WSD	7
CLM_KEY	0478927
MILGE	10734
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2586
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	12001

TECH_TXT1	R&R RT FRONT SEAT. REPLACED SEAT BELT BUCKLE ASSY....
TECH_TXT2	
CUST_TXT	CUST SAYS RIGHT FRONT SEAT BELT DOES NOT HOLD AND COMES UNLATCHED
AREA_CD	072
COUNTRY_CD	USA
SLS_DLR_CD	152013
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17L1L [REDACTED]
LBR_COST	[REDACTED] 21.00
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAF
DRIVE_CD	T/B
ENG_CD	TN2
Field50	

ID	17
MDL_YR	2001
SORT_INDEX	107
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/7/2001
WRTY_START_D	10/7/2001
NAME	HALL FORD
DOC_NUM	280481A
PH_NUM	8896700
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	4520443
MILGE	7
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0042
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VA
Field27	a
CPSC_CD_6	12001

TECH_TXT1	PASSENGER SIDE SEATBELT WILL NOT HOLD, REMOVED PASSENGER FRONT SEAT TO ACCESS SEATBELT BUCKLE, REPLACED SEATBELT BUCKLE, NO LABOR OPS, USE M TIME
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEATBELT BUCKLE WILL NOT HOLD
AREA_CD	757
COUNTRY_CD	USA
SLS_DLR_CD	127000
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRJ18WX1L [REDACTED]
LBR_COST	[REDACTED] 43,001
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	T4N
Field58	

ID	18
MDL_YR	2001
SORT_INDEX	113
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	1/27/2001
NAME	OASIS FORD
DOC_NUM	81852
PH_NUM	5911111
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	2/8/2002
TIS_WSD	13
CLM_KEY	6887585
MILGE	15787
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3004
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
Field27	0
CPSC_CD_6	12001

TECH_TXT1	NOP REPLACE	SEATBELT ASSEMBLY R FRONT
TECH_TXT2		
CUST_TXT	CUS ST CK SEAT BELTS FT PASS DISCONNECTS WHILE DRIVING	
AREA_CD	732	
COUNTRY_CD	USA	
SLS_DLR_CD	112058	
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	908	
TIS_FLAG		
VIN_CD	1FMRU16W81L [REDACTED]	
LBR_COST	32.1	
VEH_LINE_CD	T83	
MKT_DERIVED	.	
BOD_CAB_STL	TWD	
VER_SERIES_C	TEF	
DRIVE_CD	TAE	
ENG_CD	TAV	
Field50		

ID	19
MDL_YR	2001
SORT_INDEX	115
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	2/15/2001
NAME	CHAPMAN FORD SALES
DOC_NUM	16683801
PH_NUM	9990261
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7991202
PART_NUM_CA	AAB
CUST_CONC_C	526
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	13
CLM_KEY	6992781
MILGE	13399
MTRL_COST	13399
TOT_COST_GRO	13399
LBR_HRS	6.4
DLR_CD	1402
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	DE
Field27	R
CPSC_CD_6	12001

TECH_TXT1	DOES NOT OPERATE PROPERLY REPLACE RT FRT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RT FRT SEAT BELT WILL NOT STAY BUCKLED
AREA_CD	302
COUNTRY_CD	USA
SLS_DLR_CD	18801L
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	306
TIS_FLAG	
VIN_CD	1FMRUJ16W71 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VRR_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/WN
Field59	

ID	20
MDL_YR	2001
SORT_INDEX	118
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/3/2001
NAME	KORUM FORD INC
DOC_NUM	34803901
PH_NUM	8628270
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAC
CUST_CONC_C	825
COND_CD	42
RPR_DT	1/2/2002
TIS_WSD	8
CLM_KEY	8267038
MILGE	5724
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8851
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Field27	C
CPSC_CD_6	12001

TECH_TXT1	TESTED ALL SEAT BELT BUCKLES BOTH FRONT FAILED TEST. ORDERED PRIORITY REPLACED BOTH FRONT SEAT BUCKELS, WITH NEW.
TECH_TXT2	
CUST_TXT	SEAT BELT COMING UNSNAPED CHECK AND ADVISE
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	174206
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	SD8
TIS_FLAG	
VIN_CD	1FMRU16W01L [REDACTED]
LBR_COST	[REDACTED] 41.58
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TND
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
Field30	

ID	21
MDL_YR	2001
SORT_INDEX	117
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	3/3/2001
WRTY_START_D	6/20/2001
NAME	GENE BLITMAN FORD SLS INC
DOC_NUM	2962401
PH_NUM	4828581
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7581202
PART_NUM_CA	AAC
CUST_CONC_C	B40
COND_CD	42
RPR_DT	10/29/2001
TIS_WSD	5
CLM_KEY	4714147
MILGE	7052
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2984
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	b
CPSC_CD_6	12001

TECH_TXT1	REPLACE RIGHT AND LEFT FRONT SEAT BELT BUCKLES PER OLD ONES WOULD NOT STAY LATCHED
TECH_TXT2	
CUST_TXT	THE SEAT BELT BUCKLE IS NOT STAYING LATCHED PARTS IN
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	148438
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W011 [REDACTED]
LBR_COST	[REDACTED] 48.00
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TW0
VER_SERIES_C	TIEF
DRIVE_CD	TE
ENG_CD	TVN
Field50	

ID	22
MDL_YR	2001
SORT_INDEX	126
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/31/2001
NAME	HARROLD FORD
DOC_NUM	228116C
PH_NUM	9221636
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAC
CUST_CONC_C	E26
COND_CD	42
RPR_DT	3/16/2002
TIS_WSD	7
CLM_KEY	7450871
MILGE	11515
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7882
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	0
CPSC_CD_6	12001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES
TECH_TXT2	
CUST_TXT	REPAIR FOR DRIVER SEAT BELT COMES UNDONE AT TIMES.INSTALL SOP.
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	172202
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	
VIN_CD	1FMRU16W11L [REDACTED]
LBR_COST	[REDACTED] 50.10
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
Field50	

ID	23
MDL_YR	2001
SORT_INDEX	133
TRANS_CD	TDL
PLANT_CD	AP
PRODN_DT	8/28/2001
WRTY_START_D	10/19/2001
NAME	AUDIBON FORD
DOC_NUM	183046A
PH_NUM	2938900
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7551202
PART_NUM_CA	AAB
CUST_CONC_C	T80
COND_CD	42
RPR_DT	10/22/2001
TIS_WSD	1
CLM_KEY	4725574
MILGE	372
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0621
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	C
CPSC_CD_6	12001

TECH_TXT1	372 RECALL 82 TESTED AND REPLACED BOTH FRONT SEATBELTS
TECH_TXT2	
CUST_TXT	CUST STATES WHILE DRIVING DRIVERS SEAT BELT CAME UNLATCHED BY ITSELF
AREA_CD	226
COUNTRY_CD	USA
SLS_DLR_CD	123203
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU16W91 [REDACTED]
LBR_COST	[REDACTED] 15,47
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	24
MDL_YR	2001
SORT_INDEX	139
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	8/30/2001
NAME	MCAULEY FORD-MERCURY
DOC_NUM	799201
PH_NUM	8823341
WCC_CD	6F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	7
CLM_KEY	7209766
MILGE	9421
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	827
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	12001

TECH_TXT1	VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED NEW BUCKLE & RE CK OK
TECH_TXT2	
CUST_TXT	RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK
AREA_CD	209
COUNTRY_CD	USA
SLS_DLR_CD	172614
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15W81 [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	25
MDL_YR	2001
SORT_INDEX	149
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/18/2000
WRTY_START_D	11/8/2000
NAME	GREENWAY FORD, INC.
DOC_NUM	8682752
PH_NUM	2753200
WCC_CD	8R02
PART_NUM_CA	1L72
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	T90
COND_CD	42
RPR_DT	1/18/2002
TIS_WSD	15
CLM_KEY	5485458
MILGE	28276
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4822
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	12001

TECH_TXT1	INOP REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	CUSTOMER STATES THAT AFTER THE SEAT BELT RECALL WAS DONE THE PASS FRONT SEAT BELT POPS OFF	
AREA_CD	407	
COUNTRY_CD	USA	
SLS_DLR_CD	124213	
TXN_CD	EB4	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V74	
AWS_VL_CD	83	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMRU16WB1L	
LBR_COST		225.30
VEH_LINE_CD	T/BS	
MKT_DERIVED	*	
BOD_CAB_STL	T/WD	
VRR_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/VN	
Field59		

ID	26
MDL_YR	2001
SORT_INDEX	155
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/23/2000
WRTY_START_D	11/7/2000
NAME	TOWN EAST FORD
DOC_NUM	793098A
PH_NUM	2700441
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	788-1202
PART_NUM_CA	AAB
CUST_CONC_C	525
COND_CD	42
RPR_DT	4/15/2002
TIS_WSD	18
CLM_KEY	5197893
MILGE	32891
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8182
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	12001

TECH_TXT1	32881 VERIFIED CUSTOMER CONCERN BOTH FRT SEAT BELT BIKLES INOP REPLACED BOTH FRT BUCKLES
TECH_TXT2	
CUST_TXT	BOTH FT SEAT BELTS UNBUCKLE WHILE DRIVING
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	171206
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	S05
TIS_FLAG	Ⓢ
VIN_CD	1FMRU15W71L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T/B
ENG_CD	TMN
Field50	

ID	27
MDL_YR	2001
SORT_INDEX	196
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	9/22/2000
WRTY_START_D	11/30/2000
NAME	ANDERSON BROS FORD L-M
DOC_NUM	053833A
PH_NUM	3841700
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	
PART_NUM_CA	AAC
CUST_CONC_C	S28
COND_CD	42
RPR_DT	1/16/2002
TIS_WSD	14
CLM_KEY	8434420
MILGE	44788
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7148
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NE
Field27	a
CPSC_CD_6	11001

TECH_TXT1	44788 REMOVE AND INSTALL SEATBELT ON PASSENGER SIDE
TECH_TXT2	
CUST_TXT	RT FT SEATBELT WONT HOLD IN BUCKLE ASY
AREA_CD	308
COUNTRY_CD	USA
SLS_DLR_CD	141078
TXN_CD	E61
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU15W71L [REDACTED]
LBR_COST	[REDACTED] 2187
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TAND
VER_SERIES_C	TEF
DRIVE_CD	TB
ENG_CD	TMN
Field59	

ID	28
MDL_YR	2001
SORT_INDEX	181
TRANS_CD	T00
PLANT_CD	AP
PRODN_DT	11/1/2000
WRTY_START_D	2/18/2001
NAME	ERNE HAIRE FORD, INC.
DOC_NUM	8585051
PH_NUM	8338571
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/6/2001
TIS_WSD	10
CLM_KEY	5670787
MILGE	21000
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4999
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	12001

TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	C/S PASSENGER SEAT BELT COMES UNLATCHED WHILE DRIVING , INSTALL SOP BELT ASSY HAS OPEN 01821 RECALL
AREA_CD	B13
COUNTRY_CD	USA
SLS_DLR_CD	124208
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W41 [REDACTED]
LRR_COST	[REDACTED]
VBH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	28
MDL_YR	2001
SORT_INDEX	182
TRANS_CD	TIDU
PLANT_CD	AP
PRODN_DT	09/6/2000
WRTY_START_D	3/10/2001
NAME	CROWN FORD
DOC_NUM	388051
PH_NUM	8871121
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7081202
PART_NUM_CA	AAS
CUST_CONC_C	S40
COND_CD	42
RPR_DT	4/6/2002
TIS_WSD	14
CLM_KEY	8008805
MILGE	33704
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3824
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Field27	b
CPSC_CD_6	12001

TECH_TXT1	SEAT BELT LATCH	REPLACED SEAT BELT LATCH
TECH_TXT2		
CUST_TXT	PASSENGER SEATBELT WILL NOT LATCH (PARTS IN)	
AREA_CD	910	
COUNTRY_CD	USA	
SLS_DLR_CD	121028	
TXN_CD	EM4	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	B08	
TIS_FLAG	@	
VIN_CD	1FMRU16W41L	
LBR_COST		
VEH_LINE_CD	TB3	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	TEF	
DRIVE_CD	TB	
ENG_CD	TVN	
Field50		

ID	30
MDL_YR	2001
SORT_INDEX	190
TRANS_CD	T0U
PLANT_CD	AP
PRODN_DT	5/25/2001
WRTY_START_D	7/28/2001
NAME	COVERT FORD, INC.
DOC_NUM	1140201
PH_NUM	3464343
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	
PART_NUM_CA	AAC
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/30/2002
TIS_WSD	7
CLM_KEY	6887906
MILGE	12718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4437
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	DEFECTIVE REPLACED RH BUCKLE
TECH_TXT2	
CUST_TXT	R F SEAT BELT COMES LOOSE DRIVING
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	152302
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	31
MDL_YR	2001
SORT_INDEX	200
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	12/17/2000
WRTY_START_D	2/7/2001
NAME	TED RUSSELL FORD INC
DOC_NUM	32000201
PH_NUM	.
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001202
PART_NUM_CA	AAB
CUST_CONC_C	820
COND_CD	42
RPR_DT	4/1/2002
TTS_WSD	14
CLM_KEY	7700010
MILGE	12300
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3795
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	TN
Field27	0
CPSC_CD_6	12001

TECH_TXT1	REPLACE SEAT BELT ASSY
TECH_TXT2	
CUST_TXT	CUJST STATES PASS SIDE SEAT BELT IS POPPING LOOSE WHEN IN USE
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	121218
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W11 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	32
MDL_YR	2001
SORT_INDEX	214
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	5/10/2001
WRTY_START_D	7/30/2001
NAME	WOODY ANDERSON FORD
DOC_NUM	8741351
PH_NUM	5329441
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/6/2001
TIS_WSD	5
CLM_KEY	5928712
MILGE	2800
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6822
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AL
Field27	c
CPSC_CD_6	12001

TECH_TXT1	RECALL INSPECT PER RECALL, R+R RT. FT. SEAT REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES PASS FRONT SEAT BELT WILL NOT STAY LATCHED UNBUCKLES WHEN DRIVING DOWN THE ROAD AND LEFT
AREA_CD	256
COUNTRY_CD	USA
SLS_DLR_CD	121717
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W01 [REDACTED]
LBR_COST	[REDACTED] 24.32
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VEH_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/WN
Field58	

ID	33
MDL_YR	2001
SORT_INDEX	225
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	7/25/2001
NAME	NICHOLS FORD
DOC_NUM	20340801
PH_NUM	6363673
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAB
CUST_CONC_C	540
COND_CD	42
RPR_DT	7/19/2001
TIS_WSD	0
CLM_KEY	2857739
MILGE	2
MTRL_COST	10727
TOT_COST_GRO	10727
LBR_HRS	214
DLR_CD	2611
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	12001

TECH_TXT1	REPLACE RIGHT SIDE BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT RIGHT SIDE BELT WILL NOT HOLD REPLACE RIGHT SIDE BELT
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152008
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	83
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15L710
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAF
DRIVE_CD	TB
ENG_CD	TNZ
Field50	

ID	84
MDL_YR	2001
SORT_INDEX	234
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/4/2001
WRTY_START_D	8/8/2001
NAME	EL CAJON FORD
DOC_NUM	6289851
PH_NUM	6796886
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/20/2001
TIS_WSD	1
CLM_KEY	3123905
MILGE	1283
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5458
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	12001

TECH_TXT1	BUCKLE REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	CUST STATES RT FRONT SEAT BELT WILL NOT STAY LATCHED COMES LOOSE	
AREA_CD	819	
COUNTRY_CD	USA	
SLS_DLR_CD	171078	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B3	
VRT_CD	B08	
TIS_FLAG		
VIN_CD	1FMRU19L411	
LBR_COST		28.00
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAR_STL	TWD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/NZ	
Field56		

ID	35
MDL_YR	2001
SORT_INDEX	238
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	8/29/2001
NAME	SUNSET ALITO CO INC
DOC_NUM	25887801
PH_NUM	8434431
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/11/2001
TIS_WSD	1
CLM_KEY	5018805
MILGE	12
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	a
CPSC_CD_6	12001

TECH_TXT1	REPLACED BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT BUCKLES WILL NOT HOLD
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	153082
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	4FMPU18LX1L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T1EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field58	

ID	36
MDL_YR	2001
SORT_INDEX	240
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/26/2001
WRTY_START_D	10/10/2001
NAME	SUNSET AUTO CO INC
DOC_NUM	26484001
PH_NUM	8434431
WCC_CD	BR02
PART_NUM_CA	1172
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/20/2001
TLS_WSD	0
CLM_KEY	4253351
MILGE	12
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8198
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Field27	
CPSC_CD_6	12001

TECH_TXT1	REPLACED BOTH SEATBELTS
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT HOLD BACK
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	153164
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	
VIN_CD	1FMPU18LX1L [REDACTED]
LBR_COST	48.22
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	37
MDL_YR	2001
SORT_INDEX	245
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/10/2001
WRTY_START_D	6/31/2001
NAME	JERRYS FORD SALES INC
DOC_NUM	25805201
PH_NUM	2685000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	4/23/2002
TIS_WSD	8
CLM_KEY	01B2004
MILGE	5857
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	135
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VA
Field27	c
CPSC_CD_6	12001

TECH_TXT1	DIAGNOSE AND REPLACE FRONT SEAT BELT BUCKLE, RETEST O.K.
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE (NOP, SOP IN PASS FRONT SEAT BELT BUCKLE RELEASES BY ITSELF
AREA_CD	703
COUNTRY_CD	USA
SLS_DLR_CD	127012
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPU18L81L
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	T/CF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	38
MDL_YR	2001
SORT_INDEX	250
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/15/2001
WRTY_START_D	8/21/2001
NAME	CRANDALL FORD, INC.
DOC_NUM	3542001
PH_NUM	2983523
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	2/2/2002
TIS_WSD	8
CLM_KEY	8882784
MILGE	8882
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2350
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Field27	c
CPSC_CD_6	12001

TECH_TXT1	REPLACED BOTH FRT SEAT BELT BUCKLES CHECKED OPERATION OK
TECH_TXT2	
CUST_TXT	DRIVERS SEATBELT COMES UNDONE REPLACE BOTH FRONT
AREA_CD	216
COUNTRY_CD	USA
SLS_DLR_CD	144043
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L81L [REDACTED]
LBR_COST	[REDACTED] 30.83
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	39
MDL_YR	2001
SORT_INDEX	260
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	6/29/2001
NAME	BANKSTON L-M, INC.
DOC_NUM	3523701
PH_NUM	2331441
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7061202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	2/18/2002
TIS_WSD	8
CLM_KEY	0858175
MILGE	9837
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1356B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	12001

TECH_TXT1	CHECKED BOTH FRONT SEAT BELT OPP FOUND THAT AT TIMES WHEN SEAT BELTS ARE PULLED HARD BUCKLES WILL INT RELEASE
TECH_TXT2	
CUST_TXT	FRONT SEAT BELTS WILL NOT STAY ATTACHED
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152012
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L51L
LBR_COST	21.00
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	TN2
Field50	

ID	40
MDL_YR	2001
SORT_INDEX	281
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/23/2000
WRTY_START_D	11/9/2000
NAME	DON SANDERSON FORD, INC.
DOC_NUM	88056101
PH_NUM	8428500
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	BAA
CUST_CONC_C	S20
COND_CD	
RPR_DT	5/2/2002
TYS_WSD	18
CLM_KEY	8459798
MILGE	17148
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	20301
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECK FOR CONCERN REPLACE DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT BUCKLE RED KNOB WILL NOT COME ALL THE WAY OUT AT TIMES, AND THE SEAT BELT WILL NOT STAY IN BUCKLE
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	171171
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	Ⓢ
VIN_CD	1FMPLH8LJ1 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T8F
DRIVE_CD	TE
ENG_CD	TNZ
Field50	

ID	41
MDL_YR	2001
SORT_INDEX	288
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	9/28/2001
NAME	PETERSON FORD-MERCURY
DOC_NUM	886332
PH_NUM	8462826
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	BAB
CUST_CONC_C	S26
COND_CD	42
RPR_DT	7/20/2001
TIS_WSD	0
CLM_KEY	3557837
MILGE	4
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6291
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACED BOTH FRONT SEAT BELT BUCKLES THAT DO NOT HOLD.
TECH_TXT2	
CUST_TXT	BOTH FRONT SEATBELT BUCKLES DONT HOLD
AREA_CD	020
COUNTRY_CD	USA
SLS_DLR_CD	141837
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	008
TIS_FLAG	
VIN_CD	1FMPU18L31L
LBR_COST	30297
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAR_STL	TVA
VER_SERIES_C	TIEF
DRIVE_CD	TE
ENG_CD	TNZ
Field50	

ID	42
MDL_YR	2001
SORT_INDEX	288
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/20/2000
WRTY_START_D	8/20/2001
NAME	LANDMARK FORD, INC.
DOC_NUM	10780702
PH_NUM	8825200
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	41
RPR_DT	4/25/2002
TIS_WSD	9
CLM_KEY	8282620
MILGE	18074
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8007
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
Field27	c
CPSC_CD_6	12001

TECH_TXT1	REPLACE RT FRT BUCKLE INOP
TECH_TXT2	
CUST_TXT	PSSGR FRT SEATBELT COMES UNLATCHED PARTS ORDERED ONE MONTH AGO
AREA_CD	217
COUNTRY_CD	USA
SLS_DLR_CD	141105
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	83
VRT_CD	808
FIS_FLAG	@
VIN_CD	1FMPU10L31
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VZ
Field50	

ID	43
MDL_YR	2001
SORT_INDEX	271
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/8/2001
WRTY_START_D	8/24/2001
NAME	LITHIA FORD OF FRESNO
DOC_NUM	119844A
PH_NUM	4358400
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	9/27/2001
TIS_WSD	1
CLM_KEY	3892014
MILGE	417
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2811
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INSTALLED PASS SIDE SEAT BELT BUCKLE AS CUST REQUESTED
TECH_TXT2	
CUST_TXT	CJST. STATES SEAT BUCKLE PASS FRONT CAME APART.
AREA_CD	559
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VRR_SERIES_C	TIE
DRIVE_CD	TIE
ENG_CD	TNZ
Field56	

ID	44
MDL_YR	2001
SORT_INDEX	278
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	11/2/2001
NAME	FOX LAKE FORD MERCURY, INC.
DOC_NUM	800701
PH_NUM	6873400
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/9/2002
TIS_WSD	3
CLM_KEY	6167834
MILGE	3847
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1552
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IL
Field27	c
CPSC_CD_6	12001

TECH_TXT1	INSPECT, REPLACE DRIVERS SIDE AND PASSENGER SIDE FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNBUCKLED
AREA_CD	847
COUNTRY_CD	USA
SLS_DLR_CD	141415
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU16LX1U [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	TVZ
Field58	

ID	45
MDL_YR	2001
SORT_INDEX	280
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/3/2001
NAME	SIGNATURE LINCOLN-MERCURY
DOC_NUM	1812151
PH_NUM	4570321
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	
PART_NUM_CA	AAC
CUST_CONC_C	S40
COND_CD	33
RPR_DT	11/21/2001
TIS_WSD	7
CLM_KEY	5217826
MILGE	10133
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12788
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NV
Field27	b
CPSC_CD_6	11001

TECH_TXT1	RECALL	DONE PER RECALL
TECH_TXT2		
CUST_TXT	PASS SEAT BELT WONT STAY LATCHED	SOPART HERE
AREA_CD	702	
COUNTRY_CD	USA	
SLS_DLR_CD	183000	
TXN_CD	2	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B5	
VRT_CD	S08	
TIS_FLAG		
VIN_CD	1FMPU18LX11	
LBR_COST		
VEH_LINE_CD	T7B3	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/E	
ENG_CD	TVZ	
Field50		

ID	4B
MDL_YR	2001
SORT_INDEX	281
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/11/2001
WRTY_START_D	3/31/2001
NAME	INVER GROVE FORD
DOC_NUM	29848001
PH_NUM	4512201
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAB
CUST_CONC_C	828
COND_CD	42
RPR_DT	1/31/2002
TIS_WSD	11
CLM_KEY	8815850
MILGE	16582
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8170
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Field27	c
CPSC_CD_6	12001

TECH_TXT1	INSTALLED SO SEAT BELT BUCKLE. RETESTED OK.
TECH_TXT2	
CUST_TXT	CUST STATED THE DR SIDE BUCKLE WILL RELEASE SEAT BELT AT TIMES, INSTALL SOP 1L7Z.7681202.AAB
AREA_CD	651
COUNTRY_CD	USA
SLS_DLR_CD	150485
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	
VIN_CD	1FMPU16LX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VZ
Field50	

ID	47
MDL_YR	2001
SORT_INDEX	285
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/7/2001
NAME	HERTZ RAC - COLUMBIA
DOC_NUM	54459401
PH_NUM	*
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	4/4/2002
TIS_WSD	12
CLM_KEY	8208209
MILGE	23053
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	45278
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SC
Field27	8
CPSC_CD_6	12001

TECH_TXT1	REPLACED THE BUCKLE ASSY
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT BUCKLES WONT HOLD
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	116802
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	Ⓢ
VIN_CD	1FMPU18L91L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T183
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	TN2
Field50	

ID	40
MDL_YR	2001
SORT_INDEX	291
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/7/2001
WRTY_START_D	2/2/2001
NAME	DENISON FORD INC
DOC_NUM	22075501
PH_NUM	8831331
WCC_CD	BF02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AA8
CUST_CONG_C	S40
COND_CD	42
RPR_DT	1/18/2002
TIS_WSD	12
CLM_KEY	6385010
MILGE	33441
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20148
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	L
Field27	b
CPSC_CD_6	12001

TECH_TXT1	CONFIRMED CUSTOMERS CONCERN REPLACED RIGHT FRONT SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT DOES NOT STAY LATCHED PARTS ARE IN
AREA_CD	308
COUNTRY_CD	USA
SLS_DLR_CD	141448
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMPU16L71L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field58	

ID	40
MDL_YR	2001
SORT_INDEX	283
TRANS_CD	TRDE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	5/2/2001
NAME	BERGE FORD
DOC_NUM	18268701
PH_NUM	4971111
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881282
PART_NUM_CA	AAA
CUST_CONC_C	928
COND_CD	42
RPR_DT	3/15/2002
TIS_WSD	11
CLM_KEY	7457704
MILGE	4185
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20305
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
Field27	C
CPSC_CD_6	12001

TECH_TXT1	VERIFIED R F BUCKLE COMES UNBUCKLED BY ITSELF CCC S26 REPLACED RIGHT FRONT BUCKLE, GOOD.
TECH_TXT2	
CUST_TXT	CUST STS PASS FT SEAT BELT COMES UNBUCKLED BT ITSELF
AREA_CD	480
COUNTRY_CD	USA
SLS_DLR_CD	171227
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPU16L81
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	60
MDL_YR	2001
SORT_INDEX	287
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/19/2000
WRTY_START_D	1/5/2001
NAME	FOLSOM LAKE FORD INC
DOC_NUM	32871402
PH_NUM	3532000
WCC_CD	8F832
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	3/2/2002
TIS_WSD	15
CLM_KEY	7271571
MILGE	21541
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7727
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	12001

TECH_TXT1	REPLACE SEAT BELT
TECH_TXT2	
CUST_TXT	CS FRT PASS SEAT BELT UNLATCHES BY ITSELF
AREA_CD	918
COUNTRY_CD	USA
SLS_DLR_CD	171227
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU16L41L
LRR_COST	42.88
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TAWD
VER_SERIES_C	T8F
DRIVE_CD	T/E
ENG_CD	TN2
Field50	

ID	51
MDL_YR	2001
SORT_INDEX	307
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/10/2001
NAME	SIGNATURE LINCOLN-MERCURY
DOC_NUM	1636351
PH_NUM	4570321
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	
PART_NUM_CA	AAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/28/2001
TIS_WSD	7
CLM_KEY	6413162
MILGE	7081
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12738
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NV
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSTALL SOP
TECH_TXT2	
CUST_TXT	PASS SEAT BELT WONT STAY LATCHED SOPART HERE
AREA_CD	702
COUNTRY_CD	USA
SLS_DLR_CD	183000
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMPU16L21
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field59	

ID	62
MDL_YR	2001
SORT_INDEX	308
TRANS_CD	T0E
PLANT_CD	AP
PRODN_DT	3/26/2001
WRTY_START_D	7/28/2001
NAME	KING CHARLIE HILLARD FORD
DOC_NUM	21258801
PH_NUM	3705000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/20/2002
TIS_WSD	7
CLM_KEY	7018919
MLGE	6883
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	247B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	12001

TECH_TXT1	CONFIRMED CONCERN. FOUND PASS. SEAT BELT BUCKLE COMING LOOSE INTERNALLY. R&I PASSENGER SEAT TO REPL. BELT MO 8893
TECH_TXT2	
CUST_TXT	S28 CUSTOMER SAID PASS FRT SEAT BELT BUCKLE RATTLES WHILE DRIVING ON HIGHWAY
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152010
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L211
LBR_COST	88.6
VEH_LINE_CD	T/63
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	63
MDL_YR	2001
SORT_INDEX	311
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/25/2001
WRTY_START_D	7/11/2001
NAME	PURVIS FORD, INC.
DOC_NUM	087987A
PH_NUM	8883000
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAC
CUST_CONC_C	S25
COND_CD	42
RPR_DT	10/1/2001
TIS_WSD	3
CLM_KEY	4132352
MILGE	4
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	81
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
Field27	c
CPSC_CD_6	12001

TECH_TXT1	SEAT BELT BUCKLES CUSTOMER SAYS BOTH FRONT KEEP COMING UNBUCKLED VERIFY R&R LEFT FRONT AND RIGHT FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLES CUSTOMER SAYS BOTH FRONT KEEP COMING UNBUCKLED
AREA_CD	540
COUNTRY_CD	USA
SLS_DLR_CD	127440
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TTS_FLAG	
VIN_CD	1FMPU16L11L [REDACTED]
LBR_COST	[REDACTED] 38,200
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VRR_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	54
MDL_YR	2001
SORT_INDEX	312
TRANS_CD	TRDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/3/2001
NAME	HERTZ RAC - DENVER
DOC_NUM	44713701
PH_NUM	*
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/1/2001
TIS_WSD	7
CLM_KEY	6006028
MILGE	18503
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	45248
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	"
CPSC_CD_6	12001

TECH_TXT1	REPLACED THE BELT
TECH_TXT2	
CUST_TXT	CHECK FRONT SEATBELT BUCKLES WONT HOLD
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	156823
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPU16L11L
LRR_COST	
VEH_LINE_CD	T813
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T7EF
DRIVE_CD	T7E
ENG_CD	TWZ
Field50	

ID	65
MDL_YR	2001
SORT_INDEX	313
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/15/2001
NAME	SUNTRUP FORD - KIRKWOOD
DOC_NUM	094124A
PH_NUM	8228300
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/16/2001
TIS_WSD	3
CLM_KEY	3083860
MILGE	1090
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2722
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Field27	a
CPSC_CD_6	12001

TECH_TXT1	REPLACED BOTH SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	OWNER STATES DRIVER SEATBELT NOT HOLDING
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	153052
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU1BL11L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	TTF
DRIVE_CD	TIE
ENG_CD	TN2
Field50	

ID	58
MDL_YR	2001
SORT_INDEX	318
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	6/8/2001
WRTY_START_D	7/9/2001
NAME	RAABE MOTOR SALES, INC.
DOC_NUM	043378A
PH_NUM	8820055
WCC_CD	6R02
PART_NUM_CA	1LTZ
PART_NUM_CA	7881202
PART_NUM_CA	AAC
CUST_CONG_C	840
COND_CD	42
RPR_DT	7/28/2001
TIS_WSD	1
CLM_KEY	2850818
MILGE	570
MTRL_COST	10.57
TOT_COST_GRO	10.22
LBR_HRS	10.22
DLR_CD	2188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Field27	a
CPSC_CD_6	12001

TECH_TXT1	BUCKLE COMES LOOSE, REPLACE
TECH_TXT2	
CUST_TXT	PASSENGER SEAT BELT DOES NOT HOLD
AREA_CD	418
COUNTRY_CD	USA
SLS_DLR_CD	148078
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPU18L01 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NZ
Field59	

ID	57
MDL_YR	2001
SORT_INDEX	318
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	2/8/2001
NAME	GRAND PRAIRIE FORD, INC.
DOC_NUM	0882204
PH_NUM	6411334
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/22/2002
TIS_WSD	12
CLM_KEY	6570226
MILGE	18508
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2408
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	G
CPSC_CD_6	12001

TECH_TXT1	MO 16808 CC 42 61202 VERIFIED CUSTOMER CONCERN. REPLACED PASSENGER FRONT SEAT BELT BUCKLE. BUCKET SEATS, REMOVE SEAT TO ACCESS
TECH_TXT2	
CUST_TXT	840 CUSTOMER STATES RT FT SEAT BELT BUCKLE RELEASES WHILE DRIVING
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	168623
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPU16L01 [REDACTED]
LBR_COST	[REDACTED] 27
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field59	

ID	58
MDL_YR	2001
SORT_INDEX	323
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/2/2001
WRTY_START_D	3/31/2001
NAME	PHIL LONG FORD OF DENVER, LLC
DOC_NUM	51414603
PH_NUM	U323673
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	525
COND_CD	41
RPR_DT	11/8/2001
TIS_WSD	8
CLM_KEY	5128533
MILGE	10734
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3130
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	*
CPSC_CD_6	12001

TECH_TXT1	REPLACED SEAT BELT BUCKLE AND RETESTED.4837
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE PASSENGER FRONT SEAT BELT DOES NOT LOCK PROPERLY. STATES WILL COME UNBUCKLED AT TIMES.
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	158002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMFU18LX1L [REDACTED]
LBR_COST	[REDACTED] 28.6
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	TEF
DRIVE_CD	TIE
ENG_CD	TNZ
Field59	

ID	58
MDL_YR	2001
SORT_INDEX	325
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	10/1/2001
NAME	SUNSET AUTO CO INC
DOC_NUM	25484101
PH_NUM	8434431
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/20/2001
TIS_WSD	0
CLM_KEY	4253360
MILGE	12
MTRL_COST	5.534632
TOT_COST_GRO	92.54
LBR_HRS	10.32
DLR_CD	8198
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	4
CPSC_CD_6	12001

TECH_TXT1	REPLACED BOTH SEATBELTS
TECH_TXT2	
CUST_TXT	SEATBELT WILL NOT HOLD IN LOCK
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	153062
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	005
TIS_FLAG	
VIN_CD	1FMEU18L01
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	T/VZ
Field58	

ID	60
MDL_YR	2001
SORT_INDEX	336
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/17/2001
WRTY_START_D	1/25/2001
NAME	SHEEHY FORD MERCURY
DOC_NUM	10289501
PH_NUM	7084761
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7081202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	11/28/2001
TIS_WSD	11
CLM_KEY	5484501
MILGE	18122
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4224
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VA
Field27	b
CPSC_CD_6	12001

TECH_TXT1	REPLACE PASS. SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT ON PASS. SIDE COMES UNBUCKLED RECALL??
AREA_CD	804
COUNTRY_CD	USA
SLS_DLR_CD	127072
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMFU18L71L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/A
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ
Field50	

ID	61
MDL_YR	2001
SORT_INDEX	348
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	10/1/2001
NAME	MOCKS FORD SALES
DOC_NUM	187484B
PH_NUM	4788898
WCC_CD	*
PART_NUM_CA	*
PART_NUM_CA	
PART_NUM_CA	*
CUST_CONC_C	T90
COND_CD	41
RPR_DT	10/8/2001
TIS_WSD	1
CLM_KEY	4857238
MILGE	6679
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7774
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OR
Field27	*
CPSC_CD_6	

TECH_TXT1	REMOVED SEAT BELT BUCKEL AND REPAIR TO WORK PROPERLY
TECH_TXT2	
CUST_TXT	REPAIR CENTER SEAT BUCKLE WONT LATCH CODE T90
AREA_CD	541
COUNTRY_CD	USA
SLS_DLR_CD	172422
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	
VFG_CD	V74
AWS_VL_CD	98
VRT_CD	808
TIS_FLAG	Ⓢ
VIN_CD	1FMFU18L21L [REDACTED]
LBR_COST	[REDACTED] 12.00
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	T7F
DRIVE_CD	T7E
ENG_CD	T7Z
Field59	

ID	82
MDL_YR	2001
SORT_INDEX	381
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/15/2001
WRTY_START_D	6/28/2001
NAME	DARCARR FORD
DOC_NUM	18355201
PH_NUM	4581100
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	6
CLM_KEY	5881135
MILGE	4903
MTRL_COST	3632
TOT_COST_GRO	6047
LBR_HRS	208
DLR_CD	143
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MD
Field27	c
CPSC_CD_6	12001

TECH_TXT1	REPLACE BOTH SEATBELTS,INOPWERATIVE COMPONENT.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS FRONT SEATBELT KEEPS COMING A LOOSE WAS INSPECT FOR RECALL
AREA_CD	301
COUNTRY_CD	USA
SLS_DLR_CD	127021
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S00
TIS_FLAG	
VIN_CD	1FMFJ18LX1L
LBR_COST	8950
VEH_LINE_CD	T/B8
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	TN2
Field50	

ID	63
MDL_YR	2001
SORT_INDEX	362
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	10/27/2001
NAME	ED KENLEY FORD INC
DOC_NUM	8748331
PH_NUM	7784281
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AA8
CUST_CONC_C	840
COND_CD	42
RPR_DT	3/29/2002
TIS_WSD	6
CLM_KEY	7818050
MILGE	1801
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	837B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	UT
Field27	c
CPSC_CD_6	12801

Tuesday, December 14, 2004

Page 125 of 442

RQ04-011 E 0125

TECH_TXT1	R & R RF SEAT AND REPLACED SEAT BUCKLE DUE TO NO LOCK
TECH_TXT2	
CUST_TXT	RF SEAT BELT BUCKLE POPS LOOSE
AREA_CD	801
COUNTRY_CD	USA
SLS_DLR_CD	155558
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	508
YIS_FLAG	
VIN_CD	1FMFL18L81L [REDACTED]
LBR_COST	[REDACTED] 24.02
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	T7WD
VRR_SERIES_C	T7EF
DRIVE_CD	T7E
ENG_CD	T7Z
Field56	

ID	64
MDL_YR	2001
SORT_INDEX	353
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	4/2/2001
NAME	NORTHTOWN FORD INC
DOC_NUM	9418501
PH_NUM	8778441
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981202
PART_NUM_CA	AAB
CUST_CONC_C	S2H
COND_CD	42
RPR_DT	4/28/2002
TIS_WSD	13
CLM_KEY	8491109
MILGE	46267
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	8107
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	L
Field27	a
CPSC_CD_6	12001

TECH_TXT1	REPLACE 2 SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	RT FRT SEAT BELT WONT LATCH INTO BUCKLE MIDDLE SEAT BELT CAME APART
AREA_CD	217
COUNTRY_CD	USA
SLS_DLR_CD	141141
TXN_CD	E01
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	0
VIN_CD	1FMPJ16L81L [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAR_STL	TMD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TN2
Field50	

ID	85
MDL_YR	2001
SORT_INDEX	384
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	10/9/2000
WRTY_START_D	2/19/2001
NAME	FORD COUNTRY
DOC_NUM	9410551
PH_NUM	5883873
WCC_CD	0R02
PART_NUM_CA	*
PART_NUM_CA	7881202
PART_NUM_CA	*
CUST_CONC_C	840
COND_CD	48
RPR_DT	10/6/2001
TIS_WSD	8
CLM_KEY	4198368
MLGE	8821
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1440
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NV
Field27	B
CPSC_CD_6	12001

TECH_TXT1 FOUND LEFTOVER DEBRIS FROM BUCKLE
MANUFACTURING STUCK IN IN LATCH OF
BUCKLE.REMOVED PLASTIC DEBRIS.RETEST.QC
CHECK.RF SEATBELT BUCKLE OPERATING
NORMALLY

TECH_TXT2

CUST_TXT RT FRONT SHOULDER HARNESS WONT BUCKLE

AREA_CD 702

COUNTRY_CD USA

SLS_DLR_CD 171168

TXN_CD 2

CNTRY_SOLD USA

QRT_CD Q21

VFG_CD V05

AWS_VL_CD B9

VRT_CD 908

TIS_FLAG

VIN_CD 1FMEJ17L41L

LBR_COST

VEH_LINE_CD T758

MKT_DERIVED *

BOD_CAB_STL TMD

VER_SERIES_C TEF

DRIVE_CD T78

ENG_CD TNZ

Field50

ID	85
MDL_YR	2001
SORT_INDEX	288
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	6/19/2001
NAME	WATSON QUALITY FORD
DOC_NUM	100244A
PH_NUM	9657000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	12/21/2001
TIS_WSD	7
CLM_KEY	680630
MILGE	0088
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5905
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MS
Field27	
CPSC_CD_6	12001

TECH_TXT1	9088 81202 42 W R&I PASS SIDE SEAT AND REMOVED OLD SEAT BELT BUCKEL AND INSTALLED NEW ONE Y
TECH_TXT2	
CUST_TXT	(S40) CK PASS FRONT SEATBELT WILL NOT LATCH
AREA_CD	801
COUNTRY_CD	USA
SLS_DLR_CD	123308
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMEU17L21L [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
Field59	

ID	67
MDL_YR	2001
SORT_INDEX	388
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/2/2001
WRTY_START_D	4/4/2001
NAME	BILLINGSLEY FORD LINCOLN MERCU
DOC_NUM	189448C
PH_NUM	2655500
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/11/2001
TIS_WSD	0
CLM_KEY	0380501
MILGE	14757
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3039
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
Field27	b
CPSC_CD_6	12001

TECH_TXT1	REPLACED BOTH SEAT BELT BUCKLES FOR WILL NOT LATCH
TECH_TXT2	
CUST_TXT	DIAG PASS SEAT BELT DOES NOT STAY LATCHED (HAS BEEN CHANGED PER RECALL)
AREA_CD	580
COUNTRY_CD	USA
SLS_DLR_CD	152873
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	905
TIS_FLAG	
VIN_CD	1FMEU17L01L [REDACTED]
LBR_COST	[REDACTED] 923
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/MQ
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
Field50	

ID	88
MDL_YR	2001
SORT_INDEX	371
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/29/2001
NAME	WALNUT CREEK FORD
DOC_NUM	342865A
PH_NUM	8322900
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	3
CLM_KEY	5788554
MILGE	3311
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7820
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	C
CPSC_CD_6	12001

TECH_TXT1	3311 COND 33 (WARR) REMOVED DRIVERS SEAT ASSEMBLY REMOVED SEAT TRACK ASSEMBLY AND HARNESSES REMOVED LOWER SEAT CUSHION COVER REMOVED PINCHED HARNESS AND REROUTE NEW HARNESS REINSTALLED COVER ANDTRAC
TECH_TXT2	K REPLACED BUCKLET RECHECKED OK REPLACE RIGHT BUCKLE LOOSE.
CUST_TXT	LEFT FRONT SEAT BELT ASSEMBLY COMES LOOSE WHILE DRIVING. REPLACE LEFT FRONT SEATBELT ASSEMBLY. (SOP) RIGHT FRONT SEAT BELT ASSY COMES LOOSE.
AREA_CD	025
COUNTRY_CD	USA
SLS_DLR_CD	172022
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMEU15V01L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
Field50	

ID	69
MDL_YR	2001
SORT_INDEX	372
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/19/2001
WRTY_START_D	3/28/2001
NAME	FRIENDLY FORD
DOC_NUM	4444551
PH_NUM	8707221
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	7/25/2001
TIS_WSD	4
CLM_KEY	2030892
MILGE	4448
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6634
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NV
Field27	0
CPSC_CD_6	12001

TECH_TXT1	SEAT BELT SEAT REPLACE	TRACK ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	REPAIR PASS FRONT SEAT BELT COMES UNDONE WHILE DRIVING, SOP PART IN	
AREA_CD	702	
COUNTRY_CD	USA	
SLS_DLR_CD	171170	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMEU15W21	
LBR_COST		
VEH_LINE_CD	T1B3	
MKT_DERIVED		
BOD_CAB_STL	TWO	
VER_SERIES_C	T1EF	
DRIVE_CD	T1B	
ENG_CD	T1VN	
Field50		

ID	70
MDL_YR	2001
SORT_INDEX	373
TRANS_CD	TCE
PLANT_CD	AP
PRODN_DT	8/13/2001
WRTY_START_D	8/8/2001
NAME	ANTELOPE VALLEY FORD
DOC_NUM	8798851
PH_NUM	9493586
WCC_CD	8F012
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAB
CUST_CONC_C	T80
COND_CD	1
RPR_DT	7/19/2001
TIS_WSD	0
CLM_KEY	2753831
MILGE	5
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	5420
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	12001

TECH_TXT1	BUCKLE FAILED REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT BUCKLES COMED UNDONE
AREA_CD	B05
COUNTRY_CD	USA
SLS_DLR_CD	171459
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMEU15L91L [REDACTED]
LBR_COST	[REDACTED] 1378
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
Field58	

ID	71
MDL_YR	2001
SORT_INDEX	376
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/28/2000
WRTY_START_D	8/14/2001
NAME	BOB WONDRIES FORD
DOC_NUM	241002A
PH_NUM	2883581
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/18/2001
TIS_WSD	3
CLM_KEY	4723118
MILGE	4387
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5520
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	12001

TECH_TXT1	4387 ERRATIC SEAT BELT BUCKLE MT 01202 D.B INSPECTED ERRATIC RT. FRONT SEAT BELT OPERATION. REPLACED SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE INOP. SEAT BELT COMES LOOSE WHEN DRIVING
AREA_CD	626
COUNTRY_CD	USA
SLS_DLR_CD	171081
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	BS
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMEU16L81
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
Field50	

ID	72
MDL_YR	2001
SORT_INDEX	1
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	5/31/2001
NAME	TEMPLE LINCOLN-MERCURY
DOC_NUM	0638083
PH_NUM	7738077
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	8/21/2001
TIS_WSD	3
CLM_KEY	3518448
MILGE	4800
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10804
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEAT BELT WONT HOLD
TECH_TXT2	
CUST_TXT	CUST SAYS PASS SEAT BELT WONT HOLD
AREA_CD	
COUNTRY_CD	254
SLS_DLR_CD	USA
TXN_CD	387328
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	23.94
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	73
MDL_YR	2001
SORT_INDEX	3
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	5/2/2001
NAME	HERTZ RAC - ALEXANDRIA
DOC_NUM	42927501
PH_NUM	
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/24/2001
TIS_WSD	8
CLM_KEY	6608100
MILGE	14158
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	46285
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT DISCONNECTS BY ITSELF
AREA_CD	
COUNTRY_CD	*
SLS_DLR_CD	USA
TXN_CD	245834
CNTRY_SOLD	ES4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S06
VIN_CD	
LBR_COST	
VEH_LINE_CD	80.5
MKT_DERIVED	TB4
BOD_CAB_STL	*
VER_SERIES_C	TWYD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	74
MDL_YR	2001
SORT_INDEX	8
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/18/2000
WRTY_START_D	12/7/2001
NAME	BARNEY A SMITH LINC-MERC INC
DOC_NUM	8888801
PH_NUM	7485621
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	1
CLM_KEY	8000078
MILGE	718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10128
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	R+R BELT BUCKLE
TECH_TXT2	
CUST_TXT	FRONT LEFT SEAT BELT WILL COME UNATTACHED WHILE DRIVING DOWN THE ROAD
AREA_CD	
COUNTRY_CD	912
SLS_DLR_CD	USA
TXN_CD	326234
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	22.00
MKT_DERIVED	TBA
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E1
ENG_CD	T/E
Field56	TWGC

ID	75
MDL_YR	2001
SORT_INDEX	8
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	8/9/2001
NAME	BAY STATE LINCOLN-MERCURY
DOC_NUM	4581201
PH_NUM	8727600
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	8/29/2001
TIS_WSD	1
CLM_KEY	2371388
MILGE	1400
MTRL_COST	
TOT_COST_GRO	
LAB_HRS	
DLR_CD	10831
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MA
Field27	b
CPSC_CD_6	11001