

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 2 OF 6

BOOK 1 OF 43

TECH_TXT1	1 REPLACED SEAT BELT BUCKLE DRIVERS SEAT
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE IS NOT HOLDING PART IN STOCK
AREA_CD	
COUNTRY_CD	506
SLS_DLR_CD	USA
TXN_CD	312146
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TKS_FLAG	S06
VIN_CD	
LBR_COST	
VEH_LINE_CD	2B.52
MKT_DERIVED	T84
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	78
MDL_YR	2001
SORT_INDEX	10
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	9/5/2001
NAME	PAUL CERAME LING-MERC INC
DOC_NUM	218488B
PH_NUM	8310200
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	3/22/2002
TIS_WSD	7
CLM_KEY	7728948
MILGE	10175
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12825
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INSPECTED SEAT BELT ASSEMBLY, UNABLE TO VERIFY CONCERN, INSPECTED SEAT BELT LATCH ASSEMBLY, NO FORIEGN MATERIAL IN LATCH, ORDERED LATCH.
TECH_TXT2	
CUST_TXT	S20 CUST SAYS L F SEAT BELT KEEPS POPPING OFF
AREA_CD	
COUNTRY_CD	314
SLS_DLR_CD	USA
TXN_CD	383504
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	90.99
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field58	T/WC

ID	77
MDL_YR	2001
SORT_INDEX	11
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	6/17/2001
NAME	GALPIN LINCOLN-MERCURY
DOC_NUM	3625312
PH_NUM	8923600
WCC_CD	6R02
PART_NUM_CA	F86Z
PART_NUM_CA	7861203
PART_NUM_CA	BBE
CUST_CONC_C	S2B
COND_CD	42
RPR_DT	7/6/2001
TIS_WSD	2
CLM_KEY	3132586
MILGE	4180
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11820
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	12001

TECH_TXT1	VERIFIED CONCERN, PERFORMED 01521 RECALL AND REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST STS DRIVERS SEAT BELT BUCKLE DOESNT STAY LATCHED SOMETIMES
AREA_CD	
COUNTRY_CD	010
SLS_DLR_CD	USA
TXN_CD	354301
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	43.96
MKT_DERIVED	T/B4
BOD_CAB_STL	"
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	78
MDL_YR	2001
SORT_INDEX	17
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/11/2001
WRTY_START_D	7/10/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	4588152
PH_NUM	8414650
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	2/27/2002
TIS_WSD	6
CLM_KEY	7148123
MILGE	12218
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	10021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	R
CPSC_CD_6	11001

TECH_TXT1	B L F SEAT BELT BUCKLE DOESNT LATCH ALL THE TIME, REPL BUCKLE
TECH_TXT2	
CUST_TXT	C S LEFT FRONT SEATBELT DOES NOT LATCH AT TIMES. INT TRIM CODE KH
AREA_CD	
COUNTRY_CD	407
SLS_DLR_CD	USA
TXN_CD	325188
CNTRY_SOLD	E94
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	13.27
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TMD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	79
MDL_YR	2001
SORT_INDEX	18
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/29/2001
WRTY_START_D	1/31/2001
NAME	HAVRE FORD LINCOLN MERCURY
DOC_NUM	078047A
PH_NUM	2862246
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/27/2001
FIS_WSD	11
CLM_KEY	5637411
MILGE	9643
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3119
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MT
Field27	B
CPSC_CD_6	11001

TECH_TXT1	FOUND LATCH TO BE FAULTY, REPLACED LATCH ASSEMBLY
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT DOESNT LATCH AT TIMES
AREA_CD	
COUNTRY_CD	406
SLS_DLR_CD	USA
TXN_CD	38403R
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	31.03
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	80
MDL_YR	2001
SORT_INDEX	19
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	2/17/2001
NAME	ROCKLAND LINCOLN MERCURY SALES
DOC_NUM	1228102
PH_NUM	3588400
WCC_CD	BR02
PART_NUM_CA	3L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/3/2001
TIS_WSD	10
CLM_KEY	5532144
MILGE	11681
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10089
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 159 of 442

RQ04-011 E 0159

TECH_TXT1	. VERIFIED CUST CONCERN, INSTALLED NEW SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES THAT DRIVERS SIDE SEAT BELT UNHOOKS ON ITS OWN.
AREA_CD	
COUNTRY_CD	914
SLS_DLR_CD	LIBA
TXN_CD	314541
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	32.5
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field58	T/WC

ID	91
MDL_YR	2001
SORT_INDEX	20
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	3/26/2001
NAME	COUNTRY LINC-MERC SALES INC
DOC_NUM	6558553
PH_NUM	2716800
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	628
COND_CD	1
RPR_DT	4/20/2002
TIS_WSD	14
CLM_KEY	6142297
MILGE	9943
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	13807
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 161 of 442

RQ04-011 E 0181

TECH_TXT1	UNLATCH FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUSTOMER STATES CK BOTH FRONT SEAT BELTS UNLATCH AT TIMES FOR NO REASON	
AREA_CD		
COUNTRY_CD	516	
SLS_DLR_CD	USA	
TXN_CD	314160	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V06	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD	0	
LRR_COST		
VEH_LINE_CD	52.78	
MKT_DERIVED	T/BA	
BOD_CAB_STL	*	
VER_SERIES_C	T/WD	
DRIVE_CD	T/EL	
ENG_CD	T/E	
Field50	T/WC	

ID	02
MDL_YR	2001
SORT_INDEX	21
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	7/23/2001
NAME	DANA MOTORS LTD
DOC_NUM	8942552
PH_NUM	8838700
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S15
COND_CD	42
RPR_DT	8/27/2001
TIS_WSD	3
CLM_KEY	4010683
MILGE	4608
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11281
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
Field27	8
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT NOT LOCKING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	C STATES DRIVES SIDE SEAT BELT DONT LOCK.
AREA_CD	
COUNTRY_CD	718
SLS_DLR_CD	USA
TXN_CD	314081
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	B4
TIS_FLAG	805
VIN_CD	
LBR_COST	
VEH_LINE_CD	36.08
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	59
MDL_YR	2001
SORT_INDEX	26
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/21/2000
WRTY_START_D	9/4/2001
NAME	VARISITY LINCOLN-MERCURY INC
DOC_NUM	8883301
PH_NUM	3055300
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/20/2001
TIS_WSD	2
CLM_KEY	4883836
MILGE	3567
MTRL_COST	2330
TOT_COST_GRO	2330
LBR_HRS	2330
DLR_CD	10011
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	8
CPSC_CD_6	11001

TECH_TXT1	7861203 42 VERIFIED CONCERN INSPECT AND TEST SEAT BELT LATCH FOUND LATCH NOT LATCHING PROPERLY R&R DRIVERS SEAT REPLACED
TECH_TXT2	
CUST_TXT	CK ADVISE DRIVERS SEAT BELT INOP PARTS NOW IN STOCK
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	345335
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	48.55
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TWD
DRIVE_CD	T/E
ENG_CD	T/E
Field50	T/WC

ID	84
MDL_YR	2001
SORT_INDEX	28
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	8/30/2001
NAME	OLATHE LINCOLN-MERCURY INC
DOC_NUM	5817552
PH_NUM	7627820
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/21/2001
TIS_WSD	8
CLM_KEY	5880829
MILGE	14112
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12803
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KS
Field27	b
CPSC_CD_6	11001

TECH_TXT1	VERIFY CONCERN. REPLACE DRIVERS SEAT BELT LATCH ASSY WILL NOT HOLD SECURLY
TECH_TXT2	
CUST_TXT	THE DRIVERS SEATBELT WILL UNLATCH ON ITS OWN WHEN DRIVING
AREA_CD	
COUNTRY_CD	913
SLS_DLR_CD	USA
TXN_CD	383666
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	14.15
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VRR_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	55
MDL_YR	2001
SORT_INDEX	30
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/3/2001
WRTY_START_D	8/8/2001
NAME	FIESTA LINCOLN-MERCURY
DOC_NUM	3387401
PH_NUM	8134900
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	8
CLM_KEY	8242132
MILGE	5080
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11898
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REMOVE DRIVERS SEAT FOR ACCESS, REPLACE DRIVERS SEAT BUCKLE #61203, CODE 42, TECH 0871
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES LOOSE WHEN DRIVING INSTALL SOP
AREA_CD	
COUNTRY_CD	480
SLS_DLR_CD	USA
TXN_CD	354288
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	58.82
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field56	T/WC

ID	B8
MDL_YR	2001
SORT_INDEX	31
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	3/30/2001
NAME	BANKSTON L-M, INC.
DOC_NUM	3830402
PH_NUM	2331441
WCC_CD	0R02
PART_NUM_CA	1LTZ
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S28
COND_CD	33
RPR_DT	3/11/2002
TIS_WSD	12
CLM_KEY	7353548
MILGE	18862
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13560
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	33 61203 VERIFY CUSTOMERS CONCERN.REPLACE DRIVERS SEAT BELT BUCKLE. LOOSE
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS SEATBELT BUCKLE KEEPS POPPING LOOSE
AREA_CD	
COUNTRY_CD	972
SLS_DLR_CD	USA
TXN_CD	367365
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	306
VIN_CD	
LBR_COST	
VEH_LINE_CD	14.08
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	87
MDL_YR	2001
SORT_INDEX	33
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	6/13/2001
NAME	MCAULEY MOTORS INC
DOC_NUM	1000852
PH_NUM	7222777
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	2/6/2002
TIS_WSD	8
CLM_KEY	8747988
MILGE	481B
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12701
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT NOT STAYING ENGAGED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEATBELT NOT STAYING ENGAGED
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	LISA
TXN_CD	361077
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.77
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VBR_SERIES_C	TW0
DRIVE_CD	T/E1
ENG_CD	T/E
Field56	T/WC

ID	88
MDL_YR	2001
SORT_INDEX	35
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	7/15/2001
NAME	GLENWOOD SPRINGS FORD-LIN-MER
DOC_NUM	9033801
PH_NUM	9452317
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7681203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/9/2001
TIS_WSD	1
CLM_KEY	3284804
MILGE	3123
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3172
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	FOUND DRIVERS SIDE SEAT BELT BROKEN. R&R DRIVERS SEAT BELT. VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT CAME UNLATCHED WHILE DRIVING. S40
AREA_CD	
COUNTRY_CD	970
SLS_DLR_CD	USA
TXN_CD	365491
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	B08
VIN_CD	
LBR_COST	
VEH_LINE_CD	07A
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TWD
DRIVE_CD	T/E
ENG_CD	T/E
Field50	T/WC

ID	89
MDL_YR	2001
SORT_INDEX	38
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/17/2000
WRTY_START_D	1/4/2001
NAME	UPTOWN MOTORS, INC.
DOC_NUM	137101A
PH_NUM	7718000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAS
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/4/2001
TIS_WSD	10
CLM_KEY	4258778
MILGE	10898
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12152
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REMOVE AND INSTALL SEAT BELTS
TECH_TXT2	
CUST_TXT	INSTALL SOP SEATBELT BUCKLES BOTH FRONT, WONT STAY LATCHED, RD 188518 TECH 7619
AREA_CD	
COUNTRY_CD	414
SLS_DLR_CD	USA
TXN_CD	342527
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V15
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	B028
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field30	T/WC

ID	80
MDL_YR	2001
SORT_INDEX	41
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	8/16/2001
NAME	BLOAN MOTORS INC
DOC_NUM	0587128
PH_NUM	3832870
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/13/2002
TIS_WSD	13
CLM_KEY	7412574
MILGE	26003
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1209
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WONT LATCH
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	315002
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	C21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LRR_COST	
VEH_LINE_CD	59.37
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T7W0
DRIVE_CD	T/EL
ENG_CD	T/E
Flid50	T/WC

ID	81
MDL_YR	2001
SORT_INDEX	43
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/5/2001
WRTY_START_D	3/18/2001
NAME	COOROLI LINCOLN-MERCURY
DOC_NUM	3554851
PH_NUM	2947700
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	2/5/2002
TIS_WSD	11
CLM_KEY	6603421
MILGE	15410
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12718
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE BELT INOP
TECH_TXT2	
CUST_TXT	LT FRONT SEAT BELT WONT LATCH AT TIMES 8 0
AREA_CD	
COUNTRY_CD	825
SLS_DLR_CD	USA
TXN_CD	351078
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LRR_COST	
VEH_LINE_CD	56.12
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WC
DRIVE_CD	T/EL
ENG_CD	T/E
Field58	T/WC

ID	02
MDL_YR	2001
SORT_INDEX	45
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	4/7/2001
NAME	FRED BEANS FORD-LINCOLN-MERCUR
DOC_NUM	27296202
PH_NUM	3482900
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7651203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	9/27/2001
TIS_WSD	6
CLM_KEY	4338246
MILGE	7131
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1203
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLACE (811A72 811A73) 61203,S25,42
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT BUCKLE RELEASE CLIP DOES NOT COME ALL THE UP WHEN ENGAUGED
AREA_CD	
COUNTRY_CD	215
SLS_DLR_CD	USA
TKN_CD	315071
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	C21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.14
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E
ENG_CD	T/E
Field50	TWC

ID	03
MDL_YR	2001
SORT_INDEX	50
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/23/2001
WRTY_START_D	9/15/2001
NAME	REEDMAN LINCOLN MERCURY
DOC_NUM	34580001
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	CAA
CUST_CONC_C	B40
COND_CD	42
RFR_DT	8/9/2001
TIS_WSD	0
CLM_KEY	3183477
MILGE	5
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10435
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECK BOTH FRONT SEATBELT BUCKLES WILL NOT STAY LATCHED, REPLACED BOTH BUCKLES
TECH_TXT2	
CUST_TXT	
AREA_CD	
COUNTRY_CD	
SLS_DLR_CD	USA
TXN_CD	31E148
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LRR_COST	
VEH_LINE_CD	49.41
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	94
MDL_YR	2001
SORT_INDEX	51
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/23/2001
WRTY_START_D	6/25/2001
NAME	NORTHEAST LINCOLN-MERCURY
DOC_NUM	12996304
PH_NUM	3318800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/19/2001
TIS_WSD	0
CLM_KEY	3229819
MILGE	4
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	10454
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT LATCH WONT LOCK 840 42 CHECK AND REPLACE LEFT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RECALL 01 S21 SEAT BELT INSPECTION NOT ON RECALL BUT LEFT BUCKLE WONT LATCH
AREA_CD	
COUNTRY_CD	215
SLS_DLR_CD	USA
TXN_CD	315306
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	87A8
MKT_DERIVED	T/BA
BOD_CAB_STL	
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	65
MDL_YR	2001
SORT_INDEX	66
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/17/2001
NAME	MEL FARR LINCOLN-MERCURY INC
DOC_NUM	257454B
PH_NUM	6839500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	640
COND_CD	1
RPR_DT	8/12/2001
TIS_WSD	1
CLM_KEY	3727057
MILGE	1237
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10810
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1237 01 INSPECTED ABD FOUND BAD SEAT BELTLATCH REPLACED DRIVER SEAT BELT LATCH RECHECKED GOOD
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT UNHOOKS WHILE DRIVING
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	348275
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	14.43
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	98
MDL_YR	2001
SORT_INDEX	58
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/4/2001
WRTY_START_D	6/16/2001
NAME	NORTHTOWNE LINCOLN-MERCURY INC
DOC_NUM	12078701
PH_NUM	4532710
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	GAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	1/9/2002
TIS_WSD	7
CLM_KEY	6168487
MILGE	15884
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12828
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	G
CPSC_CD_6	11001

TECH_TXT1	TESTED THE SEAT BELT CAME UNLATCHED PUT IN A NEW BUCKLE TESTED DID NOT COME UNDONE MOVED THE LATCH AROUND
TECH_TXT2	
CUST_TXT	S26 CUST STATE LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING & LATCH ON BELT IS BACKWARD
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	303559
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	94
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	25.43
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field59	T/WC

ID	97
MDL_YR	2001
SORT_INDEX	80
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	3/8/2001
NAME	VARSITY LINCOLN-MERCURY INC
DOC_NUM	8788202
PH_NUM	3055300
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	2/4/2002
TIS_WSD	12
CLM_KEY	6721834
MILGE	13542
MTRL_COST	28.55
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10011
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	c
CPSC_CD_6	11001

TECH_TXT1	81203 42 VERIFY CONCERN. REPLACE LH FR SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL INTERMITTENTLY COME UNLATCHED
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	345335
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S05
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.32
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TWD
DRIVE_CD	T/E1
ENG_CD	T/E
Field50	T/WC

ID	98
MDL_YR	2001
SORT_INDEX	83
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	3/24/2001
NAME	MAPLECREST LINCOLN-MERCURY, IN
DOC_NUM	9041103
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S2B
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	12
CLM_KEY	7454731
MILGE	14241
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10290
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
Field27	G
CPSC_CD_6	11001

TECH_TXT1	1 1 CHECK AND REPLACE SEATBELT
TECH_TXT2	
CUST_TXT	OWNER STATES LEFT FRONT SEATBELT RELEASES ON OWN
AREA_CD	
COUNTRY_CD	*
SLS_DLR_CD	USA
TXN_CD	314474
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	32.06
MKT_DERIVED	TB4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E1
ENG_CD	T/E
Field50	T/WC

ID	99
MDL_YR	2001
SORT_INDEX	65
TRANS_CD	T/D E
PLANT_CD	AP
PRODN_DT	3/29/2001
WRTY_START_D	8/25/2001
NAME	KUMPF LINCOLN MERCURY, INC.
DOC_NUM	130104A
PH_NUM	7611580
WCC_CD	4R02
PART_NUM_CA	1U7
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/11/2001
TIS_WSD	1
CLM_KEY	4358713
MILGE	498
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11068
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPL SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT ON DRIVERS SIDE UN LATCHES ITSELF
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	358116
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	G21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.22
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	T7W0
DRIVE_CD	T7EL
ENG_CD	T7E
Field30	T7WC

ID	100
MDL_YR	2001
SORT_INDEX	87
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/14/2001
WRTY_START_D	7/7/2001
NAME	VALLEY FORD LINCOLN-MERCURY
DOC_NUM	4353156
PH_NUM	6846591
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAB
CUST_CONC_C	880
COND_CD	33
RPR_DT	12/17/2001
TIS_WSD	8
CLM_KEY	5906148
MILGE	10275
MTEL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7887
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	63: VERIFY DRIVERS SEATBELT UNLATCHES, R&R FRONT SEAT AND REPLACED SEATBELT BUCKLE, REASSEMBLE, RECHECK OK AT THIS TIME
TECH_TXT2	
CUST_TXT	CUSTOMER STATED THE DRIVERS SEAT BELT HAS COME UNLOCKED THREE DIFFERENT TIMES
AREA_CD	
COUNTRY_CD	660
SLS_DLR_CD	USA
TXN_CD	351046
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	74.87
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	101
MDL_YR	2001
SORT_INDEX	08
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/7/2001
WRTY_START_D	3/28/2001
NAME	Fiesta Lincoln-Mercury
DOC_NUM	3365401
PH_NUM	8134600
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	803
COND_CD	41
RPR_DT	1/11/2002
TIS_WSD	10
CLM_KEY	8271235
MILGE	13246
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11096
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Field27	C
CPSC_CD_6	11001

TECH_TXT1 CODE 41,7981203,SEAT BELT BUCKLE BINDING TECH
245 SS 0994 REMOVE DRIVERS SEAT TO
ACCESS,REMOVE AND REPLACE SEAT BELT
BUCKLE,REINSTALL DRIVERS SEAT.TECH 245 SS 0994

TECH_TXT2

CUST_TXT C S THAT LEFT FRONT SEAT KEEPS COMING LOOSE
CHECK AND ADVISE

AREA_CD

COUNTRY_CD 480

SLS_DLR_CD USA

TXN_CD 354288

CNTRY_SOLD E64

QRT_CD USA

VFG_CD Q21

AWS_VL_CD V03

VRT_CD B4

TIS_FLAG S05

VIN_CD

LRR_COST

VEH_LINE_CD 20.31

MKT_DERIVED T/B4

BOD_CAB_STL

VER_SERIES_C TMD

DRIVE_CD T/E1

ENG_CD T/E

Field50 T/WC

ID	102
MDL_YR	2001
SORT_INDEX	70
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	5/23/2001
NAME	BURT LINCOLN MERCURY
DOC_NUM	1008148
PH_NUM	3808000
WCC_CD	BF02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	7
CLM_KEY	5618838
MILGE	10622
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10472
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REMOVE DRIVERS SEAT TO REPLACE SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	SAYS DRIVER SEAT BELT WONT STAY LATCHED POPS OUT WHILE DRIVING
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	855289
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	2722
MKT_DERIVED	T/B4
BOD_CAB_STL	.
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field58	T/WC

ID	109
MDL_YR	2001
SORT_INDEX	71
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	7/9/2001
NAME	KUMPF LINCOLN MERCURY, INC.
DOC_NUM	127355A
PH_NUM	7811580
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RFR_DT	8/13/2001
TIS_WSD	2
CLM_KEY	3007878
MILGE	1982
MTRL_COST	28.05
TOT_COST_GRO	2327
LBR_HRS	28
DLR_CD	11056
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPL SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT WILL RELEASE AT TIMES, SOP IS IN
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	353115
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	27.22
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TWVD
DRIVE_CD	T/EL
ENG_CD	T/E
Field58	T/WC

ID	104
MDL_YR	2001
SORT_INDEX	73
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/26/2001
WRTY_START_D	4/10/2001
NAME	OLYMPIC LINCOLN-MERCURY INC
DOC_NUM	19818501
PH_NUM	3648500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S26
COND_CD	41
RPR_DT	3/1/2002
TIS_WSD	11
CLM_KEY	7202580
MILGE	27533
MTRL_COST	
TOI_COST_GRO	
LBR_HRS	
DLR_CD	13013
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 287 of 462

RQ04-011 E 0207

TECH_TXT1	REPLACED LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE UNCOUPLES WHILE IN USE
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	USA
TXN_CD	354708
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	VB6
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	15.13
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field59	T/WC

ID	105
MDL_YR	2001
SORT_INDEX	76
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	2/25/2002
NAME	MARME FORD-LINCOLN-MERCURY
DOC_NUM	8358502
PH_NUM	7835427
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	1
CLM_KEY	8185854
MILGE	4501
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5247
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KS
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT WONT LATCH
AREA_CD	
COUNTRY_CD	820
SLS_DLR_CD	USA
TXN_CD	383174
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	17.72
MKT_DERIVED	TIB4
BOD_CAB_STL	*
VER_SERIES_C	TWO
DRIVE_CD	TFL
ENG_CD	TIE
Field50	TWC

ID	108
MDL_YR	2001
SORT_INDEX	77
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	8/28/2001
NAME	COUNTRY LINC-MERC SALES INC
DOC_NUM	5905452
PH_NUM	2718800
WCC_CD	8R02
PART_NUM_CA	1L72
PART_NUM_CA	7861203
PART_NUM_CA	GAB
CUST_CONC_C	825
COND_CD	42
RPR_DT	12/14/2001
TIS_WSD	3
CLM_KEY	5734427
MILGE	1093
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13307
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
Field27	a
CPSC_CD_6	11001

TECH_TXT1	INOP REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	C S DRIVERS SEAT BELT NOT LOCKING (SOP)	
AREA_CD		
COUNTRY_CD	516	
SLS_DLR_CD	USA	
TXN_CD	314017	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LRR_COST		
VEH_LINE_CD	35.10	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	T/WO	
DRIVE_CD	T/EL	
ENG_CD	T/E	
Field50	T/WC	

ID	107
MDL_YR	2001
SORT_INDEX	79
TRANS_CD	TYPE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	5/18/2001
NAME	BRIGHTON FORD-MERCURY, INC.
DOC_NUM	134422A
PH_NUM	2271171
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/20/2002
TIS_WSD	5
CLM_KEY	7520077
MILGE	19500
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2707
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	b
CPSC_CD_6	11001

TECH_TXT1	19600 BASIC 7881203 CONDITION 42 REPLACED LEFT FRONT SEATBELT BUCKLE THAT WOULD NOT STAY LATCHED. OK NOW.
TECH_TXT2	
CUST_TXT	LEFT FRT SEAT BELT AT TIMES RELEASES FROM BUCKLE FOR NO REASON
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	345275
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.89
MKT_DERIVED	T84
BOD_CAB_STL	
VER_SERIES_C	TWD
DRIVE_CD	TFL
ENG_CD	TIE
Field50	TWC

ID	108
MDL_YR	2001
SORT_INDEX	80
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	2/17/2001
NAME	NAPLETON LINCOLN-MERCURY
DOC_NUM	073318A
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/13/2001
TIS_WSD	10
CLM_KEY	5782105
MILGE	8801
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10278
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
Field27	#
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEAT BELT BUCKLE C
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT LATCH DRIVERS FRONT
AREA_CD	
COUNTRY_CD	*
SLS_DLR_CD	USA
TXN_CD	342402
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	32.08
MKT_DERIVED	T7B4
BOD_CAR_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field56	T/WC

ID	108
MDL_YR	2001
SORT_INDEX	88
TRANS_CD	YOE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	9/28/2001
NAME	LITHIA LINCOLN MERCURY OF BOIS
DOC_NUM	358858A
PH_NUM	3236200
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	T90
COND_CD	42
RPR_DT	11/1/2001
TIS_WSD	2
CLM_KEY	4982828
MILGE	1874
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	ID
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1974 42 42 THE CUSTOMER STATES THE DRIVERS SIDE FRONT SEAT BELT INTERMINTELY WILL UNLATCH VERIFIED THE PROBLEM I REPLACED THE DRIVERS SIDE FRONT SEAT BELT BUCKLE AS NEEDED MILES OUT 1974 FAILED PA
TECH_TXT2	RT 1L7Z 7881203 GAA
CUST_TXT	T90 C S THE DVS FRONT SEAT BELT INTERMIT WILL UNLATCH
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	USA
TXN_CD	355575
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V74
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	19.98
MKT_DERIVED	T784
BOD_CAB_STL	*
VER_SERIES_C	TW0
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/MC

ID	110
MDL_YR	2001
SORT_INDEX	87
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/17/2001
WRTY_START_D	4/18/2001
NAME	THEISEN MOTORS INC
DOC_NUM	9832701
PH_NUM	7337700
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/4/2001
TIS_WSD	6
CLM_KEY	3884807
MILGE	5887
MTRL_COST	
TOT_COST_GEO	
LBR_HRS	
DLR_CD	12930
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	ID
Field27	8
CPSC_CD_6	11001

TECH_TXT1	REMOVE AND REPLACE DRIVERS FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT FOR DRIVER WILL NOT LATCH
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	USA
TXN_CD	335468
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	25
MKT_DERIVED	T/BA
BOD_CAR_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field58	T/WG

ID	111
MDL_YR	2001
SORT_INDEX	89
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	8/28/2001
NAME	BURT LINCOLN MERCURY
DOC_NUM	103628E
PH_NUM	3806000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	8
CLM_KEY	7608304
MILGE	8428
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	10472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	*
CPSC_CD_6	11001

TECH_TXT1	BUCKLE WILL NOT OPERATE PROPERLY REPLACE LEFT SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL NOT CLIP SOP HERE
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	355120
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	306
VIN_CD	
LBR_COST	
VEH_LINE_CD	2722
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	112
MDL_YR	2001
SORT_INDEX	87
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	8/16/2001
NAME	MOMENTUM LINCOLN MERCURY, INC.
DOC_NUM	7771953
PH_NUM	2412060
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	12/8/2001
TIS_WSD	4
CLM_KEY	5792720
MILGE	5347
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10485
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	b
CPSC_CD_6	11001

TECH_TXT1	R&R SEATBELT BUCKLE DR. FRONT TESTED FAULTY
TECH_TXT2	
CUST_TXT	DR FRT SEATBELT DOES NOT STAY LATCHED
AREA_CD	
COUNTRY_CD	794
SLS_DLR_CD	USA
TXN_CD	345362
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	39.9
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	113
MDL_YR	2001
SORT_INDEX	101
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	6/2/2001
NAME	SOUTH-WEST LINCOLN-MERCURY INC
DOC_NUM	22702801
PH_NUM	9813600
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONG_C	340
COND_CD	42
RPR_DT	7/31/2001
TTS_WSD	2
CLM_KEY	2881304
MILGE	2639
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11458
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	1 REPLACE DRIVERS SEAT BELT COMES UNLATCHED
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SEAT BELT COMES UNLATCHED 840
AREA_CD	
COUNTRY_CD	713
SLS_DLR_CD	USA
TXN_CD	357208
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	632
MKT_DERIVED	T/B4
BOD_CAR_STL	
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	114
MDL_YR	2001
SORT_INDEX	103
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	5/21/2001
NAME	HOLMAN LINCOLN-MERCURY
DOC_NUM	187853A
PH_NUM	2344800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	9/21/2001
TIS_WSD	5
CLM_KEY	3823744
MILGE	3125
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10408
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECK AND REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	O S SEAT BELT DOES NOT STAY BUCKLED
AREA_CD	
COUNTRY_CD	808
SLS_DLR_CD	USA
TXN_CD	315040
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRF_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	2B.41
MKT_DERIVED	T/B4
BOD_CAB_STL	'
VER_SERIES_C	TWD
DRIVE_CD	T/E
ENG_CD	T/E
Field50	T/WC

ID	115
MDL_YR	2001
SORT_INDEX	109
TRANS_CD	10E
PLANT_CD	AP
PRODN_DT	10/8/2000
WRTY_START_D	6/31/2001
NAME	BTIVERS LINCOLN-MERCURY INC
DOC_NUM	2702551
PH_NUM	2435200
WCC_CD	8R02
PART_NUM_CA	1L72
PART_NUM_CA	7901203
PART_NUM_CA	GAA
CUST_CONC_C	825
COND_CD	41
RPR_DT	8/10/2001
TIS_WSD	3
CLM_KEY	2918030
MILGE	5179
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12832
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	WONT LATCH FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED	
AREA_CD		
COUNTRY_CD	515	
SLS_DLR_CD	USA	
TXN_CD	883589	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	808	
VIN_CD		
LEB_COST	[REDACTED]	
VEH_LINE_CD	26.38	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	T/WD	
DRIVE_CD	T/EL	
ENG_CD	T/E	
Field50	T/WC	

ID	116
MDL_YR	2001
SORT_INDEX	116
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	8/19/2001
NAME	BARANCO LINCOLN-MERCURY INC
DOC_NUM	2468101
PH_NUM	4978900
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/31/2001
YES_WSD	4
CLM_KEY	6000127
MILGE	5041
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10157
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	ACCESS AND REPLACED SEAT BELT TO CORRECT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED S4D
AREA_CD	
COUNTRY_CD	770
SLS_DLR_CD	USA
TXN_CD	320057
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	800
VIN_CD	
LBR_COST	
VEH_LINE_CD	73.17
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	TWE
DRIVE_CD	T/E1
ENG_CD	T/B
Field50	TWC

ID	117
MDL_YR	2001
SORT_INDEX	118
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/23/2001
NAME	BOB RODGERS MOTOR CO., INC.
DOC_NUM	10824301
PH_NUM	2388466
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7081203
PART_NUM_CA	CAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	11/20/2001
TIS_WSD	7
CLM_KEY	6087662
MILGE	13875
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6878
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
Field27	b
CPSC_CD_6	11001

TECH_TXT1	NECESSARY TO REPLACE LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT BUCKLE WILL NOT STAY LATCHED.
AREA_CD	
COUNTRY_CD	405
SLS_DLR_CD	USA
TXN_CD	387391
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	41.29
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field58	T/WC

ID	118
MDL_YR	2001
SORT_INDEX	117
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/16/2001
WRTY_START_D	7/26/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	3782854
PH_NUM	8414660
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	41
RPR_DT	8/19/2001
TIS_WSD	2
CLM_KEY	4188238
MILGE	2782
MTRL_COST	28.00
TOT_COST_GRO	28.00
LBR_HRS	
DLR_CD	10021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSPECTED,LF SEAT BUCKLE WILL NOT LATCH,R&REPLACED LF SEAT BELT BUCKLE ASY.VERIFY REPAIR.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WONT STAY LATCHED
AREA_CD	
COUNTRY_CD	407
SLS_DLR_CD	USA
TXN_CD	325188
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.53
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/VB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	118
MDL_YR	2001
SORT_INDEX	122
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	6/30/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	3488851
PH_NUM	8414650
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/31/2001
YIS_WSD	2
CLM_KEY	2731428
MILGE	2650
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	UNLOCKS SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVER S SEAT BELT KEEPS UNLOCKING WHILE DRIVING SEE FILE
AREA_CD	
COUNTRY_CD	407
SLS_DLR_CD	USA
TXN_CD	325189
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.53
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TWVB
DRIVE_CD	T7EL
ENG_CD	T7E
Field58	T7WC

ID	120
MDL_YR	2001
SORT_INDEX	123
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	6/5/2001
NAME	COVINGTON PIKE LINCOLN MERCURY
DOC_NUM	8158101
PH_NUM	3735700
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	6/22/2001
TYS_WSD	3
CLM_KEY	3229233
MILGE	8270
MTRL_COST	2835
TOT_COST_GRO	66.08
LBR_HRS	0.4
DLR_CD	10198
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED LFT FRT SEAT BELT BUCKLE ASSY. COMES LOOSE WHILE DRIVING.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVER SEAT BELT COMES OUT WHILE DRIVING SQP IN
AREA_CD	
COUNTRY_CD	901
SLS_DLR_CD	USA
TXN_CD	322884
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	EA
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.9
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
F1el450	T/WC

ID	121
MDL_YR	2001
SORT_INDEX	128
TRANS_CD	T0E
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	8/24/2001
NAME	MARGATE LINCOLN-MERCURY INC
DOC_NUM	291814B
PH_NUM	9782277
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	7
CLM_KEY	8771478
MILGE	14837
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11888
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	a
CPSC_CD_6	11001

TECH_TXT1	14937 42 W RR LT FT SEAT TO REPLACE SEAT BELT BUCKLE SOP
TECH_TXT2	
CUST_TXT	S40,LEFT FRT SEAT BELT WONT LATCH.,
AREA_CD	
COUNTRY_CD	306
SLS_DLR_CD	USA
TXN_CD	325258
CNTRY_SOLD	EB4
QRT_CD	LISA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	33.07
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field58	T/WC

ID	122
MDL_YR	2001
SORT_INDEX	127
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/5/2001
WRTY_START_D	6/17/2001
NAME	RAY PEARMAN LINCOLN MERCURY, I
DOC_NUM	2385301
PH_NUM	5387451
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	540
COND_CD	12
RPR_DT	9/5/2001
TIS_WSD	4
CLM_KEY	3441443
MILGE	7819
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12043
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	LEFT FRONT SEATBELT WONT BUCKLE REPLACED LEFT FRONT SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT COMES LOOSE AFTER BUCKLING TRIM KH
AREA_CD	
COUNTRY_CD	205
SLS_DLR_CD	USA
TXN_CD	326330
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	G21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	46.51
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	TWB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	123
MDL_YR	2001
SORT_INDEX	128
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	8/22/2001
NAME	ANTELOPE VALLEY FORD
DOC_NUM	8770251
PH_NUM	9493588
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	41
RPR_DT	7/20/2001
TIS_WSD	1
CLM_KEY	4000482
MILGE	1701
MTBL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5428
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	WONT STAY LATCHED DRIVERS SIDE SEAT BELT	REPLACED
TECH_TXT2		
CUST_TXT	CUST STATES DRIVER SEAT BELT WONT STAY LATCHED	
AREA_CD		
COUNTRY_CD	806	
SLS_DLR_CD	USA	
TXN_CD	354183	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	C21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	808	
VIN_CD		
LBR_COST		
VEH_LINE_CD	53.78	
MKT_DERIVED	TB4	
BOD_CAB_STL		
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Field50	T/WC	

ID	124
MDL_YR	2001
SORT_INDEX	133
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	5/25/2001
NAME	EAGLE LINCOLN-MERCURY INC
DOC_NUM	40872902
PH_NUM	3570461
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/10/2001
TIS_WSD	7
CLM_KEY	5798222
MILGE	11786
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10835
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT LATCH,RECHECKED OK.
TECH_TXT2	
CUST_TXT	CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.
AREA_CD	
COUNTRY_CD	214
SLS_DLR_CD	USA
TXN_CD	387510
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LRR_COST	
VEH_LINE_CD	28.06
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TMB
DRIVE_CD	T/E1
ENG_CD	T/B
Field50	TWC

ID	125
MDL_YR	2001
SORT_INDEX	137
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/20/2000
WRTY_START_D	2/2/2001
NAME	PUGMRE LINCOLN-MERCURY INC
DOC_NUM	5572452
PH_NUM	9522261
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	33
RPR_DT	7/12/2001
TIS_WSD	6
CLM_KEY	2455141
MILGE	5392
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10188
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	
CPSC_CD_6	11001

TECH_TXT1	SEATBELT FAULTY FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	O B THE DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING	
AREA_CD		
COUNTRY_CD	770	
SLS_DLR_CD	USA	
TXN_CD	328067	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	908	
VIN_CD		
LBR_COST		
VEH_LINE_CD	28.83	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Flold50	T/WC	

ID	128
MDL_YR	2001
SORT_INDEX	138
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	5/31/2001
NAME	DAVID MCDAVID'S PLANO LINCOLN
DOC_NUM	42181BA
PH_NUM	0846000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	7/18/2001
TIS_WSD	2
CLM_KEY	2423233
MILGE	1342
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11442
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEATBELT; WILL NOT LATCH
TECH_TXT2	
CUST_TXT	840 C S DRIVERS SEATBELT WILL NOT STAY LATCHED SOP IN
AREA_CD	
COUNTRY_CD	972
SLS_DLR_CD	USA
TXN_CD	387324
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	806
VIN_CD	
LBR_COST	
VEH_LINE_CD	34.96
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field58	T/WC

ID	127
MDL_YR	2001
SORT_INDEX	140
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/23/2001
WRTY_START_D	11/10/2001
NAME	BARANCO LINCOLN-MERCURY INC
DOC_NUM	2406001
PH_NUM	4976900
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7681203
PART_NUM_CA	CAA
CUST_CONC_C	640
COND_CD	12
RPR_DT	11/23/2001
TIS_WSD	1
CLM_KEY	5288780
MILGE	500
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	10157
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT LATCH TO CORRECT
TECH_TXT2	
CUST_TXT	GK CUST STATES DRIVERS SEAT BELT WILL COME LOOSE FROM BUCKLE INTERMITTANTLY. S40
AREA_CD	
COUNTRY_CD	770
SLS_DLR_CD	USA
TXN_CD	328057
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VRH_LINE_CD	33.26
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	12B
MDL_YR	2001
SORT_INDEX	142
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/22/2000
WRTY_START_D	11/22/2000
NAME	DOWNEY LINCOLN MERCURY
DOC_NUM	078170A
PH_NUM	0810721
WCC_CD	BR02
PART_NUM_CA	3L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	14
CLM_KEY	5028702
MILGE	23718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10348
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field17	C
CPSC_CD_6	11001

TECH_TXT1	ROAD TEST,UNABLE TO VERIFY CONCERN,REPLACE SEAT BELT BUCKLE PER HOTLINE
TECH_TXT2	
CUST_TXT	ADVISE CUST STATES DRIVERS SEAT BELT OPENS WHILE JUST SITTING IN SEAT
AREA_CD	
COUNTRY_CD	582
SLS_DLR_CD	USA
TXN_CD	364081
CNTRY_SOLD	ED4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	4823
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field58	T/WC

ID	128
MDL_YR	2001
SORT_INDEX	148
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/12/2001
NAME	
DOC_NUM	16528601
PH_NUM	5015225
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	328
COND_CD	42
RPR_DT	4/18/2002
TIS_WSD	12
CLM_KEY	8140519
MILGE	10683
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10687
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	
CPSC_CD_6	11001

TECH_TXT1	1 REPLACED LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE LEFT FRONT SEATBELT BUCKLE INTERMITTENTLY COMES LOOSE
AREA_CD	
COUNTRY_CD	903
SLS_DLR_CD	USA
TXN_CD	387311
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	G21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	@
LBR_COST	
VEH_LINK_CD	13
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	130
MDL_YR	2001
SORT_INDEX	147
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	10/15/2001
NAME	FUGMIRE LINCOLN-MERCURY INC
DOC_NUM	8581051
PH_NUM	9522281
WCC_CD	DR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	5/6/2002
TIS_WSD	6
CLM_KEY	7403186
MILGE	7600
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT FAILURE FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUST. STATES DRIVER SEAT BELT COMES UNBUCKLED AT TIMES WHILE DRIVING (SOP) TECH 128	
AREA_CD		
COUNTRY_CD	770	
SLS_DLR_CD	USA	
TXN_CD	328233	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V06	
VRT_CD	B4	
TIS_FLAG	908	
VIN_CD		
LBR_COST		
VRH_LINE_CD	40.24	
MKT_DERIVED	T/B4	
BOD_CAB_STL		
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Field50	T/WC	

ID	131
MDL_YR	2001
SORT_INDEX	149
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	10/30/2000
WRTY_START_D	7/20/2001
NAME	POMPANO LINCOLN-MERCURY INC
DOC_NUM	251081E
PH_NUM	7528110
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	CAA
CUST_CONC_C	823
COND_CD	42
RPR_DT	3/22/2002
TIS_WSD	9
CLM_KEY	7813006
MILGE	11857
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11045
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	*
CPSC_CD_6	11001

TECH_TXT1	11857 42 INOP WARR 6810 REPLACE LT FRT SEAT BELT BUCKLE ASSY GA
TECH_TXT2	
CUST_TXT	S26 LEFT FRONT SEAT BELT FEMALE END NOT WORKING PROPERLY WILL NOT LATCH W
AREA_CD	
COUNTRY_CD	306
SLS_DLR_CD	USA
TXN_CD	325118
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	26.48
MKT_DERIVED	T84
BOD_CAB_STL	.
VER_SERIES_C	TWB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	132
MDL_YR	2001
SORT_INDEX	150
TRANS_CD	TDC
PLANT_CD	AP
PRODN_DT	8/27/2001
WRTY_START_D	5/20/2001
NAME	ASTRO LINCOLN-MERCURY INC
DOC_NUM	15262701
PH_NUM	4788681
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/6/2001
TIS_WSD	1
CLM_KEY	3863895
MILGE	963
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11518
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACR DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	
COUNTRY_CD	850
SLS_DLR_CD	USA
TXN_CD	325123
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	308
VIN_CD	
LBR_COST	
VEH_LINE_CD	23.78
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	133
MDL_YR	2001
SORT_INDEX	181
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/22/2001
WRTY_START_D	7/27/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	6456551
PH_NUM	5394900
WCC_CD	6F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7681208
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	7/28/2001
TIS_WSD	0
CLM_KEY	4122240
MILGE	24
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10184
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INSTALLED BOTH BUCKLES COME LOOSE
TECH_TXT2	
CUST_TXT	CHECK SEAT BELTS BINDS
AREA_CD	
COUNTRY_CD	251
SLS_DLR_CD	USA
TXN_CD	367268
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	49
MKT_DERIVED	T/B4
BOD_CAB_STL	"
VER_SERIES_C	TAWB
DRIVE_CD	T/EL
ENG_CD	T/B
Field59	TAWC

ID	134
MDL_YR	2001
SORT_INDEX	152
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	7/20/2001
NAME	BAYWAY LINCOLN MERCURY, INC.
DOC_NUM	6405351
PH_NUM	9298500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001203
PART_NUM_CA	GAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	0
CLM_KEY	0325100
MILGE	7309
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10003
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field17	#
CPSC_CD_6	11001

TECH_TXT1	LEFT FRONT SEAT BELT WILL NOT LOCK, REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT KEEPS COMING UNBUCKLED
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	387032
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	26.74
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	135
MDL_YR	2001
SORT_INDEX	154
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	2/15/2001
NAME	ALTMAN LINCOLN MERCURY
DOC_NUM	280771A
PH_NUM	7872324
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	11
CLM_KEY	8000577
MILGE	17449
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10488
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
Field37	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT LATCH NOT HOLDING R AND I DRIVERS SEAT TO REPL SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CK FOR DRIVERS SEATELT KEEPS COMING UNHOOKED
AREA_CD	
COUNTRY_CD	843
SLS_DLR_CD	USA
TXN_CD	328365
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	84
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	31.52
MKT_DERIVED	TB4
BOD_CAR_STL	*
VER_SERIES_C	TWB
DRIVE_CD	T1L
ENG_CD	TB
Field50	TWC

ID	138
MDL_YR	2001
SORT_INDEX	155
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/28/2001
NAME	LONG-LEWIS FORD
DOC_NUM	24688101
PH_NUM	9893673
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	528
COND_CD	42
RPR_DT	2/28/2002
TIS_WSD	7
CLM_KEY	7158133
MILGE	14718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	228
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	0713,CK R R SEAT REPL SEAT BELT BUCKEL CC 42 INSIDE LATCH IS NOT STRONG ENOUGH.
TECH_TXT2	
CUST_TXT	S26 CUST STATES DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED AT TIMES, PARTS ORDERED AND HERE.
AREA_CD	
COUNTRY_CD	205
SLS_DLR_CD	USA
TXN_CD	328074
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	25
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/E1
ENG_CD	T/B
Field50	T/WC

ID	137
MDL_YR	2001
SORT_INDEX	167
TRANS_CD	70E
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	9/1/2001
NAME	DON DAVIS LINCOLN MERCURY INC
DOC_NUM	218524A
PH_NUM	2850101
WCC_CD	6R02
PART_NUM_CA	1172
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	9/15/2001
TIS_WSD	1
CLM_KEY	2092650
MILGE	447
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11404
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	
CPSC_CD_6	11001

TECH_TXT1	447 SEAT BELT BUCKLE NOT LATCHING CORRECTLY.REMOVE SEAT REPLACE BUCKLE REINSTALL SEAT.DRIVERS.42 70121
TECH_TXT2	
CUST_TXT	625 DRIVERS SEAT BELT WILL COME UNLATCHED
AREA_CD	
COUNTRY_CD	817
SLS_DLR_CD	USA
TXN_CD	387013
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	508
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.57
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field56	T/WC

ID	138
MDL_YR	2001
SORT_INDRX	165
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	9/5/2001
NAME	PUGMIRE LINCOLN-MERCURY INC
DOC_NUM	6322951
PH_NUM	9522261
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/3/2002
TIS_WSD	5
CLM_KEY	6102253
MILGE	5067
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT INOP TRIM COVER OR PAD FRONT SEAT BACK REPLACE
TECH_TXT2	
CUST_TXT	C S THE DRIVERS SIDE SEAT BELT DOESNT STAY LATCHED
AREA_CD	
COUNTRY_CD	770
SLS_DLR_CD	USA
TXN_CD	328233
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	8048
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	139
MDL_YR	2001
SORT_INDEX	169
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/5/2001
WRTY_START_D	2/26/2001
NAME	MARGATE LINCOLN-MERCURY INC
DOC_NUM	297124A
PH_NUM	8782277
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	GAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/12/2002
TIS_WSD	13
CLM_KEY	7352716
MILGE	20885
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11838
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	0
CPSC_CD_6	11001

TECH_TXT1	20663 42 1L7Z7861203CAA R&R DRIVERS SEAT & R&R DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S40 DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING SOP #293627
AREA_CD	
COUNTRY_CD	305
SLS_DLR_CD	USA
TXN_CD	325256
CNTRY_SOLD	ES4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.48
MKT_DERIVED	T7B4
BOD_CAR_STL	*
VER_SERIES_C	T7WC
DRIVE_CD	T/E1
ENG_CD	T/B
Field50	T7WC

ID	140
MDL_YR	2001
SORT_INDEX	172
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/4/2001
WRTY_START_D	8/27/2001
NAME	PALM SPRINGS LINCOLN-MERCURY
DOC_NUM	086849C
PH_NUM	3282102
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/24/2001
TIS_WSD	4
CLM_KEY	5009781
MILGE	5785
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10007
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE ASSY THAT WOULD NOT LATCH PROPERLY
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT POPS OUT
AREA_CD	
COUNTRY_CD	780
SLS_DLR_CD	USA
TXN_CD	354188
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.52
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	141
MDL_YR	2001
SORT_INDEX	174
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	10/23/2000
WRTY_START_D	6/22/2001
NAME	NORTH FLORIDA LINCOLN-MERCURY
DOC_NUM	3724888
PH_NUM	8424100
WCC_CD	BR02
PART_NUM_CA	1LTZ
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/8/2001
TIS_WSD	6
CLM_KEY	2878174
MILGE	9871
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11830
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	DOES NOT WORK PROP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE DRIVERSEAT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES NOT STAY LATCHED REPLACE BUCLE PART HERE SEE KEY
AREA_CD	
COUNTRY_CD	904
SLS_DLR_CD	USA
TXN_CD	354283
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBB_COST	
VEH_LINE_CD	2550
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	142
MDL_YR	2001
SORT_INDEX	175
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/22/2000
WRTY_START_D	5/30/2001
NAME	PUENTE HILLS FORD
DOC_NUM	2485082
PH_NUM	9843873
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	7/3/2001
TIS_WSD	2
CLM_KEY	2825297
MILGE	1973
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6560
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001