

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 3 OF 6

BOOK 1 OF 43

TECH_TXT1	SEAT BELT FAILURE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT COMES UNDONE WHEN BRAKING
AREA_CD	
COUNTRY_CD	626
SLS_DLR_CD	USA
TXN_CD	354283
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	998
VIN_CD	
LBR_COST	
VEH_LINE_CD	29.69
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	T7WB
DRIVE_CD	T7EL
ENG_CD	T7B
Field50	T7WC

ID	143
MDL_YR	2001
SORT_INDEX	176
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/4/2001
WRTY_START_D	8/23/2001
NAME	GERMAIN LINC-MERC OF NAPLES
DOC_NUM	1807051
PH_NUM	5878011
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	853
COND_CD	41
RPR_DT	12/11/2001
TIS_WSD	4
CLM_KEY	5783828
MILGE	3858
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11624
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	0
CPSC_CD_6	11001

TECH_TXT1	BINDING SEAT REPLACE	TRACK ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	DRIVERS SEATBELT BUCKLE COMES UNDONE PART IN STOCK SEE TED PASS. FRONT IS FALLING ALSO	
AREA_CD		
COUNTRY_CD	B41	
SLS_DLR_CD	USA	
TXN_CD	325044	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V03	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LBR_COST		
VEH_LINE_CD	65.28	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Field50	T/WC	

ID	144
MDL_YR	2001
SORT_INDEX	178
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	7/30/2001
NAME	STAR LINCOLN-MERCURY SALES, IN
DOC_NUM	60827402
PH_NUM	2471003
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	7
CLM_KEY	8878554
MILGE	9459
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	11822
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	1 REPLACE LEFT FRONT SEATBELT LATCH.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT COMES UNBUCKLED BY ITSELF AT TIMES
AREA_CD	
COUNTRY_CD	B18
SLS_DLR_CD	USA
TXN_CD	354301
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	800
VIN_CD	
LBR_COST	
VEH_LINE_CD	73.5
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	145
MDL_YR	2001
SORT_INDEX	184
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	01/12/2000
WPTY_START_D	03/30/2001
NAME	BAYWAY LINCOLN MERCURY, INC.
DOC_NUM	5957251
PH_NUM	8298500
WCC_CD	6R82
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	5
CLM_KEY	4980480
MILGE	4991
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10083
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE WEAK
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLES WILL NOT STAY LATCHED USE SPO 01275014
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	387032
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	80.17
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	146
MDL_YR	2001
SORT_INDEX	100
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	6/22/2000
WRTY_START_D	2/26/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	7343752
PH_NUM	5304000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7581203
PART_NUM_CA	CAA
CUST_CONC_C	T90
COND_CD	42
RPR_DT	12/31/2001
TIS_WSD	11
CLM_KEY	6074790
MILGE	20237
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10164
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SIDE FRONT SEAT BELT POPS OUT OF LOCK
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	387023
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V74
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	28
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	147
MDL_YR	2001
SORT_INDEX	1
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	5/31/2001
NAME	TEMPLE LINCOLN-MERCURY
DOC_NUM	0835088
PH_NUM	7739077
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	GAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	8/21/2001
TIS_WSD	3
CLM_KEY	5519448
MILGE	4500
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10904
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
FidR27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEAT BELT WONT HOLD
TECH_TXT2	
CUST_TXT	CUST SAYS PASS SEAT BELT WONT HOLD
AREA_CD	
COUNTRY_CD	254
SLS_DLR_CD	USA
TXN_CD	387328
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S00
VIN_CD	
LBR_COST	
VBH_LINE_CD	23.04
MKT_DERIVED	T004
BOD_CAB_STL	*
VER_SERIES_C	T7WD
DRIVE_CD	T7EL
ENG_CD	T7E
Field50	T7WC

ID	148
MDL_YR	2001
SORT_INDEX	3
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	6/2/2001
NAME	[REDACTED]
DOC_NUM	42827501
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/24/2001
TIS_WSD	6
CLM_KEY	5508100
MILGE	14168
MTRL_COST	[REDACTED]
TOT_COST_GRO	[REDACTED]
LBR_HRS	[REDACTED]
DLR_CD	45285
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT DISCONNECTS BY ITSELF
AREA_CD	
COUNTRY_CD	*
SLS_DLR_CD	USA
TXN_CD	345834
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	80.8
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	148
MDL_YR	2001
SORT_INDEX	8
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/19/2000
WRTY_START_D	12/7/2001
NAME	BARNEY A SMITH LINC-MERC INC
DOC_NUM	6689601
PH_NUM	7485621
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	1
CLM_KEY	0000078
MILGE	715
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	10128
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	R+R BELT BUCKLE
TECH_TXT2	
CUST_TXT	FRONT LEFT SEAT BELT WILL COME UNATTACHED WHILE DRIVING DOWN THE ROAD
AREA_CD	
COUNTRY_CD	912
SLS_DLR_CD	USA
TXN_CD	326234
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	22.88
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	150
MDL_YR	2001
SORT_INDEX	8
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	8/8/2001
NAME	BAY STATE LINCOLN-MERCURY
DOC_NUM	4581201
PH_NUM	8727800
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	5/28/2001
TIS_WSD	1
CLM_KEY	3371388
MILGE	1480
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10331
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	1 REPLACED SEAT BELT BUCKLE DRIVERS SEAT
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE IS NOT HOLDING PART IN STOCK
AREA_CD	
COUNTRY_CD	508
SLS_DLR_CD	USA
TXN_CD	312145
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	806
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.52
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	T7WD
DRIVE_CD	T7EL
ENG_CD	T7E
Field50	T7WC

ID	151
MDL_YR	2001
SORT_INDEX	10
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	8/6/2001
NAME	PAUL CERAME LINC-MERG INC
DOC_NUM	216488B
PH_NUM	8310200
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/22/2002
TIS_WSD	7
CLM_KEY	7723948
MILGE	10175
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12826
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Field27	G
CPSC_CD_6	11001

TECH_TXT1	INSPECTED SEAT BELT ASSEMBLY, UNABLE TO VERIFY CONCERN, INSPECTED SEAT BELT LATCH ASSEMBLY, NO FOREIGN MATERIAL IN LATCH, ORDERED LATCH.
TECH_TXT2	
CUST_TXT	828 CUST SAYS L F SEAT BELT KEEPS POPPING OFF
AREA_CD	
COUNTRY_CD	314
SLS_DLR_CD	178A
TXN_CD	983904
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	B08
VIN_CD	
LBR_COST	
VEH_LINE_CD	90.99
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	152
MDL_YR	2001
SORT_INDEX	11
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	6/17/2001
NAME	GALPIN LINCOLN-MERCURY
DOC_NUM	3625312
PH_NUM	8923600
WCC_CD	BR02
PART_NUM_CA	F85Z
PART_NUM_CA	7861203
PART_NUM_CA	BDE
CUST_CONC_C	825
COND_CD	42
RPR_DT	7/9/2001
TIS_WSD	2
CLM_KEY	3132698
MILGE	4180
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11820
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	12001

TECH_TXT1	VERIFIED CONCERN, PERFORMED 01S21 RECALL AND REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST STS DRIVERS SEAT BELT BUCKLE DOESNT STAY LATCHED SOMETIMES
AREA_CD	
COUNTRY_CD	B1B
SLS_DLR_CD	USA
TXN_CD	354301
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	80B
VIN_CD	
LBR_COST	
VEH_LINE_CD	48.00
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	153
MDL_YR	2001
SORT_INDEX	17
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/11/2001
WRTY_START_D	7/10/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	4588152
PH_NUM	8414560
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	41
RPR_DT	2/27/2002
TIS_WSD	8
CLM_KEY	7149123
MILGE	12218
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	*
CPSC_CD_6	11001

TECH_TXT1	B L F SEAT BELT BUCKLE DOESNT LATCH ALL THE TIME, REPL BUCKLE
TECH_TXT2	
CUST_TXT	C S LEFT FRONT SEATBELT DOES NOT LATCH AT TIMES. INT TRIM CODE KH
AREA_CD	
COUNTRY_CD	407
SLS_DLR_CD	USA
TXN_CD	32B180
CNTRY_SOLD	ES4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	1327
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VEH_SERIES_C	T/W0
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	154
MDL_YR	2001
SORT_INDEX	18
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	1/31/2001
NAME	HAVRE FORD LINCOLN MERCURY
DOC_NUM	078047A
PH_NUM	2652246
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/27/2001
TIS_WSD	11
CLM_KEY	5837411
MILGE	8843
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3118
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MT
Field27	*
CPSC_CD_6	11001

TECH_TXT1	FOUND LATCH TO BE FAULTY, REPLACED LATCH ASSEMBLY
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT DOESNT LATCH AT TIMES
AREA_CD	
COUNTRY_CD	408
SLS_DLR_CD	USA
TXN_CD	3B403R
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V08
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	S1.03
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WC
DRIVE_CD	T/E1
ENG_CD	T/E
Field50	T/WC

ID	155
MDL_YR	2001
SORT_INDEX	18
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	2/17/2001
NAME	ROCKLAND LINCOLN MERCURY SALES
DOC_NUM	1228102
PH_NUM	3586400
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	925
COND_CD	42
RPR_DT	12/3/2001
TIS_WSD	10
CLM_KEY	5532144
MILGE	11881
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10088
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Field27	C
CPSC_CD_6	11001

TECH_TXT1	. VERIFIED CUST CONCERN, INSTALLED NEW SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUST STATES THAT DRIVERS SIDE SEAT BELT LINHOOKS ON ITS OWN.
AREA_CD	
COUNTRY_CD	914
SLS_DLR_CD	USA
TXN_CD	314641
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	32.5
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	166
MDL_YR	2001
SORT_INDEX	20
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	3/28/2001
NAME	COUNTRY LINC-MERC SALES INC
DOC_NUM	6668563
PH_NUM	2718800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7661209
PART_NUM_CA	CAA
CUST_CONC_C	828
COND_CD	1
RPR_DT	4/20/2002
TIS_WSD	14
CLM_KEY	8142287
MILGE	8843
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13307
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
Field27	c
CPSC_CD_6	11001

TECH_TXT1	UNLATCH FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUSTOMER STATES CK BOTH FRONT SEAT BELTS UNLATCH AT TIMES FOR NO REASON	
AREA_CD		
COUNTRY_CD	516	
SLS_DLR_CD	USA	
TXN_CD	314150	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V03	
VRT_CD	B4	
TIS_FLAG	608	
VIN_CD	Q	
LBR_COST		
VEH_LINE_CD	6276	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	TWD	
DRIVE_CD	T/EL	
ENG_CD	T/E	
Field50	T/WC	

ID	157
MDL_YR	2001
SORT_INDEX	21
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	7/29/2001
NAME	DANA MOTORS LTD
DOC_NUM	8842652
PH_NUM	8838700
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	B15
COND_CD	42
RPR_DT	9/27/2001
TIS_WSD	3
CLM_KEY	4010893
MILGE	4500
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11281
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
Field27	*
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT NOT LOCKING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	C STATES DRIVES SIDE SEAT BELT DONT LOCK.
AREA_CD	
COUNTRY_CD	718
SLS_DLR_CD	USA
TXN_CD	314081
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	B4
TIS_FLAG	S06
VIN_CD	
LBR_COST	
VEH_LINE_CD	35.08
MKT_DERIVED	7784
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	TVEL
ENG_CD	T/E
Field50	TWC

ID	158
MDL_YR	2001
SORT_INDEX	26
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/21/2000
WRTY_START_D	9/4/2001
NAME	VARSITY LINCOLN-MERCURY INC
DOC_NUM	8863301
PH_NUM	3065300
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/20/2001
TIS_WSD	2
CLM_KEY	4093838
MILGE	3587
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10011
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	*
CPSC_CD_6	11001

TECH_TXT1	7881203 42 VERIFIED CONCERN INSPECT AND TEST SEAT BELT LATCH FOUND LATCH NOT LATCHING PROPERLY R&R DRIVERS SEAT REPLACED
TECH_TXT2	
CUST_TXT	CK ADVISE DRIVERS SEAT BELT INOP PARTS NOW IN STOCK
AREA_CD	
COUNTRY_CD	010
SLS_DLR_CD	USA
TXN_CD	348336
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	40.05
MKT_DERIVED	TBA
BOD_CAB_STL	
VER_SERIES_C	TWD
DRIVE_CD	TFL
ENG_CD	T/E
Field50	TWC

ID	198
MDL_YR	2001
SORT_INDEX	28
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	6/30/2001
NAME	OLATHE LINCOLN-MERCURY INC
DOC_NUM	5917582
PH_NUM	7827820
WCC_CD	0R02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/21/2001
TIS_WSD	8
CLM_KEY	6880629
MILGE	14112
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12903
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	KS
Field27	b
CPSC_CD_6	11001

TECH_TXT1	VERIFY CONCERN, REPLACE DRIVERS SEAT BELT LATCH ASSY WILL NOT HOLD SECURLY
TECH_TXT2	
CUST_TXT	THE DRIVERS SEATBELT WILL UNLATCH ON ITS OWN WHEN DRIVING
AREA_CD	
COUNTRY_CD	B13
SLS_DLR_CD	USA
TXN_CD	383558
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S06
VIN_CD	
LBR_COST	
VEH_LINE_CD	14.16
MKT_DERIVED	T/84
BOD_CAB_STL	*
VRR_SERIES_C	TWC
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	100
MDL_YR	2001
SORT_INDEX	30
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/3/2001
WRTY_START_D	9/8/2001
NAME	FIESTA LINCOLN-MERCURY
DOC_NUM	3987401
PH_NUM	8134800
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	5
CLM_KEY	8242132
MILGE	6080
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11806
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REMOVE DRIVERS SEAT FOR ACCESS, REPLACE DRIVERS SEAT BUCKLE #81203, CODE 42, TECH 9871
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES LOOSE WHEN DRIVING INSTALL SOP
AREA_CD	
COUNTRY_CD	480
SLS_DLR_CD	USA
TXN_CD	354288
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	806
VIN_CD	
LBR_COST	
VRH_LINE_CD	58.82
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EI
ENG_CD	T/E
Field58	TWC

ID	161
MDL_YR	2001
SORT_INDEX	31
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	3/30/2001
NAME	BANKSTON L-M, INC.
DOC_NUM	3830402
PH_NUM	2331441
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	626
COND_CD	33
RPR_DT	3/11/2002
TIS_WSD	12
CLM_KEY	7353548
MILGE	19882
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13589
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11003

TECH_TXT1	33 81203 VERIFY CUSTOMERS CONCERN.REPLACE DRIVERS SEAT BELT BUCKLE. LOOSE
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS SEATBELT BUCKLE KEEPS POPPING LOOSE
AREA_CD	
COUNTRY_CD	872
SLS_DLR_CD	USA
TXN_CD	987985
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	14.08
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	182
MDL_YR	2001
SORT_INDEX	33
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	8/13/2001
NAME	HCAULEY MOTORS INC
DOC_NUM	1000952
PH_NUM	7222777
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	926
COND_CD	42
RPR_DT	2/5/2002
TIS_WSD	8
CLM_KEY	6747868
MILGE	4518
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	127D1
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT NOT STAYING ENGAGED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEATBELT NOT STAYING ENGAGED
AREA_CD	
COUNTRY_CD	209
SLS_DLR_CD	USA
TXN_CD	351077
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S05
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.77
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	163
MDL_YR	2001
SORT_INDEX	35
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	7/15/2001
NAME	GLENWOOD SPRINGS FORD-LIN-MER,
DOC_NUM	903901
PH_NUM	9452317
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/8/2001
TIS_WSD	1
CLM_KEY	3284604
MILGE	3123
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	3172
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	FOUND DRIVERS SIDE SEAT BELT BROKEN. R&R DRIVERS SEAT BELT. VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT CAME UNLATCHED WHILE DRIVING. 840
AREA_CD	
COUNTRY_CD	970
SLS_DLR_CD	USA
TXN_CD	355491
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	97.4
MKT_DERIVED	T84
BOD_CAB_STL	
VER_SERIES_C	TWD
DRIVE_CD	TFL
ENG_CD	T/E
Field50	TWC

ID	184
MDL_YR	2001
SORT_INDEX	38
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	12/17/2000
WRTY_START_D	1/4/2001
NAME	UPTOWN MOTORS, INC.
DOC_NUM	137181A
PH_NUM	7719000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/4/2001
TIS_WSD	10
CLM_KEY	4258776
MILGE	10599
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12152
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WI
Field27	h
CPSC_CD_6	11001

TECH_TXT1	REMOVE AND INSTALL SEAT BELTS
TECH_TXT2	
CUST_TXT	INSTALL SOP SEATBELT BUCKLES BOTH FRONT, WONT STAY LATCHED, RO 138815 TECH 7819
AREA_CD	
COUNTRY_CD	414
SLS_DLR_CD	USA
TXN_CD	342527
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	806
VIN_CD	
LBR_COST	
VEH_LINE_CD	8028
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E1
ENG_CD	T/E
Field59	T/WC

ID	165
MDL_YR	2001
SORT_INDEX	41
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	3/16/2001
NAME	SLOAN MOTORS INC
DOC_NUM	068712B
PH_NUM	3632870
WCC_CD	8R02
PART_NUM_CA	1L72
PART_NUM_CA	7801203
PART_NUM_CA	CAB
CUST_CONC_C	328
COND_CD	42
RPR_DT	3/13/2002
TIS_WSD	13
CLM_KEY	7412674
MILGE	28853
MTBL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1200
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
Field27	
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 319 of 442

RQ04-011 E 0328

TECH_TXT1	REPLACE DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WONT LATCH
AREA_CD	
COUNTRY_CD	610
SLS_DLR_CD	USA
TXN_CD	315062
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	909
VIN_CD	
LBR_COST	
VEH_LINE_CD	53.37
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/W0
DRIVE_CD	T/E1
ENG_CD	T/E
Field50	T/WC

ID	168
MDL_YR	2001
SORT_INDEX	43
TRANS_CD	T/DI
PLANT_CD	AP
PRODN_DT	3/5/2001
WRTY_START_D	3/18/2001
NAME	CODROLI LINCOLN-MERCURY
DOC_NUM	3554851
PH_NUM	2847700
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	2/5/2002
TIS_WSD	11
CLM_KEY	8903421
MILGE	15410
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12718
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Flid27	x
CPSC_CD_6	11001

TECH_TXT1	REPLACE BELT INOP
TECH_TXT2	
CUST_TXT	LT FRONT SEAT BELT WONT LATCH AT TIMES S O
AREA_CD	
COUNTRY_CD	925
SLS_DLR_CD	USA
TXN_CD	351078
CNTRY_SOLD	EM4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	60.12
MKT_DERIVED	T84
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWIC

ID	167
MDL_YR	2001
SORT_INDEX	45
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	4/7/2001
NAME	FRED BEANS FORD-LINCOLN-MERCUR
DOC_NUM	27286202
PH_NUM	3482900
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	9/27/2001
TIS_WSD	6
CLM_KEY	4338246
MILGE	7131
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1203
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLAGE (811A72 811A73) 61203,925.42
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT BUCKLE RELEASE CLIP DOES NOT COME ALL THE UP WHEN ENGAGED
AREA_CD	
COUNTRY_CD	215
SLS_DLR_CD	USA
TXN_CD	315071
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	84
TIS_FLAG	308
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.14
MKT_DERIVED	T/84
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	108
MDL_YR	2001
SORT_INDEX	50
TRANS_CD	T/DI
PLANT_CD	AP
PRODN_DT	5/23/2001
WRTY_START_D	8/15/2001
NAME	REEDMAN LINCOLN MERCURY
DOC_NUM	34598801
PH_NUM	*
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/8/2001
TIS_WSD	0
CLM_KEY	3183477
MILGE	6
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10435
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECK BOTH FRONT SEATBELT BUCKLES WILL NOT STAY LATCHED, REPLACED BOTH BUCKLES
TECH_TXT2	
CUST_TXT	
AREA_CD	
COUNTRY_CD	*
SLS_DLR_CD	USA
TXN_CD	315148
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	43A1
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E1
ENG_CD	TE
Field50	TWC

ID	169
MDL_YR	2001
SORT_INDEX	51
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/23/2001
WRTY_START_D	6/28/2001
NAME	NORTHEAST LINCOLN-MERCURY
DOC_NUM	12896304
PH_NUM	3318800
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	0
CLM_KEY	3229810
MILGE	4
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10484
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT LATCH WONT LOCK 540 42 CHECK AND REPLACE LEFT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RECALL 01821 SEAT BELT INSPECTION NOT ON RECALL BUT LEFT BUCKLE WONT LATCH
AREA_CD	
COUNTRY_CD	215
SLS_DLR_CD	USA
TXN_CD	315308
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	57.40
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E
ENG_CD	T/E
Flt1450	T/WC

ID	170
MDL_YR	2001
SORT_INDEX	55
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/17/2001
NAME	MEL FARR LINCOLN-MERCURY INC
DOC_NUM	2574548
PH_NUM	8839500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	9/12/2001
TIS_WSD	1
CLM_KEY	3727057
MILGE	1237
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10010
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1237 01 INSPECTED ABD FOUND BAD SEAT BELTLATCH / REPLACED DRIVER SEAT BELT LATCH RECHECKED GOOD
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT UNHOOKS WHILE DRIVING
AREA_CD	
COUNTRY_CD	B10
SLS_DLR_CD	USA
TXN_CD	345275
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	14.43
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	171
MDL_YR	2001
SORT_INDEX	58
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/4/2001
WRTY_START_D	6/15/2001
NAME	NORTHTOWNE LINCOLN-MERCURY INC
DOC_NUM	12078701
PH_NUM	4582710
WCC_CD	BRQ2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	1/9/2002
TIS_WSD	7
CLM_KEY	8158487
MILGE	10584
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12828
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	TESTED THE SEAT BELT CAME UNLATCHED PUT IN A NEW BUCKLE TESTED DID NOT COME UNDONE MOVED THE LATCH AROUND
TECH_TXT2	
CUST_TXT	826 CUST STATE LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING & LATCH ON BELT IS BACKWARD
AREA_CD	
COUNTRY_CD	816
SLS_DLR_CD	USA
TXN_CD	363959
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TTS_FLAG	908
VIN_CD	
LRR_COST	
VEH_LINE_CD	28.49
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	172
MDL_YR	2001
SORT_INDEX	50
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/26/2001
WRTY_START_D	3/6/2001
NAME	VARSITY LINCOLN-MERCURY INC
DOC_NUM	9788202
PH_NUM	3055300
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/4/2002
TIS_WSD	12
CLM_KEY	8721834
MILGE	13542
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10011
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	C
CPSC_CD_6	11001

TECH_TXT1	81203 42 VERIFY CONCERN, REPLACE LH FR SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL INTERMITTENTLY COME UNLATCHED
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	345335
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S05
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.32
MKT_DERIVED	T/84
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	173
MDL_YR	2001
SORT_INDEX	63
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	3/24/2001
NAME	MAPLECREST LINCOLN-MERCURY, IN
DOC_NUM	0041103
PH_NUM	.
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	626
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	12
CLM_KEY	7464731
MILGE	14241
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10280
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	NJ
Field27	c
CPSC_CD_6	19001

Tuesday, December 14, 2004

Page 345 of 442

RQ04-011 E 0345

TECH_TXT1	1 1 CHECK AND REPLACE SEATBELT
TECH_TXT2	
CUST_TXT	OWNER STATES LEFT FRONT SEATBELT RELEASES ON OWN
AREA_CD	
COUNTRY_CD	
SLS_DLR_CD	USA
TXN_CD	314474
CNTRY_SOLD	ES4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	32.06
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field56	T/WC

ID	174
MDL_YR	2001
SORT_INDEX	85
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	8/28/2001
NAME	KUMPF LINCOLN MERCURY, INC.
DOC_NUM	130104A
PH_NUM	7811580
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/11/2001
TIS_WSD	1
CLM_KEY	4358713
MILGE	488
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11058
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPL SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT ON DRIVERS SIDE UN LATCHES ITSELF
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	355115
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	308
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.22
MKT_DERIVED	TBA
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/E
ENG_CD	T/E
Field50	TWC

ID	175
MDL_YR	2001
SORT_INDEX	67
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/14/2001
WRTY_START_D	7/7/2001
NAME	VALLEY FORD LINCOLN-MERCURY
DOC_NUM	4353158
PH_NUM	5845531
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	880
COND_CD	33
RPR_DT	12/17/2001
TLS_WSD	0
CLM_KEY	5909148
MILGE	10276
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7887
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

Thursday, December 14, 2006

Page 349 of 442

RQ04-011 E 0349

TECH_TXT1	63: VERIFY DRIVERS SEATBELT UNLATCHES, R&R FRONT SEAT AND REPLACED SEATBELT BUCKLE, REASSEMBLE, RECHECK OK AT THIS TIME
TECH_TXT2	
CUST_TXT	CUSTOMER STATED THE DRIVERS SEAT BELT HAS COME UNLOCKED THREE DIFFERENT TIMES
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	USA
TXN_CD	851048
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	84
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	74.97
MKT_DERIVED	TBA
BOD_CAB_STL	
VER_SERIES_C	TAND
DRIVE_CD	TFL
ENG_CD	T/E
Field50	TWNC

ID	176
MDL_YR	2001
SORT_INDEX	68
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/7/2001
WRTY_START_D	3/28/2001
NAME	FIESTA LINCOLN-MERCURY
DOC_NUM	3365401
PH_NUM	8134800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S03
COND_CD	41
RPR_DT	1/11/2002
TIS_WSD	10
CLM_KEY	8271235
MILGE	13248
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11898
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Field27	C
CPSC_CD_6	11001

TECH_TXT1	CODE 41,7501203,SEAT BELT BUCKLE BINDING TECH 245 SS 0994 REMOVE DRIVERS SEAT TO ACCESS,REMOVE AND REPLACE SEAT BELT BUCKLE,REINSTALL DRIVERS SEAR.TECH 245 SS 0994
TECH_TXT2	
CUST_TXT	C S THAT LEFT FRONT SEAT KEEPS COMING LOOSE CHECK AND ADVISE
AREA_CD	
COUNTRY_CD	480
SLS_DLR_CD	USA
TXN_CD	354289
CNTRY_SOLD	EM4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	29.31
MKT_DERIVED	T/94
BOD_CAR_STL	*
VER_SERIES_C	TWVD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WG

ID	177
MDL_YR	2001
SORT_INDEX	70
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	5/23/2001
NAME	BURT LINCOLN MERCURY
DOC_NUM	1009148
PH_NUM	3508000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	7
CLM_KEY	5818838
MILGE	10522
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REMOVE DRIVERS SEAT TO REPLACE SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	SAYS DRIVER SEAT BELT WONT STAY LATCHED POPS OUT WHILE DRIVING
AREA_CD	
COUNTRY_CD	908
SLS_DLR_CD	USA
TXN_CD	368208
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S06
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.22
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T7ND
DRIVE_CD	T/E
ENG_CD	T/E
Field50	T/WC

ID	178
MDL_YR	2001
SORT_INDEX	71
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	7/9/2001
NAME	KUMPF LINCOLN MERCURY, INC.
DOC_NUM	127955A
PH_NUM	7811580
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPE_DT	8/13/2001
TIS_WSD	2
CLM_KEY	3807878
MILGE	1082
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11058
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPL SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT WILL RELEASE AT TIMES, SOP IS IN
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	355115
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.22
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WC
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	179
MDL_YR	2001
SORT_INDEX	73
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/25/2001
WRTY_START_D	4/10/2001
NAME	OLYMPIC LINCOLN-MERCURY INC
DOC_NUM	18616501
PH_NUM	3848500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	528
COND_CD	41
RPR_DT	3/1/2002
TIS_WSD	11
CLM_KEY	7202388
MILGE	27533
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13013
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACED LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE UNCOUPLES WHILE IN USE
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	USA
TXN_CD	354708
CNTRY_SOLD	E64
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	15.13
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Fldd58	T/WG

ID	180
MDL_YR	2001
SORT_INDEX	78
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	2/25/2002
NAME	MARMIE FORD-LINCOLN-MERCURY
DOC_NUM	8358502
PH_NUM	7896427
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	1
CLM_KEY	8196884
MILGE	4801
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5247
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KS
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT WONT LATCH
AREA_CD	
COUNTRY_CD	820
SLS_DLR_CD	USA
TXN_CD	383174
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	SIB
VIN_CD	
LBR_COST	
VEH_LINE_CD	17.72
MKT_DERIVED	Y/B4
BOD_CAR_STL	*
VER_SERIES_C	TAWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/MC

ID	181
MDL_YR	2001
SORT_INDEX	77
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	02/02/2001
NAME	COUNTRY LINC-MERC SALES INC
DOC_NUM	6906462
PH_NUM	2718800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881209
PART_NUM_CA	CAS
CUST_CONC_C	325
COND_CD	42
RPR_DT	12/14/2001
TIS_WSD	9
CLM_KEY	5734427
MILGE	1983
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13307
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Field27	
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 361 of 442

RQ04-011 E 0361

TECH_TXT1	INOP REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	C 8 DRIVERS SEAT BELT NOT LOCKING (SOP)	
AREA_CD		
COUNTRY_CD	518	
SLS_DLR_CD	USA	
TXN_CD	314017	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LRR_COST		
VEH_LINE_CD	35.18	
MKT_DERIVED	T/B4	
BOD_CAB_STL		
VER_SERIES_C	TMD	
DRIVE_CD	T/EL	
ENG_CD	T/E	
Field50	TMC	

ID	152
MDL_YR	2001
SORT_INDEX	79
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	8/18/2001
NAME	BRIGHTON FORD-MERCURY, INC.
DOC_NUM	134422A
PH_NUM	2271171
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	340
COND_CD	42
RPR_DT	3/20/2002
TIS_WSD	8
CLM_KEY	7620077
MILGE	10500
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2707
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	b
CPSC_CD_6	11001

TECH_TXT1	19600 BASIC 7981203 CONDITION 42 REPLACED LEFT FRONT SEATBELT BUCKLE THAT WOULD NOT STAY LATCHED OK NOW.
TECH_TXT2	
CUST_TXT	LEFT FRT SEAT BELT AT TIMES RELEASES FROM BUCKLE FOR NO REASON
AREA_CD	
COUNTRY_CD	810
SLS_DLR_CD	USA
TXN_CD	348275
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	500
VIN_CD	
LRR_COST	
VEH_LINE_CD	27.00
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	183
MDL_YR	2001
SORT_INDEX	80
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	2/17/2001
NAME	NAPLETON LINCOLN-MERCURY
DOC_NUM	073316A
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/13/2001
TIS_WSD	10
CLM_KEY	6762105
MILGE	8501
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1027B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
Field27	8
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEAT BELT BUCKLE C
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT LATCH DRIVERS FRONT
AREA_CD	
COUNTRY_CD	*
SLS_DLR_CD	USA
TXN_CD	342402
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	908
VIN_CD	
LBR_COST	
VEH_LINE_CD	32.08
MKT_DERIVED	TB4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	TWC

ID	184
MDL_YR	2001
SORT_INDEX	00
TRANS_CD	TRDE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	9/28/2001
NAME	LITHIA LINCOLN MERCURY OF BOIS
DOC_NUM	350058A
PH_NUM	3235200
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	CAA
CUST_CONC_C	T80
COND_CD	42
RPR_DT	11/1/2001
TIS_WSD	2
CLM_KEY	4002829
MILGE	1974
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	ID
Field17	c
CPSC_CD_6	11001

TECH_TXT1	1974 42 42 THE CUSTOMER STATES THE DRIVERS SIDE FRONT SEAT BELT INTERMINTELY WILL UNLATCH VERIFIED THE PROBLEM I REPLACED THE DRIVERS SIDE FRONT SEAT BELT BUCKLE AS NEEDED MILES OUT 1974 FAILED PA
TECH_TXT2	RT 1L7Z 7961203 CAA
CUST_TXT	790 C 6 THE DVS FRONT SEAT BELT INTERMIT WILL UNLATCH
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	USA
TXN_CD	356676
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V74
VRT_CD	B4
TIS_FLAG	308
VIN_CD	
LBR_COST	
VEH_LINE_CD	18.98
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	TWWD
DRIVE_CD	T/E/L
ENG_CD	T/E
Field56	T/W/C

ID	185
MDL_YR	2001
SORT_INDEX	87
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/17/2001
WRTY_START_D	4/18/2001
NAME	THEISEN MOTORS INC
DOC_NUM	9932701
PH_NUM	7397700
WCC_CD	BR02
PART_NUM_CA	1LZ
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/4/2001
TIS_WSD	6
CLM_KEY	3884807
MILGE	6887
MTRL_COST	
TOT_COST_GRO	
LAB_HRS	
DLR_CD	12930
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	ID
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REMOVE AND REPLACE DRIVERS FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT FOR DRIVER WILL NOT LATCH
AREA_CD	
COUNTRY_CD	208
SLS_DLR_CD	USA
TXN_CD	355486
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	25
MKT_DERIVED	T/B4
BOD_CAR_STL	*
VER_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	188
MDL_YR	2001
SORT_INDEX	89
TRANS_CD	TRDE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	8/28/2001
NAME	BURT LINCOLN MERCURY
DOC_NUM	103828E
PH_NUM	3808000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	3/11/2002
TIS_WSD	9
CLM_KEY	7508304
MILGE	9428
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10472
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Field27	a
CPSC_CD_6	11001

TECH_TXT1	BUCKLE WILL NOT OPERATE PROPERLY REPLACE LEFT SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL NOT CLIP SOP HERE
AREA_CD	
COUNTRY_CD	303
SLS_DLR_CD	USA
TXN_CD	356120
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S03
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.22
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WO
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	187
MDL_YR	2001
SORT_INDEX	97
TRANS_CD	T/DE
PLANT_CD	AP
FRODN_DT	3/18/2001
WRTY_START_D	8/15/2001
NAME	MOMENTUM LINCOLN MERCURY, INC.
DOC_NUM	7771953
PH_NUM	2412080
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/8/2001
TIS_WSD	4
CLM_KEY	5702720
MILGE	5347
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10485
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	b
CPSC_CD_6	11001