

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 4 OF 6

BOOK 1 OF 43

TECH_TXT1	R&R SEATBELT BUCKLE DR. FRONT TESTED FAULTY
TECH_TXT2	
CUST_TXT	DR FRT SEATBELT DOES NOT STAY LATCHED
AREA_CD	
COUNTRY_CD	734
SLS_DLR_CD	USA
TXN_CD	345352
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	39.8
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WD
DRIVE_CD	T/EL
ENG_CD	T/E
Field59	T/WC

ID	188
MDL_YR	2001
SORT_INDEX	101
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	8/2/2001
NAME	SOUTHWEST LINCOLN-MERCURY INC
DOC_NUM	22702801
PH_NUM	8813500
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/8/2001
TIS_WSD	2
CLM_KEY	2881304
MILGE	2888
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11458
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	G
CPSC_CD_6	11001

TECH_TXT1	1 REPLACE DRIVERS SEAT BELT COMES UNLATCHED
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SEAT BELT COMES UNLATCHED S40
AREA_CD	
COUNTRY_CD	713
SLS_DLR_CD	USA
TXN_CD	387208
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	C21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	E32
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWD
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	188
MDL_YR	2001
SORT_INDEX	103
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	6/21/2001
NAME	HOLMAN LINCOLN-MERCURY
DOC_NUM	187853A
PH_NUM	2344900
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	8/21/2001
TIS_WSD	5
CLM_KEY	3823744
MILGE	3126
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10408
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECK AND REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	D S SEAT BELT DOES NOT STAY BUCKLED
AREA_CD	
COUNTRY_CD	609
SLS_DLR_CD	USA
TXN_CD	315040
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	C21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.41
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TW0
DRIVE_CD	T/EL
ENG_CD	T/E
Field50	T/WC

ID	190
MDL_YR	2001
SORT_INDEX	109
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	10/9/2000
WRTY_START_D	5/31/2001
NAME	STIVERS LINCOLN-MERCURY INC
DOC_NUM	2702551
PH_NUM	2435200
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	41
RPR_DT	8/10/2001
TIS_WSD	3
CLM_KEY	2915030
MILGE	5173
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12532
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IA
Field17	8
CPSC_CD_6	11001

TECH_TXT1	WONT LATCH FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED	
AREA_CD		
COUNTRY_CD	816	
SLS_DLR_CD	USA	
TXN_CD	363589	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	VO6	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LBR_COST		
VEH_LINE_CD	28.38	
MKT_DERIVED	T84	
BOD_CAB_STL		
VER_SERIES_C	TWD	
DRIVE_CD	T/E	
ENG_CD	T/E	
Field50	TWC	

ID	181
MDL_YR	2001
SORT_INDEX	115
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	9/18/2001
NAME	BARANCO LINCOLN-MERCURY INC
DOC_NUM	2485101
PH_NUM	4978900
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/31/2001
TIS_WSD	4
CLM_KEY	6000127
MILGE	8041
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10167
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

ID	182
MDL_YR	2001
SORT_INDEX	118
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/23/2001
NAME	BOB RODGERS MOTOR CO., INC.
DOC_NUM	10824301
PH_NUM	2380485
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/20/2001
TIS_WSD	7
CLM_KEY	8097682
MILGE	13878
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	8878
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
Field27	b
CPSC_CD_6	11001

TECH_TXT1	NECESSARY TO REPLACE LEFT FRONT SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT BUCKLE WILL NOT STAY LATCHED.
AREA_CD	
COUNTRY_CD	405
SLS_DLR_CD	USA
TXN_CD	367331
CNTRY_SOLD	E94
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LRR_COST	
VEH_LINE_CD	41.29
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	193
MDL_YR	2001
SORT_INDEX	117
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/18/2001
WRTY_START_D	7/28/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	3782854
PH_NUM	8414650
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	41
RPR_DT	9/18/2001
TIS_WSD	2
CLM_KEY	4188238
MILGE	2792
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSPECTED,LF SEAT BUCKLE WILL NOT LATCH,R&REPLACED LF SEAT BELT BUCKLE ASY.VERIFY REPAIR.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WONT STAY LATCHED
AREA_CD	
COUNTRY_CD	407
SLS_DLR_CD	USA
TXN_CD	325189
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	20.63
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	194
MDL_YR	2001
SORT_INDEX	122
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/30/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	3499961
PH_NUM	8414550
WCC_CD	9R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	2
CLM_KEY	2731428
MILGE	2850
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10021
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	UNLOCKS SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVER S SEAT BELT KEEPS UNLOCKING WHILE DRIVING SEE FILE
AREA_CD	
COUNTRY_CD	407
SLS_DLR_CD	USA
TXN_CD	325189
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	2853
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	T7WB
DRIVE_CD	T7EL
ENG_CD	T7B
Field30	T7WC

ID	195
MDL_YR	2001
SORT_INDEX	123
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	8/5/2001
NAME	COVINGTON PIKE LINCOLN MERCURY
DOC_NUM	8188101
PH_NUM	3735700
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/22/2001
TIS_WSD	3
CLM_KEY	3229238
MILGE	8270
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10198
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED LFT FRT SEAT BELT BUCKLE ASSY. COMES LOOSE WHILE DRIVING.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVER SEAT BELT COMES OUT WHILE DRIVING SOP IN
AREA_CD	
COUNTRY_CD	901
SLS_DLR_CD	USA
TXN_CD	322984
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AFS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	27.9
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field58	T/WC

ID	190
MDL_YR	2001
SORT_INDEX	125
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	8/24/2001
NAME	MARGATE LINCOLN-MERCURY INC
DOC_NUM	291814B
PH_NUM	9782277
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/26/2001
TIS_WSD	7
CLM_KEY	6771478
MILGE	14937
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11638
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	a
CPSC_CD_6	11001

TECH_TXT1	14837 42 W RR LT FT SEAT TO REPLACE SEAT BELT BUCKLE SOP
TECH_TXT2	
CUST_TXT	S40,LEFT FRT SEAT BELT WONT LATCH.
AREA_CD	
COUNTRY_CD	306
SLS_DLR_CD	USA
TXN_CD	325256
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	33.07
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	TWB3
DRIVE_CD	T/E1
ENG_CD	T/B
Field50	T/WC

ID	197
MDL_YR	2001
SORT_INDEX	127
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/5/2001
WRTY_START_D	5/17/2001
NAME	RAY PEARMAN LINCOLN MERCURY, I
DOC_NUM	2385301
PH_NUM	5387451
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	12
RPR_DT	8/5/2001
TYS_WSD	4
CLM_KEY	3441443
MILGE	7819
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	12046
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	LEFT FRONT SEATBELT WONT BUCKLE REPLACED LEFT FRONT SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT COMES LOOSE AFTER BUCKLING TRIM KH
AREA_CD	
COUNTRY_CD	205
SLS_DLR_CD	USA
TXN_CD	328330
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	48.51
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	T7WB
DRIVE_CD	T1EL
ENG_CD	T7B
Field50	T7WC

ID	180
MDL_YR	2001
SORT_INDEX	128
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/16/2001
WRTY_START_D	8/22/2001
NAME	ANTELOPE VALLEY FORD
DOC_NUM	8770261
PH_NUM	9483588
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	7/20/2001
TIS_WSD	1
CLM_KEY	4000482
MILGE	1701
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5428
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	WONT STAY LATCHED DRIVERS SIDE SEAT BELT	REPLACED
TECH_TXT2		
CUST_TXT	CURT STATES DRIVER SEAT BELT WONT STAY LATCHED	
AREA_CD		
COUNTRY_CD	806	
SLS_DLR_CD	LISA	
TXN_CD	354133	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LBR_COST		
VEH_LINE_CD	53.78	
MKT_DERIVED	T/64	
BOD_CAB_STL		
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Field50	T/WC	

ID	109
MDL_YR	2001
SORT_INDEX	133
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	5/25/2001
NAME	EAGLE LINCOLN-MERCURY INC
DOC_NUM	40573902
PH_NUM	3570461
WCC_CD	SR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/10/2001
TIS_WSD	7
CLM_KEY	6793222
MILGE	11789
MTBL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10865
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT LATCH,RECHECKED OK.
TECH_TXT2	
CUST_TXT	CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.
AREA_CD	
COUNTRY_CD	214
SLS_DLR_CD	USA
TXN_CD	387510
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.08
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	200
MDL_YR	2001
SORT_INDEX	137
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	12/20/2000
WRTY_START_D	2/2/2001
NAME	PUGMIRE LINCOLN-MERCURY INC
DOC_NUM	6572452
PH_NUM	0522281
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7081203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	33
RPR_DT	7/12/2001
TIS_WSD	6
CLM_KEY	2465141
MILGE	5392
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEATBELT FAULTY FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	C S THE DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING	
AREA_CD		
COUNTRY_CD	770	
SLS_DLR_CD	USA	
TXN_CD	328057	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	021	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	80B	
VIN_CD		
LBR_COST		
VEH_LINE_CD	28.83	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Field50	T/WC	

ID	201
MDL_YR	2001
SORT_INDEX	138
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	5/31/2001
NAME	DAVID MCDAVID'S PLANO LINCOLN
DOC_NUM	421818A
PH_NUM	9646000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	540
COND_CD	1
RPR_DT	7/19/2001
TIS_WSD	2
CLM_KEY	2425235
MILGE	1342
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11442
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT; WILL NOT LATCH
TECH_TXT2	
CUST_TXT	S40 C 8 DRIVERS SEATBELT WILL NOT STAY LATCHED SOP IN
AREA_CD	
COUNTRY_CD	972
SLS_DLR_CD	USA
TXN_CD	387324
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V03
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	34.85
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VKR_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	202
MDL_YR	2001
SORT_INDEX	140
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/23/2001
WRTY_START_D	11/10/2001
NAME	BARANCO LINCOLN-MERCLURY INC
DOC_NUM	2408001
PH_NUM	4979900
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	12
RPR_DT	11/23/2001
TIS_WSD	1
CLM_KEY	6288790
MILGE	586
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10167
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT LATCH TO CORRECT
TECH_TXT2	
CUST_TXT1	OK CUST STATES DRIVERS SEAT BELT WILL COME LOOSE FROM BUCKLE INTERMITTANTLY. S40
AREA_CD	
COUNTRY_CD	770
SLS_DLR_CD	USA
TXN_CD	320057
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	33.25
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	203
MDL_YR	2001
SORT_INDEX	142
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/22/2000
WRTY_START_D	11/22/2000
NAME	DOWNEY LINCOLN MERCURY
DOC_NUM	078170A
PH_NUM	8810721
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	14
CLM_KEY	6028702
MILGE	23718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10346
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	ROAD TEST,UNABLE TO VERIFY CONCERN,REPLACE SEAT BELT BUCKLE PER HOTLINE
TECH_TXT2	
CUST_TXT	ADVISE CUST STATES DRIVERS SEAT BELT OPENS WHILE JUST SITTING IN SEAT
AREA_CD	
COUNTRY_CD	882
SLS_DLR_CD	USA
TXN_CD	264081
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	4823
MKT_DERIVED	T04
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	204
MDL_YR	2001
SORT_INDEX	148
TRANS_CD	TDC
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	6/12/2001
NAME	
DOC_NUM	1652901
PH_NUM	6815225
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	4/19/2002
TIS_WSD	12
CLM_KEY	8140516
MILGE	10893
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10857
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1 REPLACED LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE LEFT FRONT SEATBELT BUCKLE INTERMITTENTLY COMES LOOSE
AREA_CD	
COUNTRY_CD	S08
SLS_DLR_CD	USA
TXN_CD	387311
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	8
LBR_COST	
VEH_LINE_CD	13
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/VC

ID	205
MDL_YR	2001
SORT_INDEX	147
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/13/2001
WRKY_START_D	10/15/2001
NAME	PUMFIRE LINCOLN-MERCURY INC
DOC_NUM	0591051
PH_NUM	0522261
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	340
COND_CD	42
RPR_DT	3/8/2002
TIS_WSD	5
CLM_KEY	7403183
MILGE	YB01
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT FAILURE FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUST. STATES DRIVER SEAT BELT COMES UNBUCKLED AT TIMES WHILE DRIVING (SOP) TECH 128	
AREA_CD		
COUNTRY_CD	770	
SLS_DLR_CD	USA	
TXN_CD	328233	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V05	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LBR_COST		
VRH_LINE_CD	40.24	
MKT_DERIVED	T/B4	
BOD_CAB_STL	*	
VER_SERIES_C	T/WB	
DRIVE_CD	T/EL	
ENG_CD	T/B	
Field50	T/WC	

ID	208
MDL_YR	2001
SORT_INDEX	148
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	10/30/2000
WRTY_START_D	7/29/2001
NAME	POMPANO LINCOLN-MERCURY INC
DOC_NUM	281881B
PH_NUM	7828110
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	3/22/2002
TIS_WSD	9
CLM_KEY	7813988
MILGE	11857
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11848
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	*
CPSC_CD_6	11001

TECH_TXT1	11657 42 INOP WARR 6310 REPLACE LT FRT SEAT BELT BUCKLE ASSY GA
TECH_TXT2	
CUST_TXT	826 LEFT FRONT SEAT BELT FEMALE END NOT WORKING PROPERLY WILL NOT LATCH W
AREA_CD	
COUNTRY_CD	306
SLS_DLR_CD	USA
TXN_CD	325118
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	26.46
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/MC

ID	207
MDL_YR	2001
SORT_INDEX	150
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	8/27/2001
WRTY_START_D	8/29/2001
NAME	ASTRO LINCOLN-MERCURY INC
DOC_NUM	16292701
PH_NUM	4799531
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/8/2001
TIS_WSD	1
CLM_KEY	3899996
MILGE	983
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11816
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACR DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	
COUNTRY_CD	850
SLS_DLR_CD	USA
TXN_CD	325123
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	23.78
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	208
MDL_YR	2001
SORT_INDEX	161
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/22/2001
WRTY_START_D	7/27/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	6458551
PH_NUM	5384800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	925
COND_CD	42
RPR_DT	7/28/2001
TIS_WSD	0
CLM_KEY	4122240
MILGE	24
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10184
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	INSTALLED BOTH BUCKLES COME LOOSE
TECH_TXT2	
CUST_TXT	CHECK SEAT BELTS BINDS
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	387288
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	308
VIN_CD	
LBR_COST	
VEH_LINE_CD	49
MKT_DERIVED	T84
BOD_CAB_STL	
VER_SERIES_C	TMB
DRIVE_CD	TFL
ENG_CD	T/B
Field50	TWC

ID	209
MDL_YR	2001
SORT_INDEX	152
TRANS_CD	YDE
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	7/20/2001
NAME	BAYWAY LINCOLN MERCURY, INC.
DOC_NUM	6405351
PH_NUM	8286500
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981203
PART_NUM_CA	GAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	8
CLM_KEY	6325108
MILGE	7188
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10093
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	8
CPSC_CD_6	11001

TECH_TXT1	LEFT FRONT SEAT BELT WILL NOT LOCK, REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT KEEPS COMING UNBUCKLED
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	997032
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	26.74
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	TWC

ID	210
MDL_YR	2001
SORT_INDEX	154
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	2/15/2001
NAME	ALTMAN LINCOLN MERCURY
DOC_NUM	200771A
PH_NUM	7872324
WCC_CD	6F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/16/2001
TIS_WSD	11
CLM_KEY	6000877
MILGE	17440
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10488
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT LATCH NOT HOLDING R AND I DRIVERS SEAT TO REPL SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CK FOR DRIVERS SEATELT KEEPS COMING UNHOOKED
AREA_CD	
COUNTRY_CD	B43
SLS_DLR_CD	UBA
TXN_CD	326355
CNTRY_SOLD	EB4
QRT_CD	UBA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	SC8
VIN_CD	
LBR_COST	
VEH_LINE_CD	3152
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	211
MDL_YR	2001
SORT_INDEX	155
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/28/2001
NAME	LONG LEWIS FORD
DOC_NUM	24899101
PH_NUM	9883873
WCC_CD	0F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	328
COND_CD	42
RPR_DT	2/28/2002
TIS_WSD	7
CLM_KEY	7158133
MILGE	14718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	226
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	8713,CK R R SEAT REPL SEAT BELT BUCKEL CC 42 INSIDE LATCH IS NOT STRONG ENOUGH.
TECH_TXT2	
CUST_TXT	828 CUST STATES DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED AT TIMES, PARTS ORDERED AND HERE.
AREA_CD	
COUNTRY_CD	205
SLS_DLR_CD	USA
TXN_CD	328074
CNTRY_SOLD	EB4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VRH_LINE_CD	2B
MKT_DERIVED	TB4
BOD_CAB_STL	
VER_SERIES_C	TWB
DRIVE_CD	TWEL
ENG_CD	T/B
Field58	TWC

ID	212
MDL_YR	2001
SORT_INDEX	157
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	01/2001
NAME	DON DAVIS LINCOLN-MERCURY INC
DOC_NUM	218524A
PH_NUM	2050101
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	01/16/2001
TIS_WSD	1
CLM_KEY	3063550
MILGE	447
MTRL_COST	
TOT_COST_GRO	
LHR_HRS	
DLR_CD	11484
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	447 SEAT BELT BUCKLE NOT LATCHING CORRECTLY.REMOVE SEAT REPLACE BUCKLE REINSTALL SEAT DRIVERS. 42 70121
TECH_TXT2	
CUST_TXT	S25 DRIVERS SEAT BELT WILL COME UNLATCHED
AREA_CD	
COUNTRY_CD	017
SLS_DLR_CD	USA
TXN_CD	367013
CNTRY_SOLD	1
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.57
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	213
MDL_YR	2001
SORT_INDEX	185
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	9/5/2001
NAME	PUGMIRE LINCOLN-MERCURY INC
DOC_NUM	6322851
PH_NUM	0522261
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/3/2002
TIS_WSD	5
CLM_KEY	6102253
MILGE	5067
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT INOP TRIM COVER OR PAD FRONT SEAT BACK REPLACE
TECH_TXT2	
CUST_TXT	C S THE DRIVERS SIDE SEAT BELT DOESNT STAY LATCHED
AREA_CD	
COUNTRY_CD	770
SLS_DLR_CD	USA
TXN_CD	328233
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	80.48
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field59	T/WC

ID	214
MDL_YR	2001
SORT_INDEX	189
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/6/2001
WRTY_START_D	2/26/2001
NAME	MARGATE LINCOLN-MERCURY INC
DOC_NUM	267124A
PH_NUM	0782277
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/12/2002
TIS_WSD	13
CLM_KEY	7382716
MILGE	20865
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1983B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	C
CPSC_CD_6	11001

TECH_TXT1	20065 42 1L7Z7881 [REDACTED] R/L DRIVERS SEAT & R/R DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S40 DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING SOP #285827
AREA_CD	
COUNTRY_CD	305
SLS_DLR_CD	USA
TXN_CD	326258
CNTRY_SOLD	Es4
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	[REDACTED]
VEH_LINE_CD	25.48
MKT_DERIVED	TB4
BOD_CAR_STL	*
VER_SERIES_C	TW6
DRIVE_CD	T/EI
ENG_CD	T/B
Field50	T/WC

ID	215
MDL_YR	2001
SORT_INDEX	172
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/4/2001
WRTY_START_D	8/27/2001
NAME	PALM SPRINGS LINCOLN-MERCURY
DOC_NUM	095846C
PH_NUM	3282102
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	B25
COND_CD	42
RPR_DT	12/24/2001
TIS_WSD	4
CLM_KEY	5890751
MILGE	5755
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	10007
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE ASSY THAT WOULD NOT LATCH PROPERLY
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT POPS OUT
AREA_CD	
COUNTRY_CD	780
SLS_DLR_CD	USA
TXN_CD	354198
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	SCB
VIN_CD	
LBR_COST	
VEH_LINE_CD	28.52
MKT_DERIVED	T/BA
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	T/WC

ID	210
MDL_YR	2001
SORT_INDEX	174
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	10/25/2000
WRTY_START_D	1/22/2001
NAME	NORTH FLORIDA LINCOLN-MERCURY
DOC_NUM	3724896
PH_NUM	8424100
WCC_CD	6R02
PART_NUM_CA	1LZ
PART_NUM_CA	7861203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/6/2001
TIS_WSD	6
CLM_KEY	2878174
MILGE	9871
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11830
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	DOES NOT WORK PROP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE DRIVERSEAT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES NOT STAY LATCHED REPLACE BUCKLE PART HERE SEE KEY
AREA_CD	
COUNTRY_CD	B04
SLS_DLR_CD	USA
TXN_CD	354263
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	25.58
MKT_DERIVED	T7B4
BOD_CAB_STL	
VRR_SERIES_C	T7WB
DRIVE_CD	T/E1
ENG_CD	T/B
Field58	T/WC

ID	217
MDL_YR	2001
SORT_INDEX	175
TRANS_CD	T0E
PLANT_CD	AP
PRODN_DT	10/22/2000
WRTY_START_D	5/30/2001
NAME	PUENTE HILLS FORD
DOC_NUM	2405962
PH_NUM	0949073
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	7/3/2001
TIS_WSD	2
CLM_KEY	2325287
MILGE	1073
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	5550
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT FAILURE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT COMES UNDONE WHEN BRAKING
AREA_CD	
COUNTRY_CD	828
SLS_DLR_CD	USA
TXN_CD	354283
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V06
VRT_CD	B4
TIS_FLAG	805
VIN_CD	
LBR_COST	
VRH_LINE_CD	29.63
MKT_DERIVED	T/B4
BOD_CAB_STL	
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
RNG_CD	T/B
Field59	T/WC

ID	218
MDL_YR	2001
SORT_INDEX	178
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/4/2001
WRTY_START_D	8/23/2001
NAME	GERMAIN LINC-MERC OF NAPLES
DOC_NUM	1807051
PH_NUM	5878011
WCC_CD	6R32
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	853
COND_CD	41
RPR_DT	12/11/2001
TIS_WSD	4
CLM_KEY	5793828
MILGE	3958
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11624
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	BINDING SEAT REPLACE	TRACK ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	DRIVERS SEATBELT BUCKLE COMES UNDONE PART IN STOCK SEE TED PASS. FRONT IS FALLING ALSO	
AREA_CD		
COUNTRY_CD	941	
SLS_DLR_CD	USA	
TXN_CD	325044	
CNTRY_SOLD	2	
QRT_CD	USA	
VFG_CD	Q21	
AWS_VL_CD	V03	
VRT_CD	B4	
TIS_FLAG	S08	
VIN_CD		
LBR_COST	[REDACTED]	
VEH_LINE_CD	68.2B	
MKT_DERIVED	TB4	
BOD_CAB_STL		
VER_SERIES_C	TWB	
DRIVE_CD	T1L	
ENG_CD	TB	
Field50	TWC	

ID	210
MDL_YR	2001
SORT_INDEX	17B
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	7/30/2001
NAME	STAR LINCOLN-MERCURY SALES, IN
DOC_NUM	50827402
PH_NUM	2471903
WCC_CD	BR02
PART_NUM_CA	1LZ
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	7
CLM_KEY	6879564
MILGE	0490
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	11822
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1 REPLACE LEFT FRONT SEATBELT LATCH.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT COMES UNBUCKLED BY ITSELF AT TIMES
AREA_CD	
COUNTRY_CD	818
SLS_DLR_CD	USA
TXN_CD	354301
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	808
VIN_CD	
LBR_COST	
VEH_LINE_CD	73.5
MKT_DERIVED	T7B4
BOD_CAB_STL	*
VER_SERIES_C	T7WB
DRIVE_CD	T7EL
ENG_CD	T7B
Field50	T7WC

ID	220
MDL_YR	2001
SORT_INDEX	194
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/11/2000
WRTY_START_D	6/30/2001
NAME	BAYWAY LINCOLN MERCURY, INC.
DOC_NUM	6957251
PH_NUM	9296500
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881209
PART_NUM_CA	BAA
CUST_CONC_C	328
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	6
CLM_KEY	4980480
MILGE	4891
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10083
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE WEAK
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLES WILL NOT STAY LATCHED USE SPO 01275014
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	367032
CNTRY_SOLD	2
QRT_CD	USA
VFG_CD	Q21
AWS_VL_CD	V05
VRT_CD	B4
TIS_FLAG	S00
VIN_CD	
LBR_COST	
VEH_LINE_CD	60.17
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	T/WB
DRIVE_CD	T/EL
ENG_CD	T/B
Field58	T/WC

ID	221
MDL_YR	2001
SORT_INDEX	188
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/22/2000
WRTY_START_D	2/28/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	7343752
PH_NUM	5394900
WCC_CD	6F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	T90
COND_CD	42
RPR_DT	12/31/2001
TIS_WSD	11
CLM_KEY	8074790
MILGE	28237
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10184
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SIDE FRONT SEAT BELT POPS OUT OF LOCK
AREA_CD	
COUNTRY_CD	281
SLS_DLR_CD	USA
TXN_CD	387023
CNTRY_SOLD	E84
QRT_CD	USA
VFG_CD	021
AWS_VL_CD	V74
VRT_CD	B4
TIS_FLAG	S08
VIN_CD	
LBR_COST	
VEH_LINE_CD	28
MKT_DERIVED	T/B4
BOD_CAB_STL	*
VER_SERIES_C	TWB
DRIVE_CD	T/EL
ENG_CD	T/B
Field50	TWC

TBL2001 ExpedLF

ID	1
MDL_YR	2001
SORT_INDEX	198
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	5/28/2001
NAME	HOFFMAN FORD, INC.
DOC_NUM	778532A
PH_NUM	6284511
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	6/7/2002
TIS_WSD	12
CLM_KEY	857444
MILGE	8085
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9185
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CT

Tuesday, December 14, 2004

Page 1 of 748

RQ04-011 E 0444

Field27	c
CPSC_CD_6	11001
TECH_TXT1	DRIVER SEAT BELT DOESNT BUCKLE BROKEN REPLACED BUCKLE AND RETESTED OK
TECH_TXT2	
CUST_TXT	CS DRIVER SIDE SEAT BELT BUCKLE KEEPS UNBUCKLING
AREA_CD	203
COUNTRY_CD	USA
SLS_DLR_CD	124008
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S02
TIS_FLAG	0
VIN_CD	1FMRU17WX1
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T7B
ENG_CD	T7M

ID	2
MDL_YR	2001
SORT_INDEX	199
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	6/28/2001
NAME	MAC HAIK FORD
DOC_NUM	154827A
PH_NUM	8328000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	1
RPR_DT	10/24/2001
TIS_WSD	4
CLM_KEY	4882818
MILGE	5328
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4511
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	6326 01 61209 R R DRIVER SEAT ACCESS REPLACED DRIVER SEAT BELT BUCKLE BINDING
TECH_TXT2	
CUST_TXT	S25 LT FT SEAT BELT WONT STAY LATCHED
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	152031
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	
VIN_CD	1FMRU17WX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	9
MDL_YR	2001
SORT_INDEX	200
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	8/14/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	414852B
PH_NUM	2914281
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	33
RPR_DT	1/24/2002
TIS_WSD	8
CLM_KEY	6478521
MILGE	8228
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2417
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	8226 LOOSE REPLACE LOOSE LF SEAT BELT BUCKEL
TECH_TXT2	
CUST_TXT	D SIDE SEAT BELT KEEPS COMING OFF
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU17WX1[REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EP
DRIVE_CD	T/B
ENG_CD	T/VN

ID	4
MDL_YR	2001
SORT_INDEX	201
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/14/2001
WRTY_START_D	8/25/2001
NAME	LOU GRUBB FORD
DOC_NUM	3420861
PH_NUM	0013333
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/11/2001
TIS_WSD	0
CLM_KEY	5765464
MILGE	10023
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
Field27	0
CPSC_CD_6	11001

TECH_TXT1	MTIME TO DIAG BELT BUCKLE NOT WORKING CORRECTLY REPLACED DRIVERS
TECH_TXT2	
CUST_TXT	CS DRIVERS SEAT BELT COMES UNDONE WHEN DRIVING
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	17117B
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17WX1L
LBR_COST	4824
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	6
MDL_YR	2001
SORT_INDEX	202
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/17/2001
NAME	TOWN EAST FORD
DOC_NUM	775884A
PH_NUM	2706441
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	11/12/2001
TIS_WSD	3
CLM_KEY	5107288
MILGE	5122
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8182
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	6
CPSC_CD_6	11001

TECH_TXT1	5122 TEST AND REPLACE DRIVER SIDE SEATBELT CC 42
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEATBELT RELEASE WHEN STOPPING...SOP PARTS...
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	162002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17W0X1L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EP
DRIVE_CD	T/B
ENG_CD	T/VN

ID	8
MDL_YR	2001
SORT_INDEX	203
TRANS_CD	T7DU
PLANT_CD	AF
PRODN_DT	4/20/2001
WRTY_START_D	7/7/2001
NAME	TOMBALL FORD, INC.
DOC_NUM	222688A
PH_NUM	3515427
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/23/2001
TIS_WSD	1
CLM_KEY	2908284
MILGE	1012
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8042
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field17	b
CPSC_CD_6	11001

TECH_TXT1	1012 FOUND SERAT BELT WOULD NOT STAY BUCKLED R&R DRIVER SEAT REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S40 CK DRIVER SEAT BELT WONT STAY BUCKLED REPORT
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152055
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ17WXX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TW0
VER_SERIES_C	T1EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	7
MDL_YR	2001
SORT_INDEX	204
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	7/2/2001
NAME	RUSSELL & SMITH FORD INC
DOC_NUM	770881
PH_NUM	0034111
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	1
CLM_KEY	2322903
MTLGE	629
MTBL_COST	
TOT_COST_GRO	
LBR_HES	
DLR_CD	4672
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACE THE DRIVERS SEAT BELT BUCKLE UNLATCHING AT TIMES WHILE DRIVING RE TEST RAISE SEAT TO GAIN ACCESS TO SEAT BELT LATCHED INPUT CONNECTOR WORKING PROPERLY
TECH_TXT2	
CUST_TXT	CUSTOMER SAYS THAT DRIVERS SEATBELT WILL UNLATCH WHILE DRIVING
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	152026
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B8
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17WX1U
LBR_COST	
VEH_LINE_CD	T/B8
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	8
MDL_YR	2001
SORT_INDEX	207
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	8/19/2001
NAME	MAXWELL FORD
DOC_NUM	583176A
PH_NUM	4496000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/7/2001
TIS_WSD	8
CLM_KEY	5603634
MILGE	8250
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2923
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEATBELT ASSY
TECH_TXT2	
CUST_TXT	L.F. SEAT BELT BUCKLE COMES LOOSE AT TIMES SOP IN
AREA_CD	612
COUNTRY_CD	USA
SLS_DLR_CD	152308
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17W81L
LAB_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	9
MDL_YR	2001
SORT_INDEX	208
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/17/2001
WRTY_START_D	3/18/2001
NAME	TOWNE FORD SALES
DOC_NUM	5558101
PH_NUM	3865744
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	12
RPR_DT	3/18/2001
TIS_WSD	7
CLM_KEY	3865747
MILGE	5706
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7851
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PPC PARTS HERE.
AREA_CD	850
COUNTRY_CD	USA
SLS_DLR_CD	172013
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRL117W91L
LBR_COST	
VRH_LINK_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWMD
VER_SERIES_C	T7EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	10
MDL_YR	2001
SORT_INDEX	211
TRANS_CD	T/DLJ
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/19/2001
NAME	SKYLINE FORD SALES, INC.
DOC_NUM	108052A
PH_NUM	3274500
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	8/12/2001
TIS_WSD	4
CLM_KEY	388833
MILGE	5158
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	543
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1

TECH_TXT2

CUST_TXT 840*CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT COMEG UNLATCHED WHILE DRIVING

AREA_CD 214

COUNTRY_CD USA

SLS_DLR_CD 152003

TXN_CD 1

CNTRY_SOLD USA

QRT_CD Q21

VFG_CD VIB

AWS_VL_CD B3

VRT_CD S08

TIS_FLAG

VIN_CD 1FMRU17W81L

LBR_COST

VEH_LINE_CD T/B3

MKT_DERIVED *

BOD_CAB_STL T/WD

VER_SERIES_C T/EF

DRIVE_CD T/B

ENG_CD T/VN

ID	11
MDL_YR	2001
SORT_INDEX	216
TRANS_CD	TIDJ
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	7/31/2001
NAME	MCREE FORD, INC.
DOC_NUM	427428B
PH_NUM	3371629
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	8
CLM_KEY	6041850
MILGE	5436
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4443
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	8
CPSC_CD_6	11001

TECH_TXT1	DIAGNOSED AND TESTED TO VERIFY COMPLAINT,RFR DR IVER SIDE SEAT BUCKET TO REMOVE AND REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT WONT STAY BUCKLED
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	162052
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	12
MDL_YR	2001
SORT_INDEX	216
TRANS_CD	77DU
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	7/16/2001
NAME	LEADERSHIP FORD
DOC_NUM	284681A
PH_NUM	3818100
WCC_CD	6R02
PART_NUM_CA	*
PART_NUM_CA	7861203
PART_NUM_CA	*
CUST_CONC_C	S26
COND_CD	41
RPR_DT	11/19/2001
TIS_WSD	E
CLM_KEY	5277893
MILGE	9128
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2490
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	8128 STICKING WARR REPAIR STICKING RELEASE BUTTON ON LEFT MIDDLE ROW SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES 2ND ROW LH SIDE SEAT BELT LATCH WICHT STAY IN LATCHED POSITION
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	152006
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMFU17W71L
LBR_COST	
VEH_LINK_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	13
MDL_YR	2001
SORT_INDEX	218
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/26/2001
WRTY_START_D	8/10/2001
NAME	GREENWAY FORD, INC.
DOC_NUM	7435651
PH_NUM	2753200
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAA
CUST_CONC_C	T80
COND_CD	33
RPR_DT	11/14/2001
TIS_WSD	6
CLM_KEY	5133947
MILGE	6426
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4822
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	LOOSE SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	O R L F SEATBELT BUCKLE COME LOOSE
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124224
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W61L
LBR_COST	
VEH_LINE_CD	77B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	14
MDL_YR	2001
SORT_INDEX	218
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/16/2001
WRTY_START_D	5/28/2001
NAME	ERNIE HAIRE FORD, INC.
DOC_NUM	7475151
PH_NUM	8388571
WCC_CD	BF02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	928
COND_CD	42
RPR_DT	3/12/2002
TIS_WSD	10
CLM_KEY	7370870
MILGE	12158
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4005
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	*
CPSC_CD_6	11001

TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CJST STATES BOTH FRT SEAT BELTS DONT LATCH
AREA_CD	813
COUNTRY_CD	USA
SLS_DLR_CD	124321
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL17W81L
LBR_COST	
VEH_LINE_CD	T/53
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	16
MDL_YR	2001
SORT_INDEX	220
TRANS_CD	T/DL
PLANT_CD	AP
PRODN_DT	5/22/2001
WRTY_START_D	8/21/2001
NAME	GREENE FORD COMPANY
DOC_NUM	160829E
PH_NUM	8326620
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7891200
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	41
RPR_DT	11/21/2001
TIS_WSD	4
CLM_KEY	5283570
MILGE	2071
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	290
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	B
CPSC_CD_6	11001

TECH_TXT1	DIAG AND RR SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CSLT STATES DRIVERS SEAT BELT WONT CATCH BUCKLE AND STAY FASTENED
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121405
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W51E
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	18
MDL_YR	2001
SORT_INDEX	222
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	3/7/2001
NAME	MAC HAIK FORD
DOC_NUM	1582638
PH_NUM	9325000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAA
CUST_CONC_C	T90
COND_CD	42
RPR_DT	1/2/2002
TIS_WSD	11
CLM_KEY	8082424
MILGE	33327
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4811
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	33327 61203,42 DOES NOT OPERATE PROPERLY R R DRIVER SEAT REPLACED SEAT BELT BUCKLE TEST OK
TECH_TXT2	
CUST_TXT	T90 DRIVER SEAT BELT UNBUCKLE 6T TIMES BY IT SELF
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	162031
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU17W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/ND
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	17
MDL_YR	2001
SORT_INDEX	224
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	5/14/2001
NAME	WESTWAY FORD
DOC_NUM	84608701
PH_NUM	8580333
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	626
COND_CD	33
RPR_DT	1/14/2002
TIS_WSD	6
CLM_KEY	8254898
MILGE	14172
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2586
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1 R&R SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE RELEASES WHILE DRIVING..NO WARNING
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152017
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU17W51L
LBR_COST	
VEH_LINE_CD	T03
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	18
MDL_YR	2001
SORT_INDEX	227
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/30/2000
WRTY_START_D	12/23/2000
NAME	CERRITOS FORD
DOC_NUM	28234901
PH_NUM	885554
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	11
CLM_KEY	5725697
MILGE	18858
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	6401
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	DEFECTED RT FT SEAT BELT BUCKLE 1L7Z 7 BAA C001 REPLACED RT FT SEAT BELT BUCKLE ALL SYSTEMS OK
TECH_TXT2	
CUST_TXT	CUSTOMER BITAES RIGHT FRONT SEAT BELT BUCKLE DOES NOT LATCH
AREA_CD	582
COUNTRY_CD	USA
SLS_DLR_CD	171047
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRJ17W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	19
MDL_YR	2001
SORT_INDEX	228
TRANS_CD	TDLJ
PLANT_CD	AP
PRODN_DT	3/9/2001
WRTY_START_D	8/11/2001
NAME	WESTWAY FORD
DOC_NUM	82738201
PH_NUM	6590333
WCC_CD	8RD2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	7
RPR_DT	9/26/2001
TIS_WSD	2
CLM_KEY	3916054
MILGE	8461
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2586
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	VERIFIED CUSTOMER'S CONCERN, PERFORMED INSPECTION. FOUND BUCKLE SPRING BROKEN. REPLACED BUCKLE, RETEST OK...
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	152013
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17W41L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EP
DRIVE_CD	T/B
ENG_CD	T/VN

ID	20
MDL_YR	2001
SORT_INDEX	228
TRANS_CD	TIDU
PLANT_CD	AP
PRODN_DT	3/9/2001
WRTY_START_D	5/11/2001
NAME	HAYWARD FORD
DOC_NUM	38631802
PH_NUM	8811200
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/10/2001
TIS_WSD	6
CLM_KEY	0048878
MILGE	5978
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7728
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field37	b
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT DEFECTIVE REPLACED SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	SPECIAL ORDER PARTS IN MIDDLE SEAT MIDDLE SEAT BELT RECEPTICLE AND REAR BENT LEFT OUT RECEPTICLE DO NOT STAY
AREA_CD	510
COUNTRY_CD	USA
SLS_DLR_CD	172013
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/W0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	21
MDL_YR	2001
SORT_INDEX	233
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	8/15/2001
NAME	WEST TEXAS FORD, INC.
DOC_NUM	5285201
PH_NUM	8233211
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881209
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	2/18/2002
TIS_WSD	7
CLM_KEY	0091871
MILGE	7201
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5118
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	6
CPSC_CD_6	11001

TECH_TXT1	<u>REPL LEFT SEATBELT BUCKLE DUE TO COMING APART</u>
TECH_TXT2	
CUST_TXT	<u>CUSTOMER STATES SEATBELT WONT LATCH</u>
AREA_CD	<u>815</u>
COUNTRY_CD	<u>USA</u>
SLS_DLR_CD	<u>152540</u>
TXN_CD	<u>1</u>
CNTRY_SOLD	<u>USA</u>
QRT_CD	<u>C21</u>
VFG_CD	<u>V05</u>
AWS_VL_CD	<u>B3</u>
VRT_CD	<u>S08</u>
TIS_FLAG	
VIN_CD	<u>1FMRU17W31L</u>
LBR_COST	<u>[REDACTED]</u>
VEH_LINE_CD	<u>T/B3</u>
MKT_DERIVED	<u>*</u>
BOD_CAB_STL	<u>T/WD</u>
VER_SERIES_C	<u>T/EF</u>
DRIVE_CD	<u>T/B</u>
ENG_CD	<u>T/VN</u>

ID	22
MDL_YR	2007
SORT_INDEX	236
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	6/18/2001
NAME	TOMBALL FORD, INC.
DOC_NUM	227220A
PH_NUM	3515427
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	6/21/2001
TIS_WSD	4
CLM_KEY	4387488
MILGE	3381
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6042
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	3381 DRIVERS SEAT BELT DOES NOT LATCH AT TIMES. R R DRIVERS SEAT TO GAIN ACCESS TO SEAT BELT ANCHOR. REMOVE AND REPLACE SEAT BELT BUCKLE ASSY. CONFIRM PROPER LATCH AFTER REPLACEMENT. OK
TECH_TXT2	MILEAGE ON RO 224538 SHOULD HAVE BEEN 2420 NOT 24206.
CUST_TXT	S40 OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED AT TIMES, RED CAP DOESNT COME BACK UP PROPERL.
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152020
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17W31L
LBR_COST	
VEH_LINE_CD	T783
MKT_DERIVED	*
BOD_CAB_STL	T740
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	T7VN

ID	23
MDL_YR	2001
SORT_INDEX	238
TRANS_CD	7DU
PLANT_CD	AP
PRODN_DT	6/25/2001
WRTY_START_D	7/13/2001
NAME	HUB CITY FORD, INC.
DOC_NUM	5838652
PH_NUM	2334800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	11/21/2001
TIS_WSD	6
CLM_KEY	6283913
MILGE	8007
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9481
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	
CPSC_CD_6	11001

TECH_TXT1	INOP REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	CUST STATES DRIVERS SEATBELT BUCKLE WONT LATCH AT TIMES	
AREA_CD		337
COUNTRY_CD	USA	
SLS_DLR_CD		123271
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG		
VIN_CD	1FMRU17W21 [REDACTED]	
LRR_COST	[REDACTED]	
VEH_LINE_CD	T83	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T8F	
DRIVE_CD	T8	
ENG_CD	T8N	

ID	24
MDL_YR	2001
SORT_INDEX	238
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/11/2001
WRTY_START_D	3/24/2001
NAME	PLANET FORD
DOC_NUM	18517402
PH_NUM	7183700
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	U
CLM_KEY	5808708
MILGE	B348
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2091
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	VERIFIED CONCERN RETEST BUCKLES WITH RECALL TEST BOTH BUCKLES PASS BUT DRIVERS WILL LUNHOOK APPROX 1 OUT OF 10 TIMES
TECH_TXT2	
CUST_TXT	S40 CUSTOMER STATES LEFT SEAT BELT BUCKLE POPS OUT DOES NOT RETAIN SEAT BELT.
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152032
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	E3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	25
MDL_YR	2001
SORT_INDEX	239
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/28/2001
WRTY_START_D	3/30/2001
NAME	TOMMIE VAUGHN MOTORS, INC.
DOC_NUM	184187A
PH_NUM	8884881
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	D4
RFB_DT	11/12/2001
TIS_WSD	8
CLM_KEY	8071108
MILGE	14984
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4474
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	E
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 49 of 740

RQD4-011 E 0482

TECH_TXT1	14364 INSPECT AND VERIFY CONCERN DRIVERS EAT BELT BUCKLE UNBUCKLES WHILE DRIVING. REPLACE BUCKLE AND VERIFY REPAIR..CCD4..M:14364.
TECH_TXT2	
CUST_TXT	S40 INSTALL SOP PARTS, DR FRONT SEAT BELT UNBUCKLES WHILE DRIVING
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	152241
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W211
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAE
DRIVE_CD	T/B
ENG_CD	T/VN

ID	28
MDL_YR	2001
SORT_INDEX	240
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/9/2001
WRTY_START_D	2/27/2001
NAME	JENNINGS ANDERSON FORD
DOC_NUM	4200451
PH_NUM	2402538
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	3/25/2002
TIS_WSD	14
CLM_KEY	7710017
MILGE	18041
MTBL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4424
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	SEATBELT WONT BUCKLE SEATBELT ASSY.	REPLACED
TECH_TXT2		
CUST_TXT	DR SEAT BELT WILL COME UN LATCHED	
AREA_CD	210	
COUNTRY_CD	USA	
SLS_DLR_CD	152143	
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S06	
TIS_FLAG	G	
VIN_CD	1FMRU17W21L	
LBR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	TWO	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	TMN	

ID	27
MDL_YR	2001
SORT_INDEX	248
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	8/8/2001
WRTY_START_D	8/8/2001
NAME	NORTH BROS. FORD, INC.
DOC_NUM	4378301
PH_NUM	4211300
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	A85
COND_CD	42
RPR_DT	8/9/2001
TIS_WSD	1
CLM_KEY	2882351
MILGE	448
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2875
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	*
CPSC_CD_6	11001

TECH_TXT1	CC 42 A55 7861203 REMOVED DRIVERS SIDE SEAT AND REMOVED BUCKLE AND INSTALLED NEW AND RETESTED OK
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT BUCKLE PART IS HERE
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	146018
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V17
AWS_VL_CD	B3
VRT_CD	B09
TIS_FLAG	
VIN_CD	1FMRJ17W11L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	TAF
DRIVE_CD	T8
ENG_CD	TVM

ID	28
MDL_YR	2001
SORT_INDEX	247
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	5/28/2001
NAME	MAXWELL FORD
DOC_NUM	584987A
PH_NUM	4435000
WCC_CD	8R02
PART_NUM_CA	1L72
PART_NUM_CA	7881209
PART_NUM_CA	BAA
CUST_CONC_C	T80
COND_CD	42
RPR_DT	9/24/2001
TIS_WSD	4
CLM_KEY	2882488
MILGE	7645
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	2823
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 53 of 748

RQ04-011 E 0498

TECH_TXT1	SEATBELT INOP
TECH_TXT2	
CUST_TXT	C S DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING CHECK AND ADVISE
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	152303
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17W11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	29
MDL_YR	2001
SORT_INDEX	248
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	7/31/2001
NAME	MCREE FORD, INC.
DOC_NUM	418687A
PH_NUM	3371028
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	B40
COND_CD	42
RPR_DT	8/16/2001
TIS_WSD	1
CLM_KEY	3088288
MILGE	1559
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4443
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	R AND R SEAT T60 REPLACE DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING
AREA_CD	261
COUNTRY_CD	USA
SLS_DLR_CD	182062
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU17W11
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M