

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 5 OF 6

BOOK 1 OF 43

ID	30
MDL_YR	2001
SORT_INDEX	249
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/14/2001
WRTY_START_D	6/9/2001
NAME	MAG HAIK FORD LINCOLN MERCURY
DOC_NUM	14705AA
PH_NUM	9803873
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/28/2002
TIS_WSD	10
CLM_KEY	7716002
MILGE	15888
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7570
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	G
CPSC_CD_6	11001

TECH_TXT1	REMOVED SEAT BUCKLE DRIVERS SIDE REPLACED WITH NEW REMOVED SEAT TO REACH BOTTOM OF SEAT REPLACED BUCKLE ON PASSENGER SIDE
TECH_TXT2	
CUST_TXT	C S DRIVERS AND PASS SD BUCKLES COME UNLOCKED INTERM. SOP
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	162302
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRUJ17W11
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVN

ID	31
MDL_YR	2001
SORT_INDEX	250
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/18/2001
WRTY_START_D	3/27/2001
NAME	HELFMAN FORD INC
DOC_NUM	7476551
PH_NUM	2403673
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	607
COND_CD	33
RPR_DT	11/29/2001
TIS_WSD	8
CLM_KEY	6578539
MILGE	11075
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4587
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	8
CPSC_CD_6	11001

TECH_TXT1	42 REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH
TECH_TXT2	
CUST_TXT	DR SEAT BELT BUCKLE COMES UNBUCKLED WHEN DRIVING
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152024
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRLU17W11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	TVN

ID	32
MDL_YR	2001
SORT_INDEX	251
TRANS_CD	T/DU
PLANT_CD	AP
FRODN_DT	2/10/2001
WRTY_START_D	3/3/2001
NAME	CHAMPION FORD, INC.
DOC_NUM	224482A
PH_NUM	5302277
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	328
COND_CD	42
RPR_DT	3/15/2002
TIS_WSD	13
CLM_KEY	7648617
MILGE	19001
MTRL_COST	
TOT_COST_GRO	
LHR_HRS	
DLR_CD	4527
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	19901 BOTH FRONT SEAT BELT BUCKLES WILL NOT STAY LATCHED. REPLACED BOTH FRONT SEAT BELT BUCKLES. CC 42 DUALITY CHECKED BY NJM
TECH_TXT2	
CUST_TXT	626 BOTH FRT. SEAT BELT BUCKLES HAVE POPPED OPEN AT TIMES WHEN DRIVING
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	15204B
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	33
MDL_YR	2001
SORT_INDEX	232
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	10/21/2000
WRTY_START_D	3/2/2001
NAME	GARBER FORD-MERCURY, INC.
DOC_NUM	0633408
PH_NUM	2843023
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	7
RPR_DT	1/28/2002
TIS_WSD	12
CLM_KEY	6577008
MILGE	21401
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4886
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	C
CPSC_CD_6	11001

TECH_TXT1	BUCKLE PASSED, 01921 COMES UNDONE INTERMITTENTLY REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT COMES UNLATCHED AFTER DRIVING A WHILE
AREA_CD	904
COUNTRY_CD	USA
SLS_DLR_CD	124453
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17W11L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	34
MDL_YR	2001
SORT_INDEX	254
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	7/21/2001
NAME	TEXAN FORD, INC.
DOC_NUM	364485C
PH_NUM	5789100
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	2/20/2002
TIS_WSD	8
CLM_KEY	0000000
MILGE	14504
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4817
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1

14584 DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH AND UNLATCH REPLACED BUCKLE AND RETESTED OK.

TECH_TXT2

CUST_TXT

DRIVERS FRONT SEAT BELT BUCKLE DOES NOT LATCH INTERM. WHEN IT DOES IT IS HARD TO GET BELT UN LACTCHED

AREA_CD

281

COUNTRY_CD

USA

SLS_DLR_CD

152054

TXN_CD

E84

CNTRY_SOLD

USA

QRT_CD

Q21

VFG_CD

V05

AWS_VL_CD

B3

VRT_CD

808

TIS_FLAG

VIN_CD

1FMRL17W01L

LBR_COST

VEH_LINE_CD

T/B3

MKT_DERIVED

BOD_CAB_STL

TWD

VER_SERIES_C

T/EF

DRIVE_CD

T/B

ENG_CD

TMN

ID	35
MDL_YR	2001
SORT_INDEX	255
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	5/4/2001
NAME	COURTESY FORD
DOC_NUM	6844251
PH_NUM	9222700
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	7/5/2001
TIS_WSD	3
CLM_KEY	2220350
MILGE	7383
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	358
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	REPLACED LEFT FRONT SEAT BELT 61203
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE WILL NOT CLOSE
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121024
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TMD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	36
MDL_YR	2001
SORT_INDEX	257
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/29/2001
WRTY_START_D	10/16/2001
NAME	PAUL MURREY FORD-MERCURY INC
DOC_NUM	2784850
PH_NUM	8822151
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAA
CUST_CONC_C	S26
COND_CD	41
RPR_DT	8/10/2001
TIS_WSD	0
CLM_KEY	4480182
MILGE	5
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	2615
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	BINDING BELT BUCKLE	REPLACED LEFT SIDE SEAT
TECH_TXT2		
CUST_TXT	SEAT BELT WILL NOT LATCH	
AREA_CD		214
COUNTRY_CD	USA	
SLS_DLR_CD		152464
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	908	
TIS_FLAG		
VIN_CD	1FMRL17LX1L	
LBR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	T/WO	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/NZ	

ID	37
MDL_YR	2001
SORT_INDEX	258
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/15/2001
WKTY_START_D	8/22/2001
NAME	APPEL FORD-MERCURY, INC.
DOC_NUM	4639904
PH_NUM	5563659
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981209
PART_NUM_CA	BAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/6/2001
TIS_WSD	1
CLM_KEY	4884727
MILGE	2335
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4600
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 73 of 748

RQ04-011 E 0516

TECH_TXT1	1 REPLACED SEAT BELT ASSEMBLY. RETEST. O.K.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT DOES NOT STAY LATCHED. CHIME FOR SEAT BELT GOES OFF EVEN AFTER SEAT BELT IS BUCKLED
AREA_CD	079
COUNTRY_CD	USA
SLS_DLR_CD	152734
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V15
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17LX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
RNG_CD	T/VZ

ID	38
MDL_YR	2001
SORT_INDEX	260
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/7/2001
WRTY_START_D	9/24/2001
NAME	HILLCREST FORD LINCOLN-MERCURY
DOC_NUM	1273852
PH_NUM	2953794
WCC_CD	6F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	940
COND_CD	1
RPR_DT	3/28/2002
TYS_WSD	7
CLM_KEY	7731910
MILGE	9187
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1818
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNBUCKLED
AREA_CD	098
COUNTRY_CD	USA
SLS_DLR_CD	152518
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17LX1L
LBR_COST	
VEH_LINE_CD	T83
MET_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7F
DRIVE_CD	T7B
ENG_CD	TVZ

ID	39
MDL_YR	2001
SORT_INDEX	262
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	7/20/2001
NAME	AUDUBON FORD
DOC_NUM	188142A
PH_NUM	2838900
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S25
COND_CD	42
RFR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	5372944
MILGE	1500
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8521
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	INSPECTED AND REPLACE BOTH FRONT SEATBELTS
TECH_TXT2	
CUST_TXT	CK SEATBELT WILL NOT BUCKLE
AREA_CD	225
COUNTRY_CD	USA
SLS_DLR_CD	123203
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU17LX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	40
MDL_YR	2001
SORT_INDEX	263
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/17/2001
WRTY_START_D	8/22/2001
NAME	ADVANTAGE FORD
DOC_NUM	018854C
PH_NUM	2482010
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/22/2002
TIS_WSD	8
CLM_KEY	6548332
MILGE	8790
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6440
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	8790 DEFECTIVE SEAT BUCKLE 42 R AND R SEAT IN ORDER TO ACCESS SEAT BUCKLE. REPLACED SEAT BUCKLE AND TESTED. WORKS FINE.
TECH_TXT2	
CUST_TXT	CHECK L F SEATBELT ERRATIC COMES UNLOCKED WHILE DRIVING 840
AREA_CD	504
COUNTRY_CD	USA
SLS_DLR_CD	123027
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B9
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17LX1L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	41
MDL_YR	2001
SORT_INDEX	255
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/6/2001
WRTY_START_D	5/26/2001
NAME	TOMMIE VALGHN MOTORS, INC.
DOC_NUM	185264C
PH_NUM	8894851
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	CAA
CUST_CONC_C	B40
COND_CD	D4
RPR_DT	11/27/2001
TIS_WSD	7
CLM_KEY	5484360
MILGE	10758
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4474
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1 10788 LEFT FRT SEAT BELT POPS LOOSE WHILE
DRIVING. REMOVE SEAT AND REPLACE BUCKLE AND
REINSTALL ALL PARTS AND VERIFY
REPAIR_QCDA_M:10788

TECH_TXT2

CUST_TXT 840, CUSTOMER STATES DRIVER SIDE SEAT BELT
WILL NOT STAY FASTEN, IT KEEPS POPPING LOOSE.

AREA_CD 713

COUNTRY_CD USA

SLS_DLR_CD 152241

TXN_CD 1

CNTRY_SOLD USA

QRT_CD Q21

VFG_CD V05

AWS_VL_CD B3

VRT_CD S08

TIS_FLAG

VIN_CD 1FMRU17L91L

LBR_COST

VEH_LINE_CD T/B3

MKT_DERIVED *

BOD_CAR_STL TWD

VER_SERIES_C T/EF

DRIVE_CD T/B

ENG_CD T/VZ

ID	42
MDL_YR	2001
SORT_INDEX	268
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	9/13/2000
WRTY_START_D	2/12/2001
NAME	TROTTER FORD
DOC_NUM	871302
PH_NUM	6354321
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	10/3/2001
TIS_WSD	8
CLM_KEY	4116445
MILGE	18705
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5878
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	APL
Field27	8
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SIDE FRONT SEAT BELT BUCKLE ASSEMBLY
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT LATCH YOU HAVE TO PRESS THE RED BUTTON TO LATCH
AREA_CD	870
COUNTRY_CD	USA
SLS_DLR_CD	123551
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU17L91L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TW0
VER_SERIES_C	T1EF
DRIVE_CD	T/B
ENG_CD	TN2

ID	43
MDL_YR	2001
SORT_INDEX	270
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	8/10/2000
WRTY_START_D	7/30/2001
NAME	PALMETTO TRUCK CENTER
DOC_NUM	0423878
PH_NUM	5923873
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	D90
COND_CD	42
RPR_DT	8/13/2001
TIS_WSD	1
CLM_KEY	3748215
MILGE	802
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4858
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	a
CPSC_CD_6	11001

TECH_TXT1	B02 DOES NOT OPERATE PROPERLY 01&210 0.4 ADMIN 0.1 0.6HRS LG R R DRIVERS SEAT BELT BUCKLE, TESTED, OK. REMOVED DRIVERS SEAT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES LOCK
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	124801
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V44
AWS_VL_CD	B3
VRT_CD	S11
TIS_FLAG	
VIN_CD	1FMRU17L81
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	44
MDL_YR	2001
SORT_INDEX	271
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	8/11/2001
WRTY_START_D	8/28/2001
NAME	BOB TOMES FORD, INC.
DOC_NUM	11748801
PH_NUM	8981010
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	1
RPR_DT	7/25/2001
TIS_WSD	1
CLM_KEY	2717653
MILGE	1330
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2631
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	940 CUSTOMER STATES THAT DRIVER SEAT BELT WONT LATCH
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	152013
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRJ17L81 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/E
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	45
MDL_YR	2001
SORT_INDEX	272
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/10/2001
WRTY_START_D	6/28/2001
NAME	WRAY FORD, INC.
DOC_NUM	3374601
PH_NUM	6867300
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	326
COND_CD	42
RPR_DT	4/15/2002
TIS_WSD	10
CLM_KEY	8016514
MILGE	11494
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6554
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS FRONT SEAT BELT BUCKLE ASSEMBLIE 61203 CAUS 42
TECH_TXT2	
CUST_TXT	CS DR SEAT BELY WONT LATCH S28
AREA_CD	318
COUNTRY_CD	USA
SLS_DLR_CD	123058
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	306
TIS_FLAG	
VIN_CD	1FMRU17L81L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TBF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	48
MDL_YR	2001
SORT_INDEX	273
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/4/2001
WRTY_START_D	9/22/2001
NAME	OKC AUTO COLLECTION
DOC_NUM	598203A
PH_NUM	4759000
WCC_CD	6R12
PART_NUM_CA	1L72
PART_NUM_CA	7891203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/8/2001
TIS_WSD	1
CLM_KEY	4242457
MILGE	1472
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2058
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
Field27	b
CPSC_CD_6	11001

TECH_TXT1	1472 01 REPLACED DRIVERS SEAT BELT BUCKLE WOULD NOT STAY LATCHED TECH 2525 M.D
TECH_TXT2	
CUST_TXT	CUST STATES THAT DRIVERS SEAT BELT WILL NOT STAY LATCHED
AREA_CD	405
COUNTRY_CD	USA
SLS_DLR_CD	152658
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	47
MDL_YR	2001
SORT_INDEX	274
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	6/28/2001
NAME	TED RUSSELL FORD INC
DOC_NUM	32941103
PH_NUM	
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	CAA
CUST_CONC_C	S28
COND_CD	1
RPR_DT	4/4/2002
TIS_WSD	11
CLM_KEY	7859008
MILGE	15480
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3788
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TN
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACE D S SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	OWNER REPORTS D S FRONT SEAT BELT COMES UNHOOKED BY SELF CK ALL BELTS S26
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	121420
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L81L
LBR_COST	
VRH_LINE_CD	T88
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T8F
DRIVE_CD	T8B
ENG_CD	TNZ

ID	48
MDL_YR	2001
SORT_INDEX	275
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/15/2001
NAME	HELFMAN FORD INC
DOC_NUM	7893351
PH_NUM	2403873
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	B40
COND_CD	42
RPR_DT	12/21/2001
TIS_WSD	0
CLM_KEY	5901041
MILGE	15051
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4587
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	NO REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	DRIVER SEAT BELT COMES UNLATCHED WHILE DRIVING	
AREA_CD		281
COUNTRY_CD	USA	
SLS_DLR_CD		152024
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMFUJ17L81L	
LBR_COST		
VEH_LINE_CD	T/BS	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/NZ	

ID	40
MDL_YR	2001
SORT_INDEX	276
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/1/2000
WRTY_START_D	2/3/2001
NAME	COVERT FORD, INC.
DOC_NUM	1196703
PH_NUM	3454343
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7601203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	2/6/2002
TIS_WSD	13
CLM_KEY	0782142
MILGE	20828
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4437
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	#
CPSC_CD_6	11001

TECH_TXT1	BELT BUCKLE BELT BUCKLE BROKEN REPLACED. EXTRA TIME TO REMOVE SEAT TO GAIN ACCESS
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT LATCH WONT HOLD
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	162303
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU17L81L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T8
ENG_CD	TVZ

ID	50
MDL_YR	2001
SORT_INDEX	277
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/17/2000
WRTY_START_D	8/4/2000
NAME	TEXAN FORD
DOC_NUM	20636801
PH_NUM	4873873
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7681203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	1
RFR_DT	10/26/2001
TIS_WSD	14
CLM_KEY	4818424
MILGE	26387
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2488
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	#
CPSC_CD_6	11003

TECH_TXT1	CONFIRMED CUSTOMERS COMPLAINT. REPLACED DRIVERS SEAT BELT BUCKLE FOR NOT LATCHING.
TECH_TXT2	
CUST_TXT	CUSTOMER REPORTS DRIVER S SEAT BELT BUCKLE WILL NOT LATCH.. WILL NOT HOLD BELT.
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	152020
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRLJ17L81
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWVD
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	TVZ

ID	51
MDL_YR	2001
SORT_INDEX	280
TRANS_CD	TDE
PLANT_CD	AF
PRODN_DT	6/14/2001
WRTY_START_D	7/8/2001
NAME	PACIFIC FORD
DOC_NUM	1752551
PH_NUM	8278130
WCC_CD	5R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	1/14/2002
TIS_WSD	7
CLM_KEY	6344266
MILGE	16000
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6412
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	NA REMOVE AND REINSTALL SEAT TOP REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT LEFT FRONT SEAT BELT COMES UNDONE
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	171062
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B9
VRT_CD	908
TIS_FLAG	
VIN_CD	1PMRU17L71U [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	TIB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEF
DRIVE_CD	T9
ENG_CD	TNZ

ID	52
MDL_YR	2001
SORT_INDEX	281
TRANS_CD	TICE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	6/24/2001
NAME	LAMARQUE FORD INC
DOC_NUM	181765E
PH_NUM	4432500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/4/2002
TIS_WSD	8
CLM_KEY	6070891
MILGE	0133
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6831
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	6133 BUCKLE LATCH 42 WARR VERIFIED CONCERN. REMOVED LT FR SEAT FROM VEHICLE FOR ACCESS TO REPLACE LT FR SEAT BELT BUCKLE LATCH ASSY. REINSTALLED ALL TEST ALL OK.
TECH_TXT2	
CUST_TXT	S40 O R LEFT FRONT SEAT BELT BUCKLE COMES UNDONE WHEN DRIVING
AREA_CD	504
COUNTRY_CD	USA
SLS_DLR_CD	123020
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU17L71L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TAWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	59
MDL_YR	2001
SORT_INDEX	282
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/7/2001
WRTY_START_D	6/2/2001
NAME	MULLINAX FORD
DOC_NUM	333627A
PH_NUM	6897800
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	GAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/19/2002
TIS_WSD	10
CLM_KEY	7469847
MILGE	17098
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8073
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	0
CPSC_CD_6	11001

TECH_TXT1	17098 DR LF SEAT BELT INOP W CC42 INSP AND RR DR SEAT TO ACCSSE SEAT BELT BUCKLE ASSY REPLACED LF DR SEAT BELT BUCKLE ASSY RETEST OK
TECH_TXT2	
CUST_TXT	828 CUST STS LEFT FRONT SEATBELT UNLATCHES BY ITSELF SOP ROR329063 MI 13720 1 2 02
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124227
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TTS_FLAG	
VIN_CD	1FMRU17L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	TXF
DRIVE_CD	T/B
ENG_CD	TWZ

ID	54
MDL_YR	2001
SORT_INDEX	284
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	10/5/2001
NAME	CHAMPION FORD, INC.
DOC_NUM	217778A
PH_NUM	9302277
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7B81203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/27/2001
TIS_WSD	1
CLM_KEY	4788739
MILGE	805
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4527
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1

885 LEFT FRONT SEAT BELT WILL NOT LATCH.
ACCESS LEFT FRONT SEAT AND REPLACED BUCKLE
AND HARNESS ASSEMBLY. 1.0 CC 42 QUALITY
CHECKED BY M/M

TECH_TXT2

CUST_TXT

S40 DRIVERS SEAT BELT WILL NOT LATCH

AREA_CD

713

COUNTRY_CD

USA

SLS_DLR_CD

152049

TXN_CD

2

CNTRY_SOLD

USA

QRT_CD

Q21

VFG_CD

V05

AWS_VL_CD

B3

VRT_CD

B08

TIS_FLAG

VIN_CD

1FMRU17L71U

LBR_COST

VEH_LINK_CD

T/BS

MKT_DERIVED

BOD_CAB_STL

T/WD

VER_SERIES_C

T/EF

DRIVE_CD

T/B

ENG_CD

T/VZ

ID	66
MDL_YR	2001
SORT_INDEX	285
TRANS_CD	TCE
PLANT_CD	AP
PRODN_DT	3/14/2001
WRTY_START_D	4/13/2001
NAME	CAPISTRANO FORD
DOC_NUM	21165805
PH_NUM	2407000
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/12/2001
TIS_WSD	0
CLM_KEY	5294813
MILGE	18127
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	712
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	VERIFIED, NEED NEW BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE DRIVERS SEAT BELT DOES NOT ALWAYS LOCK IN 3
AREA_CD	B49
COUNTRY_CD	USA
SLS_DLR_CD	171034
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	56
MDL_YR	2001
SORT_INDEX	288
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/9/2001
WRTY_START_D	4/30/2001
NAME	PEYTON CRAMER FORD
DOC_NUM	5440081
PH_NUM	7844700
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/12/2001
TIS_WSD	7
CLM_KEY	5654609
MILGE	8134
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5524
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT COMES APART REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES WHILE DRIVING SEAT BELT COMES APART.
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171025
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L71L [REDACTED]
LBR_COST	[REDACTED] 15.90
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	57
MDL_YR	2001
SORT_INDEX	288
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/22/2000
WRTY_START_D	5/14/2001
NAME	FORD OF CORAL GABLES
DOC_NUM	311387A
PH_NUM	8818111
WCC_CD	6P02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	8/13/2001
TIS_WSD	4
CLM_KEY	2894813
MILGE	7850
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3886
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	2
CPSC_CD_6	11001

TECH_TXT1	INOPERATIVE SEAT BUCKLE
TECH_TXT2	
CUST_TXT	825 DRIVERS SIDE SEAT BELT WILL NOT GO INTO CLAMP AT TIMES
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	124008
TAX_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRI_CD	B08
TIS_FLAG	
VIN_CD	1FMRU17L71L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	TB
ENG_CD	TNZ

ID	58
MDL_YR	2001
SORT_INDEX	281
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	8/8/2001
WRTY_START_D	5/25/2001
NAME	MULLINAX FORD
DOC_NUM	332855A
PH_NUM	8887800
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	8
CLM_KEY	7188471
MILGE	20508
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3073
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	8
CPSC_CD_6	11001

TECH_TXT1	2D608 INOP W 42 REMOVE DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE ASY. INOP
TECH_TXT2	
CUST_TXT	S28 CUST STS LEFT FRONT SEATBELT WILL NOT LATCH SOP RO#328734 MI 16880 1 14 02
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124227
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	59
MDL_YR	2001
SORT_INDEX	282
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/30/2001
WRTY_START_D	6/3/2001
NAME	GALPIN FORD
DOC_NUM	5557421
PH_NUM	7873800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	0
CLM_KEY	4001132
MILGE	88
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6596
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	SEAT BELTS WONT LATCH PROPERLY REPLACE SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELTS WILL NOT LATCH PROPERLY
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU17L61L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	60
MDL_YR	2001
SORT_INDEX	294
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/10/2001
WRTY_START_D	8/26/2001
NAME	NORTH CENTRAL FORD
DOC_NUM	57051601
PH_NUM	2313481
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/15/2002
TIS_WSD	7
CLM_KEY	6487686
MILGE	0320
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4212
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REMOVE FRONT SEAT AND REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	DR. SEAT BELT BUCKLE HAS COME LOOSE TWICE SINCE RECALL PERFORMED.
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	182017
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRUJ17L81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TN2

ID	B1
MDL_YR	2001
SORT_INDEX	297
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/3/2001
NAME	RIVERSIDE FORD INC
DOC_NUM	1850451
PH_NUM	7425771
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/4/2002
TIS_WSD	3
CLM_KEY	0082570
MILGE	0391
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	348
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNLATCHED AT TIMES PART IN
AREA_CD	478
COUNTRY_CD	USA
SLS_DLR_CD	121500
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L81L
LBR_COST	
VEH_LINE_CD	T85
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T8F
DRIVE_CD	T8
ENG_CD	T8Z

ID	02
MDL_YR	2001
SORT_INDEX	300
TRANS_CD	TCE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	1/29/2001
NAME	MAXWELL FORD
DOC_NUM	582055A
PH_NUM	4435000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	41
RPR_DT	11/27/2001
TIS_WSD	11
CLM_KEY	5964410
MILGE	21741
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1	SEATBELT BINDING
TECH_TXT2	
CUST_TXT	L.F. SEAT BELT BUCKLE WONT LATCH SOP IN
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	162303
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L811 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	83
MDL_YR	2001
SORT_INDEX	305
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	09/2001
NAME	RANDALL REED FORD OF HUMBLE
DOC_NUM	21386304
PH_NUM	4488171
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/29/2001
TYS_WSD	2
CLM_KEY	5335538
MILGE	2852
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4482
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1 CC42 DOES NOT OPERATE PROPERLY MILES IN 2852
MILES OUT 2854 TESTED DRIVERS SEATBELT BUCKLE
WITH RECALL TESTED FOUND IT DID NOT PASS
REPLACED DRIVERS SEATBELT BUCKLE AND RETEST

TECH_TXT2

CUST_TXT CUSTOMER STATES DRIVERS SEAT BELT COMES
UNBUCKLED WHILE DRIVING.

AREA_CD 281

COUNTRY_CD USA

SLS_DLR_CD 152046

TXN_CD 1

CNTRY_SOLD USA

QRT_CD Q21

VFG_CD V06

AWS_VL_CD B3

VRT_CD 808

TIS_FLAG

VIN_CD 1FMRU17L61

LBR_COST

VEH_LINE_CD T83

MKT_DERIVED *

BOD_CAB_STL TWD

VER_SERIES_C TEF

DRIVE_CD TB

ENG_CD TNZ

ID	84
MDL_YR	2001
SORT_INDEX	308
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	8/28/2001
NAME	HARRELSON FORD, INC.
DOC_NUM	4970152
PH_NUM	5522780
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7851203
PART_NUM_CA	GAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/29/2002
TIS_WSD	B
CLM_KEY	6567107
MILGE	8333
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1071
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Field27	C
CPSC_CD_6	11001

TECH_TXT1	BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	C S LF SEATBELT KEEPS COMING LOOSE AT LATCH
AREA_CD	704
COUNTRY_CD	USA
SLS_DLR_CD	121213
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B00
TIS_FLAG	
VIN_CD	1FMRU17L51L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TND
VER_SERIES_C	TEF
DRIVE_CD	T7B
ENG_CD	TN2

ID	85
MDL_YR	2001
SORT_INDEX	309
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/4/2001
WRTY_START_D	6/28/2001
NAME	HACIENDA FORD
DOC_NUM	8370402
PH_NUM	3831615
WCC_CD	BRD2
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	B28
COND_CD	42
RPR_DT	3/8/2002
TIS_WSD	10
CLM_KEY	7838804
MILGE	12924
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4449
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	
CPSC_CD_6	11001

TECH_TXT1	FAIL TO LOCK SEAT CLIP R R SEAT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	C S LF SEAT BELT WONT LOCK CK AND ADVISE
AREA_CD	958
COUNTRY_CD	USA
SLS_DLR_CD	152104
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU17L51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	66
MDL_YR	2001
SORT_INDEX	310
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/10/2001
WRTY_START_D	4/5/2001
NAME	SANTA MARGARITA FORD
DOC_NUM	215063A
PE_NUM	4598600
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	12/17/2001
TIS_WSD	0
CLM_KEY	6804500
MILGE	10000
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1697
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	1000 CP 61384 CC 38 PART REF. 002 61384A 0.4 0.4 REPLACE LH SEAT BELT BUCKLE WRONG COLOR
TECH_TXT2	
CUST_TXT	T80 SEE DUANE DRIVERS FRONT SEAT BELT WONT LATCH INT TRIM TAN 1H
AREA_CD	848
COUNTRY_CD	USA
SLS_DLR_CD	171074
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU17L51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TMD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	TNZ

ID	67
MDL_YR	2001
SORT_INDEX	311
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	11/30/2000
WRTY_START_D	12/11/2000
NAME	CASA FORD, INC.
DOC_NUM	251238A
PH_NUM	7792272
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/8/2001
TIS_WSD	10
CLM_KEY	4229000
MILGE	10546
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20455
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	S40 DRIVER SEAT BELT BUCKLE NOT LATCHING BELT REPLACE BUCKLE AND RETEST WORKING PROPERLY NOW
TECH_TXT2	
CUST_TXT	C S DRIVER SEAT BELT BUCKLE NOT LATCHING
AREA_CD	915
COUNTRY_CD	USA
SLS_DLR_CD	152210
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL17L51L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TAND
VER_SERIES_C	T1F
DRIVE_CD	T/B
ENG_CD	TAZ

ID	66
MDL_YR	2001
SORT_INDEX	312
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	6/25/2001
WRTY_START_D	7/20/2001
NAME	GALPIN FORD
DOC_NUM	6288291
PH_NUM	7873800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	526
COND_CD	66
RPR_DT	2/15/2002
TIS_WSD	8
CLM_KEY	6848451
MILGE	0484
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5538
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	CO328 CHECKED OUT REPLACED DRIVERS SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL NOT LOCK
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU17L41L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T/B
ENG_CD	TNZ

ID	68
MDL_YR	2001
SORT_INDEX	313
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	7/2/2001
NAME	BILLINGSLEY FORD, INC.
DOC_NUM	101487A
PH_NUM	2263300
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981208
PART_NUM_CA	BAA
CUST_CONC_C	626
COND_CD	42
RPR_DT	9/29/2002
TIS_WSD	10
CLM_KEY	7733212
MILGE	16526
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2414
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
Field17	b
CPSC_CD_6	11001

TECH_TXT1	INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED
AREA_CD	580
COUNTRY_CD	USA
SLS_DLR_CD	152688
TXN_CD	ED4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU17L41L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	TB
ENG_CD	TN2

ID	70
MDL_YR	2001
SORT_INDEX	314
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	5/25/2001
NAME	PLANTATION FORD
DOC_NUM	6745751
PH_NUM	5842400
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	3/12/2002
TIS_WSD	10
CLM_KEY	7843404
MILGE	8137
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4885
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	WOULD NOT HOLD BUCKLE	REPLACE DRIVERS SIDE
TECH_TXT2		
CUST_TXT	CUST TSS DRIVER SIDE SEAT BELT WHEN BUCKLED IT DELATCHES	
AREA_CD	954	
COUNTRY_CD	USA	
SLS_DLR_CD	124010	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMRLJ17L41U	
LRR_COST		
VEH_LINE_CD	T83	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	TJEF	
DRIVE_CD	T8	
ENG_CD	TNZ	

ID	71
MDL_YR	2001
SORT_INDEX	318
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	10/22/2001
NAME	JARRETT-BODIFORD FORD
DOC_NUM	7885103
PH_NUM	7824171
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	528
COND_CD	42
RPR_DT	2/12/2002
TIS_WSD	4
CLM_KEY	8835775
MILGE	8115
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	481
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1

THE ORIGINAL SEAT BELT BUCKLE IS COMING
UNLATCHED WHILE THE CUSTOMER WAS DRIVING +
REPLACED IT WITH A NEW ONE.

TECH_TXT2

CUST_TXT

CUST STATES D & FT SEATBELT WILL COME
UNLATCHED WHEN DRIVING

AREA_CD

813

COUNTRY_CD

USA

SLS_DLR_CD

124449

TXN_CD

1

CNTRY_SOLD

USA

QRT_CD

Q21

VFG_CD

V05

AWS_VL_CD

B3

VRT_CD

S08

TIS_FLAG

VIN_CD

1FMRU17L41L

LRR_COST

VEH_LINE_CD

T/B3

MKT_DERIVED

*

BOD_CAB_STL

TWD

VRR_SERIES_C

T/EF

DRIVE_CD

T/B

ENG_CD

T/VZ

ID	72
MDL_YR	2001
SORT_INDEX	317
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/7/2001
WRTY_START_D	4/10/2001
NAME	BOB TOMES FORD, INC.
DOC_NUM	12113001
PH_NUM	0091010
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/28/2001
TIS_WSD	0
CLM_KEY	3385357
MILGE	11429
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2331
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIVE.
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	152609
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L41L
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	T7B
ENG_CD	TNZ

ID	73
MDL_YR	2001
SORT_INDEX	320
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/18/2001
WRTY_START_D	5/9/2001
NAME	BENSON FORD-MERCURY INC
DOC_NUM	9927001
PH_NUM	6556383
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	3
CLM_KEY	2813102
MILGE	9024
MTRL_COST	
TOT_COST_GRO	
LAB_HRS	
DLR_CD	892
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SC
Field27	C
CPSC_CD_6	11001

TECH_TXT1	TEST AND REPLACE SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	OK DR SEATBELT COMES UNDONE WHILE DRIVING
AREA_CD	884
COUNTRY_CD	USA
SLS_DLR_CD	121782
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	74
MDL_YR	2001
SORT_INDEX	323
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	6/26/2001
WRTY_START_D	7/28/2001
NAME	RED MCCOMB6 FORD
DOC_NUM	32860301
PH_NUM	3494849
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7861209
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	2/19/2002
TIS_WSD	7
CLM_KEY	0990912
MILGE	7584
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4644
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	
CPSC_CD_6	11001

TECH_TXT1	CC,01 BROKEN BASIC#81203 REPLACE L F SEAT BELT
TECH_TXT2	
CUST_TXT	QUALITY CHECK INITIALS SEAT BELT ON DRIVERS SIDE DOES NOT BUCKLE S40
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	152056
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L31L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	75
MDL_YR	2001
SORT_INDEX	328
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	7/5/2001
NAME	HEMINGWAY MOTOR CO INC
DOC_NUM	4683201
PH_NUM	2846243
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801208
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	1
RPR_DT	11/30/2001
TIS_WSD	5
CLM_KEY	5543153
MILGE	10537
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	907
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	8C
Field27	8
CPSC_CD_6	11001

TECH_TXT1	
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WONT LATCH
AREA_CD	843
COUNTRY_CD	USA
SLS_DLR_CD	121685
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	SOB
TIS_FLAG	
VIN_CD	1FMRU17L21L
LBR_COST	
VEH_LINE_CD	T753
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	T7VZ

ID	78
MDL_YR	2001
SORT_INDEX	329
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	5/12/2001
NAME	CHARLE THOMAS FORD INC
DOC_NUM	109817A
PH_NUM	3714000
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	826
COND_CD	41
RPR_DT	9/19/2001
TIS_WSD	5
CLM_KEY	3747993
MILGE	8500
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	4473
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED FRONT 2 SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	BOTH FRONT SEAT BELT BUCKLES DONT LATCH
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	152044
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ17L21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	77
MDL_YR	2001
SORT_INDEX	331
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	5/18/2001
NAME	GRANDE FORD TRUCK SLS INC
DOC_NUM	045073E
PH_NUM	8814121
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	8
CLM_KEY	6067703
MILGE	8038
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4588
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	SEATBELT BUCKLE UNLATCHES
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	152063
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/W0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	76
MDL_YR	2001
SORT_INDEX	336
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/14/2001
WRTY_START_D	8/15/2001
NAME	GALPIN FORD
DOC_NUM	6640271
PH_NUM	7873800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861209
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	33
RPR_DT	7/31/2001
TIS_WSD	0
CLM_KEY	3267288
MILGE	41
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5636
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	GGF12 REPLACE SEATBELT BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELTS WILL NOT LATCH PROPERLY
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU17L11L
LBR_COST	27.59
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	78
MDL_YR	2001
SORT_INDEX	337
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	7/17/2001
NAME	MOSS BROS. FORD
DOC_NUM	1985451
PH_NUM	8261212
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7001208
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	11/7/2001
TIS_WSD	4
CLM_KEY	5102434
MILGE	6147
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4358
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 157 of 749

TECH_TXT1	SEAT BELT POPS OUT REPL DRV SEAT BELT BUCKLE, POPS OUT WHILE DRIVING, NO LIGHT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES WHILE DRIVING THE LEFT FRONT SEAT BELT WILL POP OUT OF THEBUCKLE ASY.
AREA_CD	809
COUNTRY_CD	USA
SLS_DLR_CD	171150
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ57L11L
LBR_COST	
VEH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T6F
DRIVE_CD	T7B
ENG_CD	TN2

ID	80
MDL_YR	2001
SORT_INDEX	338
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/14/2001
WRTY_START_D	4/29/2001
NAME	BILL UTTER FORD, INC.
DOC_NUM	9168161
PH_NUM	3825404
WCC_CD	8902
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAA
CUST_CONC_C	626
COND_CD	42
RFR_DT	3/25/2002
TIS_WSD	12
CLM_KEY	7758658
MILGE	13670
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2488
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 159 of 748

RQ04-011 E 0802

TECH_TXT1	COMES UNLATCHED FRONT REPLACE	BEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	SEATBELT BUCKLE COMES UNLATCHED WHILE DRIVING, SOP HERE SEE 08397 TECH 351	
AREA_CD		840
COUNTRY_CD	USA	
SLS_DLR_CD		152408
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG	@	
VIN_CD	1FMRLJ17L11L	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T83	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T1F	
DRIVE_CD	T8	
ENG_CD	TNZ	