

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 6 OF 6

BOOK 1 OF 43

ID	81
MDL_YR	2001
SORT_INDEX	343
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/26/2001
WRTY_START_D	
NAME	MIKE CRAIG FORD-MERCURY
DOC_NUM	28201
PH_NUM	8432821
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7801203
PART_NUM_CA	BAG
CUST_CONC_C	628
COND_CD	42
RPR_DT	4/12/2002
TLS_WSD	-1
CLM_KEY	0010117
MILGE	11732
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	6330
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSPECT SEAT BELTS AND REPLACE ONE SEAT BELT
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT STAY LATCHED
AREA_CD	903
COUNTRY_CD	USA
SLS_DLR_CD	152440
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	Ⓢ
VIN_CD	1FMRJ17L11LA98280
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
RNG_CD	T/VZ

ID	82
MDL_YR	2001
SORT_INDEX	346
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	6/14/2001
WRTY_START_D	6/22/2001
NAME	GALPIN FORD
DOC_NUM	69873851
PH_NUM	7673800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	0
CLM_KEY	3625117
MILGE	B
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5638
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEATBELTS WILL NOT LATCH
TECH_TXT2	
CUST_TXT	
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	83
MDL_YR	2001
SORT_INDEX	348
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	8/13/2001
WRTY_START_D	8/20/2001
NAME	MIDDLEKAUFF FORD, INC.
DOC_NUM	538922C
PH_NUM	8853800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	4/1/2002
TIS_WSD	8
CLM_KEY	7753406
MILGE	8907
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2478
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	8887 SEAT BELT LATCH INOP 81172A 4 REPLACED SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	S40 SEATBELT CUST STATES THE DRIVERS SEATBELT WILL NOT HOLD LATCH
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
RNG_CD	T/VZ

ID	B4
MDL_YR	2001
SORT_INDEX	347
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/21/2001
WRTY_START_D	8/31/2001
NAME	GALPIN FORD
DOC_NUM	60874161
PH_NUM	7073000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7081203
PART_NUM_CA	BAA
CUST_CONG_C	340
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	0
CLM_KEY	3625118
MILGE	82
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5638
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEATBELT WILL NOT LATCH PROPERLY
TECH_TXT2	
CUST_TXT	
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	85
MDL_YR	2001
SORT_INDEX	348
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	7/31/2001
NAME	JOHNSON BROTHERS FORD, LTD.
DOC_NUM	12813002
PH_NUM	7735258
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	8AD
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	4
CLM_KEY	6003897
MILGE	5772
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2458
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	1 TESTED SEAT BELTS AND FOUND BOTH FRONT BUCKLES FAILED REPLACED BOTH BUCKLES, POWER SEATS BUCKETS
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT COMES UNDONE WHEN DRIVING
AREA_CD	254
COUNTRY_CD	USA
SLS_DLR_CD	152481
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B06
TIS_FLAG	
VIN_CD	1FMRU17L01
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	86
MDL_YR	2001
SORT_INDEX	350
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	5/28/2001
NAME	JACK ROACH FORD
DOC_NUM	788051
PH_NUM	5885000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	826
COND_CD	7
RPR_DT	4/4/2002
TIS_WSD	11
CLM_KEY	7837809
MILGE	14274
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4590
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1	TEST DRIVER SEATBELT BUCKLE NOT LATCHING PROPERLY, REPLACE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE NOT LATCHING PROP
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152037
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	87
MDL_YR	2001
SORT_INDEX	353
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	6/27/2001
NAME	BAY CITY AUTO & SALES CO.
DOC_NUM	7645051
PH_NUM	2451771
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	BAA
CUST_CONC_C	B40
COND_CD	1
RPR_DT	1/14/2002
TIS_WSD	7
CLM_KEY	0098439
MILGE	12300
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4411
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEAT BELT CHIMES, SEAT BELT DOESNT CLICK IN ALL THE WAY
AREA_CD	979
COUNTRY_CD	USA
SLS_DLR_CD	152134
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VEH_SERIES_C	T/E3
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	88
MDL_YR	2001
SORT_INDEX	356
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	10/12/2000
WRTY_START_D	6/9/2001
NAME	LEESVILLE FORD LINCOLN MERCURY
DOC_NUM	8810801
PH_NUM	2383434
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/9/2002
TIS_WSD	B
CLM_KEY	6785880
MILGE	8533
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6585
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REMOVED AND REPLACED SEAT BELT BUCKLE TESTED OK
TECH_TXT2	
CUST_TXT	DRIVERS SEATBELT WILL POP LOOSE INSTALL PARTS..
AREA_CD	337
COUNTRY_CD	USA
SLS_DLR_CD	123248
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU17L01L [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/E-
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	89
MDL_YR	2001
SORT_INDEX	357
TRANS_CD	T/0E
PLANT_CD	AP
PROBN_DT	10/3/2000
WRTY_START_D	10/30/2000
NAME	MAXWELL FORD
DOC_NUM	601042A
PH_NUM	4435000
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	540
COND_CD	41
RPR_DT	2/25/2002
TIS_WSD	17
CLM_KEY	7078274
MILGE	31869
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2923
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1	BUCKLE BINDING
TECH_TXT2	
CUST_TXT	C S DRIVERS SEAT BELT DOES NOT BUCKEL SEE TOM IN PARTS
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	152020
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B06
TIS_FLAG	
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	TB
ENG_CD	TNZ

ID	80
MDL_YR	2001
SORT_INDEX	358
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	9/13/2000
WRTY_START_D	11/30/2000
NAME	LONE STAR FORD
DOC_NUM	28580501
PH_NUM	8313300
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	10/4/2001
TIS_WSD	11
CLM_KEY	4320550
MILGE	14181
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8947
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEATBELT BUCKLES.
TECH_TXT2	
CUST_TXT	CHECKED RIGHT FRONT SEAT BELT LATCH WONT WORK
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152032
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU17L1M1
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	91
MDL_YR	2001
SORT_INDEX	338
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	4/30/2001
NAME	HILBISH MOTOR CO
DOC_NUM	5887101
PH_NUM	8383121
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/4/2001
TIS_WSD	0
CLM_KEY	5487178
MILGE	19884
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	080
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	CK OUT R&R DRIVER SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVER SEAT BELT KEEPS COMING LOOSE WHILE DRIVING
AREA_CD	704
COUNTRY_CD	USA
SLS_DLR_CD	171085
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRUJ18WX1L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	92
MDL_YR	2001
SORT_INDEX	380
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	8/29/2001
NAME	JOHN MARKEI, INC.
DOC_NUM	247851A
PH_NUM	3889700
WCC_CD	8R02
PART_NUM_CA	1LTZ
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/27/2001
TIS_WSD	0
CLM_KEY	5373687
MILGE	7808
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7232
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NE
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WILL NOT HOLD (SOP)
AREA_CD	402
COUNTRY_CD	USA
SLS_DLR_CD	153024
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRL16WXX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	93
MDL_YR	2001
SORT_INDEX	381
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	3/17/2001
WRTY_START_D	9/30/2001
NAME	FUTURE FORD
DOC_NUM	457095A
PH_NUM	7869873
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/26/2002
TIS_WSD	6
CLM_KEY	7635148
MILGE	6000
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	774B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	VERIFIED CONCERN. INSPECT FOUND DRIVERS BUCKLE FAULTY. REPLACED BUCKLE AND RECHECK, OK.
TECH_TXT2	
CUST_TXT	CUST STATES SEATBELT NOT LATCHED WARNING LAMP AND BUZZER INTERMITTENTLY GOES OFF EVEN WHEN SEATBELT IS LATCHED
AREA_CD	918
COUNTRY_CD	USA
SLS_DLR_CD	172208
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL1BWX1L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	94
MDL_YR	2001
SORT_INDEX	382
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/28/2001
NAME	PASO ROBLES FORD LINC-MERC
DOC_NUM	8748501
PH_NUM	2393873
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/5/2001
TIS_WSD	1
CLM_KEY	4488798
MILGE	821
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5498
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEATBELT DOESN T HOLD
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	171488
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	805
TIS_FLAG	
VIN_CD	1FMRU16WX1L
LBR_COST	
VEH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T6F
DRIVE_CD	T6
ENG_CD	T6N

ID	96
MDL_YR	2001
SORT_INDEX	383
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	9/19/2001
NAME	STURMAN & LARKIN FORD, INC.
DOC_NUM	1605451
PH_NUM	8922300
WCC_CD	6R02
PART_NUM_CA	F85Z
PART_NUM_CA	7881203
PART_NUM_CA	88E
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/27/2001
TIS_WSD	1
CLM_KEY	6044811
MILGE	810
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	7430
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	b
CPSC_CD_6	12001

TECH_TXT1	TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE
AREA_CD	412
COUNTRY_CD	USA
SLS_DLR_CD	144017
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16WXX1
LBR_COST	
VER_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VRR_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	96
MDL_YR	2001
SORT_INDEX	300
TRANS_CD	T/DX
PLANT_CD	AP
PRODN_DT	10/15/2000
WRTY_START_D	10/31/2000
NAME	ALLAN VIGIL FORD
DOC_NUM	2796851
PH_NUM	4717801
WCC_CD	BF02
PART_NUM_CA	1L72
PART_NUM_CA	7881209
PART_NUM_CA	BAB
CUST_CONC_C	520
COND_CD	42
RPR_DT	4/1/2002
TIS_WSD	18
CLM_KEY	7027828
MILGE	34638
MTRL_COST	
TOT_COST_GRO	
LAB_HRS	
DLR_CD	509
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	BUCKLE INOP SEATBELT BUCKLES	REPLACED BOTH FRONT
TECH_TXT2		
CUST_TXT	DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED	
AREA_CD		770
COUNTRY_CD	USA	
SLS_DLR_CD		141293
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG	Ⓢ	
VIN_CD	1FMRU16WX1L	
LRR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAR_STL	TWD	
VER_SERIES_C	TIEF	
DRIVE_CD	T/E	
ENG_CD	T/M	

ID	07
MDL_YR	2001
SORT_INDEX	387
TRANS_CD	TDL
PLANT_CD	AP
PRODN_DT	8/10/2000
WRTY_START_D	10/12/2000
NAME	ROCKLAND FORD LINCOLN-MERCURY
DOC_NUM	8389001
PH_NUM	5944486
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7561203
PART_NUM_CA	BAC
CUST_CONC_C	S28
COND_CD	42
RPR_DT	2/14/2002
TIS_WSD	17
CLM_KEY	6854426
MILGE	17243
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8053
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	ME
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECK AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT DOES NOT STAY BUCKLED
AREA_CD	207
COUNTRY_CD	USA
SLS_DLR_CD	111569
TXN_CD	ES4
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU16WX11 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/BF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	88
MDL_YR	2001
SORT_INDEX	388
TRANS_CD	T/DL
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	10/8/2001
NAME	DUTHLER FORD SALES, INC.
DOC_NUM	7048001
PH_NUM	9585511
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/21/2002
TIS_WSD	4
CLM_KEY	8410521
MILGE	8721
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9870
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	0
CPSC_CD_6	11001

TECH_TXT1	INSTALLED SOP DRIVERS SEAT BUCKLE RECEIVER VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	S25 INSTALL SPECIAL ORDERED DRIVERS SEAT BELT RECEIVER INTERMITTANT CONCERN COMES UNLATCHED WHILE DRIVING
AREA_CD	616
COUNTRY_CD	USA
SLS_DLR_CD	148072
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W81L
LBR_COST	
VH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7F
DRIVE_CD	T7E
ENG_CD	TMN

ID	90
MDL_YR	2001
SORT_INDEX	371
TRANS_CD	TDX
PLANT_CD	AP
PRODN_DT	4/2/2001
WRTY_START_D	4/25/2001
NAME	HARRELSON FORD, INC.
DOC_NUM	4502851
PH_NUM	6522760
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7501209
PART_NUM_CA	BAB
CUST_CONC_C	825
COND_CD	42
RPR_DT	12/9/2001
TIS_WSD	8
CLM_KEY	6487437
MILGE	11787
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1071
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Field27	0
CPSC_CD_6	11001

TECH_TXT1	BUCKLE & SWITCH BAD FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	OK DRIVERS SIDE FRONT SEAT HAS COME LOOSE WHILE DRIVING	
AREA_CD	704	
COUNTRY_CD	USA	
SLS_DLR_CD	121213	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	508	
TIS_FLAG		
VIN_CD	1FMRU16W91L	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T/63	
MKT_DERIVED	*	
BOD_CAB_STL	T/WD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/E	
ENG_CD	T/WN	

ID	100
MDL_YR	2001
SORT_INDEX	373
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	3/1/2001
NAME	CHAMPION FORD OF ALEXANDRIA
DOC_NUM	062115A
PH_NUM	4488400
WCC_CD	5R02
PART_NUM_CA	1L72
PART_NUM_CA	7661203
PART_NUM_CA	BAC
CUST_CONC_C	540
COND_CD	42
RPR_DT	3/13/2002
TIS_WSD	5
CLM_KEY	7364367
MILGE	11408
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2088
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KY
Field27	c
CPSC_CD_6	11001

TECH_TXT1	11408 REPLACE DRIVE SIDE SEAT BUCKLED
TECH_TXT2	
CUST_TXT	CUST. STATES THAT THE DRIVERS SEAT BELT COMES UNBUCKLED S.O.P IS IN
AREA_CD	859
COUNTRY_CD	USA
SLS_DLR_CD	147013
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU16W91L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	101
MDL_YR	2001
SORT_INDEX	378
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	11/11/2000
WRTY_START_D	3/13/2001
NAME	RAY SERAPHIN FORD INC
DOC_NUM	4670952
PH_NUM	8753389
WCC_CD	6F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S28
COND_CD	42
RPR_DT	4/11/2002
TLS_WSD	14
CLM_KEY	8020547
MILGE	28318
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8850
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GT
Field27	
CPSC_CD_6	11001

TECH_TXT1	SEATBELT WONT LATCH FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	DRIVERS SEAT BELT WONT LATCH	
AREA_CD	860	
COUNTRY_CD	USA	
SLS_DLR_CD	111497	
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG	G	
VIN_CD	1FMRU18W91L [REDACTED]	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T1B3	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T1EF	
DRIVE_CD	T1E	
ENG_CD	T1VN	

ID	102
MDL_YR	2001
SORT_INDEX	377
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/17/2001
NAME	ROWE FORD SALES
DOC_NUM	23410001
PH_NUM	8542555
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	825
COND_CD	42
RPR_DT	12/22/2001
TES_WSD	0
CLM_KEY	5984854
MILGE	10326
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0143
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	ME
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED BOTH FRONT SEATBELT BUCKLES
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT BUCKLE RELEASES ON IT S OWN INTERMITANTLY
AREA_CD	207
COUNTRY_CD	USA
SLS_DLR_CD	111212
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S03
TIS_FLAG	
VIN_CD	1FMRU18W81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	103
MDL_YR	2001
SORT_INDEX	378
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	9/21/2001
NAME	TOWNE FORD
DOC_NUM	061038A
PH_NUM	8865200
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/24/2001
TIS_WSD	3
CLM_KEY	4215014
MILGE	525
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8190
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS FRONR SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT STAY LATCHED
AREA_CD	202
COUNTRY_CD	USA
SLS_DLR_CD	141304
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU16W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	104
MDL_YR	2001
SORT_INDEX	388
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/9/2001
WRTY_START_D	6/4/2001
NAME	JEROME-DUNCAN, INC.
DOC_NUM	10675101
PH_NUM	2887500
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	41
RPR_DT	10/11/2001
TIS_WSD	5
CLM_KEY	4343888
MILGE	8393
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3025
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	8
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 287 of 740

RQ04-011 E 0850

TECH_TXT1	LEFT FRONT SEAT BELT BUCKEL NOT LATCHING CC 42 BP#7861203 BUCKET SEATS CHECKED OPERATION OF LEFT FRONT SEAT BELT BUCKEL INTERMITTLY WILL NOT LATCH CHECKED BELT FOR DAMAGE OK REMOVED AND REPLACED LEFT
TECH_TXT2	FRONT SEAT BELT BUCKEL OK
CUST_TXT	CUSTOMER STATES DRIVERS SIDE SEAT BELT RECEPICLE DOES NOT ALWAYS LATCH. BUCKLE WAS INSPECTED LAST MONTH PER RECALL AND PASSED INSPECTION
AREA_CD	810
COUNTRY_CD	USA
SLS_DLR_CD	148048
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRJ16W81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	106
MDL_YR	2001
SORT_INDEX	390
TRANS_CD	TDUJ
PLANT_CD	AP
PRODN_DT	3/9/2001
WRTY_START_D	10/31/2001
NAME	PAUL MILLER FORD, INC.
DOC_NUM	13418701
PH_NUM	2554242
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	1
RPR_DT	2/19/2002
TIS_WSD	4
CLM_KEY	7063818
MILGE	3352
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6888
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KY
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SEATBELT LATCH FOR NOT LOCKING C001 FP7861203
TECH_TXT2	
CUST_TXT	S26 DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING. INSTALL SOP 1L7Z786
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	147301
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU16W01
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	100
MDL_YR	2001
SORT_INDEX	383
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	8/20/2001
NAME	FAIRLANE FORD SALES, INC.
DOC_NUM	1071908
PH_NUM	8486000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S25
COND_CD	42
RPR_DT	8/21/2001
TIS_WSD	2
CLM_KEY	4074184
MILGE	1871
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3050
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	b
CPSC_CD_6	11001

TECH_TXT1	1671 REPLACE DRIVERS SIDE BELT BUCKLE WILL NOT STAY BUCKLED
TECH_TXT2	
CUST_TXT	S25 CK DRIVERS SEAT BELT SHOULDER HARNESS FEMALE PART WILL NOT STAY BUCKLE COMES UNBUCKLED AFTER LOCKED WHILE DRIVING DIAG \$36.00
AREA_CD	313
COUNTRY_CD	USA
SLS_DLR_CD	148020
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TTS_FLAG	
VIN_CD	1FMRU16W31L
LRR_COST	
VEH_LINE_CD	T/B8
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	107
MDL_YR	2001
SORT_INDEX	402
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	2/20/2001
NAME	CAPITAL LINCOLN-MERCURY INC
DOC_NUM	087840A
PH_NUM	7209100
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7051203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RFR_DT	9/27/2001
TIS_WSD	6
CLM_KEY	400080
MILGE	10497
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10528
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACED LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU16W41L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	108
MDL_YR	2001
SORT_INDEX	410
TRANS_CD	T0U
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	12/31/2001
NAME	D-PATRICK, INC.
DOC_NUM	188694A
PH_NUM	4287800
WCC_CD	5RC02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAS
CUST_CONC_C	640
COND_CD	42
RPR_DT	1/22/2002
TIS_WSD	1
CLM_KEY	6402478
MILGE	590
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IN
Field27	A
CPSC_CD_6	11001

TECH_TXT1	590 LEFT FRONT SEAT BELT LATCH NOT OPERATING PROP 42 MT61203 VERIFIED CUSTOMER COMPLAINT THAT THE SEAT BELT LATCH ON LF SEAT WILL NOT LATCH MAJORITY OF THE TIME. REMOVED OLD LATCH AND INSTALLED NEW
TECH_TXT2	ONE
CUST_TXT	S40 CUS STS THAT THE LF SEAT BELT WONT LATCH, S O PART
AREA_CD	612
COUNTRY_CD	USA
SLS_DLR_CD	147527
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W31L
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7F
DRIVE_CD	T7E
ENG_CD	T7M

ID	109
MDL_YR	2001
SORT_INDEX	412
TRANS_CD	T/DL1
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	7/18/2001
NAME	COUNTRY FORD LTD
DOC_NUM	2307252
PH_NUM	7357400
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S26
COND_CD	42
RPR_DT	2/7/2002
TIS_WSD	7
CLM_KEY	8816453
MILGE	4288
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3856
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Field27	*
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 217 of 748

RQ04-011 E 0860

TECH_TXT1	REPLACE DRIVERS SIDE SEAT BELT REPLACE SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT DONT LOCK ALL THE TIME
AREA_CD	51B
COUNTRY_CD	USA
SLS_DLR_CD	113082
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W31L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T85
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAE
DRIVE_CD	TE
ENG_CD	TVM

ID	110
MDL_YR	2001
SORT_INDEX	414
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	10/20/2000
WRTY_START_D	12/13/2000
NAME	MKE DORIAN FORD INC
DOC_NUM	2503853
PH_NUM	7824100
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/20/2001
TIS_WSD	0
CLM_KEY	3282364
MILGE	10828
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	287B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	0
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT COMES LOOSE INTERMITTENTLY, REPLACED LEFT FRONT SEAT BELT ASSEMBLY. RECHECKED, OK.
TECH_TXT2	
CUST_TXT	CLIST STATES DRIVERS SEATBELT KEEPS COMING UNHOOKED
AREA_CD	B10
COUNTRY_CD	USA
SLS_DLR_CD	148048
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU1BW31L [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T/93
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/WN

ID	111
MDL_YR	2001
SORT_INDEX	419
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/3/2001
NAME	SNO-COUNTRY FORD, INC.
DOC_NUM	4484801
PH_NUM	7436244
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7961203
PART_NUM_CA	BAA
CUST_CONC_C	B40
COND_CD	42
RPE_DT	10/26/2001
TIS_WSD	3
CLM_KEY	6780470
MILGE	3489
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8945
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 221 of 740

RQ04-011 E 0664

TECH_TXT1	VERIFIED CONCERN REPLACE SEAT BELT.
TECH_TXT2	
CUST_TXT	CUST STATES DRS SEAT BELT KEEPS COMING UNLATCHED, JUST HAD 01321 AND CHECKED OK, RECHECK
AREA_CD	360
COUNTRY_CD	USA
SLS_DLR_CD	.174011
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W21L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/ND
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	112
MDL_YR	2001
SORT_INDEX	420
TRANS_CD	TDL
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/3/2001
NAME	8NO-COUNTRY FORD, INC.
DOC_NUM	482001
PH_NUM	7436244
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RFR_DT	12/1/2001
TIS_WSD	5
CLM_KEY	5730471
MILGE	13152
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8848
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	VERIFIED BELT COMES UNHOOKED WAS REPLACED 10 26 01...RO #44848 INSTALL NEW SEAT BELT, RETEST, OK.
TECH_TXT2	
CUST_TXT	SERVICE PART WARR. SEAT BELT COMES UNHOOKED. REPLACED ON RO 44806
AREA_CD	360
COUNTRY_CD	USA
SLS_DLR_CD	174011
TXN_CD	E83
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU18W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/CF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	113
MDL_YR	2001
SORT_INDEX	421
TRANS_CD	TIDU
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	7/28/2001
NAME	BATTLEFIELD FORD
DOC_NUM	207703A
PH_NUM	3583104
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S40
CONB_CD	42
RPR_DT	8/22/2001
TIS_WSD	1
CLM_KEY	8478281
MILGE	412
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	07
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE LT FRT SEATBELT ASSY
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WONT LATCH
AREA_CD	703
COUNTRY_CD	USA
SLS_DLR_CD	127049
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRJ18W21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEF
DRIVE_CD	TIE
ENG_CD	TVN

ID	114
MDL_YR	2001
SORT_INDEX	422
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	10/22/2001
NAME	SLOAN MOTORS INC
DOC_NUM	058484A
PH_NUM	8832870
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	8AC
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/6/2002
TIS_WSD	5
CLM_KEY	7317001
MILGE	3844
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1208
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVER SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT UNLATCHES WHEN DRIVING.
AREA_CD	810
COUNTRY_CD	USA
SLS_DLR_CD	118402
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU18W21L
LBR_COST	
VEH_LINE_CD	TES
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	115
MDL_YR	2001
SORT_INDEX	425
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/26/2001
WRTY_START_D	11/20/2001
NAME	SCOTT MCNAMARA FORD MERCURY OF
DOC_NUM	044803C
PH_NUM	4256218
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/12/2002
TIS_WSD	4
CLM_KEY	7350428
MILGE	7301
MTBL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9734
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Field27	
CPSC_CD_6	11001

TECH_TXT1	TESTED AND FOUND BAD LATCH, REPLACED LATCH ASSEMBLY.
TECH_TXT2	
CUST_TXT	INT DR BEAT BELT DONT LATCH, CANT HEAR IT CLICK
AREA_CD	000
COUNTRY_CD	USA
SLS_DLR_CD	148606
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU16W11L
LRR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	118
MDL_YR	2001
SORT_INDEX	428
TRANS_CD	TDL
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	6/29/2001
NAME	FAMILY FORD INC
DOC_NUM	8017051
PH_NUM	3473000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	4/17/2002
TIS_WSD	11
CLM_KEY	8175762
MILGE	18718
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20323
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
Field27	*
CPSC_CD_6	11001

TECH_TXT1	CHECK SEAT BELT OPERATION PERFORM DIAG FOUND LATCH NOT LATCHING REPLACE SEAT BELT LATCH RETEST OPERATION OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES INSTALL SPO SEAT BELT PART LEFT FRONT SEAT BELT WILL NOT LATCH
AREA_CD	973
COUNTRY_CD	USA
SLS_DLR_CD	113452
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W11U
LRR_COST	
VEH_LINK_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T1E
ENG_CD	T1V1

ID	117
MDL_YR	2001
SORT_INDEX	427
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	8/3/2001
NAME	MALOUF FORD, INC.
DOC_NUM	20088A
PH_NUM	8510300
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	626
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	7
CLM_KEY	7208804
MILGE	8861
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20627
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
Field27	*
CPSC_CD_6	11001

TECH_TXT1

0901 INSTALLED NEW DRIVERS SEAT BELT BUCKLE
CANT PERFORM 01S21 RECALL W OUI TOOL D S
BUCKLE WOULDNT LATCH

TECH_TXT2

CUST_TXT

CUST STATES D S FRONT SEATBELT DOES NOT
LATCH IN SPO PART CHECK ALSO FOR 01S21 RECALL
SEATBELT BUCKLE

AREA_CD

732

COUNTRY_CD

USA

SLS_DLR_CD

113055

TXN_CD

1

CNTRY_SOLD

USA

QRT_CD

Q21

VFG_CD

V06

AWS_VL_CD

B3

VRT_CD

S08

TIS_FLAG

VIN_CD

1FMRU16W11L

LBR_COST

VEH_LINE_CD

TRE3

MKT_DERIVED

*

BOD_CAB_STL

TWD

VER_SERIES_C

TRE

DRIVE_CD

T/E

ENG_CD

T/VN

ID	118
MDL_YR	2001
SORT_INDEX	430
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	5/18/2001
NAME	FRIENDLY FORD, INC.
DOC_NUM	214260C
PH_NUM	8834330
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONG_C	S40
COND_CD	42
RPR_DT	11/29/2001
TIS_WSD	7
CLM_KEY	5902291
MILGE	890E
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6017
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	C
CPSC_CD_6	11001

TECH_TXT1	8985 7581203 BUCKLE, 42 DNOP CONFIRMED CUST CONCERN OF DRIVER SIDE SEAT BELT BUCKLE NOT HOLDING. REPLACED LF BUCKET SEAT BUCKLE ASSEMBLY. RETEST, WORKING PROPERLY AFTER REPAIR.
TECH_TXT2	
CUST_TXT	C S DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING
AREA_CD	417
COUNTRY_CD	USA
SLS_DLR_CD	153480
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W11L
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	118
MDL_YR	2001
SORT_INDEX	433
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	10/26/2000
WRTY_START_D	11/17/2000
NAME	JERRY ALDERMAN FORD INC
DOC_NUM	8120551
PH_NUM	2511441
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/13/2001
TIS_WSD	6
CLM_KEY	2935140
MILGE	8142
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4871
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
Field27	b
CPSC_CD_6	11001

TECH_TXT1	HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.
TECH_TXT2	
CUST_TXT	CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART
AREA_CD	317
COUNTRY_CD	USA
SLS_DLR_CD	147027
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU18W11L
LBR_COST	
VKH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN

ID	120
MDL_YR	2001
SORT_INDEX	434
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	12/4/2001
NAME	NORRIS FORD OF EASTON, LLC
DOC_NUM	2870251
PH_NUM	8222800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7581203
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	4/10/2002
TIS_WSD	6
CLM_KEY	0040573
MILGE	3775
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3008
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MD
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 239 of 740

RQ04-011 E 0682

TECH_TXT1	D S SEAT BELT FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CUSTOMER STATES DRIVER SEAT BELT UNFASTENS WHILE DRIVING	
AREA_CD	410	
COUNTRY_CD	USA	
SLS_DLR_CD	127558	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VPG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	308	
TIS_FLAG	@	
VIN_CD	1FMRU16W01L	
LRR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	T/WD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/E	
ENG_CD	T/WN	

ID	121
MDL_YR	2001
SORT_INDEX	437
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/25/2001
WRTY_START_D	12/31/2001
NAME	HEINTZELMAN'S TRUCK CENTER INC
DOC_NUM	199864A
PH_NUM	2881000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7961203
PART_NUM_CA	BAB
CUST_CONC_C	940
COND_CD	42
RPR_DT	10/18/2001
TIS_WSD	0
CLM_KEY	4695325
MILGE	11
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6025
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	a
CPSC_CD_6	11001

TECH_TXT1	11 SEAT BELT NOT LATCHING. 4 DR SEAT BELT BUCKLE NOT LATCHING. ORDERED NEW BUCKLE. INSTALLED. PROBLEM FIXED
TECH_TXT2	
CUST_TXT	C.S LEFT FRONT SEAT BELT INOP. CH ADVISE
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124900
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15WX1L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T8
RNG_CD	TAV

ID	122
MDL_YR	2001
SORT_INDEX	441
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/10/2001
WRTY_START_D	5/28/2001
NAME	BOWDEN FORD LINCOLN MERCURY CO
DOC_NUM	D90571A
PH_NUM	8649541
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAC
CUST_CONC_C	S25
COND_CD	42
RPR_DT	4/25/2002
TIS_WSD	12
CLM_KEY	8378501
MILGE	8845
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4400
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	■
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 243 of 749

RQ04-011 E 0688

TECH_TXT1	RAN DIAG FOUND SEAT BELT WOULD NOT LATCH REPLACE SEAT BELT ASSY
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT ON DRIVER SIDE DOES NOT WORK
AREA_CD	381
COUNTRY_CD	USA
SLS_DLR_CD	152088
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	@
VIN_CD	1FMRJ15WX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVN

ID	123
MDL_YR	2001
SORT_INDEX	446
TRANS_CD	TADJ
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	8/3/2001
NAME	HARELSON FORD, INC.
DOC_NUM	5518152
PH_NUM	5522760
WCC_CD	6R02
PART_NUM_CA	F85Z
PART_NUM_CA	7881203
PART_NUM_CA	AAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	4/4/2002
TIS_WSD	11
CLM_KEY	7904993
MILGE	7419
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	1071
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Field27	o
CPSC_CD_6	12001

TECH_TXT1	SEATBELT _____ REPLACED LEFT FRONT BELT
TECH_TXT2	_____
CUST_TXT	LF SEAT BELT COMES UNHOOKED. PLS R R (PARTS SHOULD HAVE BEEN ORDERED)
AREA_CD	_____ 704
COUNTRY_CD	USA _____
SLS_DLR_CD	_____ 121213
TXN_CD	1 _____
CNTRY_SOLD	USA _____
QRT_CD	Q21 _____
VFG_CD	V05 _____
AWS_VL_CD	B8 _____
VRT_CD	B08 _____
TIS_FLAG	_____
VIN_CD	1FMRJ16WXX1L _____
LBR_COST	_____
VEH_LINE_CD	T/B3 _____
MKT_DERIVED	* _____
BOD_CAB_STL	TWD _____
VER_SERIAL_C	T/EF _____
DRIVE_CD	T/B _____
ENG_CD	TMN _____

ID	124
MDL_YR	2001
SORT_INDEX	44B
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	5/10/2001
NAME	WESTWAY FORD
DOC_NUM	05000001
PH_NUM	6590339
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	4/13/2002
TIS_WSD	12
CLM_KEY	7873634
MILGE	10839
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	2580
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 247 of 740

RQ04-011 E 0690

TECH_TXT1	TESTED; DRIVER SIDE FAILED
TECH_TXT2	
CUST_TXT	CUST REPORTS DRIVERS SEAT BELT WILL NOT STAY LATCHED AT TIMES...POPS OUT
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152013
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	0
VIN_CD	1FMRU15WX1
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	125
MDL_YR	2001
SORT_INDEX	447
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/26/2001
NAME	VISTA FORD
DOC_NUM	4801861
PH_NUM	8847800
WCC_CD	GR02
PART_NUM_CA	1L72
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	7/12/2001
TIS_WSD	2
CLM_KEY	2451504
MILGE	1588
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7823
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	09 7861203 LEFT FRONT SEAT ACCESS TO REPLACE DRIVERS SEAT BELT BUCKLE THAT
TECH_TXT2	
CUST_TXT	CUST STATES DR FRNT SEAT BELT WILL POP OUT OF RECEPTACLE WHILE DRIVING INTERIM AND TAKES ABOUT 3 4 TIMES BEFORE WILL LOCK BACK INTO RECEPTACLE
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171049
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15WXX1L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TBF
DRIVE_CD	TB
ENG_CD	TVN

ID	128
MDL_YR	2001
SORT_INDEX	451
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	6/23/2001
NAME	FORD COUNTRY OF LEWISVILLE
DOC_NUM	1006532
PH_NUM	2212800
WCC_CD	8R02
PART_NUM_CA	1L72
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/7/2001
TIS_WSD	7
CLM_KEY	5815266
MILGE	7078
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7987
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT BUCKLE INOP SEAT BELT BUCKLE	REPLACE DRIVER
TECH_TXT2		
CUST_TXT	THE DRIVERS SIDE SEAT BELT COMES UNLATCH WHILE DRIVING 328 CK AND SAYS THEY ARE OK	
AREA_CD	972	
COUNTRY_CD	USA	
SLS_DLR_CD	162007	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG		
VIN_CD	1FMRU13WX1	
LBR_COST		
VEH_LINE_CD	TB3	
MKT_DERIVED		
BOD_CAB_STL	TWD	
VER_SERIRS_C	TIEF	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	127
MDL_YR	2001
SORT_INDEX	452
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/9/2001
WRTY_START_D	8/25/2001
NAME	FORD WEST
DOC_NUM	5388451
PH_NUM	7803673
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	8AB
CUST_CONC_C	540
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	6
CLM_KEY	6044011
MILGE	4105
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6440
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	INOP DRIVERS SIDE SEAT BELT BUCKLE MT TO REPL DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUST SAYS DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING
AREA_CD	582
COUNTRY_CD	USA
SLS_DLR_CD	171047
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU18WXC1L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/W3
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	128
MDL_YR	2001
SORT_INDEX	453
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	9/10/2001
NAME	GOLDING MOTORS INC
DOC_NUM	7875361
PH_NUM	3725707
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	9/28/2001
TIS_WSD	1
CLM_KEY	4171748
MILGE	1509
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2588
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACE LEFT FRONT SEATBELT FEMALE INOP
TECH_TXT2	
CUST_TXT	C S DRIVERS SEATBELT COMES OFF DRIVING DOWN THE ROAD
AREA_CD	015
COUNTRY_CD	USA
SLS_DLR_CD	152498
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16NXX1L
LBR_COST	
VEH_LINE_CD	T/ES
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	129
MDL_YR	2001
SORT_INDEX	454
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/7/2001
WRTY_START_D	5/11/2001
NAME	FORD OF UPLAND
DOC_NUM	178722A
PH_NUM	8485555
WCC_CD	BR02
PART_NUM_CA	F85Z
PART_NUM_CA	7861203
PART_NUM_CA	B8E
CUST_CONC_C	326
COND_CD	41
RPR_DT	7/12/2001
TIS_WSD	3
CLM_KEY	2340082
MILGE	2254
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6566
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_5	12001

Tuesday, December 14, 2004

Page 237 of 740

RQ04-011 E 0700