

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 2 OF 6

BOOK 2 OF 43

TECH_TXT1	08 01821D O.B REPL D SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CK SEATBELT WONT LATCH
AREA_CD	938
COUNTRY_CD	USA
SLS_DLR_CD	152188
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W81L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	195
MDL_YR	2001
SORT_INDEX	558
TRANS_CD	TDLJ
PLANT_CD	AP
PRODN_DT	1/31/2001
WRTY_START_D	3/9/2001
NAME	SAM GALLOWAY FORD, INC.
DOC_NUM	53544501
PH_NUM	8383873
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881209
PART_NUM_CA	9AB
CUST_CONC_C	S40
COND_CD	88
RPR_DT	10/28/2001
TIS_WSD	8
CLM_KEY	4720518
MILGE	7448
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4845
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	C
CPSC_CD_6	11001

TECH_TXT1	7861202 CODE 89 7448 M O R 1 BOTH FRONT BUCKET SEATS.REPLACED BOTH FRONT SEATBELTS. RETEST PASS.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES:DRIVERS SEAT BELT KEEPS COMING UNLATCHED PLS RECHECK PASSENGERS AS WELL
AREA_CD	841
COUNTRY_CD	USA
SLS_DLR_CD	124400
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W61L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	195
MDL_YR	2001
SORT_INDEX	589
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	3/7/2001
NAME	LONE STAR FORD
DOC_NUM	28875802
PH_NUM	9913900
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	BAB
CUST_CONC_C	925
COND_CD	33
RPR_DT	4/5/2002
TIS_WSD	14
CLM_KEY	7870316
MILGE	28715
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	8947
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	ACCESS AND REPLACE SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT COMES UNLATCHED
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152028
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	Ⓢ
VIN_CD	1FMRU16W61L
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	197
MDL_YR	2001
SORT_INDEX	580
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	3/31/2001
NAME	NORTH COUNTY FORD
DOC_NUM	248036A
PH_NUM	9489000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/8/2002
TIS_WSD	10
CLM_KEY	B138984
MILGE	11723
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	889
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1

11726 SEAT BELT INOP 998A 0.2 81203 0.3 CONFIRMED
CUST CONCERN INSP AND TESTED OPERATION OF
SEAT BELTS DRIVERS BUCKLE NOT STAYING LATCHED
HED REPLACED SEAT BELT BUCKLE DRIVERS SEAT
QUALITY TESTED OK

TECH_TXT2

CUST_TXT

CUSTOMER STATES: FRONT DRIVER SIDE SEAT
BELT DOES NOT STAY LATCHED ALL THE TIME.
CHECK ALL SEAT BELTS

AREA_CD

780

COUNTRY_CD

USA

SLS_DLR_CD

171079

TXN_CD

2

CNTRY_SOLD

USA

QRT_CD

Q21

VFG_CD

V06

AWS_VL_CD

B3

VRT_CD

S05

TIS_FLAG

VIN_CD

1FMRU15W81

LBR_COST

14,894

VEH_LINE_CD

TB3

MKT_DERIVED

BOD_CAB_STL

TWD

VER_SERIES_C

TAF

DRIVE_CD

TB

ENG_CD

TAV

ID	198
MDL_YR	2001
SORT_INDEX	593
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	12/8/2000
WRTY_START_D	2/25/2001
NAME	JIM TIDWELL'S WORLD FORD
DOC_NUM	9873851
PH_NUM	4275531
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	T90
COND_CD	1
RPR_DT	2/18/2002
TIS_WSD	12
CLM_KEY	0904500
MILGE	16264
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field17	C
CPSC_CD_6	11001

TECH_TXT1	R&R DRIVER SEAT, REPL BROKEN SEAT BELT BUCKLE, RETEST.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT WILL COME LOOSE WHEN DRIVING SPO PARTS IN
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121023
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRLU15W61L [REDACTED]
LHR_COST	[REDACTED]
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	199
MDL_YR	2001
SORT_INDEX	694
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/24/2000
WRTY_START_D	11/9/2000
NAME	ATASCADERO FORD
DOC_NUM	5835401
PH_NUM	4889484
WCC_CD	8RI2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S28
COND_CD	42
RPR_DT	1/18/2002
TIS_WSD	18
CLM_FBY	8551187
MILGE	31118
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7848
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEATBELT BUCKLE AND NOW OK
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEATBUCKLE WONT LATCH. SOP
AREA_CD	806
COUNTRY_CD	USA
SLS_DLR_CD	171251
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15W61L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	TB
ENG_CD	TMN

ID	200
MDL_YR	2001
SORT_INDEX	595
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	7/17/2001
WRTY_START_D	8/10/2001
NAME	FAIRWAY FORD, INC.
DOC_NUM	187885A
PH_NUM	2426000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881209
PART_NUM_CA	GAB
CUST_CONC_C	325
COND_CD	42
RPR_DT	8/1/2001
TIS_WSD	0
CLM_KEY	2803088
MILGE	4
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	977
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	9C
Field27	
CPSC_CD_6	11001

TECH_TXT1	CK AND REPLACED LEFT FRT SEAT BELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	DRIVERS SEATBELT WILL NOT LATCH
AREA_CD	864
COUNTRY_CD	USA
SLS_DLR_CD	121226
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRJ16W51L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	TTF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	201
MDL_YR	2001
SORT_INDEX	000
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	5/8/2001
WRTY_START_D	8/30/2001
NAME	SUNBELT FORD-MERCURY INC
DOC_NUM	8161801
PH_NUM	7787681
WCC_CD	6R02
PART_NUM_CA	1172
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/5/2001
TIS_WSD	1
CLM_KEY	2723308
MILGE	622
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4634
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	G
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT LATCHES DEFECTIVE REPLACE SEAT BELTS FRT.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SIDE SEAT BELT COMES LOOSE FOR NO REASON
AREA_CD	228
COUNTRY_CD	USA
SLS_DLR_CD	121573
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S00
TIS_FLAG	
VIN_CD	1FMRU15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVN

ID	202
MDL_YR	2001
SORT_INDEX	802
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	4/26/2001
WRTY_START_D	5/28/2001
NAME	GAUDIN FORD
DOC_NUM	8023351
PH_NUM	7312121
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAB
CUST_CONC_C	826
COND_CD	42
RPR_DT	2/16/2002
TIS_WSD	9
CLM_KEY	8878383
MILGE	9018
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7808
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NV
Field27	a
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT NOT WORKING PROPERLY CK SEAT BELT BUCKLE NOT LOCKING IN ALL TIMES REPLACE SEAT BELT BUC
TECH_TXT2	
CUST_TXT	RECALL ON SEATBELT WAS DONE BUT SEATBELT IS NOT LATCHING LEFT FRONT SEAT BELT CK BOTH FT SEAT BELTS
AREA_CD	702
COUNTRY_CD	USA
SLS_DLR_CD	171188
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W51L
LRR_COST	3291
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	209
MDL_YR	2001
SORT_INDEX	809
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/29/2001
WRTY_START_D	5/17/2001
NAME	HARRELSON FORD, INC.
DOC_NUM	5821852
PH_NUM	5522780
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	828
COND_CD	42
RPR_DT	5/13/2002
TIS_WSD	13
CLM_KEY	8582982
MILGE	15786
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1071
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	BUCKLE MALFUNCTIONS FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	C S LEFT FRONT SEAT BELT BUCKLE COMES UNLATCHED WHILE DRIVING INT.	
AREA_CD	704	
COUNTRY_CD	USA	
SLS_DLR_CD	121213	
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG	@	
VIN_CD	1FMRU16W51L [REDACTED]	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T/BS	
MKT_DERIVED	.	
BOD_CAR_STL	T/WD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	204
MDL_YR	2001
SORT_INDEX	808
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	9/28/2001
NAME	TOWN EAST FORD
DOC_NUM	7758300
PH_NUM	2708441
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	325
COND_CD	1
RPE_DT	11/13/2001
TIS_WSD	2
CLM_KEY	5283647
MILGE	3431
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6182
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 487 of 740

RQ04-011 E 0850

TECH_TXT1	3436 BROKEN 01 REPLACED LT FT SEAT BELT ASSY
TECH_TXT2	
CUST_TXT	S05 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU15W511
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	205
MDL_YR	2001
SORT_INDEX	607
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/6/2001
NAME	BOB BROCK FORD, INC.
DOC_NUM	7684001
PH_NUM	2677424
WCC_CD	BR02
PART_NUM_CA	1LZZ
PART_NUM_CA	7064203
PART_NUM_CA	BAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	3
CLM_KEY	2283511
MILGE	1522
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2403
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE WILL NOT STAY FASTENED
AREA_CD	015
COUNTRY_CD	USA
SLS_DLR_CD	152573
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B0
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU15WS1L
LBR_COST	
VEH_LINE_CD	T03
MKT_DERIVED	
BOD_CAB_STL	TAND
VER_SERIES_C	TJEF
DRIVE_CD	T/B
ENG_CD	TVN

ID	208
MDL_YR	2001
SORT_INDEX	009
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/14/2001
WRTY_START_D	7/7/2001
NAME	CERRITOS FORD
DOC_NUM	28853002
PH_NUM	8855564
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851208
PART_NUM_CA	BAB
CUST_CONC_C	525
COND_CD	42
RPR_DT	9/19/2001
TIS_WSD	3
CLM_KEY	3851949
MILGE	3187
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5401
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	TEST AND REPLACE BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEAT BELT UNBUCKLES AT TIMES WHILE DRIVING
AREA_CD	582
COUNTRY_CD	USA
SLS_DLR_CD	171055
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TAM0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	207
MDL_YR	2001
SORT_INDEX	610
TRANS_CD	TDU
PLANT_CD	AF
PRODN_DT	4/12/2001
WRTY_START_D	5/15/2001
NAME	DON REID FORD, INC.
DOC_NUM	1324751
PH_NUM	6447111
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	T50
COND_CD	42
RPR_DT	3/25/2002
TIS_WSD	8
CLM_KEY	7604283
MILGE	15853
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4892
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INOP CONCERN.REPLACE DRIVERS SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS SEAT BELT POPS OPEN WHILE DRIVING
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124214
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V71
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W51L
LBR_COST	
VEH_LINK_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAF
DRIVE_CD	T8
ENG_CD	TVN

ID	208
MDL_YR	2001
SORT_INDEX	611
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/30/2001
WKTY_START_D	4/22/2001
NAME	AIRPORT MARINA FORD
DOC_NUM	25807601
PH_NUM	8483873
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	GAB
CUST_CONC_C	926
COND_CD	42
RPR_DT	3/15/2002
TTS_WSD	11
CLM_KEY	7447982
MILGE	10850
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5563
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	E REPLACED DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES: THE DRIVER S SEAT BELT WILL NOT STAY LATCHED, SOP IN
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W51
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EP
DRIVE_CD	T/B
ENG_CD	T/VN

ID	208
MDL_YR	2001
SORT_INDEX	812
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/30/2001
WRTY_START_D	8/22/2001
NAME	FORD OF NORTH MIAMI BEACH
DOC_NUM	24692002
PH_NUM	8481311
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/17/2001
TIS_WSD	3
CLM_KEY	6304003
MILGE	3488
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4088
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED THE FRONT DRIVER SIDE SEAT BELT BUCKEL. THE DRIVER SIDE SEAT SLET BUCKLE WAS DEFECTIVE.
TECH_TXT2	
CUST_TXT	S40 D S F RESTRAINT UNLOCKS WHILE DRIVING
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	124001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	
VIN_CD	1FMRU15W61U
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TAF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	210
MDL_YR	2001
SORT_INDEX	813
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	5/22/2001
NAME	PINECREST FORD-MERCURY, INC.
DOC_NUM	218551
PH_NUM	3274327
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/10/2001
TIS_WSD	5
CLM_KEY	4063702
MILGE	7048
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7018
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT BUCKLE WITH NEW ONE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING LIGHT TAN
AREA_CD	036
COUNTRY_CD	USA
SLS_DLR_CD	152158
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINE_CD	YB3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	211
MDL_YR	2001
SORT_INDEX	615
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/12/2001
WRTY_START_D	7/20/2001
NAME	KRIEGER FORD, INC.
DOC_NUM	323442A
PH_NUM	8853320
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	10/12/2001
TIS_WSD	3
CLM_KEY	4373214
MILGE	3321
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2198
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Field27	8
CPSC_CD_6	11001

TECH_TXT1	3321 REPLACED DRIVER SIDE SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	REP. DRIVERS SEAT BELT WILL NOT LATCH
AREA_CD	814
COUNTRY_CD	USA
SLS_DLR_CD	147018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	G08
TIS_FLAG	
VIN_CD	1FMRU19W511
LBR_COST	19322
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/RWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	212
MDL_YR	2001
SORT_INDEX	622
TRANS_CD	TIOU
PLANT_CD	AP
PRODN_DT	12/21/2000
WRTY_START_D	8/28/2001
NAME	BOB TILLERY FORD, INC.
DOC_NUM	1142401
PH_NUM	5423171
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/8/2001
TIS_WSD	1
CLM_KEY	2247581
MILGE	388
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4481
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT WILL NOT LATCH
AREA_CD	400
COUNTRY_CD	USA
SLS_DLR_CD	162771
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W51L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	213
MDL_YR	2001
SORT_INDEX	628
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	8/16/2001
NAME	LAFAYETTE MOTOR SALES INC
DOC_NUM	812851
PH_NUM	4240281
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	Y881203
PART_NUM_CA	BAB
CUST_CONC_C	T90
COND_CD	42
RPR_DT	3/5/2002
TIS_WSD	7
CLM_KEY	7306854
MILGE	13458
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	900
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Field27	a
CPSC_CD_6	11001

TECH_TXT1	NO REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	DRIVER SEATBELT WILL NOT BUCKLE AT TIMES USE SPO 02050001	
AREA_CD		910
COUNTRY_CD	USA	
SLS_DLR_CD		121028
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V74	
AWS_VL_CD	B3	
VRT_CD	SGB	
TIS_FLAG		
VIN_CD	1FMRL15W41L	
LBR_COST		
VEH_LINE_CD	T8A	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T8F	
DRIVE_CD	T8	
ENG_CD	T8N	

ID	214
MDL_YR	2001
SORT_INDEX	628
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/16/2001
WRTY_START_D	10/1/2001
NAME	DOMINO FORD, INC.
DOC_NUM	151836A
PH_NUM	3853000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	SAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/17/2002
TIS_WSD	4
CLM_KEY	8364104
MILGE	4884
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1777
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	L
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSTALLED DRIVERS SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	DRIVERS SEATBELT WILL NOT STAY LATCHED INSTALL SOP
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	141052
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	306
TIS_FLAG	
VIN_CD	1FMRJ15W41
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/W

ID	215
MDL_YR	2001
SORT_INDEX	832
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	5/28/2001
NAME	HUB CITY FORD, INC.
DOC_NUM	6885852
PH_NUM	2334500
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	807
COND_CD	41
RPR_DT	11/12/2001
TIS_WSD	8
CLM_KEY	5137237
MILGE	13888
MTRL_COST	28.06
TOT_COST_GRO	87.81
LBR_HRS	0.0
DLR_CD	6481
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	
CPSC_CD_6	11001

ID	218
MDL_YR	2001
SORT_INDEX	633
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/20/2001
NAME	LOU GRUBB FORD
DOC_NUM	4477662
PH_NUM	0013333
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7081203
PART_NUM_CA	BAA
CUST_CONC_C	S26
COND_CD	33
RPR_DT	3/18/2002
TIS_WSD	10
CLM_KEY	7535389
MILGE	12008
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20323
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SEAT BELT BUCKLE DUE TO LOOSE
TECH_TXT2	
CUST_TXT	CUST STATES THAT DRIVER SEAT BELT COMES UNDONE SOMETIMES WHILE DRIVING
AREA_CD	002
COUNTRY_CD	USA
SLS_DLR_CD	171178
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU15W41L [REDACTED]
LBR_COST	[REDACTED]
VRH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/ND
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	217
MDL_YR	2001
SORT_INDEX	634
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	5/31/2001
NAME	CRESCENT FORD INC
DOC_NUM	20763603
PH_NUM	8092101
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	4/8/2002
TIS_WSD	11
CLM_KEY	7886780
MILGE	11188
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	1028
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	CHECKED OUT, R AND R DRIVERS SEAT AND REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DR. SEATBELT COMES UNFASTENED AT TIMES
AREA_CD	338
COUNTRY_CD	USA
SLS_DLR_CD	121818
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	608
TIS_FLAG	
VIN_CD	1FMRU16W41L
LBR_COST	
VBH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

TECH_TXT1	CP 7881203 CC 42 DRIVERS SIDE SEATBELT TEST SEATBELT OPERATION, REPLACED SEATBELT
TECH_TXT2	
CUST_TXT	C 8 THE SEAT BELT WILL COME UNLATCHED
AREA_CD	318
COUNTRY_CD	USA
SLS_DLR_CD	123223
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL15W41L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
HOD_CAR_STL	TND
VER_SERIES_C	T1F
DRIVE_CD	TB
ENG_CD	TMM

ID	219
MDL_YR	2001
SORT_INDEX	838
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	9/3/2001
NAME	GREENWAY FORD, INC.
DOC_NUM	740461
PH_NUM	2753200
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	640
COND_CD	42
RPR_DT	11/18/2001
TIS_WSD	a
CLM_KEY	5161101
MILGE	2728
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4622
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	a
CPSC_CD_6	11001

TECH_TXT1	INCP REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	O R DRIVERS SEATBELT CAN BE PULLED OUT, OR WHEN IT IS PUT UNDER PRESSURE IT WILL COME OUT OF BUCKLE	
AREA_CD		407
COUNTRY_CD	USA	
SLS_DLR_CD		124224
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	806	
TIS_FLAG		
VIN_CD	1FMRU15W41L	
LBR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	TWO	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	220
MDL_YR	2001
SORT_INDEX	640
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	3/14/2001
WRTY_START_D	4/5/2001
NAME	GAMES MOTOR COMPANY, INC.
DOC_NUM	040288D
PH_NUM	7214700
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7561203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	30
RPR_DT	2/15/2002
TIS_WSD	11
CLM_KEY	7130174
MILGE	10532
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4485
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	10533 SEAT BUCKLES 30 W/R INSPECTED AND FOUND BOTH SEAT BUCKLES INOP. R/R BOTH FRONT SEAT BUCKLES AND RETESTED.PASS.
TECH_TXT2	
CUST_TXT	940 CUSTOMER STATES DRIVER SEAT BELT COMES UNBUCKLED
AREA_CD	968
COUNTRY_CD	USA
SLS_DLR_CD	152772
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V15
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRJ15W41L
LBR_COST	
VEH_LINE_CD	T93
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T1B
ENG_CD	TWN

ID	221
MDL_YR	2001
SORT_INDEX	044
TRANS_CD	T0J
PLANT_CD	AP
PRODN_DT	3/5/2001
WRTY_START_D	8/2/2001
NAME	GULLO FORD-MERCURY OF CONROE
DOC_NUM	396707A
PH_NUM	7567781
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S2B
COND_CD	42
RPR_DT	5/1/2002
TIS_WSD	12
CLM_KEY	8344764
MILGE	33072
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 441 of 740

RQ04-011 E 0884

TECH_TXT1	33072 MT 7881203 .8 .8 REPLACED DRIVER SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	THE DRIVERS SEAT SEATBELT RECIEVER KEEPS LETTING LOOSE OF THE BELT. CHECK AND ADVISE
AREA_CD	030
COUNTRY_CD	USA
SLS_DLR_CD	152168
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
YFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	0
VIN_CD	1FMRU15W41
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	TVN

ID	222
MDL_YR	2001
SORT_INDEX	653
TRANS_CD	T0U
PLANT_CD	AP
PRODN_DT	11/27/2000
WRTY_START_D	9/15/2001
NAME	BROWNWOOD FORD-LINCOLN-MERCURY
DOC_NUM	8082561
PH_NUM	6431651
WCC_CD	6R02
PART_NUM_CA	F85Z
PART_NUM_CA	78B1203
PART_NUM_CA	BBE
CUST_CONC_C	340
COND_CD	42
RPR_DT	11/2/2001
TIS_WSD	2
CLM_KEY	4978737
MILGE	2558
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2874
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	12001

TECH_TXT1	CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.
TECH_TXT2	
CUST_TXT	CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...
AREA_CD	816
COUNTRY_CD	USA
SLS_DLR_CD	152016
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	228
MDL_YR	2001
SORT_INDEX	856
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	3/17/2001
NAME	COURTESY FORD
DOC_NUM	7087802
PH_NUM	3288000
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S26
COND_CD	42
RPR_DT	11/17/2001
TIS_WSD	8
CLM_KEY	5775242
MILGE	11684
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1825
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	*
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 445 of 740

RQ04-011 E 0888

TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT1	STR DR SEATBELT WONT STAY LATCHED
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124226
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W41L
LRR_COST	
VBH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	224
MDL_YR	2001
SORT_INDEX	867
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	6/20/2001
WRTY_START_D	8/28/2001
NAME	FAIRWAY FORD
DOC_NUM	8410061
PH_NUM	5241200
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/20/2002
TIS_WSD	7
CLM_KEY	8487229
MILGE	6712
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5478
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT UNLATCHES AT TIMES.
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	171009
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL15W31 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVN

ID	225
MDL_YR	2001
SORT_INDEX	880
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	8/20/2001
NAME	LAFAYETTE MOTOR SALES INC
DOC_NUM	9107861
PH_NUM	4240281
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	2836079
MILGE	2
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	000
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Fle#27	*
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 449 of 748

RQ04-011 E 0892

TECH_TXT1	REPLACED LEFT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER'S SEAT BELT BUCKLE WILL NOT HOLD.
AREA_CD	910
COUNTRY_CD	USA
SLS_DLR_CD	12122A
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRJ15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	228
MDL_YR	2001
SORT_INDEX	005
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	5/5/2001
NAME	DUB MILLER FORD INC
DOC_NUM	7382501
PH_NUM	3425811
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7981203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	1
RPR_DT	2/20/2002
TIS_WSD	9
CLM_KEY	7060124
MILGE	13041
MYRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	4480
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field 27	a
CPSC_CD_6	11001

TECH_TXT1	1 DIAG UPON INSP REVEALED INTER MIT NO LATCH CAUSED BY BUCKLE INTERNAL DAMAGED BROKE REPLACED BUCKLE ASMBLY & CKD FOR PROP
TECH_TXT2	
CUST_TXT	DRIVER SEAT BUCKLE WILL NOT ALWAYS LATCH
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152024
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEF
DRIVE_CD	T/B
ENG_CD	TVN

ID	227
MDL_YR	2001
SORT_INDEX	688
TRANS_CD	T0U
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	6/7/2001
NAME	GRAHAM FORD, INC.
DOC_NUM	043281A
PH_NUM	4848000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	640
COND_CD	42
RPR_DT	11/15/2001
TIS_WSD	6
CLM_KEY	5184768
MILGE	4288
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2232
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Field27	c
CPSC_CD_6	11001

TECH_TXT1	4268 REPLACED BELT Y
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS SEAT BELT CONSTANTLY COMES LOOSE AFTER IT HAS BEEN FASTENED.
AREA_CD	814
COUNTRY_CD	USA
SLS_DLR_CD	147312
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRJ15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVN

ID	228
MDL_YR	2001
SORT_INDEX	888
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/7/2001
NAME	TOWN EAST FORD
DOC_NUM	788041A
PH_NUM	2708441
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	825
COND_CD	33
RPR_DT	8/14/2001
TIS_WSD	1
CLM_KEY	4045134
MILGE	823
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8182
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	523 42 REPLACED DRIVERS SIDE SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES
TECH_TXT2	
CUST_TXT	DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED AT TIMES
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	162482
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B06
TIS_FLAG	
VIN_CD	1FMRJ15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	228
MDL_YR	2001
SORT_INDEX	871
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	4/25/2001
NAME	GREENWAY FORD, INC.
DOC_NUM	8418552
PH_NUM	2753200
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	0
CLM_KEY	8485454
MILGE	12863
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4822
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	ON BOTH SEAT BELT BUCKLES KEEP COMING UNDONE WHEN DRIVING?
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	14144B
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VHT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	230
MDL_YR	2001
SORT_INDEX	872
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/12/2001
NAME	MAGIC FORD
DOC_NUM	1280651
PH_NUM	2558800
WCC_CD	8R02
PART_NUM_CA	1LZ
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/11/2001
TIS_WSD	6
CLM_KEY	4973037
MILGE	5840
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1884
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	INSPECT AND REPLACE DRIVER SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS SEAT BELT WILL NOT STAY LOCKED POPS OFF WHILE DRIVING
AREA_CD	981
COUNTRY_CD	USA
SLS_DLR_CD	171481
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU16W31L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	231
MDL_YR	2001
SORT_INDEX	874
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/26/2001
NAME	PUENTE HILLS FORD
DOC_NUM	2787981
PH_NUM	8843873
WCC_CD	6R02
PART_NUM_CA	F88Z
PART_NUM_CA	7881203
PART_NUM_CA	BBE
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	3
CLM_KEY	2888787
MILGE	3082
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6550
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	12001

TECH_TXT1	REPLACE SEAT BELT BUCKLE REPAIRS	ADDITIONAL MISC.
TECH_TXT2		
CUST_TXT	INSTALL SPO PART HERE DRIVER SEAT BELT BUCKLE NOT LOCKING INTERMIT 01158003	SPO#
AREA_CD	626	
COUNTRY_CD	USA	
SLS_DLR_CD	171072	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B3	
VRT_CD	906	
TIS_FLAG		
VIN_CD	1FMRU16W31L	
LBR_COST		
VEH_LINE_CD	T83	
MKT_DERIVED		
BOD_CAB_STL	TWD	
VER_SERIES_C	T/F	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	232
MDL_YR	2001
SORT_INDEX	875
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	11/18/2001
NAME	SKYLINE FORD SALES, INC.
DOC_NUM	112755A
PH_NUM	3274500
WCC_CD	BRCZ
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	940
COND_CD	2
RPR_DT	11/15/2001
TIS_WSD	1
CLM_KEY	6151213
MILGE	688
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	543
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1

TECH_TXT2

CUST_TXT 940**DRIVERSIDE DEAT BELT LATCH WILL NOT STAY LATCHED

AREA_CD 214

COUNTRY_CD USA

SLS_DLR_CD 152003

TXN_CD 1

CNTRY_SOLD USA

QRT_CD Q21

VFG_CD V05

AWS_VL_CD B3

VRT_CD S08

TIS_FLAG

VIN_CD 1FMRUJ15W31L

LRR_COST

VRH_LINE_CD T/B3

MKT_DERIVED *

BOD_CAB_STL TMD

VER_SERIES_C TEF

DRIVE_CD T/B

ENG_CD T/WN

ID	233
MDL_YR	2001
SORT_INDEX	578
TRANS_CD	TRUJ
PLANT_CD	AP
PRODN_DT	4/23/2001
WRYY_START_D	8/30/2001
NAME	GREENE FORD COMPANY
DOC_NUM	173246A
PH_NUM	5325620
WCC_CD	9R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	41
RPR_DT	4/8/2002
TIS_WSD	8
CLM_KEY	785216
MILGE	14120
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	290
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	DIAG AND RR SEATBELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT WILL NOT LATCH SOP HERE
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121405
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/MN

ID	234
MDL_YR	2001
SORT_INDEX	877
TRANS_CD	T03U
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	5/2/2001
NAME	WATSON QUALITY FORD
DOC_NUM	158044A
PH_NUM	0667000
WCC_CD	8RU2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	823
COND_CD	42
RPR_DT	0/27/2001
TIS_WSD	5
CLM_KEY	3983057
MILGE	6841
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5885
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MS
Field27	b
CPSC_CD_6	11001

TECH_TXT1	6841 REPLACE DR FT SEAT BELT
TECH_TXT2	
CUST_TXT	825 DRIVERS SIDE SEAT BELT WONT STAY LATCHED
AREA_CD	601
COUNTRY_CD	USA
SLS_DLR_CD	125306
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRJ16W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	235
MDL_YR	2001
SORT_INDEX	678
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	6/23/2001
NAME	JOE MYERS FORD, INC.
DOC_NUM	388059A
PH_NUM	8868200
WCC_CD	BRC2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881200
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	11/23/2001
TIS_WSD	6
CLM_KEY	6304806
MILGE	8330
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4402
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 468 of 748

RQ04-011 E 0812

TECH_TXT1	REPLACED DRIVERS SIDE BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WONT LATCH
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	162169
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B06
TIS_FLAG	
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	236
MDL_YR	2001
SORT_INDEX	879
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/31/2001
WRTY_START_D	10/10/2001
NAME	REDLANDS FORD
DOC_NUM	7886782
PH_NUM	7933211
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	526
COND_CD	42
RPR_DT	1/28/2002
TIS_WSD	4
CLM_KEY	8708408
MILGE	7148
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1885
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	UNHOOKS WHILE DRIVING DRIVERS SEAT BELT BUCKLE	WTIME REPLACED
TECH_TXT2		
CUST_TXT	CHECK DRIVER SIDE SEAT BELT BUCKLE UNHOOKS WHILE DRIVING	
AREA_CD		808
COUNTRY_CD	USA	
SLS_DLR_CD		171158
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG		
VIN_CD	1FMRU15W31L [REDACTED]	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T783	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/M	

ID	237
MDL_YR	2001
SORT_INDEX	881
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	6/12/2001
NAME	REDLANDS FORD
DOC_NUM	7461661
PH_NUM	7833211
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	821
COND_CD	42
RPR_DT	10/8/2001
TIS_WSD	6
CLM_KEY	4300403
MILGE	8985
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1095
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	FOR CUSTOMER SATISFACTION M TIME NO LABOR OPF IN MANUAL TO R & R DRIVERS SIDE SEAT BELT BUCK
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SEAT BELT WILL NOT STAY LATCHED INTERMITTENT
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	171153
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	238
MDL_YR	2001
SORT_INDEX	682
TRANS_CD	T000
PLANT_CD	AP
PRODN_DT	3/13/2001
WRTY_START_D	4/13/2001
NAME	ERNE HARE FORD, INC.
DOC_NUM	6788452
PH_NUM	9338571
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	825
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	0
CLM_KEY	9088895
MILGE	18889
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4888
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	0
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 475 of 748

RQ04-011 E 0918

TECH_TXT1	TRACK ASSEMBLY FRONT SEAT REPLACE
TECH_TXT2	
CUST_TXT	G S DRIVERS FRONT SEAT BELT UNBUCKLES WHEN STOPPING
AREA_CD	813
COUNTRY_CD	USA
SLS_DLR_CD	124208
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B9
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	T/EP
DRIVE_CD	T/B
ENG_CD	T/VN

ID	238
MDL_YR	2001
SORT_INDEX	883
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	3/31/2001
NAME	PLANET FORD
DOC_NUM	16501901
PH_NUM	7193700
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONG_C	S25
COND_CD	42
RPR_DT	10/23/2001
TIS_WSD	7
CLM_KEY	5031205
MILGE	16008
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2091
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	VERIFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY , OK AT THIS TIME
TECH_TXT2	
CUST_TXT	ADD DRIVER SIDE SEAT BELT WILL NOT STAYED BUCKLE
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152032
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	BS
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAR_STL	TWO
VER_SERIES_C	T1EF
DRIVE_CD	T8
ENG_CD	TMN

ID	240
MDL_YR	2001
SORT_INDEX	004
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	5/25/2001
NAME	PUENTE HILLS FORD
DOC_NUM	5328161
PH_NUM	9643573
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	626
COND_CD	1
RPR_DT	4/9/2002
TIS_WSD	11
CLM_KEY	7898621
MILGE	11952
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5560
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	0
CPSC_CD_6	11031

TECH_TXT1	SEAT BELT BROKE FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	LEFT SEAT BELT WILL NOT LATCH	
AREA_CD	626	
COUNTRY_CD	USA	
SLS_DLR_CD	171072	
TXN_CD	2	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S06	
TIS_FLAG		
VIN_CD	1FMRU15W31L	
LBR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	T/WD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	241
MDL_YR	2001
SORT_INDEX	686
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	3/26/2001
NAME	ADAMSON FORD, L.L.C.
DOC_NUM	072815A
PH_NUM	3242553
WCC_CD	6R02
PART_NUM_CA	F85Z
PART_NUM_CA	7581203
PART_NUM_CA	B8E
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/12/2001
TIS_WSD	4
CLM_KEY	2382623
MILGE	3052
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	417
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
Field27	
CPSC_CD_6	12001

TECH_TXT1	3052 FOUND DRVS SEAT BELT BUCKLE NOT LATCHING REMOVED AND REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	C S DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT
AREA_CD	205
COUNTRY_CD	USA
SLS_DLR_CD	121011
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W31L
LRR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	T7WD
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	T7N

ID	242
MDL_YR	2001
SORT_INDEX	690
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	8/18/2000
WRTY_START_D	9/18/2000
NAME	FIVE STAR FORD
DOC_NUM	147889A
PH_NUM	4968838
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	8AB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/8/2002
TIS_WSD	18
CLM_KEY	6783873
MILGE	31170
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2486
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	
CPSC_CD_6	11001

TECH_TXT1	31170 BUCKEL R,I LT FT SEAT TO REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	INSP. L F SEAT BELT WILL NOT BUCKLE AT TIMES AND IS HARD TO BUCKLE AT OTHER TIMES
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152020
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W31
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VKR_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	243
MDL_YR	2001
SORT_INDEX	893
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/29/2001
WRTY_START_D	6/27/2001
NAME	KOONS STERLING FORD
DOC_NUM	1528261
PH_NUM	4307700
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	B40
COND_CD	42
RPR_DT	1/16/2002
TIS_WSD	7
CLM_KEY	8368273
MILGE	11028
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	31
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INSPECT 7 TEST SEAT BELT BUCKLE & VERIFIED NOT WORKING PROPERLY,R&R SEAT ASSB TO GAIN ACCESS,REPLACE DRIVERS SEAT BELT BUCKLE ASSB.
TECH_TXT2	
CUST_TXT	DRIVERS SIDE FRONT SEAT BELT KEEPS COMING LOOSE...INSTALL SOP
AREA_CD	703
COUNTRY_CD	USA
SLS_DLR_CD	127044
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15A211
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
YER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	244
MDL_YR	2001
SORT_INDEX	894
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	8/27/2001
NAME	KOONS STERLING FORD
DOC_NUM	1797381
PH_NUM	4307700
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	826
COND_CD	42
RPR_DT	2/28/2002
TIS_WSD	9
CLM_KEY	7167793
MILGE	13920
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	31
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INSPECT & TEST DROVE & VERIFIED SEAT BELT LIGHT COMES ON, LAST VISIT NGS TESTING, NO CODES. NGS PIDS MONITOR WHILE MOVING SEAT BELT AROUND THE CONNECTION CHANGES. PINPOINT TESTING. R&R SEAT ASSB. TO GAIN
TECH_TXT2	ACCESS. REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSB. TEST DROVE AFTER REPAIRS.
CUST_TXT	DRIVER SEAT BELT HAS COME LOOSE SEAT BELT LIGHT ON INSTALL SOP SEATBELT
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	127044
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU16W21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7F
DRIVE_CD	T8
ENG_CD	T7N

ID	245
MDL_YR	2001
SORT_INDEX	685
TRANS_CD	T/DLI
PLANT_CD	AP
PRODN_DT	5/9/2001
WRTY_START_D	5/31/2001
NAME	ALL STAR FORD
DOC_NUM	096264A
PH_NUM	6547811
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	625
COND_CD	42
RPR_DT	2/19/2002
TIS_WSD	8
CLM_KEY	6060030
MILGE	13057
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2763
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	b
CPSC_CD_5	11001

TECH_TXT1	13057 REPLACED DRIVER SIDE SEAT BELT BUCKLE ORDERED DRIVER SEAT BELT LATCH ASSY
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT LATCH WILL NOT HOLD AT TIMES(REFER TO RO #85200)
AREA_CD	226
COUNTRY_CD	USA
SLS_DLR_CD	123148
TXN_CD	E94
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W21L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	246
MDL_YR	2001
SORT_INDEX	699
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	8/23/2001
NAME	MELROSE FORD
DOC_NUM	7150001
PH_NUM	5346520
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7891203
PART_NUM_CA	BAC
CUST_CONC_C	825
COND_CD	42
RPR_DT	1/25/2002
TIS_WSD	0
CLM_KEY	8962087
MILGE	6823
MTEL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7762
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	FOUND SEAT BELT BUCKLE DEFECTIVE REPLACED THE DRIVERS SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	D B FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	610
COUNTRY_CD	USA
SLS_DLR_CD	172008
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU18W21U
LRR_COST	
VEH_LINE_CD	T/ES
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	247
MDL_YR	2001
SORT_INDEX	697
TRANS_CD	T/DLI
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/16/2001
NAME	HARRELSON FORD, INC.
DOC_NUM	5090852
PH_NUM	5622780
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	826
COND_CD	42
RPR_DT	2/4/2002
TIS_WSD	8
CLM_KEY	8781174
MILGE	5877
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1071
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Field27	#
CPSC_CD_6	11001

TECH_TXT1	BUCKLE MALFUNCTION FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	C S LEFT FRONT SEAT BELT BUCKLE WONT LATCH	
AREA_CD	704	
COUNTRY_CD	USA	
SLS_DLR_CD	121213	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG		
VIN_CD	1FMRU16W21L	
LBR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	TEF	
DRIVE_CD	T/B	
ENG_CD	T/WN	

ID	248
MDL_YR	2001
SORT_INDEX	699
TRANS_CD	T3U
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	6/30/2001
NAME	FORD OF MONTEBELLO
DOC_NUM	78151502
PH_NUM	8388920
WCC_CD	BR02
PART_NUM_CA	F6SZ
PART_NUM_CA	7861203
PART_NUM_CA	68E
CUST_CONC_C	840
COND_CD	41
RPR_DT	7/14/2001
TIS_WSD	1
CLM_KEY	2364580
MILGE	510
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3250
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field17	*
CPSC_CD_6	12001

TECH_TXT1	VERIFIED CONCERN, REPLACED BAD SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CK REASON WHY DRIVERS SEAT BELT BUCKLE WONT LOCK BELT AT TIMES. INSTALL S.O.P.
AREA_CD	323
COUNTRY_CD	USA
SLS_DLR_CD	171007
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W21L
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T1B
ENG_CD	T1V1

ID	249
MDL_YR	2001
SORT_INDEX	700
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/28/2001
WRTY_START_D	6/24/2001
NAME	ERNE HARE FORD, INC.
DOC_NUM	7602352
PH_NUM	9336571
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/21/2002
TIS_WSD	10
CLM_KEY	7677138
MILGE	14357
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4989
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	G
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 497 of 749

RQ04-011 E 0940

TECH_TXT1	RENEW DRIVER SEAT BELT ASSY
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT COMES LINHOOKED
AREA_CD	813
COUNTRY_CD	USA
SLS_DLR_CD	124446
TXN_CD	E54
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S09
TIS_FLAG	
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	250
MDL_YR	2001
SORT_INDEX	702
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/11/2001
NAME	GILLESPIE FORD
DOC_NUM	7583151
PH_NUM	5081000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/1/2001
TIS_WSD	3
CLM_KEY	2751250
MILGE	2346
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4546
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEATBELT BUCKLE INOP FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	SEAT BELT DRIVERS SIDE COMES LOOSE WHILE DRIVING SOP PART HERE	
AREA_CD	210	
COUNTRY_CD	USA	
SLS_DLR_CD	152057	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	B08	
TIS_FLAG		
VIN_CD	1FMRU1BW21 [REDACTED]	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T83	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	TEF	
DRIVE_CD	T8	
ENG_CD	TAM	

ID	251
MDL_YR	2001
SORT_INDEX	703
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	7/26/2001
NAME	FULLER FORD
DOC_NUM	177581B
PH_NUM	0062500
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/18/2001
TIS_WSD	2
CLM_KEY	3705289
MILGE	2417
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	5578
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSTALLED LH SEAT BELT BUCKLE. NEEDED TO REMOVE FRONT SEAT TO INSTALL NEW PART AND PUT ALL BACK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT THE DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT. REFER TO LINE A
AREA_CD	819
COUNTRY_CD	USA
SLS_DLR_CD	171078
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	Ba
VRT_CD	S08
TIS_FLAG	
VIN_CD	?FMRU16W21L
LBR_COST	
VEH_LINK_CD	T83
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_C	T/F
DRIVE_CD	TB
ENG_CD	T/VN

ID	252
MDL_YR	2001
SORT_INDEX	704
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/9/2001
NAME	HJB CITY FORD, INC.
DOC_NUM	6878951
PH_NUM	2334500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7901203
PART_NUM_CA	BAA
CUST_CONC_C	S07
COND_CD	42
RPR_DT	11/13/2001
TIS_WSD	7
CLM_KEY	5228985
MILGE	7312
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0481
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	01S21 RECALL PERFORMED	01S21 RECALL PERFORMED
TECH_TXT2		
CUST_TXT	CK THE DRIVER SIDE SEAT BELT LATCHES THEN WHEN DRIVING COMES LOOSE OR PULLS OUT OF LATCH	
AREA_CD	397	
COUNTRY_CD	USA	
SLS_DLR_CD	123271	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VPG_CD	V03	
AWS_VL_CD	B3	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMRU15WZ1L [REDACTED]	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	T/WD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/WN	

ID	259
MDL_YR	2001
SORT_INDEX	706
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/14/2001
WRTY_START_D	8/14/2001
NAME	FORD COUNTRY
DOC_NUM	1511752
PH_NUM	5653873
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/3/2002
TIS_WSD	7
CLM_KEY	8506420
MILGE	12300
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1440
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NV
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEATBELT FAILED FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	CK DR SEATBELT POPS OUT WHILE DRIVING	
AREA_CD	702	
COUNTRY_CD	USA	
SLS_DLR_CD	171158	
TXN_CD	E84	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	806	
TIS_FLAG		
VIN_CD	1FMRU15W21L [REDACTED]	
LBB_COST	[REDACTED]	
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	T/WD	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	254
MDL_YR	2001
SORT_INDEX	706
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	6/13/2001
NAME	TREADWELL FORD
DOC_NUM	27853001
PH_NUM	4783351
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/16/2001
TIS_WSD	E
CLM_KEY	4490530
MILGE	18924
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6629
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AL
Field27	C
CPSC_CD_6	11001

TECH_TXT1	DRIVERS SEAT BELT WILL POP LOOSE REPLACE DRIVERS SEAT BELT WAITING.....
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL POP LOOSE WHEN DRIVING, REBUCKLE AND WILL POP LOOSE AGAIN
AREA_CD	251
COUNTRY_CD	USA
SLS_DLR_CD	124017
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMFU15W21L
LBR_COST	
VEH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	255
MDL_YR	2001
SORT_INDEX	708
TRANS_CD	T/DL
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	5/22/2001
NAME	CASA FORD, INC.
DOC_NUM	248510C
PH_NUM	7782272
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	540
COND_CD	33
RPR_DT	9/8/2001
TIS_WSD	4
CLM_KEY	3588212
MILGE	3258
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20455
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	3259 42 DOES NOT OPERATE PROPERLY REPLACED L FRONT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER SHOULDER HARNESS POPS LOOSE AT TIMES WHILE DRIVING
AREA_CD	815
COUNTRY_CD	USA
SLS_DLR_CD	152210
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU18W21L
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	T1WD
VER_SERIES_C	T1EF
DRIVE_CD	T1B
ENG_CD	T1VN

ID	298
MDL_YR	2001
SORT_INDEX	708
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/31/2001
WRTY_START_D	4/17/2001
NAME	CASA FORD, INC.
DOC_NUM	257848C
PH_NUM	7782272
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAS
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/20/2001
TIS_WSD	8
CLM_KEY	5852810
MILGE	12242
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20455
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 511 of 740

RQ04-011 E 0854