

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 3 OF 6

BOOK 2 OF 43

TECH_TXT1	12242 VERIFIED SEATBELT BUCKLE RELEASES REMOVED AND REPLACED WITH NEW ONE RETESTED NEW ONE WORKS OK
TECH_TXT2	
CUST_TXT	G 8 DRIVERS SEATBELT BUCKLE RELEASES
AREA_CD	915
COUNTRY_CD	USA
SLS_DLR_CD	152210
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15W21LB26603
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	257
MDL_YR	2001
SORT_INDEX	710
TRANS_CD	TJOU
PLANT_CD	AP
PRODN_DT	4/1/2001
WRTY_START_D	4/21/2001
NAME	COVERT FORD OF TAYLOR, INC.
DOC_NUM	680401
PH_NUM	3868000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	4/2/2002
TIS_WSD	12
CLM_KEY	7862076
MILGE	18107
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3042
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	G
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	S28 THE DRIVERS SEAT BELT BUBKLE COMES UNLATCHED.
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	132740
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	@
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T1B
ENG_CD	T1N

ID	258
MDL_YR	2001
SORT_INDEX	712
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/15/2001
WRTY_START_D	7/30/2001
NAME	LA PLACE FORD, INC.
DOC_NUM	2225001
PH_NUM	8528000
WCC_CD	8R02
PART_NUM_CA	1172
PART_NUM_CA	7681208
PART_NUM_CA	BAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	8
CLM_KEY	7190673
MILGE	5884
MTBL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4127
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT BUCKLE DEFECTIVE REPLACE DRIVER SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT N DR SIDE COMES APART WHILE DRIVING WILL NOT STAY LATCHED
AREA_CD	985
COUNTRY_CD	USA
SLS_DLR_CD	123050
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	TAB3
MKT_DERIVED	*
BOD_CAB_STL	TW03
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TAVN

ID	258
MDL_YR	2001
SORT_INDEX	714
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	8/8/2001
NAME	VALLEY PARK FORD
DOC_NUM	307719B
PH_NUM	7780076
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	1
RPR_DT	10/11/2001
TIS_WSD	2
CLM_KEY	4388647
MILGE	1292
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5588
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	
TECH_TXT2	
CUST_TXT	LEFT SEAT BELT DOES NOT KEEP BELT IN PLACE
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171088
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU16W21U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	280
MDL_YR	2001
SORT_INDEX	718
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	2/13/2001
WRTY_START_D	3/13/2001
NAME	BANKSTON L-M, INC.
DOC_NUM	2992201
PH_NUM	2331441
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	41
RPR_DT	11/8/2001
TIS_WSD	8
CLM_KEY	4083288
MILGE	6278
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	13589
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	CONFIRM SEATBELTS UNBUCKLE. REPLACE BOTH FRONT SEAT BELT FEMALE ENDS. CONFIRM REPAIR. 41 81202
TECH_TXT2	
CUST_TXT	CUST STATES THE FRONT SEATBELTS ARE UNBUCKLING. WE PERFORMED RECALL TEST 8 28 01 RQ# 25824 AND PASSED
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	152012
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL16W21 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T8
ENG_CD	TAM

ID	281
MDL_YR	2001
SORT_INDEX	721
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	2/24/2001
NAME	TOWN EAST FORD
DOC_NUM	770755A
PH_NUM	2700441
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7601203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	33
RPR_DT	8/29/2001
TIS_WSD	8
CLM_KEY	4045133
MILGE	3150
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6192
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	6
CPSC_CD_6	11001

TECH_TXT1	3158 42 REPLACED DRIVER SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES LOOSE, UNBUCKLES AT TIMES, S.O.P. AT PARTS
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B8
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/MN

ID	282
MDL_YR	2001
SORT_INDEX	722
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	2/18/2001
NAME	FRIENDLY FORD
DOC_NUM	24008301
PH_NUM	2856000
WCC_CD	BF02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	AAH
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/5/2001
TIS_WSD	6
CLM_KEY	2842808
MILGE	9197
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3821
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	1 REPLACED SOP DRIVERS SEAT BELT BUCKLE ASSEMBLY
TECH_TXT2	
CUST_TXT	CLIENT STATES DRIVERS SEAT BELT WONT LATCH SOP HERE TO REPAIR.
AREA_CD	408
COUNTRY_CD	USA
SLS_DLR_CD	172038
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TW0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	283
MDL_YR	2001
SORT_INDEX	728
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/27/2000
WRTY_START_D	5/3/2001
NAME	WATSON QUALITY FORD
DOC_NUM	180431A
PH_NUM	8567000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S26
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	8
CLM_KEY	5959687
MILGE	18612
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5996
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MS
Field27	*
CPSC_CD_6	11001

TECH_TXT1	16612 R&I BAD DRIVERS FT SEAT BELT 42 7881203
TECH_TXT2	
CUST_TXT	525 DRIVERS SEAT BELT WONT LATCH, PART IN
AREA_CD	601
COUNTRY_CD	USA
SLS_DLR_CD	128308
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPJ15W21L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	284
MDL_YR	2001
SORT_INDEX	727
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	8/20/2000
WRTY_START_D	2/22/2001
NAME	MAROONE FORD
DOC_NUM	518450C
PH_NUM	8727200
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	11
CLM_KEY	6018011
MILGE	12220
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4820
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	8
CPSC_CD_6	11001

TECH_TXT1	12220 W TECH 898, VERIFIED CONCERN, R 1 DR SEAT TO GAIN ACCESS, RR BAD DR SIDE SEAT BELT BUCKLE, RETEST, A LL OPER OK AT THIS TIME
TECH_TXT2	
CUST_TXT	840 CHECK CUST CONCERN FOR DRIVER SIDE SEAT BELT BUCKLE WILL NOT LATCH.
AREA_CD	954
COUNTRY_CD	USA
SLS_DLR_CD	124016
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	285
MDL_YR	2001
SORT_INDEX	728
TRANS_CD	TIDU
PLANT_CD	AP
PRODN_DT	8/20/2000
WRTY_START_D	2/22/2001
NAME	MARCOONE FORD
DOC_NUM	527284A
PH_NUM	8727200
WCC_CD	5R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	8/12/2002
TIS_WSD	13
CLM_KEY	7385177
MILGE	14881
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4820
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	a
CPSC_CD_6	11001

TECH_TXT1	14891 W 302 VERIFIED CONCERN.REPLACE DRIVER SEATBELT RECIEVER DUE TO INOP.RETEST,OK AT THIS TIME. QUALITY INSPECTED BY 302. 14891.
TECH_TXT2	
CUST_TXT	840 DRIVERS SEAT BELT WONT LATCH, ALL TIMES, CUST STATES.
AREA_CD	854
COUNTRY_CD	USA
SLS_DLR_CD	124015
TXN_CD	E90
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15W21L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T7WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/M

ID	296
MDL_YR	2001
SORT_INDEX	730
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/30/2001
WRTY_START_D	6/23/2001
NAME	KEN GRODY FORD - CARLSBAD
DOC_NUM	4454861
PH_NUM	4386171
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7861203
PART_NUM_CA	AAF
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/25/2001
TIS_WSD	0
CLM_KEY	2874218
MILGE	21
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5512
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACE BOTH FRONT SEAT BELTS.
TECH_TXT2	
CUST_TXT	BOTH FRONT SEAT BELTS WONT LATCH
AREA_CD	780
COUNTRY_CD	USA
SLS_DLR_CD	171102
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRL16W11L
LBR_COST	
VEH_LINE_CD	T/B3
MRT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	267
MDL_YR	2001
SORT_INDEX	736
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	7/14/2001
NAME	MARNE MYERS FORD LINCOLN MERC
DOC_NUM	3118502
PH_NUM	5281804
WCC_CD	BR02
PART_NUM_CA	1L72
PART_NUM_CA	7851203
PART_NUM_CA	BAB
CUST_CONC_C	826
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	8
CLM_KEY	0841084
MILGE	13380
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2818
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KY
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 533 of 748

RQ04-011 E 0978

TECH_TXT1	CK & RPL DRIVERS SEAT BELT, DOES NOT WORK, RECK OK
TECH_TXT2	
CUST_TXT	S25 DRIVERS SEAT BELT COMES OPEN WHEN DRIVING AT TIMES
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	171104
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU1BW11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	268
MDL_YR	2001
SORT_INDEX	740
TRANS_CD	T0U
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	9/10/2001
NAME	MAXWELL FORD
DOC_NUM	584434C
PH_NUM	4435000
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	EAB
CUST_CONC_C	525
COND_CD	1
RPR_DT	12/19/2001
TIS_WSD	4
CLM_KEY	5883170
MILGE	3306
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	SEATBELT BUCKLE CAME APART
TECH_TXT2	
CUST_TXT	C S DRIVERS SEAT BELT POPS LOSE WHILE DRIVING
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	162303
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMRU15W11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	288
MDL_YR	2001
SORT_INDEX	747
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	6/23/2001
NAME	CHARLIE THOMAS FORD INC
DOC_NUM	1225785
PH_NUM	3714000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	526
COND_CD	33
RPR_DT	3/23/2002
TIS_WSD	11
CLM_KEY	5352407
MILGE	18816
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4473
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVER SIDE BUCKLE
TECH_TXT2	
CUST_TXT	CHECK DRIVER FRONT SEAT BUCKLE COMES LOOSE WHILE DRIVING
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	152024
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU15W11
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TND
VER_SERIES_C	TEF
DRIVE_CD	T8
ENG_CD	TVM

ID	270
MDL_YR	2001
SORT_INDEX	760
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	2/5/2001
WRTY_START_D	3/8/2001
NAME	BIG VALLEY FORD
DOC_NUM	42648801
PH_NUM	0704400
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S26
COND_CD	42
RPR_DT	2/1/2002
TIS_WSD	12
CLM_KEY	0682770
MILGE	27283
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	7742
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CHECKED OUT, CONFIRMED INTERMITTANT CONCERN. REPLACE DRIVERS SEATBELT ASSY. RETESTS OK
TECH_TXT2	
CUST_TXT	CUSTOMER REPORTS DRIVERS SEATBELT WILL NOT HOLD AT TIMES
AREA_CD	209
COUNTRY_CD	USA
SLS_DLR_CD	172402
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU19W11L
LBR_COST	
VEH_LINE_CD	T89
MKT_DERIVED	*
BOD_CAB_STL	TMD
VER_SERIES_C	TEF
DRIVE_CD	T8
ENG_CD	TVM

ID	271
MDL_YR	2001
SORT_INDEX	752
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	4/28/2001
NAME	LEE JARMON FORD, INC.
DOC_NUM	315233A
PH_NUM	2428416
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	T60
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	8
CLM_KEY	8013834
MILGE	10112
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2458
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	10112 42 81384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CK DRIVERS SEAT BELT WONT STAY ATTACHED
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	162014
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W11U
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	272
MDL_YR	2001
SORT_INDEX	757
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/22/2000
WRTY_START_D	11/1/2000
NAME	KEN GRODY FORD - CARLEBAD
DOC_NUM	6320851
PH_NUM	4389171
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	AAH
CUST_CONC_C	828
COND_CD	1
RPR_DT	4/23/2002
TLS_WSD	18
CLM_KEY	8198416
MILGE	21778
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8812
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	LEFT SEATBELT BUCKLE BROKEN SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT LATCH
AREA_CD	790
COUNTRY_CD	USA
SLS_DLR_CD	171102
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B05
TIS_FLAG	
VIN_CD	1FMRJ15W11 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TMD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	T/MN

ID	273
MDL_YR	2001
SORT_INDEX	756
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/21/2000
WRTY_START_D	5/18/2001
NAME	TEAM FORD OF MARIETTA
DOC_NUM	8487883
PH_NUM	4221100
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/30/2001
TIS_WSD	7
CLM_KEY	6465878
MILGE	18521
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	243
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REMOVE SEAT ASSY. AND REPLACE SEATBELT ASSY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE DRIVERS SEAT BELT CAME UNLATCHED
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121003
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W11
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	TVN

ID	274
MDL_YR	2001
SORT_INDEX	753
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/9/2001
WRTY_START_D	5/30/2001
NAME	SKYLINE FORD SALES, INC.
DOC_NUM	112588B
PH_NUM	3274500
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	540
COND_CD	1
RPR_DT	11/13/2001
TIS_WSD	0
CLM_KEY	5082857
MILGE	0700
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	543
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	6
CPSC_CD_6	11001

TECH_TXT1

TECH_TXT2

CUST_TXT 840 PASS SIDE MIDDLE SEAT BELT LATCH COMING APART

AREA_CD 214

COUNTRY_CD USA

SLS_DLR_CD 152003

TXN_CD 1

CNTRY_SOLD USA

QRT_CD Q21

VFG_CD V05

AWS_VL_CD B5

VRT_CD B08

TIS_FLAG

VIN_CD 1FMRU15W01

LBR_COST

VEH_LINE_CD TBS

MKT_DERIVED

BOD_CAB_STL TWD

VER_SERIES_C TEF

DRIVE_CD TBS

ENG_CD TMM

ID	275
MDL_YR	2001
SORT_INDEX	757
TRANS_CD	TIDU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	7/30/2001
NAME	GWINNETT PLACE FORD
DOC_NUM	8183881
PH_NUM	4762080
WCC_CD	0R02
PART_NUM_CA	1LTZ
PART_NUM_CA	7061203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	1
RPR_DT	8/20/2001
TIS_WSD	1
CLM_KEY	3322499
MILGE	415
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3573
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field17	G
CPSC_CD_6	11001

TECH_TXT1	BROKEN REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	CUST STATES DRIVER SEAT BELT SNAPS LOOSE BY ITSELF POPS OUT BY ITSELF	
AREA_CD		770
COUNTRY_CD	USA	
SLS_DLR_CD		121025
TXN_CD	2	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V06	
AWS_VL_CD	B3	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMRL16W01U [REDACTED]	
LRR_COST	[REDACTED]	
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	T/BF	
DRIVE_CD	T/B	
ENG_CD	T/VN	

ID	278
MDL_YR	2001
SORT_INDEX	768
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	6/4/2001
NAME	JOHN BLEAKLEY FORD INC
DOC_NUM	6795551
PH_NUM	9419000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAA
CUST_CONC_C	B40
COND_CD	42
RPR_DT	11/7/2001
TIS_WSD	6
CLM_KEY	5082705
MILGE	8397
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	487
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	INOP REPLACE	SEATBELT ASSEMBLY FRONT
TECH_TXT2		
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT KEEP COMING UNBUCKLED	
AREA_CD		770
COUNTRY_CD	USA	
SLS_DLR_CD		121060
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	B09	
TIS_FLAG		
VIN_CD	1FMRU15W01L	
LBR_COST		
VEH_LINE_CD	T83	
MKT_DERIVED	*	
BOD_CAB_STL	TWD	
VER_SERIES_C	TEF	
DRIVE_CD	T/B	
ENG_CD	T/M	

ID	277
MDL_YR	2001
SORT_INDEX	771
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	6/30/2001
NAME	PASADENA FORD, INC.
DOC_NUM	3338863
PH_NUM	8833873
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/12/2001
TIS_WSD	0
CLM_KEY	5830000
MILGE	8428
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4223
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED BUCKLE DUE TO NOT WORKING PROPERLY
TECH_TXT2	
CUST_TXT	OK DRIVER SEAT BELT BUCKET NOT HOLDING
AREA_CD	626
COUNTRY_CD	USA
SLS_DLR_CD	171037
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ16W01
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	278
MDL_YR	2001
SORT_INDEX	775
TRANS_CD	T/III
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	5/31/2001
NAME	COVERT FORD, INC.
DOC_NUM	3015802
PH_NUM	3454343
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	8AA
CUST_CONC_C	625
COND_CD	7
RPR_DT	2/18/2002
TIS_WSD	0
CLM_KEY	8888515
MILGE	15816
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4437
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	DEFECTIVE REPLACED LF SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	825 L F SEAT BELT COMES UNFASTENED
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	162302
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16W01L
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TAWD
VER_SERIES_C	TAEF
DRIVE_CD	T7B
ENG_CD	TAVN

ID	278
MDL_YR	2001
SORT_INDEX	776
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	5/9/2001
NAME	ALBANY FORD, INC.
DOC_NUM	5994551
PH_NUM	8839100
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	8AB
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/9/2001
TIS_WSD	5
CLM_KEY	4143888
MILGE	5716
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9832
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED
AREA_CD	229
COUNTRY_CD	USA
SLS_DLR_CD	121408
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15W01
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T7F
DRIVE_CD	T7B
ENG_CD	T7N

ID	280
MDL_YR	2001
SORT_INDEX	778
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/3/2001
WRTY_START_D	8/31/2001
NAME	NORTHSIDE FORD
DOC_NUM	33683301
PH_NUM	6258800
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	11
CLM_KEY	8844088
MILGE	14841
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4410
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD
TECH_TXT2	
CUST_TXT	340 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	152063
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	800
TIS_FLAG	
VIN_CD	1FMRL15W01L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/MO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	281
MDL_YR	2001
SORT_INDEX	782
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	3/4/2001
NAME	PUENTE HILLS FORD
DOC_NUM	3122981
PH_NUM	9843673
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7081203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	1
RPR_DT	8/28/2001
TIS_WSD	6
CLM_KEY	3383213
MILGE	8462
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5550
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 561 of 748

RQ04-011 E 1004

TECH_TXT1	ACCESS BOTH SEATS, REPL BUCKLES TRACK ASSEMBLY FRONT SEAT REPLACE
TECH_TXT2	
CUST_TXT	DIAG DRIVER AND PASS SEAT BELTS UNLOCK WHILE DRIVING DOWN THE FREEWAY
AREA_CD	026
COUNTRY_CD	USA
SLS_DLR_CD	171072
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	282
MDL_YR	2001
SORT_INDEX	787
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/27/2000
WRTY_START_D	3/7/2001
NAME	BOB PAGAN FORD, INC.
DOC_NUM	119288C
PH_NUM	7440451
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S28
COND_CD	1
RPR_DT	3/29/2002
TIS_WSD	13
CLM_KEY	7737439
MILGE	10389
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4458
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	■
CPSC_CD_6	11001

TECH_TXT1	FOUND SEAT BELT RECIVER NOT HOLDING REPLACED AND RECHECKED OPERATION
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEATBELT RECIVER DOES NOT HOLD
AREA_CD	408
COUNTRY_CD	USA
SLS_DLR_CD	182763
TXN_CD	ED4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRL115W011
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN

ID	263
MDL_YR	2001
SORT_INDEX	788
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/29/2001
NAME	HASTINGS FORD, INC.
DOC_NUM	058804B
PH_NUM	7680114
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7661203
PART_NUM_CA	8AB
CUST_CONC_C	803
COND_CD	42
RPR_DT	1/3/2002
YES_WSD	5
CLM_KEY	6691908
MILGE	7841
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6744
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED FRONT SEAT BUCKLE
TECH_TXT2	
CUST_TXT	LH FRT SEAT BELT BUCKLE IS NOT HOLDING ALL THE TIME
AREA_CD	252
COUNTRY_CD	USA
SLS_DLR_CD	121541
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU19LX11
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TN2

ID	254
MDL_YR	2001
SORT_INDEX	790
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	11/19/2001
NAME	JAMES HODGE FORD LINCOLN-MERCU
DOC_NUM	271387A
PH_NUM	6821345
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/2/2002
TIS_WSD	2
CLM_KEY	0305771
MILGE	2828
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2490
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
Field37	G
CPSC_CD_6	11001

TECH_TXT1	R AND R DRIVER SEAT, REPLACE SEAT BELT WITH NEW. RAND R PASSENGER SEAT, REPLACE SEATBELT.
TECH_TXT2	
CUST_TXT	CK BOTH FRONT SEAT BELT BUCKLES COMING UNLATCH
AREA_CD	918
COUNTRY_CD	USA
SLS_DLR_CD	162535
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15LX1
LBR_COST	
VEH_LINE_CD	T7E3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	T7VZ

ID	285
MDL_YR	2001
SORT_INDEX	781
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	11/30/2001
NAME	MCREE FORD, INC.
DOC_NUM	428000A
PH_NUM	3371528
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	33
RPR_DT	12/4/2001
TIS_WSD	1
CLM_KEY	5838388
MILGE	148
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4443
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	R&R SEAT CAPTAINS CHAIR TO REPLACE SEAT BELT ASSEMBLY, LOOSE.
TECH_TXT2	
CUST_TXT	THE DRIVERS SEAT BELT RELEASES WHILE DRIVING
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152052
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VKT_CD	806
TIS_FLAG	
VIN_CD	1FMRU15LX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	298
MDL_YR	2001
SORT_INDEX	797
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	3/20/2001
NAME	PACIFIC FORD
DOC_NUM	1810251
PH_NUM	8275130
WCC_CD	6R02
PART_NUM_CA	1LTZ
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S28
COND_CD	42
RPR_DT	1/20/2002
TIS_WSD	11
CLM_KEY	8608792
MILGE	8237
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5412
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	X	REMOVE REPLACE BELT BUCKLE
TECH_TXT2		
CUST_TXT		CUSTOMER STATES THAT LEFT FRONT SEAT BELT KEEPS COMING UNLATCHED WHILE DRIVING
AREA_CD		714
COUNTRY_CD		USA
SLS_DLR_CD		171062
TXN_CD		1
CNTRY_SOLD		USA
QRT_CD		Q21
VFG_CD		V05
AWS_VL_CD		B3
VRT_CD		808
TIS_FLAG		
VIN_CD		1FMRU15LX1L [REDACTED]
LBR_COST		[REDACTED]
VEH_LINE_CD		T/83
MKT_DERIVED		*
BOD_CAB_STL		T/ND
VER_SERIES_C		T/EF
DRIVE_CD		T/8
ENG_CD		T/NZ

ID	257
MDL_YR	2001
SORT_INDEX	799
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/19/2001
WRTY_START_D	2/16/2001
NAME	AKINS FORD CORPORATION
DOC_NUM	9488768
PH_NUM	8679136
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7961203
PART_NUM_CA	BAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/12/2001
TIS_WSD	7
CLM_KEY	3739738
MILGE	17578
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	402
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	
CPSC_CD_6	11001

TECH_TXT1	DRIVERS SEAT BELT FAILED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CK FOR DRIVER SIDE FRT SEATBELT DOES NOT LATCH AT TIMES
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121400
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B8
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU13LX1 [REDACTED]
LBR_COST	[REDACTED]
VKH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	TIEF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	288
MDL_YR	2001
SORT_INDEX	801
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	10/15/2001
NAME	JIM BURKE FORD
DOC_NUM	8148252
PH_NUM	3283800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7061203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	12/19/2001
TIS_WSD	3
CLM_KEY	0170588
MILGE	2587
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5471
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	LEFT SEAT BELT BUCKLE BINDING DG, RPLD SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT NOT LATCHING
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	171438
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRU16L91E00000
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	258
MDL_YR	2001
SORT_INDEX	502
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	11/7/2001
NAME	GALPIN FORD
DOC_NUM	6186801
PH_NUM	7573600
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	340
COND_CD	1
RPR_DT	12/14/2001
TIS_WSD	2
CLM_KEY	5815518
MILGE	1440
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5638
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CC487 REPLACED BOTH SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139594/ 139633
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRJ15L91L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T8F
DRIVE_CD	T8
ENG_CD	TVZ

ID	290
MDL_YR	2001
SORT_INDEX	803
TRANS_CD	7DE
PLANT_CD	AP
PRODN_DT	11/28/2000
WRTY_START_D	3/19/2001
NAME	PALATKA FORD LINCOLN-MERCURY
DOC_NUM	8891351
PH_NUM	3250051
WCC_CD	5R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	3/25/2002
TIS_WSD	13
CLM_KEY	7801140
MILGE	29446
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3473
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Field27	b
CPSC_CD_6	11001

TECH_TXT1	RF SEAT BELT WONT STAY LATCHED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT KEEPS UN LOCKING
AREA_CD	388
COUNTRY_CD	USA
SLS_DLR_CD	124200
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B05
TIS_FLAG	
VIN_CD	1FMRU15LR1L
LBR_COST	
VKH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	281
MDL_YR	2001
SORT_INDEX	808
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/10/2001
WRTY_START_D	10/13/2001
NAME	J.C. LEWIS MOTOR CO., INC.
DOC_NUM	30843101
PH_NUM	0260234
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	2/18/2002
TIS_WSD	5
CLM_KEY	7192800
MILGE	8710
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4827
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	NO OPERATING PROPERLY REPLACE DRIVER SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	STATES SEAT BELT WILL NOT LATCH 840
AREA_CD	812
COUNTRY_CD	USA
SLS_DLR_CD	121209
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU15L81L [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	282
MDL_YR	2001
SORT_INDEX	818
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/17/2000
WRTY_START_D	11/13/2000
NAME	BOB WONDRIES FORD
DOC_NUM	248878A
PH_NUM	2883581
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/30/2002
TIS_WSD	17
CLM_KEY	7713582
MILGE	18811
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6520
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	19811 81172A A REPLACED SEAT BELT WAS POPPING OUT CC 42
TECH_TXT2	
CUST_TXT	CJBT REPROTS THAT WHEN DRIVING AND DRIVERS SEATBELT IS LOCKED IN PLACE,WILL AUTOMATICALLY UNLOCK,DOES CLICK WHEN USED,SEE RUBEN
AREA_CD	628
COUNTRY_CD	USA
SLS_DLR_CD	171015
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMFU18L811
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TNZ

ID	288
MDL_YR	2001
SORT_INDEX	810
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	9/24/2000
WRTY_START_D	1/8/2001
NAME	FIESTA FORD, INC.
DOC_NUM	5488851
PH_NUM	7728000
WCC_CD	6R02
PART_NUM_CA	4L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	A85
COND_CD	42
RPR_DT	1/25/2002
TIS_WSD	13
CLM_KEY	6610886
MILGE	25001
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5438
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

TECH_TXT1	SEATBELT BUCKLE INOP DIAGNOSIS REMOVED AND REPLACED LEFT FRONT SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	O S SEAT BELT INOP DOES NOT BUCKLE AT TIMES
AREA_CD	700
COUNTRY_CD	USA
SLS_DLR_CD	171427
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V17
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU16L81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	284
MDL_YR	2001
SORT_INDEX	821
TRANS_CD	T/GE
PLANT_CD	AP
PRODN_DT	5/8/2001
WRTY_START_D	7/2/2001
NAME	UNIVERSITY FORD, INC.
DOC_NUM	8580651
PH_NUM	9829171
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/25/2001
TIS_WSD	4
CLM_KEY	4889493
MILGE	481D
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6834
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
FltM27	c
CPSC_CD_6	11001

TECH_TXT1	SEATBELT RECEIVER INOP CK REPLACED DRIVERS SEATBELT BUCKLE RECEIVER
TECH_TXT2	
CUST_TXT	CK DRIVERS SIDE SEATBELT UNBUCKLES ON ITS OWN
AREA_CD	019
COUNTRY_CD	USA
SLS_DLR_CD	121026
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	505
TIS_FLAG	
VIN_CD	1FMRU15L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/W3
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	205
MDL_YR	2001
SORT_INDEX	824
TRANS_CD	TUE
PLANT_CD	AP
PRODN_DT	4/26/2001
WRTY_START_D	6/4/2001
NAME	GALPIN FORD
DOC_NUM	6164371
PH_NUM	7879800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/19/2001
YIS_WSD	7
CLM_KEY	5058789
MILGE	7528
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5538
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	CCA87 REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ15L71L
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	298
MDL_YR	2001
SORT_INDEX	825
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/30/2001
NAME	TOMBALL FORD, INC.
DOC_NUM	223114G
PH_NUM	3815427
WCC_CD	BR02
PART_NUM_CA	F95Z
PART_NUM_CA	7861203
PART_NUM_CA	B8E
CUST_CONC_C	840
COND_CD	31
RPR_DT	7/30/2001
TIS_WSD	2
CLM_KEY	3928858
MILGE	079
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0042
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	12001

TECH_TXT1	REPLACED LEFT FRONT SEAT BETL BUCKLE
TECH_TXT2	
CUST_TXT	S40CLIST STATES SEAT BELTS COME APRT WHILE DRIVING
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152055
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L71L
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T1B
ENG_CD	T1NZ

ID	287
MDL_YR	2001
SORT_INDEX	826
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/2/2001
WRTY_START_D	6/22/2001
NAME	SOLITHWEST FORD INC
DOC_NUM	19818302
PH_NUM	5885700
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	1/31/2002
TIS_WSD	8
CLM_KEY	8828984
MILGE	5703
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2448
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	8
CPSC_CD_6	11001

TECH_TXT1	CHECKED SEAT BELT LATCHES BOTH FAILED REPLACED FRONT SEAT BELT LATCHES
TECH_TXT2	
CUST_TXT	S26 CUST STATES DRIVERS SIDE SEAT BELT BUCKLE DOES NOT LATCH EASILY ENOUGH HARD TO LATCH REQUEST CHECK PASSENGER
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	182408
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L71U
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	208
MDL_YR	2001
SORT_INDEX	831
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/9/2001
WRTY_START_D	4/4/2001
NAME	TIPTON MOTORS, INC.
DOC_NUM	5042801
PH_NUM	3505800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S23
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	4
CLM_KEY	2449007
MILGE	4102
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4421
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE FAULTY SEAT BELT LATCH AS NEEDED DONE
TECH_TXT2	
CUST_TXT	S25 STATES RT FRONT SEAT BELT DOES NOT LATCH
AREA_CD	968
COUNTRY_CD	USA
SLS_DLR_CD	182093
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRJ16L71L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TN2

ID	288
MDL_YR	2001
SORT_INDEX	834
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	6/27/2001
NAME	LOU GRUBB FORD
DOC_NUM	4247861
PH_NUM	9813333
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/28/2002
YES_WSD	B
CLM_KEY	7177307
MILGE	12825
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20323
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
Field27	c
CPSC_CD_6	11001

TECH_TXT1	DIAG BELT BUCKLE ON DRIVER SEAT NOT WORKING PROPERLY R AND R DRIVER SEAT BELT BUCKLE TESTED
TECH_TXT2	
CUST_TXT	CS DRIVERS FRT SEAT BELT WILL COME UNBUCKLED WHEN DRIVING
AREA_CD	602
COUNTRY_CD	USA
SLS_DLR_CD	171178
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	300
MDL_YR	2001
SORT_INDEX	837
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/24/2000
WRTY_START_D	11/9/2000
NAME	SAMES MOTOR COMPANY, INC.
DOC_NUM	8368248
PH_NUM	7214700
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S39
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	14
CLM_KEY	6622857
MILGE	23559
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	4498
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	25555 SEAT BELT WOULD COME LOOSE (NOT RECALL) 42 WR VERIFIED CUSTOMERS CONCERN AND ROAD TESTED VEHICLE. FOUND THAT SEAT BELT BUCKLE WOULD NOT HOLD SEAT BELT AND WOULD BECOME LOOSE AT A SUDDEN STOP.
TECH_TXT2	REMOVED SEAT IN ORDER TO ACCESS SEAT BELT BUCKLE. R R SEAT BELT BUCKLE ON DRIVER SIDE. ROAD TESTED AND FOUND BELT BUCKLE WORKING NORMALLY
CUST_TXT	S39 CUSTOMER STATES SEAT BELT BUCKLE LOOSE
AREA_CD	968
COUNTRY_CD	USA
SLS_DLR_CD	124125
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L71
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	301
MDL_YR	2001
SORT_INDEX	848
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/28/2001
NAME	JIM TIDWELL'S WORLD FORD
DOC_NUM	9482861
PH_NUM	4278531
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/29/2001
TIS_WSD	5
CLM_KEY	6476848
MILGE	10855
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	42	REPLACED DRIVERS SIDE SEAT BELT LATCH. WOULDNT STAY LATCHED.
TECH_TXT2		
CUST_TXT		DRIVERS SIDE SEATBELT KEEPS POPPING OUT WHILE DRIVING
AREA_CD		770
COUNTRY_CD		USA
SLS_DLR_CD		121858
TXN_CD		2
CNTRY_SOLD		USA
QRT_CD		Q21
VFG_CD		V05
AWS_VL_CD		BS
VRT_CD		S08
TIS_FLAG		
VIN_CD		1FMRJ19L81
LBR_COST		
VEH_LINE_CD		TAE3
MKT_DERIVED		*
BOD_CAR_STL		TWD
VER_SERIES_C		TXF
DRIVE_CD		T18
ENG_CD		TN2

ID	302
MDL_YR	2001
SORT_INDEX	844
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	12/8/2000
WRTY_START_D	8/5/2001
NAME	SHTLER-CORLEY MOTORS, LIMITED
DOC_NUM	11135801
PH_NUM	7834800
WCC_CD	6R32
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/13/2001
TIS_WSD	2
CLM_KEY	3818332
MILGE	2307
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8588
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACE BUCKLE INOP
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DR SEAT BELT DOES NOT BUCKLE ALL THE TIME
AREA_CD	337
COUNTRY_CD	USA
SLS_DLR_CD	123264
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU15L611
LBB_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	303
MDL_YR	2001
SORT_INDEX	847
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRYY_START_D	8/30/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	403444B
PH_NUM	2614281
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
CONB_CD	42
RPR_DT	10/20/2001
TIS_WSD	2
CLM_KEY	4514388
MILGE	3570
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2417
DLR_SUB_CD	A
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 685 of 748

RQ04-011 E 104B

TECH_TXT1	3570 FAULTY BUCKLE R R SEAT, REPLACED PASS SEATBELT BUCKLE **QUALITY CONTROL BY ANDREW RADER**
TECH_TXT2	
CUST_TXT	SOP PART IN PASSENGERS SIDE SEATBELT BUCKLE WILL NOT STAY BUCKLED
AREA_CD	617
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMRJ16L51 [REDACTED]
LBB_COST	[REDACTED]
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAR_STL	T7WD
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	T7Z

ID	304
MDL_YR	2001
SORT_INDEX	848
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	9/27/2001
WRTY_START_D	12/17/2001
NAME	ROCKWALL FORD-MERCURY
DOC_NUM	8488101
FH_NUM	2982200
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	63
RPR_DT	2/7/2002
TIS_WSD	2
CLM_KEY	8780436
MILGE	2287
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3687
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACE DRIVERS SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CUST. STATES DRIVERS SIDE SEAT BELT WILL NOT HOLD KEEP'S RELEASING SOP IS HERE
AREA_CD	B72
COUNTRY_CD	USA
SLS_DLR_CD	162620
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU16L51L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TNZ

ID	305
MDL_YR	2001
SORT_INDEX	850
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/11/2001
WRTY_START_D	3/30/2001
NAME	PECHELES FORD MERCURY
DOC_NUM	10823401
PH_NUM	9489104
WCC_CD	8F02
PART_NUM_CA	1LJZ
PART_NUM_CA	7881203
PART_NUM_CA	CAB
CUST_CONC_C	340
COND_CD	42
RPR_DT	4/18/2002
TIS_WSD	13
CLM_KEY	8097127
MILGE	18028
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3878
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEATBELT BUCKLE RELEASES
AREA_CD	252
COUNTRY_CD	USA
SLS_DLR_CD	121620
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	Q
VIN_CD	1FMRU15L611
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T8F
DRIVE_CD	T/B
ENG_CD	TNZ

ID	308
MDL_YR	2001
SORT_INDEX	851
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/2/2001
WRTY_START_D	9/10/2001
NAME	GALPIN FORD
DOC_NUM	60381761
PH_NUM	7873800
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/30/2001
TIS_WSD	0
CLM_KEY	3649805
MILGE	28
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5538
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001