

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 4 OF 6

BOOK 2 OF 43

TECH_TXT1	REPLACE SEAT BELTS WONT LATCH PROPERLY
TECH_TXT2	
CUST_TXT	
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	2
CNTRY_SOLD	USA
QBT_CD	Q21
VFG_CD	V05
AWS_VL_CD	BS
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15L51L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VBR_SERIES_C	T/EF
DRIVE_CD	T/EI
ENG_CD	T/VZ

ID	907
MDL_YR	2001
SORT_INDEX	883
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1A/2001
WRTY_START_D	6/12/2001
NAME	LONE STAR FORD
DOC_NUM	28819201
PH_NUM	8913900
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S25
COND_CD	41
RPR_DT	10/19/2001
TIS_WSD	6
CLM_KEY	4720000
MILGE	8645
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0947
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	C
CPSC_CD_6	11001

TECH_TXT1	REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	OK DRIVERS SEAT BELT POPPS LOOS DRIVING
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152241
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V15
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMFU18L51
LRR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	308
MDL_YR	2001
SORT_INDEX	854
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/30/2000
WRTY_START_D	12/20/2001
NAME	FORD GROVES
DOC_NUM	9845001
PH_NUM	3355572
WCC_CD	8RC2
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	828
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	1
CLM_KEY	7248902
MILGE	896
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8029
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field27	b
CPSC_CD_6	11001

Thursday, December 14, 2001

Page 415 of 740

RQ04-011 E 1058

TECH_TXT1	1 CHECKED OUT AND REPLACED DRIVERS SIDE FEMALE END
TECH_TXT2	
CUST_TXT	CUSTOMER STATES: THE DRIVERS SIDE FRONT SEATBELT WILL NOT STAY LATCHED
AREA_CD	573
COUNTRY_CD	USA
SLS_DLR_CD	152183
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L51L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	309
MDL_YR	2001
SORT_INDEX	855
TRANS_CD	T0E
PLANT_CD	AP
PRODN_DT	10/14/2000
WRTY_START_D	3/15/2001
NAME	GALPIN FORD
DOC_NUM	6082261
PH_NUM	7873000
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAB
CUST_CONC_C	S40
COND_CD	41
RPR_DT	10/16/2001
TIS_WSD	8
CLM_KEY	4629048
MILGE	9722
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6838
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	a
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 617 of 748

RQ04-011 E 1080

TECH_TXT1	GG487/Q44 REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATESW DRIVER SIDE SEAT BELT INOP WILL NOT BUCKEL
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU15L51L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TN2

ID	310
MDL_YR	2001
SORT_INDEX	680
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	5/11/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	411354G
PH_NUM	2814281
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	8
CLM_KEY	5850830
MILGE	3600
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	2417
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	3500 1.0 REPLACED SEAT BELT LOCK
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT WONT STAY ATTACHED
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRJH1SL41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	311
MDL_YR	2001
SORT_INDEX	882
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/4/2001
WRTY_START_D	8/8/2001
NAME	EL CAJON FORD
DOC_NUM	0840161
PH_NUM	5788888
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/24/2001
TIS_WSD	2
CLM_KEY	4080787
MILGE	3080
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8488
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	BUCKLE WOULD NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUST STATES LEFT FRONT SEAT BELT WILL NOT NOT STAY LATCH IN THE BUCKLE COMES LOOSE
AREA_CD	618
COUNTRY_CD	USA
SLS_DLR_CD	171078
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU18L41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	TEF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	312
MDL_YR	2001
SORT_INDEX	898
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRKY_START_D	8/17/2001
NAME	GWINNETT PLACE FORD
DOC_NUM	9312402
PH_NUM	4762380
WCC_CD	8F02
PART_NUM_CA	1L7Z
PART_NUM_CA	7581203
PART_NUM_CA	BAB
CUST_CONC_C	T80
COND_CD	42
RPR_DT	1/7/2002
TIS_WSD	5
CLM_KEY	8090070
MILGE	7584
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	3573
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	DRIVER SIDE SEAT BUCKEL WOULD NOT HOLD REPLACE DRIVER SIDE SEAT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT WONT BUCKLE
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121025
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L41L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	313
MDL_YR	2001
SORT_INDEX	898
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	8/18/2001
NAME	J.C. LEWIS MOTOR CO., INC.
DOC_NUM	30824502
PH_NUM	8250234
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAB
CUST_CONC_C	B40
COND_CD	42
RPR_DT	2/15/2002
YIS_WSD	0
CLM_KEY	0047888
MILGE	3478
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4827
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	*
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVER SIDE BUCKLE; WAS NOT LATCHING PROPERLY
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVER'S SIDE BUCKLE BECOMES UNLATCHED FROM TIME TO TIME
AREA_CD	912
COUNTRY_CD	USA
SLS_DLR_CD	121209
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	
VIN_CD	1FMRJ15L41L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T8
ENG_CD	TN2

ID	314
MDL_YR	2001
SORT_INDEX	672
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	5/11/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	331338B
PH_NUM	2814261
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7801203
PART_NUM_CA	GAB
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/20/2001
TIS_WSD	3
CLM_KEY	2489423
MILGE	3817
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2417
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	11001

TECH_TXT1	3817 DRIVERS SEAT BELT BUCKLE MALFUNCTIONING. REPLACED DRIVERS SEAT BELT BUCKLE *** QUALITY CONTROL BY JOHN MEDROW ***
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES LOOSE SOP HERE
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU15L31U
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VBR_SERIES_C	T/EF
DRIVE_CD	T/81
ENG_CD	T/VZ

ID	315
MDL_YR	2001
SORT_INDEX	874
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	7/28/2001
NAME	BILLINGSLEY FORD, INC.
DOC_NUM	086356A
PH_NUM	2283300
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/25/2001
TIS_WSD	3
CLM_KEY	5980508
MILGE	4863
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2414
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INSPECT AND REPLACE LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WONT STAY BUCKLED INTERMITTENLY
AREA_CD	680
COUNTRY_CD	USA
SLS_DLR_CD	162810
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU1BL31U [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	316
MDL_YR	2001
SORT_INDEX	876
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/5/2001
WRTY_START_D	6/7/2001
NAME	JOHN BLEAKLEY FORD INC
DOC_NUM	7463851
PH_NUM	9419000
WCC_CD	5R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAC
CUST_CONG_C	825
COND_CD	42
RPR_DT	1/16/2002
TIS_WSD	8
CLM_KEY	8307159
MILGE	10770
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	467
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 431 of 749

RQ04-011 E 1074

TECH_TXT1	LEFT SEAT BELT INOP FRONT REPLACE	SEATBELT ASSEMBLY
TECH_TXT2		
CUST_TXT	LEFT SEAT BELT WONT STAY LATCHED	PART HERE WAIT
AREA_CD	770	
COUNTRY_CD	USA	
SLS_DLR_CD	121069	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	808	
TIS_FLAG		
VIN_CD	1FMRL16L81L	
LBR_COST		
VEH_LINE_CD	T/B3	
MKT_DERIVED	*	
BOD_CAB_STL	T/ND	
VER_SERIES_C	T/EF	
DRIVE_CD	T/B	
ENG_CD	T/VZ	

ID	317
MDL_YR	2001
SORT_INDEX	577
TRANS_CD	T0E
PLANT_CD	AP
PRODN_DT	2/6/2001
WRTY_START_D	7/4/2001
NAME	TOWN & COUNTRY FORD , INC.
DOC_NUM	28161501
PH_NUM	5385900
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S25
COND_CD	42
RPR_DT	11/3/2001
TIS_WSD	8
CLM_KEY	4842658
MILGE	5888
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1057
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Field27	c
CPSC_CD_6	11001

TECH_TXT1	42 REMOVE D S SEAT R R BUCKLE 7881203
TECH_TXT2	
CUST_TXT	CUST STATES SEAT BELT COMES UNFASTENED,JUST DID RECALL CC 828
AREA_CD	704
COUNTRY_CD	USA
SLS_DLR_CD	121212
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L31L
LRR_COST	
VEH_LINE_CD	T/S9
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	318
MDL_YR	2001
SORT_INDEX	878
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	8/12/2001
WRTY_START_D	8/3/2001
NAME	COURTESY MOTORS, INC.
DOC_NUM	084047A
PH_NUM	5448111
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	6/1/2002
TIS_WSD	9
CLM_KEY	8484258
MILGE	12168
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8678
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MS
Field27	a
CPSC_CD_6	11001

TECH_TXT1	12162 W CHECKED DRIVERS SEAT BEALT OPERATION TO FIND FAULTY SEAT BELT BUCKLE ASY R&R BUCKLE ASY TO FIX CONCERN RETEST.
TECH_TXT2	
CUST_TXT	CK DRIVER SEATBELT WILL NOT HOLD
AREA_CD	001
COUNTRY_CD	USA
SLS_DLR_CD	123307
TXN_CD	EM
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	@
VIN_CD	1FMRJ16L21L
LR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	318
MDL_YR	2001
SORT_INDEX	880
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/5/2001
WRTY_START_D	10/22/2001
NAME	JENKINS AND WYNNE FORD LINCOLN
DOC_NUM	076600A
PH_NUM	8473353
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	1
RPR_DT	10/4/2001
TIS_WSD	0
CLM_KEY	4422683
MILGE	90
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6816
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TN
Field27	a
CPSC_CD_6	11001

TECH_TXT1	REPLACED LEFT FRONT SEATBELT
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BUCKLE WONT LATCH
AREA_CD	831
COUNTRY_CD	USA
SLS_DLR_CD	123079
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L21L
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VRR_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	320
MDL_YR	2001
SORT_INDEX	884
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	8/17/2001
NAME	SKYLINE FORD SALES, INC.
DOC_NUM	110133A
PH_NUM	3274500
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	840
COND_CD	33
RPR_DT	10/10/2001
TIS_WSD	2
CLM_KEY	4339700
MILGE	3770
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	543
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	e
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 639 of 746

RQ04-011 E 1082

TECH_TXT1	
TECH_TXT2	
CUST_TXT	S40*CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT UNLATCHES WHILE DRIVING
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	152003
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMRU15L21L
LRR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	321
MDL_YR	2001
SORT_INDEX	886
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	8/18/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	409278D
PH_NUM	2814281
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	340
COND_CD	33
RPR_DT	12/7/2001
TIS_WSD	3
CLM_KEY	5601509
MILGE	3272
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2417
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	c
CPSC_CD_6	19001

TECH_TXT1	3272 NOT STAYING LOCKED R DRIVERS SEAT TO TEAR DOWN AND REPLACE DRIVERS SEAT BELT SUCKLE. ****QUALITY TESTED BY LOUIS TREVINO****
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRI_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	T8F
DRIVE_CD	T8
ENG_CD	T8Z

ID	322
MDL_YR	2001
SORT_INDEX	888
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/7/2001
WRTY_START_D	6/18/2001
NAME	SANDERSON L-M INC
DOC_NUM	84041801
PH_NUM	
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAC
CUST_CONC_C	S25
COND_CD	41
RPR_DT	9/24/2001
TIS_WSD	4
CLM_KEY	4221288
MILGE	8192
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	10083
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
Field27	c
CPSC_CD_6	11001

TECH_TXT1	LF SEATBELT WILL NOT LATCH REPLACED LF SEATBELT BUCKLE M 1 USED FOR REPAIR DUE TO LACK OF ALBOR OP AND TIME ESTABLISHED IN LABOR MANUAL
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT KEEPS COMING LOOSE
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	171171
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU16L21
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T1B
ENG_CD	TVZ

ID	323
MDL_YR	2001
SORT_INDEX	690
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	8/18/2001
NAME	KING CHARLIE HILLARD FORD
DOC_NUM	18230503
PH_NUM	3705000
WCC_CD	6RD2
PART_NUM_CA	1L7Z
PART_NUM_CA	7881209
PART_NUM_CA	AAF
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/17/2001
TIS_WSD	0
CLM_KEY	3778301
MILGE	BB
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2478
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	8
CPSC_CD_6	11001

TECH_TXT1	VERIF CONCERN.REMOVED DEFECTIVE SEAT BELT BUCKLE AND REPLACED.OPERATES AS DESIGNED AFTER REPLACEMENT
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE ON DRIVERS SIDE WILL NOT LATCH
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152010
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1F
DRIVE_CD	T1B
ENG_CD	T1Z

ID	324
MDL_YR	2001
SORT_INDEX	891
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/20/2000
WRTY_START_D	1/29/2001
NAME	BEVERLY HILLS FORD
DOC_NUM	15162101
PH_NUM	2753673
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	5/1/2002
TIS_WSD	18
CLM_KEY	6374355
MILGE	11967
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2657
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	8
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 647 of 748

RQ04-011 E 1090

TECH_TXT1	INTERMITTENT CONCERN,BUCKLE WILL NOT LATCH. REPLACE DRIVERS SIDE SEAL BELT AND BUCKLE ASSY
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS SEAT BELT IS INOP
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	805
TIS_FLAG	0
VIN_CD	1FMRL16L21L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	T7F
DRIVE_CD	T7B
ENG_CD	T7Z

ID	325
MDL_YR	2001
SORT_INDEX	883
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	5/22/2001
NAME	WOODY ANDERSON FORD
DOC_NUM	B444852
PH_NUM	5388441
WCC_CD	0R02
PART_NUM_CA	FB5Z
PART_NUM_CA	7881203
PART_NUM_CA	BBE
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/24/2001
TIS_WSD	B
CLM_KEY	4798388
MILGE	14742
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6882
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
Field27	c
CPSC_CD_6	12001

TECH_TXT1	PINPOINT TESTS R&I DRIVER SEAT R&R SEAT BELT RECEIVER NOT LATCHING
TECH_TXT2	
CUST_TXT	CK DRIVERS SEATBELT KEEPS COMING UNBUCKLED
AREA_CD	288
COUNTRY_CD	USA
SLS_DLR_CD	121707
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRU15L11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T&F
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	328
MDL_YR	2001
SORT_INDEX	895
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/25/2001
NAME	HOLLINGSWORTH RICHARDS FORD
DOC_NUM	19871401
PH_NUM	9278855
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/11/2001
TIS_WSD	1
CLM_KEY	2318084
MILGE	547
MTBL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1188
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPL SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL NOT STAY BUCKLED
AREA_CD	ZZ5
COUNTRY_CD	USA
SLS_DLR_CD	123378
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMRU15L11L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TNZ

ID	327
MDL_YR	2001
SORT_INDEX	897
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/15/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	4017788
PH_NUM	2814281
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAB
CUST_CONC_C	S26
COND_CD	33
RPR_DT	10/8/2001
TIS_WSD	1
CLM_KEY	4341436
MILGE	1898
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2417
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11001

TECH_TXT1	1600 DEFECTIVE SEATBELT R R SEAT, REMOVED SEATBELT CONNECTOR FROM UNDER SEAT, REPLACED DRIVER SIDE SEATBELT ***QUALITY CONTROL BY ANDREW RADER***
TECH_TXT2	
CUST_TXT	SOP HERE DRIVERS SEAT BELT WONT STAY LATCHED
AREA_CD	017
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B9
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ

ID	328
MDL_YR	2001
SORT_INDEX	898
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/4/2001
NAME	GWINNETT PLACE FORD
DOC_NUM	8857803
PH_NUM	4782080
WCC_CD	8F02
PART_NUM_CA	F85Z
PART_NUM_CA	7881208
PART_NUM_CA	BBE
CUST_CONC_C	T80
COND_CD	33
RPR_DT	11/28/2001
TIS_WSD	4
CLM_KEY	5428380
MILGE	8721
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3572
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	12001

TECH_TXT1	DEFECTIVE SEAT BELT BUCKLE REPLACE D B SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT RELEASES BY ITSELF
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121026
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L11L
LRR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
RNG_CD	T/VZ

ID	329
MDL_YR	2001
SORT_INDEX	899
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	5/25/2001
NAME	SAWGRASS FORD
DOC_NUM	36286301
PH_NUM	8519000
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7851203
PART_NUM_CA	BAC
CUST_CONC_C	640
COND_CD	42
RPR_DT	2/18/2002
TIS_WSD	8
CLM_KEY	8947752
MILGE	11248
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	4808
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Field27	c
CPSC_CD_6	11001

TECH_TXT1	DRIVER SEAT BUCKLE ASSY DOES NOT LATCH 611 INSPECT AND TEST, REMOVE DRIVER SEAT, REPLACE SEAT BUCKLE ASSY, TEST OP
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEAT BELT UNLATCH BY SELF DRIVERS SEAT
AREA_CD	854
COUNTRY_CD	USA
SLS_DLR_CD	124009
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMRJ15L11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	TNZ

ID	330
MDL_YR	2001
SORT_INDEX	600
TRANS_CD	T/DIE
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	10/5/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	402214C
PH_NUM	2814281
WCC_CD	8P02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	83
RPR_DT	10/10/2001
TIS_WSD	1
CLM_KEY	4711512
MILGE	31
MTRL_COST	
TOY_COST_GRO	
LBR_HRS	
DLR_CD	2417
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	D
CPSC_CD_6	11001

TECH_TXT1	31 NOT STAYING BUCKLED TESTED DRIVERS SEAT BELT OPERATION, R1 SEAT AND REPLACED SEAT BELT BUCKLE, RETEST, ALL FINE AT THIS TIME. ***QUALITY TESTED BY LOUIS TREVINO***
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT WILL NOT STAY BUCKLED
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	162016
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V09
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L111
LRR_COST	
VEH_LINE_CD	T83
MRT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/E
DRIVE_CD	T/B
ENG_CD	TWZ

ID	331
MDL_YR	2001
SORT_INDEX	901
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	3/21/2001
NAME	D & D MOTORS, INC.
DOC_NUM	171072B
PH_NUM	8770711
WCC_CD	6R02
PART_NUM_CA	1LJZ
PART_NUM_CA	7881203
PART_NUM_CA	BAC
CUST_CONC_C	S40
COND_CD	41
RPR_DT	1/31/2002
TIS_WSD	11
CLM_KEY	0008030
MILGE	25564
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	878
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
Field27	
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 661 of 748

RQ04-011 E 1104

TECH_TXT1	26664 TESTED SEAT BELT OPERATION REPL SEAT BELT BUCKLE FOR DRIVERS SEAT C.C. 42
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BUCKLE WILL NOT LATCH
AREA_CD	004
COUNTRY_CD	USA
SLS_DLR_CD	121796
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU16L11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINK_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	TWO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	332
MDL_YR	2001
SORT_INDEX	802
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/29/2001
WRTY_START_D	4/1/2001
NAME	RANCHO FORD L-M
DOC_NUM	28552002
PH_NUM	8081302
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861208
PART_NUM_CA	BAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	12/17/2001
TIS_WSD	8
CLM_KEY	8020568
MILGE	17742
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6492
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	REPLACED L F SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT WHEN BUCKLED AND CAN BE PULLED AND RELEASED WITHOUT PUSHING BUTTON
AREA_CD	9189
COUNTRY_CD	USA
SLS_DLR_CD	171424
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	
VIN_CD	1FMRJ16L11
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	333
MDL_YR	2001
SORT_INDEX	903
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/24/2001
WRTY_START_D	9/18/2001
NAME	CAREY PAUL FORD
DOC_NUM	9789751
PH_NUM	0678000
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7981203
PART_NUM_CA	BAB
CUST_CONC_C	S26
COND_CD	42
RPR_DT	4/4/2002
TIS_WSD	7
CLM_KEY	7987488
MILGE	17183
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	277
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Field27	b
CPSC_CD_6	11001

TECH_TXT1	INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVERS SIDE FRONT SEAT BELT KEEPS SLIPPING OUT..WILL NOT STAY LATCHED GOOD
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121007
TXN_CD	ES4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L011
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	T7W0
VER_SERIES_C	T7EF
DRIVE_CD	T7B
ENG_CD	T7VZ

ID	394
MDL_YR	2001
SORT_INDEX	904
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/25/2001
WRTY_START_D	8/12/2001
NAME	VISTA FORD OF OXNARD
DOC_NUM	2597451
PH_NUM	
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	7/21/2001
TIS_WSD	0
CLM_KEY	2870123
MILGE	80
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3893
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	SEATBELT INOP REPLACE LEFT SEAT BELT BUCKLE DID NOT LATCH.RETEST OK
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT RECEPTACLE INOP
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	171448
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMRU15L01L
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T1EF
DRIVE_CD	T7B
ENG_CD	TN2

ID	335
MDL_YR	2001
SORT_INDEX	907
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	5/27/2001
NAME	DOWNTOWN FORD SALES
DOC_NUM	173582A
PH_NUM	4428931
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/18/2002
TIS_WSD	6
CLM_KEY	6378628
MILGE	13333
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7883
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNDONE AS DRIVING
AREA_CD	B16
COUNTRY_CD	USA
SLS_DLR_CD	172201
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L01
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	338
MDL_YR	2001
SORT_INDEX	908
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/7/2001
WRTY_START_D	6/8/2001
NAME	GALPIN FORD
DOC_NUM	8333884
PH_NUM	7573500
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	S28
COND_CD	41
RPR_DT	3/16/2002
TIS_WSD	10
CLM_KEY	7806880
MILGE	20887
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	5536
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Field27	c
CPSC_CD_6	11001

TECH_TXT1	CC396 CHECKED AND REPLACED DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S28 CUSTOMER STATES THAT DRIVERS FRONT SEAT BELT BUCKLE UNLOCKS BY ITSELF WHILE DRIVING.
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	E3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMRU15L01L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ

ID	337
MDL_YR	2001
SORT_INDEX	914
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/19/2000
WRTY_START_D	4/17/2001
NAME	ALL STAR FORD LINCOLN MERCURY,
DOC_NUM	240987A
PH_NUM	8778181
WCC_CD	BR02
PART_NUM_CA	1LTZ
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	528
COND_CD	42
RPR_DT	2/15/2002
TIS_WSD	11
CLM_KEY	8046955
MILGE	17797
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6480
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE ONE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BUCKLE WOULD NOT LATCH
AREA_CD	228
COUNTRY_CD	USA
SLS_DLR_CD	123148
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VEN_CD	1FMRU16LD1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ

ID	338
MDL_YR	2001
SORT_INDEX	817
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/3/2001
WRTY_START_D	5/16/2001
NAME	ANDREWS COUNTY FORD
DOC_NUM	028191B
PH_NUM	5243673
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7081203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RFR_DT	9/8/2001
TIS_WSD	4
CLM_KEY	4873781
MILGE	1B144
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2388
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	8
CPSC_CD_6	11001

TECH_TXT1	SEAT BELT ON LEFT HAND OF THIRD SEAT WILL NOT BUCKLE. REPLACED SEATBELT ASSEMBLY. INSPECTED BELTS ON CAPTAINS SEATS. OK.
TECH_TXT2	
CUST_TXT	CHECK LAST SEAT SEATBELT BUCKLE
AREA_CD	815
COUNTRY_CD	USA
SLS_DLR_CD	152880
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPUH6LX1
LBR_COST	
VEH_LINE_CD	T/B3
MRY_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	TN2

ID	339
MDL_YR	2001
SORT_INDEX	921
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/26/2000
WRTY_START_D	6/8/2001
NAME	MAGARINO FORD-MERCURY, INC.
DOC_NUM	3067301
PH_NUM	7028000
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7661203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/23/2002
TIS_WSD	0
CLM_KEY	6476290
MILGE	4035
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1052
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
Field7	a
CPSC_CD_6	11001

TECH_TXT1	INSTALLED SEAT BELT BUCKLE ASSEMBLY WOULDN'T LATCH
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEAT BELT BUCKLE DOESN'T STAY LATCHED
AREA_CD	973
COUNTRY_CD	USA
SLS_DLR_CD	113510
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	805
TIS_FLAG	
VIN_CD	1FMPU18LX1 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/A
VEH_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/VZ

ID	340
MDL_YR	2001
SORT_INDEX	022
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/15/2001
WRTY_START_D	6/13/2001
NAME	ALL STAR FORD-MERCURY, INC.
DOC_NUM	9914303
PH_NUM	7292171
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7561203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/29/2001
TIS_WSD	7
CLM_KEY	5949787
MILGE	6240
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	812
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	*
CPSC_CD_6	11001

TECH_TXT1	VERIFY CONCERN AND CK. SEAT BELT ON LEFT FRONT SEAT BELT FAILED TO LATCH, REPLACE SEAT BELT LATCH. VERIFY REPAIR,OK.
TECH_TXT2	
CUST_TXT	CUST. REQUEST CK. FOR LF SEAT BELT WILL NOT LATCH AT TIMES
AREA_CD	003
COUNTRY_CD	USA
SLS_DLR_CD	152707
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L91L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/A
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	341
MDL_YR	2001
SORT_INDEX	923
TRANS_CD	TDC
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	6/30/2001
NAME	BOYER FORD TRUCKS, INC.
DOC_NUM	226757A
PH_NUM	3781851
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/9/2001
TIS_WSD	5
CLM_KEY	4185760
MILGE	9018
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	0441
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 681 of 748

RQ04-011 E 1124

TECH_TXT1	901B REPLACED BOTH FRONT BELT LATCHES AND TEST THE OP.
TECH_TXT2	
CUST_TXT	BEAT BELT COMES UNBUCKLED AT TIMES INSTALL SOP
AREA_CD	812
COUNTRY_CD	USA
SLS_DLR_CD	168900
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L91L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/A
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	342
MDL_YR	2001
SORT_INDEX	928
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	7/0/2001
NAME	GRIFFITH FORD-MERCURY, INC.
DOC_NUM	4387852
PH_NUM	7821505
WCC_CD	BR02
PART_NUM_CA	1LTZ
PART_NUM_CA	7881208
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/14/2001
TIS_WSD	1
CLM_KEY	2321018
MILGE	187
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8498
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	DRIVERS SEATBELT WONT LATCH, REPLAGED LATCH ASSEMBLY
TECH_TXT2	
CUST_TXT	DRIVER SEATBELT WONT LATCH PART HERE
AREA_CD	712
COUNTRY_CD	USA
SLS_DLR_CD	153654
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	83
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMPU18L01L
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAR_STL	TVA
VER_SERIES_C	TJF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	343
MDL_YR	2001
SORT_INDEX	929
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	1/4/2001
WRTY_START_D	8/28/2001
NAME	VICTORY FORD MERCURY, INC.
DOC_NUM	8094201
PH_NUM	8517036
WCC_CD	8R02
PART_NUM_CA	1LTZ
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/17/2001
TIS_WSD	4
CLM_KEY	5779167
MILGE	3098
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3078
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field27	8
CPSC_CD_6	11001

TECH_TXT1	REPLACE LF. SEAT BELT LATCH AND CHECKS OK FW.
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT LATCH
AREA_CD	617
COUNTRY_CD	USA
SLS_DLR_CD	14B517
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU1BL91L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	Y
BOD_CAB_STL	TVA
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	344
MDL_YR	2001
SORT_INDEX	833
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	8/21/2000
WRTY_START_D	11/21/2000
NAME	CERRITOS FORD
DOC_NUM	ZT71004
PH_NUM	8855554
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	GAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	3/27/2002
TIS_WSD	17
CLM_KEY	7712813
MILGE	17537
MTRL_COST	
TOT_COST_GRO	
LRR_HRS	
DLR_CD	6401
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Field27	
CPSC_CD_6	11001

TECH_TXT1	WF CODE 42 M1 0.7 REPLACED DEFECTIVE DRIVERS SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAR BELT WONT LATCH
AREA_CD	562
COUNTRY_CD	USA
SLS_DLR_CD	171011
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L01 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINK_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	245
MDL_YR	2001
SORT_INDEX	834
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	8/8/2001
NAME	VALLEY FORD-MERCURY, INC.
DOC_NUM	886843
PH_NUM	7382311
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	1
CLM_KEY	4214208
MILGE	880
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5061
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
Field27	8
CPSC_CD_6	11001

TECH_TXT1	REPLACED LEFT FRT SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	CHECK DRIVER SIDE SEAT BELT COMES LOOSE
AREA_CD	031
COUNTRY_CD	USA
SLS_DLR_CD	123253
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L61L
LBR_COST	
VEH_LINE_CD	T03
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	TIEF
DRIVE_CD	TIE
ENG_CD	TNZ

ID	346
MDL_YR	2001
SORT_INDEX	03E
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	8/4/2001
NAME	QUIRK FORD, INC.
DOC_NUM	3384458
PH_NUM	7700070
WCC_CD	0R02
PART_NUM_CA	F76Z
PART_NUM_CA	7881203
PART_NUM_CA	AA0
CUST_CONC_C	825
COND_CD	42
RPR_DT	12/3/2001
TIS_WSD	4
CLM_KEY	5474883
MILGE	3895
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8980
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MA
Field27	0
CPSC_CD_6	11001

TECH_TXT1	VERIFY AND REPLACE SEAT BELT ASSEMBLY
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT COMES UNFASTENED WHILE DRIVING.
AREA_CD	617
COUNTRY_CD	USA
SLS_DLR_CD	111010
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	
VIN_CD	1FMPU18L81
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	347
MDL_YR	2001
SORT_INDEX	837
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/12/2001
NAME	MIDDLEKAUFF FORD, INC.
DOC_NUM	618938A
PH_NUM	8853800
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	8/1/2001
TIS_WSD	3
CLM_KEY	2744383
MILGE	8050
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2478
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Field27	b
CPSC_CD_6	11B01

TECH_TXT1	8058 WONT LATCH REPLACE DRIVER SEAT BUCKLE
TECH_TXT2	
CUST_TXT	840 DRIVERS SEAT BELT WILL NOT STAY LATCHED
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	152001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU16L811
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	TEF
DRIVE_CD	TIE
ENG_CD	TNZ

ID	348
MDL_YR	2001
SORT_INDEX	941
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/16/2001
WRTY_START_D	6/9/2001
NAME	LOU GRUBB FORD
DOC_NUM	3571859
PH_NUM	9013333
WCC_CD	0R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	7
CLM_KEY	6009823
MILGE	13000
MYRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20329
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Field27	0
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SEAT BELT BUCKLES DUE TO FAULTY AND NOT STAYING
TECH_TXT2	
CUST_TXT	GUEST STATES THAT DRIVER SEATBELT COMES UNDONE SOMETIMES WHILE DRIVING
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	171178
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	
VIN_CD	1FMPU16L71L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	TNA
VEH_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	349
MDL_YR	2001
SORT_INDEX	945
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	2/28/2001
WRTY_START_D	3/7/2001
NAME	TOMS FORD, INC.
DOC_NUM	207122A
PH_NUM	2841800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	10/18/2001
TIS_WSD	8
CLM_KEY	4488950
MILGE	10880
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20639
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
Field27	b
CPSC_CD_6	11001

TECH_TXT1	10650 INSTALL SOPS REMOVED AND INSTALLED SEAT BELT BUCKLE FRONT SEATS BOTH SIDES.
TECH_TXT2	
CUST_TXT	CUST STS BOTH FRONT SEATBELT BUCKLES DONT HOLD PROPERLY, STICK CCC 840
AREA_CD	732
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	TIEF
DRIVE_CD	TIE
ENG_CD	TNZ

ID	350
MDL_YR	2001
SORT_INDEX	848
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	8/8/2001
NAME	BLD SHELL FORD INC
DOC_NUM	8545201
PH_NUM	6247478
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861209
PART_NUM_CA	BAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	8/20/2001
TIS_WSD	2
CLM_KEY	4522588
MILGE	2237
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9088
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Field17	G
CPSC_CD_6	11001

TECH_TXT1	REPLACE DR SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	CHECK LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING
AREA_CD	573
COUNTRY_CD	USA
SLS_DLR_CD	123230
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	
VIN_CD	1FMPU18161L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	351
MDL_YR	2001
SORT_INDEX	652
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	8/18/2001
NAME	WEBB FORD INC
DOC_NUM	6889162
PH_NUM	7211994
WCC_CD	6R02
PART_NUM_CA	1LJZ
PART_NUM_CA	7881208
PART_NUM_CA	BAA
CUST_CONC_C	940
COND_CD	69
RPR_DT	10/25/2001
TIS_WSD	5
CLM_KEY	4877257
MILGE	7837
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1892
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
Field27	*
CPSC_CD_6	11001

TECH_TXT1	BINDING SEAT BELT BUCKLE FRONT SEAT BELT BUCKLE	REPLACED LEFT
TECH_TXT2		
CUST_TXT	CHECK VEHICLE DRIVERS SIDE FRONT SEAT BELT WILL NOT BUCKLE AT TIMES	
AREA_CD	312	
COUNTRY_CD	USA	
SLS_DLR_CD	141075	
TXN_CD	1	
CNTRY_SOLD	USA	
QRT_CD	Q21	
VFG_CD	V05	
AWS_VL_CD	B3	
VRT_CD	S08	
TIS_FLAG		
VIN_CD	1FMPU18L1L [REDACTED]	
LBR_COST	[REDACTED]	
VEH_LINE_CD	T1B3	
MKT_DERIVED	*	
BOD_CAB_STL	TVA	
VER_SERIES_C	T1EF	
DRIVE_CD	T/E	
ENG_CD	TNZ	

ID	352
MDL_YR	2001
SORT_INDEX	054
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/9/2001
WRTY_START_D	4/30/2001
NAME	LANDERS FORD
DOC_NUM	6548602
PH_NUM	8543673
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	528
COND_CD	42
RPR_DT	2/1/2002
TIS_WSD	10
CLM_KEY	7108448
MILGE	15600
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3820
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
Field27	0
CPSC_CD_6	11001

TECH_TXT1	VERIFY CONCERN LEFT SEAT BELT UNLATCHES INTERMITTENT, R&R LEFT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT WILL COME LOOSE BY ITSELF
AREA_CD	901
COUNTRY_CD	USA
SLS_DLR_CD	123006
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU16L81L [REDACTED]
LRR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/A
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	353
MDL_YR	2001
SORT_INDEX	856
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	6/30/2001
NAME	TOWN EAST FORD
DOC_NUM	781623A
PH_NUM	2706441
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	7/12/2001
TIS_WSD	1
CLM_KEY	2537578
MILGE	207
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	6102
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Field27	0
CPSC_CD_6	11001

TECH_TXT1	210 42 VERIFY CUSTOMER CONCERN, INSPEXCT AND FOUND DRIVER SEAT BELT BUCKLE NOT HOLDING SEAT BELT AT TIMES, REPLACED DRIVERS SIDE SEAT BELT BUCKL E, REINSTALL ROAD TEST RETEST OK.
TECH_TXT2	
CUST_TXT	S26 DRIVERS SEAT BELT WONT STAY LATCHED
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	
VIN_CD	1FMPU16L61L
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T1EF
DRIVE_CD	T1E
ENG_CD	T1Z

ID	354
MDL_YR	2001
SORT_INDEX	668
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/8/2001
WRTY_START_D	2/27/2001
NAME	SAYWILLE FORD
DOC_NUM	40900801
PH_NUM	5894800
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	B40
COND_CD	4Z
RPR_DT	12/7/2001
TIS_WSD	10
CLM_KEY	6483142
MILGE	11147
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	9867
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
Field27	
CPSC_CD_6	11001

TECH_TXT1	CONFIRMED. REMOVED AND REPLACED DRIVERS SEAT BELT LATCH TO CORRECT
TECH_TXT2	
CUST_TXT	C S DRIVERS SEAT BELT COMES UNLATCHED SOP IS IN
AREA_CD	631
COUNTRY_CD	USA
SLS_DLR_CD	113103
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B05
TIS_FLAG	
VIN_CD	1FMPU16LS1
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TVA
VER_SERIES_C	T1EF
DRIVE_CD	TE
ENG_CD	TNZ

ID	355
MDL_YR	2001
SORT_INDEX	961
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/8/2001
WRTY_START_D	7/10/2001
NAME	AUFFENBERG FORD, INC.
DOC_NUM	000841A
PH_NUM	2340330
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/17/2001
TIS_WSD	4
CLM_KEY	4483141
MILGE	8587
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	5017
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
Field27	*
CPSC_CD_6	11001

TECH_TXT1	9587 DEFECTIVE SEAT BELT BUCKLE DRIVERS SEATBELT BUCKLE INTERMITTENTLY INOP. REMOVED AND REPLACED SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	840 SEATBELT WOULD NOT LATCH
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	116638
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	G08
TIS_FLAG	
VIN_CD	1FMPL18L51L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	TE
ENG_CD	TNZ

ID	368
MDL_YR	2001
SORT_INDEX	884
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/28/2001
NAME	SIGNATURE FORD LINCOLN-MERCURY
DOC_NUM	075788B
PH_NUM	7262888
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	7
CLM_KEY	6580370
MILGE	8851
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Field17	8
CPSC_CD_6	11001

TECH_TXT1	REPLACED LEFT FRONT SEAT BELT BUCKEL BN 7861203 OC 42 TECH 173
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	909
COUNTRY_CD	USA
SLS_DLR_CD	148825
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	357
MDL_YR	2001
SORT_INDEX	968
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRFY_START_D	7/18/2001
NAME	GEWEKE FORD
DOC_NUM	13333901
PH_NUM	3346500
WCC_CD	6R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	63
RPR_DT	1/30/2002
TIS_WSD	7
CLM_KEY	8813122
MILGE	10945
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	7800
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
Field27	a
CPSC_CD_6	11001

TECH_TXT1	VERIFIED CONCERN, SEAT BELT WILL NOT HOLD. NEC TO REPLACE BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE DRIVER SIDE BELT WILL NOT STAY LATCHED...SOP HERE
AREA_CD	206
COUNTRY_CD	USA
SLS_DLR_CD	158011
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	
VIN_CD	1FMPU18L41
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TAZ

ID	358
MDL_YR	2001
SORT_INDEX	871
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	8/28/2001
NAME	BARBER-DYSON FORD L-14, L.L.C.
DOC_NUM	1388001
PH_NUM	2290450
WCC_CD	8R02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/30/2001
TIS_WSD	2
CLM_KEY	4788873
MILGE	658
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	772
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
Field27	c
CPSC_CD_6	11001

Tuesday, December 14, 2004

Page 715 of 748

RQ04-011 E 1158

TECH_TXT1	REPLACE BOTH ASSYS
TECH_TXT2	
CUST_TXT	LH FRONT SEAT BELT BUCKLE WILL NOT RELEASE RH FRONT BELT BUCKLE CAME APART
AREA_CD	580
COUNTRY_CD	USA
SLS_DLR_CD	152051
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	
VIN_CD	1FMPU18L41L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TVA
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	TVZ

ID	358
MDL_YR	2001
SORT_INDEX	873
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	2/27/2001
WRTY_START_D	6/4/2001
NAME	APACHE FORD MERCURY, INC.
DOC_NUM	7701781
PH_NUM	7883333
WCC_CD	6R02
PART_NUM_CA	1L72
PART_NUM_CA	7561203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	10
CLM_KEY	7211307
MILGE	8070
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	1633
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IL
Field27	
CPSC_CD_6	11001

TECH_TXT1	BUCKLES WILL NOT LATCH REPLACE SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	
AREA_CD	815
COUNTRY_CD	USA
SLS_DLR_CD	141432
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	
VIN_CD	1FMPU18L41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/A
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	380
MDL_YR	2001
SORT_INDEX	974
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	2/28/2001
NAME	O'DANIEL FORD, INC.
DOC_NUM	073040A
PH_NUM	7480200
WCC_CD	GR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	11
CLM_KEY	6189842
MILGE	28608
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	2787
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IN
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACED DRIVERS SEATBELT BUCKLE, DID NOT LATCH PROPERLY.
TECH_TXT2	
CUST_TXT	INSTALL SOP SEATBELT PER RECALL
AREA_CD	219
COUNTRY_CD	USA
SLS_DLR_CD	140029
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L41L
LBR_COST	
VEH_LINE_CD	T/GS
MKT_DERIVED	*
BOD_CAB_STL	TVA
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	TN2

ID	381
MDL_YR	2001
SORT_INDEX	981
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/27/2000
WRTY_START_D	1/18/2001
NAME	RICHARDSON FORD
DOC_NUM	1821901
PH_NUM	7681771
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	CAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/3/2001
TIS_WSD	0
CLM_KEY	3845110
MILGE	7368
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	3768
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
Field27	
CPSC_CD_6	11001

TECH_TXT1	REPLACE SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT NOT LATCHING
AREA_CD	843
COUNTRY_CD	USA
SLS_DLR_CD	121306
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	
VIN_CD	1FMPU18L31L
LBR_COST	
VRH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAB_STL	TNA
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNZ

ID	382
MDL_YR	2001
SORT_INDEX	984
TRANS_CD	TIDE
PLANT_CD	AP
PRODN_DT	5/1/2001
WRTY_START_D	7/27/2001
NAME	LOU GRUBB FORD
DOC_NUM	2315551
PH_NUM	8913333
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7881203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/8/2001
TTS_WSD	2
CLM_KEY	3596851
MILGE	1007
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	20323
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Field7	C
CPSC_CD_6	11001

TECH_TXT1	REPLACED BOTH SEAT BELT BUCKLES POP PUT CODE
TECH_TXT2	
CUST_TXT1	CUST STATES BOTH FRONT SEAT BELTS POPP OUT WHEN DRIVING
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	17117B
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	
VIN_CD	1FMPU18L21L
LBR_COST	
VEH_LINK_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TNA
VRR_SERIES_C	TBF
DRIVE_CD	T/E
ENG_CD	T/NZ

ID	383
MDL_YR	2001
SORT_INDEX	886
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	7/16/2001
NAME	DICK BRANTMEIER FORD INC
DOC_NUM	1707301
PH_NUM	4586111
WCC_CD	BR02
PART_NUM_CA	1L7Z
PART_NUM_CA	7861203
PART_NUM_CA	BAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	0
CLM_KEY	5818503
MILGE	5167
MTRL_COST	
TOT_COST_GRO	
LBR_HRS	
DLR_CD	8107
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Field27	a
CPSC_CD_6	11001