

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 2 OF 6

BOOK 3 OF 43

TOY_COST_GRO	
LBR_HRS	
DLR_CD	3678
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	STATES SEAT BELT BUCKLE DOES NOT HOLD SEATBELT IN PASSENGER SIDE
AREA_CD	831
COUNTRY_CD	USA
SLS_DLR_CD	113488
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRI_CD	808
TIS_FLAG	

ID	53
MDL_YR	2001
SORT_INDEX	232
VIN_CD	1FTZR15E01
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	5/17/2001
WRTY_START_D	5/21/2001
NAME	SUNBURY MOTOR CO
DOC_NUM	087112A
PH_NUM	2987748
WCC_CD	0R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	1
RPR_DT	2/11/2002
TIS_WSD	8
CLM_KEY	7018852
MILGE	3686
MTRL_COST	

TOT_COST_GRO	21.97
LBR_HRS	88
DLR_CD	1426
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	INSPECTED & VERIFIED THE LATCH DID NOT OPERATE PROPERLY. REPLACED SEATBELT BUCKLE ASSEMBLY.
TECH_TXT2	
CUST_TXT	IF SEATBELT DOES NOT LATCH PROPERLY RECALL Q1S21 WAS ALREADY CHECKED AT ANOTHER DEALER?
AREA_CD	570
COUNTRY_CD	USA
SLS_DLR_CD	110577
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	54
MDL_YR	2001
SORT_INDEX	234
VIN_CD	1FTZR15E91T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/27/2001
WRTY_START_D	7/10/2001
NAME	SEXTON FORD SALES INC
DOC_NUM	4009351
PH_NUM	7973911
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/5/2001
TYS_WSD	4
CLM_KEY	5020829
MILGE	5436
MTRL_COST	

TOT_COST_GRO	1546
LBR_HRS	327
DLR_CD	20147
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IL
Ratings	
CPSC_CD_6	19001
TECH_TXT1	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	FRT SEAT BELTS WONT LATCH
AREA_CD	309
COUNTRY_CD	USA
SLS_DLR_CD	153030
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	55
MDL_YR	2001
SORT_INDEX	236
VIN_CD	1FTZR13E817
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/20/2001
WRTY_START_D	8/25/2001
NAME	JOHN ELWAY FORD DOWNTOWN
DOC_NUM	064043A
PH_NUM	3213073
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	12/12/2001
TIS_WSD	6
CLM_KEY	5773005
MILGE	0308
MTRL_COST	

TOT_COST_GRO	10852
LBR_HRS	8.7
DLR_CD	1175
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	B385 REMOVE SEAT AND REPLACE SEAT BELT
TECH_TXT2	
CUST_TXT	OK OR SEATBELT DOES NOT LATCH UNLESS YOU PUSH BUTTON IN 1 2 WAY
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	150004
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	58
MDL_YR	2001
SORT_INDEX	238
VIN_CD	1FTZR15E91T
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/10/2001
WRTY_START_D	7/13/2001
NAME	ASHE COUNTY MOTORS INC
DOC_NUM	5828303
PH_NUM	2487183
WCC_CD	6R02
PART_NUM_CA	1152
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	536
COND_CD	42
RPR_DT	4/22/2002
TIS_WSD	10
CLM_KEY	8150748
MILGE	0728
MTRL_COST	

TOT_COST_GRO	87.89
LBR_HRS	0.8
DLR_CD	803
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Ratings	
CPSC_CD_6	11001
TECH_TXT1	REMOVE SEAT REPL BUCKLE ASSY M TIME FOR SEAT REMOVAL
TECH_TXT2	
CUST_TXT	CK DRIVERS SIDE SEAT BELT WONT LATCH
AREA_CD	336
COUNTRY_CD	USA
SLS_DLR_CD	121817
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	57
MDL_YR	2001
SORT_INDEX	237
VIN_CD	1FTZR16E81T
LBR_COST	
VEH_LINE_CD	T/R3
MET_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/11/2001
WRTY_START_D	4/30/2001
NAME	BAY AREA FORD, INC.
DOC_NUM	4878853
PH_NUM	4885820
WCC_CD	GR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	4/15/2002
TIS_WSD	12
CLM_KEY	8279284
MILGE	10948
MTRL_COST	

Tuesday, December 14, 2004

Page 113 of 336

RQ04-D11 E 1588

TOT_COST_GRO	342
LBR_HRS	94
DLR_CD	3048
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	REG,REPLACE DRIVERS SEAT BELT BUCKLE INOP RETESTED
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WHEN DRIVING POPS OUT, UN LATCHES
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	182047
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	58
MDL_YR	2001
SORT_INDEX	238
VIN_CD	1FTZR15E81
LRR_COST	
VEH_LINE_CD	T/F3
MKT_DERIVED	*
BOD_CAR_STL	T/B0
VER_SERIES_C	T/F3
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/30/2001
WRTY_START_D	5/18/2001
NAME	FORD OF MANSFIELD
DOC_NUM	8865701
PH_NUM	5291800
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S26
COND_CD	42
RPR_DT	2/12/2002
TIS_WSD	10
CLM_KEY	0812422
MILGE	8707
MTRL_COST	

TOT_COST_GRO	8148
LBR_HRS	
DLR_CD	2178
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Ratings	
CPSC_CD_6	11001
TECH_TXT1	1 REMOVED PASS SEAT REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	PASS SEATBELT BUCKLE WILL NOT LATCH
AREA_CD	419
COUNTRY_CD	USA
SLS_DLR_CD	144210
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S03
TIS_FLAG	

ID	59
MDL_YR	2001
SORT_INDEX	239
VIN_CD	1FTZR16E011
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/AE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	2/22/2001
WRTY_START_D	3/8/2001
NAME	JOHNSON FORD LINC-MERC INC
DOC_NUM	8265551
PH_NUM	4438432
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S20
COND_CD	1
RPR_DT	1/24/2002
TIS_WSD	11
CLM_KEY	8496098
MILGE	16225
MTRL_COST	

TOT_COST_GRO	118.01
LBR_HRS	
DLR_CD	13111
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MA
Ratings	R
CPSC_CD_6	11001
TECH_TXT1	BROKEN SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PASS SIDE SEAT BELT BUCKLE DOES NOT LATCH REPLACE SOP BUCKLE
AREA_CD	413
COUNTRY_CD	USA
SLS_DLR_CD	148211
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	805
TIS_FLAG	

ID	00
MDL_YR	2001
SORT_INDEX	240
VIN_CD	1FTZR16E01T
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TIEF
DRIVE_CD	TIE
ENG_CD	TME
TRANS_CD	TTC
PLANT_CD	A3
PRODN_DT	3/7/2001
WRTY_START_D	4/13/2001
NAME	MILLBURY MOTOR COMPANY, INC.
DOC_NUM	37189701
PH_NUM	8326281
WCC_CD	8R02
PART_NUM_CA	1LEZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	11
CLM_KEY	7322890
MILGE	15156
MTRL_COST	

TOT_COST_GRO	16275
LBR_HRS	126
DLR_CD	8881
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MA
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	INSPECTED VEHICLE FOR CUSTOMERS CONCERN AND VERIFIED REPLACED MALFUNCTIONING SEAT BELT BUCKLE AND RE INSPECTED
TECH_TXT2	
CUST_TXT	CUSTOMER REPORTS DRIVERS SAFETY BELT DOES NOT LOCK INTO BUCKLE ALSO WARNING ALARM ON DASH BOARD IS INOPERATIVE
AREA_CD	508
COUNTRY_CD	USA
SLS_DLR_CD	111213
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	61
MDL_YR	2001
SORT_INDEX	241
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/ED
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/8/2001
WRTY_START_D	7/14/2001
NAME	BILL BARTH FORD, INC.
DOC_NUM	087485B
PH_NUM	8838584
WCC_CD	0R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/26/2001
TIS_WSD	4
CLM_KEY	4585246
MILGE	1480
MTRL_COST	

TOT_COST_GRO	9281
LBR_HRS	08
DLR_CD	9284
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	ND
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACED LEFT FRT SEAT BLET ASSY
TECH_TXT2	
CUST_TXT	LEFT FRT SEAT BELT WONT STAY LATCHED
AREA_CD	701
COUNTRY_CD	USA
SLS_DLR_CD	158499
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	02
MDL_YR	2001
SORT_INDEX	242
VIN_CD	1F7ZR15E91T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AG
PRODN_DT	1/18/2001
WRTY_START_D	4/27/2001
NAME	THOMASON FORD OF BEAVERTON
DOC_NUM	60663601
PH_NUM	B441151
WCC_CD	BRD2
PART_NUM_CA	1L6Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	11/17/2001
TIS_WSD	7
CLM_KEY	5408268
MILGE	6387
MTRL_COST	

TOT_COST_GRO	8728
LBR_HRS	8728
DLR_CD	8728
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CR
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	BROKEN SEATBELT DRIVERS SIDE TECH6840 REPLACE SEATBELT DRIVERS SIDE 60 40 SEATS
TECH_TXT2	
CUST_TXT	C 8 THAT THE DRIVERS SIDE SEAT BELT WILL NOT LATCH INSTALL SOP
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	174017
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	83
MDL_YR	2001
SORT_INDEX	248
VIN_CD	1FTZR15E91
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	12/19/2000
WRTY_START_D	1/17/2001
NAME	ANDY CLARK FORD LINC-MERC INC
DOC_NUM	051459A
PH_NUM	4282128
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	11/15/2001
TIS_WSD	11
CLM_KEY	5778138
MILGE	8742
MTRL_COST	

TOT_COST_GRO	88.10
LBR_HRS	0.2
DLR_CD	2061
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WV
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	REPLACE RIGHT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	CHECK PASS SEAT BELT STAY LATCHED
AREA_CD	304
COUNTRY_CD	USA
SLS_DLR_CD	147945
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	84
MDL_YR	2004
SORT_INDEX	250
VIN_CD	1FTZR15E91T
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	TR3
VER_SERIES_C	TIE
DRIVE_CD	TIE
ENG_CD	TIE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	11/28/2000
WRTY_START_D	11/10/2001
NAME	PLAZA FORD
DOC_NUM	3622404
PH_NUM	9221060
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	1/17/2002
TIS_WSD	3
CLM_KEY	6368112
MILGE	7826
MTRL_COST	

TOT_COST_GRO	128.78
LBR_HRS	30.4
DLR_CD	20574
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
Rating	a
CPSC_CD_6	11001
TECH_TXT1	REMOVE RIGHT SIDE SEAT AND REPLACE SEAT BELT. WILL NOT LOCK.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES RIGHT SIDE SEAT BELT WILL NOT LOCK.
AREA_CD	732
COUNTRY_CD	USA
SLS_DLR_CD	113488
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	85
MDL_YR	2001
SORT_INDEX	263
VIN_CD	1FTZR15E91P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	7/18/2001
WRTY_START_D	9/8/2001
NAME	BRAEGER FORD, INC.
DOC_NUM	0894708
PH_NUM	2818100
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	540
COND_CD	89
RPR_DT	10/15/2001
TIS_WSD	2
CLM_KEY	4845033
MILGE	2102
MTRL_COST	

TOT_COST_GRO	142.84
LBR_HRS	1.3
DLR_CD	1753
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VI
Ratings	#
CPSC_CD_6	11001
TECH_TXT1	MT EQUALS TIME TO REPLACE SEATBELT BUCKLE DRIVERS SIDE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT SEATBELT DOESNT ALWAYS LATCH
AREA_CD	414
COUNTRY_CD	USA
SLS_DLR_CD	141032
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	908
TIS_FLAG	

ID	68
MDL_YR	2001
SORT_INDEX	268
VIN_CD	1FTZR15E81F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/18/2001
WRTY_START_D	6/30/2001
NAME	SARASOTA FCRD
DOC_NUM	3067862
PH_NUM	3663673
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	2/28/2002
TIS_WSD	10
CLM_KEY	7071573
MILGE	10191
MTRL_COST	

TOT_COST_GRO	8343
LAB_HRS	624
DLR_CD	1167
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Ratings	A
CPSC_CD_6	11001
TECH_TXT1	WILL NOT SECURE SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUST STATES THE PASS SEATBELT WILL NOT SECURE.
AREA_CD	941
COUNTRY_CD	USA
SLS_DLR_CD	124402
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	67
MDL_YR	2001
SORT_INDEX	288
VIN_CD	1FTZR15E81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/4/2001
WRTY_START_D	8/8/2001
NAME	PRICE-GNADE FORD MERCURY, INC.
DOC_NUM	4388404
PH_NUM	5288252
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1051203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	5
CLM_KEY	6115221
MILGE	14891
MTRL_COST	

TOY_COST_GRO	89.7
LBR_HRS	
DLR_CD	2845
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Ratings	
CPSC_CD_6	11001
TECH_TXT1	1 CHECK FOR DRIVERS SEATBELT BUCKLE WILL NOT HOLD LATCH AT TIMES. VERIFIED CONCERN. INSTALLED NEW BUCKLE AND VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVES SEAT BELT WILL NOT LOCK AT TIMES
AREA_CD	638
COUNTRY_CD	USA
SLS_DLR_CD	163341
TXN_CD	ES4
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	

ID	68
MDL_YR	2001
SORT_INDEX	270
VIN_CD	1FTZR15E9M1
LRR_COST	6900
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/2/2001
WRTY_START_D	8/17/2001
NAME	FIVE STAR FORD-LINCOLN-MERCURY
DOC_NUM	8517003
PH_NUM	5333873
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/22/2001
TIS_WSD	5
CLM_KEY	8587902
MILGE	7192
MTRL_COST	

TOT_COST_GRO	111.98
LBR_HRS	0.00
DLR_CD	1358
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	DEFECTIVE LATCH ORDERED PARTS CONFIRM REMOVE DRIVERS SIDE SEAT, AND IN TIME TO REPLACE SEATBELT BUCKLE, AND CHECK, OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT THE DRIVERS SIDE FRONT SEATBELT WOULD NOT LATCH IN RECEIVER, REPORT
AREA_CD	380
COUNTRY_CD	USA
SLS_DLR_CD	174494
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	09
MDL_YR	2001
SORT_INDEX	277
VIN_CD	1F1ZR15E81F
LBR_COST	
VEH_LINE_CD	TFG
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/4/2001
WRTY_START_D	6/13/2001
NAME	BERGSTROM FORD LINCOLN MERCURY
DOC_NUM	7245102
PH_NUM	3863873
WCC_CD	8R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	11/20/2001
TIS_WSD	8
CLM_KEY	5686368
MILGE	5204
MTRL_COST	

TOY_COST_GRO	9872
LBR_HRS	34
DLR_CD	9847
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Rating	C
CPSC_CD_6	11001
TECH_TXT1	TEST BUCKLE, PASS SIDE FAILURE REPLACE PASSENGER SEAT BELT
TECH_TXT2	
CUST_TXT	PASSENGER SEAT BELT UNBUCKLES BY ITSELF.
AREA_CD	715
COUNTRY_CD	USA
SLS_DLR_CD	141183
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	70
MDL_YR	2001
SORT_INDEX	282
VIN_CD	1FTZR15E91F
LBR_COST	26.38
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/B0
VER_SERIES_C	T/F
DRIVE_CD	T/E
ENG_CD	T/AE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	11/30/2000
WRTY_START_D	2/28/2001
NAME	LAKE ELSDORE FORD, INC.
DOC_NUM	1357290
PH_NUM	4711405
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	1
RPR_DT	12/5/2001
TIS_WSD	10
CLM_KEY	6578880
MILGE	84280
MTRL_COST	

TOT_COST_GRO	154.38
LBR_HRS	1.3
DLR_CD	3814
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	34280 01S21Q 1.3 REPLACED RF BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES PASS SIDE SEAT BELT WILL POP OUT OF BUCKLE AT TIMES
AREA_CD	908
COUNTRY_CD	USA
SLS_DLR_CD	171156
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	71
MDL_YR	2001
SORT_INDEX	285
VIN_CD	1FTZR15E81
LRR_COST	1054
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T8D
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	11/8/2000
WRTY_START_D	12/29/2000
NAME	VIRGOA FORD
DOC_NUM	290001
PH_NUM	6372145
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S46
COND_CD	1
RPR_DT	11/21/2001
TIS_WSD	11
CLM_KEY	5527406
MILGE	5339
MTRL_COST	

TOT_COST_GRO	7741
LBR_HRS	04
DLR_CD	8245
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WI
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	VERIFY CONCERN REMOVE AND REPLACE LH SEATBELT
TECH_TXT2	
CUST_TXT	LH SEATBELT KEEPS COMING UNHOOKED
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	158448
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S05
TIS_FLAG	

ID	72
MDL_YR	2001
SORT_INDEX	288
VIN_CD	1FTZR15E81P
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/ED
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	11/8/2000
WRTY_START_D	12/29/2000
NAME	VIROQUA FORD
DOC_NUM	2888001
PH_NUM	6372145
WCC_CD	GR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	12/8/2001
TIS_WSD	12
CLM_KEY	6727380
MILGE	6879
MTRL_COST	

TOT_COST_GRO	7241
LBR_HRS	04
DLR_CD	6245
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	VERIFY CONCERN REMOVE AND REPLACE RH SEATBELT ASSY
TECH_TXT2	
CUST_TXT	RH SEATBELT DOES NOT STAY BUCKLED
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	158448
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	73
MDL_YR	2001
SORT_INDEX	288
VIN_CD	1FTZR15E91F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	10/20/2000
WRTY_START_D	3/3/2001
NAME	WICKSTROM FORD, INC.
DOC_NUM	043414A
PH_NUM	3818850
WCC_CD	B/R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1D8120S
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	6
CLM_KEY	3017891
MILGE	3581
MTRL_COST	

TOT_COST_GRO	287.34
LBR_HRS	1.5
DLR_CD	1587
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IL
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEAT BELT
TECH_TXT2	
CUST_TXT	CHECK SEAT BELTS WAS IN ACCIDENT????
AREA_CD	047
COUNTRY_CD	USA
SLS_DLR_CD	141081
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	74
MDL_YR	2001
SORT_INDEX	295
VIN_CD	1FTZR16E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	T/NE
TRANS_CD	T/8C
PLANT_CD	AG
PRODN_DT	4/18/2001
WRTY_START_D	5/10/2001
NAME	HERITAGE FORD
DOC_NUM	359841B
PH_NUM	8858100
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S26
COND_CD	42
RPR_DT	6/7/2002
TIS_WSD	13
CLM_KEY	6128188
MILGE	34018
MTRL_COST	

TOT_COST_GRO	5123
LBR_HRS	02
DLR_CD	9178
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VT
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	VERIFY CONCERN LEFT FRONT SEATBELT NOT STAYING LATCHED. REPLACED FEMALE END OF SEATBELT, RETEST. CONCERN REPAIRED.
TECH_TXT2	
CUST_TXT	C'S LEFT FRONT SEAT BELT WILL COME UNBUCKLED WHILE DRIVING
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	111632
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	Ⓢ

ID	75
MDL_YR	2001
SORT_INDEX	300
VIN_CD	1FTZR15E81
LRR_COST	
VEH_LINE_CD	T/RS
MKT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	8/19/2001
NAME	ATCHLEY FORD INC
DOC_NUM	22810901
PH_NUM	6718801
WCC_CD	8R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/8/2001
TIS_WSD	8
CLM_KEY	5813829
MILGE	7686
MTRL_COST	

TOT_COST_GRO	84.48
LRR_HRS	0.4
DLR_CD	7130
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NE
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	TEST AND R&I PASSENGER SEAT, REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST SAYS PASSENGER SIDE SEATBELT WILL COME UNBUCKLED WHILE DRIVING
AREA_CD	402
COUNTRY_CD	USA
SLS_DLR_CD	158022
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	78
MDL_YR	2001
SORT_INDEX	301
VIN_CD	1FTZR18E81
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TIEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	4/2/2001
WRTY_START_D	6/26/2001
NAME	RAY VILES FORD, LLC
DOC_NUM	8308751
PH_NUM	4570704
WCC_CD	9R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	L28
COND_CD	42
RPR_DT	9/21/2001
TIS_WSD	4
CLM_KEY	3862980
MILGE	1308
MTRL_COST	

TOT_COST_GRO	199.74
LBR_HRS	1.8
DLR_CD	6823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
Ratings	"
CPSC_CD_6	11001
TECH_TXT1	PERFORMED RECALL
TECH_TXT2	
CUST_TXT	01S21 SEAT BELT
AREA_CD	885
COUNTRY_CD	USA
SLS_DLR_CD	121686
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V77
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	77
MDL_YR	2001
SORT_INDEX	303
VIN_CD	1FTZR16E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/BD
VKR_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/6/2001
WRTY_START_D	8/11/2001
NAME	LARRY MILLER FORD LINCOLN MERC
DOC_NUM	18810802
PH_NUM	464000
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	4/5/2002
TIS_WSD	8
CLM_KEY	7980107
MILGE	7272
MTRL_COST	

TOT_COST_GRO	7538
LBR_HRS	98
DLR_CD	8341
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	ID
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	USED SPECIAL TOOL TO FIND THAT SEAT BELTS DID NOT PASS STANDARD REPLACED BOTH SEAT BELTS
TECH_TXT2	
CUST_TXT	CUST SAYS THAT PASS SIDE SEAT BELT COMES UNDONE INTER.
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	158585
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	78
MDL_YR	2001
SORT_INDEX	306
VIN_CD	1FTZR16E81T
LRR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	12/7/2000
WRTY_START_D	8/13/2001
NAME	VICTORY FORD MERCURY, INC.
DOC_NUM	6383505
PH_NUM	8517085
WCC_CD	BR02
PART_NUM_CA	1L8Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	928
COND_CD	42
RPR_DT	5/2/2002
TIS_WSD	8
CLM_KEY	B401394
MILGE	18120
MTRL_COST	

TOT_COST_GRO	8388
LRR_HRS	0.2
DLR_CD	3078
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	
CPSC_CD_6	11001
TECH_TXT1	VARIFIED CONCERN, DRIVERS SEAT BELT BUCKLE WON LATCH. REMOVED DRIVERS SEAT AND SEATBELT BUCKLE AND REPLACED BUCKLE. INSTALLED SEAT. SEATBELT BUCKLE WORKS FINE NOW.
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT WILL NOT BUCKLE
AREA_CD	517
COUNTRY_CD	USA
SLS_DLR_CD	148517
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	79
MDL_YR	2001
SORT_INDEX	307
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/RS
MKT_DERIVED	*
BOD_CAB_STL	T/RS
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	11/29/2000
WRTY_START_D	8/27/2001
NAME	TRU MOTOR SALES INC
DOC_NUM	032176B
PH_NUM	8962931
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	5/8/2002
TIS_WSD	14
CLM_KEY	8481854
MILGE	10581
MTRL_COST	

TOI_COST_GRO	14757
LBR_HRS	0.6
DLR_CD	2897
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Ratings	
CPSC_CD_6	11001
TECH_TXT1	CHECK OUT AND REPLACE BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	FRONT SEATBELT BUCKLES ARE HARD TO LATCH
AREA_CD	419
COUNTRY_CD	USA
SLS_DLR_CD	148055
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	B08
TYS_FLAG	

ID	BC
MDL_YR	2001
SORT_INDEX	306
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/R8
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AG
PRODN_DT	11/22/2000
WRTY_START_D	11/30/2000
NAME	CLASSIC FORD MERCURY OF CHARDO
DOC_NUM	5720801
PH_NUM	2807131
WCC_CD	8R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	B25
COND_CD	41
RPR_DT	9/27/2001
TIS_WSD	11
CLM_KEY	4105207
MILGE	17757
MTRL_COST	

TOT_COST_GRO	8248
LBR_HRS	0.8
DLR_CD	2200
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Rating	
CPSC_CD_6	11001
TECH_TXT1	SEATBELT WILL NOT OPERATE HAD TO REMOVE SEAT TO REPLACE RT. SEAT BELT. REPLACED SEAT BELT.
TECH_TXT2	
CUST_TXT	RIGHT SEAT BELT SOP FAILED TEST
AREA_CD	216
COUNTRY_CD	USA
SLS_DLR_CD	144128
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S00
TIS_FLAG	

ID	01
MDL_YR	2001
SORT_INDEX	313
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AG
PRODN_DT	10/18/2000
WRTY_START_D	11/16/2000
NAME	CLARION FORD-MERCURY
DOC_NUM	7071801
PH_NUM	2287440
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	6/5/2002
TIS_WSD	18
CLM_KEY	8073232
MILGE	16012
MTRL_COST	

TOT_COST_GRO	7582
LBR_HRS	964
DLR_CD	7450
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Ratings	■
CPSC_CD_6	11001
TECH_TXT1	FOUND BELT BUCKLE WOULD NOT LATCH R1 FRT DRIVERS SEAT AND REPLACE LT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LT BELT BUCKLE WILL NOT LATCH
AREA_CD	B14
COUNTRY_CD	USA
SLS_DLR_CD	144470
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TES_FLAG	Ⓢ

ID	82
MDL_YR	2001
SORT_INDEX	321
VIN_CD	1FTZR15E01P
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/M
TRANS_CD	T/T
PLANT_CD	AX
PRODN_DT	4/18/2001
WRTY_START_D	6/15/2001
NAME	JOHN DEOSKY FORD, INC.
DOC_NUM	2251001
PH_NUM	8220001
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/8/2002
TIS_WSD	8
CLM_KEY	0788701
MILGE	1804
MTRL_COST	

TOT_COST_GRO	77.86
LBR_HRS	4.4
DLR_CD	3555
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEAT BELT ON PASS SIDE WONT HOLD
TECH_TXT2	
CUST_TXT	CK PASSSIDE SEAT BELT BUCKLE WONT HOLD
AREA_CD	740
COUNTRY_CD	USA
SLS_DLR_CD	147045
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	B05
TIS_FLAG	

ID	83
MDL_YR	2001
SORT_INDEX	323
VIN_CD	1FTZR15E81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	4/28/2001
NAME	GLACIER VALLEY FORD/MERC INC
DOC_NUM	35880403
PH_NUM	3582222
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/12/2001
TIS_WSD	6
CLM_KEY	6843224
MILGE	6848
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	6370
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
Ratings	D
CPSC_CD_6	11001
TECH_TXT1	REPLACED PASS SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	PASS SIDE SEAT BELT DOESNT STAY BUCKLED
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	141102
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	84
MDL_YR	2001
SORT_INDEX	325
VIN_CD	1FTZR16E81F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	3/21/2001
WRTY_START_D	7/31/2001
NAME	BILL-TERHAR MOTORS, INC.
DOC_NUM	6781551
PH_NUM	4691801
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061208
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	1/3/2002
TIS_WSD	6
CLM_KEY	6038966
MILGE	3218
MTRL_COST	