

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 3 OF 6

BOOK 3 OF 43

TOT_COST_GRO	0182
LBR_HRS	
DLR_CD	3297
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Ratings	
CPSC_CD_6	11001
TECH_TXT1	BUCKLE BAD R AND R DRIVER SEAT BUCKLE
TECH_TXT2	
CUST_TX1	RECEIVER PART OF SEAT BELT WILL NOT ACCEPT BUCKLE DRIVERS SIDE
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	156012
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	88
MDL_YR	2001
SORT_INDEX	331
VIN_CD	1F7ZR15E81P
LBR_COST	
VEH_LINE_CD	T/R9
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	2/14/2001
WRTY_START_D	4/19/2001
NAME	ATCHINSON FORD SALES INC
DOC_NUM	15818303
PH_NUM	6879181
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	B40
COND_CD	42
RPR_DT	2/15/2002
TIS_WSD	11
CLM_KEY	6894834
MILGE	28508
MTRL_COST	

TOT_COST_GRO	0138
LBR_HRS	0.35
DLR_CD	2731
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	#
CPSC_CD_6	11001
TECH_TXT1	MT TIME TO REPLACE DRIVER SIDE SEAT BELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT DOES NOT CLICK AND LOCK S40
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	148400
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	608
TIS_FLAG	

ID	88
MDL_YR	2001
SORT_INDEX	383
VIN_CD	1FTZR15E81P
LBR_COST	
VEH_LINE_CD	TFS
MKT_DERIVED	*
BOD_CAB_STL	TED
VER_SERIES_C	TIEF
DRIVE_CD	TIE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AX
PRODN_DT	4/12/2001
WRTY_START_D	5/21/2001
NAME	TEAM FORD
DOC_NUM	4520161
PH_NUM	3855100
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	9/29/2001
TIS_WSD	5
CLM_KEY	4813241
MILGE	6365
MTRL_COST	

TOT_COST_GRO	8344
LBR_HRS	9.4
DLR_CD	9916
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NV
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	RECALL 01821
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE PASSENGER SIDE SEAT BELT RELEASES WHILE DRIVING
AREA_CD	702
COUNTRY_CD	USA
SLS_DLR_CD	171170
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	505
TIS_FLAG	

ID	87
MDL_YR	2001
SORT_INDEX	334
VIN_CD	1FTZR15E81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/R0
VEH_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	4/10/2001
WRTY_START_D	10/1/2001
NAME	TOWN & COUNTRY FORD L-M, INC.
DOC_NUM	041807A
PH_NUM	5890083
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	925
COND_CD	41
RPR_DT	4/25/2002
TIS_WSD	7
CLM_KEY	8280031
MILGE	5858
MTRL_COST	

TOT_COST_GRO	81.58
LBR_HRS	0.4
DLR_CD	3247
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Ratings	6
CPSC_CD_6	11001
TECH_TXT1	REMOVED AND REPLACED PASSENGER SEATBELT BUCKLE ASSEMBLY REMOVED SEAT TO REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	CHECK PASSENGER SEAT BELT WONT LOCK
AREA_CD	719
COUNTRY_CD	USA
SLS_DLR_CD	150008
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	88
MDL_YR	2001
SORT_INDEX	335
VIN_CD	1FTZR15E81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/9/2001
WRTY_START_D	8/14/2001
NAME	FRIENDLY FORD, INC.
DOC_NUM	222746A
PH_NUM	8834330
WCC_CD	8RD2
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	528
COND_CD	42
RPR_DT	3/19/2002
TIS_WSD	8
CLM_KEY	7500758
MILGE	5508
MTRL_COST	

TOT_COST_GRO	148.82
LBR_HRS	1.3
DLR_CD	6017
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	5700 1061202 BUCKLE 42 DNOP CHECK PASS FRONT SEATBELT OPERATION, WILL NOT LATCH. R&I RF SEAT (80 40) TO REPLACE SEAT BELT LATCH, BUCKLE ASSEMBLY. (HAS PRE TENSIONER) RE TEST, WORKING PROPERLY AFTE
TECH_TXT2	R REPAIR.
CUST_TXT	SEAT BELT BUCKLE LATCHING TROUBLES C S PASS SEAT BELT WILL NOT LATCH, SOP PART HERE
AREA_CD	417
COUNTRY_CD	USA
SLS_DLR_CD	153480
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	

ID	89
MDL_YR	2001
SORT_INDEX	338
VIN_CD	1FTZR15E81F
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/10/2001
WRTY_START_D	6/2/2001
NAME	BIG VALLEY FORD
DOC_NUM	42815202
PH_NUM	8704400
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/11/2002
TIS_WSD	10
CLM_KEY	8850198
MILGE	20480
MTRL_COST	

TOT_COST_GRO	8258
LBR_HRS	00
DLR_CD	7742
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	VERIFIED THE R F SEATBELT DISINGAGES. REMOVE AND REPLACE THE R F SEATBELT ASY, RECHECK OK.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE RIGHT FRONT SEATBELT DISINGAGES WHILE DRIVING. CUST STATES IT WAS CHANGED FOR RECALL AND STILL
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	172402
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TTS_FLAG	

ID	00
MDL_YR	2001
SORT_INDEX	342
VIN_CD	1FTZR1BE61P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAR_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	11/8/2000
WRTY_START_D	0/19/2001
NAME	SOUTHWEST FORD INC
DOC_NUM	19979408
PH_NUM	5985700
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1091202
PART_NUM_CA	AAA
CUST_CONC_C	625
COND_CD	42
RPR_DT	4/16/2002
TIS_WSD	11
CLM_KEY	0154708
MILGE	8488
MTRL_COST	

Tuesday, December 14, 2004

Page 179 of 550

RQ04-011 E 1654

TOT_COST_GRO	102.47
LBR_HRS	65
DLR_CD	2448
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	VERIFY CONCERN, PASS SEAT BELT BUCKLE DOES NOT STAY CLIPED. REMOVED PASS BEAT, REPLACED PASS SEAT BELT BUCKLE. REINSTALLED SEAT.
TECH_TXT2	
CUST_TXT	826 CUSTOMER STATES THE PASSENGER FRONT SEAT BELT COMES UNBUCKLED.
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	152408
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TTS_FLAG	

ID	91
MDL_YR	2001
SORT_INDEX	345
VIN_CD	1FTZR18E81P
LBR_COST	
VEH_LINE_CD	T7R3
MKT_DERIVED	*
BOD_CAB_STL	T7SD
VER_SERIES_C	T7EF
DRIVE_CD	T7E
ENG_CD	T7NE
TRANS_CD	T7TC
PLANT_CD	AX
PRODN_DT	11/8/2000
WRTY_START_D	1/1/2001
NAME	BILL COLLINS FORD INC
DOC_NUM	28347702
PH_NUM	4699660
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	640
COND_CD	42
RPR_DT	1/22/2002
TIS_WSD	13
CLM_KEY	6461178
MILGE	10640
MTRL_COST	

TOT_COST_GRO	182.45
LBR_HRS	0.7
DLR_CD	5885
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KY
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	R R SEAT TO GAIN SEAT BELT BUCKLE BOLT REPLACED RIGHT SEAT B BELT BUCKLE
TECH_TXT2	
CUST_TXT	PASSENGER SEAT BELT UNBUCKLES AT TIME WHEN IN USE NO PATTERN
AREA_CD	602
COUNTRY_CD	USA
SLS_DLR_CD	147022
TXN_CD	ES4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VET_CD	S06
TIS_FLAG	

ID	92
MDL_YR	2001
SORT_INDEX	348
VIN_CD	1FTZR19E81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	10/25/2000
WRTY_START_D	1/20/2000
NAME	HANSEL FORD LINCOLN MERCURY
DOC_NUM	8889281
PH_NUM	5437300
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	12/13/2001
TIS_WSD	13
CLM_KEY	8726432
MILGE	13210
MTRL_COST	

TOT_COST_GRO	82-79
LBR_HRS	04
DLR_CD	7894
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	BUCKLE INSPECTED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEATBELT POFS LOOSE WHILE DRIVING
AREA_CD	707
COUNTRY_CD	USA
SLS_DLR_CD	172417
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRY_CD	908
TIS_FLAG	

ID	93
MDL_YR	2001
SORT_INDEX	359
VIN_CD	1FTZR15E711
LBR_COST	
VEH_LINE_CD	T7R3
MKT_DERIVED	*
BOD_CAB_STL	T7B0
VER_SERIES_C	T7E
DRIVE_CD	T7E
ENG_CD	T7E
TRANS_CD	T7B0
PLANT_CD	AG
PRODN_DT	4/23/2001
WRTY_START_D	5/9/2001
NAME	SOUTH POINT FORD
DOC_NUM	2815302
PH_NUM	8843873
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RFR_DT	11/30/2001
TIS_WSD	7
CLM_KEY	6871475
MILGE	4826
MTRL_COST	

TOT_COST_GRO	13054
LBR_HRS	24
DLR_CD	7551
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	BROKEN PERFORMED DIAG, CHECKED AND FOUND PASS FRONT SEAT BELT BUCKLE WILL NOT RELEASE, REMOVED PASS SEAT AND INSTALLED
TECH_TXT2	
CUST_TXT	CUST STATES THE PASSENGER SEAT BELT BUCKLES POPS LOOSE
AREA_CD	740
COUNTRY_CD	USA
SLS_DLR_CD	147428
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S00
TIS_FLAG	

ID	94
MDL_YR	2001
SORT_INDEX	360
VIN_CD	1FTZR15E71
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/8/2001
WRTY_START_D	4/25/2001
NAME	LEARN FORD INC
DOC_NUM	10015201
PH_NUM	2687113
WCC_CD	BF02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/29/2002
TIS_WSD	10
CLM_KEY	0565894
MILGE	10908
MTRL_COST	

TOT_COST_GRO	86.88
LBR_HRS	0.8
DLR_CD	582
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
Ratings	0
CPSC_CD_6	14001
TECH_TXT1	REPLACE SEAT BELT LATCH ASSY.
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEAT BELT WONT STAY LATCHED.
AREA_CD	B14
COUNTRY_CD	USA
SLS_DLR_CD	118838
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	95
MDL_YR	2001
SORT_INDEX	352
VIN_CD	1FTZR15E71
LRR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	
BOD_CAR_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	3/23/2001
WRTY_START_D	5/5/2001
NAME	FRANKLIN AUTO INC
DOC_NUM	500801
PH_NUM	4373044
WCC_CD	BRD2
PART_NUM_CA	1LEZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	4/12/2002
TIS_WSD	12
CLM_KEY	8311833
MILGE	15878
MTRL_COST	

TOT_COST_GRO	12583
LBR_HRS	
DLR_CD	2253
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
Ratings	
CPSC_CD_6	11001
TECH_TXT1	REPLACE PASSENGER SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PASSENGER SIDE SEATBELT BUCKLE WILL NOT LATCH
AREA_CD	B14
COUNTRY_CD	USA
SLS_DLR_CD	144443
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	B08
TIS_FLAG	

ID	86
MDL_YR	2001
SORT_INDEX	903
VIN_CD	1FTZR15E71T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/8/2001
WRTY_START_D	5/26/2001
NAME	BURT PAQUIN FORD, INC.
DOC_NUM	362601
PH_NUM	5247343
WCC_CD	0R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/28/2001
TIS_WSD	E
CLM_KEY	4580528
MILGE	4364
MTRL_COST	

TOT_COST_GRO	134.83
LBR_HRS	34
DLR_CD	8941
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VT
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	RECALL #01521 REPLACE RIGHT SIDE SEAT BELT BUCKLE LEFT SIDE PASS INSPECTION
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE SEAT BELTS DO NOT WORK PROPERLY. FAILED RECALL 01521, INSTALL S O RIGHT SEAT BELT BUCKLE
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	111519
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	97
MDL_YR	2001
SORT_INDEX	385
VIN_CD	1F1ZR16E71T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/12/2001
WRTY_START_D	5/18/2001
NAME	QUALITY FORD OF W. DES MOINES,
DOC_NUM	1258361
PH_NUM	2231580
WCC_CD	8F02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	7/17/2001
TIS_WSD	2
CLM_KEY	2420719
MILGE	4771
MTBL_COST	

TOT_COST_GRO	8908
LBR_HRS	094
DLR_CD	7188
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IA
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	STICKING SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	INSTALL SO DRIVERS SEAT BELT BUCKLE COMES UNDONE WHILE DRIVING
AREA_CD	615
COUNTRY_CD	USA
SLS_DLR_CD	153030
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	88
MDL_YR	2001
SORT_INDEX	388
VIN_CD	1FTZR15E71T
LBR_COST	
VEH_LINE_CD	T/RS
MKT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/10/2001
WRTY_START_D	5/31/2001
NAME	JACK DEMMER FORD, INC.
DOC_NUM	250199A
PH_NUM	7212800
WCC_CD	6RD2
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	640
COND_CD	41
RPR_DT	8/2/2001
TIS_WSD	3
CLM_KEY	2778838
MILGE	2101
MTRL_COST	

TOT_COST_GRO	123
LBR_HRS	02
DLR_CD	2771
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	2161 REPLACED PASS SIDE FRONT SEATBELT BUCKLE, WOULD NOT LATCH.
TECH_TXT2	
CUST_TXT	PASS FRONT SEAT BELT WILL NOT STAY BUCKLED.PART HERE NOW,WAS ORDERED PREVIOUSLY
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	148016
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	B08
TIS_FLAG	

ID	99
MDL_YR	2001
SORT_INDEX	387
VIN_CD	1FTZR15E71
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AG
PRODN_DT	4/6/2001
WRTY_START_D	6/30/2001
NAME	BURT'S ARAPAHOE FORD, INC.
DOC_NUM	384286C
PH_NUM	6438000
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	B50
COND_CD	42
RPR_DT	1/29/2002
TIS_WSD	8
CLM_KEY	0572867
MILGR	5067
MTRL_COST	

TOT_COST_GRO	85.12
LBR_HRS	0.4
DLR_CD	3188
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GO
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REMOVED RIGHT FRT. SEAT TO REPLACE SEAT BELT BUCKLE ASSEMBLY AS IT WOULD NOT STAY LATCHED AT TIMES
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE PASSENGER SEAT BELT WONT STAY LATCHED(RECALL PREVIOUSLY PERFORMED)
AREA_CD	309
COUNTRY_CD	USA
SLS_DLR_CD	196001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	100
MDL_YR	2001
SORT_INDEX	388
VIN_CD	1FTZR15E71T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAR_STL	T/B0
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/5/2001
WRTY_START_D	5/25/2001
NAME	MANKATO FORD, INC.
DOC_NUM	8332352
PH_NUM	3873454
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	10/18/2001
TIS_WSD	5
CLM_KEY	4640233
MILGE	8048
MTRL_COST	

Tuesday, December 14, 2004

Page 199 of 538

RQ04-011 E 1574

TOT_COST_GRO	81.88
LBR_HRS	0.3
DLR_CD	1767
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	RIGHT FRONT SEAT BELT BAD ADD ON
TECH_TXT2	
CUST_TXT	CHECK PASSENGER FRONT SEAT BELT IT DOESNT HOLD
AREA_CD	507
COUNTRY_CD	USA
SLS_DLR_CD	168601
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	G21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	101
MDL_YR	2001
SORT_INDEX	388
VIN_CD	1FTZR15E71T
LBR_COST	
VEH_LINE_CD	TRQ
MKT_DERIVED	
BOD_CAB_STL	T7BD
VER_SERIES_C	T7EF
DRIVE_CD	T7E
ENG_CD	T7NE
TRANS_CD	T7TC
PLANT_CD	AG
PRODN_DT	4/3/2001
WRTY_START_D	3/4/2002
NAME	SALE FORD
DOC_NUM	2474101
PH_NUM	33235
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	T90
COND_CD	42
RPR_DT	6/30/2002
TIS_WSD	2
CLM_KEY	8820283
MILGE	2514
MTRL_COST	

TOT_COST_GRO	81.4
LBR_HRS	04
DLR_CD	6325
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	FOUND THE LATCH FAULTY REPLACED THE SEATBELT LATCH ASSY AND VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT THE PASS SEAT BELT WILL COME UNLATCHED WHILE DRIVING
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	121436
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	R1
VRT_CD	808
FIS_FLAG	@

ID	102
MDL_YR	2001
SORT_INDEX	370
VIN_CD	1FTZR15E71T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	8/18/2001
NAME	CELLA FORD, INC.
DOC_NUM	0842740
PH_NUM	6384011
WCC_CD	6R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	3/18/2002
TIS_WSD	10
CLM_KEY	7503286
MILGE	6419
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	6879
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	R&R PASSENGER SIDE SEAT BELT AND BUCKLE ASSEMBLY.
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEAT BELT KEEPS COMING UNBUCKLE ..
AREA_CD	252
COUNTRY_CD	USA
SLS_DLR_CD	121646
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	103
MDL_YR	2001
SORT_INDEX	371
VIN_CD	1FTZR16E71T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	8/16/2001
NAME	CELLA FORD, INC.
DOC_NUM	0658793
PH_NUM	6384011
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1091202
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	6/7/2002
TIS_WSD	11
CLM_KEY	8489129
MILGE	8065
MTRL_COST	

TOT_COST_GRO	110174
LBR_HRS	
DLR_CD	8878
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	R/R PASSENGER SIDE SEAT AND SEAT COVER, REPLACED FAULTY SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEAT RELEASES WHILE DRIVING ..
AREA_CD	282
COUNTRY_CD	USA
SLS_DLR_CD	121848
TXN_CD	E95
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	104
MDL_YR	2001
SORT_INDEX	375
VIN_CD	1FTZR1SE71T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	11/8/2000
WRTY_START_D	12/1/2000
NAME	BILL BROWN FORD INC
DOC_NUM	30168901
PH_NUM	4217000
WCC_CD	BR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/16/2001
TIS_WSD	12
CLM_KEY	5395035
MILGE	12024
MTRL_COST	

TOT_COST_GRO	128.4
LBR_HRS	1
DLR_CD	3003
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Reflags	b
CPSC_CD_6	11001
TECH_TXT1	
TECH_TXT2	
CUST_TXT	CK/ADV PASS SIDE SEAT BUCKLE WONT STAY LATCHED 40
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	14B032
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	105
MDL_YR	2001
SORT_INDEX	381
VIN_CD	1FTZR15E71F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	7/26/2001
WRTY_START_D	8/3/2001
NAME	FRIENDLY FORD, INC.
DOC_NUM	214582A
PH_NUM	8834330
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	526
COND_CD	42
RPR_DT	11/30/2001
TIS_WSD	4
CLM_KEY	5400541
MILGE	5680
MTRL_COST	

TOT_COST_GRO	99.38
LBR_HRS	0.7
DLR_CD	5017
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MD
Ratings	"
CPSC_CD_6	11001
TECH_TXT1	5889 61202 BUCKLE, 42 DNOP VERIFIED CONCERN OF PASS FRONT SEAT BELT NOT LATCHING PROPERLY. REMOVED PASS FRONT BUCKET SEAT AND REPLACED PRETENSIONED SEAT BELT BUCKLE REASSEMBLED VEHICLE AND VERIFIED
TECH_TXT2	PROPER OPERATION AFTER REPAIR.
CUST_TXT	C S PASS FRONT SEAT BELT WILL NOT LATCH SOMETIMES OK . . .
AREA_CD	417
COUNTRY_CD	USA
SLS_DLR_CD	153480
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	108
MDL_YR	2001
SORT_INDEX	385
VIN_CD	1FTZR15E71F
LRR_COST	
VEH_LINE_CD	TFC
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AX
PRODN_DT	5/17/2001
WRTY_START_D	8/22/2001
NAME	ST. PETER FORD, INC
DOC_NUM	102818A
PH_NUM	8311820
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	1/25/2002
TIS_WSD	6
CLM_KEY	0758254
MILGE	3388
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	2870
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	
CPSC_CD_6	11001
TECH_TXT1	REMOVE PASSENGER SEAT, REMOVE PART OF COVER TO EXPOSE BOLT, REMOVE BOLT AND BUCKLE ASSY, INSTALL NEW BUCKLE ASSY, TEST OK
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE LATCHING TROUBLES
AREA_CD	507
COUNTRY_CD	USA
SLS_DLR_CD	168897
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	107
MDL_YR	2001
SORT_INDEX	303
VIN_CD	1FTZR16E71F
LRR_COST	
VEH_LINE_CD	T/F3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/F
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/12/2001
WRTY_START_D	3/27/2001
NAME	BAY AREA FORD, INC.
DOC_NUM	4851932
PH_NUM	4885820
WCC_CD	B/R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	4/24/2002
TIS_WSD	14
CLM_KEY	B248120
MILGE	22675
MTRL_COST	

TOI_COST_GRO	842
LBR_HRS	84
DLR_CD	3045
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
Ratings	G
CPSC_CD_6	11001
TECH_TXT1	R I PASS SEAT TO REPLACE SEAT BELT BUCKLE INOP
TECH_TXT2	
CUST_TXT	CHK FOR PASS SEAT BELT WILL COME UNDONE BY DRIVING
AREA_CD	2B1
COUNTRY_CD	USA
SLS_DLR_CD	162084
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	508
TYS_FLAG	@

ID	106
MDL_YR	2001
SORT_INDEX	384
VIN_CD	1FTZR15E718
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
ROD_CAB_STL	T8D
VER_SERIES_C	T/F
DRIVE_CD	T/E
ENG_CD	T/N
TRANS_CD	T/T
PLANT_CD	AX
PRODN_DT	3/13/2001
WRTY_START_D	3/21/2001
NAME	DEWEY FORD, INC.
DOC_NUM	24471704
PH_NUM	2822828
WCC_CD	BRD2
PART_NUM_CA	1L6Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	2/26/2002
TIS_WSD	12
CLM_KEY	7521800
MILGE	7544
MTRL_COST	

TOT_COST_GRO	18498
LBR_HRS	1.8
DLR_CD	3540
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IA
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	1 TESTED & REPLACED BOTH FRONT OUTSIDE BUCKLES PER PROGRAM
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT AFTER RECALL 01S21 WAS CHECKED AND OK SEATBELT BUCKLE STILL KEEPS COMING APART.
AREA_CD	515
COUNTRY_CD	USA
SLS_DLR_CD	153693
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	100
MDL_YR	2001
SORT_INDEX	385
VIN_CD	1FTZR15E71F
LRR_COST	
VER_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/23/2001
WRTY_START_D	4/20/2001
NAME	LITHIA FORD OF BOISE
DOC_NUM	187034E
PH_NUM	3428511
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/30/2001
TIS_WSD	8
CLM_KEY	5482967
MILGE	15061
MTRL_COST	

Tuesday, December 14, 2004

Page 217 of 558

TOT_COST_GRO	30387
LBR_HRS	0.5
DLR_CD	3897
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	ID
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	15051 RIGHT BUCKLE FAILED INSPECTION REMOVED AND REPLACED RIGHT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	W REPLACE PASSENGER SEAT BELT, FAILED 01S21 RECALL TEST
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	150093
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	110
MDL_YR	2001
SORT_INDEX	388
VIN_CD	1FTZR16E71F
LBR_COST	
VRH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/5/2001
WRTY_START_D	7/12/2001
NAME	PENINSULA FORD OF PALO ALTO-PE
DOC_NUM	2800551
PH_NUM	4838800
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	925
COND_CD	33
RPR_DT	11/18/2001
TIS_WSD	5
CLM_KEY	5155822
MILGE	8900
MTRL_COST	

TOT_COST_GRO	0000
LBR_HRS	
DLR_CD	2051
DLR_SUB_CD	"
REGION_CD	NA
ST_PROV_CD	CA
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	VERIFIED CONCERN. REPLACED PASS. SIDE SEAT BELT CHECKS OK AT THIS
TECH_TXT2	
CUST_TXT	CUST STATES PASS. SIDE SEAT BELT LOOSE ON ATTACHMENT USE SPO 01268007
AREA_CD	050
COUNTRY_CD	USA
SLS_DLR_CD	172012
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S05
TIS_FLAG	

ID	111
MDL_YR	2001
SORT_INDEX	401
VIN_CD	1FTZR15E710
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/11/2001
WRTY_START_D	5/21/2001
NAME	WALBER MOTORS, INC.
DOC_NUM	13204203
PH_NUM	0255500
WCC_CD	BF02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	10/28/2001
TIS_WSD	6
CLM_KEY	4809044
MILGE	18320
MTRL_COST	

TOT_COST_GRO	9250
LBR_HRS	030
DLR_CD	9250
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	6
CPSC_CD_6	11001
TECH_TXT1	TAKE SEAT OUT R R GAS CHARGED BUCKEL
TECH_TXT2	
CUST_TXT	PASS SIDE SEATBELT WONT STAY LATCHED. (S25) CUST HAD 01321 PERFORMED ELSEWHERE AND WAS TOLD
AREA_CD	952
COUNTRY_CD	USA
SLS_DLR_CD	168007
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VBT_CD	S08
TIS_FLAG	

ID	112
MDL_YR	2001
SORT_INDEX	409
VIN_CD	1F1ZR15E71F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/3/2001
WRTY_START_D	5/15/2001
NAME	JOHN ELWAY FORD WEST
DOC_NUM	212509B
PH_NUM	4216350
WCC_CD	BR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	4/8/2002
TIS_WSD	11
CLM_KEY	7841783
MILGE	1667B
MTRL_COST	

TOT_COST_GRO	4338
LBR_HRS	
DLR_CD	1108
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Ratings	s
CPSC_CD_6	11001
TECH_TXT1	15576 INSTALLED BOP BUCKLE
TECH_TXT2	
CUST_TXT	RIGHT FRONT BEAT BELT WONT LATCH , BOP
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	159007
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	113
MDL_YR	2001
SORT_INDEX	404
VIN_CD	1FTZR16E71F
LRR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/E
TRANS_CD	T/C
PLANT_CD	AX
PRODN_DT	4/6/2001
WRTY_START_D	6/28/2001
NAME	DON SEELYE FORD, INC.
DOC_NUM	62430401
PH_NUM	3783820
WCC_CD	0FR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	1
RPR_DT	1/16/2002
TIS_WSD	7
CLM_KEY	6297346
MILGE	7081
MTRL_COST	

TOT_COST_GRO	85.00
LBR_HRS	0.0
DLR_CD	9708
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	5
CPSC_CD_6	19001
TECH_TXT1	1 REMOVED SEAT AND REPLACED SEAT BELT RECHECKED OPERATION OK
TECH_TXT2	
CUST_TXT	CK FOR PASS SIDE SEAT BELT DOESNT LATCH OCC 540
AREA_CD	816
COUNTRY_CD	USA
SLS_DLR_CD	14858
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	114
MDL_YR	2001
SORT_INDEX	406
VIN_CD	1FTZR15E71F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VEH_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	1/30/2001
WRTY_START_D	2/8/2001
NAME	MONTICELLO FORD-MERCURY, INC.
DOC_NUM	20325901
PH_NUM	2962066
WCC_CD	6R02
PART_NUM_CA	1LEZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/8/2002
TIS_WSD	12
CLM_KEY	6207701
MILGE	27353
MTRL_COST	

TOT_COST_GRO	83281
LBR_HRS	0.4
DLR_CD	8354
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	REPLACED PASS SIDE SEAT BELT PER RECALL
TECH_TXT2	
CUST_TXT	CHECK AND ADVISE THE PASS. SIDE SEAT BELT DOES NOT LATCH VERY WELL YOU HAVE TO PUSH ON IT VERY HARD AND SOMETIMES IT
AREA_CD	783
COUNTRY_CD	USA
SLS_DLR_CD	150043
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	115
MDL_YR	2001
SORT_INDEX	409
VIN_CD	1FTZR15E71F
LRR_COST	
VEH_LINE_CD	T/F3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	11/2/2000
WRTY_START_D	1/23/2001
NAME	BLUE SPRINGS FORD INC
DOC_NUM	451839A
PH_NUM	2294400
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/18/2001
TIS_WSD	6
CLM_KEY	3763038
MILGE	8725
MTRL_COST	

TOY_COST_GRO	128.84
LBR_HRS	1
DLR_CD	5100
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	REMOVE SEAT TO GAIN ACCESS TO REPLACE PASS SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CORRECT, PASSENGER SEAT BELT LATCH COMES APART RED BUTTON FALLS OFF SOP IS HERE, SEE GERALD TECH 9760
AREA_CD	B16
COUNTRY_CD	USA
SLS_DLR_CD	153116
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	608
TIS_FLAG	

ID	11B
MDL_YR	2001
SORT_INDEX	423
VIN_CD	1FTZR16E611
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VRR_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/11/2001
WRTY_START_D	4/28/2001
NAME	BECKMAN FORD, INC.
DOC_NUM	711977A
PH_NUM	4485441
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	1/30/2002
TIS_WSD	10
CLM_KEY	6791003
MILGE	3812
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	5008
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KS
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	WILL NOT HOLD ,STAY CLIPPED
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WILL COME UNDONE
AREA_CD	785
COUNTRY_CD	USA
SLS_DLR_CD	153404
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	117
MDL_YR	2001
SORT_INDEX	427
VIN_CD	1FTZR16E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TD
PLANT_CD	AG
PRODN_DT	4/17/2001
WRTY_START_D	7/16/2001
NAME	HOUSTON FORD, INC.
DOC_NUM	11686502
PH_NUM	5874419
WCC_CD	6R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S26
COND_CD	42
RPR_DT	3/28/2002
TIS_WSD	9
CLM_KEY	7770433
MILGE	10738
MTRL_COST	

TOT_COST_GRO	41995
LBR_HRS	
DLR_CD	9443
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	SEAT BELT LATCH INOP. BROKEN INSIDE. REMOVE SEAT FROM ANOTHER RANGER, AND REMOVE SEAT BELT LATCH REMOVE SEAT FROM THIS RANGER, AND REMOVE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CHECK AND REPAIR FOR DRIVERS SEATBELT NOT LATCHING.
AREA_CD	21B
COUNTRY_CD	USA
SLS_DLR_CD	158488
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	118
MDL_YR	2001
SORT_INDEX	428
VIN_CD	1FTZR16E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/11/2001
WRTY_START_D	7/31/2001
NAME	JAY WOLFE FORD
DOC_NUM	2248850
PH_NUM	7338100
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/13/2001
TIS_WSD	4
CLM_KEY	5088054
MILGE	2168
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	2606
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NE
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	2189 WAR INSPECT AND REPLACED LEFT BELT BUCKLE, . REINSPECT R7. BUCKLE OK.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SIDE SEAT BELT BUCKLE RELEASES BY ITSELF AT TIMES WHILE DRIVING.
AREA_CD	402
COUNTRY_CD	USA
SLS_DLR_CD	183023
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	110
MDL_YR	2001
SORT_INDEX	430
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/9/2001
WRTY_START_D	6/30/2001
NAME	STILLWATER FORD, LINCOLN-MERCU
DOC_NUM	102847A
PH_NUM	4902400
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	8/29/2001
TIS_WSD	3
CLM_KEY	4062018
MILGE	3289
MTRL_COST	

TOT_COST_GRO	16220
LBR_HRS	3.88
DLR_CD	9254
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	3289 FOUND BOTH SEAT BELTS TO DISCONNECT REPLACED BOTH FRONT BUCKLES OK NOW
TECH_TXT2	
CUST_TXT	840 CUSTOMER STATES DRIVERS SEATBELT COMES LOOSE WHEN DRIVING, HAS HAPPENS 3 TIMES LATELY
AREA_CD	651
COUNTRY_CD	USA
SLS_DLR_CD	158807
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	806
TIS_FLAG	

ID	120
MDL_YR	2001
SORT_INDEX	481
VIN_CD	1FTZR16E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	A3
PRODN_DT	4/4/2001
WRTY_START_D	4/28/2001
NAME	IMLAY CITY FORD, INC.
DOC_NUM	8088802
PH_NUM	7245800
WCC_CD	6R02
PART_NUM_CA	115Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/6/2001
TIS_WSD	B
CLM_KEY	5547486
MILGE	12268
MTRL_COST	

TOY_COST_GRO	
LBR_HRS	
DLR_CD	2872
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	REPLACED PASSENGER SIDE BELT BUCKLE
TECH_TXT2	
CUST_TXT	PASSENGER SIDE BELT BUCKLE COMES UNDONE
AREA_CD	B10
COUNTRY_CD	USA
SLS_DLR_CD	148544
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	R1
VRT_CD	B08
TIS_FLAG	

ID	121
MDL_YR	2001
SORT_INDEX	432
VIN_CD	1FTZR15E81
LRR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/2/2001
WRTY_START_D	6/25/2001
NAME	JOHNSON FORD, INC.
DOC_NUM	4623401
PH_NUM	3357800
WCC_CD	8R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	41
RPR_DT	8/18/2001
TIS_WSD	2
CLM_KEY	3268160
MILGE	2238
MTRL_COST	

TOI_COST_GRO	7301
LBR_HRS	0.2
DLR_CD	20504
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
Rating	R
CPSC_CD_6	11001
TECH_TXT1	REC.STICKING. REPLACE R S RECEPTACLE
TECH_TXT2	
CUST_TXT	CUST STATES R S SEAT BELT WILL NOT LATCH
AREA_CD	914
COUNTRY_CD	USA
SLS_DLR_CD	113624
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	B06
TIS_FLAG	

ID	122
MDL_YR	2001
SORT_INDEX	433
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	7/1/2001
NAME	FRIENDLY FORD INC
DOC_NUM	063813A
PH_NUM	2438000
WCC_CD	8R02
PART_NUM_CA	1L52
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	808
COND_CD	42
RPR_DT	3/28/2002
TIS_WSD	11
CLM_KEY	8911270
MILGE	6472
MTRL_COST	

TOT_COST_GRO	04 34
LBR_HRS	
DLR_CD	2582
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	8
CPSC_CD_6	11001
TECH_TXT1	PASSENGER FRONTSEAT BELT WOULD NOT LATCH R AND R PASS FRONT SEAT REPLAGE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	PAS FRT SEAT BELT WONT LATCH
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	148484
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	@

ID	129
MDL_YR	2001
SORT_INDEX	435
VIN_CD	1FTZR16E317
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/T0
PLANT_CD	AG
PRODN_DT	4/8/2001
WRTY_START_D	7/8/2001
NAME	CHUCK SPAETH FORD, INC.
DOC_NUM	1011301
PH_NUM	7943821
WCC_CD	6R02
PART_NUM_CA	1L6Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	6
CLM_KEY	6617307
MILGE	3887
MTRL_COST	

TOT_COST_GRO	96.84
LBR_HRS	1.00
DLR_CD	9278
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	
CPSC_CD_6	17001
TECH_TXT1	CK PASSENGER SEAT BELT FOR NOT STAYING LATCHED REMOVED AND REPLACE PASSENGER SEAT BELT BUCKLE. CK OPERATION OK
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEATBELT DOESN'T LATCH PROPERLY RECALL WAS ALREADY DONE
AREA_CD	607
COUNTRY_CD	USA
SLS_DLR_CD	158658
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	608
TIS_FLAG	

ID	124
MDL_YR	2001
SORT_INDEX	437
VIN_CD	1FTZR15E61
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/5/2001
WRTY_START_D	8/2/2001
NAME	DUNN-BENSON FORD
DOC_NUM	5038051
PH_NUM	8822800
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/8/2001
TIS_WSD	2
CLM_KEY	2337432
MILGE	2923
MTRL_COST	

TOT_COST_GRO	843
LBR_HRS	48
DLR_CD	1005
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	DIAG. R AND R SEAT. REPLACE SEATBELT RECEPTACLE
TECH_TXT2	
CUST_TXT	PASSENGER SEATBELT WONT STAY HOOKED
AREA_CD	910
COUNTRY_CD	USA
SLS_DLR_CD	113825
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	125
MDL_YR	2001
SORT_INDEX	438
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	A3
PRODN_DT	4/5/2001
WRTY_START_D	9/3/2001
NAME	UTAH AUTO COLLECTION
DOC_NUM	66383402
PH_NUM	*
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/15/2001
TIS_WSD	4
CLM_KEY	5810208
MILGE	4784
MTRL_COST	

TOT_COST_GRO	12.42
LBR_HRS	0.00
DLR_CD	3320
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	UT
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	1 PERFORMED REPLACEMENT OF BAD SEAT BELT BUCKLE. PERFORMED QUALITY CHECK.
TECH_TXT2	
CUST_TXT	GUEST STATES THAT PASSENGER SEAT BELT BUCKLE IS NOT HOLDING SEAT BELT. REQUEST POSSIBLE REPLACEMENT.
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	158800
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	128
MDL_YR	2001
SORT_INDEX	438
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/30/2001
WRTY_START_D	4/18/2001
NAME	TONY BETTEN & SONS FORD, INC.
DOC_NUM	086355A
PH_NUM	3638841
WCC_CD	6R02
PART_NUM_CA	1LE2
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	3
CLM_KEY	2515154
MILGE	2132
MTRL_COST	