

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 4 OF 6

BOOK 3 OF 43

TOT_COST_GRO	<input type="text" value=""/>
LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="9835"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="MI"/>
Ratings	<input type="text" value="D"/>
CPSC_CD_6	<input type="text" value="11001"/>
TECH_TXT1	<input type="text" value="2132 .8 REMOVE RIGHT FRT. SEAT AND REPLACE SEAT BELT BUCKEL END. FOR BUCKEL COMING UNHOOKED"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="RIGHT SEAT BUCKLE COMES UNHOOKED"/>
AREA_CD	<input type="text" value="616"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="148071"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="R1"/>
VRT_CD	<input type="text" value="S08"/>
TTS_FLAG	<input type="text" value=""/>

ID	127
MDL_YR	2001
SORT_INDEX	440
VIN_CD	1FTZR16E61T
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/30/2001
WRTY_START_D	9/27/2001
NAME	NORTH COUNTRY FORD
DOC_NUM	0218101
PH_NUM	4271120
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	4
CLM_KEY	8284872
MILGE	4150
MTRL_COST	

Tuesday, December 14, 2004

Page 253 of 350

RQ04-011 E 1728

TOT_COST_GRO	
LBR_HRS	
DLR_CD	2733
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	1 INSTALL SOP PASSENGER SIDE SEAT BLET HAD TO REMOVE DRIVE SEAT TO GAIN ACEC TO BLET LATCH
TECH_TXT2	
CUST_TXT	INSTALL SOP PASSENGER SIDE SEAT BELT LATCH ASSEMBLY LETS LOO SE AT TIMES
AREA_CD	703
COUNTRY_CD	USA
SLS_DLR_CD	158016
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	128
MDL_YR	2001
SORT_INDEX	441
VIN_CD	1FTZR15E81
LAB_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TG
PLANT_CD	AG
PRODN_DT	8/30/2001
WRTY_START_D	8/27/2001
NAME	NORTH COUNTRY FORD
DOC_NUM	8110802
PH_NUM	4271120
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	4
CLM_KEY	5981842
MILGE	3815
MTRL_COST	

TOT_COST_GRO	2733
LBR_HRS	000
DLR_CD	2733
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	CHECKED BOTH SEAT BELTS AND BOTH UNLATCHED WITH SEAT BELT TOOL REPLACED DRIVERS SIDE AND PASSENGER SIDE WE HAD TO ORDER NOT IN STOCK AT THIS TIME
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEAT BELT UNLATCHES ON OWN AT TIMES
AREA_CD	763
COUNTRY_CD	USA
SLS_DLR_CD	158018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S01
TIS_FLAG	

ID	129
MDL_YR	2001
SORT_INDEX	442
VIN_CD	1FTZR15E01
LRR_COST	
VRH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/26/2001
WRTY_START_D	4/26/2001
NAME	FORD OF KIRKLAND, INC.
DOC_NUM	32455801
PH_NUM	8216611
WCC_CD	BR02
PART_NUM_CA	1LEZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONG_C	S40
COND_CD	42
RPR_DT	5/8/2002
TIS_WSD	13
CLM_KEY	0528278
MILGE	12074
MTRL_COST	

TOT_COST_GRO	7021
LBR_HRS	
DLR_CD	847
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	VERIFIED CONCERN. REPLACED SEAT BELT BUCKLE..ALL OK NOW 898
TECH_TXT2	
CUST_TXT	CUST STATES SEAT BELT BUCKLE ISNT HOLDING. GK & ADV
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	174535
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	130
MDL_YR	2001
SORT_INDEX	445
VIN_CD	1FTZR16E01T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	12/20/2000
WRTY_START_D	1/9/2001
NAME	JOHN M. LANCE FORD, LLC
DOC_NUM	053422C
PH_NUM	8718000
WCC_CD	BF02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	12/13/2001
TIS_WSD	12
CLM_KEY	5745194
MILGE	10982
MTRL_COST	

TOT_COST_GRO	9872
LBR_HRS	0.4
DLR_CD	2284
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	INSPECT AND REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES PASS FRONT SEATBELT LINHOOKS
AREA_CD	218
COUNTRY_CD	USA
SLS_DLR_CD	144121
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	181
MDL_YR	2001
SORT_INDEX	452
VIN_CD	1FTZR15E81
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AG
PRODN_DT	10/18/2000
WRTY_START_D	11/17/2000
NAME	CHENOWETH FORD, INC.
DOC_NUM	11891301
PH_NUM	8238501
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1001203
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	2/8/2002
TIS_WSD	15
CLM_KEY	0700058
MILGE	34087
MTRL_COST	

TOT_COST_GRO	7038
LBR_HRS	
DLR_CD	7457
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WW
Ratings	
CPSC_CD_6	11001
TECH_TXT1	42 SEATBELT WONT LATCH REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES LEFT FRT SEATBELT WONT LATCH 840
AREA_CD	304
COUNTRY_CD	USA
SLS_DLR_CD	144533
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	806
TIS_FLAG	

ID	132
MDL_YR	2001
SORT_INDEX	458
VIN_CD	1FTZR15E81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	TABD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	8/18/2000
WRTY_START_D	11/30/2000
NAME	MONTAVON MOTORS, INC.
DOC_NUM	10478301
PH_NUM	3280551
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/16/2001
TIS_WSD	6
CLM_KEY	2329088
MILGE	4489
MTRL_COST	

Tuesday, December 14, 2004

Page 263 of 358

RQ04-011 E 1738

TOT_COST_GRO	
LRR_HRS	
DLR_CD	0282
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	SEAT BELT BUCKLE 1001203 CG 42 CHECK OASIS,REPLACED LEFT FRT SEAST BELT BUCKLE,CHECK OPERATION,O.K. 0107
TECH_TXT2	
CUST_TXT	CUSTOMER STATES OF DRIVERS SIDE SEAT BELT WONT LATCH
AREA_CD	218
COUNTRY_CD	USA
SLS_DLR_CD	150494
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	133
MDL_YR	2001
SORT_INDEX	474
VIN_CD	1FTZR16E81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/12/2001
WRTY_START_D	8/8/2001
NAME	SIOUX FALLS FORD
DOC_NUM	34155801
PH_NUM	3810381
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	638
COND_CD	42
RPR_DT	7/11/2001
TIS_WSD	2
CLM_KEY	4271124
MILGE	1653
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	1385
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SD
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	1 REPLACE SEATBELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	PASSENGER FRONT SEAT BELT WONT STAY LATCHED
AREA_CD	B05
COUNTRY_CD	USA
SLS_DLR_CD	158716
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	134
MDL_YR	2001
SORT_INDEX	475
VIN_CD	1FTZR15E91F
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/5/2001
WRTY_START_D	5/4/2001
NAME	DAVE SINCLAIR FORD, INC.
DOC_NUM	22876903
PH_NUM	8822800
WCC_CD	BR02
PART_NUM_CA	1LBZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/13/2001
TIS_WSD	3
CLM_KEY	2387779
MILGE	2884
MTRL_COST	

TOT_COST_GRO	115.98
LBR_HRS	307
DLR_CD	8199
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Rating	b
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CUST SAYS RT FRT SEAT BELT WILL NOTY STAY LATCHED
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	153080
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	135
MDL_YR	2001
SORT_INDEX	478
VIN_CD	1FTZR16E81F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/BC
PLANT_CD	AX
PRODN_DT	4/11/2001
WRTY_START_D	5/4/2001
NAME	COURTESY FORD
DOC_NUM	7798702
PH_NUM	2861771
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	2/16/2002
TIS_WSD	10
CLM_KEY	8826890
MILGE	10871
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	0502
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OR
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	TESTED AND VERIFIED.REPLACED FAILING BUCKEL ASSEMBLY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT THE PASSANGER SIDE BUCKEL WILL UNLATCH ON ITS OWN.
AREA_CD	503
COUNTRY_CD	USA
SLS_DLR_CD	174013
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	B08
TIS_FLAG	

ID	136
MDL_YR	2001
SORT_INDEX	477
VIN_CD	1FTZR15E81F
LBR_COST	
VEH_LINE_CD	T/RS
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/4/2001
WRTY_START_D	10/8/2001
NAME	TUNBERG MOTOR CO.
DOC_NUM	3574201
PH_NUM	8812600
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	10/12/2001
TIS_WSD	1
CLM_KEY	4452802
MILGE	181
MTRL_COST	

TOT_COST_GRO	<input type="text" value="7658"/>
LBR_HRS	<input type="text" value="0"/>
DLR_CD	<input type="text" value="4192"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="MN"/>
Ratings	<input type="text" value=""/>
CPSC_CD_6	<input type="text" value="11001"/>
TECH_TXT1	<input type="text" value="RIGHT SEAT BELT RETRACTOR WILL NOT BUCKLE SEATBELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value=""/>
AREA_CD	<input type="text" value="218"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="150640"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="R1"/>
VRT_CD	<input type="text" value="S06"/>
TIS_FLAG	<input type="text" value=""/>

ID	137
MDL_YR	2001
SORT_INDEX	478
VIN_CD	1FTZR15E81F
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	T8D
VER_SERIES_C	TFF
DRIVE_CD	TIE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	5/30/2001
NAME	WEHMEYER MOTORS INC
DOC_NUM	3149902
PH_NUM	7843331
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/20/2001
TIS_WSD	8
CLM_KEY	9988638
MILGE	22527
MTRL_COST	

TOT_COST_GRO	0075
LBR_HRS	02
DLR_CD	8177
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Ratings	
CPSC_CD_6	11001
TECH_TXT1	REPLACE RIGHT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEAT BELT DOES NOT LATCH PROPERLY
AREA_CD	573
COUNTRY_CD	USA
SLS_DLR_CD	158792
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	138
MDL_YR	2001
SORT_INDEX	488
VIN_CD	1FTZR1GE81
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/6/2001
WRTY_START_D	6/3/2001
NAME	TOM HEFFERNAN FORD-MERCURY INC
DOC_NUM	39857801
PH_NUM	3465813
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/17/2001
TIS_WSD	3
CLM_KEY	2673575
MILGE	8821
MTRL_COST	

TOT_COST_GRO	8721
LBR_HRS	00
DLR_CD	0408
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	*
CPSC_CD_6	11001
TECH_TXT1	ORDER AND REPLACE BUCKLE ASY
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE DOESNT LATCH
AREA_CD	861
COUNTRY_CD	USA
SLS_DLR_CD	138531
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	138
MDL_YR	2001
SORT_INDEX	487
VIN_CD	1FTZR15E81F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	7/18/2001
NAME	CAMPBELL FORD LINCOLN-MERCURY,
DOC_NUM	3462553
PH_NUM	6648300
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	525
COND_CD	42
RPR_DT	1/23/2002
TIS_WSD	7
CLM_KEY	6454026
MILGE	5576
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	2744
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	LATCH ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	RT FT SEAT BELT COMES UNBUCKLED AT TIMES
AREA_CD	618
COUNTRY_CD	USA
SLS_DLR_CD	148588
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	140
MDL_YR	2001
SORT_INDEX	488
VIN_CD	1FTZR15E81F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/5/2001
WRTY_START_D	7/30/2001
NAME	O'MEARA FORD CENTER INC
DOC_NUM	0882308
PH_NUM	4511331
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	925
COND_CD	42
RPR_DT	9/12/2001
TIS_WSD	2
CLM_KEY	3711804
MILGE	1448
MTRL_COST	

TOT_COST_GRO	14284
LBR_HRS	
DLR_CD	3294
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	1448 REPLASD PAS SIDE SEAT BELT LATCH AND INSPECTE D DRIVERS ALL OK AT THIS TIME
TECH_TXT2	
CUST_TXT	CUST. STATES P 8 FRONT SEAT BELT WILL RELEASE FROM BUCKLE PLEASE CHECK AND ADVISE
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	156003
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	141
MDL_YR	2001
SORT_INDEX	488
VIN_CD	1FTZR16E81F
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	5/17/2001
NAME	UTAH AUTO COLLECTION
DOC_NUM	34840501
PH_NUM	9888000
WCC_CD	BR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	T90
COND_CD	1
RPR_DT	11/28/2001
TIS_WSD	7
CLM_KEY	5302135
MILGE	7334
MTRL_COST	

TOT_COST_GRO	85.34
LBR_HRS	0.4
DLR_CD	3318
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	UT
Ratings	a
CPSC_CD_6	11031
TECH_TXT1	R R PASSENGER SEAT ... REPLACED SEAT BELT BUCKEL ... QUALITY CKED
TECH_TXT2	
CUST_TXT	RIGHT SEAT BELT WONT LATCH
AREA_CD	001
COUNTRY_CD	USA
SLS_DLR_CD	150800
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AW3_VL_CD	R1
VRT_CD	808
TES_FLAG	

ID	142
MDL_YR	2001
SORT_INDEX	490
VIN_CD	1FTZR15E51P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/ED
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	4/6/2001
WRTY_START_D	9/19/2001
NAME	BURT'S ARAPAHOE FORD, INC.
DOC_NUM	967098A
PH_NUM	0430000
WCC_CD	BF02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	325
COND_CD	41
RFR_DT	9/20/2001
TIS_WSD	4
CLM_KEY	383323
MILGE	3009
MTRL_COST	

TOT_COST_GRO	412.14
LRR_HRS	13
DLR_CD	3188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REMOVE PASSENGER SEAT, REPLACE SEAT BELT BUCKLE ASSEMBLY, REINSTALL SEAT, TESTED OPERATION, WORKING PROPERLY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES RIGHT SEAT BELT WONT STAY LATCHED
ARKA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	156001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	

ID	143
MDL_YR	2001
SORT_INDEX	491
VIN_CD	1FTZR15E81F
LRR_COST	
VEH_LINE_CD	TFC3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	6/18/2001
NAME	HASTINGS AUTOMOTIVE INC
DOC_NUM	1440660
PH_NUM	4374030
WCC_CD	BR02
PART_NUM_CA	1LEZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S26
COND_CD	42
RPR_DT	3/28/2002
TIS_WSD	10
CLM_KEY	8330271
MILGE	19217
MTRL_COST	

TOT_COST_GRO	88.33
LBR_HRS	
DLR_CD	8212
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACED SEATBELT BUCKLE ASY
TECH_TXT2	
CUST_TXT	CK RT SEAT BELT DOESNT STAY LATCH
AREA_CD	851
COUNTRY_CD	USA
SLS_DLR_CD	168504
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	144
MDL_YR	2001
SORT_INDEX	511
VIN_CD	1FTZR15E517
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/R0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/30/2001
WRTY_START_D	8/18/2001
NAME	GENOA MOTORS, INC.
DOC_NUM	8632701
PH_NUM	8558386
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	4/12/2002
TIS_WSD	8
CLM_KEY	7874588
MILGE	8028
MTRL_COST	

TOT_COST_GRO	0010
LBR_HRS	
DLR_CD	2804
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Rating	0
CPSC_CD_6	11001
TECH_TXT1	INSPECTED AND REPLACED DRIVERS SEATBELT BUCKLE RECHECKED OK
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL NOT BUCKLE
AREA_CD	418
COUNTRY_CD	USA
SLS_DLR_CD	148226
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S05
TIS_FLAG	

ID	146
MDL_YR	2001
SORT_INDEX	817
VIN_CD	1FTZR18E51T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/T0
PLANT_CD	AG
PRODN_DT	4/9/2001
WRTY_START_D	5/10/2001
NAME	ANDY MOHR FORD, INC.
DOC_NUM	15488901
PH_NUM	8366641
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/28/2001
TIS_WSD	5
CLM_KEY	3845875
MILGE	3590
MTRL_COST	

TOT_COST_GRO	84.42
LBR_HRS	0.6
DLR_CD	1418
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
Ratings	3
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEAT BELT
TECH_TXT2	
CUST_TXT	RT FRT SEAT BELT BUCKLE WILL NOT ALWAYS STAY LATCHED INSTALL SOP
AREA_CD	317
COUNTRY_CD	USA
SLS_DLR_CD	147130
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	148
MDL_YR	2001
SORT_INDEX	518
VIN_CD	1FTZR18E61
LBB_COST	
VEH_LINE_CD	T/R5
MKT_DERIVED	*
BOD_CAR_STL	T/RD
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/3/2001
WRTY_START_D	8/8/2001
NAME	ED WITTMER FORD LINCOLN-MERC
DOC_NUM	83514702
PH_NUM	8868181
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	1/24/2002
TIS_WSD	6
CLM_KEY	6681958
MILGE	7122
MTRL_COST	

TOT_COST_GRO	199.38
LBR_HRS	
DLR_CD	7780
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	CHECKED FOR CONCERN REPLACED BELT RECHECKED OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT COMES UNDONE AFTER BUCKLING UP
AREA_CD	530
COUNTRY_CD	USA
SLS_DLR_CD	172420
TXN_CD	E83
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	147
MDL_YR	2001
SORT_INDEX	518
VIN_CD	1FTZR15E51
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAR_STL	T/RD
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	5/3/2001
NAME	NORTH BROS. FORD, INC.
DOC_NUM	4885701
PH_NUM	4211300
WCC_CD	BRD2
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/18/2001
TIS_WSD	6
CLM_KEY	4108087
MILGE	4644
MTRL_COST	

TOT_COST_GRO	00.86
LBR_HRS	10.4
DLR_CD	2876
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	42 REPLACE RT SEAT BELT BUCKLE ASSY NECESSARY TO REMOVE SEAT FOR ACCESS
TECH_TXT2	
CUST_TXT	PER CUST THE PASS SEATBELT COMES APART BY ITSELF
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	145048
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	148
MDL_YR	2001
SORT_INDEX	523
VIN_CD	1FTR15E5T
LBR_COST	
VEH_LINE_CD	TTR3
MKT_DERIVED	*
BOD_CAB_STL	TTRD
VER_SERIES_C	TTRF
DRIVE_CD	TTE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	12/1/2000
WRTY_START_D	1/1/2001
NAME	CHATHAM FORD INC
DOC_NUM	06103
PH_NUM	0450500
WCC_CD	0R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	823
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	9
CLM_KEY	4007178
MILGE	8804
MTRL_COST	

TOT_COST_GRO	37.7
LBR_HRS	
DLR_CD	8571
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MA
Rollings	a
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEAT BELT BUCKLE DOES NOT WORK
AREA_CD	508
COUNTRY_CD	USA
SLS_DLR_CD	111010
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	606
TIS_FLAG	

ID	149
MDL_YR	2001
SORT_INDRX	525
VIN_CD	1FTR15E51T
LBR_COST	
VEH_LINE_CD	T/F3
MKT_DERIVED	*
BOD_CAB_STL	T/FD
VER_SERIES_C	T/F
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	11/10/2000
WRTY_START_D	3/27/2001
NAME	DICK WRIGHT FORD
DOC_NUM	019901C
PH_NUM	2852211
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	1/7/2002
TIS_WSD	10
CLM_KEY	6287305
MILGE	20232
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	8058
DLR_SUB_CD	
REGION_CD	KA
ST_PROV_CD	VT
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACE THE SEAT BELT BUCKLE ASSY WONT STAY LATCHED
TECH_TXT2	
CUST_TXT	PASSENGER SEAT BELT DOESNT HOLD
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	111541
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
ABS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	150
MDL_YR	2001
SORT_INDEX	530
VIN_CD	1FTZR15E51T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/R3
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	8/25/2000
WRTY_START_D	2/24/2001
NAME	BROOKINGS-HARBOR FORD MERCURY
DOC_NUM	2727308
PH_NUM	99254
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	10B1208
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	7/16/2001
TIS_WSD	8
CLM_KEY	3713008
MILGE	2810
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	4045
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OR
Ratings	
CPSC_CD_6	11001
TECH_TXT1	PERFORMED RECALL 01821
TECH_TXT2	
CUST_TXT	PERFORM RECALL 01821 SEAT BELT RECALL
AREA_CD	641
COUNTRY_CD	USA
SLS_DLR_CD	172489
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	151
MDL_YR	2001
SORT_INDEX	531
VIN_CD	1FTZR15E51F
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TR3
VER_SERIES_C	TRF
DRIVE_CD	TR
ENG_CD	TR
TRANS_CD	TRC
PLANT_CD	AX
PRODN_DT	7/25/2001
WRTY_START_D	8/15/2001
NAME	MEGINNIS FORD COMPANY
DOC_NUM	4320401
PH_NUM	4840801
WCC_CD	BR02
PART_NUM_CA	1152
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/19/2001
TLS_WSD	3
CLM_KEY	4790461
MILGE	3928
MTRL_COST	

TOT_COST_GRO	797
LRR_HRS	
DLR_CD	7195
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NE
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEAT BELT BUCKLE IS NOT STAYING LATCHED IN
AREA_CD	402
COUNTRY_CD	USA
SLS_DLR_CD	153028
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	152
MDL_YR	2001
SORT_INDEX	552
VIN_CD	1FTZR19E51P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	5/21/2001
WRTY_START_D	10/27/2001
NAME	SAWTOOTH AUTO SALES
DOC_NUM	0366251
PH_NUM	7882218
WCC_CD	0R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	6/29/2001
TIS_WSD	0
CLM_KEY	3408814
MILGE	20
MTRL_COST	

Tuesday, December 14, 2004

Page 383 of 558

RQ04-011 E 1778

TOT_COST_GRO	89.7
LBR_HRS	0.0
DLR_CD	8347
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	ID
Ratings	8
CPSC_CD_6	11001
TECH_TXT1	RPL SEAT BELT LEFT FRONT
TECH_TXT2	
CUST_TXT	SEATBELT WONT LATCH
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	168804
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	908
YES_FLAG	

ID	159
MDL_YR	2001
SORT_INDEX	696
VIN_CD	1FTZR15E61F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/R3D
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	5/9/2001
WRTY_START_D	5/23/2001
NAME	ANDERSON FORD OF ST. JOSEPH
DOC_NUM	128759A
PH_NUM	2797485
WCC_CD	BR02
PART_NUM_CA	1LEZ
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	10/26/2001
TIS_WSD	6
CLM_KEY	4709844
MILGE	5680
MTRL_COST	

TOT_COST_GRO	92.72
LBR_HRS	0.4
DLR_CD	1743
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	5880 REPLACED DRIVERS SIDE SEATBELT BUCKLE CUSTOMER STATED THAT THE SEAT BELT STILL WOULD NOT STAY LATCHED PROPERLY
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SEAT BELT
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	163002
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	154
MDL_YR	2001
SORT_INDEX	630
VIN_CD	1FTZR16E51F
LRR_COST	
VEH_LINE_CD	TAR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AX
PRODN_DT	4/16/2001
WRTY_START_D	6/29/2001
NAME	D-PATRICK, INC.
DOC_NUM	135608P
PH_NUM	4287800
WCC_CD	GR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	826
COND_CD	69
RPR_DT	10/29/2001
TIS_WSD	6
CLM_KEY	5103429
MILGE	1201
MTRL_COST	

Tuesday, December 14, 2004

Page 387 of 558

RQ04-011 E 1782

TOT_COST_GRO	168.08
LBR_HRS	4.5
DLR_CD	4823
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
Ratings	G
CPSC_CD_6	11001
TECH_TXT1	1201 ORDER BOTH SEAT BELTS ASSY. REPLACED BOTH FRONT SEAT BELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	825 SALES STS DRIVERS SEAT BELT COMES UNDONE
AREA_CD	812
COUNTRY_CD	USA
SLS_DLR_CD	147527
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	605
TIS_FLAG	

ID	156
MDL_YR	2001
SORT_INDEX	598
VIN_CD	1FTZR19E51P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	TE
ENG_CD	T/NE
TRANS_CD	T/8C
PLANT_CD	AX
PRODN_DT	4/18/2001
WRTY_START_D	6/15/2001
NAME	OMEARA FORD CENTER INC
DOC_NUM	078477A
PH_NUM	4511331
WCC_CD	6R02
PART_NUM_CA	1LEZ
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	0
CLM_KEY	7216121
MILGE	10398
MTRL_COST	

TOT_COST_GRO	7497
LBR_HRS	
DLR_CD	3284
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	10336 REPLACED DRIVER SEAT BELT LATCH ALL OK AT THIS TIME HAD TO REMOVE SEAT TO REPLACED LATCH
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT WONT LATCH
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	159005
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	908
TIS_FLAG	

ID	198
MDL_YR	2001
SORT_INDEX	542
VIN_CD	1FTZR19E51F
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	6/30/2001
NAME	NEW PRAGUE FORD MERCURY, INC.
DOC_NUM	8018901
PH_NUM	7552700
WCC_CD	8R02
PART_NUM_CA	1L52
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/13/2001
TIS_WSD	1
CLM_KEY	2338008
MILGE	618
MTRL_COST	

Thursday, December 14, 2004

Page 311 of 338

RQ04-011 E 1788

TOT_COST_GRO	58386
LBR_HRS	
DLR_CD	1374
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	CCC 640 CC 42 CAUSAL 1001203 DR SEAT BELT BUCKLE WILL NOT LATCH. REPLACED BUCKLE AND VERIFIED NORMAL OPERATION.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE DRIVER SEATBELT BUCKLE WILL NOT LATCH CHECK AND ADV.
AREA_CD	852
COUNTRY_CD	USA
SLS_DLR_CD	160620
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	157
MDL_YR	2001
SORT_INDEX	543
VIN_CD	1FTZR16E61F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/ED
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/9/2001
WRTY_START_D	5/22/2001
NAME	LEE SAPP FORD-MERCURY
DOC_NUM	19975401
PH_NUM	9443387
WCC_CD	6R02
PART_NUM_CA	1L62
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	925
COND_CD	42
RPR_DT	7/13/2001
TIS_WSD	2
CLM_KEY	2326004
MILGE	2806
MTRL_COST	

TOT_COST_GRO	<input type="text" value="08597"/>
LBR_HRS	<input type="text" value="0.00"/>
DLR_CD	<input type="text" value="7188"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NE"/>
Ratings	<input type="text" value=""/>
CPSC_CD_6	<input type="text" value="11001"/>
TECH_TXT1	<input type="text" value="REPLACE DRIVERS SEAT BELT RECEPTAGLE. MT NO LABOR OP LISTED IN SLTS."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DRIVERS SEAT SEAT BLET WILL NOT LATCH AT TIMES."/>
AREA_CD	<input type="text" value="402"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="162881"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="R1"/>
VRT_CD	<input type="text" value="S06"/>
TIS_FLAG	<input type="text" value=""/>

ID	158
MDL_YR	2001
SORT_INDEX	544
VIN_CD	1FTZR15E81
LBR_COST	
VEH_LINE_CD	T/RS
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/9/2001
WRTY_START_D	5/22/2001
NAME	LEE SAPP FORD-MERCURY
DOC_NUM	19884801
PH_NUM	9443387
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	326
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	3
CLM_KEY	288857
MILGE	8497
MTRL_COST	

TOT_COST_GRO	10E92
LBR_HRS	5R
DLR_CD	7108
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NE
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	MT NO OP LISTED IN SLTS TO REMOVE PASSENGER SIDE SEAT TOOK COVER LOOSE REMOVED LATCH ASSEMBLY AND REINSTALL, REINSTALLED SEAT.
TECH_TXT2	
CUST_TXT	RF SEATBELT COMES UNBUCKLED.
AREA_CD	402
COUNTRY_CD	USA
SLS_DLR_CD	163061
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	159
MDL_YR	2001
SORT_INDEX	548
VIN_CD	1FTR15E51H
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/12/2001
WRTY_START_D	5/15/2001
NAME	WENDLE FORD SALES
DOC_NUM	1801348
PH_NUM	4844800
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	525
COND_CD	42
RPR_DT	7/27/2001
TIS_WSD	3
CLM_KEY	3128831
MILGE	2501
MTRL_COST	

TOT_COST_GRO	64.85
LBR_HRS	0.4
DLR_CD	8084
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WA
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	RECALL REPLACED R SIDE SEAT BELT BUCKEL
TECH_TXT2	
CUST_TXT	CHECK RF SEAT BELT DOES NOT STAY BUCKLED
AREA_CD	509
COUNTRY_CD	USA
SLS_DLR_CD	174201
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRI_CD	S08
TIS_FLAG	

ID	180
MDL_YR	2001
SORT_INDEX	547
VIN_CD	1FTZR15E61F
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	TFB0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	3/7/2001
WRTY_START_D	3/27/2001
NAME	COURTESY FORD
DOC_NUM	46823005
PH_NUM	7944343
WCC_CD	BRD2
PART_NUM_CA	1LGZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/14/2002
TIS_WSD	12
CLM_KEY	7498946
MILGE	8041
MTRL_COST	

TOT_COST_GRO	146.02
LBR_HRS	0.4
DLR_CD	3170
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	1 CHECKED BUCKLE, LATCH FEELS LOOSE. REMOVED SEAT, REPAVED BUCKLE. RETESTED, OK.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES R F SEAT BELT WILL NOT STAY BUCKELED
AREA_CD	308
COUNTRY_CD	USA
SLS_DLR_CD	158008
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	

ID	181
MDL_YR	2001
SORT_INDEX	640
VIN_CD	1FTZR15E51F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/9/2001
WRTY_START_D	8/28/2001
NAME	UTAH AUTO COLLECTION
DOC_NUM	54104801
PH_NUM	2824433
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/30/2001
TIS_WSD	3
CLM_KEY	4782818
MILGE	3048
MTRL_COST	

TOT_COST_GRO	88.34
LBR_HRS	0.4
DLR_CD	3324
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	UT
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	1 CHECKED AND FOUND THE SEAT BELT BUCKEL IS INOP. REPLACED THE PASS. SIDE BUCKEL. LM
TECH_TXT2	
CUST_TXT	GUEST STATES: THE PASS SIDE SEATBELT WILL COME UNDONE WHILE DRIVING.
AREA_CD	801
COUNTRY_CD	LISA
SLS_DLR_CD	168800
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	162
MDL_YR	2001
SORT_INDEX	550
VIN_CD	1FTZR15E51F
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AX
PRODN_DT	4/8/2001
WRTY_START_D	6/6/2001
NAME	FOREST LAKE FORD, INC.
DOC_NUM	9320051
PH_NUM	4644600
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	11/13/2001
YES_WSD	7
CLM_KEY	5140014
MILGE	13090
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	0210
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	X SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
TECH_TXT2	
CUST_TXT	SEAT BELT ON PASSENGER SIDE WILL NOT BUCKLE, IT DOESNT LATCH COMPLETELY
AREA_CD	651
COUNTRY_CD	USA
SLS_DLR_CD	168583
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	806
TIS_FLAG	

ID	183
MDL_YR	2001
SORT_INDEX	582
VIN_CD	1FTZR15E51P
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	1/30/2001
WRTY_START_D	3/14/2001
NAME	CROWN FORD LINCOLN-MERCURY
DOC_NUM	032328A
PH_NUM	2281800
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	525
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	11
CLM_KEY	901632E
MILGE	11220
MTRL_COST	

TOY_COST_GRO	9848
LRR_HRS	0.7
DLR_CD	2765
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	#
CPSC_CD_6	11001
TECH_TXT1	REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT DOES NOT LATCH
AREA_CD	S08
COUNTRY_CD	USA
SLS_DLR_CD	141625
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	184
MDL_YR	2001
SORT_INDEX	654
VIN_CD	1FTZR15E31P
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TR30
VER_SERIES_C	TAF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	11/8/2000
WRTY_START_D	12/4/2000
NAME	BARBEE'S FREEWAY FORD, INC.
DOC_NUM	8824901
PH_NUM	7573873
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RFR_DT	12/10/2001
TIS_WSD	13
CLM_KEY	6721163
MILGE	14802
MTRL_COST	

TOT_COST_GRO	81.88
LRR_HRS	2.5
DLR_CD	3148
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GO
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	UNSCREW 4 STAR BOLTS FROM FLOOR BOARDS 1 STAR BOLT FROM SEAT BELT RESCREW 1 STAR BOLT TO SEAT AND 4 STAR BOLTS TO SEAT TO FLOOR BOARD QUALITY CHECKED OK
TECH_TXT2	
CUST_TXT	PASS SEATBELT INOP WONT ALWAYS LATCH WILL POP OUT SOP IS IN TIME IN 9:00 TIME OUT 9:28 APPROVED BY BG
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	158008
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	165
MDL_YR	2001
SORT_INDEX	659
VIN_CD	1FTZR15E51F
LRR_COST	
VEH_LINE_CD	T7R3
MKT_DERIVED	
BOD_CAB_STL	T7BD
VER_SERIES_C	T7EF
DRIVE_CD	T7E
ENG_CD	T7NE
TRANS_CD	T7TC
PLANT_CD	AX
PRODN_DT	11/3/2000
WRTY_START_D	8/12/2001
NAME	BROWNS SALES & LEASING, INC.
DOC_NUM	081903A
PH_NUM	2521011
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1001208
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	1
RPR_DT	12/7/2001
TIS_WSD	8
CLM_KEY	6304848
MILGE	15708
MTRL_COST	

TOT_COST_GRO	0619
LBR_HRS	0.0
DLR_CD	20048
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IA
Ratings	A
CPSC_CD_6	11001
TECH_TXT1	CHECK SEAT BELT. LEFT SIDE WONT LATCH. REMOVE LEFT SEAT TO ACCESS BELT LATCH. R AND R LATCH AS SEMBLY. REINSTALL SEAT. BELT LATCHES OK THANKS, ROSS
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT BUCKLE INOP
AREA_CD	319
COUNTRY_CD	USA
SLS_DLR_CD	141689
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	188
MDL_YR	2001
SORT_INDEX	502
VIN_CD	1FTZR15E31F
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	10/12/2000
WRTY_START_D	2/28/2001
NAME	UTAH AUTO COLLECTION
DOC_NUM	51693901
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	8/10/2001
TIS_WSD	7
CLM_KEY	9971868
MILGE	BR02
MTRL_COST	

TOT_COST_GRO	8834
LBR_HRS	84
DLR_CD	10374
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	UT
Rating	a
CPSC_CD_6	11001
TECH_TXT1	FOUND RIGHT FRONT SEAT BELT TOTALLY INOP REPLACED RF SEAT BELT QUALITY CHECKED FOUND TO OPERATE TO MANUFACTURES SPECS AFTER REPAIR.
TECH_TXT2	
CUST_TXT	GUEST STATES RF SEAT BELT BUCKLE STICKS AND WILL NOT LATCH PROPERLY. SA VERIFIED CONCERN
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	158900
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	187
MDL_YR	2001
SORT_INDEX	673
VIN_CD	1FTZR15E41T
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TIEF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/12/2001
WRTY_START_D	9/25/2001
NAME	MCDONALD FORD INC
DOC_NUM	073688A
PH_NUM	8955698
WCC_CD	BRD2
PART_NUM_CA	1LSZ
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	4/18/2002
TIS_WSD	7
CLM_KEY	853084
MILGE	0125
MTRL_COST	

TOT_COST_GRO	02.00
LBR_HRS	00
DLR_CD	1850
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	2
CPSC_CD_6	11001
TECH_TXT1	REPLACED LATCH
TECH_TXT2	
CUST_TXT	SEAT BELT WONT LATCH
AREA_CD	989
COUNTRY_CD	USA
SLS_DLR_CD	148533
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	SCB
TIS_FLAG	

ID	168
MDL_YR	2001
SORT_INDEX	574
VIN_CD	1FTZR16E41
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/17/2001
WRTY_START_D	5/12/2001
NAME	NEW HOLLAND FORD
DOC_NUM	24578903
PH_NUM	3644901
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	1
RPR_DT	2/22/2002
TIS_WSD	10
CLM_KEY	7072107
MILGE	3383
MTRL_COST	

TOT_COST_GRO	10684
LRR_HRS	07
DLR_CD	1380
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	SEAT BELT BUCKLE BROKEN AND NOT WORKING PROPERLY REMOVE AND REPLACE SEAT BELT BUCKLE ASSEMBLY
TECH_TXT2	
CUST_TXT	CUST SAYS DR. SEAT BELT POP OUT AT TIME TO DEMO IF NESS
AREA_CD	717
COUNTRY_CD	USA
SLS_DLR_CD	116808
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	189
MDL_YR	2001
SORT_INDEX	573
VIN_CD	1FTZR1SE41T
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/22/2001
WRTY_START_D	9/18/2001
NAME	KRUG RIVERTOWN MOTORS
DOC_NUM	4142701
PH_NUM	6279985
WCC_CD	BR02
PART_NUM_CA	1L8Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	11/13/2001
TIS_WSD	2
CLM_KEY	6188600
MILGE	5108
MTRL_COST	

TOT_COST_GRO	78.88
LBR_HRS	0.8
DLR_CD	9878
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Rating	b
CPSC_CD_6	11001
TECH_TXT1	BUCKLE WILL NOT HOLD REPLACE RIGHT FRONT SEATBELT BUCKLE ASSEMBLY
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEAT BELT WILL NOT BUCKLE STAY LATCHED
AREA_CD	231
COUNTRY_CD	USA
SLS_DLR_CD	148000
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	170
MDL_YR	2001
SORT_INDEX	580
VIN_CD	1FTZR15E41
LBR_COST	
VEH_LINE_CD	TFRS
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	T/E
ENG_CD	TNE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	1/30/2001
WRTY_START_D	3/20/2001
NAME	FORD OF GREENSBURG
DOC_NUM	27387702
PH_NUM	8346820
WCC_CD	6R02
PART_NUM_CA	1LEZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	7/17/2001
TIS_WSD	4
CLM_KEY	4047222
MILGE	4222
MTRL_COST	

TOT_COST_GRO	143.41
LRR_HRS	14
DLR_CD	7479
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
Rating	b
CPSC_CD_6	11001
TECH_TXT1	DEFECTIVE SEAT BELT REMOVE THE OLD BELT AND INSTALL NEW SEAT BELT
TECH_TXT2	
CUST_TXT	OWNER STATES THE RIGHT FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	724
COUNTRY_CD	USA
SLS_DLR_CD	144414
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S00
TIS_FLAG	

ID	171
MDL_YR	2001
SORT_INDEX	581
VIN_CD	1FTZR15E41
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	TRE0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/17/2001
WRTY_START_D	6/11/2001
NAME	TOUSLEY FORD, INC.
DOC_NUM	407128B
PH_NUM	4847231
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/02/2001
TIS_WSD	6
CLM_KEY	4325023
MILGE	6556
MTRL_COST	

TOT_COST_GRO	168.42
LBR_HRS	0.00
DLR_CD	9372
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	VERIFIED, TESTED BOT BUCKLES, BOTH FAILED. REPLACED BOTH BUCKELS AND RETEST
TECH_TXT2	
CUST_TXT	CHECK RIGHT SEAT BELT BUCKLE COMES UNHOOKED WHILE DRIVING
AREA_CD	051
COUNTRY_CD	USA
SLS_DLR_CD	158015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	172
MDL_YR	2001
SORT_INDEX	582
VIN_CD	1FTZR15E41T
LBR_COST	
VEH_LINE_CD	T/FB
MKT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	8/16/2001
NAME	VARSITY FORD
DOC_NUM	13888201
PH_NUM	8882300
WCC_CD	BFD2
PART_NUM_CA	1152
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	540
COND_CD	33
RPR_DT	9/19/2001
TIS_WSD	2
CLM_KEY	3853121
MILGE	2511
MTRL_COST	

TOT_COST_GRO	0623
LBR_HRS	64
DLR_CD	2738
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	REPLACE RT FRONT SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	RIGHT SEAT BELT COMES UNBUCKLED INTERMITTENTLY CUSTOMER IS WAITING
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	148428
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	173
MDL_YR	2001
SORT_INDEX	583
VIN_CD	1FTZR1GE41T
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TIEF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	4/5/2001
WRTY_START_D	7/15/2001
NAME	THE FREDERICK MOTOR COMPANY
DOC_NUM	327340E
PH_NUM	6838111
WCC_CD	0R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUSY_CONC_C	640
COND_CD	42
RPR_DT	10/24/2001
TIS_WSD	4
CLM_KEY	4813053
MILGE	9197
MTRL_COST	

TOT_COST_GRO	107.88
LBR_HRS	9.7
DLR_CD	42
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MD
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	9107 R&R RIGHT SEAT, REPLACE RIGHT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES R F SEAT BELT POPS LOOSE OUT OF BUCKLE
AREA_CD	201
COUNTRY_CD	USA
SLS_DLR_CD	127414
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	174
MDL_YR	2001
SORT_INDEX	685
VIN_CD	1FTZR15E41T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/4/2001
WRTY_START_D	4/27/2001
NAME	BELL FORD
DOC_NUM	7451208
PH_NUM	8881778
WCC_CD	0F02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	320
COND_CD	83
RPR_DT	3/22/2002
TIS_WSD	11
CLM_KEY	787726
MILGE	13675
MTRL_COST	

TOT_COST_GRO	8584
LBR_HRS	34
DLR_CD	20360
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPL RF SEAT BELT ASSY.
TECH_TXT2	
CUST_TXT	RF SEATBELT ASSY WILL NOT STAY LATCHED
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	17177
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	175
MDL_YR	2001
SORT_INDEX	588
VIN_CD	1FTZR15E41
LBR_COST	
VEH_LINE_CD	TTR3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	TE
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/3/2001
WRTY_START_D	8/21/2001
NAME	WAYNE COUNTY FORD
DOC_NUM	0134808
PH_NUM	2521567
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S28
COND_CD	42
RPR_DT	6/9/2002
TIS_WSD	6
CLM_KEY	8583828
MILGE	14235
MTRL_COST	

TOT_COST_GRO	78.87
LBR_HRS	3.44
DLR_CD	1417
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	CHECK LATCHING OF PASS SIDE SEAT BELT, FOUND THA IF YOU PULLED ON BUCKLE, SEAT BELT POPS OUT, REMOVE AND REPLACE NEW SEAT BELT BUCKLE AND RE CHECK OPE RATION
TECH_TXT2	
CUST_TXT	PASS SIDE SEAT BELT BUCKLE DOES NOT STAY CLIPPED
AREA_CD	570
COUNTRY_CD	USA
SLS_DLR_CD	115488
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	178
MDL_YR	2001
SORT_INDEX	801
VIN_CD	1FTZR16E41F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/R3C
PLANT_CD	AX
PRODN_DT	7/18/2001
WRTY_START_D	10/30/2001
NAME	LEGACY FORD LINCOLN MERCURY
DOC_NUM	6318501
PH_NUM	0032161
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/17/2001
TIS_WSD	0
CLM_KEY	4532003
MILGE	878
MTRL_COST	

TOT_COST_GRO	191.9
LBR_HRS	0.0
DLR_CD	1881
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OR
Ratings	#
CPSC_CD_6	11001
TECH_TXT1	
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKELS WONT LATCH ON PS AND DS BUCKELS
AREA_CD	541
COUNTRY_CD	USA
SLS_DLR_CD	174487
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRI_CD	808
TIS_FLAG	

ID	177
MDL_YR	2001
SORT_INDEX	602
VIN_CD	1FTZR15E41P
LBR_COST	
VEH_LINE_CD	T/R3
MRT_DERIVED	
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	6/20/2001
WRTY_START_D	8/14/2001
NAME	LUNDE FORD LINCOLN MERCURY
DOC_NUM	048872A
PH_NUM	8472801
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	L15
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	2821021
MILGE	10
MTRL_COST	

TOT_COST_GRO	78.38
LRR_HRS	0.4
DLR_CD	2862
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	CHECK OUT RIGHT SEAT BELT BUCKLE WILL NOT LATCH, CHECK OUT NOT INVOLVED IN RECALL 01821, REMOVE AND REPLACE SEAT BELT LATCH ASSEMBLY
TECH_TXT2	
CUST_TXT	RH SEAT BELT BUCKLE WONT LATCH..NOT INVOLVED IN 01821 RECALL
AREA_CD	218
COUNTRY_CD	USA
SLS_DLR_CD	158402
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V07
AWS_VL_CD	R1
VRT_CD	908
TIS_FLAG	

ID	178
MDL_YR	2001
SORT_INDEX	605
VIN_CD	1FTZR15E41F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	8/25/2001
WRTY_START_D	8/27/2001
NAME	DEE THOMASON FORD
DOC_NUM	67128101
PH_NUM	6553355
WCC_CD	6/RD2
PART_NUM_CA	1LSZ
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	42
RPR_DT	8/7/2001
TIS_WSD	0
CLM_KEY	3560544
MILGE	4
MTRL_COST	

TOT_COST_GRO	162.46
LBR_HRS	1.4
DLR_CD	8575
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OR
Ratings	A
CPSC_CD_6	11001
TECH_TXT1	REPAIR AND REPLACE THE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE NOT WORKING CORRECTLY
AREA_CD	G03
COUNTRY_CD	USA
SLS_DLR_CD	174023
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	170
MDL_YR	2001
SORT_INDEX	007
VIN_CD	1FTZR15E41F
LBR_COST	35588
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	07/02/2001
WRTY_START_D	08/02/2001
NAME	ATWATER FORD INC
DOC_NUM	5433041
PH_NUM	9740011
WCC_CD	0R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S20
COND_CD	42
RPR_DT	2/15/2002
TIS_WSD	7
CLM_KEY	7056736
MILGE	4878
MTRL_COST	

TOT_COST_GRO	97.78
LBR_HRS	0.7
DLR_CD	9227
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	REPLACE LEFT SEAT BELT BUCKLE, WILL NOT LATCH. HAD BEEN REPLACED UNDER 01S21 RECALL.
TECH_TXT2	
CUST_TXT	L.F. SEAT BELT CANNOT BE BUCKLED.
AREA_CD	320
COUNTRY_CD	USA
SLS_DLR_CD	158505
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	906
TIS_FLAG	

ID	180
MDL_YR	2001
SORT_INDEX	008
VIN_CD	1FTZR16E41P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/T0
PLANT_CD	AX
PRODN_DT	5/1/2001
WRTY_START_D	9/28/2001
NAME	FORD COUNTRY
DOC_NUM	2809153
PH_NUM	5063073
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1051203
PART_NUM_CA	AAA
CUST_CONC_C	B40
COND_CD	42
RPR_DT	3/30/2002
TIS_WSD	7
CLM_KEY	7701041
MILGE	15708
MTRL_COST	

TOT_COST_GRO	121.26
LBR_HRS	0.9
DLR_CD	1440
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NV
Ratings	
CPSC_CD_6	11001
TECH_TXT1	CHECK OUT CONCERN , R&R DRIVER SEAT 40 80 SPLIT BENCH R&R SEAT BELT BUCKLE , INSTALLED NEW SEAT BELT BUCKLE , PUT SEAT BACK IN TRUCK , OLD BUCKEL WONT LATCH SEAT BELT , QC NEW SEAT BELT BUCKLE WORKING
TECH_TXT2	OK , PART # 81203
CUST_TXT	DRIVERS SEAT BELT WILL NOT LATCH
AREA_CD	702
COUNTRY_CD	USA
SLS_DLR_CD	171188
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	181
MDL_YR	2001
SORT_INDEX	811
VIN_CD	1FTZR18E41
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/18/2001
WRTY_START_D	6/8/2001
NAME	TOMBOLAND FORD, INC.
DOC_NUM	0446088
PH_NUM	2219950
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	825
COND_CD	1
RPR_DT	11/14/2001
TIS_WSD	7
CLM_KEY	5558792
MILGE	12340
MTRL_COST	

TOT_COST_GRO	7835
LBR_HRS	04
DLR_CD	3203
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	12340 BROKEN RIGHT FRONT SEAT BELT BUCKLE WILL NOT LATCH, PO REPLACE PASS. SEAT BELT BUCKLE CLOSED BY WPI
TECH_TXT2	
CUST_TXT	PASS SEATBELT WILL NOT STAY HOOKED
AREA_CD	873
COUNTRY_CD	USA
SLS_DLR_CD	153373
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	182
MDL_YR	2001
SORT_INDEX	618
VIN_CD	1FTZR16E41F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/22/2001
WRTY_START_D	8/17/2001
NAME	DAVE HOLT FORD-MERCURY, INC.
DOC_NUM	11862803
PH_NUM	3862334
WCC_CD	0R02
PART_NUM_CA	1L3Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	2/6/2002
TIS_WSD	6
CLM_KEY	6788506
MILGE	8132
MTRL_COST	

TOT_COST_GRO	166.57
LBR_HRS	EA
DLR_CD	9483
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WI
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	INSPECT REPLACED SEAT BELT BUCKLE DRIVERSIDE
TECH_TXT2	
CUST_TXT	DRIVERSIDE SEAT BELT DOES NOT BUCKLE
AREA_CD	715
COUNTRY_CD	USA
SLS_DLR_CD	156031
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	183
MDL_YR	2001
SORT_INDEX	617
VIN_CD	1FTZR16E41P
LBR_COST	
VEH_LINE_CD	TRB
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TEF
DRIVE_CD	TAE
ENG_CD	TAE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	2/27/2001
WRTY_START_D	3/5/2001
NAME	ADAMSON LINCOLN-MERCURY
DOC_NUM	020514C
PH_NUM	2894004
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	1/14/2002
TIS_WSD	11
CLM_KEY	0299970
MILGE	8822
MTRL_COST	

TOT_COST_GRO	88.7
LBR_HRS	84
DLR_CD	12508
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT SEAT BELT WONT ALWAYS LATCH
AREA_CD	507
COUNTRY_CD	USA
SLS_DLR_CD	18828
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	184
MDL_YR	2001
SORT_INDEX	819
VIN_CD	1FTZR15E41F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/11/2001
WRTY_START_D	9/12/2001
NAME	WESTLAND FORD
DOC_NUM	10327701
PH_NUM	3948803
WCC_CD	BRD2
PART_NUM_CA	1L5Z
PART_NUM_CA	1051202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPE_DT	11/3/2001
TIS_WSD	2
CLM_KEY	4927364
MILGE	2182
MTRL_COST	

TOT_COST_GRO	139.14
LBR_HRS	14.8
DLR_CD	8430
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LT
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	1 REPLACED THE FRONT PASSENGER SIDE SEAT BELT 01203 42
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PERFORM RECALL ON THE SEAT BELT BUCKLES SEAT BELT BUCKLES COME UNDONE
AREA_CD	B01
COUNTRY_CD	USA
SLS_DLR_CD	156558
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	186
MDL_YR	2001
SORT_INDEX	621
VIN_CD	1FTZR15E41F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	1/18/2001
WRTY_START_D	3/2/2001
NAME	FAIRLANE FORD SALES, INC.
DOC_NUM	111888B
PH_NUM	8485000
WCC_CD	BR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/28/2001
TIS_WSD	10
CLM_KEY	5426394
MILGE	11348
MTRL_COST	

TOT_COST_GRO	8844
LBR_HRS	028
DLR_CD	3050
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	2
CPSC_CD_6	11001
TECH_TXT1	11348 42 61203 CK VECH FOR CONCERN REPLACE SEAT BELT FEMALE END WONT ALWAYS BUCKET BELT ENF WAS REPLACED UNDER RECALL RECK OK
TECH_TXT2	
CUST_TXT	840 PASS SEAT BELT WONT BUCKLE INTERMITTENLY DIAG AND ADVISE
AREA_CD	313
COUNTRY_CD	USA
SLS_DLR_CD	149024
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	188
MDL_YR	2001
SORT_INDEX	829
VIN_CD	1FTZR15E41P
LBR_COST	
VEH_LINE_CD	YR3
MKT_DERIVED	
BOD_CAB_STL	T80
VER_SERIES_C	TEF
DRIVE_CD	TE
ENG_CD	TNE
TRANS_CD	YTC
PLANT_CD	AX
PRODN_DT	11/8/2000
WRTY_START_D	1/7/2001
NAME	COURTESY FORD
DOC_NUM	7888701
PH_NUM	2551771
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	2/7/2002
TIS_WSD	14
CLM_KEY	7058294
MILGE	19778
MTRL_COST	

TOT_COST_GRO	132.00
LBR_HRS	
DLR_CD	8802
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OR
Ratings	A
CPSC_CD_6	11001
TECH_TXT1	VERIFIED CUSTOMER CONCERN DEACTIVATED SAFETY RESTRAINT SYSTEM REMOVED SEAT AND REPLACED RECEPTACLE ASSEMBLY REINSTALLED AND RETESTED OKAY AFTER REPAIRS
TECH_TXT2	
CUST_TXT	CUSTOMER REPORTS DRIVERS SIDE SEATBELT WONT BUCKLE
AREA_CD	803
COUNTRY_CD	USA
SLS_DLR_CD	174028
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	187
MDL_YR	2001
SORT_INDEX	638
VIN_CD	1FTZR15E31T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/T0
PLANT_CD	AG
PRODN_DT	3/27/2001
WRTY_START_D	4/30/2001
NAME	LIBERTY FORD SOUTHWEST, INC.
DOC_NUM	058587A
PH_NUM	8882600
WCC_CD	8R02
PART_NUM_CA	1L52
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	6/4/2002
TIS_WSD	14
CLM_KEY	0017840
MILGE	10500
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	3273
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEATBELT LATCH
TECH_TXT2	
CUST_TXT	C S THAT THE PASSENGER FRONT SEATBELT WILL NOT LATCH INTERIOR TRIM IS ET.
AREA_CD	440
COUNTRY_CD	USA
SLS_DLR_CD	144127
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	@

ID	188
MDL_YR	2001
SORT_INDEX	843
VIN_CD	1FTZR15E31
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BO
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	1/19/2001
WRKY_START_D	2/22/2001
NAME	EBY FORD SALES, INC.
DOC_NUM	141458E
PH_NUM	8343873
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/8/2001
TIS_WSD	7
CLM_KEY	4348485
MILGE	6700
MTRL_COST	

TOY_COST_GRO	1800
LBR_HRS	0.4
DLR_CD	4783
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	6725 BUCKLE 42 REMOVED THE DRIVERS SIDE SEAT REPLACED THE DRIV ERSIDE SEAT BELT BUCKLE ASSEMBLY REASSEMBLED VE HICLE SEAT BELT BUCKLE LATCHES PROPERLY NOW.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEAT BELT DOESNT LATCH PROPERLY
AREA_CD	219
COUNTRY_CD	USA
SLS_DLR_CD	148202
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	

ID	188
MDL_YR	2001
SORT_INDEX	844
VIN_CD	1FTZR15E31T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	1/10/2001
WRTY_START_D	6/29/2001
NAME	DAN BUCKEY FORD, INC.
DOC_NUM	588001
PH_NUM	3623033
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	10/23/2001
TIS_WSD	4
CLM_KEY	5414475
MILGE	2482
MTRL_COST	

TOT_COST_GRO	614.06
LBR_HRS	0.7
DLR_CD	20633
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	REPLACE DEFECTIVE BUCKLE ASSY
TECH_TXT2	
CUST_TXT	CUST STATES WHEN PULLING IN SEAT BELT LATCH,BELT RELEASES
AREA_CD	845
COUNTRY_CD	USA
SLS_DLR_CD	113483
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	190
MDL_YR	2001
SORT_INDEX	653
VIN_CD	1FTZR16E31F
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	T80
VER_SERIES_C	T1EF
DRIVE_CD	T1E
ENG_CD	T1NE
TRANS_CD	T1TC
PLANT_CD	AX
PRODN_DT	7/24/2001
WRTY_START_D	8/22/2001
NAME	RAMIREZ FORD SALES, INC.
DOC_NUM	5808751
PH_NUM	4872582
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	3/27/2002
TLS_WSD	B
CLM_KEY	7710085
MILGE	14686
MTRL_COST	

TOT_COST_GRO	150.73
LBR_HRS	1.3
DLR_CD	4448
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Ratings	8
CPSC_CD_6	11001
TECH_TXT1	WONT LATCH VERIFY CONCERN REPLACED DRIVER SIDE BUCKLE OK THIS TIME
TECH_TXT2	
CUST_TXT	OK LEFT SEAT BELT
AREA_CD	958
COUNTRY_CD	USA
SLS_DLR_CD	152124
TXN_CD	E54
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	191
MDL_YR	2001
SORT_INDEX	660
VIN_CD	1FTZR16E31F
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/18/2001
WRTY_START_D	4/26/2001
NAME	NEW BRIGHTON FORD, INC.
DOC_NUM	1111501
PH_NUM	8339010
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1051203
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	41
RPR_DT	8/4/2002
TIS_WSD	14
CLM_KEY	9101400
MILGE	16268
MTRL_COST	

TOT_COST_GRO	144.00
LBR_HRS	4.1
DLR_CD	8452
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	6
CPSC_CD_6	11001
TECH_TXT1	CG 33 LATCH WONT STAY LATCHED CHECK BEAT BELTS. WILL NOT LATCH, REPLACE DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	CERTAIN 2001 MODEL YEAR CROWN VIC EXCURSION EXPEDITION F160 F250 F350 GRAND MARQUIS NAVIGATOR RANGER TOWN CAR AND
AREA_CD	651
COUNTRY_CD	USA
SLS_DLR_CD	158015
TXN_CD	E84
CNTRY_SOLD	USA
QRY_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	@

ID	182
MDL_YR	2001
SORT_INDEX	652
VIN_CD	1FTZR15E31F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	4/12/2001
WRTY_START_D	7/17/2001
NAME	ORCHID ISLE AUTO CENTER
DOC_NUM	5833651
PH_NUM	9351181
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	1/7/2002
TIS_WSD	8
CLM_KEY	6150007
MILGE	15483
MTRL_COST	

Tuesday, December 14, 2004

Page 383 of 559

TOT_COST_GRO	161.21
LBR_HRS	0.6
DLR_CD	7761
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	HI
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	BINDS INTERMITTENT LATCH MT REPLACE FRONT SEATBELT BUCKLES
TECH_TXT2	
CUST_TXT	FRONT SEAT BELTS DONT LATCH PROPERLY SPO
AREA_CD	B08
COUNTRY_CD	USA
SLS_DLR_CD	172414
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	103
MDL_YR	2001
SORT_INDEX	883
VIN_CD	1FTZR15E31F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B3
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/T3
PLANT_CD	AX
PRODN_DT	3/15/2001
WRTY_START_D	5/11/2001
NAME	RITCHART FORD
DOC_NUM	7682801
PH_NUM	680555
WCC_CD	6R02
PART_NUM_CA	1L52
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	10/23/2001
TIS_WSD	6
CLM_KEY	4752128
MILGE	4067
MTRL_COST	

TOT_COST_GRO	2873
LBR_HRS	138
DLR_CD	9229
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MIN
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	1 CUSTOMER STATES FRONT SETA BELTS DO NOT LATCH REMOVED PASSENGER SEAT AND CARPET AND REPLACED PASSENGER SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES SEAT BELT IN FRONT WILL NOT HOLD OR STAY LATCHED
ABKA_CD	783
COUNTRY_CD	USA
SLS_DLR_CD	158670
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	194
MDL_YR	2001
SORT_INDEX	608
VIN_CD	1FTZR15E31F
LRR_COST	34.2
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/10/2001
WRTY_START_D	6/11/2001
NAME	NORTH COUNTRY FORD
DOC_NUM	8225002
PH_NUM	4271120
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	1/14/2002
TIS_WSD	6
CLM_KEY	8284871
MILGE	0206
MTRL_COST	

TOT_COST_GRO	2841
LBR_HRS	204
DLR_CD	2733
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	VERIFY THE CONCERN WITH THE PASS FRONT SEAT BELT BUCKLE. REPLACED THE PASS FRONT SEAT BELT BUCKLE. HAD TO RR THE 1
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEATBELT COMES UN BUCKLED AT TIMES
AREA_CD	79S
COUNTRY_CD	USA
SLS_DLR_CD	158018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	106
MDL_YR	2001
SORT_INDEX	009
VIN_CD	1FTZR1BE31F
LBR_COST	
VEH_LINE_CD	T/RS
MKT_DERIVED	*
BOD_CAR_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/4/2001
WRTY_START_D	7/18/2001
NAME	MIKE NAUGHTON FORD, INC.
DOC_NUM	14177303
PH_NUM	3431800
WCC_CD	0R02
PART_NUM_CA	1L8Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	42
RPR_DT	4/8/2002
TIS_WSD	9
CLM_KEY	8401784
MILGE	5953
MTRL_COST	

TOT_COST_GRO	05-12
LBR_HRS	04
DLR_CD	3278
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
Ratings	G
CPSC_CD_6	11001
TECH_TXT1	REPLACE SEAT BELT BUCKEL
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEAT BELT COMES UMLATCHED WHILE DRIVING
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	158008
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	199
MDL_YR	2001
SORT_INDEX	670
VIN_CD	1FTZR15E31F
LBR_COST	
VEH_LINE_CD	TRE
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TRE
DRIVE_CD	TRE
ENG_CD	TRE
TRANS_CD	TTC
PLANT_CD	AX
PRODN_DT	1/28/2001
WRTY_START_D	2/26/2001
NAME	HAWKINS-MARSH FORD
DOC_NUM	024638A
PH_NUM	6274861
WCC_CD	BRC2
PART_NUM_CA	1L6Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	4/28/2002
TIS_WSD	16
CLM_KEY	8518190
MILGE	11429
MTRL_COST	

TOY_COST_GRO	389.9
LBR_HRS	
DLR_CD	3383
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IA
Ratings	
CPSC_CD_6	11001
TECH_TXT1	REPLACED SEATBELT ASSY
TECH_TXT2	
CUST_TXT	CUST STATES PASSENGER SEASELT WILL NOT LATCH
AREA_CD	712
COUNTRY_CD	USA
SLS_DLR_CD	188883
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	197
MDL_YR	2001
SORT_INDEX	876
VIN_CD	1FTZR15E31F
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	T/E
DRIVE_CD	T/E
ENG_CD	T/E
TRANS_CD	T/SC
PLANT_CD	AX
PRODN_DT	11/30/2000
WRTY_START_D	1/15/2001
NAME	JOE HAYWARD FORD
DOC_NUM	620071
PH_NUM	6238261
WCC_CD	GR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	340
COND_CD	42
RPR_DT	1/15/2002
TIS_WSD	13
CLM_KEY	6552838
MILGE	13837
MTRL_COST	

Tuesday, December 14, 2004

Page 393 of 550

TOT_COST_GRO	88.1
LBR_HRS	0.2
DLR_CD	8637
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OR
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACE PASSENGER SEAT BELT FRONT BUCKLE.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES P/S SEATBELT WONT STAY LATCHED AT TIMES.
AREA_CD	508
COUNTRY_CD	USA
SLS_DLR_CD	174413
TXN_CD	EM
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	198
MDL_YR	2001
SORT_INDEX	685
VIN_CD	1FTZR15E21T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	8/18/2001
WRTY_START_D	7/9/2001
NAME	FAIRLANE FORD SALES, INC.
DOC_NUM	113173C
PH_NUM	8485000
WCC_CD	6R02
PART_NUM_CA	1LEZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	6
CLM_KEY	5898008
MILGE	0056
MTRL_COST	

TOT_COST_GRO	385.48
LBR_HRS	064
DLR_CD	3060
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
Ratings	
CPSC_CD_6	11001
TECH_TXT1	0009 41 01203 1.3 CK SEAT BUCKLE NISS TO R R SEAT AND REPLACE BUCKLE ASSY 80 40 WITH PRETENS THIS IS BUCKLE END NOT SEAT BELT ASSY
TECH_TXT2	
CUST_TXT	840 DRIVERS SEAT BELT WONT BUCKLE DIAG \$36.00
AREA_CD	319
COUNTRY_CD	USA
SLS_DLR_CD	140020
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	199
MDL_YR	2001
SORT_INDEX	688
VIN_CD	1FTZR15E21T
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	T/F
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	4/10/2001
WRTV_START_D	4/30/2001
NAME	HAYES FORD, INC.
DOC_NUM	6248901
PH_NUM	3348667
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	S2E
COND_CD	63
RPR_DT	4/13/2002
TIS_WSD	12
CLM_KEY	8202548
MILGE	11748
MTRL_COST	

Tuesday, December 14, 2004

Page 397 of 558

RQ04-011 E 1872

TOT_COST_GRO	8234
LBR_HRS	
DLR_CD	8002
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VT
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	SEATBELT LATCH ASSEMBLY WEAK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT DOESNT STAY LATCHED
AREA_CD	802
COUNTRY_CD	USA
SLS_DLR_CD	111802
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	200
MDL_YR	2001
SORT_INDEX	688
VIN_CD	1FTZR15E21
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/23/2001
WRTY_START_D	4/21/2001
NAME	HOPKINS FORD INC
DOC_NUM	13773901
PH_NUM	2244550
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081208
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	2/12/2002
TIS_WSD	10
CLM_KEY	6837347
MILGE	10252
MTRL_COST	

TOT_COST_GRO	10708
LBR_HRS	65
DLR_CD	1308
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	DS SEATBELT BUCKLE WONT ATTATCH INOP REMOVE SEAT TO ACCESS BUCKLE R R BUCKLEASBY MT61203 REPL
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT WILL NOT LOCK. SPECIAL ORDER BUCKLE IS HERE.
AREA_CD	215
COUNTRY_CD	USA
SLS_DLR_CD	116017
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	201
MDL_YR	2001
SORT_INDEX	681
VIN_CD	1FTZR1GE21T
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/12/2001
WRTY_START_D	6/23/2001
NAME	COURTESY FORD-LINCOLN-MERCURY
DOC_NUM	4893301
PH_NUM	3710380
WCC_CD	BRD2
PART_NUM_CA	1L6Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	12
RPR_DT	7/5/2001
TIS_WSD	1
CLM_KEY	2586503
MILGE	379
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	7223
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NE
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	CHECKED OGER & REPLACED SEAT BELT BUCKLE & RETEST
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNLATCHED BY MYSELF
AREA_CD	402
COUNTRY_CD	USA
SLS_DLR_CD	158410
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	608
TIS_FLAG	

ID	202
MDL_YR	2001
SORT_INDEX	694
VIN_CD	1FTZR15E21T
LBR_COST	
VEH_LINE_CD	TFR8
MKT_DERIVED	
BOD_CAB_STL	TBD
VER_SERIES_C	TAF
DRIVE_CD	TE
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	12/4/2000
WRTY_START_D	5/1/2001
NAME	SUNTRUP FORD CITY
DOC_NUM	108029A
PH_NUM	4294455
WCC_CD	BRD2
PART_NUM_CA	1L6Z
PART_NUM_CA	1081208
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	5/6/2002
TIS_WSD	12
CLM_KEY	8450800
MILGE	11437
MTRL_COST	

TOT_COST_GRO	90.8
LBR_HRS	0.4
DLR_CD	4125
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	VERIFIED NEEDS DRIVERS SEATBELT BUCKLE LATCH REPL LATCH AND TEST OPERATION
TECH_TXT2	
CUST_TXT	G S THAT DRIVER SIDE SEAT BELT IS NOT LATCHING
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	153074
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	203
MDL_YR	2001
SORT_INDEX	700
VIN_CD	1FTZR15E21T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	10/16/2000
WRTY_START_D	12/30/2000
NAME	SCOTT MCNAMARA FORD-MERCURY, I
DOC_NUM	9105404
PH_NUM	2758922
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1051203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/30/2001
TIS_WSD	8
CLM_KEY	4849750
MILGE	8278
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	2608
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACE THE FAILED BUCKLE
TECH_TXT2	
CUST_TXT	SEATBELT JUST RELEASED
AREA_CD	668
COUNTRY_CD	USA
SLS_DLR_CD	148608
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	806
TIS_FLAG	

ID	204
MDL_YR	2001
SORT_INDEX	702
VIN_CD	1FTZR1GE21T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/E
ENG_CD	T/NE
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	10/18/2000
WRTY_START_D	11/18/2000
NAME	ED MULLINAX FORD INC
DOC_NUM	153145A
PH_NUM	8842431
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	839
COND_CD	42
RPR_DT	8/13/2001
TIS_WSD	10
CLM_KEY	3114192
MILGE	9044
MTRL_COST	

TOT_COST_GRO	111.25
LBR_HRS	0.2
DLR_CD	2283
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	9044 REMOVED DRIVERS SEAT FROM VEHICLE. REMOVED SEAT BELT BUCKLE AND REPLACED BUCKLE FROM A STOCK UNIT. INSTALLED NEW BUCKLE ON CUST SEAT AND REINSTALLED SEAT IN VEHICLE AND TESTED. OK AT THIS TIME
TECH_TXT2	. WAITING FOR ORDERED BUCKLE TO INSTALL BACK IN STOCK UNIT.
CUST_TXT	CUSTOMER STATES DRIVER SIDE SEAT BELT UNBUCKLES WHILE DRIVING. DID HAVE REGALL PREFORMED
AREA_CD	215
COUNTRY_CD	USA
SLS_DLR_CD	144677
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	205
MDL_YR	2001
SORT_INDEX	711
VIN_CD	1FTZR15E21T
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	*
BOD_CAR_STL	T8D
VER_SERIES_C	T7EF
DRIVE_CD	T7E
ENG_CD	T7NE
TRANS_CD	T7TC
PLANT_CD	AG
PRODN_DT	5/24/2000
WRTY_START_D	9/14/2000
NAME	NORRIS FORD OF EASTON, LLC
DOC_NUM	2241251
PH_NUM	8222800
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	9/10/2001
TIS_WSD	13
CLM_KEY	3957222
MILGE	10970
MTRL_COST	

Tuesday, December 14, 2004

Page 409 of 550

TOT_COST_GRO	61.11
LBR_HRS	36
DLR_CD	3800
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MD
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	D & SEAT BELT ASSEMBLY FRONT REPLACE SEATBELT ASSEMBLY
TECH_TXT2	
CUST_TXT	CUST STATES SINCE THE RECALL WAS DONE ON THE SEAT BELTS, THE SEAT BELT WILL COME UNDONE ON THERE OWN FULL HISTORY
AREA_CD	410
COUNTRY_CD	USA
SLS_DLR_CD	127568
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	G21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	B05
TIS_FLAG	