

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 6 OF 6

BOOK 3 OF 43

TOT_COST_GRO	129.82
LBR_HRS	
DLR_CD	2188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
Ratings	b
CPSC_CD_6	13001
TECH_TXT1	VERIFIED CUSTOMERS CONCERN SEAT BELT BUCKLE WILL NOT STAY LATCHED R AND R PASSENGER SEAT TO REPLACE SEAT BELT BUCKLE REPLACED AND RECHECK ALL OK AT THIS TIME
TECH_TXT2	
CUST_TXT	PASS FRONT SEAT BELT WILL NOT STAY LATCHED POPS OPEN WHILE DRIVING
AREA_CD	216
COUNTRY_CD	USA
SLS_DLR_CD	127043
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	296
MDL_YR	2001
SORT_INDEX	900
VIN_CD	1FTYR14VX1
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/R
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/12/2001
WRTY_START_D	4/27/2001
NAME	BUDGET RAC - PHOENIX
DOC_NUM	4057631
PH_NUM	*
WCC_CD	6R02
PART_NUM_CA	1LSZ
PART_NUM_CA	10B1202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPE_DT	7/12/2001
TES_WSD	3
CLM_KEY	2708471
MILGE	5810
MTRL_COST	

TOT_COST_GRO	4431
LBR_HRS	
DLR_CD	48022
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	FAULTY SEAT BELT RECEPTACLE REPL
TECH_TXT2	
CUST_TXT	PASS SEAT BELT WONT STAY BUCKLED
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	124125
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S06
TIS_FLAG	

ID	257
MDL_YR	2001
SORT_INDEX	002
VIN_CD	1FTYR14VK1F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/R0
VER_SERIES_C	T/EP
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/29/2001
WRTY_START_D	4/18/2001
NAME	BUDGET RAC - ROMULUS
DOC_NUM	2835281
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	B25
COND_CD	42
RPR_DT	11/28/2001
TIS_WSD	0
CLM_KEY	5690674
MILGE	21700
MTRL_COST	

TOT_COST_GRO	4218
LRR_HRS	9.8
DLR_CD	45307
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
Ratings	#
CPSC_CD_6	11001
TECH_TXT1	RF SEATBELT WONT LATCH INTERNAL PROBLEM WITH BUCKLE REPLACED SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	124326
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	258
MDL_YR	2001
SORT_INDEX	904
VIN_CD	1FTYR14VX1F
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/F
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/T
PLANT_CD	AX
PRODN_DT	4/2/2001
WRTY_START_D	4/17/2001
NAME	BUDGET RAC - OAKLAND
DOC_NUM	8851361
PH_NUM	
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	826
COND_CD	42
RPR_DT	3/13/2002
TIS_WSD	12
CLM_KEY	7580934
MILGE	282A6
MTRL_COST	

TOT_COST_GRO	43
LBR_HRS	
DLR_CD	45186
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
Ratings	
CPSC_CD_6	11001
TECH_TXT1	SEAT BUCKLE WILL NOT LATCH. INTERNAL MECHANISM FAILURE. REPL
TECH_TXT2	
CUST_TXT	PASS SEAT BELT INOP
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	171227
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	259
MDL_YR	2001
SORT_INDEX	908
VIN_CD	1FTYR14VX1F
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/30/2001
WRYY_START_D	4/25/2001
NAME	BUDGET RAC - RALEIGH/DURHAM
DOC_NUM	80903201
PH_NUM	*
WCC_CD	6R02
PART_NUM_CA	115Z
PART_NUM_CA	1061203
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	7/7/2001
TIS_WSD	3
CLM_KEY	2378871
MILGE	8605
MTRL_COST	

TOT_COST_GRO	<input type="text" value="10743"/>
LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="48138"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NG"/>
Ratings	<input type="text" value="a"/>
CPSC_CD_6	<input type="text" value="11001"/>
TECH_TXT1	<input type="text" value=""/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DR SEAT BELT WONT LATCH SEAT BELT BUCKLE"/>
AREA_CD	<input type="text" value=""/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124328"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="R1"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

ID	280
MDL_YR	2001
SORT_INDEX	818
VIN_CD	1FTYR14V011
LBR_COST	
VEH_LINE_CD	TFC
MKT_DERIVED	*
BOD_CAB_STL	TBD
VER_SERIES_C	TFF
DRIVE_CD	TB
ENG_CD	TAA
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	6/28/2001
WRTY_START_D	7/13/2001
NAME	BUDGET RAC - MIAMI
DOC_NUM	8009471
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	115Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONG_C	S28
COND_CD	42
RPR_DT	4/17/2002
TIS_WSD	10
CLM_KEY	8255646
MILGE	28007
MTRL_COST	

Tuesday, December 14, 2004

Page 519 of 558

TOT_COST_GRO	117.83
LBR_HRS	1.4
DLR_CD	46282
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Ratings	0
CPSC_CD_6	11001
TECH_TXT1	DRIVER SEAT BELT BUCKLE WONT LOCK DUE TO INTERNAL MECHANISM FAILURE R AND R THE LF SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	SEAT BELT INOP
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	124325
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

ID	281
MDL_YR	2001
SORT_INDEX	817
VIN_CD	1FTYR14V91T
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	8/28/2001
WRYY_START_D	7/27/2001
NAME	BLOOMINGTON FORD, INC.
DOC_NUM	1417208
PH_NUM	3312200
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/6/2001
TIS_WSD	1
CLM_KEY	2802157
MILGE	748
MTRL_COST	

TOT_COST_GRO	1967
LBR_HRS	
DLR_CD	4881
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	748 DUPLICATE CUST CONCERN. PROBLEM DETERMINED TO BE IN BUCKLE ASSY. ORDER REPLACEMENT. REMOVE SEAT ASSY. REMOVE AND REPLACE SEAT BLET BUCKLE ASSY. RETEST. ALL OKAY. NGS TEST SYSTEM DUE TO BUCKLE BE
TECH_TXT2	ING PART OF SRS SYSTEM. CLEAR CODES. RETEST. ALL OKAY. 0020
CUST_TXT	CUSTOMER STATES DRIVERS SIDE SEATBELT COMES UNLATCHED. CHECK AND ADVISE
AREA_CD	812
COUNTRY_CD	USA
SLS_DLR_CD	147574
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AW3_VL_CD	R1
VRT_CD	B08
TIS_FLAG	

ID	262
MDL_YR	2001
SORT_INDEX	920
VIN_CD	1FTYR14V81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/R
ENG_CD	T/LA
TRANS_CD	T/TTC
PLANT_CD	AG
PRODN_DT	5/17/2001
WRTY_START_D	7/18/2001
NAME	DUVAL FORD
DOC_NUM	2084361
PH_NUM	3878641
WCC_CD	6F02
PART_NUM_CA	1L6Z
PART_NUM_CA	1001202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	12/6/2001
TIS_WSD	3
CLM_KEY	5808008
MILGE	12924
MTRL_COST	

TOT_COST_GRO	37473
LBR_HRS	0.0
DLR_CD	4883
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	CK. FOR CONCERN, FOUND SEAT BELTS WOULD NOT LATCH. REMOVE BETH FT, SEATS REMOVE LOWER SEAT COVERS, REMOVE SEAT BELT, REMOVE WIRING HARNESS REPLACE SEAT BELTS, ALL O.K. CC 42
TECH_TXT2	
CUST_TXT	CUST STATES PASS FRM SEAT BELT WONT LOCK IN. SPO HERE
AREA_CD	804
COUNTRY_CD	USA
SLS_DLR_CD	124600
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S05
TIS_FLAG	

ID	283
MDL_YR	2001
SORT_INDEX	924
VIN_CD	1FTYR14V91T [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VKR_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/10/2001
WRTY_START_D	8/22/2001
NAME	COURTESY FORD
DOC_NUM	7889702
PH_NUM	3286000
WCC_CD	BR02
PART_NUM_CA	1L6Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	41
RPR_DT	2/25/2002
TIS_WSD	8
CLM_KEY	7907822
MILGE	8795
MTRL_COST	[REDACTED]

TOT_COST_GRO	10950
LBR_HRS	34
DLR_CD	1025
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	REPLACED PASS BIDE SEAT BELT
TECH_TXT2	
CUST_TXT	G S PASS BIDE SEAT BELT WILL NOT STAY LOCKED
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124220
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	254
MDL_YR	2001
SORT_INDEX	928
VIN_CD	1FTYR14V811
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/5/2001
WRTY_START_D	5/14/2001
NAME	SOUTHWAY FORD, INC.
DOC_NUM	430468A
PH_NUM	9222222
WCC_CD	BR02
PART_NUM_CA	1LEZ
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	540
COND_CD	42
RPR_DT	7/17/2001
TIS_WSD	3
CLM_KEY	2390880
MILGE	3848
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	4522
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	3948 INSTALL SOP PART. FP 61202 CC 42 R I RIGHT FRONT SEAT FOR ACCESS TO R R SEATBELT BUCKLE ASY. INSTALLED SOP RIGHT FRONT SEATBELT BUCKLE ASY. REINSTALLED SEAT ASY.
TECH_TXT2	
CUST_TXT	840 RIGHT FRONT SEAT BELT IS NOT LATCHING SOPARTS ARE HERE
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	162204
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	286
MDL_YR	2001
SORT_INDEX	827
VIN_CD	1FTYR14V91T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAR_STL	T/BD
VEH_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	4/5/2001
WRTY_START_D	7/18/2001
NAME	FOX LAKE FORD MERCURY, INC.
DOC_NUM	434801
PH_NUM	5873400
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	940
COND_CD	42
RPR_DT	7/28/2001
TIS_WSD	1
CLM_KEY	2836881
MILGE	637
MTRL_COST	

TOY_COST_GRO	04,85
LBR_HRS	83
DLR_CD	1552
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IL
Ratings	8
CPSC_CD_6	11001
TECH_TXT1	REPLACED LATCH ASSEMBLY
TECH_TXT2	
CUST_TXT	PASSENGER SEAT BELT BUCKLE WONT LATCH
AREA_CD	847
COUNTRY_CD	USA
SLS_DLR_CD	141415
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	288
MDL_YR	2001
SORT_INDEX	828
VIN_CD	1FTYR14V91T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/T/C
PLANT_CD	AG
PRODN_DT	3/19/2001
WRTY_START_D	8/15/2001
NAME	MARSHALL FORD CO, INC.
DOC_NUM	4628062
PH_NUM	7749222
WCC_CD	6R02
PART_NUM_CA	11.5Z
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	2/4/2002
TIS_WSD	6
CLM_KEY	8821448
MILGE	8134
MTRL_COST	

Tuesday, December 14, 2004

Page 531 of 558

TOT_COST_GRO	8577
LBR_HRS	488
DLR_CD	6508
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MS
Ratings	C
CPSC_CD_6	11001
TECH_TXT1	SEAT BELT BUCKLE INOPERATIVE B TIME TO R&I PASSENGER SEAT REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CHECK SEAT BELT ON DRIVER SIDE COMING UNLATCHED
AREA_CD	B01
COUNTRY_CD	USA
SLS_DLR_CD	123430
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	287
MDL_YR	2001
SORT_INDEX	930
VIN_CD	1FTYR14V81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	
BOD_CAB_STL	T/RD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/A
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/28/2001
WRTY_START_D	4/21/2001
NAME	JACKY JONES FORD OF ANDREWS, I
DOC_NUM	3004601
PH_NUM	3213214
WCC_CD	0R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1001203
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	6/20/2001
TIS_WSD	6
CLM_KEY	3089983
MILGE	3167
MTRL_COST	

TOT_COST_GRO	144.08
LBR_HRS	0.8
DLR_CD	3332
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
Ratings	b
CPSC_CD_6	11001
TECH_TXT1	TESTED TO VERIFY.FOUND SEAT BELT WOULD NOT STAY BUCKLED. CK OASIS FOR RECALL, NO RECALL PRESENT IN SPECT SEATBELTS HAVE INTERNAL DEFECT.NEC TO RR SEATBELT.
TECH_TXT2	
CUST_TXT	BOTH DRIVER AND PASSENGER SIDE SEAT BELTS WILL NOT STAY BUCKLED
AREA_CD	B2B
COUNTRY_CD	USA
SLS_DLR_CD	121881
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	258
MDL_YR	2001
SORT_INDEX	833
VIN_CD	1FTYR14V01P
LBR_COST	
VEH_LINE_CD	TR3
MKT_DERIVED	
BOD_CAR_STL	TBD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	7/18/2001
WRTY_START_D	8/12/2001
NAME	GALPIN FORD
DOC_NUM	5886141
PH_NUM	7873800
WCC_CD	8R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	1
CLM_KEY	4001240
MILGE	43
MTRL_COST	

TOT_COST_GRO	10222
LBR_HRS	
DLR_CD	5536
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	SEAT BELTS WONT LATCH REPLACE SEATBELTS
TECH_TXT2	
CUST_TXT	SEAT BELTS WILL NOT LATCH PROPERLY
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	269
MDL_YR	2001
SORT_INDEX	638
VIN_CD	1FTYR14V91P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	6/25/2001
WRTY_START_D	11/2/2001
NAME	OKC AUTO COLLECTION
DOC_NUM	228260A
PH_NUM	2327171
WCC_CD	6R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	7/26/2001
TIS_WSD	0
CLM_KEY	2589236
MILGE	14
MTRL_COST	

ID	270
MDL_YR	2001
SORT_INDEX	953
VIN_CD	1FTYR14V81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/A
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/11/2001
WRTY_START_D	4/28/2001
NAME	BUDGET RAC - PORTLAND AIRPORT
DOC_NUM	6215841
PH_NUM	*
WCC_CD	GRIZ
PART_NUM_CA	1L5Z
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	7
CLM_KEY	5206683
MILGE	17814
MTRL_COST	

TOT_COST_GRO	70.88
LBR_HRS	6.2
DLR_CD	45997
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OR
Ratings	a
CPSC_CD_6	11001
TECH_TXT1	INTERNAL FAULT IN SEAT BELT LATCH RR SEAT BELT LATCH
TECH_TXT2	
CUST_TX1	RIGHT SEAT BELT WONT LATCH
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	124126
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	271
MDL_YR	2001
SORT_INDEX	058
VIN_CD	1FTYR14V81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	3/14/2001
WRTY_START_D	8/6/2001
NAME	FINDLAY FORD LINC-MERC, INC.
DOC_NUM	7069651
PH_NUM	4221061
WCC_CD	9R02
PART_NUM_CA	1L5Z
PART_NUM_CA	1051202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	41
RPR_DT	1/28/2002
TIS_WSD	8
CLM_KEY	8629511
MILGE	5871
MTRL_COST	

TOT_COST_GRO	
LBR_HRS	
DLR_CD	2837
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
Ratings	
CPSC_CD_6	11001
TECH_TXT1	VERIFIED BUCKLE STICKING REMOVED SEAT FOR ACCESS REMOVED AND REPLACED BUCKLE ASSEMBLY AND RETESTED OK
TECH_TXT2	
CUST_TXT	THE P S SEAT BELT WILL NOT BUCKLE
AREA_CD	419
COUNTRY_CD	USA
SLS_DLR_CD	140077
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	S05
TIS_FLAG	

ID	272
MDL_YR	2001
SORT_INDEX	988
VIN_CD	1FTYR14V81P
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/RD
VEH_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	2/27/2001
WRTY_START_D	3/21/2001
NAME	BUDGET RAC - S. SAN FRANCISCO
DOC_NUM	5161641
PH_NUM	*
WCC_CD	BR02
PART_NUM_CA	1L52
PART_NUM_CA	1081202
PART_NUM_CA	AAA
CUST_CONC_C	S40
COND_CD	42
RPR_DT	9/4/2001
TIS_WSD	B
CLM_KEY	3787017
MILGE	21671
MTRL_COST	

TOT_COST_GRO	7889
LBR_HRS	94
DLR_CD	48185
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	RF BUCKLE WONT LATCH. RR RF BUCKLE ASY
TECH_TXT2	
CUST_TXT	RF BUCKLE INOP
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	171227
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	308
TIS_FLAG	

ID	273
MDL_YR	2001
SORT_INDEX	976
VIN_CD	1FTYR14V811
LBR_COST	
VEH_LINE_CD	TFR3
MKT_DERIVED	
BOD_CAB_STL	TFRD
VER_SERIES_C	TFRF
DRIVE_CD	TFR
ENG_CD	TILA
TRANS_CD	TTC
PLANT_CD	AG
PRODN_DT	4/8/2001
WRTY_START_D	8/15/2001
NAME	FLETCHER-TATE FORD
DOC_NUM	17168001
PH_NUM	2213673
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1061202
PART_NUM_CA	AAA
CUST_CONC_C	840
COND_CD	42
RPR_DT	9/28/2001
TIS_WSD	2
CLM_KEY	3857180
MILGE	10201
MTRL_COST	

TOT_COST_GRO	137
LBR_HRS	1480
DLR_CD	1480
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AR
Ratings	B
CPSC_CD_6	11001
TECH_TXT1	REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	SOP IN PASS SEAT BELT WILLNOT LATCH.
AREA_CD	501
COUNTRY_CD	USA
SLS_DLR_CD	122207
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	805
TIS_FLAG	

ID	274
MDL_YR	2001
SORT_INDEX	07B
VIN_CD	1FTYR14V81T
LBR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/BD
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/LA
TRANS_CD	T/TC
PLANT_CD	AG
PRODN_DT	3/29/2001
WRTY_START_D	4/28/2001
NAME	ALL STAR FORD-MERCURY, INC.
DOC_NUM	10202908
PH_NUM	7282171
WCC_CD	BR02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	S25
COND_CD	42
RPR_DT	4/8/2002
TIS_WSD	12
CLM_KEY	788531E
MILGE	12170
MTRL_COST	

TOT_COST_GRO	180.32
LBR_HRS	028
DLR_CD	812
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
Ratings	c
CPSC_CD_6	11001
TECH_TXT1	VERIFY CONCERN FOR BOTH FRONT SEAT BELTS INOP. TEST BUCKLES TEST BAD. R&R BOTH FRONT SEATS & REPLACED BUCKLES. VERIFY REPAIR
TECH_TXT2	
CUST_TXT	BOTH FT. SEAT BELYS COME UNLATCHED WHILE DRIVING
AREA_CD	903
COUNTRY_CD	USA
SLS_DLR_CD	162475
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V06
AWS_VL_CD	R1
VRT_CD	S08
TIS_FLAG	

ID	275
MDL_YR	2001
SORT_INDEX	890
VIN_CD	1FTYR14V81F
LRR_COST	
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/B0
VER_SERIES_C	T/EF
DRIVE_CD	T/B
ENG_CD	T/A
TRANS_CD	T/TC
PLANT_CD	AX
PRODN_DT	4/4/2001
WRTY_START_D	6/25/2001
NAME	ROUNTREE-MOORE INC
DOC_NUM	13140201
PH_NUM	7580830
WCC_CD	8R02
PART_NUM_CA	1LSZ
PART_NUM_CA	1081203
PART_NUM_CA	AAA
CUST_CONC_C	828
COND_CD	41
RPR_DT	2/20/2002
TIS_WSD	10
CLM_KEY	8898015
MILGE	16730
MTRL_COST	

TOT_COST_GRO	79.16
LBR_HRS	004
DLR_CD	4875
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
Ratings	
CPSC_CD_6	11001
TECH_TXT1	REPLACED DRIVERS SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SIDE SEAT BELT WILL NOT BUCKLE IN GOP HERE
AREA_CD	888
COUNTRY_CD	USA
SLS_DLR_CD	124207
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R1
VRT_CD	808
TIS_FLAG	

Raw Data

MDL_YR	2001
SORT_INDEX	1
VIN_CD	5LAFU28RX1L
LBR_COST	
VRH_LINE_CD	T/PA
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	5/31/2001
NAME	TEMPLE LINCOLN-MERCURY
DOC_NUM	0635098
PH_NUM	7739077
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	GAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	5/21/2001
TIS_WSD	3
CLM_KEY	5818449
MILGE	4890

Tuesday, December 14, 2004

Page 1 of 1298

MTRL_COST	26.05
TOT_COST_GROS	49.99
LBR_HRS	0.4
DLR_CD	10804
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACE SEAT BELT WONT HOLD
TECH_TXT2	
CUST_TXT	CUST SAYS PASS SEAT BELT WONT HOLD
AREA_CD	254
COUNTRY_CD	USA
SLS_DLR_CD	387326
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	2
VIN_CD	5LMFU2BFX1
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	5/18/2001
NAME	HOLMAN LINCOLN-MERCURY
DOC_NUM	191855A
PH_NUM	2944900
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	788120S
PART_NUM_CAU	GAA
CUST_CONC_CD	325
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	7
CLM_KEY	981977S
MILGE	9359
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	10488
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	31001
Ratings	8
TECH_TXT1	8358 CK & REPLACED BOTH FRONT SEAT BELT ASSY.
TECH_TXT2	
CUST_TXT	INSTALL S.O. PART FOR SEAT BELT BUCKLE (POSS RECALL)
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	315040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	5
VIN_CD	6LMFU2BRX1L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	3/10/2001
NAME	NAPLETON LINCOLN-MERCURY
DOC_NUM	077651A
PH_NUM	*
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7961203
PART_NUM_CAU	CAA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	6/10/2002
TIS_WSD	18
CLM_KEY	0128288
MILGE	17900
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10279
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACED BUCKLE ASSY INOP
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE INOP
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	342574
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	806
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	6
VIN_CD	5LMFU28RX1
LBR_COST	3428
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/8/2000
WRTY_START_D	12/23/2000
NAME	JOHN DEERY MOTORS INC
DOC_NUM	354229A
PH_NUM	2778200
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	CAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	6/14/2002
TIS_WSD	18
CLM_KEY	8205707
MILGE	42134
MTRL_COST	24
TOT_COST_GROS	3428

Tuesday, December 14, 2004

Page 7 of 1298

LBR_HRS	0.8
DLR_CD	10197
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	42134 REPLACED DRIVER & PASS, SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELT LIGHT ON PARTS IN
AREA_CD	319
COUNTRY_CD	USA
SLS_DLR_CD	325727
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	7
VIN_CD	5LMFLJ28RX11
LBR_COST	2288
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/19/2000
WRTY_START_D	12/7/2001
NAME	BARNEY A SMITH LINC-MERC INC
DOC_NUM	6688001
PH_NUM	7485821
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861208
PART_NUM_CAU	CAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	1
CLM_KEY	6000076
MILGE	715
MTRL_COST	
TOI_COST_GROS	

Tuesday, December 14, 2004

Page 9 of 1298

LBR_HRS	04
DLR_CD	10129
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	R+R BELT BUCKLE
TECH_TXT2	
CUST_TXT	FRONT LEFT SEAT BELT WILL COME UNATTACHED WHILE DRIVING DOWN THE ROAD
AREA_CD	912
COUNTRY_CD	USA
SLS_DLR_CD	326234
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	8
VIN_CD	GLMFU28FX1U
LBR_COST	98.28
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/VC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/4/2000
WRTY_START_D	12/28/2000
NAME	BARON LINCOLN-MERCURY INC
DOC_NUM	5585701
PH_NUM	6319600
WCC_CD	BR02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	10/22/2001
TIS_WSD	10
CLM_KEY	4898580
MILGE	14383
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 11 of 1288

LBR_HRS	0A
DLR_CD	13128
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	INSTALL L F SEAT BELT AS PER RECALL
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELT L F
AREA_CD	718
COUNTRY_CD	USA
SLS_DLR_CD	314437
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	9
VIN_CD	5LMFLJ28RX1L
LBR_COST	6021
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DIE
PLANT_CD	AP
PRODN_DT	12/3/2001
WRTY_START_D	6/8/2001
NAME	METROPOLITAN FORD
DOC_NUM	3330401
PH_NUM	8438000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	S25
COND_CD	41
RPR_DT	10/22/2001
TIS_WSD	5
CLM_KEY	5517887
MILGE	8005
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	2981
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
CPSC_CD_6	11001
Ratings	6
TECH_TXT1	INSTALL PASS SIDE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	SO PART SEAT BELT INSTALL
AREA_CD	852
COUNTRY_CD	USA
SLS_DLR_CD	343008
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	10
VIN_CD	5LMFU28R91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	5/12/2001
NAME	COON RAPIDS LINCOLN MERCURY
DOC_NUM	13258004
PH_NUM	4220848
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7661203
PART_NUM_CAU	CAB
CUST_CONC_CD	S26
COND_CD	41
RPR_DT	5/13/2002
TIS_WSD	13
CLM_KEY	0930267
MILGE	16324
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	13208
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	CP 7801203;CC 41;CC 920 REPLACED DRIVERS SEAT BELT BUCKLE ASSEMBLY. UTILIZED LABOR OPERATION FROM PROGRAM 01S21
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNBUCKLED.
AREA_CD	783
COUNTRY_CD	USA
SLS_DLR_CD	343318
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	11
VIN_CD	5LMFU28R91L
LBR_COST	
VEH_LINE_CD	T/BA
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	8/4/2001
NAME	NICK MAYER LINCOLN-MERCURY INC
DOC_NUM	9381501
PH_NUM	8353700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	7
RPR_DT	7/12/2001
TIS_WSD	2
CLM_KEY	2400882
MILGE	2652
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	10705
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	INSPECT AND REPLACE DR SEAT BELKT RETEST OK 7881203 07 840
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELT
AREA_CD	216
COUNTRY_CD	USA
SLS_DLR_CD	318838
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	12
VIN_CD	5LMFU28R91L
LBR_COST	21.25
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/24/2001
NAME	TENNESSEE MOTOR COMPANY, INC.
DOC_NUM	155226A
PH_NUM	2823000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	BAB
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	1/10/2002
TIS_WSD	6
CLM_KEY	8168777
MILGE	10534
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	1900
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACED RIGHT FRONT PASS SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	940 STATES THAT THE PASS SIDE SEATBELT IS NOT LATCHING PROPE
AREA_CD	423
COUNTRY_CD	USA
SLS_DLR_CD	348235
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	13
VIN_CD	5LMFU28R91
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	5/17/2001
NAME	GALPIN LINCOLN-MERCURY
DOC_NUM	3825312
PH_NUM	8823800
WCC_CD	8R02
PART_NUM_CAU	F85Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BBE
CUST_CONC_CD	825
COND_CD	42
RPR_DT	7/8/2001
TIS_WSD	2
CLM_KEY	3132598
MILGE	4180
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11B20
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	b
TECH_TXT1	VERIFIED CONCERN, PERFORMED 01S21 RECALL AND REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST STS DRIVERS SEAT BELT BUCKLE DOESNT STAY LATCHED SOMETIMES
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	354301
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	14
VIN_CD	5LMFLJ28R81L
LBR_COST	28.4
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	3/11/2001
WRTY_START_D	7/18/2001
NAME	HOLMAN LINCOLN-MERCURY
DOC_NUM	191243C
PH_NUM	2344800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	325
COND_CD	42
RPR_DT	11/27/2001
TIS_WSD	5
CLM_KEY	5410885
MILGE	7222
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	1040B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	7222 REPLACE DRIVER FRONT SEAT BUCKLE
TECH_TXT2	
CUST_TXT	CHECK SEAT BELT SOP
AREA_CD	609
COUNTRY_CD	USA
SLS_DLR_CD	316040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	15
VIN_CD	5LMFU26R81
LBR_COST	37.57
VEH_LINE_CD	T/B4
MKT_DERIVED	-
BOD_CAB_STL	TMD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	3/27/2001
NAME	KEN SMITH MOTORS INC
DOC_NUM	4802002
PH_NUM	4442200
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	10/24/2001
TIS_WSD	8
CLM_KEY	4884318
MILGE	6238
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11280
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	"
TECH_TXT1	1 REPLACE L FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	REPLACE SEAT BELT (SOP) STICKS
AREA_CD	201
COUNTRY_CD	USA
SLS_DLR_CD	314340
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	16
VIN_CD	5LMFU2BR91L
LBR_COST	84.34
VEH_LINE_CD	T/84
MKT_DERIVED	-
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/3/2001
WRTY_START_D	4/30/2001
NAME	L & B LINCOLN MERCURY INC
DOC_NUM	12453802
PH_NUM	8882800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	825
COND_CD	41
RPR_DT	10/30/2001
TIS_WSD	7
CLM_KEY	4838883
MILGE	5881
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	19383
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	e
TECH_TXT1	1 REPL P 8 SEATBELT
TECH_TXT2	
CUST_TXT	C S SEAT BELT ON D S
AREA_CD	616
COUNTRY_CD	USA
SLS_DLR_CD	314014
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	800
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	18
VIN_CD	ELMFL128R91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/27/2001
WRTY_START_D	3/14/2001
NAME	HERTZ RAC - DENVER
DOC_NUM	37316901
PH_NUM	*
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/19/2001
TIS_WSD	6
CLM_KEY	4635889
MILGE	7147
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	03
DLR_CD	45246
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPL LF BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT BUCKLE INOP
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	366898
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	19
VIN_CD	5LMFL2BR81L
LBR_COST	42.78
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	8/8/2001
NAME	CITRUS FORD
DOC_NUM	40421801
PH_NUM	3000830
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	5/24/2002
TIS_WSD	10
CLM_KEY	8088294
MILGE	12811
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	5613
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	...BUCKLES ARE NOTS HOLDING AT TIMES... ...INSPECTED WITH TOOL BOTH FRONTS FAILED.REPLACED.OK
TECH_TXT2	
CUST_TXT	CUST STATES THE DRIVERS BEAT BELT UNLATCHES WHILE DRIVING. CONCERN OCCURS INTERMITTENTLY...CK & ADVI
AREA_CD	809
COUNTRY_CD	USA
SLS_DLR_CD	354172
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	BA
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	20
VIN_CD	5LMFU28R91
LBR_COST	
VEH_LINE_CD	T1B4
MKT_DERIVED	*
BOD_CAB_STL	TW0
VER_SERIES_CD	T1EL
DRIVE_CD	T1E
ENG_CD	TW0
TRANS_CD	T10E
PLANT_CD	AP
PRODN_DT	1/16/2001
WRTY_START_D	4/2/2001
NAME	STU EVANS L44, GARDEN CITY, IN
DOC_NUM	38878201
PH_NUM	4284300
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	S40
COND_CD	42
RFB_DT	8/31/2001
TIS_WSD	6
CLM_KEY	3411824
MILGE	8428
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="19928"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="MI"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="1 REPLACE DRIVERS SEAT BELT BUCKLE WITH NEW BUCKLE IN OP CC 42 BASIC#61203"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value=""/>
AREA_CD	<input type="text" value="918"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="345345"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	21
VIN_CD	BLJAFU28R91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	5/5/2001
NAME	LYNNHAVEN LINCOLN-MERCURY
DOC_NUM	387229C
PH_NUM	3400800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851202
PART_NUM_CAU	BAC
CUST_CONC_CD	540
COND_CD	42
RPR_DT	10/10/2001
TIS_WSD	8
CLM_KEY	4387288
MILGE	12074
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	12314
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	12074 REMOVED SEAT AND R R SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEATBELT INOP BOP IS IN
AREA_CD	757
COUNTRY_CD	USA
SLS_DLR_CD	326276
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	G21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	22
VIN_CD	5LMFU2BR911
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/16/2000
WRTY_START_D	7/9/2001
NAME	TUSTIN LINCOLN MERCURY
DOC_NUM	5845852
PH_NUM	5448111
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	4/26/2002
TIS_WSD	10
CLM_KEY	6309735
MILGE	19691
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	69
DLR_CD	11804
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	SEAT BELTS IN OP REPLACE SEAT BELTS
TECH_TXT2	
CUST_TXT	INSTALL SPECIAL ORDER PARTS RELATED TO SEAT BELT RECALL ON PREVIOUS RO.
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	364296
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
YIS_FLAG	

MDL_YR	2001
SORT_INDEX	25
VIN_CD	5LMFL28R81L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EL
DRIVE_CD	T1E
ENG_CD	T1WC
TRANS_CD	T1DE
PLANT_CD	AP
PRODN_DT	5/1/2001
WRTY_START_D	6/22/2001
NAME	PFEIFFER LINCOLN-MERCURY INC
DOC_NUM	7481651
PH_NUM	9487800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	525
COND_CD	42
RPR_DT	5/7/2002
TIS_WSD	11
CLM_KEY	8468031
MILGE	21309
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	9.4
DLR_CD	10839
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT LATCH
AREA_CD	B16
COUNTRY_CD	USA
SLS_DLR_CD	345100
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	28
VIN_CD	5LMFU28R81
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	8/30/2001
NAME	OLATHE LINCOLN-MERCURY INC
DOC_NUM	6817562
PH_NUM	7827820
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/21/2001
TIS_WSD	6
CLM_KEY	5889828
MILGE	14112
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	82
DLR_CD	12903
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KS
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	VERIFY CONCERN, REPLACE DRIVERS SEAT BELT LATCH ASSY WILL NOT HOLD SECURLY
TECH_TXT2	
CUST_TXT	THE DRIVERS SEATBELT WILL UNLATCH ON ITS OWN WHEN DRIVING
AREA_CD	913
COUNTRY_CD	USA
SLS_DLR_CD	361558
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	27
VIN_CD	5LMFU28R81L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T8L
DRIVE_CD	T8E
ENG_CD	T8C
TRANS_CD	T8E
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	5/15/2001
NAME	D'AMICO LINCOLN-MERCURY
DOC_NUM	2228802
PH_NUM	2576300
WCC_CD	8R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7001202
PART_NUM_CAU	8A8
CUST_CONC_CD	840
COND_CD	33
RPR_DT	8/3/2002
TIS_WSD	13
CLM_KEY	9028778
MILGE	14408
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 43 of 1298

RQ04-011 E 2088

LBR_HRS	83
DLR_CD	11218
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	PASS AND DSIDE SEATBELT BUCKLE FAULTY TECH REPLACED PASS AND DSIDE FRONT BUCKLE TO CORRECT CUST CONCERN
TECH_TXT2	
CUST_TXT	CUST STATES DSIDE SEATBELT BUCKLE COMES LOOSE
AREA_CD	782
COUNTRY_CD	USA
SLS_DLR_CD	314376
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	28
VIN_CD	5LMFUJ28R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	6/21/2001
NAME	DON THOMPSON LINCOLN MERCURY,
DOC_NUM	2850401
PH_NUM	4742185
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801208
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	9/11/2001
TIS_WSD	1
CLM_KEY	3827813
MILGE	10178
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	10888
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OH
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED DRIVERS SEAT BELT AND VERIFIED REPAIRS
TECH_TXT2	
CUST_TXT	CUSTOMER SAYS DRIVERS SEAT BELT IS INOP PARTS ARE IN
AREA_CD	614
COUNTRY_CD	USA
SLS_DLR_CD	346382
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	31
VIN_CD	5LMFU28R81L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VRR_SERIES_CD	TIEL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	8/13/2001
NAME	MGAULEY MOTORS INC
DOC_NUM	1000852
PH_NUM	7222771
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	E28
COND_CD	42
RPR_DT	2/5/2002
TIS_WSD	8
CLM_KEY	8747988
MILGE	4518
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	12701
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	SEAT BELT NOT STAYING ENGAGED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEATBELT NOT STAYING ENGAGED
AREA_CD	209
COUNTRY_CD	USA
SLS_DLR_CD	351977
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	SC8
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	33
VIN_CD	5LMFU28R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	7/15/2001
NAME	GLENWOOD SPRINGS FORD-LIN-MER,
DOC_NUM	9033801
PH_NUM	9462317
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/8/2001
TIS_WSD	1
CLM_KEY	3284804
MILGE	3123
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	62
DLR_CD	3172
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	11001
Ratings	6
TECH_TXT1	FOUND DRIVERS SIDE SEAT BELT BROKEN. R&R DRIVERS SEAT BELT. VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT CAME UNLATCHED WHILE DRIVING..S40
AREA_CD	970
COUNTRY_CD	USA
SLS_DLR_CD	386401
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	900
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	34
VIN_CD	6LMFL28R81L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/17/2000
WRTY_START_D	1/4/2001
NAME	UPTOWN MOTORS, INC.
DOC_NUM	137181A
PH_NUM	7719000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	786120S
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/4/2001
TIS_WSD	10
CLM_KEY	4258776
MILGE	10500
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 51 of 1298

LBR_HRS	08
DLR_CD	12162
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WI
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REMOVE AND INSTALL SEAT BELTS
TECH_TXT2	
CUST_TXT	INSTALL SOP SEATBELT BUCKLES BOTH FRONT, WONT STAY LATCHED, RO 130016 TECH 7019
AREA_CD	414
COUNTRY_CD	USA
SLS_DLR_CD	942527
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	37
VIN_CD	6LMFL2BR711
LBR_COST	4835
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/17/2001
WRTY_START_D	8/1/2001
NAME	WHITE BEAR LINCOLN-MERCURY INC
DOC_NUM	251925A
PH_NUM	4032031
WCC_CD	5R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	525
COND_CD	42
RPR_DT	11/7/2001
TIS_WSD	3
CLM_KEY	5051432
MILGE	6004
MTRL_COST	31
TOT_COST_GROS	31

LBR_HRS	08
DLR_CD	12507
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MN
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	0084 REMOVED RIGHT FRONT SEAT BELT AND INSTALLED NEW BUCKLE REMOVED LEFT FRONT SEAT BELT BUCKLE AND AND FISHED OUT CONNECTOR, REINSTALLED NEW ONE. NOT AN EASY TASK.
TECH_TXT2	
CUST_TXT	RECALL SEAT BELT BUCKLES PARTS IN
AREA_CD	061
COUNTRY_CD	USA
SLS_DLR_CD	343319
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	608
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	38
VIN_CD	5LMFU28R71L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/9/2001
WRTY_START_D	8/18/2001
NAME	SENTRY LINCOLN-MERCURY SLS INC
DOC_NUM	180321B
PH_NUM	3916700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	8/16/2002
TIS_WSD	8
CLM_KEY	8568285
MILGE	14515
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 55 of 1298

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="13130"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="MA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="14515 REPLACED DRIVER SEATBELT RECEIPT. RECEIPT. WOULD NOT ACCEPT SEATBELT BUCKLE AND LOCK BELT OPERATED PROPERLY AT THIS TIME"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CK CAN NOT SECURE DRIVER FRONT SEATBELT"/>
AREA_CD	<input type="text" value="781"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="312388"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	44
VIN_CD	5LMFU28F81
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	10/18/2001
NAME	WEISLEDER, INC.
DOC_NUM	3182961
PH_NUM	
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	SS
RPR_DT	7/21/2001
TIS_WSD	0
CLM_KEY	2782571
MILGE	8
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="10432"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NJ"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACED RIGHT FR"/> <input type="text" value="ONT BELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="NEEDSR FRONT BELT"/>
AREA_CD	<input type="text" value="908"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="314031"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S05"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	45
VIN_CD	5LMFU28R81
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	10/24/2001
NAME	BILL SMITH FORD INC
DOC_NUM	4828351
PH_NUM	8828765
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7951203
PART_NUM_CAU	GAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	4/8/2002
TIS_WSD	8
CLM_KEY	9118848
MILGE	1884
MTRL_COST	
TOT_COST_GROS	

MDL_YR	2001
SORT_INDEX	46
VIN_CD	6LMFLJ28R81L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	3/31/2001
WRTY_START_D	4/20/2001
NAME	CAPE COD LINCOLN MERCURY MAZDA
DOC_NUM	11441702
PH_NUM	7751444
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	GAA
CUST_CONC_CD	828
COND_CD	42
RPR_DT	1/19/2002
TIS_WSD	10
CLM_KEY	6882288
MILGE	10755
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	034
DLR_CD	10328
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MA
CPSC_CD_6	11001
Ratings	6
TECH_TXT1	PERFORMED RECALL AND REPLACED DRIVER SEATBELT BUCKLE RECHECKED OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEATBELT RECALL INSTALL SOP
AREA_CD	508
COUNTRY_CD	USA
SLS_DLR_CD	312190
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	505
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	48
VIN_CD	5LMPJ29R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/5/2001
WRTY_START_D	3/18/2001
NAME	CODIROL LINCOLN-MERCURY
DOC_NUM	3654851
PH_NUM	2947700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	2/5/2002
TIS_WSD	11
CLM_KEY	6903421
MILGE	15410
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	12718
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	#
TECH_TXT1	REPLACE BELT INOP
TECH_TXT2	
CUST_TXT	LT FRONT SEAT BELT WONT LATCH AT TIMES 5 0
AREA_CD	925
COUNTRY_CD	USA
SLS_DLR_CD	361075
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	49
VIN_CD	5LMFU28R61L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/2/2001
WRTY_START_D	3/21/2001
NAME	SCHAUMBURG LINCOLN-MERCURY
DOC_NUM	1000832
PH_NUM	8824100
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/6/2001
TIS_WSD	5
CLM_KEY	3038277
MILGE	5382
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 65 of 1298

LBR_HRS	88
DLR_CD	13678
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	#
TECH_TXT1	REPLACE BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT BUCKLES DO NOT FULLY LATCH
AREA_CD	847
COUNTRY_CD	USA
SLS_DLR_CD	342412
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	52
VIN_CD	6LMFU26R61L
LRR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	*
BOD_CAB_STL	TND
VER_SERIES_CD	TFL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	2/28/2001
NAME	JIM XAMIS FORD-LINCOLN-MERCURY
DOC_NUM	6820051
PH_NUM	7322111
WCC_CD	BR02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7801203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	9/18/2001
TIS_WSD	7
CLM_KEY	3788127
MILGE	4727
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	5047
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	INOPERATIVE SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	R R S O SEATBELT
AREA_CD	217
COUNTRY_CD	USA
SLS_DLR_CD	384195
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	505
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	53
VIN_CD	5LMFU26R01
LBR_COST	
VEH_LINE_CD	T/84
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/26/2001
WRTY_START_D	6/29/2001
NAME	MIDLAND FORD LINCOLN-MERCURY,
DOC_NUM	17528302
PH_NUM	8310040
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7961208
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/7/2001
TIS_WSD	8
CLM_KEY	5761428
MILGE	8772
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="8801"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="MI"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="9"/>
TECH_TXT1	<input type="text" value="INSPECTED SEATBELTS,NEEDS DRIVERS
BUCKLE,REQUEST MT INSPECT AND REPLACE
DRIVER BELT AND BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="LEFT FRONT SEAT BELT INTERMIT STICKS"/>
AREA_CD	<input type="text" value="888"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="345237"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	54
VIN_CD	5LMFU28R51L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TREL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TCE
PLANT_CD	AP
PRODN_DT	6/29/2001
WRTY_START_D	8/31/2001
NAME	ALBUQUERQUE LINCOLN-MERCURY
DOC_NUM	3480001
PH_NUM	2802200
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	2/15/2002
TIS_WSD	6
CLM_KEY	7031096
MILGE	15824
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	043
DLR_CD	10140
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NM
CPSC_CD_6	11001
Ratings	
TECH_TXT1	SEAT BELT BUCKLE VISIBLY BROKEN INTERNALLY. R&R SEAT BELT BUCKLE. 61172A 0.4
TECH_TXT2	
CUST_TXT	CUSTOMER STATES FRIT PASS. SEAT BELT LATCH WOULD NOT LET YOU LATCH IT IN.
AREA_CD	505
COUNTRY_CD	USA
SLS_DLR_CD	366522
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	608
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	56
VIN_CD	SLMFU2BR51
LBR_COST	
VEH_LINE_CD	T/BA
MKT_DERIVED	
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/8/2001
WRTY_START_D	
NAME	OLATHE LINCOLN-MERCURY INC
DOC_NUM	5708161
PH_NUM	7827820
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	CAA
CUST_CONC_CD	839
COND_CD	1
RPR_DT	9/21/2001
TIS_WSD	-1
CLM_KEY	4735088
MILGE	6
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	24
DLR_CD	12909
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	KS
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	VERIFY CUSTOMER CONCERN SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT IS INOP
AREA_CD	913
COUNTRY_CD	USA
SLS_DLR_CD	383658
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	58
VIN_CD	5LMFU2BRS1L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/23/2001
WRTY_START_D	9/15/2001
NAME	REEDMAN LINCOLN MERCURY
DOC_NUM	34588801
PH_NUM	*
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7BB1203
PART_NUM_CAU	GAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/9/2001
TLS_WSD	0
CLM_KEY	3183477
MILGE	6
MTRL_COST	
TOT_COST_GROS	