

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 1 OF 6

BOOK 4 OF 43

LBR_HRS	00
DLR_CD	10435
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	CHECK BOTH FRONT SEATBELT BUCKLES WILL NOT STAY LATCHED, REPLACED BOTH BUCKLES
TECH_TXT2	
CUST_TXT	
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	316148
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	57
VIN_CD	5LMFU28R51L
LBR_COST	
VEH_LINE_CD	T/64
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/ANC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/23/2001
WRTY_START_D	8/28/2001
NAME	NORTHEAST LINCOLN-MERCURY
DOC_NUM	1298004
PH_NUM	3316500
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	0
CLM_KEY	3229819
MILGE	4
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	10464
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	11001
Ratings	4
TECH_TXT1	SEAT BELT LATCH WONT LOCK S40 42 CHECK AND REPLACE LEFT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RECALL 01621 SEAT BELT INSPECTION NOT ON RECALL BUT LEFT BUCKLE WONT LATCH
AREA_CD	216
COUNTRY_CD	USA
SLS_DLR_CD	313308
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	89
VIN_CD	5LMFU28R51L
LRR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	TWIC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	7/11/2001
NAME	HASSETT L-M SALES INC
DOC_NUM	13948701
PR_NUM	7857800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	825
COND_CD	41
RPR_DT	4/18/2002
TLS_WSD	10
CLM_KEY	8108547
MILGE	10264
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	11270
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	INSTALLED SOP SEATBELT
TECH_TXT2	
CUST_TXT	
AREA_CD	518
COUNTRY_CD	USA
SLS_DLR_CD	314361
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	61
VIN_CD	SLMFU28R51
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/MC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	8/17/2001
NAME	MEL FARR LINCOLN-MERCURY INC
DOC_NUM	257434B
PH_NUM	6838500
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	9/12/2001
TIS_WSD	1
CLM_KEY	3727067
MILGE	1237
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	10910
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	1237 01 INSPECTED ABD FOUND BAD SEAT BELTLATCH REPLACED DRIVER SEAT BELT LATCH RECHECKED GOOD
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT UNHOOKS WHILE DRIVING
AREA_CD	810
COUNTRY_CD	USA
SLS_DLR_CD	343275
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	62
VIN_CD	BLMFJ28R61L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	7/17/2001
NAME	FREEDOM LINCOLN MERCURY
DOC_NUM	161771A
PH_NUM	4241100
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881205
PART_NUM_CAU	CAA
CUST_CONC_CD	926
COND_CD	42
RPR_DT	12/4/2001
TIS_WSD	5
CLM_KEY	5583252
MILGE	247Z
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	12390
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	2472 INSPECT AND REPLACE DRIVER SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CERTAIN 2001 GRAND MARQUIS, NAVIGATOR, AND TOWNCAR VEHICLES SEAT BELT BUCKLE RETENTION SEE RECA
AREA_CD	767
COUNTRY_CD	USA
SLS_DLR_CD	328637
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	86
VIN_CD	8LMFU28R51L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/4/2001
WRTY_START_D	8/15/2001
NAME	NORTHTOWNE LINCOLN-MERCURY INC
DOC_NUM	12078701
PH_NUM	4532710
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	CAA
CUST_CONC_CD	328
COND_CD	42
RPR_DT	1/8/2002
TIS_WSD	7
CLM_KEY	8158487
MILGE	15884
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	EA
DLR_CD	12826
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MO
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	TESTED THE SEAT BELT CAME UNLATCHED PUT IN A NEW BUCKLE TESTED DID NOT COME UNDONE MOVED THE LATCH AROUND
TECH_TXT2	
CUST_TXY	526 CUST STATE LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING & LATCH ON BELT IS BACKWARD
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	38358
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	68
VIN_CD	5LNMFU28R51L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/22/2001
WRTY_START_D	6/16/2001
NAME	PREMIER LINCOLN MERCURY
DOC_NUM	3860902
PH_NUM	7721177
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/30/2001
TIS_WSD	6
CLM_KEY	4804857
MILGE	4083
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	06
DLR_CD	10838
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	SEAT BUCKLES NEED REPLACED REPLACED LEFT AND RIGHT FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	REPLACE LEFT AND RIGHT FRONT SEAT BELT BUCKLES S.O.PARTS
AREA_CD	724
COUNTRY_CD	USA
SLS_DLR_CD	318368
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	68
VIN_CD	5LMFU20R51L
LBR_COST	
VEH_LINE_CD	T7B4
MKT_DERIVED	
BOD_CAB_STL	TWD
VEH_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/21/2001
WRTY_START_D	3/17/2001
NAME	ROSEN LINCOLN-MERCURY
DOC_NUM	212845A
PH_NUM	8568440
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	9/27/2001
TIS_WSD	7
CLM_KEY	4836277
MILGE	7883
MTRL_COST	
TOT_COST_GROS	

Thursday, December 14, 2001

Page 89 of 1298

R004-011 E 2114

LBR_HRS	948
DLR_CD	10699
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	L
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACED RIGHT FRONT SEAT BELT BUCKLE DUE TO INOP
TECH_TXT2	
CUST_TXT	SEAT BLET INOP
AREA_CD	B47
COUNTRY_CD	USA
SLS_DLR_CD	342535
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	70
VIN_CD	5LMFU2BFS1L
LRR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/16/2001
WRTY_START_D	10/30/2001
NAME	BOB WILLIAMS LM INC
DOC_NUM	10874701
PH_NUM	8087880
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	11/21/2001
TIS_WSD	1
CLM_KEY	5380434
MILGE	2303
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	6.6
DLR_CD	12010
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TN
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	MTIME TO REMOVE LEFT FRT SEAT AND LEFT FRT SEATBELT FEMALE END. REPLACED FEMALE END OF LEFT FRT SEATBELT. RETEST. OK.
TECH_TXT2	
CUST_TXT	CHECK SEAT BELT ON DRIVER SIDE WONT LATCH EASILY
AREA_CD	815
COUNTRY_CD	USA
SLS_DLR_CD	322320
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	71
VIN_CD	5LMFL28R51L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWC
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	1/2/2001
WRTY_START_D	7/2/2001
NAME	JACK ROSS MOTORS INC
DOC_NUM	14887801
PH_NUM	8944600
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	7/27/2001
TIS_WSD	1
CLM_KEY	2842182
MILGE	822
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 93 of 1258

RQ04-011 E 2118

LRR_HRS	0.4
DLR_CD	11895
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
CPSC_CD_6	12001
Ratings	*
TECH_TXT1	REPLACED PASS SIDE BUCKLE
TECH_TXT2	
CUST_TXT	PASS SIDE SEAT BELT INOP
AREA_CD	450
COUNTRY_CD	USA
SLS_DLR_CD	364547
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	B06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	72
VIN_CD	8LMFU28R41L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	8/31/2001
NAME	HASBETT L-M SALES INC
DOC_NUM	13289701
PH_NUM	7857800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	AB5
COND_CD	41
RPR_DT	11/14/2001
TIS_WSD	3
CLM_KEY	6238541
MILGE	2504
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11270
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	#
TECH_TXT1	REPLACE L.FRONTSEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	518
COUNTRY_CD	USA
SLS_DLR_CD	314361
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V17
AWS_VL_CD	B4
VRT_CD	S09
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	73
VIN_CD	5LMFU28R41L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/31/2001
WRTY_START_D	4/21/2001
NAME	JACKSON LINCOLN MERCURY
DOC_NUM	117207A
PH_NUM	8902441
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	6/18/2002
TIS_WSD	14
CLM_KEY	8759878
MILGE	7589
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08:00:00
DLR_CD	10325
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	HI
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	
TECH_TXT2	
CUST_TXT	OWNER STATES LT FRT SEATBELT COMES OUT OF BUCKLE WHILE DRIVING
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	361494
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	Q

MDL_YR	2001
SORT_INDEX	74
VIN_CD	5LMFU28R41L
LRR_COST	2728
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/29/2001
WRTY_START_D	9/28/2001
NAME	KUMPF LINCOLN MERCURY, INC.
DOC_NUM	130104A
PH_NUM	7811580
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	10/11/2001
TIS_WSD	1
CLM_KEY	4358713
MILGE	498
MTRL_COST	6332
TOT_COST_GROS	6332

LBR_HRS	04
DLR_CD	11056
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	REPL SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT ON DRIVERS SIDE UN LATCHES ITSELF
AREA_CD	308
COUNTRY_CD	USA
SLS_DLR_CD	355115
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	75
VIN_CD	5LMFU28R41L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TFL
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	3/16/2001
WRTY_START_D	4/5/2002
NAME	ALYN MOORE LINCOLN-MERCURY, I
DOC_NUM	8769851
PH_NUM	4414400
WCC_CD	6R02
PART_NUM_CAU	11.7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	2/28/2002
TIS_WSD	0
CLM_KEY	7228233
MILGE	255
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	156
DLR_CD	10470
DLR_SUB_CD	
REGION_CD	MA
ST_PROV_CD	MO
CPSC_CD_6	11001
Ratings	
TECH_TXT1	SEATBELT ASSEMBLY FRT REPLACED DUE TO LATCH INOP
TECH_TXT2	
CUST_TXT	SEATBELTS DO NOT LATCH PROPERLY WITH TOOL
AREA_CD	314
COUNTRY_CD	USA
SLS_DLR_CD	383187
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	76
VIN_CD	5LMFU28R41L
LBR_COST	7200
VEH_LINE_CD	T84
MKT_DERIVED	.
BOD_CAB_STL	TAWD
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	3/14/2001
WRTY_START_D	7/7/2001
NAME	VALLEY FORD LINCOLN-MERCURY
DOC_NUM	4363156
PH_NUM	5845531
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	850
COND_CD	33
RPR_DT	12/17/2001
TIS_WSD	6
CLM_KEY	5906148
MILGE	10275
MTBL_COST	
TOT_COST_GROS	

LBR_HRS	11000000000000000000
DLR_CD	7887
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	63: VERIFY DRIVERS SEATBELT UNLATCHES, R&R FRONT SEAT AND REPLACED SEATBELT BUCKLE, REASSEMBLE, RECHECK OK AT THIS TIME
TECH_TXT2	
CUST_TXT	CUSTOMER STATED THE DRIVERS SEAT BELT HAS COME UNLOCKED THREE DIFFERENT TIMES
AREA_CD	558
COUNTRY_CD	USA
SLS_DLR_CD	351048
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	78
VIN_CD	5LMFL128R41
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T8L
DRIVE_CD	T8E
ENG_CD	TWC
TRANS_CD	T8E
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	4/18/2001
NAME	ROCKLAND LINCOLN MERCURY SALES
DOC_NUM	1583504
PH_NUM	3588400
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	825
COND_CD	41
RFR_DT	6/16/2002
TTS_WSD	14
CLM_KEY	8702343
MILGE	15512
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 105 of 1298

LBR_HRS	0
DLR_CD	10089
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	PERFORMED SEAT BELT RECALL
TECH_TXT2	
CUST_TXT	CUST STATES TO PERFORM SEAT BELT RECALL 01821
AREA_CD	B14
COUNTRY_CD	USA
SLS_DLR_CD	314541
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	80
VIN_CD	5LMFU28R41
LBR_COST	13
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/4/2001
WRTY_START_D	1/5/2001
NAME	FORD MOTOR COMPANY (VHQ)
DOC_NUM	2429251
PH_NUM	*
WCC_CD	6R02
PART_NUM_CAU	1L2Z
PART_NUM_CAU	78B1203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	11/7/2001
TIS_WSD	11
CLM_KEY	6188002
MILGE	11688
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	05099
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	12001
Ratings	9
TECH_TXT1	REPLACED DRIVER SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	83
VIN_CD	5LMFU2BR31L
LBR_COST	
VEH_LINE_CD	T/04
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EI
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DX
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	10/30/2001
NAME	DON KOTT LINCOLN MERCURY
DOC_NUM	3856451
PH_NUM	8182500
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7B81203
PART_NUM_CAU	BAA
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	7/24/2001
TIS_WSD	0
CLM_KEY	5850245
MILGE	9
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11616
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED DRIVERS SEAT BUCKLE INOP
TECH_TXT2	
CUST_TXT	REPLACE SEAT BELT BUCKLE
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	35422
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	B4
VIN_CD	6LNFJ28R31L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_CD	T8L
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	T8E
PLANT_CD	AP
PRODN_DT	2/27/2001
WRTY_START_D	3/14/2001
NAME	HERTZ RAC - ALBUQUERQUE
DOC_NUM	43089601
PH_NUM	
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	10/31/2001
TIS_WSD	8
CLM_KEY	5852393
MILGE	15047
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	45220
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NM
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED THE BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEATBELT BUCKLE INOP
AREA_CD	
COUNTRY_CD	USA
SLS_DLR_CD	355536
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	85
VIN_CD	5LMFU28R31
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	2/25/2002
NAME	MARMIE FORD-LINCOLN-MERCURY
DOC_NUM	9358502
PH_NUM	7935427
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	1
CLM_KEY	8185864
MILGE	4501
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	5247
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	KS
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPLACE LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT WONT LATCH
AREA_CD	020
COUNTRY_CD	USA
SLS_DLR_CD	363174
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	88
VIN_CD	6LMFL126R31L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TAND
VER_SERIES_CD	TSL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/29/2001
WRTY_START_D	8/18/2001
NAME	MAPLECREST FORD
DOC_NUM	4002002
PH_NUM	5432331
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	5/21/2002
TIS_WSD	12
CLM_KEY	8714143
MILGE	18711
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	64.0000000000000000
DLR_CD	1788
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	1 REPLACE DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT COME UN BUCKLED WHILE DRIVING
AREA_CD	973
COUNTRY_CD	USA
SLS_DLR_CD	314474
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	88
VIN_CD	5LMFU28FC11
LBR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TFL
DRIVE_CD	T/E
ENG_CD	TMC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/21/2001
WRTY_START_D	
NAME	SENTRY SOUTH LINCOLN-MERCURY INC
DOC_NUM	081838C
PH_NUM	8258900
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801202
PART_NUM_CAU	BAC
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	8/17/2001
TIS_WSD	-1
CLM_KEY	3371164
MILGE	25
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.5
DLR_CD	10233
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	VERIFIED RIGHT FRONT SEAT BELT BUCKEL WILL NOT LOCK. REPLACED THE BUCKLES AND RECHECKED TO CONFIRM REPAIR.
TECH_TXT2	
CUST_TXT	THE RIGHT FRONT SEAT BELT BUCKLE WILL NOT ENGAGE.
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	312308
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	B08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	90
VIN_CD	6LMFU28R31L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/25/2001
WRTY_START_D	2/17/2001
NAME	NAPLETON LINCOLN-MERCURY
DOC_NUM	073816A
PH_NUM	*
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	788120S
PART_NUM_CAU	CAA
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	12/13/2001
TIS_WSD	10
CLM_KEY	5782105
MILGE	8801
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10279
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACE SEAT BELT BUCKLE C
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT LATCH DRIVERS FRONT
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	342402
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	91
VIN_CD	6LMFU28R31L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/22/2000
WRTY_START_D	10/6/2001
NAME	PRESTIGE LINCOLN-MERCURY
DOC_NUM	18018401
PH_NUM	5448661
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	1/23/2002
TIS_WSD	4
CLM_KEY	6440933
MILGE	5060
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	12545
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MN
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	1 REPLACE DRIVER SEAT BELT BUCKLE
TECH_TXT2	
CUST_YXT	SOP SEAT BELT
AREA_CD	982
COUNTRY_CD	USA
SLS_DLR_CD	343882
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	83
VIN_CD	5LJMFJ28RQ31L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DX
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	4/18/2001
NAME	DEMPEWOLF FORD LINCOLN-MERCURY
DOC_NUM	4211252
PH_NUM	8273588
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	540
COND_CD	28
RPR_DT	12/8/2001
TIS_WSD	8
CLM_KEY	6888882
MILGE	5774
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	5668
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	KY
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	BUCKLE FAILED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	PARTS REPLACE SEAT BELT ON THE DRIVERS SEAT
AREA_CD	270
COUNTRY_CD	USA
SLS_DLR_CD	348898
TXN_CD	E83
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	97
VIN_CD	5LMFU28R21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/RND
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/29/2001
WRTY_START_D	3/29/2001
NAME	HARVEST FORD LINCOLN-MERCURY
DOC_NUM	65732701
PH_NUM	8843121
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7081203
PART_NUM_CAU	CAA
CUST_CONC_CD	626
COND_CD	42
RPR_DT	6/16/2002
TIS_WSD	14
CLM_KEY	8837087
MILGE	11028
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	07
DLR_CD	7845
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OR
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	1 INSPECTED VEHICLE AND REPLACED LEFT FRONT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT DOES NOT LATCH
AREA_CD	541
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TES_FLAG	@

MDL_YR	2001
SORT_INDEX	98
VIN_CD	5LMFL128F21
LBR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	
BOD_CAB_STL	TND
VER_SERIES_CD	TEL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/7/2001
WRTY_START_D	8/18/2001
NAME	NORTH FLORIDA LINCOLN-MERCURY
DOC_NUM	5123253
PH_NUM	8424100
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881213
PART_NUM_CAU	CAA
CUST_CONC_CD	340
COND_CD	33
RPR_DT	5/2/2002
TIS_WSD	9
CLM_KEY	8485410
MILGE	20804
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0:4
DLR_CD	11830
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	LOOSE SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEATBELT UNLATCHES ITSELF
AREA_CD	904
COUNTRY_CD	USA
SLS_DLR_CD	325082
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	100
VIN_CD	5LMPU28R21L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	6/28/2001
NAME	BURT LINCOLN MERCURY
DOC_NUM	103628E
PH_NUM	900000
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	3/11/2002
TIS_WSD	0
CLM_KEY	7508304
MILGE	9426
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	09
DLR_CD	10472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	11001
Ratings	#
TECH_TXT1	BUCKLE WILL NOT OPERATE PROPERLY REPLACE LEFT SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL NOT CLIP SOP HERE
AREA_CD	303
COUNTRY_CD	USA
SLS_DLR_CD	355120
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	101
VIN_CD	5LMFLJ28R21L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EL
DRIVE_CD	T1E
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/22/2001
WRTY_START_D	2/7/2001
NAME	BAYWAY LINCOLN MERCURY, INC.
DOC_NUM	8767063
PH_NUM	8298500
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7981293
PART_NUM_CAU	CAB
CUST_CONC_CD	S20
COND_CD	41
RPR_DT	3/7/2002
TIS_WSD	14
CLM_KEY	7323791
MILGE	9182
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	10093
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Estbgs	
TECH_TXT1	INSPECT SEAT BELT REPLACE BELT AND BUCKLE ASSY BINDING
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	387082
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	B05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	102
VIN_CD	9LMFU28R21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	7/10/2001
NAME	ROBERT H. IRWIN MOTORS, INC.
DOC_NUM	395044A
PH_NUM	6244822
WCC_CD	BR02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7961203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/9/2001
TIS_WSD	5
CLM_KEY	6559683
MILGE	9601
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 133 of 1298

RQ04-011 E 2158

LBR_HRS	03
DLR_CD	8827
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NH
CPSC_CD_6	11001
Ratings	■
TECH_TXT1	REPLACED DRIVERS SEATBELT
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WILL NOT BUCKLE AND CHIME STAYS ON
AREA_CD	803
COUNTRY_CD	USA
SLS_DLR_CD	312489
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	84
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	105
VIN_CD	5LMFLJ28F21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	8/11/2001
NAME	BAFFORD LINCOLN-MERCURY
DOC_NUM	216848A
PH_NUM	5603800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	BAC
CUST_CONC_CD	826
COND_CD	42
RPR_DT	5/15/2002
TIS_WSD	10
CLM_KEY	0653368
MILGE	10769
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	10018
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MD
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	10789 15 WPC REPLAE RIGHT FRONTR SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEAT BELT BUCKLE INOP
AREA_CD	301
COUNTRY_CD	USA
SLS_DLR_CD	328488
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	107
VIN_CD	5LMFU28R11L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T1E
DRIVE_CD	T1E
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/14/2001
WRTY_START_D	6/22/2001
NAME	FORD MOTOR COMPANY (WHQ)
DOC_NUM	1935551
PH_NUM	
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	940
COND_CD	33
RPR_DT	9/10/2001
TIS_WSD	4
CLM_KEY	4630748
MILGE	6858
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	66098
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPLACE PASS. SBLT. RELEASE
TECH_TXT2	
COST_TXT	
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	108
VIN_CD	5LMFU2BR11L
LRR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/E
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	12/17/2001
NAME	AL PACKER LINCOLN-MERCURY INC
DOC_NUM	0701388
PH_NUM	4858100
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7961203
PART_NUM_CAU	CAA
CUST_CONC_CD	928
COND_CD	42
RPR_DT	8/4/2002
TIS_WSD	8
CLM_KEY	9178942
MILGE	21848
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	10058
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MD
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	AFTER TESTING SEVERAL TIMES VERIFIED CONECNR REMOVED AND REPALCED LEFT SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT LATCH NOT WORKING AT TIMES
AREA_CD	410
COUNTRY_CD	USA
SLB_DLR_CD	328057
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	110
VIN_CD	9LMFU26R11L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WG
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/4/2001
WRTY_START_D	4/18/2001
NAME	HERTZ RAC - DENVER
DOC_NUM	44005201
PH_NUM	*
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	10/29/2001
TIS_WSD	7
CLM_KEY	6006056
MILGE	16150
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="46248"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CO"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACED THE BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="VEH SEATBELT LATCH INOP"/>
AREA_CD	<input type="text" value=""/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="365836"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="806"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	111
VIN_CD	5LMFU28R11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/4/2001
WRTY_START_D	4/10/2001
NAME	HERTZ RAC - DENVER
DOC_NUM	47135501
PH_NUM	*
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	12/11/2001
TIS_WSD	8
CLM_KEY	8725537
MILGE	18225
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	107
DLR_CD	45245
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED THE BELT
TECH_TXT2	
CUST_TXT	L F SEAT BELT W N LATCH
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	355836
TXN_CD	EDC
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	112
VIN_CD	5LMFU28R11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/1/2001
WRTY_START_D	11/6/2001
NAME	FIESTA LINCOLN-MERCURY
DOC_NUM	3320403
PH_NUM	8134000
WCC_CD	6R02
PART_NUM_CAU	1LZ
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	340
COND_CD	42
RPR_DT	1/3/2002
TIS_WSD	2
CLM_KEY	8131315
MILGE	2804
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 145 of 1298

RQ04-011 E 2170

LBR_HRS	0.5
DLR_CD	11890
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AZ
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	TECH 0468 BASIC7881233 CODE 42 CONFIRM DR SIDE SEAT BELT WONT LATCH AT TIMES RR DR SEAT ACCESS REPLACE SEAT BELT BUCKLE ASSY RETEST OK
TECH_TXT2	
CUST_TXT	C 8 THAT LEFT FRONT SEAT BELT RECEIVER WILL NOT LOCK CHECK AND ADVISE
AREA_CD	480
COUNTRY_CD	USA
SLS_DLR_CD	354280
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	114
VIN_CD	5LMFU28R11U
LBR_COST	
VEH_LINE_CD	704
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EI
DRIVE_CD	T/E
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/27/2001
WRTY_START_D	5/25/2001
NAME	HASSETT L-M SALES INC
DOC_NUM	18167901
PH_NUM	7857800
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	A85
COND_CD	41
RPR_DT	10/28/2001
TIS_WSD	6
CLM_KEY	4764892
MILGE	3592
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	11270
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Rating	0
TECH_TXT1	REPLACE L FRONT SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	516
COUNTRY_CD	USA
SLS_DLR_CD	314381
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V17
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	115
VIN_CD	5LMFU29R11L
LBR_COST	
VEH_LINE_CD	T7B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T7EL
DRIVE_CD	T7E
ENG_CD	T7WC
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	11/11/2000
WRTY_START_D	9/25/2001
NAME	ROSEN LINCOLN-MERCURY
DOC_NUM	234005B
PH_NUM	8508440
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	78B1202
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	33
RPR_DT	6/2/2002
TIS_WSD	8
CLM_KEY	8549583
MILGE	18803
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	64
DLR_CD	10593
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACED SEATBELT RT FT SEATBELT
TECH_TXT2	
CUST_TXT	OK RIGHT FORNT SEATBELT BUCKLE INTERMITTANTLY WILL NOT LATCH
AREA_CD	B47
COUNTRY_CD	USA
SLS_DLR_CD	342536
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	