

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 2 OF 6

BOOK 4 OF 43

MDL_YR	2001
SORT_INDEX	116
VIN_CD	5LMFU28R01LJS3377
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/22/2001
WRTY_START_D	7/12/2001
NAME	BOWDEN FORD LINCOLN MERCURY CO
DOC_NUM	080270A
PH_NUM	8849541
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	826
COND_CD	42
RPR_DT	4/15/2002
TIS_WSD	10
CLM_KEY	8885874
MILGE	11218
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4408"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="TX"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACE SEAT BELT BUCKLE ASSY"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES SEAT BELT BUCKLE ON DRIVER SIDE IT JAMMED"/>
AREA_CD	<input type="text" value="381"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="387046"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	117
VIN_CD	5LMFU28R01L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	2/18/2002
NAME	RANCHO FORD L-M
DOC_NUM	28183001
PH_NUM	8891302
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BA8
CUST_CONC_CD	540
COND_CD	42
RPR_DT	7/16/2001
TIS_WSD	0
CLM_KEY	3818374
MILGE	25
MTEL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	5432
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	INSPECT.REPLACED R BUCKLE.L BUCKLE OK.
TECH_TXT2	
CUST_TXT	SEAT BELT NOT WORKING PROPERLY
AREA_CD	000
COUNTRY_CD	USA
SLS_DLR_CD	334000
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	119
VIN_CD	ELMPJ28R01L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	7/15/2001
NAME	BRIAN HOSKINS FORD LINCOLN-MER
DOC_NUM	10354801
PH_NUM	3844242
WCC_CD	BR02
PART_NUM_CAU	1L72
PART_NUM_CAU	7861208
PART_NUM_CAU	BAA
CUST_CONC_CD	326
COND_CD	41
RPR_DT	12/12/2001
TIS_WSD	8
CLM_KEY	5774081
MILGE	5319
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	1239
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACED SEAT BELTS
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELT BUCKLE.
AREA_CD	810
COUNTRY_CD	USA
SLS_DLR_CD	315304
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	120
VIN_CD	5LMFL126R01L
LBR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TFL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	8/2/2001
NAME	SOUTHWEST LINCOLN-MERCURY INC
DOC_NUM	22702801
PH_NUM	9813300
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	2
CLM_KEY	2881304
MILGE	2838
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	88
DLR_CD	11458
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	1 REPLACE DRIVERS SEAT BELT COMES UNLATCHED
TECH_TXT2	
CUST_TXT	CHECK DRIVERS SEAT BELT COMES UNLATCHED S40
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	367298
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	122
VIN_CD	5LMFU2BR01L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T&L
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	1/31/2001
NAME	FORD MOTOR COMPANY (WHQ)
DOC_NUM	1030261
PH_NUM	*
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	GAA
CUST_CONC_CD	940
COND_CD	33
RPR_DT	7/24/2001
TIS_WSD	6
CLM_KEY	5303795
MILGE	10812
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	03
DLR_CD	0000
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	E03
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	123
VIN_CD	5LMFU26R01
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/ND
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/MC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	5/21/2001
NAME	HOLMAN LINCOLN-MERCURY
DOC_NUM	187653A
PH_NUM	2944000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	9/21/2001
TIS_WSD	5
CLM_KEY	3823744
MILGE	3125
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	10409
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	CHECK AND REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	D S SEAT BELT DOES NOT STAY BUCKLED
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	315040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	124
VEN_CD	5LMFU28R01L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/26/2000
WRTY_START_D	11/15/2000
NAME	MULLINAX LINCOLN MERCURY SALES
DOC_NUM	13117401
PH_NUM	4768501
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/17/2001
TIS_WSD	12
CLM_KEY	4525438
MILGE	13740
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	10311
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TN
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	PERFORMED RECALL AND REPLACED SEAT BLET
TECH_TXT2	
CUST_TXT	RECALL 01821 REPLACE SEATBELT
AREA_CD	429
COUNTRY_CD	USA
SLS_DLR_CD	328105
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	506
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	125
VIN_CD	5LMFU28AB1L
LBR_COST	
VEH_LINK_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	9/14/2000
WRTY_START_D	9/24/2001
NAME	LYNNHAVEN LINCOLN-MERCURY
DOC_NUM	306675A
PH_NUM	3400600
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7561203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	11/14/2001
TIS_WSD	2
CLM_KEY	5144110
MILGE	13437
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	12314
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	13437 REPLACED PASS SEAT BELT BUCKEL #29
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEATBELT BUTTON STICKS SOP IN
AREA_CD	757
COUNTRY_CD	USA
SLS_DLR_CD	328278
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	128
VIN_CD	5LMFU2BA91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DRRIVED	*
ROD_CAB_STL	T/WD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/9/2000
WRTY_START_D	12/15/2000
NAME	UPTOWN MOTORS, INC.
DOC_NUM	142728A
PH_NUM	7719000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861213
PART_NUM_CAU	CAA
CUST_CONC_CD	925
COND_CD	42
RPR_DT	2/7/2002
TIS_WSD	14
CLM_KEY	6067689
MILGE	20600
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 167 of 1298

RQ04-011 E 2192

LBR_HRS	92
DLR_CD	12102
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WI
CPSC_CD_6	11001
Ratings	
TECH_TXT1	INSPECTED AND REPLACED SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	OK DRIVERS SIDE SEAT BELT BUCKLE INOP
AREA_CD	414
COUNTRY_CD	USA
SLS_DLR_CD	342384
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	128
VIN_CD	5LMFLJ28A811
LBR_COST	
VEH_LINK_CD	T84
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/19/2000
WRTY_START_D	10/21/2000
NAME	CHESTER LM-ANNANDALE
DOC_NUM	168496D
PH_NUM	7602700
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7681203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	9/16/2001
TIS_WSD	12
CLM_KEY	3823072
MILGE	19994
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	10013
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	e
TECH_TXT1	10904 REPLACE RIGHT FRT SEAT BELT BUCKLE BUTTON STICKS AT TIMES
TECH_TXT2	
CUST_TXT	RIGHT FRONT SEATBELT BUCKLE JAMS
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	328008
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	129
VIN_CD	5LMFL128A81L
LRR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_CD	T/E1
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/18/2000
WRTY_START_D	11/7/2000
NAME	BOB BORST LINCOLN MERCURY
DOC_NUM	070088A
PH_NUM	8496600
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAA
CUST_CONC_CD	525
COND_CD	42
RPR_DT	1/10/2002
TIS_WSD	15
CLM_KEY	01B4512
MILGE	3409
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	10909
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACE RT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	REPLACE RIGHT FRONT SEAT BELT BUCKLE WITH NEW WILL NOT LATCH PARTS IN STOCK TO REPLACE
AREA_CD	810
COUNTRY_CD	USA
SLS_DLR_CD	345350
TXN_CD	E54
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	84
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	130
VIN_CD	5LMFU2BA71L
LBR_COST	28383
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/D/E
PLANT_CD	AP
PRODN_DT	10/8/2000
WRTY_START_D	5/31/2001
NAME	STIVERS LINCOLN-MERCURY INC
DOC_NUM	2702551
PH_NUM	2435200
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	CAA
CUST_CONC_CD	625
COND_CD	41
RPR_DT	8/10/2001
TLS_WSD	3
CLM_KEY	2016030
MILGE	6173
MTRL_COST	28383
TOT_COST_GROS	28383

LBR_HRS	04
DLR_CD	12832
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED
AREA_CD	515
COUNTRY_CD	USA
SLS_DLR_CD	383589
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S05
TLS_FLAG	

MDL_YR	2001
SORT_INDEX	132
VIN_CD	5LMFL23A41L
LBR_COST	
VEH_LINE_CD	T64
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TFL
DRIVE_CD	TE
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	10/6/2000
WRTY_START_D	8/27/2001
NAME	BLUE HILL LINCOLN-MERCURY INC
DOC_NUM	25823308
PH_NUM	8287180
WCC_CD	6RQ2
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	640
COND_CD	42
RPR_DT	10/10/2001
TIS_WSD	4
CLM_KEY	4806488
MILGE	3851
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	02
DLR_CD	13136
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACE SEATBELT
TECH_TXT2	
CUST_TXT	
AREA_CD	781
COUNTRY_CD	USA
SLS_DLR_CD	312206
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	806
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	134
VIN_CD	5LMFU28A41L
LBR_COST	
VEH_LINE_CD	T7B4
MKT_DERIVED	*
BOD_CAR_STL	T7WD
VEH_SERIES_CD	T7EL
DRIVE_CD	T7E
ENG_CD	T7WC
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	8/12/2000
WRTY_START_D	12/27/2000
NAME	BOB BIGHT LINCOLN-MERCURY INC
DOC_NUM	1383068
PH_NUM	3812100
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	6/31/2002
TES_WSD	18
CLM_KEY	8854058
MILGE	34405
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	12805
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	KS
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	34405 81172A 0.4 0.4 REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	PASSENGER FRONT SEAT BELT HARD TO CLASP IN
AREA_CD	813
COUNTRY_CD	USA
SLS_DLR_CD	383407
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	137
VIN_CD	6LMEU27RX1L
LBR_COST	
VRH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/21/2001
WRTY_START_D	8/14/2001
NAME	WEST POINT LINCOLN-MERCURY
DOC_NUM	33585101
PH_NUM	5292511
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801202
PART_NUM_CAU	BAC
CUST_CONC_CD	940
COND_CD	42
RPR_DT	7/26/2001
TIS_WSD	0
CLM_KEY	3007324
MILGE	6
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	108
DLR_CD	11406
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	SEAT BELT BUCKLE INOPERATIVE REPLACE PASSENGER SIDE SEAT BELT BUCKLE INOPERATIVE
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE NOT WORKING PROPERLY
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	387020
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	138
VIN_CD	5LMEU27RX1L
LBR_COST	
VBH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/1/2001
WRTY_START_D	10/3/2001
NAME	O. C. WELCH FORD LINCOLN-MERCU
DOC_NUM	7863161
PH_NUM	5243171
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/12/2001
TIS_WSD	3
CLM_KEY	6742165
MILGE	2876
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	1018
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	12001
Ratings	c
TECH_TXT1	REPLACE PASS FRONT SEATBELT
TECH_TXT2	
CUST_TXT	CHECK PASS SIDE COMES UNLATCHED
AREA_CD	848
COUNTRY_CD	USA
SLS_DLR_CD	328223
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	139
VIN_CD	5LMEL27RX1
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAR_STL	TWB
VER_SERIES_CD	T/E
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/7/2001
WRTY_START_D	3/1/2001
NAME	VILLAGE LINCOLN MERCURY OF IRV
DOC_NUM	1805252
PH_NUM	4457200
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	8AB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	7/21/2001
TIS_WSD	5
CLM_KEY	2618361
MILGE	10087
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	10478
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	RECALL INSPECT AND REPLACE ONE SEATBELT BUCKLE PER RECALL
TECH_TXT2	
CUST_TXT	01821 SEAT BELT BUCKLE
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	387006
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	140
VIN_CD	5LMEU27RX1L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VBR_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/19/2000
WRTY_START_D	7/6/2001
NAME	DON KOTT LINCOLN MERCURY
DOC_NUM	3826382
PH_NUM	8182500
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	1
RPR_DT	7/11/2001
TIS_WSD	1
CLM_KEY	2878398
MILGE	146
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	11818
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	BROKEN REPLACED DRIVERS BUCKLE AND PASS BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES THAT DRIVER SEAT BELT SOMETIMES DOES NOT LOCK IN AND COMES LOOSE WHEN DRIVING
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	364260
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	141
VIN_CD	6LMEL27RX1U
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
KNG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/21/2000
WRTY_START_D	1/13/2001
NAME	SPARTAN LINCOLN-MERCURY, INC.
DOC_NUM	22786201
PH_NUM	9881246
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	10/3/2001
TIS_WSD	8
CLM_KEY	4256210
MILGE	7410
MTRL_COST	
TOY_COST_GROS	

LBR_HRS	QA
DLR_CD	10176
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACED DRIVERS SIDE SEATBELT BUCKLE ASSY GC01
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT INOP
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	328140
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	142
VIN_CD	5LMEU27RX1
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/26/2000
WRTY_START_D	05/2001
NAME	PUGMIRE LINCOLN-MERCURY INC
DOC_NUM	6848452
PH_NUM	8522281
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S26
COND_CD	68
RPR_DT	5/13/2002
TIS_WSD	12
CLM_KEY	8827755
MILGE	24025
MYRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10188
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	SEATBELT RECEIVER FAILURE SEATBELT RECEIVER FRONT REPLACE
TECH_TXT2	
CUST_TXT	G B THE DRIVERS SEAT BELT WILL NOT STAY LATCHED
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	328233
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	143
VIN_CD	5LMEU27R91L
LBR_COST	
VEH_LINE_CD	T7B4
MKT_DERIVED	*
BOD_CAB_STL	T7WB
VER_SERIES_CD	T7E1
DRIVE_CD	T7B
ENG_CD	T7WC
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	8/13/2001
WRTY_START_D	8/22/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	8463251
PH_NUM	5384900
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	7/26/2001
TIS_WSD	0
CLM_KEY	4009070
MILGE	11
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	10184
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACE BOTRH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELTS NO WORKING CORRECTLY
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	387023
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S03
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	144
VIN_CD	5LMEU27R91L
LBR_COST	36485
VEH_LINE_CD	T/B4
MKT_DERIVED	1
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/21/2001
WRTY_START_D	9/9/2001
NAME	CERRITOS LINCOLN-MERCURY
DOC_NUM	8281801
PH_NUM	9856025
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	325
COND_CD	42
RPR_DT	7/27/2001
TIS_WSD	0
CLM_KEY	3088088
MILGE	10
MTRL_COST	36485
TOT_COST_GROS	36485

LBR_HRS	04
DLR_CD	11907
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Rating	0
TECH_TXT1	REPLACED DRIVER SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELTINOP
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	364015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	145
VIN_CD	6LMEU27R91
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/VB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	6/30/2001
NAME	CENTRAL FLORIDA LINCOLN MERCUR
DOC_NUM	3490851
PH_NUM	8414550
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	GAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	2
CLM_KEY	2781428
MILGE	2650
MTRL_COST	
TOY_COST_GROS	

LBR_HRS	04
DLR_CD	10021
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	UNLOCKS SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVER S SEAT BELT KEEPS UNLOCKING WHILE DRIVING SEE FILE
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	325189
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	146
VIN_CD	6LMEU27R91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	6/5/2001
NAME	COVINGTON PIKE LINCOLN MERCURY
DOC_NUM	8188101
PH_NUM	3735700
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/22/2001
TIS_WSD	3
CLM_KEY	3229238
MILGE	8270
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10198
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	REPLACED LFT FRT SEAT BELT BUCKLE ASSY. COMES LOOSE WHILE DRIVING.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVER SEAT BELT COMES OUT WHILE DRIVING SOP IN
AREA_CD	901
COUNTRY_CD	USA
SLS_DLR_CD	322684
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	147
VIN_CD	5LMEU27R91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	5/12/2001
NAME	LEGACY LINCOLN-MERCURY
DOC_NUM	5799101
PH_NUM	2404020
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	6/11/2002
TIS_WSD	14
CLM_KEY	6130856
MILGE	20288
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11857
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	7861203 7881202 C 042 M20288 CHECK BOTH SEAT BELT OPERATION WITH RECALL TESTER FAIL REPLACED LEFT & RIGHT FRONT SEAT BELT BUCKLES RETEST OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT WILL COME UNLATCHED BY ITSELF WHILE DRIVING.CC 526
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	326216
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	806
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	148
VIN_CD	5LMEU27R91L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
MOD_CAR_STL	7WB
VER_SERIES_CD	T/E1
DRIVE_CD	T/B
ENG_CD	TWC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	2/27/2001
WRTY_START_D	4/18/2001
NAME	SANTA MONICA LINCOLN-MERCURY
DOC_NUM	21605501
PH_NUM	3939981
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	CAA
CUST_CONC_CD	640
COND_CD	41
RPR_DT	3/6/2002
TIS_WSD	11
CLM_KEY	7814161
MILGE	7316
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 261 of 1298

RQ04-011 E 2228

LBR_HRS	096
DLR_CD	11B43
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Radngs	o
TECH_TXT1	REPL L FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	354200
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	140
VIN_CD	5LMEL27R91L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	2/28/2001
NAME	WITT LINCOLN MERCURY
DOC_NUM	11175701
PH_NUM	3586000
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	625
COND_CD	42
RPR_DT	6/23/2001
TIS_WSD	8
CLM_KEY	3498740
MILGE	7000
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	9.7
DLR_CD	10473
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	PERFORMED SEAT BELT BUCKLE TEST LEFT BELT BUCKLE FAILED RIGHT BELT BUCKLE FAILED REPLACED LEFT FRONT BELT BUCKLE REPLACED RIGHT FRONT BELT BUCKLE AS PER BULLETIN QC 8F
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLES DID NOT PASS NEED TO REPLACE SOP BELTS ARE HERE
AREA_CD	B10
COUNTRY_CD	USA
SLS_DLR_CD	354800
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	150
VIN_CD	5LME1J27R811
LBR_COST	
VEH_LINE_CD	T7B4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	T7EL
DRIVE_CD	T7B
ENG_CD	T7WC
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	10/10/2000
WRTY_START_D	10/30/2000
NAME	CERRITOS LINCOLN-MERCURY
DOC_NUM	9493501
PH_NUM	9855025
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/15/2001
TIS_WSD	12
CLM_KEY	4585000
MILGE	22404
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	11807
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	61202 M TIME TO REPLACE THE RIGHT FRONT SEAT BELT BUCKLE. STICKING, NOT RELATED TO RECALL
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE RIGHT FRONT SEAT BELT DOES NOT LATCH
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	354015
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	151
VIN_CD	6LMEU27R81L
LBR_COST	
VEH_LINE_CD	T1B4
MKT_DERIVED	
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	9/22/2001
NAME	ANTELOPE VALLEY FORD
DOC_NUM	8770281
PH_NUM	9483588
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	41
RPR_DT	7/20/2001
TIS_WSD	1
CLM_KEY	4000482
MILGE	1701
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	9.8
DLR_CD	5426
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	WONT STAY LATCHED REPLACED DRIVERS SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT WONT STAY LATCHED
AREA_CD	806
COUNTRY_CD	USA
SLS_DLR_CD	354133
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	162
VIN_CD	5LMEU27R81L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	T/E
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	4/3/2001
WRTY_START_D	3/18/2001
NAME	DIABLO LINCOLN-MERCURY INC
DOC_NUM	044807B
PH_NUM	6823150
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	1/15/2002
TIS_WSD	9
CLM_KEY	6900020
MILGE	14187
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	12711
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	INSPECTED REAR MIDDLE SEAT BELT BUCKLE, WILL NOT LATCH, REPLACED SEAT BELT BUCKLE AND RETEST
TECH_TXT2	
CUST_TXT	SPECIAL ORDERED PARTS ORDERED FOR RECALL, PREVIOUS RO 41002, TECH # 12, L F DRIVERS SEAT BELT, R F PASS SEAT SIDE, AND RIGHT REAR OF MIDDLE ROW SEAT BELT WONT BUCKLE
AREA_CD	925
COUNTRY_CD	USA
SLS_DLR_CD	351024
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S00
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	153
VIN_CD	5LMEJ27R81L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/28/2001
WRTY_START_D	10/31/2001
NAME	CERRITOS LINCOLN-MERCURY
DOC_NUM	9413501
PH_NUM	9955025
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	9/19/2001
TIS_WSD	0
CLM_KEY	4488071
MILGE	1112
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	64
DLR_CD	11907
DLR_SUB_CD	7
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	7861203 CC 42 0.8 TO REPLACE DRIVERS SEAT BELT BUCKLE. NGS BODY CHASSIS ELECTRICAL BCE START UP TEST NGS BODY CHASSIS ELECTRICAL DIAGNOSIS *NGS PIN POINT TEST FOUND
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT INDICATOR INOP
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	354016
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	154
VIN_CD	5LMEU27R71L
LRR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/19/2001
WRTY_START_D	8/14/2001
NAME	DON RICH FORD CO., INC.
DOC_NUM	588602
PH_NUM	4885132
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RFR_DT	12/28/2001
TIS_WSD	5
CLM_KEY	8838845
MILGE	18977
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	404
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	CK OUT INSP.TEST REPLACE FAULTY BELT
TECH_TXT2	
CUST_TXT	CK SEAT BELT WILL NOT BUCKLE
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	328233
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	156
VIN_CD	3LMEU27R71
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/4/2001
NAME	POFFENBAUGH FORD-LINC-MERC
DOC_NUM	6735861
PH_NUM	8822141
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7961203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	11/16/2001
TIS_WSD	5
CLM_KEY	5191148
MILGE	13278
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	4822
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES LEFT FRONT SEATBELT WONT LATCH
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	325132
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S0B
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	156
VIN_CD	5LMEL27R71
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	
BOD_CAB_STL	TMB
VER_SERIES_CD	T/EL
DRIVE_CD	TB
ENG_CD	TWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/13/2002
WRTY_START_D	4/3/2001
NAME	NORTHGATE LINCOLN-MERCURY INC
DOC_NUM	38845901
PH_NUM	9338781
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7551203
PART_NUM_CAU	CAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	5/15/2002
TIS_WSD	14
CLM_KEY	8876385
MILGE	11B85
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	64
DLR_CD	11845
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	1 VERIFIED CONCERN INSTALLED SOP THE DRIVER SEAT BELT BUCKLE RETESTED OK AT THIS TIME
TECH_TXT2	
CUST_TXT	825 LEFT FRONT SEAT BELT WONT STAY LATCHED AT TIMES SPECIAL ORDER SEAT BELT LATCH HERE
AREA_CD	B13
COUNTRY_CD	USA
SLS_DLR_CD	325160
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S0B
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	157
VIN_CD	5LMEU27R71L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EI
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	2/4/2001
WRTY_START_D	5/28/2001
NAME	WITT LINCOLN MERCURY
DOC_NUM	12187102
PH_NUM	3585000
WCC_CD	5R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7981202
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/27/2001
TIS_WSD	8
CLM_KEY	5068558
MILGE	3127
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10475
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Rating	a
TECH_TXT1	PREVIOUSLY TEST SEAT BELT BUCKELS FOR LEFT AND RIGHT FRONT BUCKELS REPLACED LEFT LAST VISIT HAD TO ORDER RIGHT LAST REPLACED RIGHT SEAT BELT BUCKEL FAILED UNDER SEAT BELT BUCKEL TEST QC BF
TECH_TXT2	
CUST_TXT	RECALL 01S21 SEAT BELT BUCKLE SOP HERE PASSENGER SIDE
AREA_CD	615
COUNTRY_CD	USA
SLS_DLR_CD	354600
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	158
VIN_CD	8LMEU27R71L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/26/2001
WRTY_START_D	4/23/2001
NAME	VERO BEACH LINCOLN-MERCURY INC
DOC_NUM	1384383
PH_NUM	5875272
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	GAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	3/15/2002
TIS_WSD	11
CLM_KEY	0827443
MILGE	16991
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11607
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	REPLACED LEFT FRONT SEATBELT
TECH_TXT2	
CUST_TXT	SPO HERE FOR RECALL # 02S21 INSPECTED ON 12 18 01 ROW 10504 LEFT FRONT FAILED
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	326184
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	159
VIN_CD	5LMEU27R71L
LBR_COST	2875
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/16/2000
WRTY_START_D	3/28/2001
NAME	DELRAY LINCOLN-MERCURY INC
DOC_NUM	0333861
PH_NUM	2782411
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	CAA
CUST_CONC_CD	928
COND_CD	1
RPR_DT	5/4/2002
YIS_WSD	14
CLM_KEY	8488489
MILGE	12786
MTRL_COST	
TOT_COST_GROS	

Thursday, December 14, 2004

Page 223 of 1298

RQ04-011 E 2248

LBR_HRS	0.5
DLR_CD	11812
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	BROKEN REPLACE LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	C S DRIVER SEAT BELT WONT LATCH
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	325032
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	180
VIN_CD	6LMEU27R61L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/5/2001
WRTY_START_D	4/23/2002
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	6483162
PH_NUM	5394800
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7801203
PART_NUM_CAU	BAA
CUST_CONC_CD	926
COND_CD	42
RPR_DT	7/26/2001
TIS_WSD	0
CLM_KEY	3826348
MILGE	11
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	68
DLR_CD	10164
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	
TECH_TXT1	SEAT BELTS INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEAT BELTS INOP
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	387023
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	161
VIN_CD	5LMEL27R81L
LBR_COST	
VEH_LINE_CD	T/84
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/4/2001
WRTY_START_D	8/28/2001
NAME	WEST POINT LINCOLN-MERCURY
DOC_NUM	33585201
PH_NUM	5292511
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/28/2001
TIS_WSD	0
CLM_KEY	3087328
MILGE	0
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	11405
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	SEAT BELT BUCKLE PASSENGER SIDE INOPERATIVE REPLACE PASSENGER SIDE SEAT BELT BUCKLE INOPERATIVE
TECH_TXT2	
CUST_TXT	SEAT BELT BUSKLE INOPERATIVE
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	367021
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	163
VIN_CD	5LMEU27R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DIE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	6/25/2001
NAME	EAGLE LINCOLN-MERCURY INC
DOC_NUM	40673802
PH_NUM	3570481
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/10/2001
TIS_WSD	7
CLM_KEY	5785222
MILGE	11768
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10855
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT LATCH,RECHECKED OK.
TECH_TXT2	
CUST_TXT	CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	357510
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	184
VIN_CD	5LMEL27R81L
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
BOD_CAB_STL	TAWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/4/2001
WRTY_START_D	8/11/2001
NAME	LADIN LINCOLN-MERCURY
DOC_NUM	5118505
PH_NUM	4962193
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	6
CLM_KEY	6908055
MILGE	8583
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	93
DLR_CD	11803
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	REPLACED DRIVERS SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	354290
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	166
VIN_CD	5LMEU27R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/6/2001
WRTY_START_D	5/31/2001
NAME	ALEX KARRAS LING-MERC INC
DOC_NUM	9988201
PH_NUM	7564004
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	B26
COND_CD	42
RPR_DT	4/23/2002
TIS_WSD	11
CLM_KEY	8757028
MILGE	12624
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	
DLR_CD	11803
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACE BOTH FRONT SEAT BELT ASY
TECH_TXT2	
CUST_TXT	BOTH FRONT SEAT BELT DONT SNAP TOGETHER GOOD
AREA_CD	B13
COUNTRY_CD	USA
SLS_DLR_CD	325007
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	