

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 3 OF 6

BOOK 4 OF 43

MDL_YR	2001
SORT_INDEX	167
VIN_CD	6LMELJ27R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	3/13/2001
NAME	KING FORD LINCOLN MERCURY
DOC_NUM	12178201
PH_NUM	7587111
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	GAA
CUST_CONC_CD	528
COND_CD	41
RPR_DT	2/2/2002
TIS_WSD	11
CLM_KEY	8878680
MILGE	5908
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	83
DLR_CD	271
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	CHECK AND REPLACE DRIVERS SEAT BELT BUCKLE.WILL NOT FASTEN.
TECH_TXT2	
CUST_TXT	REPLACE DRIVERS SEAT BELT BUCKLE INOP
AREA_CD	334
COUNTRY_CD	USA
SLS_DLR_CD	328582
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B4
VRI_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	100
VIN_CD	6LMEL27R81L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/20/2000
WRTY_START_D	2/2/2001
NAME	FUGMFE LINCOLN-MERCURY INC
DOC_NUM	6672452
PH_NUM	8522281
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	640
COND_CD	33
RPR_DT	7/12/2001
TIS_WSD	8
CLM_KEY	2455141
MILGE	6302
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	01
DLR_CD	10198
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	SEATBELT FAULTY SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	C & THE DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	326057
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	170
VIN_CD	6LMEL27R51L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/20/2001
WRTY_START_D	8/8/2001
NAME	LADIN LINCOLN-MERCURY
DOC_NUM	4485201
PH_NUM	4852198
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	940
COND_CD	42
RPR_DT	7/20/2001
TIS_WSD	0
CLM_KEY	3287190
MILGE	5
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	09
DLR_CD	11803
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11801
Ratings	9
TECH_TXT1	VOLUNTARY FACTORY SAFETY RECALL. INSPECT AND REPLACE ONE SEAT BELT BUCKLE RIGHT
TECH_TXT2	
CUST_TXT	
AREA_CD	B05
COUNTRY_CD	USA
SLS_DLR_CD	354290
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	171
VIN_CD	6LMEU27R61
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/10/2001
WRTY_START_D	9/1/2001
NAME	CERRITOS LINCOLN-MERCURY
DOC_NUM	8879001
PH_NUM	9855025
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	9/8/2001
TIS_WSD	1
CLM_KEY	3694482
MILGE	211
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	000
DLR_CD	11907
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	FAULTY RT SIDE BUCKLE SEATBELT BUCKLE DOESNT HOLD.REPLACED PASS SIDE BUCKLE NO RECALL ON VEHICLE
TECH_TXT2	
CUST_TXT	PASSENGER SIDE SEAT BELT DOESNT HOLD PER OASIS NO OPEN CAMPAIGN BUT FAILED TEST
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	354015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	172
VIN_CD	6LMEJ27R61L
LRR_COST	
VEH_LINE_CD	7B4
MKT_DERIVED	
BOD_CAB_STL	TWB
VER_SERIES_CD	TTEL
DRIVE_CD	TB
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/29/2001
WRTY_START_D	5/51/2001
NAME	DAVID MCDAVID'S PLANO LINCOLN
DOC_NUM	421818A
PH_NUM	9845000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	1
RPR_DT	7/18/2001
TLS_WSD	2
CLM_KEY	2425235
MILGE	1342
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0:5
DLR_CD	11442
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACE DRIVERS SEAT BELT; WILL NOT LATCH
TECH_TXT2	
CUST_TXT	S40 C S DRIVERS SEATBELT WILL NOT STAY LATCHED SOP IN
AREA_CD	072
COUNTRY_CD	USA
SLS_DLR_CD	367324
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	173
VIN_CD	6LMEU27R61L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	5/21/2001
NAME	CLOVERLEAF LINCOLN-MERCURY INC
DOC_NUM	17758602
PH_NUM	3503071
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S26
COND_CD	68
RPR_DT	4/24/2002
TIS_WSD	12
CLM_KEY	8234634
MILGE	12328
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	12048
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACED FRONT SEATBELT AS PART OF RECALL
TECH_TXT2	
CUST_TXT	CUST STATES PERFORM RECALL ON SEATBELT ASSY
AREA_CD	205
COUNTRY_CD	USA
SLS_DLR_CD	328378
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	174
VIN_CD	5LN6U27R51
LBR_COST	
VRH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/14/2001
WRTY_START_D	4/2/2001
NAME	SHETLER LINCOLN-MERCURY LTD
DOC_NUM	262201
PH_NUM	4781720
WCC_CD	8R02
PART_NUM_CAU	5L72
PART_NUM_CAU	7081203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	
RPR_DT	8/22/2001
TIS_WSD	5
CLM_KEY	3302050
MILGE	4687
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 247 of 1298

RQ04-011 E 2272

LBR_HRS	00
DLR_CD	12213
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPLACED BOTH FRONT SEAT BUCKLES
TECH_TXT2	
CUST_TXT	LEFT & RIGHT FRONT SEAT BELT BUCKLES DEFECTIVE
AREA_CD	318
COUNTRY_CD	USA
SLS_DLR_CD	322842
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	175
VIN_CD	5LMEU27R51L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/23/2001
WRTY_START_D	11/10/2001
NAME	BARANCO LINCOLN-MERCURY INC
DOC_NUM	2406001
PH_NUM	4976900
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	540
COND_CD	12
RPR_DT	11/23/2001
TIS_WSD	1
CLM_KEY	5286790
MILGE	588
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 249 of 1298

RQ04-011 E 2274

LBR_HRS	0A
DLR_CD	10157
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	REPLACED SEAT BELT LATCH TO CORRECT
TECH_TXT2	
CUST_TXT	CK CUST STATES DRIVERS SEAT BELT WILL COME LOOSE FROM BUCKLE INTERMITTANTLY. S40
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	328057
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	177
VIN_CD	SLMEU27R41L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/25/2001
WRTY_START_D	7/24/2001
NAME	VISTA LINCOLN-MERCURY
DOC_NUM	6067961
PH_NUM	3488600
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	78B1203
PART_NUM_CAU	CAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	7/17/2001
TIS_WSD	0
CLM_KEY	2704307
MILGE	12
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 251 of 1298

RQ04-011 E 2278

LBR_HRS	85
DLR_CD	10095
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACE SEAT BELTS 01921
TECH_TXT2	
CUST_TXT	PERFORM RECALL #01921
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	354291
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	180
VIN_CD	SLMEU27R41U
LBR_COST	
VEH_LINE_CD	T84
MKT_DERIVED	
HOD_CAB_STL	T/WB
VER_SERIES_CD	TEL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/17/2000
WRTY_START_D	3/2/2001
NAME	LADIN LINCOLN-MERCURY
DOC_NUM	4582801
PH_NUM	4982183
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/15/2001
TIS_WSD	8
CLM_KEY	3373082
MILGE	5300
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	11803
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	1
TECH_TXT1	1 DISCUSS WITH ERIC TAYLOR FORD CSM IN THE INTREST OF CUSTOMER SATISFACTION REPLACED FRONT SEAT BELT BUCKLES.
TECH_TXT2	
CUST_TXT	
AREA_CD	806
COUNTRY_CD	USA
SLS_DLR_CD	354280
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	181
VIN_CD	6LMEU27R31L
LBR_COST	2.76
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/27/2001
WRTY_START_D	8/29/2001
NAME	ASTRO LINCOLN-MERCURY INC
DOC_NUM	15292701
PH_NUM	4788631
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/6/2001
TIS_WSD	1
CLM_KEY	3883885
MILGE	983
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	11818
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACR DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	860
COUNTRY_CD	USA
SLS_DLR_CD	325123
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	505
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	182
VIN_CD	ELMEU27RS1L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	3/6/2002
NAME	ANTELOPE VALLEY FORD
DOC_NUM	6762461
PH_NUM	6493566
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BA8
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	7/16/2001
TIS_WSD	0
CLM_KEY	3027144
MILGE	B
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	01
DLR_CD	5426
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	e
TECH_TXT1	RECALL 01S21 01S21 REPLACED PASS. SEAT BELT
TECH_TXT2	
CUST_TXT	CUST REQS RECALL 01S21 PASS BELT
AREA_CD	505
COUNTRY_CD	USA
SLS_DLR_CD	354133
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	183
VIN_CD	5LMEL27R31L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/22/2001
WRTY_START_D	7/27/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	8458551
PH_NUM	5394800
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	7/26/2001
TIS_WSD	0
CLM_KEY	4122240
MILGE	24
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	07
DLR_CD	10164
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	INSTALLED BOTH BUCKLES COME LOOSE
TECH_TXT2	
CUST_TXT	CHECK SEAT BELTS BINDS
AREA_CD	261
COUNTRY_CD	USA
SLS_DLR_CD	367266
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	184
VIN_CD	5LMELJ27R81L
LBR_COST	19.31
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/27/2001
WRTY_START_D	3/10/2001
NAME	MEDFORD FORD, INC.
DOC_NUM	017371A
PH_NUM	6877821
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	5/21/2002
TIS_WSD	15
CLM_KEY	8977889
MILGE	20248
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 261 of 1298

RQ04-011 E 2286

LBR_HRS	04
DLR_CD	3718
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	CHECK AND TEST WILL NOT CLICK REMOVE AND REPALCE ASSMY RETES T
TECH_TXT2	
CUST_TXT	PASS FRT SEAT BELT INSPECTION
AREA_CD	S34
COUNTRY_CD	USA
SLS_DLR_CD	328136
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRI_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	185
VIN_CD	6LMEU27R311
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	6/7/2001
NAME	SIGNATURE LINCOLN-MERCURY
DOC_NUM	3229552
PH_NUM	4570321
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAC
CUST_CONC_CD	626
COND_CD	41
RPR_DT	4/19/2002
TIS_WSD	12
CLM_KEY	6235646
MILGE	28003
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	12738
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NV
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	BINDING REPLACED RIGHT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	OK PASSENGER FRONT SEAT BELT WONT LATCH
AREA_CD	702
COUNTRY_CD	USA
SLS_DLR_CD	264137
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRI_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	187
VIN_CD	6LMELJ27R31
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	12/13/2000
WRTY_START_D	9/24/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	7073852
PH_NUM	5394000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	2
CLM_KEY	4900130
MILGE	8332
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10164
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	•
TECH_TXT1	REPLACE RT FT SEAT BELT
TECH_TXT2	
CUST_TXT	CUST STATES CK PASS FT SEAT BELT BUCKLE WOP
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	367023
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B4
VRT_CD	608
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	188
VIN_CD	5LMEU27R21
LBR_COST	
VEH_LINE_CD	T/B4
MET_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	8/28/2001
NAME	LONG-LEWIS FORD
DOC_NUM	24899101
PH_NUM	9893873
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	2/28/2002
TIS_WSD	7
CLM_KEY	7168133
MILGE	14718
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	BA
DLR_CD	225
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	0713,CK R R SEAT REPL SEAT BELT BUCKEL CC 42 INSIDE LATCH IS NOT STRONG ENOUGH.
TECH_TXT2	
CUST_TXT	S28 CUST STATES DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED AT TIMES, PARTS ORDERED AND HERE.
AREA_CD	205
COUNTRY_CD	USA
SLS_DLR_CD	328074
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	189
VIN_CD	5LMEU27R21L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/4/2001
WRTY_START_D	8/28/2001
NAME	GALPIN LINCOLN-MERCURY
DOC_NUM	3882811
PH_NUM	8828800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7891203
PART_NUM_CAU	CAA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	5
CLM_KEY	5234331
MILGE	8082
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	11820
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	. REPLACED DRIVERS SEAT BELT ASSEMBLY TO CORRECT CONCERN
TECH_TXT2	
CUST_TXT	CUST STS DRIVERS SEATBELT WONT LATCH
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	354301
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	190
VIN_CD	5LMEU27R21L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	9/1/2001
NAME	DON DAVIS LINCOLN-MERCURY INC
DOC_NUM	218824A
PH_NUM	2850101
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	78B1203
PART_NUM_CAU	GAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	9/15/2001
TIS_WSD	1
CLM_KEY	385350
MILGE	447
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	11484
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	447 SEAT BELT BUCKLE NOT LATCHING CORRECTLY.REMOVE SEAT REPLACE BUCKLE REINSTALL SEAT.DRIVERS. 42 70121
TECH_TXT2	
CUST_TXT	825 DRIVERS SEAT BELT WILL COME UNLATCHED
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	387018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	181
VIN_CD	5LMEU27R21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TNRB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/NC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/13/2001
WRTY_START_D	8/1/2001
NAME	MAGIC LINCOLN-MERCURY
DOC_NUM	4273262
PH_NUM	2557703
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	1
RPR_DT	2/28/2002
TIS_WSD	10
CLM_KEY	7149558
MILGE	18611
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10240
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	SEAT BELT LATCH BROKEN M TIME TO REPLACE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	CK PASS FRT SEAT BELT LATCH WONT STAY UP SOP IN
AREA_CD	651
COUNTRY_CD	USA
SLS_DLR_CD	354041
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	192
VIN_CD	6LMEU27R21L
LBR_COST	
VEH_LINE_CD	T7B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	8/4/2001
NAME	LYNNHAVEN LINCOLN-MERCURY
DOC_NUM	363548A
PH_NUM	3400600
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7961203
PART_NUM_CAU	CAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	5/24/2001
TIS_WSD	1
CLM_KEY	3504808
MILGE	783
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="12314"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="VA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Radings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="788 BELT WONT LATCH REPL DR8 SEAT BELT LATCH *28"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DRIVERS BELT WILL NOT CLOSE"/>
AREA_CD	<input type="text" value="787"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="328278"/>
TXN_CD	<input type="text" value="E93"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	193
VIN_CD	6LMEU27R21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	6/4/2001
NAME	LYNNHAVEN LINCOLN-MERCURY
DOC_NUM	350647B
PH_NUM	3400800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7B61208
PART_NUM_CAU	CAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	3302127
MILGE	58
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	12314
DLR_CD	12314
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	INSTALL 2 BUCKLE ASSYS
TECH_TXT2	
CUST_TXT	INSTALL TESTER FAILED INSTALLED 2 BUCKLE ASSYS
AREA_CD	757
COUNTRY_CD	USA
SLS_DLR_CD	328278
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	104
VIN_CD	SLMEJZ7R21
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	9/14/2001
NAME	HUB CITY FORD-MERCURY INC
DOC_NUM	GT3604A
PH_NUM	6822721
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/8/2001
TIS_WSD	0
CLM_KEY	5401161
MILGE	1186
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 279 of 1298

LBR_HRS	92
DLR_CD	4918
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	DIAG OPERATION OF LEFT FRONT SEAT BELT. NECESSARY TO REPLACE.
TECH_TXT2	
CUST_TXT	CHECK FOR LEFT FRONT SEATBELT INOP
AREA_CD	850
COUNTRY_CD	USA
SLS_DLR_CD	325131
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	195
VIN_CD	6LMEU27R21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	12/17/2001
NAME	VULCAN LINCOLN-MERCURY
DOC_NUM	7832201
PH_NUM	0785300
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	828
COND_CD	42
RPR_DT	1/16/2002
TIS_WSD	2
CLM_KEY	9554888
MILGE	2102
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10123
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	TECH VERIFIED COMPLIANT, REPLACED LEFT FRONT SEAT BELT BUCKLE, RETESTED, OK AT THIS TIME
TECH_TXT2	
CUST_TXT	LEFT FRONT DRIVER SEAT BELT INOP
AREA_CD	205
COUNTRY_CD	USA
SLS_DLR_CD	328075
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	198
VIN_CD	6LMEUJ7R21L
LRR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VRR_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/14/2000
WRTY_START_D	5/25/2001
NAME	PUGMIRE LINCOLN MERCURY AT TOW
DOC_NUM	117863A
PH_NUM	4270650
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7681202
PART_NUM_CAU	BAC
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	1/23/2002
TIS_WSD	0
CLM_KEY	8567024
MILGE	11114
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	07
DLR_CD	10854
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	11114 REPLACE BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PASSENGER FRONT SEAT BELT WILL NOT CLICK IN BUCKLE
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	328057
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S03
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	197
VIN_CD	5LMEU27R21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/23/2000
WRTY_START_D	01/3/2001
NAME	RANCHO FORD L-M
DOC_NUM	28775101
PH_NUM	8881302
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	828
COND_CD	42
RPR_DT	1/5/2002
TIS_WSD	7
CLM_KEY	8578707
MILGE	11705
MTRL_COST	
TOT_COST_GROS	

LAR_HRS	97
DLR_CD	5432
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACE LEFT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE
AREA_CD	909
COUNTRY_CD	USA
SLS_DLR_CD	364283
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B4
VRT_CD	800
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	199
VIN_CD	5LMEU27R11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/12/2001
WRTY_START_D	8/30/2001
NAME	FT LAUDERDALE L-M INC
DOC_NUM	ZZ7739C
PH_NUM	7782000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801202
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RFR_DT	7/17/2001
TIS_WSD	0
CLM_KEY	4837385
MILGE	4
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	11627
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	325036
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	808
TTS_FLAG	

MDL_YR	2001
SORT_INDEX	200
VIN_CD	6LMEL27R11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	8/14/2001
NAME	LONGWOOD LINCOLN-MERCURY INC
DOC_NUM	2018880
PH_NUM	5318090
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	3S
RPR_DT	7/8/2001
TIS_WSD	1
CLM_KEY	2308583
MILGE	653
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	11809
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	653 01 WPB40 REPLACE SEAT BELT END
TECH_TXT2	
CUST_TXT	WPG40.840.CUSTOMER SAYS DRIVERS SEAT BELT BUCKLE DOES NOT LOCK.
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	325143
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	202
VIN_CD	6LNEL27R11U
LBR_COST	2197
VEH_LINE_CD	T84
MKT_DERIVED	*
BOD_CAR_STL	TWB
VER_SERIES_CD	T1EL
DRIVE_CD	T7B
ENG_CD	T7WC
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	410/2001
WRTY_START_D	7/20/2001
NAME	JOHNSON-SEWELL FORD LINCOLN ME
DOC_NUM	442437A
PH_NUM	7508286
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	12/7/2001
TIS_WSD	5
CLM_KEY	0578244
MILGE	12001
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	4540
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPLACED FRONT BELT ASY
TECH_TXT2	
CUST_TXT	
AREA_CD	512
COUNTRY_CD	USA
SLS_DLR_CD	387038
TXN_CD	E34
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	203
VIN_CD	5LMEU27R11
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/8/2001
NAME	PREMIER FORD L-M INC
DOC_NUM	11572001
PH_NUM	3273873
WCC_CD	BF02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	GAB
CUST_CONC_CD	840
COND_CD	1
RPR_DT	10/5/2001
TIS_WSD	6
CLM_KEY	4489008
MILGE	10024
MTRL_COST	
TOT_COST_GROS	

LBR_HBS	
DLR_CD	5928
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MS
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	BROKEN NECESSARY TO REPLACE BROKEN SEAT BELT AND BUCKLE
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIMES
AREA_CD	682
COUNTRY_CD	USA
SLS_DLR_CD	322428
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	204
VIN_CD	5LMEU27R11L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/13/2001
WRTY_START_D	5/7/2001
NAME	CLINTON HERRING LINC-MERC
DOC_NUM	46889202
PH_NUM	3663883
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	3/27/2002
TIS_WSD	11
CLM_KEY	7847851
MILGE	16225
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	0:00:00
DLR_CD	10870
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
CPSC_CD_6	11001
Ratings	
TECH_TXT1	R/R SEAT AND REPLACE LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	LEFT SEAT BLET NOT LATCHING AT TIMES
AREA_CD	406
COUNTRY_CD	USA
SLS_DLR_CD	387235
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	205
VIN_CD	5LMEU27R11LJ
LBR_COST	3248
VEH_LINE_CD	T/B4
MKT_DERIVED	.
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	5/22/2001
NAME	FREEDOM LINCOLN MERCURY
DOC_NUM	160423A
PH_NUM	4241100
WCC_CD	6R02
PART_NUM_CAU	1172
PART_NUM_CAU	7801203
PART_NUM_CAU	CAA
COST_CONC_CD	925
COND_CD	42
RPR_DT	11/9/2001
TIS_WSD	6
CLM_KEY	4808064
MILGE	3067
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	6.5
DLR_CD	12390
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	6
TECH_TXT1	3967 COMPLETED RECALL 01B21 INSPECTED BOTH FRONT SEAT BELT BUCKLES FOUND DRIVERS BUCKLE FAULTY REPLACED DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CERTAIN 2001 GRAND MARQUIS, NAVIGATOR, AND TOWNCAR VEHICLES SEAT BELT BUCKLE RETENTION SEE RECALL FOR LABOR OPS AND TIMES
AREA_CD	757
COUNTRY_CD	USA
SLS_DLR_CD	328837
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	207
VIN_CD	5LMEJ27R11L
LRR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	
BOD_CAB_STL	TWB
VER_SERIES_CD	T/E1
DRIVE_CD	TB
ENG_CD	TWC
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	12/18/2000
WRTY_START_D	2/7/2001
NAME	BUDDY JONES FORD LINCOLN MERCU
DOC_NUM	6722351
PH_NUM	4538131
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7581203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	7/6/2001
TIS_WSD	5
CLM_KEY	2478051
MILGE	14866
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	62
DLR_CD	5813
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MS
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	NOT OPERATING PROPERLY REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CK. DRIVERS SEAT BELT FEMALE END WONT LATCH
AREA_CD	662
COUNTRY_CD	USA
SLS_DLR_CD	322584
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	800
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	208
VIN_CD	5LMEU27R11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/25/2000
WBTY_START_D	1/22/2001
NAME	NORTH FLORIDA LINCOLN-MERCURY
DOC_NUM	3724958
PH_NUM	8424100
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	CAB
CUST_CONC_CD	S40
COND_CD	42
RFR_DT	7/8/2001
TIS_WSD	8
CLM_KEY	2878174
MILGE	8871
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	94
DLR_CD	11030
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	2
TECH_TXT1	DOES NOT WORK PROP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE DRIVERSEAT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES NOT STAY LATCHED REPLACE BUCKLE PART HERE SEE KEY
AREA_CD	B04
COUNTRY_CD	USA
SLS_DLR_CD	354283
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	209
VIN_CD	5LMEU27R11L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/22/2000
WRTY_START_D	5/30/2001
NAME	PUENTE HILLS FORD
DOC_NUM	2406002
PH_NUM	9843873
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881289
PART_NUM_CAU	CAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	7/3/2001
TYS_WSD	2
CLM_KEY	2325287
MILGE	1873
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="5550"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="d"/>
TECH_TXT1	<input type="text" value="SEAT BELT FAILURE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="LEFT FRONT SEAT BELT COMES UNDONE WHEN BRAKING"/>
AREA_CD	<input type="text" value="528"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="354283"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="306"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	210
VIN_CD	6LMEU27R01
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/4/2001
WRTY_START_D	6/23/2001
NAME	GERMAIN LINC-MERG OF NAPLES
DOC_NUM	1607051
PH_NUM	5570011
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	GAA
CUST_CONC_CD	853
COND_CD	41
RPR_DT	12/11/2001
TIS_WSD	4
CLM_KEY	5763828
MILGE	3885
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<u>11624</u>
DLR_CD	<u>11624</u>
DLR_SUB_CD	<u> </u>
REGION_CD	<u>NA</u>
ST_PROV_CD	<u>FL</u>
CPSC_CD_6	<u>11001</u>
Ratings	<u>C</u>
TECH_TXT1	<u>BINDING TRACK ASSEMBLY FRONT SEAT REPLACE</u>
TECH_TXT2	<u> </u>
CUST_TXT	<u>DRIVERS SEATBELT BUCKLE COMES UNDONE PART IN STOCK SEE TED PASS. FRONT IS FALLING ALSO</u>
AREA_CD	<u>041</u>
COUNTRY_CD	<u>USA</u>
SLS_DLR_CD	<u>325044</u>
TXN_CD	<u>2</u>
CNTRY_SOLD	<u>USA</u>
QRT_CD	<u>Q21</u>
VFG_CD	<u>V08</u>
AWS_VL_CD	<u>B4</u>
VRT_CD	<u>S08</u>
TIS_FLAG	<u> </u>

MDL_YR	2001
SORT_INDEX	211
VIN_CD	5LMELJ27R011
LBR_COST	2202
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	5/25/2001
NAME	WADE LINCOLN MERCURY
DOC_NUM	021351B
PH_NUM	6024200
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	9/10/2001
TIS_WSD	4
CLM_KEY	3593782
MILGE	5237
MTRL_COST	2000
TOT_COST_GROS	2000

LBR_HRS	04
DLR_CD	10099
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	5237 REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT HERE FOR VEHICLE SEE RECALL
AREA_CD	878
COUNTRY_CD	USA
SLS_DLR_CD	328233
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	212
VIN_CD	6LMEU27R01L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRKY_START_D	7/30/2001
NAME	STAR LINCOLN-MERCURY SALES, IN
DOC_NUM	60527402
PH_NUM	2471903
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	528
COND_CD	42
RPR_DT	2/11/2002
TIS_WSD	7
CLM_KEY	6670654
MILGE	0458
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	11822
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	1 REPLACE LEFT FRONT SEATBELT LATCH.
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT COMES UNBUCKLED BY ITSELF AT TIMES
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	864301
TKN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	213
VIN_CD	5LMEU27R01L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/E1
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/17/2001
WRTY_START_D	5/30/2001
NAME	FAIRWAY LINCOLN-MERCURY INC
DOC_NUM	945452
PH_NUM	9271000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	928
COND_CD	42
RPR_DT	6/8/2002
TIS_WSD	13
CLM_KEY	9178588
MILGE	12234
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 311 of 1298

RQ04-011 E 2336

LBR_HRS	05
DLR_CD	11633
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Rating	C
TECH_TXT1	L F SEAT BELT COMES UNBUCKLED REPLACED
TECH_TXT2	
CUST_TXT	CUST STATES L F SEAT BELT KEEPS COMING UNBUCKLED
AREA_CD	012
COUNTRY_CD	USA
SLS_DLR_CD	328218
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B4
VRT_CD	608
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	214
VIN_CD	6LMEU27R01L
LBR_COST	8278
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DI
PLANT_CD	AP
PRODN_DT	4/6/2001
WRTY_START_D	6/2/2001
NAME	LAMARQUE LINCOLN-MERCURY INC
DOC_NUM	071788A
PH_NUM	3404500
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	5/15/2002
TIS_WSD	12
CLM_KEY	8029700
MILGE	16680
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	12038
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	16590 BHRS. LABOR TIME REPLACED LEFT SEAT BUCKLE AS PER LABOR OPERATI ON 01S21D.
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELT FOR RECALL 01S21
AREA_CD	604
CDOUNTRY_CD	USA
SLS_DLR_CD	322600
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	215
VIN_CD	9LMEU27R01L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/3/2001
WRTY_START_D	7/3/2001
NAME	RANCHO FORD L-M
DOC_NUM	28758701
PH_NUM	6891302
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	9/17/2001
TIS_WSD	2
CLM_KEY	4000622
MILGE	283B
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	1
DLR_CD	5432
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACE LEFT AND RIGHT SEAT BELT BUCKLES.
TECH_TXT2	
CUST_TXT	SEAT BELT INOP
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	354015
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	210
VIN_CD	5LMEU27R01
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	TAWB
VBR_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	TAWC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/18/2001
WRTY_START_D	6/8/2001
NAME	GABLES LINCOLN-MERCURY INC
DOC_NUM	806793A
PH_NUM	4457711
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	340
COND_CD	42
RPR_DT	8/20/2001
TIS_WSD	3
CLM_KEY	3067814
MILGE	3813
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 317 of 1298

LBR_HRS	93
DLR_CD	11655
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	3813 09 ERRATIC TEST AND REPLACE DRIVERS SEAT BELT BUCKLE SOMETIMES WONT LOCK
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEATBELT LOCKS,SOP HERE
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	325201
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	BA
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	217
VIN_CD	6LMELJ27R01
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/4/2001
WRTY_START_D	3/18/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	8884451
PH_NUM	5394800
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	340
COND_CD	42
RPR_DT	10/1/2001
TIS_WSD	7
CLM_KEY	4268154
MILGE	8620
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	94
DLR_CD	10164
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	VERIFIED CONCERN, DRIVERS SEAT BELT BUCKLE INOP, REPLACED SEAT BELT BUCKLE ASSY, TESTED, FIXED VEHICLE CC 42
TECH_TXT2	
CUST_TXT	CUST STATES DR SIDE SEAT BELT WONT BUCKLE
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	367023
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	218
VIN_CD	5LMEU27R01L
LBR_COST	
VRH_LINK_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/E
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/4/2001
WRIT_START_D	3/21/2001
NAME	LADIN LINCOLN-MERCURY
DOC_NUM	4803101
PH_NUM	4952193
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	6/28/2001
TIS_WSD	6
CLM_KEY	3441279
MILGE	5249
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	92
DLR_CD	11803
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	BUCKLE REPLACED PASS SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	354290
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S00
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	219
VIN_CD	5LNEL27R01
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	TB
ENG_CD	T/WG
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/26/2000
WRTY_START_D	11/21/2000
NAME	HOLLYWOOD LINCOLN-MERCURY INC
DOC_NUM	192771D
PH_NUM	9208010
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	1/22/2002
TIS_WSD	15
CLM_KEY	648851
MILGE	15140
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	8.4
DLR_CD	11838
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	18140 42 (NOF INTALL SOP LF SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SOP SEAT BELT IN
AREA_CD	305
COUNTRY_CD	USA
SLS_DLR_CD	325044
TXN_CD	ESA
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	220
VIN_CD	9LMEU27AX1L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAR_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/27/2000
WRTY_START_D	1/27/2001
NAME	WEST POINT LINCOLN-MERCURY
DOC_NUM	34217801
PH_NUM	5292811
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881232
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	9/17/2001
TIS_WSD	6
CLM_KEY	3883370
MILGE	13152
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	11408
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	RIGHT FRONT SEAT BELT WONT BUCKLE REPLACE RIGHT FRONT SEAT BELT BUCKLE END INOPERATIVE NO LABOR OPERATION IN SLTSM
TECH_TXT2	
CUST_TXT	RF SEAT BELT WONT BUCKLE
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	887023
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	221
VIN_CD	5LMEL27A91L
LBR_COST	
VEH_LINE_CD	TB4
MKT_DERIVED	*
BOD_CAB_STL	TWB
VER_SERIES_CD	TREL
DRIVE_CD	TB
ENG_CD	TWC
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	8/11/2000
WRTY_START_D	6/30/2001
NAME	BAYWAY LINCOLN MERCURY, INC.
DOC_NUM	5967251
PH_NUM	9289500
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	525
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	5
CLM_KEY	4980450
MILGE	4681
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	<input type="text" value="0"/>
DLR_CD	<input type="text" value="10003"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="TX"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="b"/>
TECH_TXT1	<input type="text" value="REPLACE DRIVERS SEAT BELT BUCKLE WEAK"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="SEAT BELT BUCKLES WILL NOT STAY LATCHED USE SPO 01278014"/>
AREA_CD	<input type="text" value="281"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="387132"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	222
VIN_CD	5LMEU27A511
LBR_COST	
VEH_LINE_CD	T784
MKT_DERIVED	*
BOD_CAB_STL	T785
VER_SERIES_CD	T7EL
DRIVE_CD	T7B
ENG_CD	T7WC
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	8/14/2000
WRTY_START_D	10/4/2000
NAME	SANTA MONICA LINCOLN-MERCURY
DOC_NUM	21908502
PH_NUM	3090881
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	CAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	4/4/2002
TIS_WSD	19
CLM_KEY	7878401
MILGE	1477
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04:23:57.000000
DLR_CD	11843
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	g
TECH_TXT1	REPLACED LEFT FRT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	864100
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	223
VIN_CD	5LMEU27A811
LBR_COST	
VEH_LINE_CD	TBA
MKT_DERIVED	*
BOD_CAR_STL	TWB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/MC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	9/29/2000
WRTY_START_D	4/2/2001
NAME	VALDOSTA LINCOLN MERCURY
DOC_NUM	031857A
PH_NUM	2427930
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	B40
COND_CD	B9
RPR_DT	11/30/2001
TIS_WSD	9
CLM_KEY	544415
MILGE	17402
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	11685
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	CHECKED LEFT FRONT SEAT BELT FOUND BUCKLE NOT WORKING PROPERLY REMOVED AND REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CHECK SEAT BELT P O
AREA_CD	912
COUNTRY_CD	USA
SLS_DLR_CD	325182
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	224
VIN_CD	5LMEU27A61
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/7/2000
WRTY_START_D	2/16/2001
NAME	CHAPMAN LINCOLN MERCURY
DOC_NUM	2797188
PH_NUM	2841851
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	CAA
CUST_CONG_CD	825
COND_CD	41
RPR_DT	11/17/2001
TIS_WSD	10
CLM_KEY	5262347
MILGE	8795
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 333 of 1198

RQ04-011 E 2358

LBR_HRS	92
DLR_CD	10836
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AZ
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPL LEFT FRT SEAT BELT BUCKLE WONT RELEASE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL NOT UNBUCKLE, SOMETIMES
AREA_CD	888
COUNTRY_CD	USA
SLS_DLR_CD	354588
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	225
VIN_CD	6LMEU27A51
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
ROD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/20/2000
WRTY_START_D	1/13/2001
NAME	DOWNEY LINCOLN MERCURY
DOC_NUM	070108A
PH_NUM	8810721
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	41
RPR_DT	12/26/2001
TIS_WSD	12
CLM_KEY	6028887
MILGE	14144
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	5.9
DLR_CD	10348
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	VERIFY CONCERN FOUND DEFECTED SEAT BELT BUCKLE REMOVE SEAT AND REPLACE BUCKLE AND RETEST SYS O K AT THIS TIME.
TECH_TXT2	
CUST_TXT	CHECK AND ADVISE CUST STATES DRIVER SIDE SEAT BELT DOES NOT LOCK IN TO BUCKLE. S40
AREA_CD	682
COUNTRY_CD	USA
SLS_DLR_CD	354051
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B4
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	228
VIN_CD	6LME127A41
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	9/14/2000
WRTY_START_D	9/29/2000
NAME	BILTON LINCOLN-MERCURY INC
DOC_NUM	78371
PH_NUM	7757358
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	928
COND_CD	49
RPR_DT	5/21/2002
TIS_WSD	20
CLM_KEY	9027640
MILGE	18887
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="10380"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="SC"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="INSTALLED SEAT BELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="LEFT FRONT SEAT BELT WONT BUCKLE"/>
AREA_CD	<input type="text" value="803"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="328219"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="C21"/>
VFG_CD	<input type="text" value="V08"/>
AWS_VL_CD	<input type="text" value="84"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value="0"/>

MDL_YR	2001
SORT_INDEX	227
VIN_CD	5LMEL27A21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	10/6/2000
WRTY_START_D	4/23/2001
NAME	SOUTHERN LINCOLN-MERCURY INC
DOC_NUM	116128D
PH_NUM	8331500
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7561202
PART_NUM_CAU	8A8
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	5/6/2002
TIS_WSD	13
CLM_KEY	8727782
MILGE	24591
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 339 of 1288

RQ04-011 E 2384

LBR_HRS	04
DLR_CD	10111
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	REPLACED SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	THE RIGHT FRONT SEAT BELT BUCKLE IS INOPERATIVE.
AREA_CD	404
COUNTRY_CD	USA
SLS_DLR_CD	328135
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B4
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	228
VIN_CD	5LMEU27A21L
LBR_COST	
VEH_LINE_CD	T/B4
MKT_DERIVED	*
HOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/MC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/22/2000
WRTY_START_D	2/26/2001
NAME	NORTHWOOD LINCOLN-MERCURY
DOC_NUM	7349752
PH_NUM	5394800
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	T90
COND_CD	42
RPR_DT	12/31/2001
TIS_WSD	11
CLM_KEY	8074790
MILGE	28237
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	10184
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE ASSY.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SIDE FRONT SEAT BELT POPS OUT OF LOCK
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	357023
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B4
VRT_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	229
VIN_CD	5LMEJZ7A11L
LBR_COST	
VEH_LINE_CD	T/B4
MKY_DERIVED	*
BOD_CAB_STL	T/WB
VER_SERIES_CD	T/EL
DRIVE_CD	T/B
ENG_CD	T/WC
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/22/2000
WRTY_START_D	2/28/2001
NAME	CERRITOS LINCOLN-MERCURY
DOC_NUM	8982401
PH_NUM	8856026
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	3/20/2002
TIS_WSD	19
CLM_KEY	7534530
MILGE	27120
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 343 of 1298

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="11907"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="61202.CC42 REPLACE R F SEATBELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP."/>
AREA_CD	<input type="text" value="714"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="364016"/>
TXN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B4"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	230
VIN_CD	1FMRU17WX1L
LBR_COST	
VEH_LINE_CD	T/ES
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	8/1/2001
WRTY_START_D	10/8/2001
NAME	CERRITOS FORD
DOC_NUM	25478901
PH_NUM	8652554
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	7/28/2001
TES_WSD	0
CLM_KEY	3524217
MILGE	7
MTRL_COST	
TOT_COST_GROS	

Thursday, December 14, 2001

Page 345 of 1298

RQ04-011 E 2370

LRR_HRS	01/15/2004
DLR_CD	5401
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	01S21 E BOTH BELT BUCKLES FAILED RPL BOTH BELT BUCKLES
TECH_TXT2	
CUST_TXT	PERFORM RECALL #01S21
AREA_CD	562
COUNTRY_CD	USA
SLS_DLR_CD	171065
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRI_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	231
VIN_CD	1FMRU17WX1
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	.
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/30/2001
WRTY_START_D	7/30/2001
NAME	NICHOLS FORD
DOC_NUM	20348401
PH_NUM	5353073
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	75B1202
PART_NUM_CAU	AAA
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	7/20/2001
TIS_WSD	0
CLM_KEY	3305282
MILGE	9
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.45
DLR_CD	2511
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	8
TECH_TXT1	1 REPLACE RIGHT HAND SEAT BELT.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	152526
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
FIS_FLAG	

MDL_YR	2001
SORT_INDEX	232
VIN_CD	1FMRU17WX1L
LBR_COST	
VEH_LINE_CD	T88
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T8
ENG_CD	TVN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	6/4/2001
WRTY_START_D	8/31/2001
NAME	CERRITOS FORD
DOC_NUM	25477201
PH_NUM	6055554
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	7/28/2001
TIS_WSD	0
CLM_KEY	3324275
MILGE	4
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	9.5
DLR_CD	5401
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	01S21 D DRIVER SIDE FAILED RPL DRIVER SIDE BUCKLE
TECH_TXT2	
CUST_TXT	PERFORM RECALL #01S21
AREA_CD	582
COUNTRY_CD	USA
SLS_DLR_CD	171007
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	233
VIN_CD	1FMRU17WX1L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TAWD
VER_SERIES_CD	T8F
DRIVE_CD	T/B
ENG_CD	T/MN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	8/4/2001
WPTY_START_D	8/4/2001
NAME	CERRITOS FORD
DOC_NUM	26987402
PH_NUM	0055564
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	10/8/2001
TIS_WSD	3
CLM_KEY	4000006
MILGE	3618
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	5401
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	*
TECH_TXT1	WF 0821D PERFORMED SEAT BELT RECALL RIGHT FRONT SEAT.
TECH_TXT2	
CUST_TXT	INSTALL SPECIAL ORDERED PART,RIGHT FRONT SEAT BELT BUCKLE PART WAS SPECIAL, ORDERED,NOT LATCHING
AREA_CD	662
COUNTRY_CD	USA
SLS_DLR_CD	171055
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	88
VRT_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	234
VIN_CD	1FMRU17WX1L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/8
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	8/1/2001
WRTY_START_D	8/27/2001
NAME	GERRITOS FORD
DOC_NUM	25481201
PH_NUM	865554
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/30/2001
TIS_WSD	0
CLM_KEY	2490988
MILGE	8
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 353 of 1298

RQ04-011 E 2378

LBR_HRS	0.0
DLR_CD	5401
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	01921 D DRIVER SIDE FAILED RPL DRIVER SIDE BELT BUCKLE
TECH_TXT2	
CUST_TXT	PERFORM RECALL #01921
AREA_CD	682
COUNTRY_CD	USA
SLS_DLR_CD	171055
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	905
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	235
VIN_CD	1FMRU17WX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	5/28/2001
NAME	HOFFMAN FORD, INC.
DOC_NUM	778532A
PH_NUM	3284811
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801208
PART_NUM_CAU	CAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	5/7/2002
TIS_WSD	12
CLM_KEY	8571444
MILGE	8086
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	8185
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GT
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	DRIVER SEAT BELT DOESNT BUCKLE BROKEN REPLACED BUCKLE AND RETESTED OK
TECH_TXT2	
CUST_TXT	CS DRIVER SIDE SEAT BELT BUCKLE KEEPS UNBUCKLING
AREA_CD	203
COUNTRY_CD	USA
SLS_DLR_CD	124009
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	Q

MDL_YR	2001
SORT_INDEX	236
VIN_CD	1FMRU17WXL
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/30/2001
WRTY_START_D	6/28/2001
NAME	MAC HAK FORO
DOC_NUM	154827A
PH_NUM	9325000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7651203
PART_NUM_CAU	BAA
CUST_CONC_CD	625
COND_CD	1
RPR_DT	10/24/2001
TIS_WSD	4
CLM_KEY	4852618
MILGE	5326
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	9A
DLR_CD	4511
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	6326 01 61203 R R DRIVER SEAT ACCESS REPLACED DRIVER SEAT BELT BUCKLE BINDING
TECH_TXT2	
CUST_TXT	825 LT FT SEAT BELT WONT STAY LATCHED
AREA_CD	713
COUNTRY_CD	USA
SLS_DLR_CD	152031
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	88
VRT_CD	506
TIS_FLAG	