

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 6 OF 6

BOOK 4 OF 43

MDL_YR	2001
SORT_INDEX	400
VIN_CD	1FMRU17L21LB07127
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	6/21/2001
NAME	DON DAVIS FORD, INC.
DOC_NUM	422378B
PH_NUM	2814281
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	Z8
RPR_DT	3/28/2002
TIS_WSD	10
CLM_KEY	7852497
MILGE	21000
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 671 of 1298

LBR_HRS	04
DLR_CD	2417
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	21000 OPEN ELECTRICAL DIAG ,FOUND DRIVERS SEAT BELT BUCKLE TO HAHE AN OPEN REPLACED AND TESTED OK ***QUALITY CONTROL BY TIM HUDSON***
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT BUCKLE INOP INTERIOR CODE IH
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	401
VIN_CD	1FMRU17L21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/RVD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	10/25/2000
WRTY_START_D	10/31/2000
NAME	THOMASVILLE SALES COMPANY
DOC_NUM	0401051
PH_NUM	2286133
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	GAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	12/3/2001
TIS_WSD	14
CLM_KEY	8524080
MILGE	12504
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 673 of 1238

LBR_HRS	53
DLR_CD	4831
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	SEAT BLET HARD TO UN SNAP REPLACE BOTH SEAT BLET BUCKLES
TECH_TXT2	
CUST_TXT	CK BOTH DRIVER AND PASSANGER SEAT BELT HARD TO UNSNAP
AREA_CD	228
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	402
VIN_CD	1FMEUJ17L21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T8
ENG_CD	TNZ
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	10/2000
WRTY_START_D	2/10/2001
NAME	JOE MACPHERSON FORD
DOC_NUM	3487801
PH_NUM	8323300
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S2B
COND_CD	41
RPR_DT	1/8/2002
TIS_WSD	12
CLM_KEY	6290817
MILGE	13119
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	E414
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	8
TECH_TXT1	FAILED BUCKLE REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES PASS FRT BELT WONT LATCH CHECK AND ADVISE
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	171057
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRY_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	409
VIN_CD	1FMRU17L11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/14/2001
WRTY_START_D	8/15/2001
NAME	GALPIN FORD
DOC_NUM	5840271
PH_NUM	7573800
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7681203
PART_NUM_CAU	BAA
CUST_CONC_CD	B40
COND_CD	33
RPR_DT	7/31/2001
TIS_WSD	0
CLM_KEY	3257235
MILGE	41
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	14
DLR_CD	6536
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	CGF12 REPLACE SEATBELT BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELTS WILL NOT LATCH PROPERLY
AREA_CD	B18
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	404
VIN_CD	1FMRU17L11U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
MOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/15/2001
WRTY_START_D	7/28/2001
NAME	O. G. WELCH FORD LINCOLN-MERCU
DOC_NUM	7350053
PH_NUM	5243171
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	8/21/2001
TIS_WSD	1
CLM_KEY	4101871
MILGE	1940
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	82
DLR_CD	1018
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED LEFT AND RIGHT SEATBELTS.
TECH_TXT2	
CUST_TXT	CHECK SEATBELTS INOP
AREA_CD	843
COUNTRY_CD	USA
SLS_DLR_CD	121248
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TES_FLAG	

MDL_YR	2001
SORT_INDEX	405
VIN_CD	1FMRU17L11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/4/2001
WRTY_START_D	7/24/2001
NAME	WESTWAY FORD
DOC_NUM	84675001
PH_NUM	6690333
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7561202
PART_NUM_CAU	AAA
CUST_CONC_CD	S25
COND_CD	41
RPR_DT	1/24/2002
TIS_WSD	7
CLM_KEY	6478927
MILGE	10734
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	2508
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	c
TECH_TXT1	R&R RT FRONT SEAT. REPLACED SEAT BELT BUCKLE ASSY....
TECH_TXT2	
CUST_TXT	CUST SAYS RIGHT FRONT SEAT BELT DOES NOT HOLD AND COMES UNLATCHED
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	182013
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	406
VIN_CD	1FMRU17L11
LBR_COST	
VEH_LINK_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	T/B
ENG_CD	TVZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	6/21/2001
NAME	OKC AUTO COLLECTION
DOC_NUM	387798A
PH_NUM	2327171
WCC_CD	6R02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/10/2001
TIS_WSD	4
CLM_KEY	4817900
MILGE	6934
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	05
DLR_CD	3856
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	5034 REPLACE FRT BUCKELS AS PER RECALL
TECH_TXT2	
CUST_TXT	REPAIR RIGHT AND LEFT FRT SEAT BELT BUCKLES DO NOT CATCH AT TIMES. ** PARTS ORDERED & HERE ** TECH# 6370 **
AREA_CD	405
COUNTRY_CD	USA
SLS_DLR_CD	152684
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	408
VIN_CD	1FWRU17L11U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
RNG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/15/2001
WRTY_START_D	3/17/2001
NAME	MIKE SHAD FORD AT THE AVENUES
DOC_NUM	3822451
PH_NUM	2823325
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7981203
PART_NUM_CAU	BAA
CUST_CONC_CD	T/0
COND_CD	42
RPR_DT	10/30/2001
TIS_WSD	8
CLM_KEY	5401482
MILGE	6040
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	4882
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	01S21 SPECIAL PART ORDERED
TECH_TXT2	
CUST_TXT	RECALL 01S21 SEAR BELT BUCKLE
AREA_CD	804
COUNTRY_CD	USA
SLS_DLR_CD	124223
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	410
VIN_CD	1FMRJ17L11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/11/2001
WRTY_START_D	5/4/2001
NAME	GLS MACHADO FORD, INC.
DOC_NUM	237786A
PH_NUM	8223211
WCC_CD	BRD2
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	CAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	1/10/2002
TYS_WSD	B
CLM_KEY	6175838
MILGE	6208
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4831"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="FL"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="d"/>
TECH_TXT1	<input type="text" value="6206 INOP 81208 42 WARRI REPLACE LEFT SEAT
BBELT BUCKLE 81202A"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUST STATES LEFT SEAT BELT GET LOOSE WHEN
DRIVING"/>
AREA_CD	<input type="text" value="305"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124007"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	412
VIN_CD	1FMRU17L11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	12/18/2000
WRTY_START_D	1/21/2001
NAME	GALPIN FORD
DOC_NUM	6103821
PH_NUM	7873800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	525
COND_CD	42
RPR_DT	10/27/2001
TIS_WSD	10
CLM_KEY	4888630
MILGE	9821
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	<input type="text" value="0"/>
DLR_CD	<input type="text" value="5538"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="CC107 REPLACED RIGHT FRONT SEAT BELT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="INSTALL SPECIAL ORDERED PART. SPOT ID 133827 BEAT BELTS"/>
AREA_CD	<input type="text" value="518"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171040"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="908"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	413
VIN_CD	1FMRU17L11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	TVZ
TRANS_CD	T/D E
PLANT_CD	AP
PRODN_DT	9/29/2000
WRTY_START_D	5/4/2001
NAME	TEXAN FORD
DOC_NUM	22145202
PH_NUM	4873573
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	340
COND_CD	1
RPR_DT	5/8/2002
TIS_WSD	13
CLM_KEY	8566801
MILGE	12700
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	62
DLR_CD	2488
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	BINDING (41) HAD TO ACCESS REAR MIDDLE SEAT & REPLACE CENTER SEATBELT BUCKLE, TK0882
TECH_TXT2	
CUST_TXT	CUST STATES MIDDLE SEAT CENTER SEAT BELT WONT LATCH
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152018
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	03
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	415
VIN_CD	1FMRU17L015
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/28/2001
WRTY_START_D	8/28/2001
NAME	GALPIN FORD
DOC_NUM	5908121
PH_NUM	7873800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S40
COND_CD	33
RPR_DT	8/14/2001
TIS_WSD	0
CLM_KEY	4148848
MILGE	10
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	DA
DLR_CD	5536
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	SEAT BELTS WONT LATCH REPLACE BUCKLES
TECH_TXT2	
CUST_TXT	SEAT BELTS WILL NOT LATCH PROPERLY
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TTS_FLAG	

MDL_YR	2001
SORT_INDEX	418
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/14/2001
WRTY_START_D	9/22/2001
NAME	GALPIN FORD
DOC_NUM	58673851
PH_NUM	7873800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861208
PART_NUM_CAU	BAA
CUST_CONC_CD	340
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	0
CLM_KEY	3525117
MILGE	5
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	05
DLR_CD	5636
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	REPLACE SEATBELTS WILL NOT LATCH
TECH_TXT2	
CUST_TXT	
AREA_CD	816
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	417
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/13/2001
WRTY_START_D	6/20/2001
NAME	MIDDLEKAUFF FORD, INC.
DOC_NUM	58822C
PH_NUM	683600
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	4/1/2002
TIS_WSD	8
CLM_KEY	7783400
MILGE	6887
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 697 of 1298

RQD4-011 E 2722

LRR_HRS	836
DLR_CD	2478
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TRCH_TXT1	6997 SEAT BELT LATCH INOP 61172A.4 REPLACED SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	S40 SEATBELT CUST STATES THE DRIVERS SEATBELT WILL NOT HOLD LATCH
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	418
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TW0
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TN2
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/1/2001
WRTY_START_D	8/29/2001
NAME	ALEXIBON FORD
DOC_NUM	188852A
PH_NUM	2938900
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	7/23/2001
TIS_WSD	0
CLM_KEY	8434403
MILGE	14
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0:0
DLR_CD	6521
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
CPSC_CD_6	12001
Ratings	6
TECH_TXT1	14 INSPECTED SEAT BELTS,FALTY PREFORMED RECALL,REPLACED SEAT BELT
TECH_TXT2	
CUST_TXT	INSPECT PER 01821 RECALL INSTRUCTIONS
AREA_CD	ZZ5
COUNTRY_CD	USA
SLS_DLR_CD	129208
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	419
VIN_CD	1FMRU17L01
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	TB
ENG_CD	TVZ
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	6/29/2001
WRTY_START_D	8/12/2001
NAME	BEACH FORD, INC.
DOC_NUM	14345101
PH_NUM	8263868
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	8/1/2002
TIS_WSD	12
CLM_KEY	8012106
MILGE	18498
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	59
DLR_CD	871
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	12007
Ratings	8
TECH_TXT1	REPACE BELTS
TECH_TXT2	
CUST_TXT	
AREA_CD	M3
COUNTRY_CD	USA
SLS_DLR_CD	124010
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRI_CD	S08
TIS_FLAG	Q

MDL_YR	2001
SORT_INDEX	421
VIN_CD	1FMRU17L01
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	TB
ENG_CD	TVZ
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	5/21/2001
WRTY_START_D	8/31/2001
NAME	GALPIN FORD
DOC_NUM	58874151
PH_NUM	7873800
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/14/2001
TIS_WSD	0
CLM_KEY	3625118
MILGE	82
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	0.00000000
DLR_CD	5836
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACE SEATBELT WILL NOT LATCH PROPERLY
TECH_TXT2	
CUST_TXT	
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	424
VIN_CD	1FMRJ17L01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	8/27/2001
NAME	BAY CITY AUTO & SALES CO.
DOC_NUM	7846061
PH_NUM	2451771
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	1/14/2002
TIS_WSD	7
CLM_KEY	8988439
MILGE	12500
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	4411
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	SEAT BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEAT BELT CHIMES,SEAT BELT DOESNT CLICK IN ALL THE WAY
AREA_CD	B79
COUNTRY_CD	USA
SLS_DLR_CD	152134
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	425
VIN_CD	1FMRU17L010
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SRRIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/6/2001
WRTY_START_D	6/27/2001
NAME	BAY CITY AUTO & SALES CO.
DOC_NUM	7228261
PH_NUM	2451771
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	6/6/2001
TIS_WSD	2
CLM_KEY	2901035
MILGE	1818
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	18
DLR_CD	4411
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	INOP,WOULD NOT LOCK IN PLACE REPLACED SEATBELT BUCKLE.
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE INOP. SERVICE INSTALL PART
AREA_CD	979
COUNTRY_CD	USA
SLS_DLR_CD	182134
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	420
VIN_CD	1FMRU17L01U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/16/2001
WRTY_START_D	3/31/2001
NAME	VILLA FORD
DOC_NUM	78930151
PH_NUM	6378222
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	GAA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	8/17/2001
TIS_WSD	5
CLM_KEY	3058868
MILGE	3559
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.5
DLR_CD	555B
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	SCP M TIME TO REPLACE LEFT BUCKLE
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELT BUCKLE
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	1710B2
TKN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	427
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T6F
DRIVE_CD	T6
ENG_CD	TAZ
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/15/2001
WRTY_START_D	6/31/2001
NAME	BEN SATCHEL MOTORS, INC.
DOC_NUM	4087151
PH_NUM	3594114
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	41
RPR_DT	8/11/2002
TIS_WSD	10
CLM_KEY	9113858
MILGE	21237
MTRL_COST	
TOT_COST_GROS	

LABR_HRS	00
DLR_CD	1078
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	81230 M TIME TO REPLACE LEFT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL NOT BUCKLE
AREA_CD	803
COUNTRY_CD	USA
SLS_DLR_CD	121274
TXN_CD	E54
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	428
VIN_CD	1PMRU17L01
LBR_COST	
VEH_LINE_CD	T783
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T7F
DRIVE_CD	T7B
ENG_CD	TVZ
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	2/11/2001
WRTY_START_D	5/5/2001
NAME	ENGEL BROS INC
DOC_NUM	027818A
PE_NUM	2458551
WCC_CD	8R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881202
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	1/9/2002
TYS_WSD	9
CLM_KEY	8163874
MILGE	10343
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	12
DLR_CD	8119
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	#
TECH_TXT1	REPLACE BOTH SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	FRONT SEAT BELT BUCKLES ERRATIC WONT LATCH.
AREA_CD	015
COUNTRY_CD	USA
SLS_DLR_CD	124208
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	430
VIN_CD	1FMRU17L01L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1F
DRIVE_CD	TB
ENG_CD	TN2
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	2/10/2001
WRTY_START_D	4/1/2001
NAME	TOWN & COUNTRY FORD , INC.
DOC_NUM	27009703
PH_NUM	5305600
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	4/25/2002
TIS_WSD	13
CLM_KEY	8304621
MILGE	28534
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	62
DLR_CD	1067
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	12001
Ratings	B
TECH_TXT1	42 REMOVED RITE FRONT SEAT FOR ACCESS TO BELT BUCKLE REPLACED BUCKLE AND REINSTALLED SEAT
TECH_TXT2	
CUST_TXT	CUST STATES THAT PASS SIDE FRT SEAT BELT WILL NOT LOCK 826
AREA_CD	704
COUNTRY_CD	USA
SLS_DLR_CD	121212
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V06
AWS_VL_CD	B3
VRT_CD	SK8
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	433
VIN_CD	1FMFLJ16WX1L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MRT_DERIVED	*
BOD_CAB_STL	TMD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/7/2001
WRTY_START_D	10/7/2001
NAME	HALL FORD
DOC_NUM	290491A
PH_NUM	9885700
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	4520443
MILGE	7
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	9.2
DLR_CD	8842
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	12001
Ratings	b
TECH_TXT1	PASSENGER SIDE SEATBELT WILL NOT HOLD, REMOVED PASSENGER FRONT SEAT TO ACCESS SEATBELT BUCKLE, REPLACED SEATBELT BUCKLE, NO LABOR OPS, USE M TIME
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEATBELT BUCKLE WILL NOT HOLD
AREA_CD	757
COUNTRY_CD	USA
SLS_DLR_CD	127060
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	434
VIN_CD	1FMRU18WXC1L
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	5/30/2001
NAME	WYMAN FORD, INC.
DOC_NUM	4180102
PH_NUM	7816000
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881202
PART_NUM_CAU	AAC
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/18/2001
TIS_WSD	3
CLM_KEY	4013745
MILGE	4901
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	69
DLR_CD	20884
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NI
CPSC_CD_6	12001
Ratings	9
TECH_TXT1	FOUND BOTH SEATBELTS MALFUNCTIONING REPLACED BOTH ASSEMBLIES AS NEEDED TO REGAIN PROPER SEATBELT OPERATION
TECH_TXT2	
CUST_TXT	CUSTOMER STATES BOTH SEATBELTS WILL NOT BUCKLE UP PROPERLY AT ALL TIMES
AREA_CD	973
COUNTRY_CD	USA
SLS_DLR_CD	113044
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	VD6
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	435
VIN_CD	1FMRU16W1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DX1
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	11/7/2001
NAME	HALDEMAN FORD
DOC_NUM	8047703
PH_NUM	48040
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S26
COND_CD	41
RPR_DT	5/7/2002
TIS_WSD	7
CLM_KEY	8834640
MILGE	8786
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	89
DLR_CD	8283
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	SEATBELT ASSEMBLY FRONT REPLACE (811A72 811A72) DRIVERS FRONT SEAT
TECH_TXT2	
CUST_TXT	CUST BT THE DRIVERS SIDE BUCKLE IS COMING LOOSE SEATBELT POPS OPEN BY ITSELF
AREA_CD	608
COUNTRY_CD	USA
SLS_DLR_CD	116445
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	608
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	437
VIN_CD	1FMRU18WX1U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/MN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/28/2001
NAME	PASO ROBLES FORD LINC-MERC
DOC_NUM	6746501
PH_NUM	2393673
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	10/8/2001
TIS_WSD	1
CLM_KEY	4488786
MILGE	821
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0
DLR_CD	5493
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEATBELT DOEN T HOLD
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	171488
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	805
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	438
VIN_CD	1FMRU18WX1
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	2/14/2001
WRTY_START_D	8/15/2001
NAME	STURMAN & LARKIN FORD, INC.
DOC_NUM	1005451
PH_NUM	8822300
WCC_CD	6R02
PART_NUM_CAU	F85Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BBE
CUST_CONC_CD	940
COND_CD	42
RPR_DT	8/27/2001
TIS_WSD	1
CLM_KEY	5044811
MILGE	818
MTRL_COST	
TOT_COST_GROS	

Thursday, December 14, 2000

Page 725 of 1238

R004-011 E 2750

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="7430"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="PA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value="B"/>
TECH_TXT1	<input type="text" value="TECHNICIAN #127 VERIFIED CONCERN REPLACED
S O SEAT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CLIST STATES DRIVERS SEAT BELT WILL NOT
STAY IN BUCKLE"/>
AREA_CD	<input type="text" value="412"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="144017"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="B08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	440
VIN_CD	1FMRU16WXX
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	2/5/2001
NAME	BYERLY FORD INC
DOC_NUM	28141AB
PH_NUM	4461861
WCC_CD	BF02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7661203
PART_NUM_CAU	BAB
CUST_CONC_CD	828
COND_CD	42
RPR_DT	5/24/2002
TIS_WSD	18
CLM_KEY	8800581
MILGE	16028
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.3
DLR_CD	5702
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	KY
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	15038 WARR REPLACE BROKEN DRIVER SEAT BELT BUCKLE CC IN TECH 5772
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEATBELT BUCKLE BOP
AREA_CD	602
COUNTRY_CD	USA
SLS_DLR_CD	147017
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRY_CD	308
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	442
VIN_CD	1FMRU16WX1L
LBR_COST	
VEH_LINE_CD	T753
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T4F
DRIVE_CD	TIE
ENG_CD	TVN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	8/28/2000
WRTY_START_D	12/2/2000
NAME	JOHN KENNEDY FORD
DOC_NUM	18863401
PH_NUM	3576800
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAB
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	7/9/2001
TIS_WSD	0
CLM_KEY	2518777
MILGE	10889
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	1232
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	12001
Ratings	*
TECH_TXT1	SEATBELT ASSY REPLACED FRONT SEATBELT ASSY
TECH_TXT2	
CUST_TXT	SOP RIGHT SIDE SEATBELT
AREA_CD	215
COUNTRY_CD	USA
SLS_DLR_CD	116045
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	443
VIN_CD	1FMRU16W91L
LBR_COST	
VEH_LINE_CD	T/ES
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	10/2/2001
NAME	ALL AMERICAN FORD, INC.
DOC_NUM	108438A
PH_NUM	4876700
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881208
PART_NUM_CAU	BAB
CUST_CONC_CD	826
COND_CD	42
RPR_DT	5/28/2002
TIS_WSD	8
CLM_KEY	0811848
MILGE	4844
MTBL_COST	
TOT_COST_GROS	

LBR_HRS	09
DLR_CD	2724
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	REPLACED THE LEFT FRONT SEAT BELT ASSEMBLY. CHECKED OPERATION, OKAY NOW.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE DRIVERS SEAT BELT WILL POP OUT (UNLATCH) WHILE DRIVING.
AREA_CD	201
COUNTRY_CD	USA
SLS_DLR_CD	113147
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	445
VIN_CD	1FMRU16W91L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TMO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	5/17/2001
NAME	SENATOR FORD INC
DOC_NUM	32385401
PH_NUM	3813000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AA
CUST_CONC_CD	825
COND_CD	42
RPR_DT	1/31/2002
TIS_WSD	0
CLM_KEY	8512528
MILGE	14770
MTRL_COST	
TOT_COST_GROS	

Thursday, December 14, 2004

Page 733 of 1298

RQ04-011 E 2758

LBR_HRS	18
DLR_CD	7762
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACED SEAT BUCKLES
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BUCKLE REFER TO LAST RD 320838 BOTH FRONT
AREA_CD	916
COUNTRY_CD	USA
SLS_DLR_CD	172209
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	448
VIN_CD	1FMRU18W91L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T7B5
MKT_DERIVED	*
BOD_CAB_STL	T7WD
VER_SERIES_CD	T7EF
DRIVE_CD	T7E
ENG_CD	T7VN
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	4/2/2001
WRTY_START_D	4/28/2001
NAME	HARRELSON FORD, INC.
DOC_NUM	4502951
PH_NUM	5522780
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BA8
CUST_CONC_CD	025
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	8
CLM_KEY	5487437
MILGE	11787
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LRR_HRS	04
DLR_CD	1071
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	BUCKLE & SWITCH BAD SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	OK DRIVERS SIDE FRONT SEAT HAS COME LOOSE WHILE DRIVING
AREA_CD	704
COUNTRY_CD	USA
SLS_DLR_CD	121213
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	451
VIN_CD	1FMRU18W91
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	.
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	12/8/2000
WRTY_START_D	2/13/2001
NAME	WANTAGH AUTO SALES INC
DOC_NUM	7901901
PH_NUM	7851700
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	42
RPR_DT	2/27/2002
TIS_WSD	13
CLM_KEY	7340928
MILGE	12871
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	3000
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEATBELT DOESNT LOCK CLICK SHUT
AREA_CD	516
COUNTRY_CD	USA
SLS_DLR_CD	113089
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	453
VIN_CD	1FMRU18W81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/R3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VRR_SRRIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	TVN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/14/2001
WRTY_START_D	6/8/2001
NAME	SYL WORNACZ FORD, INC.
DOC_NUM	7281802
PH_NUM	8486777
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	826
COND_CD	42
RPR_DT	4/24/2002
TIS_WSD	11
CLM_KEY	8114483
MILGE	12382
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	06
DLR_CD	1340
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	12001
Ratings	B
TECH_TXT1	CK OASIS,FOUND RECALL WAS PERFORMED AT ANOTHER DEALER,TEST SEAT BELT WITH TOOL AND IT DID NOT HOLD.REPLACE RF SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RF SEAT BELT DOES NOT ALLWAYS LATCH
AREA_CD	570
COUNTRY_CD	USA
SLS_DLR_CD	116574
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	455
VIN_CD	1FMRU16W81L
LBR_COST	
VEH_LINE_CD	783
MKT_DERIVED	
BOD_CAR_STL	7AND
VER_SERIES_CD	TEF
DRIVE_CD	TE
ENG_CD	TAN
TRANS_CD	TGU
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	8/21/2001
NAME	TOWNE FORD
DOC_NUM	081098A
PH_NUM	8886200
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	540
COND_CD	42
RPR_DT	8/24/2001
TIS_WSD	1
CLM_KEY	4215014
MILGE	525
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	06
DLR_CD	6190
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WI
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACE DRIVERS FRONR SEAT BELT
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT STAY LATCHED
AREA_CD	282
COUNTRY_CD	USA
SLS_DLR_CD	141304
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B3
VRI_CD	S03
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	458
VIN_CD	1FMRU10W81L
LBR_COST	
VEH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	T/E
ENG_CD	TVN
TRANS_CD	TDLJ
PLANT_CD	AP
PRODN_DT	2/26/2001
WRTY_START_D	3/2/2001
NAME	FORD MOTOR COMPANY
DOC_NUM	3155731
PH_NUM	*
WCC_CD	BR02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7981203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	11/8/2001
TIS_WSD	9
CLM_KEY	8030784
MILGE	18620
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	60340
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	6
TECH_TXT1	INSTALLED NEW LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	482
VIN_CD	1FMRU16W71
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	TVN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	8/14/2001
NAME	NORTH COUNTY FORD
DOC_NUM	261720A
PH_NUM	9458900
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7891203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	6/8/2002
TIS_WSD	8
CLM_KEY	8526306
MILGE	18593
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	4.3
DLR_CD	888
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	18503 BELT RELEASE INT 1.3 CK BELTS,REPLACE BOTH BUCKLES AND DRIVERS BELT AND RETEST OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES: DRIVER SEAT BELT IS INOPERATIVE; PER S.O.P INSTALL SEAT BELT PART. INSPECT AND ADVISE
AREA_CD	760
COUNTRY_CD	USA
SLS_DLR_CD	171078
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	463
VIN_CD	1FMRU16W71L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
ROD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	10/18/2001
NAME	KOONS FORD OF BALTIMORE INC
DOC_NUM	2832551
PH_NUM	2883600
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAC
CUST_CONC_CD	340
COND_CD	42
RPR_DT	10/24/2001
TIS_WSD	1
CLM_KEY	4640472
MILGE	207
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	144
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MD
CPS_CCD_6	11001
Ratings	a
TECH_TXT1	INSTALL SOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	INSTALL SOP DRIVERS SIDE SEAT BELT
AREA_CD	410
COUNTRY_CD	USA
SLS_DLR_CD	127037
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VI_CD	B3
VRT_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	467
VIN_CD	1FMFU16V81
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	TE
ENG_CD	TVN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	6/2/2001
WRTY_START_D	6/4/2001
NAME	JEROME-DUNCAN, INC.
DOC_NUM	10875101
PH_NUM	2887600
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	41
RPR_DT	10/11/2001
TIS_WSD	5
CLM_KEY	4343988
MILGE	8903
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="3025"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="MI"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="LEFT FRONT SEAT BELT BUCKEL NOT LATCHING
CC 42 BP#7861203 BUCKET SEATS CHECKED
OPERATION OF LEFT FRONT SEAT BELT BUCKEL
INTERMITTLY WILL NOT LATCH CHECKED BELT
FOR DAMAGE OK REMOVED AND REPLACED LEFT"/>
TECH_TXT2	<input type="text" value="FRONT SEAT BELT BUCKEL OK"/>
CUST_TXT	<input type="text" value="CUSTOMER STATES DRIVERS SIDE SEAT BELT
RECEPTICLE DOES NOT ALWAYS LATCH. BUCKLE
WAS INSPECTED LAST MONTH PER RECALL AND
PASSED INSPECTION"/>
AREA_CD	<input type="text" value="310"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="148048"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="B08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	468
VIN_CD	1FMEFL16W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/9/2001
WRTY_START_D	5/28/2001
NAME	WAYSIDE FORD, INC.
DOC_NUM	8979901
PH_NUM	4808400
WCC_CD	8F02
PART_NUM_CAU	F85Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BBE
CUST_CONC_CD	325
COND_CD	42
RPR_DT	8/10/2001
TIS_WSD	3
CLM_KEY	4051231
MILGE	6018
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	8878
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MA
CPSC_CD_6	12001
Ratings	
TECH_TXT1	REPLACED DR SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	REPLACING DR SIDE SEAT BELT PARTS ORDERED
AREA_CD	605
COUNTRY_CD	USA
SLS_DLR_CD	111489
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	470
VIN_CD	1FMRU16W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	11/30/2000
WRTY_START_D	1/17/2001
NAME	VALLEY FORD INC
DOC_NUM	10331002
PH_NUM	8844800
WCC_CD	8P02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7661202
PART_NUM_CAU	AAC
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	3/13/2002
TIS_WSD	15
CLM_KEY	7550369
MILGE	12250
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 733 of 1298

RQ04-011 E 2778

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="2061B"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NJ"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="NECC TO REPLACE RIGHT SIDE SEAT BELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUST STATES SEAT BELT INOP"/>
AREA_CD	<input type="text" value="201"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="113164"/>
TXN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="B08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	472
VIN_CD	1FMRU16W61L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/23/2001
WRTY_START_D	7/20/2001
NAME	JACK TREBOUR FORD
DOC_NUM	27001
PH_NUM	9275700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/31/2001
TIS_WSD	4
CLM_KEY	4817106
MILGE	1329
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	0.4
DLR_CD	3701
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	12001
Rating	a
TECH_TXT1	540 42 VERIFY CONCERN REPLCAED SEAT BELT BUCKLE WITH NEW RECHECK OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES P S FRONT SEAT BELT WILL NOT LATCH REPORT
AREA_CD	201
COUNTRY_CD	USA
SLS_DLR_CD	118460
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	473
VIN_CD	1FMRU10W51L
LBR_COST	
VEH_LINE_CD	T03
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	4/12/2001
NAME	FRITTS FORD
DOC_NUM	8151151
PH_NUM	*
WCC_CD	BRIZ
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	B40
COND_CD	1
RPR_DT	8/31/2001
TIS_WSD	5
CLM_KEY	2482213
MILGE	11055
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	6A
DLR_CD	6667
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Rating	*
TECH_TXT1	INSPECTED FOUND SEAT BELT BUCKLE BROKEN, REPLACED BUCKLE AND RETESTED OK.
TECH_TXT2	
CUST_TXT	PLEASE INSTALL SOP (SEAT BELT BUCKLES)
AREA_CD	*
COUNTRY_CD	USA
SLS_DLR_CD	171155
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B3
VRT_CD	606
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	474
VIN_CD	1FMRU16W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/6/2001
WRTY_START_D	8/28/2001
NAME	MC CRACKIN FORD
DOC_NUM	180884A
PH_NUM	8318880
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AB
CUST_CONC_CD	928
COND_CD	41
RPR_DT	2/18/2002
TIS_WSD	8
CLM_KEY	8851885
MILGE	12083
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	7459
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	PA
CPSC_CD_6	11001
Rafings	*
TECH_TXT1	REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT INOPP
AREA_CD	412
COUNTRY_CD	USA
SLS_DLR_CD	144007
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B8
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	476
VIN_CD	1FMRU16W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/M
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	8/8/2000
WRTY_START_D	8/21/2000
NAME	OWNS FORD, INC.
DOC_NUM	5881851
PH_NUM	3492240
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	BAB
CUST_CONC_CD	826
COND_CD	42
RPR_DT	1/10/2002
TIS_WSD	18
CLM_KEY	8212052
MILGE	31818
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	20881
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	LEFT SEAT BELT BUCKLE INOP REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	O S DRIVERS SIDE SEAT BELT BUCKLE INOP. INSTALL SPEC ORDERED PART
AREA_CD	732
COUNTRY_CD	USA
SLS_DLR_CD	113688
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	47B
VIN_CD	1FMRU16W41U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/1/2001
WRTY_START_D	11/7/2001
NAME	HARRIS FORD, INC.
DOC_NUM	9803001
PH_NUM	7744141
WCC_CD	8P02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	YBS1203
PART_NUM_CAU	BAA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	3/13/2002
TIS_WSD	6
CLM_KEY	7478888
MILGE	5568
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	USA
DLR_CD	8738
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	WA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	R I SEAT AND REPLACE DRIVERS SEAT BELT BUCKLE CHECK OP, OK.
TECH_TXT2	
CUST_TXT	
AREA_CD	208
COUNTRY_CD	USA
SLS_DLR_CD	174024
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	481
VIN_CD	1FMRU16W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/28/2001
WRTY_START_D	8/31/2001
NAME	FRIENDLY FORD INC
DOC_NUM	058048A
PH_NUM	2438000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	825
COND_CD	42
RPR_DT	10/13/2001
TES_WSD	2
CLM_KEY	4480870
MILGE	1244
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	2882
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACE SEAT BELT ASSEMBLY
TECH_TXT2	
CUST_TXT	OS SEAT BELT SOP HERE
AREA_CD	734
COUNTRY_CD	USA
SLS_DLR_CD	148434
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	83
VRT_CD	805
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	482
VIN_CD	1FMRU16W41
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/E F
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/12/2001
WRTY_START_D	2/20/2001
NAME	CAPITAL LINCOLN-MERCURY INC
DOC_NUM	087940A
PH_NUM	7209100
WCC_CD	9R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	9/27/2001
TIS_WSD	B
CLM_KEY	4009689
MILGE	10497
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	8A
DLR_CD	10528
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACED LEFT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WILL NOT STAY LATCHED
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	484
VIN_CD	1FMRJ18W41
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/MO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	3/20/2001
NAME	CROWN FORD, INC.
DOC_NUM	188301
PH_NUM	6990900
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S25
COND_CD	41
RPR_DT	11/27/2001
TIS_WSD	9
CLM_KEY	6307833
MILGE	8917
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	9717
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NY
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	INSTALLED SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	
AREA_CD	518
COUNTRY_CD	USA
SLS_DLR_CD	113088
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	485
VIN_CD	1FMRU16W41
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TND
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/13/2000
WRTY_START_D	3/3/2001
NAME	FREDERICK FORD-MERCURY INC
DOC_NUM	6668101
PH_NUM	8294564
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	CAA
CUST_CONC_CD	826
COND_CD	42
RPR_DT	2/22/2002
TIS_WSD	12
CLM_KEY	7130787
MILGE	18008
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="1229"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="DE"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="e"/>
TECH_TXT1	<input type="text" value="DEFECTIVE CHECK BELT OPERATION, ORDER PART REMOVE D S SEAT REPLACE LATCH REASSEMBLE CHECK OPERATION OK"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="D8 SEATBELT INOP"/>
AREA_CD	<input type="text" value="302"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="127588"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B9"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	488
VIN_CD	1FMRU18W31L
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/28/2001
WRTY_START_D	7/31/2001
NAME	HINES PARK FORD, INC.
DOC_NUM	2353801
PH_NUM	4378700
WCC_CD	8F02
PART_NUM_CAU	F86Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BBE
CUST_CONC_CD	825
COND_CD	42
RPR_DT	11/27/2001
TIS_WSD	4
CLM_KEY	5381080
MILGE	8885
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	1425
DLR_CD	1425
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	12001
Ratings	#
TECH_TXT1	REPLACE DRIVERS SIDE SEAT BELT BUCKLE PER RECALL
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT DOES NOT ALWAYS LATCH SOF HERE
AREA_CD	248
COUNTRY_CD	USA
SLS_DLR_CD	148438
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	490
VIN_CD	1FMRU16W31
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	12/31/2001
NAME	D-PATRICK, INC.
DOC_NUM	158884A
PH_NUM	4287800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	1/22/2002
TIS_WSD	1
CLM_KEY	8402478
MILGE	600
MTRL_COST	
TOT_COST_GROS	