

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 1 OF 6

BOOK 5 OF 43

LBR_HRS	88
DLR_CD	4823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	IN
CPSC_CD_6	11001
Ratings	3
TECH_TXT1	880 LEFT FRONT SEAT BELT LATCH NOT OPERATING PROP 42 MTR1203 VERIFIED CUSTOMER COMPLAINT THAT THE SEAT BELT LATCH ON LF SEAT WILL NOT LATCH MAJORITY OF THE TIME. REMOVED OLD LATCH AND INSTALLED NEW
TECH_TXT2	ONE
CUST_TXT	840 CUS STS THAT THE LF SEAT BELT WONT LATCH, 8 0 PART
AREA_CD	812
COUNTRY_CD	USA
SLS_DLR_CD	147627
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	482
VIN_CD	1FMRL10W31LB22508
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	4/18/2001
NAME	MALLOY FORD
DOC_NUM	812352
PH_NUM	8418400
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	AAH
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/4/2002
TIS_WSD	14
CLM_KEY	0003088
MILGE	19988
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0:00
DLR_CD	0048
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	NH
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	TESTED SEAT BELTS AND FOUND BOTH NOT LATCHING REPLACED BELTS AND RETESTED ALL OK
TECH_TXT2	
CUST_TXT	BOTH FRONT SEAT BELTS DO NOT STAY LATCHED
AREA_CD	000
COUNTRY_CD	USA
SLS_DLR_CD	111586
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	493
VIN_CD	1FMRU16W21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	3/2/2001
WRTY_START_D	7/28/2001
NAME	MONTECLAIR BLOOMFIELD MOTORS
DOC_NUM	7883651
PH_NUM	7488800
WCC_CD	BF02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAC
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	8
CLM_KEY	8029580
MILGE	5526
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	98
DLR_CD	20598
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	12001
Ratings	8
TECH_TXT1	REPLACE RIGHT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CK R FRT SEAT BELT BUCKEL WONT LATCH
AREA_CD	973
COUNTRY_CD	USA
SLS_DLR_CD	113048
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	485
VIN_CD	1FMRJ16W31L
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/20/2000
WRTY_START_D	12/13/2000
NAME	MIKE DORIAN FORD INC
DOC_NUM	2505853
PH_NUM	7824100
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAC
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/20/2001
TIS_WSD	9
CLM_KEY	3282364
MILGE	10625
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 781 of 1298

LBR_HRS	05
DLR_CD	2078
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	SEAT BELT COMES LOOSE INTERMITTENTLY, REPLACED LEFT FRONT SEAT BELT ASSEMBLY. RECHECKED, OK.
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEATBELT KEEPS COMING UNHOOKED
AREA_CD	B10
COUNTRY_CD	USA
SIS_DLR_CD	148048
TKN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	500
VIN_CD	1FMRL118W21L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_CD	TJF
DRIVE_CD	TIE
ENG_CD	TMN
TRANS_CD	TJU
PLANT_CD	AP
PRODN_DT	4/3/2001
WRTY_START_D	7/28/2001
NAME	BATTLEFIELD FORD
DOC_NUM	207706A
PH_NUM	3583184
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7B61203
PART_NUM_CAU	BAC
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/22/2001
TIS_WSD	1
CLM_KEY	3478281
MILGE	412
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 783 of 1298

LBR_HRS	38
DLR_CD	57
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	VA
CPSC_CD_6	11001
Ratings	3
TECH_TXT1	REPLACE LT FRT SEATBELT ASSY
TECH_TXT2	
CUST_TXT	LEFT FRONT SEAT BELT WONT LATCH
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	127048
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	501
VIN_CD	1FMRU16W21L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	T/E
ENG_CD	TMN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/10/2001
WRTY_START_D	8/8/2001
NAME	ALL AMERICAN FORD, INC.
DOC_NUM	0088396
PH_NUM	4878700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAC
CUST_CONC_CD	926
COND_CD	41
RPR_DT	1/10/2002
TIS_WSD	6
CLM_KEY	6255136
MILGE	11636
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 781 of 1798

RQ04-011 E 2810

LBR_HRS	04
DLR_CD	2724
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	12001
Ratings	4
TECH_TXT1	WILL NOT LATCH. REPLACED RIGHT FRONT SEAT BELT.
TECH_TXT2	
CUST_TXT	C B RIGHT FRONT SEAT BELT WILL NOT LOCK INTO RECEIVER
AREA_CD	201
COUNTRY_CD	USA
SLS_DLR_CD	113147
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	503
VIN_CD	1FMRU16W21U [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	11/9/2000
WRTY_START_D	11/24/2000
NAME	KEN GRODY FORD
DOC_NUM	7782058
PH_NUM	8218881
WCC_CD	8R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881208
PART_NUM_CAU	8AB
CUST_CONC_CD	940
COND_CD	42
RPR_DT	8/13/2001
TIS_WSD	0
CLM_KEY	9082557
MILGE	7880
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	9.8
DLR_CD	7046
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	DR SEAT BELT BUCKLE TESTED & REPLACED BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER SEAT BELT STICKS OR DOENT MAKE A CLICKING NOISE TO LOCK IN
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171206
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	504
VIN_CD	1FMRU16W21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_CD	TEF
DRIVE_CD	TE
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/24/2000
WRTY_START_D	11/24/2000
NAME	VISTA LINCOLN-MERCURY
DOC_NUM	8690151
PH_NUM	3488800
WCC_CD	BRD2
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	4/30/2002
TIS_WSD	18
CLM_KEY	8600256
MILGE	28509
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="1.5"/>
DLR_CD	<input type="text" value="10085"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="a"/>
TECH_TXT1	<input type="text" value="COMPLETED RECALL"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="PERFORM RECALL 01S21 SEAT BELT BUCKLE"/>
AREA_CD	<input type="text" value="B1B"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171251"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="89"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	508
VIN_CD	1FMRJ16W11LE
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/21/2001
WRTY_START_D	5/29/2001
NAME	FAMILY FORD INC
DOC_NUM	8017061
PH_NUM	3473000
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	4/17/2002
TIS_WSD	11
CLM_KEY	8175752
MILGE	18718
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	07
DLR_CD	20523
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	CHECK SEAT BELT OPERATION PERFORM DIAG FOUND LATCH NAT LATCHING REPLACE SEAT BELT LATCH RETEST OPERATION OK
TECH_TXT2	
CUST_TXT	CUSTOMER STATES INSTALL SPO SEAT BELT PART LEFT FRONT SEAT BELT WILLNOT LATCH
AREA_CD	078
COUNTRY_CD	USA
SLS_DLR_CD	113462
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B8
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	508
VIN_CD	1FMRU16W11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	9/3/2001
NAME	MALOUF FORD, INC.
DOC_NUM	200088A
PH_NUM	9510900
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAB
CUST_CONC_CD	828
COND_CD	42
RPR_DT	3/4/2002
TIS_WSD	7
CLM_KEY	7203804
MILGE	8881
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	88
DLR_CD	20527
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NJ
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	6901 INSTALLED NEW DRIVERS SEAT BELT BUCKLE CANT PERFORM 01521 RECALL W OUT TOOL D S BUCKLE WOULDNT LATCH
TECH_TXT2	
CUST_TXT	CUST STATES D S FRONT SEATBELT DOES NOT LATCH IN SPO PART CHECK ALSO FOR 01521 RECALL SEATBELT BUCKLE
AREA_CD	732
COUNTRY_CD	USA
SLS_DLR_CD	113055
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	500
VIN_CD	1FMRU18W11L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	4/8/2001
WRTY_START_D	4/14/2001
NAME	WALDORF FORD, INC.
DOC_NUM	4802151
PH_NUM	8432400
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	8AB
CUST_CONC_CD	S25
COND_CD	2
RPR_DT	10/17/2001
TIS_WSD	7
CLM_KEY	4473875
MILGE	11583
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	RECALL
DLR_CD	148
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MD
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACE DR SIDE SEAT BELT FOR RECALL
TECH_TXT2	
CUST_TXT	S O PART SEAT BUCKLE DRIVERS FT USE SPO 01297005
AREA_CD	301
COUNTRY_CD	USA
SLS_DLR_CD	127047
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	511
VIN_CD	1FMFUJ18W11
LRR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	8/31/2001
NAME	HARROLD FORD
DOC_NUM	228118C
PH_NUM	9221596
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	788120Z
PART_NUM_CAU	MAC
CUST_CONC_CD	526
COND_CD	42
RPR_DT	3/15/2002
TIS_WSD	7
CLM_KEY	7450871
MILGE	11515
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	6
DLR_CD	7882
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	*
TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES
TECH_TXT2	
CUST_TXT	REPAIR FOR DRIVER SEAT BELT COMES UNDONE AT TIMES. INSTALL SOP.
AREA_CD	018
COUNTRY_CD	USA
SLS_DLR_CD	172202
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	612
VIN_CD	1FMRU16W11L
LRR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VRR_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/8/2001
WRTY_START_D	7/10/2001
NAME	BERGLIND FORD
DOC_NUM	2848228
PH_NUM	3897281
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAC
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	8/13/2002
TIS_WSD	12
CLM_KEY	8200058
MILGE	12819
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="02"/>
DLR_CD	<input type="text" value="6717"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="VA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="0"/>
TECH_TXT1	<input type="text" value="CHECKED AND CONFIRMED CONCERN.REPLACED SEAT BELT TO FIX REPAIR."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DRIVER SEAT POSITION THE MALE END OF SAFETY BELT KEEPS POPPING OUT."/>
AREA_CD	<input type="text" value="703"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="127081"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="806"/>
TIS_FLAG	<input type="text" value="0"/>

MDL_YR	2001
SORT_INDEX	619
VIN_CD	1FMRU19W11L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	TE
ENG_CD	TMN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	2/8/2001
WRTY_START_D	2/23/2001
NAME	AVIS FORD INC
DOC_NUM	197181C
PH_NUM	3557500
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AB
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	5/20/2002
TIS_WSD	16
CLM_KEY	8769320
MILGE	19665
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0A
DLR_CD	2750
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MI
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	10566 INOP WAR REPLACT HE OR SIDE SEAT BELT BUCLE,RETEETS O
TECH_TXT2	
CUST_TXT	ADD ON WARRANTYDRIVER SEATBELT DOEW NOT ALWAYS STAY SECURE
AREA_CD	248
COUNTRY_CD	USA
SLS_DLR_CD	148028
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	515
VIN_CD	1FMRU16W11L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	TIE
ENG_CD	TVM
TRANS_CD	TIDJ
PLANT_CD	AP
PRODN_DT	12/18/2000
WRTY_START_D	2/19/2001
NAME	HILLSBORO FORD, INC.
DOC_NUM	2817701
PH_NUM	4844000
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7901203
PART_NUM_CAU	BAB
CUST_CONC_CD	S25
COND_CD	B9
RPR_DT	2/27/2002
TIS_WSD	13
CLM_KEY	7190888
MILGE	32448
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	1000
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NH
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACED LEFT DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES, DRIVERS SIDE SEAT BELT FAILED INSTALLED SOP SEAT BELT (DRIVERS)
AREA_CD	003
COUNTRY_CD	USA
SLS_DLR_CD	111502
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	616
VIN_CD	1FMRU10W131
LBR_COST	
VRH_LINE_CD	T03
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TXF
DRIVE_CD	TIE
ENG_CD	TVM
TRANS_CD	T0U
PLANT_CD	AP
PRODN_DT	10/26/2000
WRTY_START_D	11/17/2000
NAME	JERRY ALDERMAN FORD INC
DOC_NUM	9120551
PH_NUM	2511441
WCC_CD	BF02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAB
CUST_CONG_CD	B40
COND_CD	42
RPR_DT	01/13/2001
TIS_WSD	9
CLM_KEY	2985140
MILGE	0142
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 895 of 1298

RQ04-011 E 2830

LBR_HRS	042
DLR_CD	4871
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IN
CPSC_CD_6	11001
Rating	b
TECH_TXT1	HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.
TECH_TXT2	
CUST_TXT	CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART
AREA_CD	917
COUNTRY_CD	USA
SLS_DLR_CD	147027
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	517
VIN_CD	1FMFU16W111
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	9/19/2000
WRTY_START_D	3/26/2001
NAME	BURT'S ARAPAHOE FORD, INC.
DOC_NUM	387920A
PH_NUM	6438000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAA
CUST_CONC_CD	S15
COND_CD	41
RPR_DT	9/28/2001
TIS_WSD	7
CLM_KEY	3983582
MILGE	7166
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	3188
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	REPLACE RIGHT FRONT SEAT BELT BUCKEL TEST ALL OK AT THIS TIME
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THE PASS FRONT SEAT BELT IS INOP SOP
AREA_CD	308
COUNTRY_CD	USA
SLS_DLR_CD	158001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	89
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	519
VIN_CD	1FMRU16W01LE
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/7/2001
WRTY_START_D	11/16/2001
NAME	BOB SIGHT FORD INC
DOC_NUM	124208A
PH_NUM	5248550
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861209
PART_NUM_CAU	BAC
CUST_CONC_CD	928
COND_CD	42
RPR_DT	8/7/2002
TIS_WSD	7
CLM_KEY	9089074
MILGE	11840
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	5113
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	MO
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	REPLACE DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	THE DRIVERS SEATBELT IS NOT WORKING PROPERLY SOP HERE
AREA_CD	B16
COUNTRY_CD	USA
SLS_DLR_CD	153015
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	524
VIN_CD	1FMRU15WX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	8/25/2001
WRTY_START_D	12/31/2001
NAME	HEINTZELMAN'S TRUCK CENTER INC
DOC_NUM	18884A
PH_NUM	2881000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	10/16/2001
TIS_WSD	0
CLM_KEY	488525
MILGE	11
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 811 of 1298

RQ04-011 E 2836

LRR_HRS	04
DLR_CD	8035
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	4
TECH_TXT1	11 SEAT BELT NOT LATCHING & DR SEAT BELT BUCKLE NOT LATCHING. ORDERED NEW BUCKLE. INSTALLED. PROBLEM FIXED
TECH_TXT2	
CUST_TXT	C.S LEFT FRONT SEAT BELT INOP. CH ADVISE
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124800
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	626
VIN_CD	1FMRU15WX1L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TAWD
VER_SERIES_CD	TAEF
DRIVE_CD	TB
ENG_CD	T/VN
TRANS_CD	TALJ
PLANT_CD	AP
PRODN_DT	5/28/2001
WRTY_START_D	8/4/2001
NAME	WAYNE AKERS FORD, INC.
DOC_NUM	238446A
PH_NUM	6824444
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAC
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	6/31/2002
TIS_WSD	11
CLM_KEY	8987051
MILGE	14802
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	4879
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	A
TECH_TXT1	14802 BUCKLE WILL NOT LATCH VERIFIED CONCERN REPLACED PASS FRONT SEAT BELT ASS QUALITY INSPECTED BY 3888.....
TECH_TXT2	
CUST_TXT	S28 CUSTOMER STATES RF SEAT BELT WONT LATCH
AREA_CD	BB1
COUNTRY_CD	USA
SLS_DLR_CD	124018
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TYS_FLAG	0

MDL_YR	2001
SORT_INDEX	328
VIN_CD	1FMRU15WXL
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T7EF
DRIVE_CD	T7B
ENG_CD	T7VN
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	5/22/2001
WRTY_START_D	8/10/2001
NAME	TOWN EAST FORD
DOC_NUM	782820A
PH_NUM	2708441
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	1/18/2002
TIS_WSD	6
CLM_KEY	6375878
MILGE	5577
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	841
DLR_CD	6182
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	6
TECH_TXT1	5577 BROKEN 01 REPLACED LT FT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	840 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	152002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	528
VIN_CD	1FMRU15WX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/9/2001
WRTY_START_D	8/27/2001
NAME	ALDUBON FORD
DOC_NUM	1974283
PH_NUM	2838800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	925
COND_CD	42
RPR_DT	11/21/2001
TIS_WSD	5
CLM_KEY	6700983
MILGE	6508
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0000000000000000
DLR_CD	8521
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	9808 REPLACED SEAT BELT BUCKLE TESTED ALL WORKS PROPERLY
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEATBELT BUCKLE NOT WORKING PROPERLY
AREA_CD	226
COUNTRY_CD	USA
SLS_DLR_CD	123203
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	534
VIN_CD	1FMRU15WXX1
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DAJ
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	3/28/2001
NAME	VISTA FORD
DOC_NUM	4801651
PH_NUM	8847600
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	7/13/2001
TIS_WSD	2
CLM_KEY	2451504
MILGE	1588
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	7823
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	08 7881203 LEFT FRONT SEAT ACCESS TO REPLACE DRIVERS SEAT BELT BUCKLE THAT
TECH_TXT2	
CUST_TXT	CUST STATES DR FRT SEAT BELT WILL POP OUT OF RECEPTACLE WHILE DRIVING INTERM AND TAKES ABOUT 3 4 TIMES BEFORE WILL LOCK BACK INTO RECEPTACLE
AREA_CD	616
COUNTRY_CD	USA
SLS_DLR_CD	174045
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V06
AWS_VL_CD	E3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	535
VIN_CD	1FMRL115W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
ROD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DX
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	7/14/2001
NAME	JOE COOPER FORD, INC.
DOC_NUM	8203203
PH_NUM	7331611
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	540
COND_CD	
RPR_DT	3/20/2002
TIS_WSD	8
CLM_KEY	7541435
MILGE	14088
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="852"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="OK"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="LEFT FRT SEAT BELT BUCKLE SWITCH FAILED. VERIFIED CONCERN, TEST AND REPLACED LEFT FRONT SEAT BELT BUCKLE CLOSED BY WPI"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value=""/>
AREA_CD	<input type="text" value="406"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="162208"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
YIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	537
VIN_CD	1FMRJ15WX1 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	4/9/2001
WRTY_START_D	5/8/2001
NAME	FULLER FORD
DOC_NUM	187573A
PH_NUM	6582600
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAC
CUST_CONC_CD	340
COND_CD	42
RPR_DT	1/9/2002
TIS_WSD	9
CLM_KEY	8291867
MILGE	11990
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	89
DLR_CD	5578
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CHECK AND ADVISE IN SEATBELT
AREA_CD	619
COUNTRY_CD	USA
SLS_DLR_CD	171102
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	538
VIN_CD	1FMRU15WX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TAND
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/MN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/7/2001
WRTY_START_D	5/11/2001
NAME	FORD OF UPLAND
DOC_NUM	178722A
PH_NUM	6463355
WCC_CD	BR02
PART_NUM_CAU	F85Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BBE
CUST_CONC_CD	S26
COND_CD	41
RPR_DT	7/12/2001
TIS_WSD	3
CLM_KEY	2348082
MILGE	2254
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.1
DLR_CD	5555
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	d
TECH_TXT1	REMOVE DRIVE SEAT BELT BUCKLE TO REPLACE (POPPE D LOOSE WHILE DRIVING
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WONT STAY LATCHED
AREA_CD	908
COUNTRY_CD	USA
SLS_DLR_CD	171108
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	642
VIN_CD	1FMRU15W1L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/MN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	4/29/2001
NAME	FRONTIER FORD
DOC_NUM	8781651
PH_NUM	2411600
WCC_CD	5R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7961203
PART_NUM_CAU	BAB
CUST_CONC_CD	826
COND_CD	41
RPR_DT	1/12/2002
TIS_WSD	9
CLM_KEY	6285824
MILGE	9595
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	0.6
DLR_CD	7881
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	CK AND REPL DFCTVE BUCKLE ASSY, REASSMBLE AND RECK,OK
TECH_TXT2	
CUST_TXT	CUSTOMER REPORTS SECOND SEAT RT. SIDE SEAT BELT WILL NOT BUCKLE.
AREA_CD	408
COUNTRY_CD	USA
SLS_DLR_CD	172402
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	544
VIN_CD	1FMRU15WC1
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/1/2001
WRTY_START_D	5/25/2001
NAME	NORTH COUNTY FORD
DOC_NUM	256638A
PH_NUM	0450000
WCC_CD	0R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	9/26/2002
TIS_WSD	11
CLM_KEY	7804345
MILGE	11849
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="800"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="d"/>
TECH_TXT1	<input type="text" value="11849 SOP PART 0.6MT REMOVED AND REPLACED FEMALE SEAT BELT BUCKLE AFTER DUPLICATING CONCERN RETESTED QUALITY OK"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING"/>
AREA_CD	<input type="text" value="760"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171078"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	661
VIN_CD	1FMRU15M0C1
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/2/2001
WRTY_START_D	4/5/2001
NAME	EL CENTRO MOTORS
DOC_NUM	5450851
PH_NUM	9829030
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAA
CUST_CONC_CD	525
COND_CD	42
RPR_DT	7/14/2001
TIS_WSD	4
CLM_KEY	4115714
MILGE	701B
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	5591
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	R&R SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	C & DRIVE SIDE SEAT BELT COME UNBUCKLED
AREA_CD	780
COUNTRY_CD	USA
SLS_DLR_CD	171423
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	552
VIN_CD	1FMRU16W01L
LBR_COST	
VEH_LINE_CD	T69
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/F
DRIVE_CD	TB
ENG_CD	TVN
TRANS_CD	T/DL
PLANT_CD	AP
PRODN_DT	1/31/2001
WRTY_START_D	5/14/2001
NAME	DON SHETLER FORD INC
DOC_NUM	100271
PH_NUM	6253030
WCC_CD	BR02
PART_NUM_CAU	F85Z
PART_NUM_CAU	7861203
PART_NUM_CAU	B6E
CUST_CONC_CD	825
COND_CD	1
RPR_DT	7/12/2001
TIS_WSD	2
CLM_KEY	2306821
MILGE	3825
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	B435
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	LA
CPSC_CD_6	12001
Radngs	
TECH_TXT1	REPLACED SEAT BELT LATCH.
TECH_TXT2	
CUST_TXT	FRT DRIVERS SEAT BELT COMES UNLATCHES
AREA_CD	337
COUNTRY_CD	USA
SLS_DLR_CD	123275
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	553
VIN_CD	1FMRU15WXX1L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/21/2000
WRTY_START_D	2/12/2001
NAME	BOWDEN FORD LINCOLN MERCURY CO
DOC_NUM	080453A
PH_NUM	6848641
WCC_CD	6F82
PART_NUM_CAU	1L7Z
PART_NUM_CAU	788-1202
PART_NUM_CAU	AAB
CUST_CONC_CD	625
COND_CD	42
RPR_DT	4/22/2002
TLS_WSD	16
CLM_KEY	8222478
MILGE	22732
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 835 of 1298

RQ04-011 E 2860

LBR_HRS	0.00000000
DLR_CD	4408
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	FOUND SEAT BELT BUCKLE NOT LATCHING REPLACE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER SAYS THE PASSENGER SEAT BELT WONT LOCK
AREA_CD	361
COUNTRY_CD	USA
SLS_DLR_CD	152088
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V08
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	556
VIN_CD	1FMRU16W91
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/28/2001
WRTY_START_D	10/19/2001
NAME	ALDUBON FORD
DOC_NUM	106048A
PH_NUM	2838900
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	T80
COND_CD	42
RPR_DT	10/22/2001
TIS_WSD	1
CLM_KEY	4725374
MILGE	372
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="6621"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="LA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value="C"/>
TECH_TXT1	<input type="text" value="372 RECALL 82 TESTED AND REPLACED BOTH FRONT SEATBELTS"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUST STATES WHILE DRIVING DRIVERS SEAT BELT CAME UNLATCHED BY ITSELF"/>
AREA_CD	<input type="text" value="Z23"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="123209"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="LBA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V74"/>
AWS_VL_CD	<input type="text" value="E3"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	658
VIN_CD	1FMRU15WB1L
LBR_COST	
VEH_LINE_CD	T/63
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VBR_SERIES_CD	T/EF
DRIVE_CD	T/8
ENG_CD	T/VN
TRANS_CD	T/UU
PLANT_CD	AP
PRODN_DT	8/27/2001
WRTY_START_D	7/23/2001
NAME	ALLAN VIGIL FORD
DOC_NUM	1828051
PH_NUM	4717801
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	12/31/2001
TIS_WSD	8
CLM_KEY	8008825
MILGE	16633
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="808"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="GA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="SEAT BELT BUCKLE INOP R&R PASS FRONT SEAT TO REPLACE SEAT BELT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES THAT RT FT SEATBELT WILL NOT LOCK IN BUCKLE"/>
AREA_CD	<input type="text" value="770"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121022"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	567
VIN_CD	1FMRUHEW91L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T8F
DRIVE_CD	T8
ENG_CD	T8N
TRANS_CD	T8U
PLANT_CD	AP
PRODN_DT	5/31/2001
WRTY_START_D	8/26/2001
NAME	AIRPORT MARINA FORD
DOC_NUM	24328001
PH_NUM	6483878
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	1
RFR_DT	10/4/2001
TIS_WSD	2
CLM_KEY	4180378
MILGE	1116
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	8.5
DLR_CD	5583
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACED BROKEN BUCKLE
TECH_TXT2	
CUST_TXT	OK DRIVERS SEAT BELT WONT LATCH. BUCKLE INOP
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	658
VIN_CD	1FMRJ15W91
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/M
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	8/29/2001
WRTY_START_D	8/17/2001
NAME	LAFAYETTE MOTOR SALES INC
DOC_NUM	9112751
PH_NUM	4240281
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7661202
PART_NUM_CAU	AAB
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	7/18/2001
TIS_WSD	0
CLM_KEY	2740023
MILGE	12
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="0.00"/>
DLR_CD	<input type="text" value="980"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NC"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value="b"/>
TECH_TXT1	<input type="text" value="DIAG AND REPLACED BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="PASS SEAT BELT WILL NOT HOLD"/>
AREA_CD	<input type="text" value="910"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121224"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	558
VIN_CD	1FMRU15W91
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	5/25/2001
WRTY_START_D	7/8/2001
NAME	PALM SPRINGS FORD
DOC_NUM	111621A
PH_NUM	3282102
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	8AB
CUST_CONC_CD	828
COND_CD	42
RPR_DT	6/28/2002
TIS_WSD	11
CLM_KEY	8947243
MILGE	17874
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	5574
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	TEST & REPLACE DRIVERS SEAT BELT BUCKLE FOR SEAT BELT LIN BUCKLES BY ITSELF CONCERN
TECH_TXT2	
CUST_TXT	DRIVER SIDE FRONT SEAT BELT BUCKLE, LIN BUCKLES ON ITS OWN WHILE DRIVING, DIAGNOSE AND REPORT.
AREA_CD	760
COUNTRY_CD	USA
SLS_DLR_CD	171480
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	@