

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 2 OF 6

BOOK 5 OF 43

| | |
|----------------------|---------------|
| MDL_YR | 2001 |
| SORT_INDEX | 581 |
| VIN_CD | 1FMRLL16W91L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T/WD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DX |
| PLANT_CD | AP |
| PRODN_DT | 5/17/2001 |
| WRTY_START_D | 10/2/2001 |
| NAME | MARCOONE FORD |
| DOC_NUM | 393480A |
| PH_NUM | 9727200 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7801208 |
| PART_NUM_CAU | BAB |
| CUST_CONC_CD | L20 |
| COND_CD | 42 |
| RPR_DT | 7/15/2001 |
| TIS_WSD | 0 |
| CLM_KEY | 2602362 |
| MILGE | 10 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | <input type="text" value="0.0"/> |
| DLR_CD | <input type="text" value="4820"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="FL"/> |
| CPSC_CD_6 | <input type="text" value="11001"/> |
| Ratings | <input type="text" value=""/> |
| TECH_TXT1 | <input type="text" value="CK AND REPLACED SEAT BELT"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="DRIVER SIDE SEAT BELT"/> |
| AREA_CD | <input type="text" value="954"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="124015"/> |
| TXN_CD | <input type="text" value="1"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V07"/> |
| AWS_VL_CD | <input type="text" value="E8"/> |
| VRT_CD | <input type="text" value="S08"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 582 |
| VIN_CD | 1FMRU15W811 |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| ROD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 5/15/2001 |
| WRTY_START_D | 8/2/2001 |
| NAME | GREENWAY FORD, INC. |
| DOC_NUM | 5883381 |
| PH_NUM | 2763200 |
| WCC_CD | DF02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881202 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 807 |
| COND_CD | 41 |
| RPR_DT | 8/18/2001 |
| TIS_WSD | 1 |
| CLM_KEY | 3089851 |
| MILGE | 241 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 849 of 1298

RQ04-011 E 2874

| | |
|-------------------|---|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="4822"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="FL"/> |
| CPSC_CD_6 | <input type="text" value="12001"/> |
| Ratings | <input type="text" value=""/> |
| TECH_TXT1 | <input type="text" value="BINDING REAR RIGHT OR LEFT SEAT BELT ASSEMBLY REPLACE"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="CUSTOMER STATES THAT THE PASS SEAT BELT WILL NOT LOCK INTO PLACE"/> |
| AREA_CD | <input type="text" value="407"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="124476"/> |
| TXN_CD | <input type="text" value="2"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V03"/> |
| AWS_VL_CD | <input type="text" value="B3"/> |
| VRT_CD | <input type="text" value="908"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|--------------|
| MDL_YR | 2001 |
| SORT_INDEX | 563 |
| VIN_CD | 1FMRU16W91L |
| LBR_COST | |
| VEH_LINE_CD | T/83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/8 |
| ENG_CD | T/VH |
| TRANS_CD | T/DL |
| PLANT_CD | AP |
| PRODN_DT | 5/11/2001 |
| WRTY_START_D | 8/14/2001 |
| NAME | PACIFIC FORD |
| DOC_NUM | 9876751 |
| PH_NUM | 8276130 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881202 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 340 |
| COND_CD | 42 |
| BPR_DT | 10/18/2001 |
| TIS_WSD | 3 |
| CLM_KEY | 4486248 |
| MILGE | 1172 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | |
| DLR_CD | 5412 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 12001 |
| Ratings | 0 |
| TECH_TXT1 | NA REMOVE AND REINSTALL SEAT,REMOVE AND REPLACE BUCKLE. |
| TECH_TXT2 | |
| CUST_TXT | INSTALL SPO # 01281014 CUSTOMER STATES PASSENGER SIDE SEAT BELT IS NOT WORKING . TECH # 110 PART #7881202 AAA USE SPO 01281014 |
| AREA_CD | 714 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171052 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 565 |
| VIN_CD | 1FMRU16W51 |
| LBR_COST | |
| VEH_LINE_CD | 7B3 |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TEF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 5/10/2001 |
| WRTY_START_D | 7/14/2001 |
| NAME | PASADENA FORD, INC. |
| DOC_NUM | 2940551 |
| PH_NUM | 9933873 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | S40 |
| COND_CD | 1 |
| RPR_DT | 7/20/2001 |
| TIS_WSD | 1 |
| CLM_KRY | 2681287 |
| MILGE | 744 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 8.4 |
| DLR_CD | 4223 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | 0 |
| TECH_TXT1 | REPLACED BELT DUE TO BEING BROKEN |
| TECH_TXT2 | |
| CUST_TXT | CUST STATES FRONT SEAT RIGHT OUTER BELT DOESNT LATCH |
| AREA_CD | 025 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171007 |
| TXN_CD | 2 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | B05 |
| TIS_FLAG | |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 584 |
| VIN_CD | 1FMRJ15W91 |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T/WD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/26/2001 |
| WRTY_START_D | 6/30/2001 |
| NAME | BAY AREA FORD, INC. |
| DOC_NUM | 6240861 |
| PH_NUM | 4865920 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | 8AB |
| CUST_CONC_CD | S25 |
| COND_CD | 42 |
| RPR_DT | 6/30/2002 |
| TIS_WSD | 13 |
| CLM_KEY | 9017202 |
| MILGE | 22747 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 855 of 1298

RQ04-011 E 2880

| | |
|-------------------|---|
| LRR_HRS | 0 |
| DLR_CD | 3048 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | c |
| TECH_TXT1 | INOP SEATBELT ASSEMBLY FRONT REPLACE |
| TECH_TXT2 | |
| CUST_TXT | DRIVERS SEAT BELT UNBUCKLES |
| AREA_CD | 281 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 162047 |
| TXN_CD | EB4 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | 0 |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 999 |
| VIN_CD | 1FMRU15W01L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/E |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 5/1/2001 |
| WRTY_START_D | 6/8/2001 |
| NAME | HALL FORD |
| DOC_NUM | 200917A |
| PH_NUM | 9885700 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | F85Z |
| PART_NUM_CAU | 7861203 |
| PART_NUM_CAU | BBE |
| CUST_CONC_CD | 940 |
| COND_CD | 42 |
| RPR_DT | 7/23/2001 |
| TIS_WSD | 2 |
| CLM_KEY | 2386009 |
| MILGE | 3365 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 05 |
| DLR_CD | 8542 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | VA |
| CPSC_CD_6 | 12001 |
| Ratings | d |
| TECH_TXT1 | 3888 INOP LATCH W VERIFY CONCERN, INSTALL DRIVERS SICE SEATBELT LATCH ASSEMBLY OK M TIME TO REPLACE PART, NO LABOR OP |
| TECH_TXT2 | |
| CUST_TXT | CUSTOMER STATES THAT THE DRIVERS FRT SEAT BELT COMES LOOSE CONTINUOUSLY WHILE DRIVING |
| AREA_CD | 757 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 127080 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 908 |
| TIS_FLAG | |

| | |
|----------------------|---------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 570 |
| VIN_CD | 1FMRU115W91 |
| LBR_COST | |
| VEH_LINE_CD | TB3 |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/19/2001 |
| WRTY_START_D | 7/8/2001 |
| NAME | WALKER FORD COMPANY, INC. |
| DOC_NUM | 7817501 |
| PH_NUM | 5353673 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | F85Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BBE |
| CUST_CONC_CD | 940 |
| COND_CD | 42 |
| RPR_DT | 7/23/2001 |
| YIS_WSD | 1 |
| CLM_KEY | 2445215 |
| MILGE | 1253 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 259 of 1298

RQ04-011 E 2884

| | |
|-------------------|---|
| LBR_HRS | 124 |
| DLR_CD | 4947 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | FL |
| CPSC_CD_6 | 12001 |
| Ratings | c |
| TECH_TXT1 | 42 TECH 14507 MO 1253 REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | 840 CUST STATES SEAT BELT POPS OPEN DRIVERS SIDE SOP PART IS IN UNDER NEIL HARVEY |
| AREA_CD | 727 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 124202 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 571 |
| VIN_CD | 1FMRJ15W81L |
| LRR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T/WD |
| VER_SERIES_CD | TEF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/11/2001 |
| WRTY_START_D | 7/14/2001 |
| NAME | DREW FORD |
| DOC_NUM | 6202662 |
| PH_NUM | 464777 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L72 |
| PART_NUM_CAU | |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 526 |
| COND_CD | 33 |
| RPR_DT | 6/7/2002 |
| TIS_WSD | 11 |
| CLM_KEY | 9070331 |
| MILGE | 9616 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 161 of 1298

RQ04-011 E 2886

| | |
|-------------------|---|
| LBR_HRS | GA |
| DLR_CD | 5488 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | INSPECTED AND FOUND PASS FRONT SEAT BELT BUCKLE FIT LOOSE REPLACE SEAT BELT VERIFY REPAIR |
| TECH_TXT2 | |
| CUST_TXT | PASSENGER FRONT SEAT BELT COMES UNLATCHED WHEN DRIVING 3 30 |
| AREA_CD | 619 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171080 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | 0 |

| | |
|----------------------|----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 573 |
| VIN_CD | 1FMRU15W911 |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWO |
| VER_SERIES_CD | TEF |
| DRIVE_CD | T/B |
| ENG_CD | TVN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 4/10/2001 |
| WRTY_START_D | 8/30/2001 |
| NAME | MCALLEY FORD-MERCURY |
| DOC_NUM | 788201 |
| PH_NUM | 8823341 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881202 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 828 |
| COND_CD | 42 |
| RPR_DT | 3/4/2002 |
| TIS_WSD | 7 |
| CLM_KEY | 7209785 |
| MILGE | 9421 |
| MTRL_COST | |
| TOY_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 608 |
| DLR_CD | 827 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 12001 |
| Ratings | 6 |
| TECH_TXT1 | VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED NEW BUCKLE & RE CK OK |
| TECH_TXT2 | |
| CUST_TXT | RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK |
| AREA_CD | 208 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 172514 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B9 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|-----------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 674 |
| VIN_CD | 1FMRU15W91L |
| LBR_COST | |
| VEH_LINE_CD | T8B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VEH_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 4/10/2001 |
| WRTY_START_D | 4/21/2001 |
| NAME | COVERT FORD OF TAYLOR, INC. |
| DOC_NUM | 672401 |
| PH_NUM | 3856000 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L72 |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | S40 |
| COND_CD | 42 |
| RPR_DT | 4/1/2002 |
| TIS_WSD | 12 |
| CLM_KEY | 7835008 |
| MILGE | 38807 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="3042"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="TX"/> |
| CPSC_CD_6 | <input type="text" value="13001"/> |
| Ratings | <input type="text" value="c"/> |
| TECH_TXT1 | <input type="text" value="REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="940 PER CUST. THE DRIVERS SEAT BELT COMES UNLATCHED. SEE HISTORY"/> |
| AREA_CD | <input type="text" value="512"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="162302"/> |
| TXN_CD | <input type="text" value="E81"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="B3"/> |
| VRT_CD | <input type="text" value="305"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 575 |
| VIN_CD | 1FMRU16W91L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T/WD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 4/8/2001 |
| WRTY_START_D | 8/29/2001 |
| NAME | DON SOHN FORD, INC. |
| DOC_NUM | 285208A |
| PH_NUM | 3477000 |
| WCC_CD | 8F02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7861203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | T90 |
| COND_CD | 42 |
| RPR_DT | 12/5/2001 |
| TIS_WSD | 7 |
| CLM_KEY | 5682285 |
| MILGE | 10518 |
| MYRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 167 of 1298

| | |
|-------------------|---|
| LRR_HRS | 85 |
| DLR_CD | 8682 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | LA |
| CPSC_CD_6 | 11001 |
| Ratings | b |
| TECH_TXT1 | 10521 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC:42 CASUAL PART 1L7Z 7851203 BAA |
| TECH_TXT2 | |
| CUST_TXT | TBD C S DRIVERS SEAT BELT WONT STAY LATCHED SOP |
| AREA_CD | 504 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 123009 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V74 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| IIS_FLAG | |

| | |
|----------------------|-------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 578 |
| VIN_CD | 1FMRU19W81L |
| LBR_COST | |
| VEH_LINK_CD | T53 |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T1EF |
| DRIVE_CD | T7E |
| ENG_CD | TVM |
| TRANS_CD | T7DU |
| PLANT_CD | AP |
| PRODN_DT | 4/1/2001 |
| WRTY_START_D | 4/16/2001 |
| NAME | CHARLIE THOMAS FORD INC |
| DOC_NUM | 128901B |
| PH_NUM | 3714000 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L72 |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | S2B |
| COND_CD | 42 |
| RPR_DT | 6/30/2002 |
| TIS_WSD | 14 |
| CLM_KEY | 8870786 |
| MILGE | 18880 |
| MTRL_COST | |
| TOT_COST_GROS | |

In cases where an investigation is initiated or your report relates to a current investigation, a copy of your report is provided to the manufacturer of the product being investigated. The Privacy Act prohibits our agency from providing your personal identifiers (name, mailing address, zip code, and complete vehicle identification number) to the manufacturer without your permission. Please mark the appropriate authorization box and sign the VOQ before returning it to the agency.

If you have access to a computer, you may obtain information about safety recalls, safety defect investigations, and other safety-related information by accessing NHTSA's Internet Web site at <http://www.nhtsa.dot.gov>.

If further assistance is needed, please contact Mr. Michael J. Jordan, Safety Defects Program Assistant, Correspondence Research Division, Office of Defects Investigation, at (202) 493-0576.

Sincerely,

A handwritten signature in black ink, appearing to read "Alberto A. Jimenez", with a horizontal line extending to the right. There is a small mark below the signature that looks like "A.A.J.".

Alberto A. Jimenez, Chief
Correspondence Research Division
Office of Defects Investigation
Enforcement

Enclosure

| | |
|----------------------|-----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 580 |
| VIN_CD | 1FMRU15W91L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWO |
| VER_SERIES_CD | TEF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 3/12/2001 |
| WRTY_START_D | 8/10/2001 |
| NAME | JARRETT-BODIFORD FORD |
| DOC_NUM | 8918101 |
| PH_NUM | 7524171 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7B81203 |
| PART_NUM_CAU | AAF |
| CUST_CONC_CD | S39 |
| COND_CD | 42 |
| RPR_DT | 8/20/2001 |
| TIS_WSD | 0 |
| CLM_KEY | 3574411 |
| MILGE | 3 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LRR_HRS | 000 |
| DLR_CD | 481 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | FL |
| CPSC_CD_6 | 11001 |
| Ratings | |
| TECH_TXT1 | IN SOME OF THE EFFECTED VEHICLES ITS POSSIBLE THAT THE DRIVERS AND OR THE PASSENGERS FRONT OUTBOARD SEAT BELT REPLACED BOTH LEFT AND RIGHT BUCKLE ASSEMBLIES PER RECALL |
| TECH_TXT2 | |
| CUST_TXT | VEHICLE EFFECTED BY SEAT BELT BUCKLE RETENSION SAFETY RECALL 01S21 CERTIAN MODEL YEAR CROWN VICTOR |
| AREA_CD | 813 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 124448 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B2 |
| VRT_CD | 000 |
| TIS_FLAG | |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 581 |
| VIN_CD | 1FMRU15W81 |
| LBR_COST | |
| VEH_LINE_CD | TBS |
| MKT_DERIVED | |
| BOD_CAR_STL | TWD |
| VER_SERIES_CD | TXF |
| DRIVE_CD | TB |
| ENG_CD | TVN |
| TRANS_CD | TDU |
| PLANT_CD | AP |
| PRODN_DT | 3/28/2001 |
| WRTY_START_D | 8/18/2001 |
| NAME | GWINNETT PLACE FORD |
| DOC_NUM | 10527501 |
| PH_NUM | 4782080 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | T90 |
| COND_CD | 42 |
| RPR_DT | 5/4/2002 |
| TIS_WSD | 8 |
| CLM_KEY | 8453350 |
| MILGE | 9293 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 04 |
| DLR_CD | 3573 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | GA |
| CPSC_CD_6 | 11001 |
| Ratings | 8 |
| TECH_TXT1 | IT WOULD WORK SOMETIMES THEN GET HUNG UP REPLACED SEAT BELT BUCKLE WITH NEW |
| TECH_TXT2 | |
| CUST_TXT | DRIVER SIDE SEAT BELT WON T LOCK |
| AREA_CD | 770 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 121025 |
| TXN_CD | 2 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V74 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 841 |
| VIN_CD | 1FMRU15W71L |
| LRR_COST | |
| VEH_LINE_CD | T/BS |
| MKT_DERIVED | |
| BOD_CAB_STL | T/WD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 7/16/2001 |
| WRTY_START_D | 8/27/2001 |
| NAME | LOU SOBH FORD, INC. |
| DOC_NUM | 9504661 |
| PH_NUM | 8334006 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | |
| PART_NUM_CAU | AAC |
| CUST_CONC_CD | 840 |
| COND_CD | 42 |
| RPR_DT | 8/7/2002 |
| TIS_WSD | 10 |
| CLM_KEY | 0087101 |
| MILGE | 10422 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 69 |
| DLR_CD | 4230 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | GA |
| CPSC_CD_6 | 11001 |
| Ratings | |
| TECH_TXT1 | INCP SEATBELT ASSEMBLY FRONT REPLACE |
| TECH_TXT2 | |
| CUST_TXT | PASS SIDE SEAT BELT BUCKLE TECH 128 |
| AREA_CD | 404 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 121008 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | @ |

| | |
|----------------------|---------------|
| MDL_YR | 2001 |
| SORT_INDEX | 642 |
| VIN_CD | 1FMRU1BW71L |
| LBR_COST | |
| VEH_LINE_CD | TBS |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TIEF |
| DRIVE_CD | TB |
| ENG_CD | TVN |
| TRANS_CD | TDU |
| PLANT_CD | AP |
| PRODN_DT | 5/28/2001 |
| WRTY_START_D | 8/25/2001 |
| NAME | CERRITOS FORD |
| DOC_NUM | 28478701 |
| PH_NUM | 9866664 |
| WCC_CD | SR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7981202 |
| PART_NUM_CAU | AAB |
| CUST_CONC_CD | 840 |
| COND_CD | 42 |
| RPR_DT | 7/28/2001 |
| TIS_WSD | 0 |
| CLM_KEY | 3524215 |
| MILGE | 0 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 08 |
| DLR_CD | 5401 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 12001 |
| Ratings | 8 |
| TECH_TXT1 | 01S21 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | PERFORM RECALL #01S21 |
| AREA_CD | 582 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171055 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | |

| | |
|----------------------|---------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 044 |
| VIN_CD | 1FMRU15W71L |
| LBR_COST | |
| VEH_LINE_CD | TB3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/M |
| TRANS_CD | T/U |
| PLANT_CD | AP |
| PRODN_DT | 4/23/2001 |
| WRTY_START_D | 5/16/2001 |
| NAME | CHAMPION FORD, INC. |
| DOC_NUM | 214208A |
| PH_NUM | 5802277 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7961208 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | B26 |
| COND_CD | 42 |
| RPR_DT | 8/21/2001 |
| TIS_WSD | 4 |
| CLM_KEY | 3184185 |
| MILGE | 3848 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 02 |
| DLR_CD | 4527 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | 3848 SEATBELTS PASSED 01821 TEST, CUSTOMER STATES DRIVERS SEATBELT BUCKLE WILL COME LOOSE AFTER DRIVING AWHILE, REPLACED DRIVERS SEATBELT BUCKLE FOR RECALL 01821 |
| TECH_TXT2 | |
| CUST_TXT | 825 DRIVERS SEAT BELT WILL NOT STAY BUCKLED (018217) |
| AREA_CD | 713 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 182048 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|---------------|
| MDL_YR | 2001 |
| SORT_INDEX | 645 |
| VIN_CD | 1FMRU15W71 |
| LBR_COST | |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TIEF |
| DRIVE_CD | T8 |
| ENG_CD | TMN |
| TRANS_CD | TDLJ |
| PLANT_CD | AP |
| PRODN_DT | 4/23/2001 |
| WRTY_START_D | 5/10/2001 |
| NAME | MARCOONE FORD |
| DOC_NUM | 534256A |
| PH_NUM | 0727200 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7001202 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 826 |
| COND_CD | 42 |
| RPR_DT | 4/28/2002 |
| TLS_WSD | 12 |
| CLM_KEY | 0320320 |
| MILGE | 9121 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 881 of 1298

RQ04-011 E 2906

| | |
|-------------------|---|
| LBR_HRS | 0 |
| DLR_CD | 4820 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | FL |
| CPSC_CD_6 | 12001 |
| Ratings | 6 |
| TECH_TXT1 | 9121 RECALL WIARR VERIFY PERFORM RECALL RR PASSENGER BELT RECHECK OK |
| TECH_TXT2 | |
| CUST_TXT | A89 SOP SEAT BELT IN PASSENGERS SIDE BUCKLE FOR RECALL |
| AREA_CD | 954 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 124015 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|-----------------|
| MDL_YR | 2001 |
| SORT_INDEX | 848 |
| VIN_CD | 1FMRUJ15W71L |
| LBR_COST | |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T8F |
| DRIVE_CD | T8 |
| ENG_CD | T8N |
| TRANS_CD | T8U |
| PLANT_CD | AP |
| PRODN_DT | 4/27/2001 |
| WRTY_START_D | 10/12/2001 |
| NAME | JACK ROACH FORD |
| DOC_NUM | 8646251 |
| PH_NUM | 5885000 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAB |
| CUST_CONC_CD | S40 |
| COND_CD | 41 |
| RPR_DT | 10/19/2001 |
| TIS_WSD | 1 |
| CLM_KEY | 4549858 |
| MILGE | 647 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 68 |
| DLR_CD | 4590 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | c |
| TECH_TXT1 | REPLACE LEFT FRT SEATBELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | OWNER STATES DRIVERS SEATBELT COMES UNLATCHED WHEN PULLED ON |
| AREA_CD | 281 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 152037 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | |

| | |
|----------------------|------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 647 |
| VIN_CD | 1FMRLJ5W71L [REDACTED] |
| LBR_COST | [REDACTED] |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TEF |
| DRIVE_CD | T8 |
| ENG_CD | T8N |
| TRANS_CD | T8J |
| PLANT_CD | AP |
| PRODN_DT | 4/20/2001 |
| WRTY_START_D | 5/23/2001 |
| NAME | TEAM FORD |
| DOC_NUM | 3088251 |
| PH_NUM | 3065100 |
| WCC_CD | 6F02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7851208 |
| PART_NUM_CAU | CAA |
| CUST_CONC_CD | 640 |
| COND_CD | 42 |
| RPR_DT | 7/17/2001 |
| IIS_WSD | 2 |
| CLM_KEY | 2721148 |
| MILGE | 1481 |
| MTRL_COST | [REDACTED] |
| TOT_COST_GROS | [REDACTED] |

| | |
|-------------------|---|
| LBK_HRS | 134 |
| DLR_CD | 3915 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | NV |
| CPSC_CD_6 | 11001 |
| Ratings | a |
| TECH_TXT1 | BAD SEAT BELT TONGUE AND ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE |
| TECH_TXT2 | |
| CUST_TXT | DRIVERS SEAT BELT DOESNT LATCH, INSTALL SOP PARTS USE SOP 01188002 |
| AREA_CD | 702 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171167 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|--------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 648 |
| VIN_CD | 1FMRU16W71L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| ROD_CAB_STL | T/WD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/23/2001 |
| WRTY_START_D | 5/18/2001 |
| NAME | FREEDOM FORD, INC. |
| DOC_NUM | 214801 |
| PH_NUM | 7972277 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7861208 |
| PART_NUM_CAU | BAB |
| CUST_CONC_CD | 840 |
| COND_CD | 42 |
| RPR_DT | 8/2/2001 |
| TIS_WSD | 3 |
| CLM_KEY | 2753821 |
| MILGE | 3017 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 04 |
| DLR_CD | 4807 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | FL |
| CPSC_CD_6 | 11001 |
| Radngs | 0 |
| TECH_TXT1 | VERIFY SEAT BELT INOP REPLACE DRIVERS SEAT BELT |
| TECH_TXT2 | |
| CUST_TXT | C & DRIVER SIDE SEAT BELT KEEPS COMING OUT OF GLIP SOP IS IN |
| AREA_CD | 727 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 124206 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 808 |
| TIS_FLAG | |

| | |
|----------------------|---------------|
| MDL_YR | 2001 |
| SORT_INDEX | 648 |
| VIN_CD | 1FMRL15W73L |
| LBR_COST | |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAR_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/W |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 4/19/2001 |
| WRTY_START_D | 9/20/2001 |
| NAME | MULLINAX FORD |
| DOC_NUM | 321323A |
| PH_NUM | 8887800 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | B40 |
| COND_CD | 42 |
| RPR_DT | 8/17/2001 |
| TIS_WSD | 2 |
| CLM_KEY | 3117058 |
| MILGE | 2413 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | |
| DLR_CD | 3073 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | FL |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | 2413 ERRATIC W 42 REMOVE RT AND LEFT FRONT SEATS AND REPLACE SEAT BELT BUCKLES ON BOTH SEATS,ERRATIC |
| TECH_TXT2 | |
| CUST_TXT | 840 DRIVERS SIDE SEAT BELT UNCLICKED OVER BUMP TWICE |
| AREA_CD | 407 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 124227 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | BS |
| VRT_CD | 805 |
| TIS_FLAG | |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 650 |
| VIN_CD | 1FMRL15W71L |
| LBR_COST | |
| VEH_LINE_CD | TBS3 |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TJF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/23/2001 |
| WRTY_START_D | 5/27/2001 |
| NAME | FULLER FORD |
| DOC_NUM | 180768A |
| PH_NUM | 8502500 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAC |
| CUST_CONC_CD | S40 |
| COND_CD | 42 |
| RPR_DT | 10/22/2001 |
| TIS_WSD | 5 |
| CLM_KEY | 4067945 |
| MILGE | 4256 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|-----------------------------------|
| LBR_HRS | 00 |
| DLR_CD | 9579 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | 0 |
| TECH_TXT1 | REPLACE DRIVERS SEAT BELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | INSTALL SOP FOR DRIVERS SEAT BELT |
| AREA_CD | 010 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171070 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S06 |
| TIS_FLAG | |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 852 |
| VIN_CD | 1FMRU15W71 |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 4/11/2001 |
| WRTY_START_D | 5/13/2001 |
| NAME | LEOVIO FORD |
| DOC_NUM | 1171751 |
| PH_NUM | 9277988 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881209 |
| PART_NUM_CAU | BAC |
| CUST_CONC_CD | S26 |
| COND_CD | 42 |
| RPR_DT | 5/14/2002 |
| TIS_WSD | 12 |
| CLM_KEY | 8871170 |
| MILGE | 33750 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 0.4 |
| DLR_CD | 5449 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | * |
| TECH_TXT1 | CUST STATE THE ELFT FRONT SEAT BELT BUCKLE WONT LATCH CAUSE: SEAT BELT CORRE: REPLACED LEFT FRONT SEAT BELT BUCKLE DEFECTED |
| TECH_TXT2 | APROX TIME: 0.4 HRS JOB STARTED 10.719.8 ON 05 15 02 |
| CUST_TXT | CUSTOMER STATES THE LEFT FRONT SEAT BELT BUCKLE WONT LATCH (GRAY) |
| AREA_CD | 692 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171058 |
| TXN_CD | EB4 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | B06 |
| TIS_FLAG | 9 |

| | |
|----------------------|------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 853 |
| VIN_CD | 1FMRU15W71L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TAWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 4/12/2001 |
| WRTY_START_D | 5/10/2001 |
| NAME | CELLA FORD. INC. |
| DOC_NUM | 077279A |
| PH_NUM | 0384011 |
| WCC_CD | 0R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7681203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | 825 |
| COND_CD | 41 |
| RPR_DT | 8/14/2001 |
| TIS_WSD | 4 |
| CLM_KEY | 3188245 |
| MILGE | 5638 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 0.0 |
| DLR_CD | 8879 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | NC |
| CPSC_CD_6 | 11001 |
| Ratings | 8 |
| TECH_TXT1 | REMOVED DRIVERS SIDE SEAT. R&R SEATBELT LATCH AND VERIFIED REPAIR. |
| TECH_TXT2 | |
| CUST_TXT | DRIVER SEATBELT INOP |
| AREA_CD | 282 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 121648 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | B08 |
| TIS_FLAG | |

| | |
|----------------------|-----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 664 |
| VIN_CD | 1FMRJ15W71L |
| LRR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 3/31/2001 |
| WRTY_START_D | 4/14/2001 |
| NAME | ASTRO LINCOLN-MERCURY |
| DOC_NUM | 014057A |
| PH_NUM | 864466 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7661293 |
| PART_NUM_CAU | AAG |
| CUST_CONC_CD | S26 |
| COND_CD | 42 |
| RPR_DT | 12/21/2001 |
| TIS_WSD | 9 |
| CLM_KEY | 6889650 |
| MILGE | 6344 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--------------------------------|
| LBR_HRS | 84 |
| DLR_CD | 10170 |
| DLR_SUB_CD | . |
| REGION_CD | NA |
| ST_PROV_CD | MS |
| CPSC_CD_6 | 11001 |
| Ratings | . |
| TECH_TXT1 | REPLACED DR FRT SEAT BELT ASSY |
| TECH_TXT2 | |
| CUST_TXT | LEFT SEAT BELT INDP PART IN |
| AREA_CD | 001 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 123947 |
| TXN_CD | 2 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | 90B |
| TIS_FLAG | |

| | |
|----------------------|----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 855 |
| VIN_CD | 1FMRJ16W71 |
| LBR_COST | |
| VEH_LINE_CD | T8S |
| MKT_DERIVED | * |
| ROD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/2/2001 |
| WRTY_START_D | 7/4/2001 |
| NAME | DON DAVIS FORD, INC. |
| DOC_NUM | 431388C |
| PH_NUM | 2814261 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7851208 |
| PART_NUM_CAU | BAB |
| CUST_CONC_CD | B40 |
| COND_CD | 33 |
| RPR_DT | 6/7/2002 |
| TIS_WSD | 12 |
| CLM_KEY | 9062617 |
| MILGE | 8400 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 899 of 1298

R004-011 E 2924

| | |
|-------------------|---|
| LBR_HRS | 2417 |
| DLR_CD | 2417 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | 9400 REPLACED DRIVERS SEAT BELT LATCH. *** QUALITY CONTROL BY JOHN MEDROW *** |
| TECH_TXT2 | |
| CUST_TXT | CHECK DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING CHECK OTHER SEAT BELTS FOR PROPER OPERATION |
| AREA_CD | 817 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 152016 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 900 |
| TIS_FLAG | @ |

| | |
|----------------------|------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 667 |
| VIN_CD | 1FMRU15W71L [REDACTED] |
| LBR_COST | [REDACTED] |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T8F |
| DRIVE_CD | T8 |
| ENG_CD | TMN |
| TRANS_CD | TIDJ |
| PLANT_CD | AP |
| PRODN_DT | 3/16/2001 |
| WRTY_START_D | 6/30/2001 |
| NAME | ATASCADERO FORD |
| DOC_NUM | 5063801 |
| PH_NUM | 4680484 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1LTZ |
| PART_NUM_CAU | 7861203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | B40 |
| COND_CD | 42 |
| RPR_DT | 7/11/2001 |
| TIS_WSD | 1 |
| CLM_KEY | 2348447 |
| MILGE | 516 |
| MTRL_COST | [REDACTED] |
| TOT_COST_GROS | [REDACTED] |

| | |
|-------------------|--|
| LBR_HRS | 0.4 |
| DLR_CD | 7848 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | b |
| TECH_TXT1 | REPLACE RECEIVER RECHECK OPERATION AND NOW OK. |
| TECH_TXT2 | |
| CUST_TXT | DRIVERS SIDE SEAT BELT RECEIVER WONT HOLD ALL THE TIME |
| AREA_CD | B05 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171472 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|---------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 650 |
| VIN_CD | 1FMRU16W71 |
| LBR_COST | |
| VEH_LINE_CD | T88 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/E |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 5/13/2001 |
| WRTY_START_D | 3/30/2001 |
| NAME | SAMES MOTOR COMPANY, INC. |
| DOC_NUM | 0488008 |
| PH_NUM | 7214700 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881208 |
| PART_NUM_CAU | CAB |
| CUST_CONC_CD | 825 |
| COND_CD | 42 |
| RPR_DT | 5/26/2002 |
| TIS_WSD | 16 |
| CLM_KEY | 8887183 |
| MILGE | 12829 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LRR_HRS | 03/20/04 10:00:00 |
| DLR_CD | 4488 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | 12831 SEAT BELT BUCKLE 42 WVR VERIFIED CUSTOMERS CONCERN AND FOUND SEAT BELT WOULD COME LOOSE WHEN BRAKING HARD. A REMOVED DRIVER SEAT, R/R SEAT BELT BUCKLE TEST DROVE VEHICLE AND FOUND SEAT BELT NO |
| TECH_TXT2 | T COMING LOOSE. |
| CUST_TXT | (825)CK. DRIVERS SIDE SEAT BELT COMES LOOSE. |
| AREA_CD | 969 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 152772 |
| TXN_CD | E84 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | Q |

| | |
|----------------------|-----------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 681 |
| VIN_CD | 1FMRU16W71 |
| LBR_COST | |
| VEH_LINE_CD | T/63 |
| MKT_DERIVED | |
| BOD_CAB_STL | T/WO |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 2/13/2001 |
| WRTY_START_D | 4/2/2001 |
| NAME | BILL ALEXANDER FORD L-M INC |
| DOC_NUM | 25194301 |
| PH_NUM | 3442200 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | S40 |
| COND_CD | 41 |
| RPR_DT | 1/10/2002 |
| TTS_WSD | 10 |
| CLM_KEY | 6272982 |
| MILGE | 4687 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="20443"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="AZ"/> |
| CPSC_CD_6 | <input type="text" value="11001"/> |
| Radngs | <input type="text" value=""/> |
| TECH_TXT1 | <input type="text" value="INSPECT LF BELT BUCKLE BINDING DOES NOT LATCH REPLACE, INSPECT LEFT REAR 2ND ROW SEAT BELT OPERATION FOUND BINDING, REPLACE SEAT BELT AND RETEST OK"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="C S DRIVER SEAT BELT BUCKLE INOP ALSO LEFT REAR SEAT BELT KEEPTS TIGHTING UP"/> |
| AREA_CD | <input type="text" value="928"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="171176"/> |
| TXN_CD | <input type="text" value="2"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="B3"/> |
| VRT_CD | <input type="text" value="808"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 656 |
| VIN_CD | 1FMRU16W71L |
| LBR_COST | |
| VEH_LINE_CD | T7B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWVO |
| VEH_SERIES_CD | T7EF |
| DRIVE_CD | T7B |
| ENG_CD | T7VH |
| TRANS_CD | T7JU |
| PLANT_CD | AP |
| PRODN_DT | 1/28/2001 |
| WRTY_START_D | 3/24/2001 |
| NAME | DON DAVIS FORD, INC. |
| DOC_NUM | 4259030 |
| PH_NUM | 2814281 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881202 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | S40 |
| COND_CD | 33 |
| RFR_DT | 4/25/2002 |
| TIS_WSD | 14 |
| CLM_KEY | 8276431 |
| MILGE | 18248 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 907 of 1298

RQ04-011 E 2832

| | |
|-------------------|--|
| LBR_HRS | 02:25 |
| DLR_CD | 2417 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 12001 |
| Ratings | a |
| TECH_TXT1 | 18246 LOOSE REPLACE LOOSE RF SEAT BELT BUCKEL |
| TECH_TXT2 | |
| CUST_TXT | PASSENGERS SIDE SEAT BELT BUCKLE WILL NOT LATCH AT TIMES |
| AREA_CD | 817 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 152001 |
| TXN_CD | E84 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | 308 |
| TIS_FLAG | |

| | |
|----------------------|----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 667 |
| VIN_CD | 1FMRU16W71L |
| LBR_COST | |
| VEH_LINE_CD | T/89 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T/WO |
| VKR_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 1/26/2001 |
| WRTY_START_D | 3/24/2001 |
| NAME | DON DAVIS FORD, INC. |
| DOC_NUM | 418258E |
| PH_NUM | 2814261 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L72 |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | 825 |
| COND_CD | 33 |
| RPR_DT | 2/21/2002 |
| TIS_WSD | 12 |
| CLM_KEY | 7074700 |
| MILGE | 18368 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 02 |
| DLR_CD | 2417 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | B |
| TECH_TXT1 | 18364 LOOSE REPLACE BOTH FRONT SEAT BELT BUCKLE'S LOOSE |
| TECH_TXT2 | |
| CUST_TXT | BOTH FRONT SEAT BELTS NOT BUCKLING INTERMITTENT PROBLEM |
| AREA_CD | 817 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 152001 |
| TXN_CD | E04 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B9 |
| VRT_CD | 80B |
| TIS_FLAG | |

| | |
|----------------------|----------------|
| MDL_YR | 2001 |
| SORT_INDEX | 668 |
| VIN_CD | 1FMRU16W71L |
| LBR_COST | |
| VEH_LINE_CD | TBS |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TRE |
| DRIVE_CD | TB |
| ENG_CD | TVN |
| TRANS_CD | TDU |
| PLANT_CD | AP |
| PRODN_DT | 1/28/2001 |
| WRTY_START_D | 4/6/2001 |
| NAME | FORD OF UPLAND |
| DOC_NUM | 177021A |
| PH_NUM | 9485555 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7961209 |
| PART_NUM_CAU | CAA |
| CUST_CONC_CD | S25 |
| COND_CD | 41 |
| RPR_DT | 7/18/2001 |
| TIS_WSD | 4 |
| CLM_KEY | 2536369 |
| MILGE | 6463 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 64 |
| DLR_CD | 5855 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | SREPLACE LEFT FRONT SEAT BELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | CHECK AND ADVISE ON DRIVERS SEAT BELT WILL COME UNLOCKED WHEN DRIVING SOP HERE |
| AREA_CD | 909 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171109 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 909 |
| TIS_FLAG | |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 009 |
| VIN_CD | 1FMRU15W71L |
| LRR_COST | |
| VEH_LINE_CD | TB3 |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SRRIES_CD | TEF |
| DRIVE_CD | TB |
| ENG_CD | TMN |
| TRANS_CD | TDU |
| PLANT_CD | AP |
| PRODN_DT | 12/20/2000 |
| WRTY_START_D | 2/19/2001 |
| NAME | CHASE FORD |
| DOC_NUM | 032403A |
| PH_NUM | 2318100 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7851203 |
| PART_NUM_CAU | CAB |
| CUST_CONC_CD | 840 |
| COND_CD | 42 |
| RPR_DT | 8/23/2001 |
| TIS_WSD | 7 |
| CLM_KEY | 3358124 |
| MILGE | 8818 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | 0.000 |
| DLR_CD | 3887 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | c |
| TECH_TXT1 | INSPECTED DR SEAT BELT REPLACED REMOVED LF FR D OOR FOUND BAD REGULATOR REPLACED MOTOR AND REGUL LATOR ASM WORKS OK |
| TECH_TXT2 | |
| CUST_TXT | CUSTOMER STATES DRIVERS SEAT BELT BUCKLE POPS IN AND OUT |
| AREA_CD | 530 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 172208 |
| TKN_CD | 2 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 908 |
| TTS_FLAG | |

| | |
|----------------------|-------------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 673 |
| VIN_CD | 1FMRU15W71L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAR_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 07222000 |
| WRTY_START_D | 11/30/2000 |
| NAME | ANDERSON FORD LINCOLN MERCURY |
| DOC_NUM | 053033A |
| PH_NUM | 3841700 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | |
| PART_NUM_CAU | AAG |
| CUST_CONC_CD | B26 |
| COND_CD | 42 |
| RPR_DT | 1/16/2002 |
| TIS_WSD | 14 |
| CLM_KEY | 0434420 |
| MILGE | 44758 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 915 of 1298

RQ04-011 E 2940

| | |
|-------------------|---|
| LRR_HRS | 04 |
| DLR_CD | 7118 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | NE |
| CPSC_CD_6 | 11001 |
| Ratings | a |
| TECH_TXT1 | 44788 REMOVE AND INSTALL SEATBELT ON PASSENGER SIDE |
| TECH_TXT2 | |
| CUST_TXT | RT FT SEATBELT WONT HOLD IN BUCKLE ASY |
| AREA_CD | 308 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 141078 |
| TXN_CD | E81 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|--------------|
| MDL_YR | 2001 |
| SORT_INDEX | 874 |
| VIN_CD | 1FMRU15W71 |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWO |
| VER_SERIES_CD | T&F |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 9/18/2000 |
| WRTY_START_D | 12/31/2000 |
| NAME | HAYWARD FORD |
| DOC_NUM | 38574501 |
| PH_NUM | 8811200 |
| WCC_CD | 8F02 |
| PART_NUM_CAU | 1LZ |
| PART_NUM_CAU | 78812D2 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 525 |
| COND_CD | 42 |
| RPR_DT | 10/30/2001 |
| TIS_WSD | 11 |
| CLM_KEY | 4882246 |
| MILGE | 12712 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 917 of 1296

RQ04-011 E 2942

| | |
|-------------------|---|
| LBR_HRS | 24 |
| DLR_CD | 7729 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 12001 |
| Ratings | * |
| TECH_TXT1 | REPLACE SEAT BELT |
| TECH_TXT2 | |
| CUST_TXT | CUSTOMER STATES RIGHT FRONT SEAT BELT IN OF REPORT |
| AREA_CD | 610 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 172013 |
| TXN_CD | E84 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|-------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 876 |
| VIN_CD | 1FMRU15W61L |
| LBR_COST | |
| VEH_LINE_CD | 763 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SRRIES_CD | T/EP |
| DRIVE_CD | T/B |
| ENG_CD | T/M |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 7/17/2001 |
| WRTY_START_D | 7/27/2001 |
| NAME | SUNSET FORD, INC. |
| DOC_NUM | 136800A |
| PH_NUM | 9775885 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7001203 |
| PART_NUM_CAU | BAC |
| CUST_CONC_CD | S28 |
| COND_CD | 42 |
| RPR_DT | 3/20/2002 |
| TIS_WSD | 8 |
| CLM_KEY | 7688172 |
| MILGE | 15865 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 9.4 |
| DLR_CD | 20328 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | AZ |
| CPSC_CD_6 | 11001 |
| Ratings | a |
| TECH_TXT1 | R AND R DRIVERS SEAT FOR ACCESS, REPLACE BELT BUCKLE WONT LATCH |
| TECH_TXT2 | |
| CUST_TXT | DRIVERS SEATBELT IS INOP |
| AREA_CD | 802 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171176 |
| TXN_CD | ES4 |
| CNTRY SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 576 |
| VIN_CD | 1FMRU15W81L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | |
| BOD_CAB_STL | TMD |
| VER_SERIES_CD | T/E |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 7/19/2001 |
| WRTY_START_D | 8/24/2001 |
| NAME | MEL CLAYTON FORD |
| DOC_NUM | 9309851 |
| PH_NUM | 8822444 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 540 |
| COND_CD | 41 |
| RPR_DT | 9/11/2002 |
| TIS_WSD | 7 |
| CLM_KEY | 7344143 |
| MILGE | 6622 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 06 |
| DLR_CD | 3445 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | 8 |
| TECH_TXT1 | RIGHT FRONT SEAT BELT BUCKLE INOPSEATBELT ASSEMBLY FRONT REPLACE |
| TECH_TXT2 | |
| CUST_TXT | CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT WILL NOT LATCH CHECK AND ADVISE |
| AREA_CD | 805 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171461 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|--------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 877 |
| VIN_CD | 1FMRU15W81 |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | |
| BOD_CAB_STL | TAND |
| VER_SERIES_CD | TEF |
| DRIVE_CD | T/B |
| ENG_CD | T/MN |
| TRANS_CD | T/RL |
| PLANT_CD | AP |
| PRODN_DT | 8/13/2001 |
| WRTY_START_D | 9/3/2001 |
| NAME | HOLMES TUTTLE FORD |
| DOC_NUM | 23882201 |
| PH_NUM | 2823800 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | 8AA |
| CUST_CONC_CD | 840 |
| COND_CD | 42 |
| RPR_DT | 7/19/2001 |
| TIS_WSD | 0 |
| CLM_KEY | 3585888 |
| MILGE | 5 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 03 |
| DLR_CD | 20357 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | AZ |
| CPSC_CD_6 | 11001 |
| Ratings | " |
| TECH_TXT1 | 1 REPLACE BELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION |
| AREA_CD | 820 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171204 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 908 |
| TIS_FLAG | |

| | |
|----------------------|-----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 678 |
| VIN_CD | 1FMRU18W81 |
| LBR_COST | |
| VEH_LINE_CD | TBS |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TIEF |
| DRIVE_CD | TB |
| ENG_CD | TVN |
| TRANS_CD | TDU |
| PLANT_CD | AP |
| PRODN_DT | 6/8/2001 |
| WRTY_START_D | 6/10/2001 |
| NAME | CROSSROADS FORD, INC. |
| DOC_NUM | 22404801 |
| PH_NUM | 4871561 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881202 |
| PART_NUM_CAU | MAB |
| CUST_CONC_CD | S40 |
| COND_CD | 42 |
| RPR_DT | 6/8/2001 |
| TIS_WSD | 0 |
| CLM_KEY | 3175285 |
| MILGE | 10 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 925 of 1298

RQ04-011 E 2950

| | |
|-------------------|---------------------|
| LBR_HRS | 98 |
| DLR_CD | 000 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | NC |
| CPSC_CD_6 | 12001 |
| Ratings | * |
| TECH_TXT1 | REPLACE SEAT BELT |
| TECH_TXT2 | |
| CUST_TXT | SEAT BELT DEFECTIVE |
| AREA_CD | 919 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 121026 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | 800 |
| TIS_FLAG | |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 880 |
| VIN_CD | 1FMFU15W81L |
| LBR_COST | |
| VEH_LINE_CD | TAS3 |
| MKT_DERIVED | * |
| BOD_CAR_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | TVN |
| TRANS_CD | T/DJ |
| PLANT_CD | AP |
| PRODN_DT | 5/30/2001 |
| WRTY_START_D | 8/17/2001 |
| NAME | GALPIN FORD |
| DOC_NUM | 8413931 |
| PH_NUM | 7873800 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAC |
| CUST_CONC_CD | 840 |
| COND_CD | 42 |
| RPR_DT | 5/6/2002 |
| TIS_WSD | 11 |
| CLM_KEY | 8821835 |
| MILGE | 15294 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|---|
| LBR_HRS | |
| DLR_CD | 5538 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | CA |
| CPSC_CD_6 | 11001 |
| Ratings | d |
| TECH_TXT1 | GCK31 INTALLED NEW BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | CUST STATES LT FRONT SEAT BELT COMES UN DONE WHILE DRIVING |
| AREA_CD | 518 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 171072 |
| TXN_CD | E84 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | B08 |
| TIS_FLAG | |

| | |
|----------------------|------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 561 |
| VIN_CD | 1FMRU15W81U [REDACTED] |
| LBR_COST | [REDACTED] |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T/WD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 5/31/2001 |
| WRTY_START_D | 7/28/2001 |
| NAME | CAVALIER FORD |
| DOC_NUM | 7E2405B |
| PH_NUM | 4241111 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7851202 |
| PART_NUM_CAU | AAB |
| CUST_CONC_CD | S25 |
| COND_CD | 41 |
| RPR_DT | 8/11/2002 |
| TYS_WSD | 10 |
| CLM_KEY | 0873078 |
| MILGE | 22182 |
| MTRL_COST | [REDACTED] |
| TOT_COST_GROS | [REDACTED] |

| | |
|-------------------|--|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="8838"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="VA"/> |
| CPSC_CD_6 | <input type="text" value="12001"/> |
| Ratings | <input type="text" value="8"/> |
| TECH_TXT1 | <input type="text" value="INSPECT ACCESS SEAT ADM REPLACE SEAT BELT"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="CUST STATES RT FRT SEAT BELT DOESNT BUCKLE INTERMITTANTLY"/> |
| AREA_CD | <input type="text" value="767"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="127061"/> |
| TXN_CD | <input type="text" value="E84"/> |
| CNTRY SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="E3"/> |
| VRI_CD | <input type="text" value="S08"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|---------------|
| MDL_YR | 2001 |
| SORT_INDEX | 882 |
| VIN_CD | 1FMRU15W81L |
| LBR_COST | |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T8F |
| DRIVE_CD | T8 |
| ENG_CD | TVN |
| TRANS_CD | T8J |
| PLANT_CD | AP |
| PRODN_DT | 5/25/2001 |
| WRTY_START_D | 7/29/2001 |
| NAME | DON KOTT FORD |
| DOC_NUM | 8423381 |
| PH_NUM | 8162500 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | B40 |
| COND_CD | 42 |
| RPR_DT | 5/13/2002 |
| TIS_WSD | 10 |
| CLM_KEY | 8847716 |
| MILGE | 18208 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="5699"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="CA"/> |
| CPSC_CD_6 | <input type="text" value="11001"/> |
| Ratings | <input type="text" value="0"/> |
| TECH_TXT1 | <input type="text" value="CK SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="CUST STATES DRIVERS SIDE SEAT BELT INOP WATER"/> |
| AREA_CD | <input type="text" value="310"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="171059"/> |
| TXN_CD | <input type="text" value="E84"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="B3"/> |
| VRT_CD | <input type="text" value="B08"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|----------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 086 |
| VIN_CD | 1FMRU15W61L |
| LBR_COST | |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T1F |
| DRIVE_CD | T/B |
| ENG_CD | T/M |
| TRANS_CD | T/D |
| PLANT_CD | AP |
| PRODN_DT | 3/8/2001 |
| WRTY_START_D | 6/4/2001 |
| NAME | SLOAN FORD LINCOLN-MERCURY |
| DOC_NUM | 3882102 |
| PH_NUM | 3882463 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7981202 |
| PART_NUM_CAU | AAC |
| CUST_CONC_CD | 826 |
| COND_CD | 42 |
| RPR_DT | 12/17/2001 |
| TIS_WSD | 7 |
| CLM_KEY | 6786160 |
| MILGE | 20876 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 0.4 |
| DLR_CD | 6738 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | TN |
| CPSC_CD_6 | 12001 |
| Ratings | a |
| TECH_TXT1 | REPLACED SEAT BELT |
| TECH_TXT2 | |
| CUST_TXT | CUST STATES FRONT SIDE PASSENGER SEAT BELT WILL NOT LATCH |
| AREA_CD | B31 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 123078 |
| TXN_CD | E84 |
| CNTRY_SOLD | USA |
| QRT_CD | C21 |
| VFG_CD | V05 |
| AWS_VL_CD | B8 |
| VRT_CD | S08 |
| TIS_FLAG | |

| | |
|----------------------|-------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 687 |
| VIN_CD | 1FMRL16W61 |
| LBR_COST | |
| VKH_LINE_CD | T68 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T6F |
| DRIVE_CD | T6 |
| ENG_CD | T6N |
| TRANS_CD | T6U |
| PLANT_CD | AP |
| PRODN_DT | 5/22/2001 |
| WRTY_START_D | 6/28/2001 |
| NAME | KENSEL FORD, INC. |
| DOC_NUM | 128838A |
| PH_NUM | 6308811 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | BAC |
| CUST_CONC_CD | S26 |
| COND_CD | 42 |
| RPR_DT | 5/23/2002 |
| TIS_WSD | 12 |
| CLM_KEY | 8773035 |
| MILGE | 10376 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 935 of 1298

RQ04-011 E 2960

| | |
|-------------------|--|
| LRR_HRS | |
| DLR_CD | 4413 |
| DLR_SUB_CD | |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 11001 |
| Ratings | c |
| TECH_TXT1 | REPLACE LEFT FRT SEATBELT |
| TECH_TXT2 | |
| CUST_TXT | CLIST STATES SEAT BELT DRIVERS SIDE WILL COME LOOSE |
| AREA_CD | 408 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 162764 |
| TXN_CD | 2 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V06 |
| AWS_VL_CD | B3 |
| VRT_CD | 308 |
| TIS_FLAG | 0 |

| | |
|----------------------|--------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 881 |
| VIN_CD | 1FMRU15W61 |
| LBR_COST | |
| VEH_LINE_CD | T83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/M |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 5/2/2001 |
| WRTY_START_D | 7/19/2001 |
| NAME | SKYLINE FORD SALES, INC. |
| DOC_NUM | 108312A |
| PH_NUM | 3274500 |
| WCC_CD | 8R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7981202 |
| PART_NUM_CAU | AAA |
| CUST_CONC_CD | 825 |
| COND_CD | 41 |
| RPR_DT | 10/1/2001 |
| TIS_WSD | 3 |
| CLM_KEY | 4100974 |
| MILGE | 8478 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 84 |
| DLR_CD | 543 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | TX |
| CPSC_CD_6 | 12001 |
| Ratings | 8 |
| TECH_TXT1 | |
| TECH_TXT2 | |
| CUST_TXT | 540' CUST STATES FRONT PASS BUCKLE WILL NOT LATCH...(SOP HERE) |
| AREA_CD | 214 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 162003 |
| TXN_CD | 1 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V05 |
| AWS_VL_CD | B3 |
| VRT_CD | B08 |
| TIS_FLAG | |

| | |
|----------------------|--------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 692 |
| VIN_CD | 1FMRU15W61L |
| LBR_COST | |
| VEH_LINE_CD | T/B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/VN |
| TRANS_CD | T/OU |
| PLANT_CD | AP |
| PRODN_DT | 4/20/2001 |
| WRTY_START_D | 7/4/2001 |
| NAME | FREEDOM FORD, INC. |
| DOC_NUM | 1698002 |
| PH_NUM | 7972277 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881203 |
| PART_NUM_CAU | 8AB |
| CUST_CONC_CD | S16 |
| COND_CD | 42 |
| RPR_DT | 1/19/2002 |
| TIS_WSD | 7 |
| CLM_KEY | 6972057 |
| MILGE | 14414 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | 53 |
| DLR_CD | 4807 |
| DLR_SUB_CD | * |
| REGION_CD | NA |
| ST_PROV_CD | FL |
| CPSC_CD_6 | 11001 |
| Ratings | G |
| TECH_TXT1 | REPLACED SEAT BELT BUCKLE |
| TECH_TXT2 | |
| CUST_TXT | C S DRIVERS SIDE SEAT BELT COMES UN FASTENED AT TIMES |
| AREA_CD | 727 |
| COUNTRY_CD | USA |
| SLS_DLR_CD | 124206 |
| TXN_CD | EM4 |
| CNTRY_SOLD | USA |
| QRT_CD | Q21 |
| VFG_CD | V03 |
| AWS_VL_CD | B3 |
| VRT_CD | 800 |
| TIS_FLAG | |

| | |
|----------------------|------------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 093 |
| VIN_CD | 1FMRU15W81U [REDACTED] |
| LBR_COST | [REDACTED] |
| VEH_LINE_CD | T7B3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | T7ND |
| VER_SERIES_CD | T7EF |
| DRIVE_CD | T7B |
| ENG_CD | T7VN |
| TRANS_CD | T7DU |
| PLANT_CD | AP |
| PRODN_DT | 4/21/2001 |
| WRKY_START_D | 7/4/2001 |
| NAME | HARRELSON FORD, INC. |
| DOC_NUM | 4044551 |
| PH_NUM | 6522780 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7881208 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | 826 |
| COND_CD | 42 |
| RPR_DT | 10/10/2001 |
| TIS_WSD | 4 |
| CLM_KEY | 4304342 |
| MILGE | 1473 |
| MTRL_COST | [REDACTED] |
| TOT_COST_GROS | [REDACTED] |

| | |
|-------------------|--|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="1071"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="NC"/> |
| CPSC_CD_6 | <input type="text" value="11001"/> |
| Ratings | <input type="text" value="a"/> |
| TECH_TXT1 | <input type="text" value="BUCKLE ASSEMBLY MALFUNCTION SEATBELT ASSEMBLY FRONT REPLACE"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="LEFT FT SEAT BELT COMES UN CLASP SOP PARTS"/> |
| AREA_CD | <input type="text" value="704"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="121213"/> |
| TXN_CD | <input type="text" value="1"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="021"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="B3"/> |
| VRT_CD | <input type="text" value="505"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|----------------------|
| MDL_YR | 2001 |
| SORT_INDEX | 894 |
| VIN_CD | 1FMRL15W811 |
| LBR_COST | |
| VEH_LINE_CD | T/83 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | T/EF |
| DRIVE_CD | T/B |
| ENG_CD | T/M |
| TRANS_CD | T/DU |
| PLANT_CD | AP |
| PRODN_DT | 4/20/2001 |
| WRTY_START_D | 8/23/2001 |
| NAME | HARRELSON FORD, INC. |
| DOC_NUM | 5847251 |
| PH_NUM | 5822760 |
| WCC_CD | GR02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7981208 |
| PART_NUM_CAU | BAB |
| CUST_CONC_CD | 825 |
| COND_CD | 42 |
| RPR_DT | 4/20/2002 |
| TIS_WSD | 11 |
| CLM_KEY | 8151223 |
| MILGE | 12156 |
| MTRL_COST | |
| TOT_COST_GROS | |

| | |
|-------------------|--|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="1071"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="NC"/> |
| CPSC_CD_6 | <input type="text" value="11001"/> |
| Ratings | <input type="text" value=""/> |
| TECH_TXT1 | <input type="text" value="SEAT BELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="LEFT FT SEAT BELT SEAT BELT COMES UNBUCKLED FOR NO REASON"/> |
| AREA_CD | <input type="text" value="704"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="121219"/> |
| TXN_CD | <input type="text" value="E84"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="B3"/> |
| VRT_CD | <input type="text" value="S08"/> |
| TIS_FLAG | <input type="text" value=""/> |

| | |
|----------------------|-------------|
| MDL_YR | 2001 |
| SORT_INDEX | 606 |
| VIN_CD | 1FMRU15W61L |
| LBR_COST | |
| VEH_LINE_CD | TB3 |
| MKT_DERIVED | * |
| BOD_CAB_STL | TWO |
| VER_SERIES_CD | TIEF |
| DRIVE_CD | TB |
| ENG_CD | TVN |
| TRANS_CD | TQU |
| PLANT_CD | AP |
| PRODN_DT | 4/20/2001 |
| WRTY_START_D | 6/23/2001 |
| NAME | TEXAN FORD |
| DOC_NUM | 22348802 |
| PH_NUM | 4873873 |
| WCC_CD | BR02 |
| PART_NUM_CAU | 1LTZ |
| PART_NUM_CAU | 7861203 |
| PART_NUM_CAU | BAA |
| CUST_CONC_CD | B40 |
| COND_CD | 1 |
| RPR_DT | 6/3/2002 |
| TIS_WSD | 13 |
| CLM_KEY | 9016340 |
| MILGE | 28788 |
| MTRL_COST | |
| TOT_COST_GROS | |

Tuesday, December 14, 2004

Page 945 of 1298

RQ04-011 E 2970

| | |
|-------------------|---|
| LBR_HRS | <input type="text" value=""/> |
| DLR_CD | <input type="text" value="248B"/> |
| DLR_SUB_CD | <input type="text" value=""/> |
| REGION_CD | <input type="text" value="NA"/> |
| ST_PROV_CD | <input type="text" value="TX"/> |
| CPSC_CD_6 | <input type="text" value="11001"/> |
| Ratings | <input type="text" value="d"/> |
| TECH_TXT1 | <input type="text" value="ERRACTIC OPERATION (33) ACCESS LF SEAT & REPLACE SEATBELT BUCKLE, TK6562"/> |
| TECH_TXT2 | <input type="text" value=""/> |
| CUST_TXT | <input type="text" value="CHK FOR D SEATBELT COMING UNLATCHED WHILE DRIVING."/> |
| AREA_CD | <input type="text" value="817"/> |
| COUNTRY_CD | <input type="text" value="USA"/> |
| SLS_DLR_CD | <input type="text" value="152013"/> |
| TXN_CD | <input type="text" value="E84"/> |
| CNTRY_SOLD | <input type="text" value="USA"/> |
| QRT_CD | <input type="text" value="Q21"/> |
| VFG_CD | <input type="text" value="V05"/> |
| AWS_VL_CD | <input type="text" value="88"/> |
| VRT_CD | <input type="text" value="308"/> |
| TIS_FLAG | <input type="text" value="0"/> |

| | |
|----------------------|----------------|
| MDL_YR | 2001 |
| SORT_INDEX | 696 |
| VIN_CD | 1FMRU15W61 |
| LBR_COST | |
| VEH_LINE_CD | TBS |
| MKT_DERIVED | |
| BOD_CAB_STL | TWD |
| VER_SERIES_CD | TEF |
| DRIVE_CD | TB |
| ENG_CD | TAN |
| TRANS_CD | TDU |
| PLANT_CD | AP |
| PRODN_DT | 4/17/2001 |
| WRTY_START_D | 7/31/2001 |
| NAME | NORTHSIDE FORD |
| DOC_NUM | 31645202 |
| PH_NUM | 5258800 |
| WCC_CD | 6R02 |
| PART_NUM_CAU | 1L7Z |
| PART_NUM_CAU | 7861203 |
| PART_NUM_CAU | BAB |
| CUST_CONC_CD | 940 |
| COND_CD | 1 |
| RPR_DT | 8/8/2001 |
| TIS_WSD | 1 |
| CLM_KEY | 9024984 |
| MILGE | 435 |
| MTRL_COST | |
| TOT_COST_GROS | |