

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 3 OF 6

BOOK 5 OF 43

LBR_HRS	04
DLR_CD	4410
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	BROKEN VERIFY CUSTOMER CONCERN. REMOVE AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	840 CUST STATE CK LEFT FT SEAT BELT WILL NOT LATCH
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	152204
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	H3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	687
VIN_CD	1FMRUJ15W811
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	7/4/2001
NAME	TOWN EAST FORD
DOC_NUM	760056A
PH_NUM	2708441
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7661209
PART_NUM_CAU	CAB
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	7/7/2001
TIS_WSD	1
CLM_KEY	2326169
MILGR	250
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	1
DLR_CD	6192
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	250 TIME TO REPLACE DRIVERS SIDE FRONT FEMALE END OF SEAT BELT ASSEMBLY TIME TO R AND 1 SEAT ASSEMBLY TO GAIN ACCESS
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT WILL NOT STAY LATCHED AT TIMES, ALSO COMES LOOSE AT TIMES WHILE DRIVING, ADVIS
AREA_CD	872
COUNTRY_CD	USA
SLS_DLR_CD	152002
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	990
VIN_CD	1FMFU15W81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TAND
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/MN
TRANS_CD	T/DLJ
PLANT_CD	AP
PRODN_DT	4/24/2001
WRTY_START_D	10/8/2001
NAME	NICHOLS FORD
DOC_NUM	22471102
PH_NUM	6359673
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	3/25/2002
TIS_WSD	8
CLM_KEY	7825173
MILGE	13847
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	05
DLR_CD	2511
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	1 REPLACED L F SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	840 CUST STATES LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIME POPS OUT WHILE DRIVING
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	162009
TXN_CD	EM4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	008
VIN_CD	1FMRU15W81L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T8
ENG_CD	T/VN
TRANS_CD	T8J
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	8/29/2001
NAME	GULLO FORD-MERCURY OF CONROE
DOC_NUM	374077A
PH_NUM	7887781
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	9/20/2001
TIS_WSD	0
CLM_KEY	4109638
MILGE	88
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	88
DLR_CD	1472
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	88 016210 D.B REPL D SIDE SEAT BELT
TECH_TXT2	
CUST_TXT	CK SEATBELT WONT LATCH
AREA_CD	835
COUNTRY_CD	USA
SLS_DLR_CD	162168
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
ITS_FLAG	

MDL_YR	2001
SORT_INDEX	700
VIN_CD	1FMRU16WS1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	5/28/2001
NAME	MAGNUSSEN'S FREMONT FORD
DOC_NUM	342880A
PH_NUM	8515000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AA
CUST_CONC_CD	328
COND_CD	7
RPR_DT	3/19/2002
TYS_WSD	10
CLM_KEY	7552704
MILGE	15411
MYRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	7277
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	16411 SERVICE REPLACE THE SEAT BELT BUCKLE CAR HAS DAMAGE TO THE LEFT FRONT FENDER BWO
TECH_TXT2	
CUST_TXT	INSTALL BOP SEAT BELTS.
AREA_CD	610
COUNTRY_CD	USA
SLS_DLR_CD	171007
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	701
VIN_CD	1FMRU16W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/W3
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/WN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	5/27/2001
NAME	CLAREMONT FORD
DOC_NUM	10421001
PH_NUM	0251500
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	8/11/2001
TIS_WSD	4
CLM_KEY	3740810
MILGE	2886
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="04"/>
DLR_CD	<input type="text" value="1781"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="DEFECTIVE BUCKLE, REPLACED SEATBELT BUCKLE CC42"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value=""/>
AREA_CD	<input type="text" value="000"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171007"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VET_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	704
VIN_CD	1FMRJ15W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/3/2001
WRTY_START_D	4/12/2001
NAME	PEYTON CRAMER FORD
DOC_NUM	6224660
PH_NUM	7844700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BA8
CUST_CONC_CD	340
COND_CD	42
RPR_DT	1/17/2002
TIS_WSD	10
CLM_KEY	0374584
MILGE	11582
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	0.5
DLR_CD	5524
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACE INOP SEATBELT INSTALLED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	INSTALL SOP HERE FOR SEATBELT
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171015
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	707
VIN_CD	1FMRU15W81L
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/MN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/13/2001
WPTY_START_D	4/13/2001
NAME	ADVANTAGE FORD OF STUART
DOC_NUM	413555A
PH_NUM	2870055
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	41
RPR_DT	9/25/2001
TIS_WSD	6
CLM_KEY	4345734
MILGE	7107
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	4838
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	12001
Ratings	B
TECH_TXT1	7108 R&R SEAT AND SEAT BUCKLE
TECH_TXT2	
CUST_TXT	840 CUST STATES PABS SEAT BELT DOES NOT LATCH EVERY TIME
AREA_CD	581
COUNTRY_CD	USA
SLS_DLR_CD	124224
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRI_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	700
VIN_CD	1FMRLJ15W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	1/31/2001
WRTY_START_D	3/6/2001
NAME	SAM GALLOWAY FORD, INC.
DOC_NUM	59544501
PH_NUM	9393673
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BA8
CUST_CONC_CD	540
COND_CD	89
RPR_DT	10/28/2001
TES_WSD	8
CLM_KEY	4720818
MILGE	7448
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 963 of 1298

RQ04-011 E 2988

LBR_HRS	1
DLR_CD	4845
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	7851202 CODE 68 7448 M O R I BOTH FRONT BUCKET SEATS REPLACED BOTH FRONT SEATBELTS. RETEST PASS.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEAT BELT KEEPS COMING UNLATCHED PLS RECHECK PASSENGERS AS WELL.
ARRA_CD	941
COUNTRY_CD	USA
SLS_DLR_CD	124460
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	806
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	712
VIN_CD	1FMRUJ15W31E [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/53
MKT_DERIVED	*
BOD_CAB_STL	T/WJ
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/29/2001
WRTY_START_D	2/19/2001
NAME	MCGARITY-CARTER FORD L-M
DOC_NUM	10223901
PH_NUM	2872513
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861208
PART_NUM_CAU	BAA
CUST_CONC_CD	640
COND_CD	42
RPR_DT	4/8/2002
TIS_WSD	14
CLM_KEY	8115523
MILGE	28480
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="349"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="GA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="0"/>
TECH_TXT1	<input type="text" value="TEST AND REPLACED SEAT BELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value=""/>
AREA_CD	<input type="text" value="770"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121480"/>
TXN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="B08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	713
VIN_CD	1FMRU15W81
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	12/6/2000
WRTY_START_D	2/3/2001
NAME	ALAN VESTER FORD LINCOLN- MERC
DOC_NUM	7458401
PH_NUM	5872011
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7061203
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	4/16/2002
TIS_WSD	15
CLM_KEY	8212510
MILGE	16661
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	385
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	•
TECH_TXT1	REPLACED DRIVERS SIDE SEATBELT
TECH_TXT2	
CUST_TXT	INSTALL SEATBELTS
AREA_CD	262
COUNTRY_CD	USA
SLS_DLR_CD	121010
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	714
VIN_CD	1FMRU15W81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/24/2000
WRTY_START_D	11/9/2000
NAME	ATASCADERO FORD
DOC_NUM	5535401
PH_NUM	4553454
WCC_CD	B/R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	B25
COND_CD	42
RPR_DT	1/19/2002
TIS_WSD	15
CLM_KEY	5551157
MILGE	31110
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	7848
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPLACED SEATBELT BUCKLE AND NOW OK.
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEATBUCKLE WONT LATCH. SOP
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	171261
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	715
VIN_CD	1FMRLJ15W61L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/22/2000
WRTY_START_D	1/18/2001
NAME	MCCOY & MILLS FORD
DOC_NUM	807648C
PH_NUM	6286601
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAB
CUST_CONC_CD	315
COND_CD	68
RPR_DT	12/16/2001
TIS_WSD	12
CLM_KEY	6842837
MILGE	15574
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	5442
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	RT FT SEATBELT WONT LATCH SEATBELT PROBLEM REP 1, BELT AND CK AFTER REPAIRS
TECH_TXT2	
CUST_TXT	R F SEAT BELT BUCKLE WONT LATCH SQP HERE
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	171085
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	710
VIN_CD	1FMRU15W81L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T63
MKT_DERIVED	*
BOD_CAB_STL	TWD
VRR_SERIES_CD	T7F
DRIVE_CD	T7B
ENG_CD	TVN
TRANS_CD	T70J
PLANT_CD	AP
PRODN_DT	8/14/2000
WRTY_START_D	11/25/2000
NAME	KERMIT MOTOR CO, INC.
DOC_NUM	187971
PH_NUM	5002551
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/5/2001
TIS_WSD	11
CLM_KEY	4226048
MILGE	10960
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LRR_HRS	
DLR_CD	20447
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	
TECH_TXT1	R/R PASSANGER SEAT REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	915
COUNTRY_CD	USA
SLS_DLR_CD	182664
TXN_CD	FB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	717
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINE_CD	17B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TXF
DRIVE_CD	TR
ENG_CD	TVN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	7/17/2001
WRTY_START_D	8/10/2001
NAME	FAIRWAY FORD, INC.
DOC_NUM	187880A
PH_NUM	2426060
WCC_CD	BRD2
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7801203
PART_NUM_CAU	CAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	8/1/2001
TIS_WSD	0
CLM_KEY	2803080
MILGE	4
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	04
DLR_CD	977
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	11001
Ratings	a
TRCH_TXT1	CK AND REPLACED LEFT FRT SEAT BELT BUCKLE ASSY.
TRCH_TXT2	
CUST_TXT	DRIVERS SEATBELT WILL NOT LATCH
AREA_CD	864
COUNTRY_CD	USA
SLS_DLR_CD	121228
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	BS
VRT_CD	808
TTS_FLAG	

MDL_YR	2001
SORT_INDEX	720
VIN_CD	1FMRU15W51L
LBR_COST	202
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	6/6/2001
WRTY_START_D	8/16/2001
NAME	SIMI VALLEY FORD
DOC_NUM	4707854
PH_NUM	5830333
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881232
PART_NUM_CAU	AAA
CUST_CONC_CD	625
COND_CD	42
RPR_DT	2/22/2002
TIS_WSD	7
CLM_KEY	7247440
MILGE	12806
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	7022
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	RECALL REPLACE RT FT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES FRONT PASSENGER SEAT BELT DOES NOT LATCH PROPERLY
AREA_CD	806
COUNTRY_CD	USA
SLS_DLR_CD	171447
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B8
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	721
VIN_CD	1FMRU15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	8/6/2001
WRTY_START_D	8/29/2001
NAME	CAPISTRANO FORD
DOC_NUM	20182801
PH_NUM	2407000
WCC_CD	9R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851202
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/6/2001
TIS_WSD	0
CLM_KEY	2882880
MILGE	15
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="00"/>
DLR_CD	<input type="text" value="712"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="3"/>
TECH_TXT1	<input type="text" value="INSPECT PASS SIDE SEAT BELT REPLACE
DEFECTIVE SEAT BELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="PASS SIDE SEAT BELT BUCKLE WONT LATCH"/>
AREA_CD	<input type="text" value="848"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171098"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	722
VIN_CD	1FMRU15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/31/2001
WRTY_START_D	8/18/2001
NAME	BUMRISE FORD
DOC_NUM	520501A
PH_NUM	8224401
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	41
RPR_DT	11/27/2001
TIS_WSD	4
CLM_KEY	6726236
MILGE	4803
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 981 of 1298

RQ04-011 E 3008

LBR_HRS	
DLR_CD	5638
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	4899 RECALL 01S21E 0.9 7282 REPLACED LH AND RH SEAT BELT BUCKLES PER RECALL 01S21
TECH_TXT2	
CUST_TXT	CUST STATES SEATBELTS WONT LATCH
AREA_CD	909
COUNTRY_CD	USA
SLS_DLR_CD	171425
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	723
VIN_CD	1FMRU16W61L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/29/2001
WRTY_START_D	6/30/2001
NAME	LANDERS FORD
DOC_NUM	16530302
PH_NUM	5623873
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7661203
PART_NUM_CAU	BAA
CUST_CONC_CD	826
COND_CD	42
RPR_DT	6/16/2002
TIS_WSD	11
CLM_KEY	8672318
MILGE	19890
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	64
DLR_CD	6620
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AR
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACE BOTH FRONT SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	CUST STATES SEAT BELTS NOT STAY LOCKED AT TIMES.
AREA_CD	501
COUNTRY_CD	USA
SLS_DLR_CD	123204
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	72A
VIN_CD	1FMRJ15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SRRIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/17/2001
WRTY_START_D	6/30/2001
NAME	MARCOONE FORD
DOC_NUM	503488A
PH_NUM	9727200
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONG_CD	840
COND_CD	42
RPR_DT	10/2/2001
TIS_WSD	2
CLM_KEY	4113084
MILGE	1008
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0000
DLR_CD	4820
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	1008 W 802 VERIFIED CONCERN.REPLACE DRIVER SEAT BELT RECIEVER DUE TO INOP.RETEST,OK AT THIS TIME. QUALITY INSPECTED BY 302,1008.
TECH_TXT2	
CUST_TXT	S40 CUST CONCERN DRIVER SIDE SEAT BELT NOT WORKING CORRECTLY
AREA_CD	054
COUNTRY_CD	USA
SLS_DLR_CD	124015
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	726
VIN_CD	1FMRU1BW51L6
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	T/MD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/6/2001
WRTY_START_D	6/30/2001
NAME	SUNBELT FORD-MERCURY INC
DOC_NUM	9181901
PH_NUM	7767881
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	340
COND_CD	42
RPR_DT	7/5/2001
TIS_WSD	1
CLM_KEY	2723388
MILGE	822
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	61
DLR_CD	4834
DLR_SUB_CD	^
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	SEAT BELT LATCHES DEFECTIVE REPLACE SEAT BELTS FRT.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SIDE SEAT BELT COMES LOOSE FOR NO REASON
AREA_CD	228
COUNTRY_CD	USA
SLS_DLR_CD	121573
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	728
VIN_CD	1FMRU115W51
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/7/2001
WRTY_START_D	6/27/2001
NAME	CROWN FORD
DOC_NUM	025051
PH_NUM	0671121
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7061202
PART_NUM_CAU	PAC
CUST_CONC_CD	928
COND_CD	42
RPR_DT	5/13/2002
TIS_WSD	12
CLM_KEY	8580182
MILGE	34053
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="3924"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NC"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value="0"/>
TECH_TXT1	<input type="text" value="SEAT BELT BUCKLE REMOVED PASS SEAT AND REPLACED SEAT BELT BUCKLE."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="SEAT BELT INOP (PARTS HERE)"/>
AREA_CD	<input type="text" value="910"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121226"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="908"/>
TIS_FLAG	<input type="text" value="0"/>

MDL_YR	2001
SORT_INDEX	730
VIN_CD	1FMRLJ15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	9/28/2001
NAME	TOWN EAST FORD
DOC_NUM	7755300
PH_NUM	2708441
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	1
RPR_DT	11/13/2001
TIS_WSD	2
CLM_KEY	5283647
MILGE	3431
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="6192"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="TX"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="c"/>
TECH_TXT1	<input type="text" value="3436 BROKEN 01 REPLACED LT FT SEAT BELT ASSY"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="S05 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES"/>
AREA_CD	<input type="text" value="872"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="152002"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	731
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	TAWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/18/2001
WRTY_START_D	5/8/2001
NAME	BOB BROCK FORD, INC.
DOC_NUM	7584001
PH_NUM	2877424
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	940
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	3
CLM_KEY	2283611
MILGE	1522
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 993 of 1298

RQ04-011 E 3018

LBR_HRS	
DLR_CD	2403
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT BUCKLE WILL NOT STAY FASTENED
AREA_CD	015
COUNTRY_CD	USA
SLS_DLR_CD	162573
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	734
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINE_CD	T/B3
MKY_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/R
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/30/2001
WRTY_START_D	8/22/2001
NAME	FORD OF NORTH MIAMI BEACH
DOC_NUM	24002002
PH_NUM	9491311
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAC
CUST_CONC_CD	340
COND_CD	42
RPR_DT	11/17/2001
TIS_WSD	3
CLM_KEY	5304003
MILGE	3489
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4038"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="FL"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="d"/>
TECH_TXT1	<input type="text" value="REPLACED THE FRONT DRIVER SIDE SEAT BELT BUCKEL. THE ORIVER SIDE SEAT SLET BUCKLE WAS DEFECTIVE."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="S40 D S F RESTRAINT UNLOCKS WHILE DRIVING"/>
AREA_CD	<input type="text" value="305"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124001"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	738
VIN_CD	1FMRU15WS1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/28/2001
WRTY_START_D	6/24/2001
NAME	FRIENDLY FORD
DOC_NUM	25398402
PH_NUM	2858000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	940
COND_CD	42
RPR_DT	6/4/2002
TES_WSD	12
CLM_KEY	9041910
MILGE	20473
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	EA
DLR_CD	3921
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	1 TECH REMOVED AND REPLACED DRIVER SIDE SEAT BELT ASY ALL OK AT THIS TIME
TECH_TXT2	
CUST_TXT	CUST STATES INNT THE DRIVER SEAT BELT WILL POP OUT FROM THE BUCKLE CHECK AND ADVISE
AREA_CD	408
COUNTRY_CD	USA
SLS_DLR_CD	172039
TXN_CD	EA
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	737
VIN_CD	1FMRL15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	5/2/2001
NAME	PINECREST FORD-MERCURY, INC.
DOC_NUM	216551
PH_NUM	3274327
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	8/10/2001
TIS_WSD	5
CLM_KEY	4083702
MILGE	7048
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	83
DLR_CD	7016
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	REPLACED SEAT BELT BUCKLE WITH NEW ONE
TECH_TXT2	
CUST_TXT	DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING LIGHT TAN
AREA_CD	838
COUNTRY_CD	USA
SLS_DLR_CD	152158
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	744
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/31/2001
WRTY_START_D	5/3/2001
NAME	DON REID FORD, INC.
DOC_NUM	8438052
PH_NUM	8447111
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/12/2001
TIS_WSD	3
CLM_KEY	3814838
MILGE	2478
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.4
DLR_CD	4892
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT DOES NOT CONNECT ALL THE TIME
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124214
TXN_CD	Z
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	749
VIN_CD	1FMRU15W51L
LBR_COST	38.99
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	12/21/2000
WRTY_START_D	8/28/2001
NAME	BOB TILLERY FORD, INC.
DOC_NUM	1142401
PH_NUM	5423171
WCC_CD	BR02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/9/2001
TIS_WSD	1
CLM_KEY	2247581
MILGE	359
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	4481
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	2
TECH_TXT1	
TECH_TXT2	
CUST_TXT	DRIVER SIDE SEAT BELT WILL NOT LATCH
AREA_CD	400
COUNTRY_CD	USA
SLS_DLR_CD	162771
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TYS_FLAG	

MDL_YR	2001
SORT_INDEX	750
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINK_CD	T/BS
MKT_DERIVED	
BOD_CAB_STL	T/ND
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	12/11/2000
WRTY_START_D	3/18/2001
NAME	DOWNTOWN FORD SALES
DOC_NUM	184491A
PH_NUM	4428851
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AB
CUST_CONC_CD	925
COND_CD	41
RPR_DT	9/20/2001
TIS_WSD	7
CLM_KEY	3887211
MILGE	8584
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	D.A. [REDACTED]
DLR_CD	7883
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED LEFT SEAT BELT
TECH_TXT2	
CUST_TXT	INSTALL S.O.P. SEAT BELT RECALL PART
AREA_CD	918
COUNTRY_CD	USA
SLS_DLR_CD	172205
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	752
VIN_CD	1FMRU15W51L
LBR_COST	27.71
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/BF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/26/2000
WRTY_START_D	11/11/2000
NAME	PHIL LONG FORD OF CHAPEL HILLS
DOC_NUM	30183001
PH_NUM	5722200
WCC_CD	BR02
PART_NUM_CAU	F85Z
PART_NUM_CAU	
PART_NUM_CAU	CCC
CUST_CONC_CD	825
COND_CD	1
RPR_DT	4/2/2002
TIS_WSD	17
CLM_KEY	7760257
MILGE	26644
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.2
DLR_CD	3134
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CO
CPSC_CD_6	12000
Rating	5
TECH_TXT1	INSP AND VERIFY FRONT CENTER SEAT BELT BUCKLE INOP, REPLACED CENTER SEAT BELT BUCKLE, CHECK OPERATION OK. COND CODE 42
TECH_TXT2	
CUST_TXT	CUST STATES FRONT SEAT CENTER SEAT BELT INOP, PLEASE INSTALL SOP SEAT BELT, SEE PHIL IN PARTS
AREA_CD	718
COUNTRY_CD	USA
SLS_DLR_CD	158481
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	800
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	753
VIN_CD	1FMRU15W51LA
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TWD
VBR_SERIES_CD	TIEF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/29/2000
WRTY_START_D	1/18/2001
NAME	MESA FORD
DOC_NUM	52832001
PH_NUM	5447725
WCC_CD	5R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851202
PART_NUM_CAU	AAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	1/17/2002
TIS_WSD	13
CLM_KEY	8348872
MILGE	20125
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	000
DLR_CD	6889
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	9
TECH_TXT1	REPLACED RIGHT FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	C 8 FT. SEAT BELT WON T BUCKLE UP AT TIMES, S O PART HERE ADVISE
AREA_CD	B16
COUNTRY_CD	USA
SLS_DLR_CD	152211
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	754
VIN_CD	1FMRU15W611
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/D11
PLANT_CD	AP
PRODN_DT	10/29/2000
WRTY_START_D	1/18/2001
NAME	MESA FORD
DOC_NUM	92084501
PH_NUM	5447725
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	AAF
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	11/29/2001
TIS_WSD	11
CLM_KEY	5470814
MILGE	18220
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1011 of 1298

RQ04-011 E 3036

LBR_HRS	0.8
DLR_CD	6809
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACE DRIVERS SEAT BELT BUCKLE NOT CATCHING AND R.REAR MIDDLE SEAT BUCKLE INOP NOT CATCHING. REPLACED.
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELTS
AREA_CD	B15
COUNTRY_CD	USA
SLS_DLR_CD	152211
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	765
VIN_CD	1FMRU15W51
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	07/23/2001
NAME	METRO FORD
DOC_NUM	155030A
PH_NUM	980900
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	11/17/2001
TIS_WSD	2
CLM_KEY	5255127
MILGE	2671
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	04
DLR_CD	5453
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	INSPECT LEFT FRONT SEAT BELT WITH TESTER. REPLACE LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	81B
COUNTRY_CD	USA
SLS_DLR_CD	171019
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	758
VIN_CD	1FMRJ15W51L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/12/2000
WRTY_START_D	1/31/2001
NAME	CROWN FORD
DOC_NUM	14450001
PH_NUM	8671121
WCC_CD	6R1E2
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAQ
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	11/17/2001
TIS_WSD	10
CLM_KEY	5280158
MILGE	27252
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	84
DLR_CD	3824
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	n
TECH_TXT1	REMOVED AND INSTALLED FRONT SEAT BELT
TECH_TXT2	
CUST_TXT	INSTALL SPECIAL ORDERED BELT BRACKS FRONT SEATBELT BROKEN REFER BACK TO RC 142840
AREA_CD	810
COUNTRY_CD	USA
SLS_DLR_CD	121226
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	R3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	757
VIN_CD	1FMRM15W51
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VH
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	9/27/2000
WRTY_START_D	12/5/2000
NAME	PALM SPRINGS FORD
DOC_NUM	004222C
PH_NUM	3282102
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	12/5/2001
TIS_WSD	13
CLM_KEY	5098537
MILGE	11985
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.2
DLR_CD	5574
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	CUSTOMER STATES PASS FRONT SEAT BELT BUCKLE WILL NOT ACCEPT BELT INTO RECEPTACLE WITHOUT DEPRESSING BUTTON AND FORCING IN OK AND ADVISE
AREA_CD	760
COUNTRY_CD	USA
SLS_DLR_CD	171430
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	759
VIN_CD	1FMRU15W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/W3
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/4/2001
WRTY_START_D	8/27/2001
NAME	NICHOLS FORD
DOC_NUM	20941101
PH_NUM	5363673
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	540
COND_CD	42
RPR_DT	7/10/2001
TIS_WSD	0
CLM_KEY	2067740
MILGE	2
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	04
DLR_CD	2511
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Rating	a
TECH_TXT1	REPLACE RT SIDE BELT.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT RT SIDE BELT INOP
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152009
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	789
VIN_CD	1FMRL115W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/30/2001
WRTY_START_D	9/14/2001
NAME	CERRITOS FORD
DOC_NUM	26478901
PH_NUM	6656554
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	78E1202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/30/2001
TIS_WSD	0
CLM_KEY	3400887
MILGE	8
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.00
DLR_CD	5401
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	WILL NOT BUCKLE UP LABOR OP. 01821D 0.8 PERFORM RECALL #01821 REPLACE PASS SEAT BELL BUCKLE PER RECALL
TECH_TXT2	
CUST_TXT	PERFORM RECALL #01821
AREA_CD	562
COUNTRY_CD	USA
SLS_DLR_CD	171065
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRI_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	781
VIN_CD	1FMRU16W41L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/18/2001
WRTY_START_D	8/18/2001
NAME	LAFAYETTE MOTOR SALES INC
DOC_NUM	812851
PH_NUM	4240281
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BA8
CUST_CONC_CD	T00
COND_CD	42
RPR_DT	3/8/2002
TIS_WSD	7
CLM_KEY	7306854
MILGE	13458
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1823 of 1298

RQ04-011 E 3048

LRR_HES	04
DLR_CD	060
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	3
TECH_TXT1	INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	DRIVER SEATBELT WILL NOT BUCKLE AT TIMES USE SPO 02058001
AREA_CD	010
COUNTRY_CD	USA
SLS_DLR_CD	121028
TXN_CD	E64
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	762
VIN_CD	1FMRL115W41
LRR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	6/18/2001
WRTY_START_D	10/1/2001
NAME	DOMINO FORD, INC.
DOC_NUM	181838A
PH_NUM	3853000
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	1/17/2002
TIS_WSD	4
CLM_KEY	8384104
MILGE	4854
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	03
DLR_CD	1777
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	IL
CPSC_CD_6	11081
Ratings	#
TECH_TXT1	INSTALLED DRIVERS SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	DRIVERS SEATBELT WILL NOT STAY LATCHED INSTALL SOP
AREA_CD	708
COUNTRY_CD	USA
SLS_DLR_CD	141062
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	756
VIN_CD	1FMRU15W41L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	5/6/2001
NAME	MARDONE FORD
DOC_NUM	613267A
PH_NUM	5843221
WCC_CD	8R02
PART_NUM_CAU	1LZ
PART_NUM_CAU	7881203
PART_NUM_CAU	8AA
CUST_CONC_CD	940
COND_CD	42
RPR_DT	6/6/2002
TIS_WSD	14
CLM_KEY	9098678
MILGE	15468
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1027 of 1298

RQ04-011 E 3052