

**RQ04-011**

**FORD**

**APRIL 26, 2005**

**REQUEST 8**

**PART 4 OF 6**

**BOOK 5 OF 43**

<b>LBR_HRS</b>	0.5
<b>DLR_CD</b>	4843
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	9
<b>TECH_TXT1</b>	LEFT FRT SEAT BELT INOP WILL NOT BUCKLE REPLACE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	DR SEATBELT WONT FASTEN
<b>AREA_CD</b>	954
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124016
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V06
<b>AWS_VL_CD</b>	E9
<b>VRT_CD</b>	S08
<b>YTS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	787
<b>VIN_CD</b>	1FMRLJ15W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VRR_SERIES_CD</b>	TJF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	TMN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/21/2001
<b>WRTY_START_D</b>	5/29/2001
<b>NAME</b>	HUB CITY FORD, INC.
<b>DOC_NUM</b>	686882
<b>PH_NUM</b>	2334600
<b>WCC_CD</b>	8P02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7861203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	507
<b>COND_CD</b>	41
<b>RPR_DT</b>	11/12/2001
<b>TIS_WSD</b>	6
<b>CLM_KEY</b>	6157237
<b>MILGE</b>	13866
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	85
<b>DLR_CD</b>	6481
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	LA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	8
<b>TECH_TXT1</b>	DOESN TO OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CK THE SEAT BELT DRIVER SIDE NOT LATCHING PROPERLEY
<b>AREA_CD</b>	337
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123271
<b>TXN_CD</b>	EB4
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VPG_CD</b>	V03
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	756
<b>VIN_CD</b>	1FMRU16W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/20/2001
<b>WRTY_START_D</b>	5/28/2001
<b>NAME</b>	GRAY-DANIELS FORD
<b>DOC_NUM</b>	2236701
<b>PH_NUM</b>	8252801
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7681203
<b>PART_NUM_CAU</b>	AAF
<b>CUST_CDNC_CD</b>	828
<b>COND_CD</b>	42
<b>RPR_DT</b>	6/3/2002
<b>TIS_WSD</b>	13
<b>CLM_KEY</b>	8049409
<b>MILGE</b>	21237
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	04
<b>DLR_CD</b>	7958
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MS
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	b
<b>TECH_TXT1</b>	CHECKED OPERATION OF BUCKLE REPLACED DRIVERS SEAT BUCKLE ASSY AND QUALITY CHECKED OPERATION
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	828 CUST STATES DRIVERS SEAT BELT WONT STAY LATCHED
<b>AREA_CD</b>	801
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	128308
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V06
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	608
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	789
<b>VIN_CD</b>	1FMRU15W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/19/2001
<b>WRTY_START_D</b>	8/10/2001
<b>NAME</b>	SOUTHPOINT FORD MERCURY, INC.
<b>DOC_NUM</b>	2421901
<b>PH_NUM</b>	8253333
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7801203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	S40
<b>COND_CD</b>	42
<b>RPR_DT</b>	8/30/2001
<b>TIS_WSD</b>	1
<b>CLM_KEY</b>	2458528
<b>MILGE</b>	825
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	04
<b>DLR_CD</b>	4158
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	LA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	c
<b>TECH_TXT1</b>	CP 7881208 CC 42 DRIVERS SIDE SEATBELT TEST SEATBELT OPERATION, REPLACED SEATBELT
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	C S THE SEAT BELT WILL COME UNLATCHED
<b>AREA_CD</b>	318
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123223
<b>TXN_CD</b>	2
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	E3
<b>VRT_CD</b>	808
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	773
<b>VIN_CD</b>	1FM6J15W41L
<b>LBR_COST</b>	
<b>VRH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VRR_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/12/2001
<b>WRTY_START_D</b>	5/4/2001
<b>NAME</b>	CRESHAW MOTORS
<b>DOC_NUM</b>	070888A
<b>PH_NUM</b>	2947181
<b>WCC_CD</b>	BR02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	T90
<b>COND_CD</b>	1
<b>RPR_DT</b>	12/12/2001
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	5786253
<b>MILGE</b>	6678
<b>MTRL_COST</b>	
<b>TOY_COST_GROS</b>	

<b>LBR_HRS</b>	0.2
<b>DLR_CD</b>	5479
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	
<b>TECH_TXT1</b>	REPLACED BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUST HAS RETURNED TO HAVE SOP INSTALLED. (REFER TO HISTORY ROW 68917)
<b>AREA_CD</b>	323
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171022
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V74
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	775
<b>VIN_CD</b>	1FMRJ15W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/14/2001
<b>WRTY_START_D</b>	4/5/2001
<b>NAME</b>	SAMES MOTOR COMPANY, INC.
<b>DOC_NUM</b>	040205D
<b>PH_NUM</b>	7214700
<b>WCC_CD</b>	BR02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7861208
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	S40
<b>COND_CD</b>	30
<b>RPR_DT</b>	2/15/2002
<b>TIS_WSD</b>	11
<b>CLM_KEY</b>	7100174
<b>MILGE</b>	10632
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	1
<b>DLR_CD</b>	4400
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	c
<b>TECH_TXT1</b>	10533 SEAT BUCKLES 30 WR INSPECTED AND FOUND BOTH SEAT BUCKLES INOP. R R BOTH FRONT SEAT BUCKLES AND RETESTED.PASS.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	540 CUSTOMER STATES DRIVER SEAT BELT COMES UNBUCKLED
<b>AREA_CD</b>	050
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152772
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	778
<b>VIN_CD</b>	1FMRUJ15W41L
<b>LRR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/MO
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/11/2001
<b>WRTY_START_D</b>	3/25/2001
<b>NAME</b>	NORTH CENTRAL FORD
<b>DOC_NUM</b>	58420703
<b>PH_NUM</b>	2318491
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	S2B
<b>COND_CD</b>	42
<b>RPR_DT</b>	4/12/2002
<b>TIS_WSD</b>	18
<b>CLM_KEY</b>	7878493
<b>MILGE</b>	12174
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	4212
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	0
<b>TECH_TXT1</b>	REPLACE DRIVERS SEAT BELT BUCKLE.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	G & TYHAT THE DRIVER SEAT BELT ENTERPRISE DW278888
<b>AREA_CD</b>	972
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	162012
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	808
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	779
<b>VIN_CD</b>	1FMRUJ15W41
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/OU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/5/2001
<b>WRTY_START_D</b>	6/2/2001
<b>NAME</b>	GULLO FORD-MERCURY OF CONROE
<b>DOC_NUM</b>	385797A
<b>PH_NUM</b>	7687781
<b>WCC_CD</b>	8F02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	828
<b>COND_CD</b>	42
<b>RPR_DT</b>	6/1/2002
<b>TIS_WSD</b>	12
<b>CLM_KEY</b>	8344784
<b>MILGE</b>	33072
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LRR_HRS</b>	08
<b>DLR_CD</b>	1472
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	c
<b>TECH_TXT1</b>	33072 MT 7801203 .0 .0 REPLACED DRIVER SEAT BELT BUCKLE.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	THE DRIVERS SEAT SEATBELT RECIEVER KEEPS LETTING LOOSE OF THE BELT, CHECK AND ADVISE
<b>AREA_CD</b>	996
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152168
<b>TXN_CD</b>	E64
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V06
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	785
<b>VIN_CD</b>	1FMRU16W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	2/9/2001
<b>WRTY_START_D</b>	9/3/2001
<b>NAME</b>	BUERGE FORD
<b>DOC_NUM</b>	245125C
<b>PH_NUM</b>	8202631
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	S2E
<b>COND_CD</b>	42
<b>RPR_DT</b>	12/17/2001
<b>TTS_WSD</b>	4
<b>CLM_KEY</b>	5658499
<b>MILGE</b>	4544
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value=""/>
<b>DLR_CD</b>	<input type="text" value="6492"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="CA"/>
<b>CPSC_CD_6</b>	<input type="text" value="11001"/>
<b>Ratings</b>	<input type="text" value="•"/>
<b>TECH_TXT1</b>	<input type="text" value="REPLACED BELT BUCKLE"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value=""/>
<b>AREA_CD</b>	<input type="text" value="310"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="171029"/>
<b>TXN_CD</b>	<input type="text" value="1"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V05"/>
<b>AWS_VL_CD</b>	<input type="text" value="B3"/>
<b>VRT_CD</b>	<input type="text" value="B06"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	780
<b>VIN_CD</b>	1FMRU16W41
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/OU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	11/27/2000
<b>WRTY_START_D</b>	9/15/2001
<b>NAME</b>	BROWNWOOD FORD-LINCOLN-MERCURY
<b>DOC_NUM</b>	8082551
<b>PH_NUM</b>	8431851
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	F85Z
<b>PART_NUM_CAU</b>	7851203
<b>PART_NUM_CAU</b>	8BE
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	11/2/2001
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	4976737
<b>MILGE</b>	2559
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	07
<b>DLR_CD</b>	2874
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	b
<b>TECH_TXT1</b>	CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...
<b>AREA_CD</b>	015
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152016
<b>TXN_CD</b>	2
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	308
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	783
<b>VIN_CD</b>	1FMRU15W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/8
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	11/11/2000
<b>WRTY_START_D</b>	2/18/2001
<b>NAME</b>	ERNE HAIRE FORD, INC.
<b>DOC_NUM</b>	8626051
<b>PH_NUM</b>	8338571
<b>WCC_CD</b>	8F02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881202
<b>PART_NUM_CAU</b>	AAB
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	12/6/2001
<b>TIS_WSD</b>	10
<b>CLM_KEY</b>	5579787
<b>MILGE</b>	21880
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	4000
<b>DLR_CD</b>	4000
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	4
<b>TECH_TXT1</b>	SEATBELT ASSEMBLY FRONT REPLACE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	C S PASSENGER SEAT BELT COMES UNLATCHED WHILE DRIVING , INSTALL SOP BELT ASSY HAS OPEN 01S21 RECALL
<b>AREA_CD</b>	813
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124208
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B8
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	784
<b>VIN_CD</b>	1FMRU15W41
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	T/RD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	6/6/2000
<b>WRTY_START_D</b>	7/27/2001
<b>NAME</b>	FOLSOM LAKE FORD INC
<b>DOC_NUM</b>	30408801
<b>PH_NUM</b>	3532000
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	F85Z
<b>PART_NUM_CAU</b>	
<b>PART_NUM_CAU</b>	CCC
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	8/1/2001
<b>TIS_WSD</b>	1
<b>CLM_KEY</b>	2877054
<b>MILGE</b>	478
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	7727
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	0
<b>TECH_TXT1</b>	SOP. INSTALLED RF SEAT BELT BUCKLE, VERIFIED REPAIRS
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	MISSING FEMALE SEAT BELT ENDS FOR RT FRONT AND CENTER PASSENGERS
<b>AREA_CD</b>	016
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	172207
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S05
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	796
<b>VIN_CD</b>	1FMRU15W41L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/OU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	8/10/2000
<b>WRTY_START_D</b>	12/4/2000
<b>NAME</b>	SANTA MARIA FORD
<b>DOC_NUM</b>	062065A
<b>PH_NUM</b>	0262446
<b>WCC_CD</b>	BF02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881202
<b>PART_NUM_CAU</b>	AAA
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	2/16/2002
<b>TIS_WSD</b>	15
<b>CLM_KEY</b>	7000800
<b>MILGE</b>	31380
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	0
<b>DLR_CD</b>	5431
<b>DLR_SUB_CD</b>	.
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	.
<b>TECH_TXT1</b>	REPLACE PASS SIDE SEAT BELT BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	
<b>AREA_CD</b>	805
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171452
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	805
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	707
<b>VIN_CD</b>	1FMRU15W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T7F
<b>DRIVE_CD</b>	T7B
<b>ENG_CD</b>	T7N
<b>TRANS_CD</b>	T7U
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	8/20/2001
<b>WRTY_START_D</b>	8/28/2001
<b>NAME</b>	FAIRWAY FORD
<b>DOC_NUM</b>	8410051
<b>PH_NUM</b>	8241200
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	828
<b>COND_CD</b>	42
<b>RPR_DT</b>	9/20/2002
<b>TIS_WSD</b>	7
<b>CLM_KEY</b>	8487229
<b>MILGE</b>	6712
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	83
<b>DLR_CD</b>	5476
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	*
<b>TECH_TXT1</b>	NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUSTOMER STATES DRIVERS SEAT BELT UNLATCHES AT TIMES.
<b>AREA_CD</b>	714
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171009
<b>TXN_CD</b>	2
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V06
<b>AWS_VL_CD</b>	B9
<b>VRT_CD</b>	S06
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	788
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	2288
<b>VEH_LINE_CD</b>	T/83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TMD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/8
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	6/30/2001
<b>WRTY_START_D</b>	9/29/2001
<b>NAME</b>	VELDE FORD INC
<b>DOC_NUM</b>	18570101
<b>PH_NUM</b>	5683400
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	8A8
<b>CUST_CONC_CD</b>	S26
<b>COND_CD</b>	42
<b>RPR_DT</b>	12/12/2001
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	5725005
<b>MILGE</b>	3784
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LRR_HRS</b>	09
<b>DLR_CD</b>	4950
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	#
<b>TECH_TXT1</b>	SEAT BELT WONT HOLD REPLACED DRIVERS SEAT BELT
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUSTOMER STATES DRIVERS SEAT BELT INOP SOP
<b>AREA_CD</b>	581
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124404
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	808
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	800
<b>VIN_CD</b>	1FMRU15W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	01/2001
<b>WRTY_START_D</b>	7/27/2001
<b>NAME</b>	TAMAMI FORD, INC.
<b>DOC_NUM</b>	2835101
<b>PH_NUM</b>	8433873
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7961202
<b>PART_NUM_CAU</b>	AAB
<b>CUST_CONC_CD</b>	825
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/29/2001
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2864122
<b>MILGE</b>	22
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LHR_HRS</b>	<input type="text" value=""/>
<b>DLR_CD</b>	<input type="text" value="1200"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="FL"/>
<b>CPSC_CD_6</b>	<input type="text" value="12001"/>
<b>Ratings</b>	<input type="text" value="•"/>
<b>TECH_TXT1</b>	<input type="text" value="1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="RECALL 01S21 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12"/>
<b>AREA_CD</b>	<input type="text" value="941"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="124428"/>
<b>TXN_CD</b>	<input type="text" value="1"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V06"/>
<b>AWS_VL_CD</b>	<input type="text" value="89"/>
<b>VRT_CD</b>	<input type="text" value="SUB"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	801
<b>VIN_CD</b>	1FMRU16W81L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TMD
<b>VKR_SERIES_CD</b>	T/EP
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/31/2001
<b>WRTY_START_D</b>	10/2/2001
<b>NAME</b>	KARL FLAMMER FORD INC
<b>DOC_NUM</b>	8028151
<b>PH_NUM</b>	8375131
<b>WCC_CD</b>	BR02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881202
<b>PART_NUM_CAU</b>	AAA
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/17/2001
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2476224
<b>MILGE</b>	32
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LRR_HRS</b>	0:8
<b>DLR_CD</b>	4970
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	*
<b>TECH_TXT1</b>	INOP BELT BUCKLE      REPLACED RIGHT SIDE SEAT BELT BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	PASSENGER SIDE SEAT BELT FAILED INSPECTION NOT ON RECALL      (FAILED)
<b>AREA_CD</b>	T27
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124544
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	B08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	802
<b>VIN_CD</b>	1FMFLJ1BW31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>HOD_CAR_STL</b>	T/WO
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/28/2001
<b>WRTY_START_D</b>	8/20/2001
<b>NAME</b>	LAFAYETTE MOTOR SALES INC
<b>DOC_NUM</b>	9107851
<b>PH_NUM</b>	4240281
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	340
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/18/2001
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2835078
<b>MILGE</b>	2
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	84
<b>DLR_CD</b>	980
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NC
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	b
<b>TECH_TXT1</b>	REPLACED LEFT BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	DRIVER'S SEAT BELT BUCKLE WILL NOT HOLD.
<b>AREA_CD</b>	910
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121224
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V06
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	808
<b>VIN_CD</b>	1FMRU16W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/28/2001
<b>WRTY_START_D</b>	8/17/2001
<b>NAME</b>	WALKER FORD COMPANY, INC.
<b>DOC_NUM</b>	7888001
<b>PH_NUM</b>	5353873
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7851208
<b>PART_NUM_CAU</b>	BAC
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/17/2001
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	3060828
<b>MILGE</b>	782
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 1063 of 1298

RQ04-011 E 3088

<b>LBR_HRS</b>	<input type="text" value=""/>
<b>DLR_CD</b>	<input type="text" value="4947"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="FL"/>
<b>CPSC_CD_6</b>	<input type="text" value="11001"/>
<b>Ratings</b>	<input type="text" value="d"/>
<b>TECH_TXT1</b>	<input type="text" value="M0782 REPLACED DR SIDE BELT BUCKEL AS PER RECALL"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="CUST STATES DRIVER SEAT BELT RELEASES WHILE DRIVING"/>
<b>AREA_CD</b>	<input type="text" value="727"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="124202"/>
<b>TXN_CD</b>	<input type="text" value="1"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V06"/>
<b>AWS_VL_CD</b>	<input type="text" value="B9"/>
<b>VRT_CD</b>	<input type="text" value="S06"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	604
<b>VIN_CD</b>	1FMRUJ15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/25/2001
<b>WRTY_START_D</b>	7/30/2001
<b>NAME</b>	BAMES MOTOR COMPANY, INC.
<b>DOC_NUM</b>	0270688
<b>PH_NUM</b>	7214700
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881202
<b>PART_NUM_CAU</b>	AAB
<b>CUST_CONC_CD</b>	S26
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/31/2001
<b>TIS_WSD</b>	1
<b>CLM_KEY</b>	2750873
<b>MILGE</b>	175
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	00
<b>DLR_CD</b>	4498
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	8
<b>TECH_TXT1</b>	176 RECALL 01821. WR. 01821D. PERFORM RECALL 01821. PERFORM INSPECTION AND REPLACE PASSENGERS SIDE SEAT BELT BUCKLE. RETEST PASS OK.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821
<b>AREA_CD</b>	888
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152772
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	805
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/25/2001
<b>WRTY_START_D</b>	8/9/2001
<b>NAME</b>	BEAULRY FORD, INC.
<b>DOC_NUM</b>	3038151
<b>PH_NUM</b>	658673
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	
<b>PART_NUM_CAU</b>	AAA
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/24/2001
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2838581
<b>MILGE</b>	1B
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	██████████
<b>DLR_CD</b>	449
<b>DLR_SUB_CD</b>	██████████
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	GA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	0
<b>TECH_TXT1</b>	REPL SEAT BELT BUCKLE      PERFORM
<b>TECH_TXT2</b>	██████████
<b>CUST_TXT</b>	REPL SEAT BELT BUCKLE
<b>AREA_CD</b>	404
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	321024
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S05
<b>TIS_FLAG</b>	██████████

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	808
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	8/28/2001
<b>WRTY_START_D</b>	7/28/2001
<b>NAME</b>	COVERT FORD, INC.
<b>DOC_NUM</b>	1140201
<b>PH_NUM</b>	3454343
<b>WCC_CD</b>	BF02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	
<b>PART_NUM_CAU</b>	AAC
<b>CUST_CONC_CD</b>	826
<b>COND_CD</b>	42
<b>RPR_DT</b>	1/30/2002
<b>TIS_WSD</b>	7
<b>CLM_KEY</b>	0887385
<b>MILGE</b>	12718
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 1869 of 1298

RQ04-011 E 3094

<b>LBR_HRS</b>	84
<b>DLR_CD</b>	4437
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	d
<b>TECH_TXT1</b>	DEFECTIVE REPLACED RH BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	R F SEAT BELT COMES LOOSE DRIVING
<b>AREA_CD</b>	512
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152302
<b>TXN_CD</b>	EB4
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	810
<b>VIN_CD</b>	1FMRJ15W31
<b>LBR_COST</b>	
<b>VEH_LINK_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/16/2001
<b>WRTY_START_D</b>	6/5/2001
<b>NAME</b>	DUB MILLER FORD INC
<b>DOC_NUM</b>	7382501
<b>PH_NUM</b>	3425811
<b>WCC_CD</b>	0R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	8AA
<b>CUST_CONC_CD</b>	S25
<b>COND_CD</b>	1
<b>RPR_DT</b>	2/20/2002
<b>TIS_WSD</b>	9
<b>CLM_KEY</b>	7050124
<b>MILGE</b>	13041
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value="0.00000000"/>
<b>DLR_CD</b>	<input type="text" value="4480"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="TX"/>
<b>CPSC_CD_6</b>	<input type="text" value="11001"/>
<b>Ratings</b>	<input type="text" value="a"/>
<b>TECH_TXT1</b>	<input type="text" value="1 DIAG UPON INSP REVEALED INTER MIT NO LATCH CAUSED BY BUCKLE INTERNAL DAMAGED BROKE REPLACED BUCKLE ASMBLY &amp; CKD FOR PROP"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="DRIVER SEAT BUCKLE WILL NOT ALWAYS LATCH"/>
<b>AREA_CD</b>	<input type="text" value="281"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="182024"/>
<b>TXN_CD</b>	<input type="text" value="EB4"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V05"/>
<b>AWS_VL_CD</b>	<input type="text" value="E3"/>
<b>VRT_CD</b>	<input type="text" value="S08"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	812
<b>VIN_CD</b>	1FMRLJ16W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	TIEF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/II
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	5/10/2001
<b>WRTY_START_D</b>	8/4/2001
<b>NAME</b>	AIRPORT MARINA FORD
<b>DOC_NUM</b>	26093901
<b>PH_NUM</b>	6483673
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7961203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	326
<b>COND_CD</b>	42
<b>RPR_DT</b>	5/21/2002
<b>TIS_WSD</b>	12
<b>CLM_KEY</b>	8749292
<b>MILGE</b>	11066
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	5563
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	8
<b>TECH_TXT1</b>	E VERIFIED COMPLAINT REPLACED FRONT BUCKLE ASSEMBLYS
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUST STATES SEAT BELST WONT LATCH INSTALL S.Q.P.
<b>AREA_CD</b>	310
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171016
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	308
<b>TIS_FLAG</b>	Ⓢ



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	814
<b>VIN_CD</b>	1FMRU15W31U
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/24/2001
<b>WRTY_START_D</b>	9/7/2001
<b>NAME</b>	TOWN EAST FORD
<b>DOC_NUM</b>	769041A
<b>PH_NUM</b>	2706441
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	T861203
<b>PART_NUM_CAU</b>	BAC
<b>CUST_CONC_CD</b>	825
<b>COND_CD</b>	33
<b>RFR_DT</b>	9/14/2001
<b>TIS_WSD</b>	1
<b>CLM_KEY</b>	4045134
<b>MILGE</b>	623
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 1875 of 1298

RQ04-011 E 3100

<b>LBR_HRS</b>	0.4
<b>DLR_CD</b>	8192
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	c
<b>TECH_TXT1</b>	823 42 REPLACED DRIVERS SIDE SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED AT TIMES
<b>AREA_CD</b>	972
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152482
<b>TXN_CD</b>	2
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	818
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/18/2001
<b>WRTY_START_D</b>	5/12/2001
<b>NAME</b>	MAGIC FORD
<b>DOC_NUM</b>	1280851
<b>PH_NUM</b>	2553600
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7861203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	11/1/2001
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	4873837
<b>MLGE</b>	3040
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	66
<b>DLR_CD</b>	1884
<b>DLR_SUB_CD</b>	^
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	d
<b>TECH_TXT1</b>	INSPECT AND REPLACE DRIVER SIDE SEAT BELT
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUST STATES THE DRIVERS SEAT BELT WILL NOT STAY LOCKED POPS OFF WHILE DRIVING
<b>AREA_CD</b>	881
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171481
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	808
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	817
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/18/2001
<b>WRTY_START_D</b>	5/29/2001
<b>NAME</b>	METRO FORD
<b>DOC_NUM</b>	160035A
<b>PH_NUM</b>	9809800
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	1/18/2002
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	8838527
<b>MILGE</b>	14408
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LRR_HRS</b>	50
<b>DLR_CD</b>	5453
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	*
<b>TECH_TXT1</b>	REPLACED ALL FRONT SEAT BELT BUCKLES
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	
<b>AREA_CD</b>	818
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171019
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S03
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	818
<b>VIN_CD</b>	1FMRL15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	7BS
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/20/2001
<b>WRTY_START_D</b>	5/28/2001
<b>NAME</b>	PUENTE HILLS FORD
<b>DOC_NUM</b>	2787381
<b>PH_NUM</b>	9543873
<b>WCC_CD</b>	BR02
<b>PART_NUM_CAU</b>	F85Z
<b>PART_NUM_CAU</b>	7851203
<b>PART_NUM_CAU</b>	B8E
<b>CUST_CONC_CD</b>	B40
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/21/2001
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	2585787
<b>MILGE</b>	3062
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 1081 of 1298

<b>LBR_HRS</b>	162
<b>DLR_CD</b>	5580
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	2
<b>TECH_TXT1</b>	REPLACE SEAT BELT BUCKLE    ADDITIONAL MISC. REPAIRS
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	INSTALL SPO PART HERE DRIVER SEAT BELT BUCKLE NOT LOCKING INTERMIT SPO# 01159003
<b>AREA_CD</b>	828
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171072
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	906
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	810
<b>VIN_CD</b>	1FMRU16W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/24/2001
<b>WRTY_START_D</b>	11/02/2001
<b>NAME</b>	SKYLINE FORD SALES, INC.
<b>DOC_NUM</b>	112789A
<b>PH_NUM</b>	3274500
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	8AA
<b>CUST_CONC_CD</b>	340
<b>COND_CD</b>	2
<b>RPR_DT</b>	11/15/2001
<b>TIS_WSD</b>	1
<b>CLM_KEY</b>	5161213
<b>MILGE</b>	888
<b>MTRL_COST</b>	
<b>TOY_COST_GROS</b>	

<b>LBR_HRS</b>	85
<b>DLR_CD</b>	543
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	a
<b>TECH_TXT1</b>	
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	S40**DRIVERSIDE DEAT BELT LATCH WILL NOT STAY LATCHED
<b>AREA_CD</b>	214
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152003
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	000
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	820
<b>VIN_CD</b>	1FMRU15W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/29/2001
<b>WRTY_START_D</b>	8/30/2001
<b>NAME</b>	GREENE FORD COMPANY
<b>DOC_NUM</b>	179248A
<b>PH_NUM</b>	5325620
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	825
<b>COND_CD</b>	41
<b>RPR_DT</b>	4/8/2002
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	7858216
<b>MILGE</b>	14120
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value="0"/>
<b>DLR_CD</b>	<input type="text" value="280"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="GA"/>
<b>CPSC_CD_6</b>	<input type="text" value="11001"/>
<b>Ratings</b>	<input type="text" value=""/>
<b>TECH_TXT1</b>	<input type="text" value="DIAG AND RR SEATBELT"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="CUSTOMER STATES SEAT BELT WILL NOT LATCH SOP HERE"/>
<b>AREA_CD</b>	<input type="text" value="770"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="121405"/>
<b>TXN_CD</b>	<input type="text" value="EM4"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V06"/>
<b>AWS_VL_CD</b>	<input type="text" value="E3"/>
<b>VRT_CD</b>	<input type="text" value="S08"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	821
<b>VIN_CD</b>	1FMRJ15W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/18/2001
<b>WRTY_START_D</b>	5/30/2001
<b>NAME</b>	ELVIN HAYES FORD
<b>DOC_NUM</b>	5115752
<b>PH_NUM</b>	3289555
<b>WCC_CD</b>	8F02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7#61202
<b>PART_NUM_CAU</b>	AAB
<b>CUST_CONC_CD</b>	S2B
<b>COND_CD</b>	42
<b>RPR_DT</b>	5/16/2002
<b>TIS_WSD</b>	12
<b>CLM_KEY</b>	8044940
<b>MILGE</b>	21284
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	02
<b>DLR_CD</b>	4448
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	
<b>TECH_TXT1</b>	CHECK SEAT BELT PASS FRONT COME OUT AT WILL COULD NOT CONFIRM RECAA WAS PERFORM AND PASSED REMOVE AND REPLACES SEAT BELT BUCKLE CHECK GOOD MT FOR NO LABOR OPPP
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	PASS SEAT BELT WILL NOT LOCK .... CK ALL SEAT BELTS
<b>AREA_CD</b>	281
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152044
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	E8
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	822
<b>VIN_CD</b>	1FMRU16W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	783
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	TEF
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TWN
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	4/12/2001
<b>WRTY_START_D</b>	5/2/2001
<b>NAME</b>	WATSON QUALITY FORD
<b>DOC_NUM</b>	1E8044A
<b>PH_NUM</b>	9667000
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1LTZ
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	S25
<b>COND_CD</b>	42
<b>RPR_DT</b>	9/27/2001
<b>TIS_WSD</b>	5
<b>CLM_KEY</b>	3063867
<b>MILGE</b>	6641
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	87
<b>DLR_CD</b>	6085
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MS
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	b
<b>TECH_TXT1</b>	0641 REPLACE DR FT SEAT BELT
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	825 DRIVERS SIDE SEAT BELT WONT STAY LATCHED
<b>AREA_CD</b>	801
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123508
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	021
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	808
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	829
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/28/2001
<b>WRTY_START_D</b>	4/14/2001
<b>NAME</b>	TEAM FORD
<b>DOC_NUM</b>	8491551
<b>PH_NUM</b>	3956100
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7861202
<b>PART_NUM_CAU</b>	AAC
<b>CUST_CONC_CD</b>	S20
<b>COND_CD</b>	42
<b>RPR_DT</b>	8/11/2002
<b>TIS_WSD</b>	15
<b>CLM_KEY</b>	0110771
<b>MILGE</b>	18778
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value=""/>
<b>DLR_CD</b>	<input type="text" value="3815"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="NV"/>
<b>CPSC_CD_6</b>	<input type="text" value="12001"/>
<b>Ratings</b>	<input type="text" value="A"/>
<b>TECH_TXT1</b>	<input type="text" value="SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="PASSENGER FRONT SEATBELT DOESNT LATCH"/>
<b>AREA_CD</b>	<input type="text" value="702"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="171167"/>
<b>TKN_CD</b>	<input type="text" value="E84"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V05"/>
<b>AWS_VL_CD</b>	<input type="text" value="B3"/>
<b>VRT_CD</b>	<input type="text" value="S08"/>
<b>TIS_FLAG</b>	<input type="text" value="0"/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	825
<b>VIN_CD</b>	1FMRU15W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/ND
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/13/2001
<b>WRTY_START_D</b>	4/13/2001
<b>NAME</b>	ERNE HAIRE FORD, INC.
<b>DOC_NUM</b>	8788482
<b>PH_NUM</b>	8330571
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881208
<b>PART_NUM_CAU</b>	8AB
<b>CUST_CONC_CD</b>	825
<b>COND_CD</b>	42
<b>RPR_DT</b>	12/27/2001
<b>TIS_WSD</b>	9
<b>CLM_KEY</b>	8888885
<b>MILGE</b>	18888
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LRR_HRS</b>	02
<b>DLR_CD</b>	4890
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	d
<b>TECH_TXT1</b>	TRACK ASSEMBLY FRONT SEAT REPLACE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	C S DRIVERS FRONT SEAT BELT UNBUCKLES WHEN STOPPING
<b>AREA_CD</b>	813
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124208
<b>TXN_CD</b>	E04
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	908
<b>TTS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	828
<b>VIN_CD</b>	1FMRU1BW31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/13/2001
<b>WRTY_START_D</b>	3/27/2001
<b>NAME</b>	BOB BROCK FORD, INC.
<b>DOC_NUM</b>	8778701
<b>PH_NUM</b>	2677424
<b>WCC_CD</b>	BR02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7B81203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	828
<b>COND_CD</b>	42
<b>RPR_DT</b>	6/6/2002
<b>TIS_WSD</b>	15
<b>CLM_KEY</b>	9038881
<b>MILGE</b>	28887
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	04
<b>DLR_CD</b>	2403
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	#
<b>TECH_TXT1</b>	REPLACE LEFT FRONT SEATBELT END
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUSTOMER STATES DRIVERS SEATBELT WILL NOT LATCH SOMETIME
<b>AREA_CD</b>	915
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152673
<b>TXN_CD</b>	EB4
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	908
<b>TIS_FLAG</b>	0

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	827
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T83
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/E
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/6/2001
<b>WRTY_START_D</b>	3/31/2001
<b>NAME</b>	PLANET FORD
<b>DOC_NUM</b>	15501301
<b>PH_NUM</b>	7125700
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	825
<b>COND_CD</b>	42
<b>RPR_DT</b>	10/23/2001
<b>TIS_WSD</b>	7
<b>CLM_KEY</b>	5031205
<b>MILGE</b>	15008
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	02
<b>DLR_CD</b>	2091
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	a
<b>TECH_TXT1</b>	VERIFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY, OK AT THIS TIME
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	ABB DRIVER SIDE SEAT BELT WILL NOT STAYED BUCKLE
<b>AREA_CD</b>	281
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	162092
<b>TXN_CD</b>	E84
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	808
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	528
<b>VIN_CD</b>	1FMRU15W31L
<b>LRR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	3/1/2001
<b>WRTY_START_D</b>	5/25/2001
<b>NAME</b>	PUENTE HILLS FORD
<b>DOC_NUM</b>	5328181
<b>PH_NUM</b>	8843873
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAC
<b>CUST_CONC_CD</b>	S26
<b>COND_CD</b>	1
<b>RPR_DT</b>	4/9/2002
<b>TIS_WSD</b>	14
<b>CLM_KEY</b>	7880021
<b>MILGE</b>	11352
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value="08"/>
<b>DLR_CD</b>	<input type="text" value="5950"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="CA"/>
<b>CPSC_CD_6</b>	<input type="text" value="11001"/>
<b>Ratings</b>	<input type="text" value="a"/>
<b>TECH_TXT1</b>	<input type="text" value="SEAT BELT BROKE FRONT REPLACE SEATBELT ASSEMBLY"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="LEFT SEAT BELT WILL NOT LATCH"/>
<b>AREA_CD</b>	<input type="text" value="628"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="171072"/>
<b>TXN_CD</b>	<input type="text" value="2"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V05"/>
<b>AWS_VL_CD</b>	<input type="text" value="B3"/>
<b>VRT_CD</b>	<input type="text" value="S08"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	830
<b>VIN_CD</b>	1FMRU16W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VEH_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	2/6/2001
<b>WRTY_START_D</b>	3/30/2001
<b>NAME</b>	CLAREMONT FORD
<b>DOC_NUM</b>	11503802
<b>PH_NUM</b>	6251500
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAC
<b>CUST_CONC_CD</b>	S40
<b>COND_CD</b>	42
<b>RPR_DT</b>	3/4/2002
<b>TIS_WSD</b>	12
<b>CLM_KEY</b>	7308123
<b>MILGE</b>	10988
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value="488"/>
<b>DLR_CD</b>	<input type="text" value="1751"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="CA"/>
<b>CPSC_CD_6</b>	<input type="text" value="11001"/>
<b>Ratings</b>	<input type="text" value="6"/>
<b>TECH_TXT1</b>	<input type="text" value="REPLD SEAT BELT BUCKLE"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="CUSTOMER STAETS SEAT BELT HARD TO OPERATE"/>
<b>AREA_CD</b>	<input type="text" value="908"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="171087"/>
<b>TXN_CD</b>	<input type="text" value="2"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value="Q21"/>
<b>VFG_CD</b>	<input type="text" value="V06"/>
<b>AWS_VL_CD</b>	<input type="text" value="B3"/>
<b>VRT_CD</b>	<input type="text" value="808"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	831
<b>VIN_CD</b>	1FMRU15W31
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TB3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	TXF
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TMN
<b>TRANS_CD</b>	TDL
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	2/2/2001
<b>WRTY_START_D</b>	3/28/2001
<b>NAME</b>	ADAMSON FORD, L.L.C.
<b>DOC_NUM</b>	072815A
<b>PH_NUM</b>	3242533
<b>WCC_CD</b>	6F02
<b>PART_NUM_CAU</b>	F85Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BBE
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	7/12/2001
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	2382623
<b>MILGE</b>	3062
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	04
<b>DLR_CD</b>	417
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AL
<b>CPSC_CD_6</b>	12001
<b>Ratings</b>	R
<b>TECH_TXT1</b>	3062 FOUND DRVS SEAT BELT BUCKLE NOT LATCHING REMOVED AND REPLACED BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	C S DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT
<b>AREA_CD</b>	205
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121011
<b>TXN_CD</b>	1
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	832
<b>VIN_CD</b>	1FMRU15W31L
<b>LRR_COST</b>	
<b>VEH_LINE_CD</b>	T/B3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/WD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DL
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	2/2/2001
<b>WRTY_START_D</b>	7/27/2001
<b>NAME</b>	ARMSTRONG FORD OF HOMESTEAD
<b>DOC_NUM</b>	898202
<b>PH_NUM</b>	2475112
<b>WCC_CD</b>	BR02
<b>PART_NUM_CAU</b>	1LTZ
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAA
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	1
<b>RPR_DT</b>	8/27/2001
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	5270847
<b>MILGE</b>	3578
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	08
<b>DLR_CD</b>	4332
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	11001
<b>Rating</b>	4
<b>TECH_TXT1</b>	REPLACED DRIVER SIDE SEAT BELT CP 61203 CG 42
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	PARTS REPLACEMENT SEAT BELT
<b>AREA_CD</b>	306
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124003
<b>TXN_CD</b>	E93
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	836
<b>VIN_CD</b>	1FMRU15W31L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TBS
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	8/16/2000
<b>WRTY_START_D</b>	9/16/2000
<b>NAME</b>	FIVE STAR FORD
<b>DOC_NUM</b>	147889A
<b>PH_NUM</b>	4885638
<b>WCC_CD</b>	8R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	7881203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	840
<b>COND_CD</b>	42
<b>RPR_DT</b>	2/8/2002
<b>TIS_WSD</b>	18
<b>CLM_KEY</b>	5783873
<b>MILGE</b>	31170
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	00
<b>DLR_CD</b>	2406
<b>DLR_SUB_CD</b>	.
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	11001
<b>Ratings</b>	a
<b>TECH_TXT1</b>	31170 BUCKEL R,ILT FT SEAT TO REPLACE SEAT BELT BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	INSP. L F SEAT BELT WILL NOT BUCKLE AT TIMES AND IS HARD TO BUCKLE AT OTHER TIMES
<b>AREA_CD</b>	817
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152020
<b>TXN_CD</b>	EB4
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	Q21
<b>VFG_CD</b>	V05
<b>AWS_VL_CD</b>	B3
<b>VRT_CD</b>	S08
<b>TIS_FLAG</b>	

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	836
<b>VIN_CD</b>	1FMRU16W21L
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TB3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TWD
<b>VER_SERIES_CD</b>	T/EF
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AP
<b>PRODN_DT</b>	7/16/2001
<b>WRTY_START_D</b>	10/8/2001
<b>NAME</b>	TEAM FORD
<b>DOC_NUM</b>	4084561
<b>PH_NUM</b>	3855100
<b>WCC_CD</b>	6R02
<b>PART_NUM_CAU</b>	1L7Z
<b>PART_NUM_CAU</b>	T881203
<b>PART_NUM_CAU</b>	BAB
<b>CUST_CONC_CD</b>	625
<b>COND_CD</b>	42
<b>RPR_DT</b>	8/7/2001
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	3119447
<b>MILGE</b>	12
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	