

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 5 OF 6

BOOK 5 OF 43

LBR_HRS	68
DLR_CD	3815
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	NV
CPSC_CD_6	11005
Ratings	0
TECH_TXT1	RECALL 01S21
TECH_TXT2	
CUST_TXT	DRIVERSIDE AND PASSENGER SIDE SEAT BELT BUCKLES INOP
AREA_CD	702
COUNTRY_CD	USA
SLS_DLR_CD	171187
TXN_CD	1
CNTRY SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	63
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	888
VIN_CD	1FMRU15W21L6
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T8
ENG_CD	TMN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	5/31/2001
WKTY_START_D	12/14/2001
NAME	KARL FLAMMER FORD INC
DOC_NUM	5928851
PH_NUM	9376131
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861292
PART_NUM_CAU	AAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	7/17/2001
TIS_WSD	0
CLM_KEY	247622S
MILGE	8
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	88
DLR_CD	4870
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	12001
Ratings	•
TECH_TXT1	REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLE INOP
AREA_CD	727
COUNTRY_CD	USA
SLS_DLR_CD	124213
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	899
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VRR_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	6/27/2001
NAME	KCONS STERLING FORD
DOC_NUM	1525261
PH_NUM	4307700
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861209
PART_NUM_CAU	BAC
CUST_CONC_CD	340
COND_CD	42
RPR_DT	1/18/2002
TIS_WSD	7
CLM_KEY	8360273
MILGE	14026
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="31"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="VA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="INSPECT 7 TEST SEAT BELT BUCKLE & VERIFIED NOT WORKING PROPERLY,R&R SEAT ASSB TO GAIN ACCEBS,REPLACE DRIVERS SEAT BELT BUCKLE ASSB."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DRIVERS SIDE FRONT SEAT BELT KEEPS COMING LOOSE..INSTALL SOP"/>
AREA_CD	<input type="text" value="X03"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="127044"/>
TKN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B5"/>
VRI_CD	<input type="text" value="908"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	841
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	
BOD_CAB_STL	TMD
VER_SERIES_CD	TEF
DRIVE_CD	TB
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/1/2001
WRTY_START_D	6/24/2001
NAME	MAGIC FORD
DOC_NUM	9622051
PH_NUM	2569000
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAA
CUST_CONC_CD	526
COND_CD	1
RPR_DT	8/22/2001
TIS_WSD	4
CLM_KEY	3207041
MILGE	5119
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	NA
DLR_CD	1884
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	B
TECH_TXT1	RT FRT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES RIGHT FRONT SEAT BELT INOP SOP
AREA_CD	881
COUNTRY_CD	USA
SLS_DLR_CD	171481
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B9
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	843
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	TB
ENG_CD	TVM
TRANS_CD	TDL
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	6/30/2001
NAME	FORD OF MONTEBELLO
DOC_NUM	78151502
PH_NUM	8348920
WCC_CD	6F02
PART_NUM_CAU	F85Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BEE
CUST_CONC_CD	840
COND_CD	41
RPR_DT	7/14/2001
TIS_WSD	1
CLM_KEY	2384580
MILGE	510
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	3250
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	R
TECH_TXT1	VERIFIED CONCERN, REPLACED BAD SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CK REASON WHY DRIVERS SEAT BELT BUCKLE WONT LOCK BELT AT TIMES INSTALL S.O.P.
AREA_CD	323
COUNTRY_CD	USA
SLS_DLR_CD	171007
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	844
VIN_CD	1FMRJ15W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	6/24/2001
NAME	ERNE HARE FORD, INC.
DOC_NUM	7582362
PH_NUM	8338571
WCC_CD	0F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	928
COND_CD	42
RPR_DT	8/21/2002
TIS_WSD	10
CLM_KEY	7577139
MILGE	14957
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4999"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="FL"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="0"/>
TECH_TXT1	<input type="text" value="RENEW DRIVER SEAT BELT ASSY"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUST STATES DRIVERS SEAT BELT COMES UNHOOKED"/>
AREA_CD	<input type="text" value="B13"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124445"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	845
VIN_CD	1FMRL15W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/22/2001
WRTY_START_D	9/9/2001
NAME	ESTABROOK MOTOR CO., INC.
DOC_NUM	18787801
PH_NUM	7822841
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	11/5/2001
TIS_WSD	2
CLM_KEY	4890720
MILGE	2601
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	8334
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	MS
CPSC_CD_6	11001
Ratings	
TECH_TXT1	RUN BCE DIAG. W NGS. RUN PINPOINT TEST. REPLACE LF FT SEAT BELT BUCKLE.
TECH_TXT2	
CUST_TXT	CLUST STATES SOP IS IN FROM FRI SEAT BELT
AREA_CD	228
COUNTRY_CD	USA
SLS_DLR_CD	124017
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	E3
VRT_CD	G08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	848
VIN_CD	1FMRJ16W21L
LBR_COST	
VEH_LINE_CD	T/BS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	5/11/2001
NAME	GILLESPIE FORD
DOC_NUM	7583161
PH_NUM	5081000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/1/2001
TIS_WSD	9
CLM_KEY	2751260
MILGE	2546
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0
DLR_CD	4646
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	SEATBELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	SEAT BELT DRIVERS SIDE COMES LOOSE WHILE DRIVING SOP PART HERE
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	162067
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	847
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DLI
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	6/13/2001
NAME	TREADWELL FORD
DOC_NUM	27553801
PH_NUM	4783351
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	GAA
CUST_CONC_CD	540
COND_CD	42
RPR_DT	10/16/2001
TIS_WSD	5
CLM_KEY	4490658
MILGE	16824
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	0520
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	DRIVERS SEAT BELT WILL POP LOOSE REPLACE DRIVERS SEAT BELT WAITING.....
TECH_TXT2	
CUST_TXT	CUST STATES DRIVERS SEAT BELT WILL POP LOOSE WHEN DRIVING, REBUCKLE AND WILL POP LOOSE AGAIN
AREA_CD	251
COUNTRY_CD	USA
SLS_DLR_CD	124017
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	850
VIN_CD	1FMRU16W21L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
ROD_CAB_STL	TND
VER_SERIES_CD	TEF
DRIVE_CD	T8
ENG_CD	TNN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	5/22/2001
NAME	CASA FORD, INC.
DOC_NUM	248510C
PH_NUM	7782272
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	EAA
CUST_CONC_CD	840
COND_CD	38
RPR_DT	8/5/2001
TIS_WSD	4
CLM_KEY	3506212
MILGE	3289
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	EA
DLR_CD	2046E
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	3269 42 DOES NOT OPERATE PROPERLY REPLACED L FRONT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVER SHOULDER HARNESS POPS LOOSE AT TIMES WHILE DRIVING
AREA_CD	915
COUNTRY_CD	USA
SLS_DLR_CD	162210
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	882
VIN_CD	1FMRL1BW21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/12/2001
WRTY_START_D	4/7/2001
NAME	DOWNTOWN FORD SALES
DOC_NUM	183481A
PH_NUM	4428031
WCC_CD	6R02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	41
RPR_DT	5/15/2002
TIS_WSD	14
CLM_KEY	8778880
MILGE	18711
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	
DLR_CD	7883
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	INSPECT. REPLACED L F SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVERS SEATBELT BUCKLE DOES NOT HOLD BELT AT TIMES. CHECK AND ADVISE.
AREA_CD	918
COUNTRY_CD	USA
SLS_DLR_CD	172201
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	854
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/15/2001
WRTY_START_D	7/30/2001
NAME	LA PLACE FORD, INC.
DOC_NUM	2228801
PH_NUM	8528000
WCC_CD	8P82
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7884203
PART_NUM_CAU	BAA
CUST_CONC_CD	828
COND_CD	42
RPR_DT	3/1/2002
TIS_WSD	8
CLM_KEY	7190573
MILGE	5884
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	4127
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	LA
CPSC_CD_6	11001
Rating	d
TECH_TXT1	SEAT BELT BUCKLE DEFECTIVE REPLACE DRIVER SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT N DR SIDE COMES APART WHILE DRIVING WILL NOT STAY LATCHED
AREA_CD	995
COUNTRY_CD	USA
SLS_DLR_CD	12ME0
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	855
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/4/2001
WRTY_START_D	7/14/2001
NAME	JONES FORD, INC.
DOC_NUM	9314251
PH_NUM	7448311
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7061203
PART_NUM_CAU	BAB
CUST_CONC_CD	908
COND_CD	42
RPR_DT	10/30/2001
TIS_WSD	4
CLM_KEY	4942895
MILGE	5707
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.5
DLR_CD	1026
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	11001
Ratings	
TECH_TXT1	DEFECTIVE REPLACED DEFECTIVE DRIVERS SEAT BELT BUCKLE MILEAGE ERROR ON PRIOR TICKET CAR HAS 6707
TECH_TXT2	
CUST_TXT	REPLACE DEFECTIVE SEATBELT BUCKLE SPW
AREA_CD	843
COUNTRY_CD	USA
SLS_DLR_CD	121281
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V03
AWS_VL_CD	SS
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	857
VIN_CD	1FMRJ15W21L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	VEF
DRIVE_CD	T/B
ENG_CD	T/VH
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	2/5/2001
WRTY_START_D	6/30/2001
NAME	CROSSROADS FORD, INC.
DOC_NUM	22252802
PH_NUM	4871881
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/27/2001
YIS_WSD	1
CLM_KEY	3348108
MILGE	2817
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	999
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPALCED DRIVER SIDE SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	CHECK SEAT BLETSSCP PART FOR DRIVERS SEAT
AREA_CD	919
COUNTRY_CD	USA
SLS_DLR_CD	121028
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	306
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	803
VIN_CD	1FMRJ18W21
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/N
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/3/2001
WRTY_START_D	2/20/2001
NAME	FIVE STAR FORD, INC.
DOC_NUM	004687C
PH_NUM	8163873
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAB
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	3/6/2002
FIS_WSD	13
CLM_KEY	7875828
MILGE	2B184
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.0
DLR_CD	7000
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OK
CPSC_CD_6	12001
Ratings	e
TECH_TXT1	25184 REPLACE RIGHT AND LEFT SEAT BELT FEMALE ENDS. (BUCKET SEATS WITH CONSOLE)
TECH_TXT2	
CUST_TXT	INSTALL SOP 2 SEAT BELTS DONT WORK PROPERLY
AREA_CD	405
COUNTRY_CD	USA
SLS_DLR_CD	152500
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	Ba
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	004
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	2/24/2001
NAME	TOWN EAST FORD
DOC_NUM	770755A
PH_NUM	2708441
WCC_CD	6FKZ
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	33
RPR_DT	9/29/2001
TIS_WSD	8
CLM_KEY	4045133
MILGE	3159
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="8182"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="TX"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="c"/>
TECH_TXT1	<input type="text" value="3189 42 REPLACED DRIVER SEAT BELT BUCKEL
DUE TO COMING LOOSE AT TIMES"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DRIVERS SEAT BELT COMES LOOSE, UNBUCKLES
AT TIMES, S.O.P. AT PARTS"/>
AREA_CD	<input type="text" value="872"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="152002"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	005
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T8F
DRIVE_CD	T8
ENG_CD	TMN
TRANS_CD	T8U
PLANT_CD	AP
PRODN_DT	1/29/2001
WRTY_START_D	4/1/2001
NAME	FREEDOM FORD, INC.
DOC_NUM	1110101
PH_NUM	7872277
WCC_CD	6F02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	41
RPR_DT	11/13/2001
TYS_WSD	8
CLM_KEY	6103787
MILGE	7801
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4807"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="FL"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="VERIFY SEAT BELT BUCKLE INOP, R&R PASSENGER SEAT ASSEMBLY, REPLACED SEAT BELT BUCKLE, CHECK OPERATION"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES PASSENGER FRONT SEAT BELT WASNT BUCKLEY CORRECTLY"/>
AREA_CD	<input type="text" value="727"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124202"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="B05"/>
TYS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	888
VIN_CD	1FMRU15W211
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
ROD_CAB_STL	T/PD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VH
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/24/2001
WRTY_START_D	2/19/2001
NAME	FRIENDLY FORD
DOC_NUM	24006301
PH_NUM	2668000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861208
PART_NUM_CAU	AAH
CUST_CONC_CD	840
COND_CD	42
RPR_DT	8/8/2001
TIS_WSD	5
CLM_KEY	2842806
MILGE	9167
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	NA
DLR_CD	3921
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	A
TECH_TXT1	1 REPLACED SOP DRIVERS SEAT BELT BUCKLE ASSEMBLY
TECH_TXT2	
CUST_TXT	CLIENT STATES DRIVERS SEAT BELT WONT LATCH. SOP HERE TO REPAIR.
AREA_CD	408
COUNTRY_CD	USA
SLS_DLR_CD	172039
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	867
VIN_CD	1FMRJ15W21L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/MO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	2/21/2001
NAME	TEXAN FORD
DOC_NUM	22320004
PH_NUM	4673673
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	1
RPR_DT	5/31/2002
TIS_WSD	16
CLM_KEY	8015344
MILGE	23517
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	2488
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Rating	9
TECH_TXT1	PERFORMED RECALL 01821, REPLACED DRIVERS SIDE SEAT BELT. 01821D...0.8...
TECH_TXT2	
CUST_TXT	PERFORM 01821 SEATBELT BUCKLE
AREA_CD	817
COUNTRY_CD	USA
SLS_DLR_CD	152010
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	S08
TIS_FLAG	6

MDL_YR	2001
SORT_INDEX	869
VIN_CD	1FMRU15W21L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAR_STL	TMO
VER_SERIES_CD	TEF
DRIVE_CD	TB
ENG_CD	TVN
TRANS_CD	TDL
PLANT_CD	AP
PRODN_DT	1/5/2001
WRTY_START_D	3/18/2001
NAME	PACIFIC FORD
DOC_NUM	2639551
PH_NUM	8276130
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	526
COND_CD	42
RPR_DT	4/12/2002
TIS_WSD	14
CLM_KEY	7982034
MILGE	18041
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	5412
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	0
TECH_TXT1	NA INSPECTED BUCKLE AND REPLACE RIGHT FRONT BUCKLE.
TECH_TXT2	
CUST_TXT	INSTALL SPECIAL ORDERED PART, SEAT BELT. USE SPO 02051000
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	171062
TXN_CD	E04
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	870
VIN_CD	1FMRU16W21
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T8
ENG_CD	T8N
TRANS_CD	T8J
PLANT_CD	AP
PRODN_DT	11/16/2000
WRTY_START_D	3/1/2001
NAME	SAM GALLOWAY FORD, INC.
DOC_NUM	52355401
PH_NUM	9369873
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7851203
PART_NUM_CAU	BAB
CUST_CONC_CD	S25
COND_CD	1
RPR_DT	8/27/2001
TIS_WSD	5
CLM_KEY	3254885
MILGE	11562
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.5
DLR_CD	4845
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACE DRIVER SIDE SEAT BELT RETEST SEAT BELT PASS TEST DONE
TECH_TXT2	
CUST_TXT	CUST STATES INSTALL SOP SEAT BELT BUCKLE
AREA_CD	041
COUNTRY_CD	USA
SLS_DLR_CD	124400
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B06
TTS_FLAG	

MDL_YR	2001
SORT_INDEX	872
VIN_CD	1FMRJ15W21
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	9/28/2000
WRTY_START_D	2/8/2001
NAME	JOHN CHANDLER FORD, INC.
DOC_NUM	4310351
PH_NUM	3784811
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881202
PART_NUM_CAU	AAC
CUST_CONC_CD	B40
COND_CD	1
RPR_DT	1/16/2001
TIS_WSD	10
CLM_KEY	5003884
MILGE	11838
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	SA
DLR_CD	2411
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	*
TECH_TXT1	BROKEN, CRACKED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	PASS SEAT BELT WILL NOT LATCH PART HERE
AREA_CD	806
COUNTRY_CD	USA
SLS_DLR_CD	152578
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	879
VIN_CD	1FMRU15WZ1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
ROD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/4/2000
WRTY_START_D	3/7/2001
NAME	BANKSTON FORD OF FRISCO, LTD.
DOC_NUM	18882602
PH_NUM	3385000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7981202
PART_NUM_CAU	AAA
CUST_CONC_CD	325
COND_CD	42
RPR_DT	12/31/2001
TIS_WSD	10
CLM_KEY	8037802
MILGE	7885
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0400
DLR_CD	2441
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	VERIFY CONCERN REPLACE SEAT BELT BUCKLE CORRECTED
TECH_TXT2	
CUST_TXT	PASS. SIDE SEAT BELT INOP WILL NOT LATCH AT TIMES
AREA_CD	072
COUNTRY_CD	USA
SLS_DLR_CD	152325
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	874
VIN_CD	1FMRU15W21
LBR_COST	
VEH_LINE_CD	T/E3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/E
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	9/22/2000
WRTY_START_D	3/12/2001
NAME	JOHNSON BROTHERS FORD, LTD.
DOC_NUM	13681802
PH_NUM	7765258
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAC
CUST_CONC_CD	528
COND_CD	42
RPR_DT	8/10/2002
TIS_WSD	16
CLM_KEY	9080282
MILGE	37762
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1155 of 1298

RQ04-011 E 3180

LBR_HRS	04
DLR_CD	2453
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	•
TECH_TXT1	1 R&R DRIVERS SEAT BELT BUCKLE ASSEMBLY. R&R SEAT TO ACCESS. RETEST. CC42
TECH_TXT2	
CUST_TXT	CUSTOMER STATES DRIVER SEATBELT LATCH INOP.SOP ORDERED BY QS.SEE DENNIS IN PARTS.
AREA_CD	254
COUNTRY_CD	USA
SLS_DLR_CD	152504
TXN_CD	E81
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	Ⓢ

MDL_YR	2001
SORT_INDEX	875
VIN_CD	1FMRU16W11
LBR_COST	
VEH_LINE_CD	17B3
MKT_DERIVED	
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/8/2001
WRTY_START_D	6/23/2001
NAME	TEXAN FORD, INC.
DOC_NUM	348457A
PH_NUM	6788100
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	12/21/2001
TIS_WSD	5
CLM_KEY	5801120
MILGE	4626
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	64
DLR_CD	4817
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	4828 FAULTY RT SIDE BUCKLE NEC TO REPLACE RT SIDE BUCKLE
TECH_TXT2	
CUST_TXT	RT FT SEATBELT WILL NOT LATCH
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152054
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	678
VIN_CD	1FMRU15W11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/ND
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/5/2001
WRTY_START_D	8/27/2001
NAME	SOUTH BAY FORD, INC.
DOC_NUM	0103351
PH_NUM	5440211
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7981202
PART_NUM_CAU	AAA
CUST_CONC_CD	L15
COND_CD	82
RPR_DT	7/29/2001
TIS_WSD	0
CLM_KEY	3042842
MILGE	10
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	388
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	.
TECH_TXT1	RECALL PERFORMED RECALL REPLACED SEAT BELT BUCKLE AT RIGHT FRONT
TECH_TXT2	
CUST_TXT	RECALL 01821 SAFETY RECALL SEAT BELT BUCKLES
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q23
VFG_CD	V07
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	877
VIN_CD	1FMRU16W11L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T8F
DRIVE_CD	T8
ENG_CD	T8N
TRANS_CD	T8DU
PLANT_CD	AP
PRODN_DT	08/2001
WRTY_START_D	10/1/2001
NAME	KARL FLAMMER FORD INC
DOC_NUM	8825251
PH_NUM	8975131
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/17/2001
TIS_WSD	0
CLM_KEY	2478222
MILGE	26
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1161 of 1298

RQ04-011 E 3188

LBR_HRS	
DLR_CD	4970
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACED SEAT BELT 01821 RECALL
TECH_TXT2	
CUST_TXT	SEAT BELT BUCKLES DONT LATCH
AREA_CD	727
COUNTRY_CD	USA
SLS_DLR_CD	124454
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	879
VIN_CD	1FMRU15W11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	5/30/2001
WRTY_START_D	9/23/2001
NAME	KEN GRODY FORD - CARLSBAD
DOC_NUM	4454851
PH_NUM	4389171
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	AAF
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/25/2001
TIS_WSD	0
CLM_KEY	2874216
MILGE	21
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	02
DLR_CD	5512
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPLACE BOTH FRONT SEAT BELTS.
TECH_TXT2	
CUST_TXT	BOTH FRONT SEAT BELTS WONT LATCH
AREA_CD	780
COUNTRY_CD	USA
SLS_DLR_CD	171102
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	680
VIN_CD	1FMRU16W111
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TTF
DRIVE_CD	TB
ENG_CD	TVN
TRANS_CD	TJU
PLANT_CD	AP
PRODN_DT	5/23/2001
WRTY_START_D	8/23/2001
NAME	CROSSROADS FORD, INC.
DOC_NUM	22133001
PH_NUM	4871861
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	540
COND_CD	42
RPR_DT	7/31/2001
TIS_WSD	0
CLM_KEY	3313732
MILGE	6
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	1
DLR_CD	000
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	
TECH_TXT1	REPLACED SEAT BELT PER ED KARAZIN
TECH_TXT2	
CUST_TXT	CUST STATES SEATELET FAILED
AREA_CD	019
COUNTRY_CD	USA
SLS_DLR_CD	121025
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	884
VIN_CD	1FMRL15W11
LBR_COST	
VEH_LINE_CD	TB9
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/8/2001
WRTY_START_D	8/25/2001
NAME	EVANS FORD INC
DOC_NUM	9532161
PH_NUM	6223873
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861202
PART_NUM_CAU	AAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	1/28/2002
TIS_WSD	6
CLM_KEY	8549811
MILGE	9826
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	54
DLR_CD	5778
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	12001
Ratings	
TECH_TXT1	RPL DEFECTIVE SEAT BELT FOUND BY SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	REPLACE DEFECTIVE SEAT BELT FOUND BY SEAT BELT RECALL INSPECTION
AREA_CD	282
COUNTRY_CD	USA
SLS_DLR_CD	121844
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	800
VIN_CD	1FMRU15W11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/W3
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/23/2001
WRTY_START_D	5/30/2001
NAME	RAY VILEE FORD, LLC
DOC_NUM	3451751
PH_NUM	4670704
WCC_CD	BR22
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	L29
COND_CD	42
RPR_DT	11/20/2001
TIS_WSD	8
CLM_KEY	5225428
MILGE	9508
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00000000000000000000
DLR_CD	5023
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TN
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	PERFORMED RECALL
TECH_TXT2	
CUST_TXT	SEAT BELT RECALL.01321.SPECIAL ORDERED PARTS HERE
AREA_CD	065
COUNTRY_CD	USA
SLS_DLR_CD	121068
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V77
AWS_VL_CD	B3
VRT_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	892
VIN_CD	1FMRU16W11L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	TB
ENG_CD	TVN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/14/2001
WRTY_START_D	5/29/2001
NAME	TREADWELL FORD
DOC_NUM	29819401
PH_NUM	4783851
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	S26
COND_CD	42
RPR_DT	6/8/2002
TIS_WSD	12
CLM_KEY	8723843
MILGE	28702
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="6528"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="AL"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="D"/>
TECH_TXT1	<input type="text" value="1 DRIVERS SEAT BELT BUCKLE WILL NOT HOLD. CK AND REPLACED SEAT BELT. RETEST"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUST STATES DRIVERS SEAT BELT BUCKLE WONT HOLD, IF BUMP IT WILL LET GO"/>
AREA_CD	<input type="text" value="261"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124017"/>
TXN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
YIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	894
VIN_CD	1FMRU16W11
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VEH_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/5/2001
WRTY_START_D	4/28/2001
NAME	KARL FLAMMER FORD INC
DOC_NUM	0000461
PH_NUM	8375131
WCC_CD	8R02
PART_NUM_CAU	1172
PART_NUM_CAU	7881203
PART_NUM_CAU	8AB
CUST_CONC_CD	540
COND_CD	42
RPR_DT	8/11/2001
TIS_WSD	4
CLM_KEY	4041028
MILGE	5172
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	4870
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	RECALL REPLACE BOTH ISDES BUCKLES PER 01S21
TECH_TXT2	
CUST_TXT	RECALL 01S21 BOTH FAILED CUS
AREA_CD	727
COUNTRY_CD	USA
SLS_DLR_CD	124454
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	887
VIN_CD	1FMRU15W11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/12/2001
WRTY_START_D	4/29/2001
NAME	WALKER FORD COMPANY, INC.
DOC_NUM	8946001
PH_NUM	5353873
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	T80
COND_CD	42
RPR_DT	4/24/2002
TIS_WSD	13
CLM_KEY	8185065
MILGE	11714
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	EA
DLR_CD	4947
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	RECALL 01821 TECH 14807 MO 11714 REMOVED AND REPLACED DRIVERS SIDE SEAT BELT LATCH BUCKET POWER SEAT
TECH_TXT2	
CUST_TXT	T80 RT FRT DRIVERS SEAT BELT BUCKLE FAILS RECALL TEST 01821 ON RD 85291 INSTALL SOP DRIVERS SEAT BELT BUCKLE
AREA_CD	727
COUNTRY_CD	USA
SLS_DLR_CD	124202
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	896
VIN_CD	1FMRU15N11L
LBR_COST	
VEH_LINE_CD	T/B9
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	9/12/2001
WRTY_START_D	7/25/2001
NAME	FAMILY FORD SALES, INC.
DOC_NUM	2824863
PH_NUM	7843351
WCC_CD	5R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	BAC
CUST_CONC_CD	525
COND_CD	42
RPR_DT	9/14/2001
TIS_WSD	2
CLM_KEY	3744608
MILGE	3264
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	8.2
DLR_CD	3085
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	11001
Ratings	.
TECH_TXT1	PASS FRONT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	PASS FRONT SEAT BELT INOP PARTS IN 316
AREA_CD	298
COUNTRY_CD	USA
SLS_DLR_CD	121108
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	898
VIN_CD	1FMRU15W11L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/7/2001
WRTY_START_D	7/31/2001
NAME	JIM CHRISTANELLI FORD, INC.
DOC_NUM	00684A
PH_NUM	5823555
WCC_CD	8R02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7581202
PART_NUM_CAU	AAA
CUST_CONC_CD	840
COND_CD	1
RPR_DT	1/18/2002
TIS_WSD	6
CLM_KEY	7385062
MILGE	11313
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	806
DLR_CD	2410
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	8
TECH_TXT1	REPLACE PASSENGER SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	FAULTY SEAT BELT BUCKLES
AREA_CD	940
COUNTRY_CD	USA
SLS_DLR_CD	152620
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	B08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	900
VIN_CD	1FMRU1BW11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EP
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	3/7/2001
WRTY_START_D	4/22/2001
NAME	SAWGRASS FORD
DOC_NUM	36412701
PH_NUM	8519000
WCC_CD	6RD2
PART_NUM_CAU	1L72
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	2/26/2002
TIS_WSD	11
CLM_KEY	7218535
MILGE	4571
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1181 of 1298

LBR_HRS	04
DLR_CD	4908
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	SEAT BUCKLE IN OP AT THIS, RELEASES BELT 011 INSPECT AND TEST DRIVER SEAT BUCKLE ASSY, REMOVE DRIVER SEAT AND REPLACE BUCKLE ASSY, TEST OP
TECH_TXT2	
CUST_TXT	C STATES DRIVERS SEAT BELT SNAPS OFF
AREA_CD	054
COUNTRY_CD	USA
SLS_DLR_CD	124003
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	608
TES_FLAG	

MDL_YR	2001
SORT_INDEX	903
VIN_CD	1FMRU15W111
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/M
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/30/2001
WRTY_START_D	4/29/2001
NAME	SAM PACK'S FIVE STAR FORD
DOC_NUM	315233A
PH_NUM	2428415
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAA
CUST_CONC_CD	T90
COND_CD	42
RPR_DT	12/29/2001
TIS_WSD	6
CLM_KEY	6013034
MILGE	10112
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	2459
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	10112 42 61384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CK DRIVERS SEAT BELT WONT STAY ATTACHED
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152014
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	905
VIN_CD	1FMRL15W11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/31/2001
WRTY_START_D	2/18/2001
NAME	MOSS BROS. FORD
DOC_NUM	2478351
PH_NUM	825(212)
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAC
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	2/21/2002
TIS_WSD	13
CLM_KEY	7243075
MILGE	9999
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4868"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="SEAT BELT BUCKLES INOP REPL INOP FRONT SEAT BELT BUCKLES"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="REPLACE SEAT BELT BUCKLES THAT FAILED UNDER RECALL 01S21 SEAT BELT BUCKLE S.O.P. ARE HERE"/>
AREA_CD	<input type="text" value="909"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171150"/>
TKN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B5"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	807
VIN_CD	1FMRU15W11L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	TAMD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TMN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	1/5/2001
WRTY_START_D	4/18/2001
NAME	NORTHGATE LINCOLN-MERCURY INC
DOC_NUM	38883901
PH_NUM	9336781
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	5/23/2002
TIS_WSD	14
CLM_KEY	8783855
MILGE	12052
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	11645
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	1 REPLACED DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DRIVERSIDE SEAT BELT WILL NOT OPERATE INSTALL SPECIAL ORDER PART
AREA_CD	813
COUNTRY_CD	USA
SLS_DLR_CD	124486
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	BS
VRT_CD	S08
TIS_FLAG	0

MDL_YR	2001
SORT_INDEX	908
VIN_CD	1FMRU15W11L
LBR_COST	558
VEH_LINE_CD	T83
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	11/13/2000
WRTY_START_D	8/14/2001
NAME	KINGS COLONIAL FORD, INC.
DOC_NUM	7885301
PH_NUM	2346400
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	2/25/2002
TIS_WSD	8
CLM_KEY	7080814
MILGE	8851
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1189 of 1298

LBR_HRS	9.4
DLR_CD	4847
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	DOES NOT WORK PROPERLY. REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY.
TECH_TXT2	
CUST_TXT	CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE DOES NOT WORK PROPERLY
AREA_CD	912
COUNTRY_CD	USA
SLS_DLR_CD	124452
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	810
VIN_CD	1FMRJ15W11L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/W/D
VER_SERIES_CD	T/EF
DRIVE_CD	T/8
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/25/2000
WRTY_START_D	11/12/2000
NAME	SANTA MARGARITA FORD
DOC_NUM	217708A
PH_NUM	4596800
WCC_CD	6R02
PART_NUM_CAU	1L72
PART_NUM_CAU	
PART_NUM_CAU	AAB
CUST_CONC_CD	540
COND_CD	12
RPR_DT	12/12/2001
TIS_WSD	14
CLM_KEY	5505708
MILGE	14007
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	<input type="text" value="0000000000"/>
DLR_CD	<input type="text" value="1587"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="0"/>
TECH_TXT1	<input type="text" value="14007 RECALL 015210 D.4 REPLACE PASSENGER SIDE SEATBELT BUCKLE PER RECALL"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="01821 REPLACE PASSENGER SIDE SEAT BELT BUCKLE SOP IN"/>
AREA_CD	<input type="text" value="949"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171082"/>
TXN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	811
VIN_CD	1FMRU15W11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/M
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	10/12/2000
WRTY_START_D	11/17/2000
NAME	PRESTIGE FORD
DOC_NUM	21317801
PH_NUM	8843873
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	11/10/2001
TIS_WSD	12
CLM_KEY	6097318
MILGE	18425
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	2415
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	REPL BUCKLE ASSY
TECH_TXT2	
CUST_TXT	SOP HERE FOR SEAT RECALL 01621 REF NO 200456
AREA_CD	972
COUNTRY_CD	USA
SLS_DLR_CD	152012
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S00
TLS_FLAG	

MDL_YR	2001
SORT_INDEX	913
VIN_CD	1FMRL15W11
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	TB
ENG_CD	TMN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	8/17/2000
WRTY_START_D	11/16/2000
NAME	BOB WONDRIES FORD
DOC_NUM	251353A
PH_NUM	2803581
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	\$2B
COND_CD	41
RPR_DT	5/20/2002
TIS_WSD	1B
CLM_KEY	8721727
MILGE	16286
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="6:30"/>
DLR_CD	<input type="text" value="6620"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="16285 MT 81202 O.B INSPECTED AND REPLACED RT. FRONT SEATBELT BUCKLE , R AND R RT.BEAT FOR ACCESS"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATED RIGHT FRONT SEAT BELT BUCKLE INOP."/>
AREA_CD	<input type="text" value="626"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171040"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="E3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value="9"/>

MDL_YR	2001
SORT_INDEX	916
VIN_CD	1FMRU15WD1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	6/12/2001
WRTY_START_D	2/12/2002
NAME	TAMIAMI FORD, INC.
DOC_NUM	2636201
PH_NUM	6433873
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAC
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	7/20/2001
TIS_WSD	0
CLM_KEY	2654121
MILGE	7
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	03
DLR_CD	1258
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	12001
Ratings	9
TECH_TXT1	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	RECALL 01321 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 7T
AREA_CD	041
COUNTRY_CD	USA
SLS_DLR_CD	124426
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	918
VIN_CD	1FMRU15W01L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/M
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/30/2001
WRTY_START_D	6/30/2001
NAME	UNIVERSITY FORD, INC.
DOC_NUM	4748152
PH_NUM	*
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	B28
COND_CD	42
RPR_DT	3/19/2002
TIS_WSD	9
CLM_KEY	7802816
MILGE	15818
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4140"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NC"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="PASSENGER SIDE SEAT BELT INOP"/>
AREA_CD	<input type="text" value=""/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121028"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	917
VIN_CD	1FMRU15W01
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	9/9/2001
NAME	SOUTH BAY FORD, INC.
DOC_NUM	6118761
PH_NUM	6440211
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	AAB
CUST_CONC_CD	L15
COND_CD	62
RPR_DT	7/30/2001
TIS_WSD	0
CLM_KEY	8077195
MILGE	12
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0%
DLR_CD	359
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	RECALL PERFORMED RECALL REPLACED 2 SEAT BELTS
TECH_TXT2	
CUST_TXT	RECALL 01921 SEAT BELT BUCKLE
AREA_CD	310
COUNTRY_CD	USA
SLS_DLR_CD	171018
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V07
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	015
VIN_CD	1FMRU15W01
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	T1B
ENG_CD	T1VN
TRANS_CD	T10U
PLANT_CD	AP
PRODN_DT	5/22/2001
WRTY_START_D	7/17/2001
NAME	CLAREMONT FORD
DOC_NUM	11060201
PH_NUM	6251600
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	AAF
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	12/28/2001
TIS_WSD	6
CLM_KEY	6036706
MILGE	6823
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0A
DLR_CD	1781
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	RECALL INSTALLED RECALL SEATBELT BUCKLE AG9
TECH_TXT2	
CUST_TXT	
AREA_CD	000
COUNTRY_CD	USA
SLS_DLR_CD	171087
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	821
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	5/8/2001
WRTY_START_D	6/30/2001
NAME	SKYLINE FORD SALES, INC.
DOC_NUM	1125888
PH_NUM	3274600
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	1
RPR_DT	11/13/2001
TIS_WSD	B
CLM_KEY	6082887
MILGE	8780
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	543
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	
TECH_TXT2	
CUST_TXT	S40 PASS SIDE MIDDLE SEAT BELT LATCH COMING APART
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	152003
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	922
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TIEF
DRIVE_CD	TB
ENG_CD	TWN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	5/10/2001
WRTY_START_D	7/30/2001
NAME	WOODY ANDERSON FORD
DOC_NUM	8741351
PH_NUM	3399441
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801202
PART_NUM_CAU	AAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/5/2001
YIS_WSD	5
CLM_KEY	5828712
MILGE	2800
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	607
DLR_CD	5902
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	AL
CPSC_CD_6	12001
Ratings	d
TECH_TXT1	RECALL INSPECT PER RECALL, R+R RT. FT. SEAT REPLACE BUCKLE
TECH_TXT2	
CUST_TXT	GUEST STATES PASS FRONT SEAT BELT WILL NOT STAY LATCHED UNBUCKLES WHEN DRIVING DOWN THE ROAD AND LEFT
AREA_CD	258
COUNTRY_CD	USA
SLS_DLR_CD	121717
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	021
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TES_FLAG	

MDL_YR	2001
SORT_INDEX	824
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWO
VKR_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	8/22/2001
NAME	MOREHEAD CITY FORD
DOC_NUM	7356801
PH_NUM	2472132
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	78B1203
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	41
RPR_DT	8/31/2001
TIS_WSD	1
CLM_KEY	4574784
MILGE	486
MTRL_COST	
TOT_COST_GROS	