

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 6 OF 6

BOOK 5 OF 43

LBR_HRS	<input type="text" value="0.00"/>
DLR_CD	<input type="text" value="1101"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NC"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="E COMPLETED ABOVE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES THAT THE FRONT SEAT BELT ARE NOT LOCKING IN NEEDS LEFT AND RIGHT SIDE BELT TRIM CODE 12"/>
AREA_CD	<input type="text" value="252"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121847"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="800"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	825
VIN_CD	1FMRJ15W011
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/25/2001
WRTY_START_D	7/10/2001
NAME	GEORGE BALLENTINE FORD LINCOLN
DOC_NUM	041254A
PH_NUM	2234351
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S28
COND_CD	42
RPR_DT	6/8/2002
TIS_WSD	12
CLM_KEY	9012240
MILGE	30503
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	973
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	SC
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	INSPECTED, REPLACED BOTH FRONT SEATBELT ASSEMBLY, TEST & RETEST.
TECH_TXT2	
CUST_TXT	SEATBELT SOP
AREA_CD	004
COUNTRY_CD	USA
SLS_DLR_CD	121794
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TTS_FLAG	0

MDL_YR	2001
SORT_INDEX	025
VIN_CD	1FMRU15W01
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/M
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	4/27/2001
WRTY_START_D	5/25/2001
NAME	JOE MACPHERSON FORD
DOC_NUM	4220101
PH_NUM	8329300
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801209
PART_NUM_CAU	BAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	4/24/2002
TIS_WSD	9
CLM_KEY	8288488
MILGE	8403
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	5414
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	"
TECH_TXT1	SEAT BELT BUCKLE REPALCE LEFT SIDE SEAT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DR SIDE SEAT BELT INOP SOP IN
AREA_CD	714
COUNTRY_CD	USA
SLS_DLR_CD	171057
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	927
VIN_CD	1FMRJ15W011 [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	T8
ENG_CD	T/MN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	7/30/2001
NAME	GWINNETT PLACE FORD
DOC_NUM	8153551
PH_NUM	4782080
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	826
COND_CD	1
RPR_DT	8/20/2001
TIS_WSD	1
CLM_KEY	3322499
MILGE	416
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="3573"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="GA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="C"/>
TECH_TXT1	<input type="text" value="BROKEN SEATBELT ASSEMBLY
FRONT REPLACE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUST STATES DRIVER SEAT BELT SNAPS LOOSE
BY ITSELF POPS OUT BY ITSELF"/>
AREA_CD	<input type="text" value="770"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121025"/>
TXN_CD	<input type="text" value="Z"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="021"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	928
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	TBS
MET_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	TJF
DRIVE_CD	TB
ENG_CD	TVN
TRANS_CD	TDU
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	8/4/2001
NAME	JOHN BLEAKLEY FORD INC
DOC_NUM	8796651
PH_NUM	8410000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	11/7/2001
TIS_WSD	8
CLM_KEY	5002705
MILGE	6387
MTBL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="487"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="GA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="C"/>
TECH_TXT1	<input type="text" value="INOP SEATBELT ASSEMBLY
FRONT REPLACE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CUSTOMER STATES DRIVERS SEAT BELT KEEP
COMING UNBUCKLED"/>
AREA_CD	<input type="text" value="770"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121058"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="E3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	029
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TAND
VER_SERIES_CD	TIEF
DRIVE_CD	T/B
ENG_CD	TVN
TRANS_CD	TIDU
PLANT_CD	AP
PRODN_DT	4/20/2001
WRTY_START_D	8/13/2001
NAME	PARAMOUNT FORD
DOC_NUM	2977901
PH_NUM	8742181
WCC_CD	6RD2
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7051203
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	9/20/2001
TIS_WSD	2
CLM_KEY	4476593
MILGE	1907
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="1140"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="NC"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACED SEAT BELT"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="SEAT BELT ON DRIVERS SIDE INOP"/>
AREA_CD	<input type="text" value="R25"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121610"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	930
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/13/2001
NAME	WORTHINGTON FORD
DOC_NUM	13845102
PH_NUM	4203333
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	9/10/2001
TIS_WSD	5
CLM_KEY	3560062
MILGE	3958
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0
DLR_CD	7933
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	9
TECH_TXT1	REPLACED DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	CS THAT THE DRIVERS SEAT BELT WILL NOT FASTEN AT TIMES
AREA_CD	562
COUNTRY_CD	USA
SLS_DLR_CD	171051
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B9
VRT_CD	805
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	934
VIN_CD	1FMRU16W01L
LBR_COST	
VEH_LINE_CD	783
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	T7B
ENG_CD	T7VN
TRANS_CD	T7DU
PLANT_CD	AP
PRODN_DT	4/19/2001
WRTY_START_D	5/9/2001
NAME	ALBANY FORD, INC.
DOC_NUM	5934651
PH_NUM	0839100
WCC_CD	8F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8AB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	10/3/2001
TIS_WSD	5
CLM_KEY	4143588
MILGE	6718
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	3852
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACED SEAT BELT LATCH
TECH_TXT2	
CUST_TXT	DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED
AREA_CD	229
COUNTRY_CD	USA
SLS_DLR_CD	121408
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	835
VIN_CD	1FMRJ15W01
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAR_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/8
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	4/10/2001
WRTY_START_D	4/28/2001
NAME	FIVE STAR FORD
DOC_NUM	144448A
PH_NUM	4888638
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAA
CUST_CONC_CD	625
COND_CD	42
RPR_DT	1/11/2002
TIS_WSD	9
CLM_KEY	8188128
MILGE	7124
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0
DLR_CD	2488
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	
TECH_TXT1	7124 W INSP AND REPLACED PASS SIDE SEAT BELT RETESTED ALL OK
TECH_TXT2	
CUST_TXT	SOP IN CUST STATES VEH HAS SEAT BUCKLE WILL NOT LATCH.
AREA_CD	517
COUNTRY_CD	USA
SLS_DLR_CD	152020
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	308
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	938
VIN_CD	1FMRU16WD1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	5/3/2001
NAME	HALL FORD
DOC_NUM	312274C
PH_NUM	9889700
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	42
RPR_DT	5/8/2002
TIS_WSD	14
CLM_KEY	9090548
MILGE	26888
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="0642"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="VA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="d"/>
TECH_TXT1	25888 SEATBELT ON DRIVERS SIDE FOUND FAULTY WARR VERIFIED CONCERN, FOUND SEATBELT BUCKLE FAULTY, REMOVED SEATBELT BUCKLE, REPLACED SEATBELT BUCKL E, VERIFIED REPAIR
TECH_TXT2	
CUST_TXT	CLIST STATES THAT THE DRIVERS SIDE SEAT BELT COMES UNBUCKLED WHILE DRIVING
AREA_CD	<input type="text" value="T57"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="127000"/>
TXN_CD	<input type="text" value="EM4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value="0"/>

MDL_YR	2001
SORT_INDEX	839
VIN_CD	1FMRU19W01L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	3/5/2001
WRTY_START_D	4/21/2001
NAME	WORLD OF FORD SALES INC
DOC_NUM	5755201
PH_NUM	6508000
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851203
PART_NUM_CAU	BAA
CUST_CONC_CD	S21
COND_CD	41
RPR_DT	8/8/2001
TIS_WSD	6
CLM_KEY	3570734
MILGE	4586
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="04"/>
DLR_CD	<input type="text" value="141"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="VA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACE DRIVERS SIDE SEAT BELT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="REPLACE SOP SEAT BELT"/>
AREA_CD	<input type="text" value="709"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="127006"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	940
VIN_CD	1FMRU15A7011
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DAJ
PLANT_CD	AP
PRODN_DT	3/3/2001
WRTY_START_D	3/3/2001
NAME	NORTHSIDE FORD
DOC_NUM	33893301
PH_NUM	5259800
WCC_CD	BF02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	2/11/2002
FIS_WSD	11
CLM_KEY	5844038
MILGE	14841
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	004
DLR_CD	4410
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD
TECH_TXT2	
CUST_TXT	S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING
AREA_CD	210
COUNTRY_CD	USA
SLS_DLR_CD	152083
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	E3
VRT_CD	508
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	945
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/M
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	3/4/2001
NAME	PUENTE HILLS FORD
DOC_NUM	3122981
PH_NUM	9643573
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7801203
PART_NUM_CAU	BAC
CUST_CONC_CD	840
COND_CD	1
RPR_DT	8/29/2001
TIS_WSD	6
CLM_KEY	3383213
MILGE	8482
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="5550"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CP8C_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="d"/>
TECH_TXT1	<input type="text" value="ACCESS BOTH SEATS, REPL BUCKLES TRACK
ASSEMBLY FRONT SEAT REPLACE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DIAG DRIVER AND PASS SEAT BELTS UNLOCK
WHILE DRIVING DOWN THE FREEWAY"/>
AREA_CD	<input type="text" value="826"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171072"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="89"/>
VRT_CD	<input type="text" value="505"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	947
VIN_CD	1FMRU16W01L
LBR_COST	
VEH_LINE_CD	T1B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T1B
ENG_CD	T/VN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	1/17/2001
WRTY_START_D	2/1/2001
NAME	WORLD FORD SANDY SPRINGS
DOC_NUM	3093051
PH_NUM	3631773
WCC_CD	0F02
PART_NUM_CAU	1L72
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	7/9/2001
TIS_WSD	8
CLM_KEY	2315580
MILGE	14228
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	GA
DLR_CD	450
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	12001
Ratings	a
TECH_TXT1	BUCKEL SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CURT REPORTS CHECK PASSENGER FRONT SEAT BELT WONT BUCKEL
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	124227
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	648
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VBR_SERIES_CD	TEF
DRIVE_CD	T/8
ENG_CD	T/VN
TRANS_CD	T/OU
PLANT_CD	AP
PRODN_DT	11/15/2000
WRTY_START_D	7/31/2001
NAME	MULLINAX FORD
DOC_NUM	320122A
PH_NUM	8887800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	11/7/2001
TIS_WSD	4
CLM_KEY	4848204
MILGE	5190
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	BA
DLR_CD	3073
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	2
TECH_TXT1	5180 42 W R&R DRIVERS SEAT FOR ACCESS, INSTALL DRIVERS BELT BUCKLE
TECH_TXT2	
CUST_TXT	340 DRIVER SEAT BELT NOT CLICKING TO LOCK
AREA_CD	407
COUNTRY_CD	USA
SLS_DLR_CD	124227
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	949
VIN_CD	1FMRLL15W011
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	.
BOD_CAB_STL	T/ND
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/28/2000
WRTY_START_D	12/24/2000
NAME	THEODORE ROBINS, INC.
DOC_NUM	8048851
PH_NUM	8420010
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	
PART_NUM_CAU	NAC
CUST_CONC_CD	S28
COND_CD	1
RPR_DT	1/29/2002
TIS_WSD	14
CLM_KEY	6578488
MILGE	13887
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1239 of 1298

LBR_HRS	64
DLR_CD	3506
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	B
TECH_TXT1	BROKEN SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES RIGHT FRT SEATBELT**** FEMALE SIDE WONT LATCH
AREA_CD	940
COUNTRY_CD	USA
SLS_DLR_CD	171089
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	050
VIN_CD	1FMRU15W01L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SRRIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VN
TRANS_CD	T/DU
PLANT_CD	AP
PRODN_DT	10/27/2000
WRTY_START_D	1/28/2001
NAME	BILLINGSLEY FORD OF LAWTON, IN
DOC_NUM	1112621
PH_NUM	2482300
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	1/4/2002
TIS_WSD	12
CLM_KEY	8114872
MILGE	16577
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	94
DLR_CD	1771
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	OK
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	REPALCED DRIVERS SIDE SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	DIAG DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES CUST HAS TO FIRST PUSH RELEASE AND THEN IT WILL BUCKLE CHECK ALL OTHERS
AREA_CD	405
COUNTRY_CD	USA
SLS_DLR_CD	152603
TXN_CD	E34
CNTRY_SOLD	USA
QRT_CD	C21
VFG_CD	V06
AWS_VL_CD	E3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	951
VIN_CD	1FMRU16W01L
LBR_COST	
VEH_LINE_CD	TBS
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TMN
TRANS_CD	T/DJ
PLANT_CD	AP
PRODN_DT	8/30/2000
WRTY_START_D	10/17/2000
NAME	GWINNETT PLACE FORD
DOC_NUM	9126461
PH_NUM	4762080
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	T80
COND_CD	33
RPR_DT	11/15/2001
TIS_WSD	14
CLM_KEY	6218483
MILGE	28354
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	0.8
DLR_CD	3573
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	0
TECH_TXT1	REPLACED SEAT BELT 01821
TECH_TXT2	
CUST_TXT	RECALL 01S21 DRIVER FRONT SEAT BELT USE SPO 01309037
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121060
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	064
VIN_CD	1FMRU15LX1L6
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T8F
DRIVE_CD	T8
ENG_CD	TVZ
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	4/28/2001
WRTY_START_D	6/23/2001
NAME	JIM KEIM FORD, INC.
DOC_NUM	172025B
PH_NUM	8883332
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	8A8
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/14/2001
TIS_WSD	6
CLM_KEY	6806289
MILGE	8871
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1245 of 1298

LBR_HRS	05
DLR_CD	1470
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	OH
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	REPLACE SEAT BELT ASSY
TECH_TXT2	
CUST_TXT	CHECK SEAT BELT
AREA_CD	B14
COUNTRY_CD	USA
SLS_DLR_CD	147030
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	956
VIN_CD	1FMRU1BLX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	11/30/2001
NAME	MCREE FORD, INC.
DOC_NUM	429000A
PH_NUM	3971529
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	625
COND_CD	33
RPR_DT	12/4/2001
TIS_WSD	1
CLM_KEY	9638366
MILGE	148
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	03
DLR_CD	4443
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	d
TECH_TXT1	R/R SEAT CAPTAINS CHAIR TO REPLACE SEAT BELT AS SEMBLY, LOOSE.
TECH_TXT2	
CUST_TXT	THE DRIVERS SEAT BELT RELEASES WHILE DRIVING
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	162052
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	989
VIN_CD	1FMRU15LX1U [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T1B3
MKT_DERIVED	*
ROD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	T1B
ENG_CD	T1VZ
TRANS_CD	T1DE
PLANT_CD	AP
PRODN_DT	2/18/2001
WRTY_START_D	10/8/2001
NAME	MOSS BROS. FORD
DOC_NUM	2240252
PH_NUM	8251212
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAC
CUST_CONC_CD	638
COND_CD	42
RPR_DT	1/7/2002
TIS_WSD	4
CLM_KEY	6228138
MILGE	4181
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="4358"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="8"/>
TECH_TXT1	<input type="text" value="DRY SEAT BELT BUCKLE INOP CHECK AND
NECESS TO REPL INOP DRY SEAT BELT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="SOP SEAT BELT"/>
AREA_CD	<input type="text" value="908"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171150"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	981
VIN_CD	1FMRU16LX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIRS_CD	T/EF
DRIVE_CD	T/B
BNG_CD	T/NZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/1/2001
WRTY_START_D	4/7/2001
NAME	FORD WEST
DOC_NUM	3838551
PH_NUM	7803873
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	CAB
CUST_CONC_CD	T00
COND_CD	42
RPR_DT	7/6/2001
TIS_WSD	4
CLM_KEY	2220194
MILGE	6337
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	83
DLR_CD	5440
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	INSTALL SOP DRIVER SEAT BELT TECH#307
AREA_CD	662
COUNTRY_CD	USA
SLS_DLR_CD	171047
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V74
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	985
VIN_CD	1FMRL115LX11
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	1/7/2001
WRTY_START_D	8/14/2001
NAME	BOB BAKER FORD MISSION VALLEY
DOC_NUM	385532A
PH_NUM	2876001
WCC_CD	6F02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	T90
COND_CD	33
RPR_DT	11/7/2001
TIS_WSD	3
CLM_KEY	4883723
MILGE	4080
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="5518"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value="9"/>
TECH_TXT1	<input type="text" value="4860 61202 83 RIGHT FRONT SEAT BELT BUCKLE WAS LOOSE R.I RIGHT FRONT SEAT TRACK TO REPLACE SEAT BELT BUCKLE. 61172A.4 61704AC .6"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="PASSENGER SIDE FRONT SEAT BELT BUCKLE CLICKS."/>
AREA_CD	<input type="text" value="B19"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171080"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V74"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	984
VIN_CD	1FMRU15LX1L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAR_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/112000
WRTY_START_D	12/2/2000
NAME	DON DAVIS FORD, INC.
DOC_NUM	416886B
PH_NUM	2814281
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAC
CUST_CONC_CD	S25
COND_CD	42
RPR_DT	2/1/2002
TIS_WSD	15
CLM_KEY	6662938
MILGE	8573
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="2417"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="TX"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="6573 REPLACED LEFT FRONT SEAT BELT LATCH.
*** QUALITY CONTROL BY JOHN MEDROW ***"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="INSTALL SO SEAT BELT ORDERED WHEN IT
FAILED SEAT BELT RETENTION RECALL"/>
AREA_CD	<input type="text" value="817"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="162018"/>
TXN_CD	<input type="text" value="EB4"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="S08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	905
VIN_CD	1FMRU15L91
LRR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T1EF
DRIVE_CD	T7B
ENG_CD	TVZ
TRANS_CD	T7DE
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	10/5/2001
NAME	SKYLINE FORD SALES, INC.
DOC_NUM	124632A
PH_NUM	3274500
WCC_CD	BR02
PART_NUM_CAU	1LTZ
PART_NUM_CAU	7891209
PART_NUM_CAU	CAB
CUST_CONC_CD	828
COND_CD	42
RPR_DT	5/22/2002
TIS_WSD	8
CLM_KEY	8822478
MILGE	9173
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1257 of 1298

LBR_HRS	0
DLR_CD	643
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	11001
Ratings	c
TECH_TXT1	
TECH_TXT2	
CUST_TXT	828* DRIVERS SEAT BELT KEEPS COMING LOOSE
AREA_CD	214
COUNTRY_CD	USA
SLS_DLR_CD	152003
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	@

MDL_YR	2001
SORT_INDEX	998
VIN_CD	1FMRU15L91L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	6/17/2001
NAME	FREWAY FORD INC
DOC_NUM	8213551
PH_NUM	5633023
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	825
COND_CD	42
RPR_DT	5/15/2002
TIS_WSD	10
CLM_KEY	8810026
MILGE	11308
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1259 of 1298

LBR_HRS	<input type="text" value="00"/>
DLR_CD	<input type="text" value="400"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="GA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value="c"/>
TECH_TXT1	<input type="text" value="A REPLACE LEFT SEAT BELT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="LEFT SEAT BELT BUCKLE COMES LOOSE BY SELF"/>
AREA_CD	<input type="text" value="705"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="121205"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value="0"/>

MDL_YR	2001
SORT_INDEX	967
VIN_CD	1FMRJH5L81
LBR_COST	
VEH_LINE_CD	T/93
MKT_DERIVED	
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	12/18/2001
NAME	BEAUFORD FORD, INC.
DOC_NUM	4045951
PH_NUM	859873
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/7/2001
TIS_WSD	0
CLM_KEY	5059884
MILGE	10
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	
DLR_CD	440
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	12001
Ratings	
TECH_TXT1	REPL SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	REPLACE CENTER ROW RIGHT SEAT BELT BUCKLE PER TOM PEELER FQE
AREA_CD	404
COUNTRY_CD	USA
SLS_DLR_CD	121001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	888
VIN_CD	1FMRU15L91L [REDACTED]
LBR_COST	[REDACTED]
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TAWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	TVZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/18/2001
WRTY_START_D	10/16/2001
NAME	JIM BURKE FORD
DOC_NUM	8148262
PH_NUM	3283600
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	41
RPR_DT	12/19/2001
TIS_WSD	3
CLM_KEY	6176860
MILGE	2587
MTRL_COST	[REDACTED]
TOT_COST_GROS	[REDACTED]

LBR_HRS	85
DLR_CD	5471
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	LEFT SEAT BELT BUCKLE BINDING DG, RPLD SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	CUST STATES DRIVER SEAT BELT NOT LATCHING
AREA_CD	805
COUNTRY_CD	USA
SLS_DLR_CD	171439
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	VD5
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	870
VIN_CD	1FMRU16L91
LBR_COST	
VEH_LINE_CD	T7B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/CE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	11/7/2001
NAME	GALPIN FORD
DOC_NUM	6188801
PH_NUM	7873800
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	1
RPR_DT	12/14/2001
TIS_WSD	2
CLM_KEY	5815516
MILGE	1440
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	48
DLR_CD	6636
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	CC187 REPLACED BOTH SEAT BELT BUCKLES
TECH_TXT2	
CUST_TXT	840 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139634/ 139839
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	971
VIN_CD	1FMRU15L91L
LBR_COST	
VRH_LINE_CD	T93
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	11/28/2000
WRTY_START_D	3/19/2001
NAME	PALATKA FORD LINCOLN-MERCURY
DOC_NUM	8881351
PH_NUM	3288881
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	3/25/2002
TIS_WSD	13
CLM_KEY	7801140
MILGE	28448
MTRL_COST	
TOT_COST_GROS	

LAB_HRS	0A
DLR_CD	3475
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	FL
CPSC_CD_6	11001
Ratings	a
TECH_TXT1	RF SEAT BELT WONT STAY LATCHED SEATBELT ASSEMBLY FRONT REPLACE
TECH_TXT2	
CUST_TXT	CUSTOMER STATES SEAT BELT KEEPS UN LOCKING
AREA_CD	388
COUNTRY_CD	USA
SLS_DLR_CD	124200
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	874
VIN_CD	1FMRU15L81L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	8/21/2000
WRTY_START_D	4/29/2001
NAME	VISTA FORD
DOC_NUM	8788161
PH_NUM	8847800
WCC_CD	GR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAB
CUST_CONC_CD	525
COND_CD	42
RPR_DT	5/9/2002
TIS_WSD	13
CLM_KEY	8587258
MILGE	10040
MTRL_COST	
TOT_COST_GROS	

LAB_HRS	08
DLR_CD	7823
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	12001
Ratings	0
TECH_TXT1	REPLACE RF SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	171043
TXN_CD	E84
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	876
VIN_CD	1FMRU16L81L
LBR_COST	
VEH_LINE_CD	T/83
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/8
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/10/2001
WRTY_START_D	10/13/2001
NAME	J.C. LEWIS MOTOR CO., INC.
DOC_NUM	30843101
PH_NUM	9250234
WCC_CD	6R02
PART_NUM_CAU	1LJZ
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	840
COND_CD	42
RPR_DT	2/18/2002
TIS_WSD	5
CLM_KEY	7192809
MILGE	8718
MYRL_COST	
TOT_COST_GROS	

LBR_HRS	GA
DLR_CD	4827
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	8
TECH_TXT1	NO OPERATING PROPERLY REPLACE DRIVER SEAT BELT BUCKLE ASSY
TECH_TXT2	
CUST_TXT	STATES SEAT BELT WILL NOT LATCH S40
AREA_CD	012
COUNTRY_CD	USA
SLS_DLR_CD	121208
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B5
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	079
VIN_CD	1FMFU19L81U
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/13/2001
WRTY_START_D	7/26/2001
NAME	METRO FORD
DOC_NUM	145981A
PH_NUM	8008000
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAA
CUST_CONC_CD	325
COND_CD	42
RPR_DT	7/19/2001
TIS_WSD	0
CLM_KEY	5810684
MILGE	10
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	5453
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	•
TECH_TXT1	INSPECT AND REPLACE DRIVERS SEAT BELT
TECH_TXT2	
CUST_TXT	
AREA_CD	B18
COUNTRY_CD	USA
SLS_DLR_CD	171010
TKN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	E3
VRT_CD	S05
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	981
VIN_CD	1FMRU15L81
LBR_COST	
VEH_LINE_CD	TB3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	TVZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/11/2001
WRTY_START_D	4/12/2001
NAME	SUNRISE FORD
DOC_NUM	521818A
PH_NUM	8224401
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAC
CUST_CONC_CD	825
COND_CD	41
RPR_DT	12/11/2001
TIS_WSD	8
CLM_KEY	5726234
MILGE	18225
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1275 of 1298

LBR_HRS	02
DLR_CD	5638
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	
TECH_TXT1	18228 01821D 0.8 8267 REPLACED DRIVERS SEATBELT BUCKLE PER RECALL
TECH_TXT2	
CUST_TXT	CUST STATES SEAT BELT IS INOP (SOP IN STOCK)
AREA_CD	908
COUNTRY_CD	USA
SLS_DLR_CD	171132
TXN_CD	EB4
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	962
VIN_CD	1FMRU15L01
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	2/26/2001
WRTY_START_D	3/15/2001
NAME	KAYSER FORD INC
DOC_NUM	065058A
PH_NUM	2700200
WCC_CD	BR02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	786120S
PART_NUM_CAU	BAC
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	8/30/2001
TIS_WSD	8
CLM_KEY	4250815
MILGE	2869
MTRL_COST	
TOT_COST_GROS	

LRR_HRS	08
DLR_CD	8395
DLR_SUB_CD	
REGION_CD	NA
ST_PROV_CD	WI
CPSC_CD_6	11001
Ratings	*
TECH_TXT1	2859 INSTALL L F SEATBELT BUCKLE PER RECALL 01S21.
TECH_TXT2	
CUST_TXT	INSTALL SOP SEAT BELT FOR RECALL 01S21
AREA_CD	808
COUNTRY_CD	USA
SLS_DLR_CD	141100
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V06
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	086
VIN_CD	1FMRU15L84L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWO
VER_SERIES_CD	T8F
DRIVE_CD	T/B
ENG_CD	TVZ
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/20/2001
WRTY_START_D	4/10/2001
NAME	CAPITAL FORD INC
DOC_NUM	2486651
PH_NUM	7904600
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7051203
PART_NUM_CAU	BAA
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	6/21/2001
TIS_WSD	5
CLM_KEY	3490206
MILGE	4183
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	08
DLR_CD	078
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	4
TECH_TXT1	SEAT BELT INSPE AND REPLACE SEATBELT BUCKLE
TECH_TXT2	
CUST_TXT	SEAT BELT WILL NOT CONNECT PROPERLY USE SPO 01212002
AREA_CD	019
COUNTRY_CD	USA
SLS_DLR_CD	121019
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q23
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	887
VIN_CD	1FMRU16L81L
LBR_COST	
VEH_LINE_CD	T83
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T8
ENG_CD	TN2
TRANS_CD	TDE
PLANT_CD	AP
PRODN_DT	1/28/2001
WRTY_START_D	8/25/2001
NAME	PIONEER FORD SALES
DOC_NUM	24530801
PH_NUM	2871833
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861208
PART_NUM_CAU	BAA
CUST_CONC_CD	825
COND_CD	41
RPR_DT	11/30/2001
TIS_WSD	3
CLM_KEY	5446180
MILGE	2137
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="20400"/>
DLR_CD	<input type="text" value="20400"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="AZ"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACED LF SEATBELT."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="DRIVER SEAT BELT LATCH HANGS AT TIMES"/>
AREA_CD	<input type="text" value="802"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171173"/>
TXN_CD	<input type="text" value="2"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="S3"/>
VRT_CD	<input type="text" value="B08"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	985
VIN_CD	1FMRU15L81
LBR_COST	
VEH_LINE_CD	T/B5
MKT_DERIVED	*
BOD_CAB_STL	T/WO
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/OE
PLANT_CD	AP
PRODN_DT	10/23/2000
WRTY_START_D	01/27/2001
NAME	CAREY PAUL FORD
DOC_NUM	8188051
PH_NUM	9879000
WCC_CD	0R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	CAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	0/28/2001
YIS_WSD	0
CLM_KEY	3507987
MILGE	10
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1283 of 1298

R004-011 E 3308

LBR_HRS	24
DLR_CD	277
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	11001
Ratings	•
TECH_TXT1	01821 INSPECT AND REPLACE ONE BUCKLE PER RECALL
TECH_TXT2	
CUST_TXT	RECALL 01821
AREA_CD	770
COUNTRY_CD	USA
SLS_DLR_CD	121007
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B9
VRT_CD	S06
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	989
VIN_CD	1FMRU15L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	"
BOD_CAB_STL	TWD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	6/5/2001
WRTY_START_D	10/23/2001
NAME	TAMAMI FORD, INC.
DOC_NUM	2894001
PH_NUM	8433873
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7851202
PART_NUM_CAU	AAB
CUST_CONC_CD	825
COND_CD	82
RPR_DT	7/20/2001
TIS_WSD	0
CLM_KEY	2854120
MILGE	7
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value=""/>
DLR_CD	<input type="text" value="1286"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="FL"/>
CPSC_CD_6	<input type="text" value="12001"/>
Ratings	<input type="text" value="0"/>
TECH_TXT1	<input type="text" value="1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE"/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="RECALL D1621 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12"/>
AREA_CD	<input type="text" value="941"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="124428"/>
TXN_CD	<input type="text" value="1"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V05"/>
AWS_VL_CD	<input type="text" value="83"/>
VRT_CD	<input type="text" value="808"/>
TIS_FLAG	<input type="text" value=""/>

MDL_YR	2001
SORT_INDEX	000
VIN_CD	1FMPU16L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TAWO
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	TNZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	8/30/2001
NAME	BEAULDRY FORD, INC.
DOC_NUM	3038851
PH_NUM	650873
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881202
PART_NUM_CAU	AAS
CUST_CONC_CD	S40
COND_CD	42
RPR_DT	7/24/2001
TIS_WSD	0
CLM_KEY	2888763
MILGE	9
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	00
DLR_CD	440
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	GA
CPSC_CD_6	12001
Ratings	0
TECH_TXT1	REPL SEAT BELT BUCKLE PERFORM
TECH_TXT2	
CUST_TXT	RECALL 01821 IS NOT ELIG FORD REP GAVE APPROVAL NUMBER
AREA_CD	404
COUNTRY_CD	USA
SLS_DLR_CD	121001
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V06
AWS_VL_CD	B3
VRT_CD	908
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	991
VIN_CD	1FMRU15L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/NZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	5/29/2001
WRTY_START_D	7/25/2001
NAME	NICHOLS FORD
DOC_NUM	20340901
PH_NUM	6963673
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7981202
PART_NUM_CAU	AAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	7/19/2001
TIS_WSD	0
CLM_KEY	2957739
MILGE	2
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	2511
DLR_SUB_CD	.
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Ratings	b
TECH_TXT1	REPLACE RIGHT SIDE BELT
TECH_TXT2	
CUST_TXT	CUSTOMER STATES THAT RIGHT SIDE BELT WILL NOT HOLD REPLACE RIGHT SIDE BELT
AREA_CD	B17
COUNTRY_CD	USA
SLS_DLR_CD	182000
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B9
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	993
VIN_CD	1FMRU16L71
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	TWD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/D
PLANT_CD	AP
PRODN_DT	5/9/2001
WRTY_START_D	7/2/2001
NAME	UNIVERSITY FORD, INC.
DOC_NUM	8589651
PH_NUM	8828171
WCC_CD	8R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881208
PART_NUM_CAU	BAA
CUST_CONC_CD	940
COND_CD	42
RPE_DT	10/25/2001
TIS_WSD	4
CLM_KEY	4680493
MILGE	4810
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	04
DLR_CD	8634
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	NC
CPSC_CD_6	11001
Ratings	C
TECH_TXT1	SEATBELT RECEIVER INOP CK REPLACED DRIVERS SEATBELT BUCKLE RECEIVER
TECH_TXT2	
CUST_TXT	CK DRIVERS SIDE SEATBELT UNBUCKLES ON ITS OWN
AREA_CD	818
COUNTRY_CD	USA
SLS_DLR_CD	121028
TXN_CD	2
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	998
VIN_CD	1FMRU16L71L
LBR_COST	
VEH_LINE_CD	T/63
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/28/2001
WRTY_START_D	6/4/2001
NAME	GALPIN FORD
DOC_NUM	6184371
PH_NUM	7873800
WCC_CD	6R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BAB
CUST_CONC_CD	840
COND_CD	42
RPR_DT	12/18/2001
TIS_WSD	7
CLM_KEY	5858789
MILGE	7528
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	09
DLR_CD	5538
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	CA
CPSC_CD_6	11001
Ratings	b
TECH_TXT1	CC487 REPLACED SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE
AREA_CD	618
COUNTRY_CD	USA
SLS_DLR_CD	171040
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VPG_CD	V05
AWS_VL_CD	B3
VRT_CD	808
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	997
VIN_CD	1FMRU15L711
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	T/EF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	4/12/2001
WRTY_START_D	6/30/2001
NAME	TOMBALL FORD, INC.
DOC_NUM	223114C
PH_NUM	3616427
WCC_CD	BF02
PART_NUM_CAU	FB5Z
PART_NUM_CAU	7861203
PART_NUM_CAU	BBE
CUST_CONC_CD	840
COND_CD	31
RPR_DT	7/30/2001
TIS_WSD	2
CLM_KEY	3926668
MILGE	879
MTRL_COST	
TOT_COST_GROS	

Tuesday, December 14, 2004

Page 1295 of 1298

LBR_HRS	64
DLR_CD	6042
DLR_SUB_CD	*
REGION_CD	NA
ST_PROV_CD	TX
CPSC_CD_6	12001
Rating	d
TECH_TXT1	REPLACED LEFT FRONT SEAT BELT BUCKLE
TECH_TXT2	
CUST_TXT	640CUST STATES SEAT BELTS COME APRT WHILE DRIVING
AREA_CD	281
COUNTRY_CD	USA
SLS_DLR_CD	152058
TXN_CD	1
CNTRY_SOLD	USA
QRT_CD	Q21
VFG_CD	V05
AWS_VL_CD	B3
VRT_CD	S08
TIS_FLAG	

MDL_YR	2001
SORT_INDEX	999
VIN_CD	1FMRU16L71L
LBR_COST	
VEH_LINE_CD	T/B3
MKT_DERIVED	*
BOD_CAB_STL	T/WD
VER_SERIES_CD	TEF
DRIVE_CD	T/B
ENG_CD	T/VZ
TRANS_CD	T/DE
PLANT_CD	AP
PRODN_DT	3/27/2001
WRTY_START_D	4/18/2001
NAME	ADVANTAGE FORD
DOC_NUM	6023303
PH_NUM	3598889
WCC_CD	B/R02
PART_NUM_CAU	1L7Z
PART_NUM_CAU	7881203
PART_NUM_CAU	BAB
CUST_CONC_CD	B40
COND_CD	42
RPR_DT	3/16/2002
TIS_WSD	12
CLM_KEY	7495432
MILGE	1E558
MTRL_COST	
TOT_COST_GROS	

LBR_HRS	<input type="text" value="0.00"/>
DLR_CD	<input type="text" value="2677"/>
DLR_SUB_CD	<input type="text" value=""/>
REGION_CD	<input type="text" value="NA"/>
ST_PROV_CD	<input type="text" value="CA"/>
CPSC_CD_6	<input type="text" value="11001"/>
Ratings	<input type="text" value=""/>
TECH_TXT1	<input type="text" value="REPLACED LEFT FRONT SEAT BELT BUCKLE
ASSY. 03 18 13.32 14.31."/>
TECH_TXT2	<input type="text" value=""/>
CUST_TXT	<input type="text" value="CHECK LEFT FRONT SEAT BELT BUCKLE IN OP AT
TIMES WONT POP UP"/>
AREA_CD	<input type="text" value="628"/>
COUNTRY_CD	<input type="text" value="USA"/>
SLS_DLR_CD	<input type="text" value="171031"/>
TXN_CD	<input type="text" value="E84"/>
CNTRY_SOLD	<input type="text" value="USA"/>
QRT_CD	<input type="text" value="Q21"/>
VFG_CD	<input type="text" value="V06"/>
AWS_VL_CD	<input type="text" value="B3"/>
VRT_CD	<input type="text" value="806"/>
TIS_FLAG	<input type="text" value=""/>