

**RQ04-011**

**FORD**

**APRIL 26, 2005**

**REQUEST 8**

**PART 6 OF 6**

**BOOK 7 OF 43**

<b>LBR_HRS</b>	0.4
<b>DLR_CD</b>	6692
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	REPLACE LFT BUCKLE AS PER RECALL
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUST REQUEST RECALL D1821
<b>AREA_CD</b>	861
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171442
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	BOX
<b>TIS_FLAG</b>	0

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	191
<b>VIN_CD</b>	1FTRF17W61P [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/B8
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	5/22/2001
<b>WRTY_START_D</b>	6/7/2001
<b>NAME</b>	HAYWARD FORD
<b>DOC_NUM</b>	36563301
<b>PH_NUM</b>	8811200
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10/29/2001
<b>TIS_WSD</b>	5
<b>CLM_KEY</b>	4748444
<b>MILGE</b>	12714
<b>MTRL_COST</b>	[REDACTED]
<b>TOT_COST_GROS</b>	[REDACTED]

<b>LBR_HRS</b>	
<b>DLR_CD</b>	7729
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	01821 COMPLETED CHECK CENTER BELT ORDER
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	01821 FIELD SERVICE ACTION
<b>AREA_CD</b>	510
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	116088
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	182
<b>VIN_CD</b>	1FTRF17W61N
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	T/98
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	3/27/2001
<b>WRTY_START_D</b>	6/10/2001
<b>NAME</b>	LAKEWOOD FORDLAND INC
<b>DOC_NUM</b>	6559751
<b>PH_NUM</b>	2322200
<b>WCC_CD</b>	
<b>PART_NUM_CAU</b>	
<b>PART_NUM_CAU</b>	
<b>PART_NUM_CAU</b>	
<b>CUST_CONC_CD</b>	
<b>COND_CD</b>	
<b>RPR_DT</b>	8/4/2001
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	2747428
<b>MILGE</b>	3651
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	3142
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CO
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	01521 RECALL PERFORMED
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	01521 SEAT BELT RECALL
<b>AREA_CD</b>	303
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	158011
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	103
<b>VIN_CD</b>	1FTRF17W51N
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B8
<b>VER_SERIES_CD</b>	TIAM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	2/5/2001
<b>WRTY_START_D</b>	3/22/2001
<b>NAME</b>	BOYD COUNTY FORD, INC.
<b>DOC_NUM</b>	106068B
<b>PH_NUM</b>	322120
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	4/18/2002
<b>TIS_WSD</b>	14
<b>CLM_KEY</b>	8163848
<b>MILGE</b>	11287
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 385 of 418

RQ04-011 E 4168

<b>LBR_HRS</b>	
<b>DLR_CD</b>	1840
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	KY
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL 01S21 AS PER BULLETIN, INSTALL SEAT BELT BUCKLES AND NO REPLACEMENT NECESSARY.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01S21 SEAT BELT
<b>AREA_CD</b>	808
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	147406
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	0



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	194
<b>VIN_CD</b>	1FTRF17W51N
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/B
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	11/15/2000
<b>WRTY_START_D</b>	12/4/2000
<b>NAME</b>	RANDALL FORD INC
<b>DOC_NUM</b>	463251
<b>PH_NUM</b>	4621811
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	4/11/2002
<b>TIS_WSD</b>	17
<b>CLM_KEY</b>	7953578
<b>MILGE</b>	38411
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	0.4
<b>DLR_CD</b>	6875
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AR
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RPLC LEFT SEAT BELT BUCKLE PER 01821
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821
<b>AREA_CD</b>	479
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	141085
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	BOX
<b>TIS_FLAG</b>	Q

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	185
<b>VIN_CD</b>	1FTRF17W51
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	10/5/2000
<b>WRTY_START_D</b>	10/1/2001
<b>NAME</b>	DOBBS FORD, INC.
<b>DOC_NUM</b>	22201102
<b>PH_NUM</b>	3026304
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10/2/2001
<b>TYS_WSD</b>	1
<b>CLM_KEY</b>	4140010
<b>MILGE</b>	4
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	6948
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TN
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	COMPLETED RECALL
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL01821
<b>AREA_CD</b>	801
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123811
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	100
<b>VIN_CD</b>	1FTRF17W41
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>RNG_CD</b>	T/VN
<b>TRANS_CD</b>	T/OU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	10/8/2000
<b>WRTY_START_D</b>	6/24/2001
<b>NAME</b>	COUNTRYSIDE FORD
<b>DOC_NUM</b>	20231
<b>PH_NUM</b>	6480678
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10/30/2001
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	6297212
<b>MILGE</b>	3767
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	3678
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NC
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL 01821 AS PER INSTRUCTIONS
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821
<b>AREA_CD</b>	338
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121648
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	187
<b>VIN_CD</b>	1FTRF17W31NE [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	3/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	3/18/2001
<b>WRTY_START_D</b>	8/30/2001
<b>NAME</b>	MOREHEAD CITY FORD
<b>DOC_NUM</b>	7787201
<b>PH_NUM</b>	2472132
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	2/6/2002
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	8780528
<b>MILGE</b>	0480
<b>MTRL_COST</b>	[REDACTED]
<b>TOY_COST_GROS</b>	[REDACTED]

<b>LBR_HRS</b>	0.3
<b>DLR_CD</b>	1101
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NC
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	ABOVE RECALL COMPLETED
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CHECK AND PERFORM RECALL# 01S21
<b>AREA_CD</b>	252
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121547
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	830L
<b>TIS_FLAG</b>	0



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	108
<b>VIN_CD</b>	1F7RF17W11N
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/AN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	5/21/2001
<b>WRTY_START_D</b>	5/27/2001
<b>NAME</b>	CHAPMAN FORD SALES
<b>DOC_NUM</b>	14197602
<b>PH_NUM</b>	0990281
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	6/23/2002
<b>TIS_WSD</b>	13
<b>CLM_KEY</b>	8791688
<b>MILGE</b>	12484
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	1402
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	DE
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	INSPECT ONLY D1S21A D.3 1
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	REPLACE ALL DEFECTIVE BUCKLES INVOLVED IN THIS RECALL.
<b>AREA_CD</b>	302
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	118213
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	S0X
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	199
<b>VIN_CD</b>	1FTRF17W11
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B8
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	2/6/2001
<b>WRKY_START_D</b>	6/16/2001
<b>NAME</b>	BLYTHEVILLE FORD LINCOLN MERCU
<b>DOC_NUM</b>	4028001
<b>PH_NUM</b>	7634453
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	6/16/2001
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	3995175
<b>MILGE</b>	4001
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	3600
<b>DLR_CD</b>	3808
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AR
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECT NO WORK NEEDED
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CJST STATES HAS RECALL
<b>AREA_CD</b>	870
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123583
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F3
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	200
<b>VIN_CD</b>	1FTRF17W1H
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	3/6/2001
<b>WRTY_START_D</b>	3/24/2001
<b>NAME</b>	TOMMIE VAUGHN MOTORS, INC.
<b>DOC_NUM</b>	1E8331C
<b>PH_NUM</b>	5584561
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	5/22/2001
<b>TIS_WSD</b>	6
<b>CLM_KBY</b>	9183846
<b>MILGE</b>	4757
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	02
<b>DLR_CD</b>	4474
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	4767 INSPECT FOR RECALL 01S21 SEAT BELT BUCKLE INSPECTION ONLY..
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01S21 BELT BUCKLE
<b>AREA_CD</b>	713
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	132024
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SDX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	201
<b>VIN_CD</b>	1FTRF17W01K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B8
<b>VER_SERIES_CD</b>	T/AN
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/AN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	12/18/2001
<b>WRTY_START_D</b>	1/18/2001
<b>NAME</b>	ARROW FORD, INC.
<b>DOC_NUM</b>	8831901
<b>PH_NUM</b>	8828500
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	08/2001
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	3613782
<b>MILGE</b>	21185
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	2404
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	1 TESTED BUCKLES PER RECALL. NO REPLACEMENT NEEDED.
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821 SEAT BELT BUCKEL
<b>AREA_CD</b>	918
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152508
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	202
<b>VIN_CD</b>	1FTRF17LX1
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	TBS
<b>VER_SERIES_CD</b>	TIAM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	4/18/2001
<b>WRTY_START_D</b>	6/30/2001
<b>NAME</b>	JIM KEIM FORD, INC.
<b>DOC_NUM</b>	177479B
<b>PH_NUM</b>	8883333
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	4/10/2002
<b>TIS_WSD</b>	10
<b>CLM_KEY</b>	7842771
<b>MILGE</b>	10128
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	
<b>DLR_CD</b>	147U
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	OH
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL PER FORD
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	INSPECT SEAT BELT BUCKLES
<b>AREA_CD</b>	814
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	147035
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	8CX
<b>TIS_FLAG</b>	0

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	203
<b>VIN_CD</b>	1FTRF17L91N
<b>LRR_COST</b>	
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/B6
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	4/26/2001
<b>WRTY_START_D</b>	7/3/2001
<b>NAME</b>	COURTESY FORD
<b>DOC_NUM</b>	8107751
<b>PH_NUM</b>	8222700
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	1/19/2002
<b>TES_WSD</b>	7
<b>CLM_KEY</b>	0878728
<b>MILGE</b>	10988
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	<input type="text" value=""/>
<b>DLR_CD</b>	<input type="text" value="300"/>
<b>DLR_SUB_CD</b>	<input type="text" value=""/>
<b>REGION_CD</b>	<input type="text" value="NA"/>
<b>ST_PROV_CD</b>	<input type="text" value="GA"/>
<b>CPSC_CD_6</b>	<input type="text" value=""/>
<b>TECH_TXT1</b>	<input type="text" value="RECALL PERFORMED RECALL 01821"/>
<b>TECH_TXT2</b>	<input type="text" value=""/>
<b>CUST_TXT</b>	<input type="text" value="01821 SEAT BELT BUCKLE"/>
<b>AREA_CD</b>	<input type="text" value="770"/>
<b>COUNTRY_CD</b>	<input type="text" value="USA"/>
<b>SLS_DLR_CD</b>	<input type="text" value="121061"/>
<b>TXN_CD</b>	<input type="text" value="01821"/>
<b>CNTRY_SOLD</b>	<input type="text" value="USA"/>
<b>QRT_CD</b>	<input type="text" value=""/>
<b>VFG_CD</b>	<input type="text" value="V00"/>
<b>AWS_VL_CD</b>	<input type="text" value="F6"/>
<b>VRT_CD</b>	<input type="text" value="SJOX"/>
<b>TIS_FLAG</b>	<input type="text" value=""/>

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	204
<b>VIN_CD</b>	1FTFR08W11K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/E
<b>ENG_CD</b>	T/VN
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	3/19/2001
<b>WRTY_START_D</b>	7/7/2001
<b>NAME</b>	TOWN & COUNTRY FORD
<b>DOC_NUM</b>	232795B
<b>PH_NUM</b>	4813673
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONG_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8/1/2001
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	3450737
<b>MILGE</b>	3880
<b>MTBL_COST</b>	
<b>TOT_COST_GROS</b>	

<b>LBR_HRS</b>	0.4
<b>DLR_CD</b>	3385
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AL
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	REPLACED ONE SEAT BELT BUCKLE
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	DRV SEAT BELT WONT STAY LATCHED
<b>AREA_CD</b>	205
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121013
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	0

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	206
<b>VIN_CD</b>	1FTFF16L11NE [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B8
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/E
<b>ENG_CD</b>	T/NZ
<b>TRANS_CD</b>	T/D8
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	4/11/2001
<b>WRTY_START_D</b>	4/24/2001
<b>NAME</b>	FAMILY FORD INC
<b>DOC_NUM</b>	7321852
<b>PH_NUM</b>	3473000
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10/17/2001
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	4588048
<b>MILGE</b>	2832
<b>MTRL_COST</b>	[REDACTED]
<b>TOT_COST_GROS</b>	[REDACTED]

<b>LBR_HRS</b>	
<b>DLR_CD</b>	20523
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NJ
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	INSPECTED SEAT BELTS AS PER RECALL CENTER BUCKLE FAILED SEE REPAIR LINES 61
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	CUST STATES PERFORM RECALL 01321 SOP PARTS ARE HERE CROSS REF 72617
<b>AREA_CD</b>	073
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	113452
<b>TXN_CD</b>	01321
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	S00
<b>TIS_FLAG</b>	0



<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	208
<b>VIN_CD</b>	1FTFF17M01K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/F5
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ
<b>TRANS_CD</b>	T/DE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	4/19/2001
<b>WRTY_START_D</b>	6/18/2001
<b>NAME</b>	MAITA FORD-MERCURY
<b>DOC_NUM</b>	5624762
<b>PH_NUM</b>	8230501
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8/3/2001
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	2898488
<b>MILGE</b>	508
<b>MTRL_COST</b>	[REDACTED]
<b>TOT_COST_GROS</b>	[REDACTED]

<b>LBR_HRS</b>	0.3
<b>DLR_CD</b>	2519
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	SAFETY RECALL 01521 INSPECT BUCKLES
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	PERFORM RECALL 01521
<b>AREA_CD</b>	530
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	172208
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	VDD
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	207
<b>VIN_CD</b>	1FTPF17LX1
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ
<b>TRANS_CD</b>	T/DE
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	12/7/2000
<b>WRTY_START_D</b>	8/16/2001
<b>NAME</b>	COLEMAN FORD LINC-MERC INC
<b>DOC_NUM</b>	008417A
<b>PH_NUM</b>	
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	3/14/2002
<b>TIS_WSD</b>	6
<b>CLM_KEY</b>	7805805
<b>MILGE</b>	10125
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 413 of 418

RQ04-011 E 4198

<b>LBR_HRS</b>	1024
<b>DLR_CD</b>	1368
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	IL
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	REPAIR AS PER RECALL
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	PERFORM RECALL 01521
<b>AREA_CD</b>	
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	141842
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	80X
<b>TIS_FLAG</b>	0

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	208
<b>VIN_CD</b>	1FTFP17L71 [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BB
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ
<b>TRANS_CD</b>	T/DE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	2/15/2001
<b>WRTY_START_D</b>	3/2/2001
<b>NAME</b>	ZIEMS FORD CORNERS, INC.
<b>DOC_NUM</b>	3281241
<b>PH_NUM</b>	3251881
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8/8/2001
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	3628703
<b>MILGE</b>	12785
<b>MTRL_COST</b>	[REDACTED]
<b>TOT_COST_GROS</b>	[REDACTED]

Tuesday, December 14, 2004

Page 413 of 418

<b>LBR_HRS</b>	08
<b>DLR_CD</b>	20341
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NM
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	D
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL ON SEAT BELT
<b>AREA_CD</b>	506
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	148211
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@

<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	208
<b>VIN_CD</b>	1FTPF17L11N
<b>LBR_COST</b>	
<b>VRH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/B5
<b>VER_SERIES_CD</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ
<b>TRANS_CD</b>	T/D5
<b>PLANT_CD</b>	AR
<b>PRODN_DT</b>	11/8/2000
<b>WRTY_START_D</b>	12/13/2000
<b>NAME</b>	MANTILIA MOTORS, INC.
<b>DOC_NUM</b>	08873BA
<b>PH_NUM</b>	8312800
<b>WCC_CD</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>PART_NUM_CAU</b>	*
<b>CUST_CONC_CD</b>	*
<b>COND_CD</b>	*
<b>RFR_DT</b>	8/7/2001
<b>TIS_WSD</b>	6
<b>CLM_KEY</b>	2813703
<b>MILGE</b>	18201
<b>MTRL_COST</b>	
<b>TOT_COST_GROS</b>	

Tuesday, December 14, 2004

Page 417 of 418

RQ04-011 E 4200

<b>LBR_HRS</b>	0.2
<b>DLR_CD</b>	3831
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CT
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	CENTER BUCKLE NOT LATCHING ON ORDER
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821 SEAT BELT INSPECTION REPLACEMENT
<b>AREA_CD</b>	203
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	113211
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	S0X
<b>TIS_FLAG</b>	0