

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 6 OF 6

BOOK 11 OF 43

01_Expd_NavFrontBuckle_Query

4836	*	NA
4845	*	NA
4820	*	NA
3924	*	NA
6102	*	NA
4036	*	NA
3921	*	NA
7018	*	NA
3134	*	NA
5453	*	NA
3684	*	NA
5574	*	NA
990	*	NA
1777	*	NA
4843	*	NA
6481	*	NA
7358	*	NA
4159	*	NA
5479	*	NA
4212	*	NA
1472	*	NA
5402	*	NA
2874	*	NA
5431	*	NA
4480	*	NA
5563	*	NA
6102	*	NA
1884	*	NA
5453	*	NA
543	*	NA
200	*	NA
4449	*	NA
3915	*	NA
4990	*	NA
2403	*	NA
2091	*	NA
5550	*	NA

01_Expact_NavFrontBuckle_Query

4332	*	NA
2488	*	NA
1864	*	NA
4908	*	NA
8534	*	NA
8529	*	NA
7883	*	NA
4127	*	NA
1025	*	NA
4807	*	NA
2488	*	NA
2411	*	NA
2441	*	NA
2453	*	NA
6778	*	NA
5623	*	NA
8529	*	NA
4870	*	NA
4847	*	NA
3085	*	NA
2410	*	NA
2459	*	NA
11843	*	NA
4847	*	NA
1587	*	NA
2415	*	NA
5520	*	NA
543	*	NA
5882	*	NA
1181	*	NA
5414	*	NA
3573	*	NA
487	*	NA
1140	*	NA
7833	*	NA
3832	*	NA
2488	*	NA

01_Expnd_NavFrontBuckle_Query

6642*	NA
141*	NA
4410*	NA
3073*	NA
5508*	NA
1771*	NA
3573*	NA
1470*	NA
4443*	NA
4358*	NA
5519*	NA
543*	NA
409*	NA
449*	NA
5536*	NA
5536*	NA
3475*	NA
7823*	NA
4827*	NA
5539*	NA
978*	NA
20400*	NA
277*	NA
6634*	NA
6538*	NA
2877*	NA

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair_ST_PROV_CD	2001 Exped repeat repair_CPSC_CD_6	Ratings
NJ	11001	e
IL	11001	e
MN	11001	e
MN	11001	c
TN	11001	a
NJ	11001	e
NJ	11001	e
CO	11001	e
CA	11001	d
MI	11001	e
CA	11001	e
MI	11001	e
NJ	11001	c
CA	11001	a
CO	11001	d
MA	11001	a
MA	11001	e
CA	11001	a
IL	11001	a
MI	11001	e
NY	11001	a
MI	11001	d
VA	11001	e
MO	11001	d
PA	11001	e
IL	11001	e
TN	11001	a
NY	11001	e
HI	11001	d
CO	11001	c
MO	11001	a
CA	11001	c
NY	11001	a
NM	11001	e
KS	11001	a
NJ	11001	d

01_Expd_NavFrontBuckle_Query

MA	11001	a
KY	11001	e
OR	11001	a
FL	11001	d
CO	11001	a
TX	11001	a
NH	11001	a
MD	11001	e
MD	11001	e
CO	11001	e
CO	11001	a
AZ	11001	a
NY	11001	e
IL	11001	a
PA	11001	e
TX	11001	c
TN	11001	e
VA	11001	e
VA	11001	a
MI	11001	a
IA	11001	b
MA	11001	e
KS	11001	e
SC	12001	c
GA	11001	e
GA	11001	b
FL	11001	d
TN	11001	d
FL	11001	d
CA	11001	a
CA	11001	a
CA	11001	a
CA	11001	a
CA	11001	a
CA	11001	a
FL	11001	a
FL	11001	b
CA	11001	a

01_Expd_NavFrontBuckle_Query

FL	11001	a
FL	11001	a
TX	11001	b
CA	11001	e
FL	11001	e
AL	11001	a
AL	11001	e
GA	11001	c
CA	11001	e
AL	11001	e
NV	11001	a
TX	12001	e
CA	11001	a
CA	11001	b
VA	11001	a
AL	11001	e
GA	11001	a
CA	11001	e
TX	11001	e
MS	11001	a
OK	11001	a
CA	11001	o
GA	11001	c
CA	11001	e
CA	11001	e
FL	11001	a
TX	11001	a
CA	11001	B
GA	11001	e
AZ	11001	a
CA	11001	a
SC	11001	a
GA	11001	e
TX	11001	c
CA	11001	e
CT	11001	c
TX	11001	b

01_Exped_NavFrontBuckle_Query

TX	11001	e
GA	11001	B
CA	11001	b
NC	12001	A
TX	11001	d
FL	11001	c
TX	12001	e
TX	12001	e
GA	12001	e
FL	12001	a
GA	11001	B
TX	12001	a
TX	11001	a
TX	11001	a
GA	12001	e
CA	11001	e
FL	11001	e
FL	11001	b
TX	11001	d
TX	11001	e
TX	11001	a
TX	11001	a
TX	11001	c
TX	11001	a
FL	11001	e
FL	11001	a
LA	11001	a
FL	11001	c
TX	11001	a
CA	11001	a
GA	11001	e
FL	12001	e
TX	11001	c
TX	11001	a
TX	11001	a
FL	11001	e
TX	11001	d

01_Exped_NavFrontBuckle_Quary

CA	11001	a
KS	11001	c
TX	11001	a
CA	11001	a
OK	11001	b
GA	11001	e
TX	11001	b
FL	11001	s
TX	12001	a
TX	11001	e
TX	11001	c
TX	12001	a
CA	12001	a
TX	11001	c
GA	11001	c
CA	12001	a
TX	12001	c
OK	12001	a
FL	11001	d
TX	12001	a
TX	11001	a
TX	11001	a
CA	11001	e
SC	11001	a
IL	11001	a
NC	12001	a
NJ	11001	c
CA	11001	b
PA	12001	b
NJ	11001	d
NC	11001	d
NY	11001	a
PA	12001	a
MI	11001	e
CA	11001	e
MI	11001	a
NJ	12001	a

01_Exped_NavFrontBuckle_Query

PA	11001	e
NJ	11001	e
WA	11001	e
IL	11001	a
DE	11001	e
MI	12001	a
IN	11001	e
NJ	12001	a
MI	11001	c
VA	11001	a
NJ	12001	a
CA	11001	a
CA	11001	e
MD	11001	e
CA	12001	a
VA	11001	c
MI	11001	a
NH	11001	e
IN	11001	b
MO	11001	e
LA	11001	e
OK	11001	e
CA	11001	e
CA	11001	d
TX	12001	a
FL	12001	a
CA	12001	e
CA	11001	a
TX	11001	c
CA	11001	d
CA	12001	b
TX	11001	c
LA	11001	b
TX	11001	c
GA	11001	a
FL	11001	a
CA	11001	e

01_Expnd_NavFrontBuckle_Query

LA	11001	e
AZ	11001	e
GA	11001	e
FL	11001	e
GA	11001	b
CA	12001	a
FL	11001	c
TX	11001	d
CA	11001	e
CA	11001	e
CA	11001	e
TX	11001	e
AR	11001	d
TX	11001	c
FL	11001	e
GA	11001	a
FL	12001	c
TX	11001	d
FL	12001	e
TX	11001	c
NV	11001	a
FL	11001	d
CA	11001	a
NC	11001	e
TX	11001	d
AZ	11001	a
CA	11001	d
NE	11001	a
CA	12001	e
TX	11001	c
TX	12001	a
NC	11001	c
TX	11001	d
TX	11001	d
TX	11001	a
CA	12001	a
CA	11001	e

01_Exped_NavFrontBuckle_Query

FL	12001	a
FL	11001	c
FL	11001	e
NC	12001	e
TX	11001	c
FL	11001	d
CA	11001	c
TX	11001	d
CO	12000	e
CA	11001	e
NC	11001	e
CA	12001	a
NC	11001	a
IL	11001	a
FL	11001	a
LA	11001	a
MS	11001	b
LA	11001	c
CA	11001	e
TX	11001	e
TX	11001	c
CA	11001	e
TX	12001	b
CA	12001	e
TX	11001	a
CA	11001	a
TX	11001	d
CA	11001	d
CA	11001	a
TX	11001	a
GA	11001	a
TX	12001	a
NV	12001	a
FL	11001	d
TX	11001	a
TX	11001	a
CA	11001	a

01_Expnd_NavFrontBuckle_Query

FL	11001	e
TX	11001	a
CA	12001	e
FL	11001	o
MS	11001	e
AL	11001	c
CA	11001	a
LA	11001	d
SC	11001	e
FL	12001	a
TX	11001	e
TX	12001	a
TX	12001	a
TX	11001	e
NC	12001	e
TN	11001	e
AL	11001	b
FL	11001	e
FL	11001	e
AL	11001	e
TX	12001	e
TX	11001	b
FL	11001	a
GA	11001	e
CA	11001	e
TX	11001	e
CA	12001	e
TX	11001	c
AL	12001	d
NC	11001	a
CA	11001	e
GA	11001	c
GA	11001	o
NC	11001	e
CA	11001	a
GA	11001	b
TX	12001	a

D1_Exped_NavFrontBucks_Query

VA	11001d
VA	11001e
TX	11001b
FL	11001a
CA	11001a
OK	11001a
GA	11001e
OH	11001e
TX	11001d
CA	11001e
CA	12001e
TX	11001c
GA	11001c
GA	12001e
CA	11001b
CA	11001b
FL	11001a
CA	12001e
GA	11001a
CA	11001e
NC	11001a
AZ	11001e
GA	11001e
NC	11001c
CA	11001b
CA	11001a

2001 Exped repeat repair TECH_TXT1
 B359 CK & REPLACED BOTH FRONT SEAT BELT ASSY.
 REPLACED BUCKLE ASSY INOP
 INSTALL PASS SIDE SEAT BELT LATCH
 CP 7861203;CC 41;CCG 826 REPLACED DRIVERS SEAT BELT BUCKLE ASSEMBLY. UTILIZED LABOR OPERATION FROM PROGRAM 01S21
 REPLACED RIGHT FRONT PASS SEAT BELT BUCKLE ASSY
 7222 REPLACE DRIVER FRONT SEAT BUCKLE
 1 REPLACE L FRONT SEAT BELT
 REPL LF BELT BUCKLE
 ..BUCKLES ARE NOTS HOLDING AT TIMES... ..INSPECTED WITH TOOL BOTH FRONTS FAILED.REPLACED.OK
 1 REPLACE DRIVERS SEAT BELT BUCKLE WITH NEW BUCKLE IN OP CC 42 BASIC#81203
 SEAT BELTS IN OP REPLACE SEAT BELTS
 DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
 PASS AND DSIDE SEATBELT BUCKLE FAULTY TECH REPLACED PASS AND DSIDE FRONT BUCKLE TO CORRECT CUST CONCERN
 SEAT BELT NOT STAYING ENGAGED SEATBELT ASSEMBLY FRONT REPLACE
 FOUND DRIVERS SIDE SEAT BELT BROKEN. R&R DRIVERS SEAT BELT. VERIFIED REPAIR
 14515 REPLACED DRIVER SEATBELT RECEPT. RECEPT. WOULD NOT ACCEPT SEATBELT BUCKLE AND LOCK BELT OPERATED PROPERLY
 PERFORMED RECALL AND REPLACED DRIVER SEATBELT BUCKLE RECHECKED OK
 REPLACE BELT INOP
 REPLACE BOTH FRONT SEAT BELT BUCKLES
 INSPECTED SEATBELTS,NEEDS DRIVERS BUCKLE,REQUEST MY INSPECT AND REPLACE DRIVER BELT AND BUCKLE
 INSTALLED SOP SEATBELT
 1237 D1 INSPECTED AND FOUND BAD SEAT BELT LATCH REPLACED DRIVER SEAT BELT LATCH RECHECKED GOOD
 2472 INSPECT AND REPLACE DRIVER SIDE SEAT BELT
 TESTED THE SEAT BELT CAME UNLATCHED PUT IN A NEW BUCKLE TESTED DID NOT COME UNDONE MOVED THE LATCH AROUND
 SEAT BUCKLES NEED REPLACED REPLACED LEFT AND RIGHT FRONT SEAT BELT BUCKLES
 REPLACED RIGHT FRONT SEAT BELT BUCKLE DUE TO INOP
 MYTIME TO REMOVE LEFT FRT SEAT AND LEFT FRT SEATBELY FEMALE END. REPLACED FEMALE END OF LEFT FRT SEATBELT. RETEST. OK.
 REPLACE L FRONTSEATBELT BUCKLE

 REPL SEAT BELT
 SEATBELT ASSEMBLY FRT REPLACED DUE TO LATCH INOP
 63: VERIFY DRIVERS SEATBELT UNLATCHES, R&R FRONT SEAT AND REPLACED SEATBELY BUCKLE, REASSEMBLE, RECHECK OK AT THIS T
 . PERFORMED SEAT BELT RECALL
 REPLACED THE BUCKLE
 REPLACE LEFT FRONT SEAT BELT
 1 REPLACE DRIVERS SEAT BELT BUCKLE

VERIFIED RIGHT FRONT SEAT BELT BUCKLE WILL NOT LOCK. REPLACED THE BUCKLES AND RECHECKED TO CONFIRM REPAIR.
 BUCKLE FAILED SEATBELT ASSEMBLY FRONT REPLACE
 1 INSPECTED VEHICLE AND REPLACED LEFT FRONT BUCKLE
 LOOSE SEATBELT ASSEMBLY FRONT REPLACE
 BUCKLE WILL NOT OPERATE PROPERLY REPLACE LEFT SEAT BELT BUCKLE.
 INSPECT SEAT BELT REPLACE BELT AND BUCKLE ASSY BINDING
 REPLACED DRIVERS SEATBELT
 10789 15 WPC REPLAE RIGHT FRONTR SEAT BELT BUCKLE
 AFTER TESTING SEVERAL TIMES VERIFIED CONCERN REMOVED AND REPALCED LEFT SIDE SEAT BELT
 REPLACED THE BUCKLE
 REPLACED THE BELT
 TECH 0458 BASIC7861203 CODE 42 CONFIRM DR SIDE SEAT BELT WONT LATCH AT TIMES RR DR SEAT ACCESS REPLACE SEAT BELT BUCKLE
 REPLACE L FRONT SEATBELT BUCKLE
 REPLACED SEATBELT RT FT SEATBELT
 REPLACED SEAT BELTS
 1 REPLACE DRIVERS SEAT BELT COMES UNLATCHED
 PERFORMED RECALL AND REPLACED SEAT BLET
 13437 REPLACED PASS SEAT BELT BUCKLE #28
 18894 REPLACE RIGHT FRT SEAT BELT BUCKLE BUTTON STICK 6 AT TIMES
 REPLACE RT FRONT SEAT BELT BUCKLE
 WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE
 REPLACE SEATBELT
 34405 81172A 0.4 0.4 REPLACED SEAT BELT BUCKLE
 REPLACE PASS FRONT SEATBELT
 REPLACED DRIVERS SIDE SEATBELT BUCKLE ASSY CC01
 SEATBELT RECEIVER FAILURE SEATBELT RECEIVER FRONT REPLACE
 UNLOCKS SEATBELT ASSEMBLY FRONT REPLACE
 REPLACED LFT FRT SEAT BELT BUCKLE ASSY. COMES LOOSE WHILE DRIVING.
 7861203 7861202 C C42 M20299 CHECK BOTH SEAT BELT OPERATION WITH RECALL TESTER FAIL REPLACED LEFT & RIGHT FRONT SEAT BELT
 REPL L FRONT SEAT BELT BUCKLE
 61202 M TIME TO REPLACE THE RIGHT FRONT SEAT BELT BUCKLE. STICKING, NOT RELATED TO RECALL.
 INSPECTED REAR MIDDLE SEAT BELT BUCKLE, WILL NO T LATCH, REPLACED SEAT BELT BUCKLE AND RETEST
 INSPECTED REAR MIDDLE SEAT BELT BUCKLE, WILL NO T LATCH, REPLACED SEAT BELT BUCKLE AND RETEST
 7861203 CC 42 0.8 TO REPLACE DRIVERS SEAT BELT BUCKLE. NGS BODY CHASSIS ELECTRICAL BCE START UP TEST NGS BODY CHASSIS E
 BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
 1 VERIFIED CONCERN INSTALLED SOP THE DRIVER SEAT BELT BUCKLE RETESTED OK AT THIS TIME
 PREVIOUSLY TEST SEAT BELT BUCKELS FOR LEFT AND RIGHT FRONT BUCKELS REPLACED LEFT LAST VISIT HAD TO ORDER RIGHT LAST R

REPLACED LEFT FRONT SEATBELT
 BROKEN REPLACE LEFT FRONT SEAT BELT BUCKLE
 DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT LATCH,RECHECKED OK.
 REPLACED DRIVERS SEATBELT BUCKLE
 REPLACE BOTH FRONT SEAT BELT ASY
 CHECK AND REPLACE DRIVERS SEAT BELT BUCKLE,WILL NOT FASTEN.
 REPLACED FRONT SEATBELT AS PART OF RECALL
 REPLACED SEAT BELT LATCH TO CORRECT
 1 DISCUSS WITH ERIC TAYLOR FORD CSM IN THE INTREST OF CUSTOMER SATISFACTION REPLACED FRONT SEAT BELT BUCKLES.
 CHECK AND TEST WILL NOT CLICK REMOVE AND REPALCE ASSMY RETES T
 BINDING REPLACE RIGHT FRONT SEAT BELT BUCKLE
 REPLACE RT FT SEAT BELT
 . REPLACED DRIVERS SEAT BELT ASSEMBLY TO CORRECT CONCERN
 SEAT BELT LATCH BROKEN M TIME TO REPLACE SEAT BELT LATCH
 789 BELT WONT LATCH REPL DRS SEAT BELT LATCH *28
 TECH VERIFIED COMPLIANT, REPLACED LEFT FRONT SEAT BELT BUCKLE, RETESTED, OK AT THIS TIME
 11114 REPLACE BOTH FRONT SEAT BELT BUCKLES
 REPLACE LEFT SEAT BELT BUCKLE
 REPLACED FRONT BELT ASY
 BROKEN NECESSARY TO REPLACE BROKEN SEAT BELT AND BUCKLE
 R/R SEAT AND REPLACE LEFT FRONT SEAT BELT
 1 REPLACE LEFT FRONT SEATBELT LATCH.
 L F SEAT BELT COMES UNBUCKLED REPLACED
 REPLACE LEFT AND RIGHT SEAT BELT BUCKLES.
 BUCKLE REPLACED PASS SEATBELT BUCKLE.
 15140 42 INOP INTALL SOP LF SEAT BELT BUCKLE
 RIGHT FRONT SEAT BELT WONT BUCKLE REPLACE RIGHT FRONT SEAT BELT BUCKLE END INOPERATIVE NO LABOR OPERATION IN SLTSM
 REPLACED LEFT FRT SEAT BELT BUCKLE
 CHECKED LEFT FRONT SEAT BELT FOUND BUCKLE NOT WORKING PROPERLY REMOVED AND REPLACED BUCKLE
 REPL LEFT FRT SEAT BELT BUCKLE WONT RELEASE
 VERIFY CONCERN FOUND DEFECTED SEAT BELT BUCKLE REMOVE SEAT AND REPLACE BUCKLE AND RETEST SYS O K AT THIS TIME.
 INSTALLED SEAT BELT
 REPLACED SEAT BELT BUCKLE.
 REPLACE DRIVERS SEAT BELT BUCKLE ASSY.
 61202.CC42 REPLACE R F SEATBELT
 DRIVER SEAT BELT DOESNT BUCKLE BROKEN REPLACED BUCKLE AND RETESTED OK
 5326 01 61203 R R DRIVER SEAT ACCESS REPLACED DRIVER SEAT BELT BUCKLE BINDING

SEAT BELT REPLACED
REPLACED DRIVER SIDE SEAT BELT BUCKLE.
TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.
INOP REPL FR SEATBELT ASY SEATBELT ASSEMBLY FRONT REPLACE
LOOSE SEATBELT ASSEMBLY FRONT REPLACE
11967 61202,42 DOES NOT OPERATE PROPERLY R R PASS FRONT SEAT REPLACED SEAT BELT BUCKLE
14022 ORIGINALLY TESTED FRONT BELT BUCKLES AND FOUND DRIVERS FAILED AND PASSENGERS PASSED LATER FOUND OUT SERVICE
INOP REPLACE RIGHT SEAT BELT
REPLACED SEAT BELT BUCKLE PER RECALL 01921
RECALL RECALL 01921,REPLACED DRIVERS SEAT BELT BUCKLE
BUCKLE WOULDNT LATCH,REPLACED AND TESTED OK
3391 DRIVERS SEAT BELT DOES NOT LATCH AT TIMES. R R DRIVERS SEAT TO GAIN ACCESS TO SEAT BELT ANCHOR. REMOVE AND REPLA
INOP SEATBELT ASSEMBLY FRONT REPLACE
WARR 944247 TEST AND REPLACE BOTH FRONT SEATBELT BUCKLES
REPLACE BUCKLE, RECK OK
INOP SEATBELT ASSEMBLY FRONT REPLACE
BUCKLE HAD A BROKEN & JAMMED PUSH BUTTON REPLACD THE DRIVER SIDE SEAT BUCKLE ASSY,TESTED ALL FUNCTIONS AFTER THE RE
R AND R SEAT T80 REPLACE DRIVERS SEAT BELT
REPLACE BUCKLE.
14584 DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH AND UNLATCH REPLACED BUCKLE AND RETESTED OK
1 REPLACED SEAT BELT ASSEMBLY. RETEST. O.K
REPLACE DRIVERS FRONT BUCKLE.
RECALL REPLACED SEAT BELT PER RECALL
REPLACE BOTH SEAT BELTS
802 DOES NOT OPERATE PROPERLY 019210 0.4 ADMIN 0.1 0.5HRS LG R R DRIVERS SEAT BELT BUCKLE, TESTED, OK. REMOVED DRIVERS
REPLACED DRIVERS FRONT SEAT BELT BUCKLE ASSEMBLY 61203 CALS 42
17088 DR LF SEAT BELT INOP W CC42 INSP AND RR DR SEAT TO ACCSSE SEAT BELT BUCKLE ASSY REPLACED LF DR SEAT BELT BUCKLE /
865 LEFT FRONT SEAT BELT WILL NOT LATCH. ACCESS LEFT FRONT SEAT AND REPLACED BUCKLE AND HARNESS ASSEMBLY. 1.0 CC 42 O
VERIFIED, NEED NEW BUCKLE.
BUCKLE FAILED REPLACE DRIVERS FRONT SEAT BELT BUCKLE
SEAT BELT BUCKLE BROKEN. PASS SIDE SEAT BELT BUCKLE INOP. REMOVED SEAT FOR ACCESS. R R BUCKLE, REINSTALLED SEAT AND V
REMOVE FRONT SEAT AND REPLACE BUCKLE
REPLACE SEAT BELT BUCKLE.
SEATBELT BINDING
REPLACED SEATBELT INOP
CC42 DOES NOT OPERATE PROPERLY MILES IN 2652 MILES OUT 2654 TESTED DRIVERS SEATBELT BUCKLE WITH RECALL TESTED FOUND T

INSPECTED AND REPLACED BOTH FRONT SEAT BELT BUCKLES.
 14884 CK BUCKLES REPLACE DR BUCKLE ORDERED MIDDLE SEAT BUCKLES
 FAIL TO LOCK SEAT CLIP R R SEAT BUCKLE ASSY
 10000 CP 81384 CC 38 PART REF. 892 81384A 0.4 0.4 REPLACE LH SEAT BELT BUCKLE WRONG COLOR
 INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.
 41 REPLACED BOTH FRONT SEATBELT BUCKLES
 REPLACED SEAT BELT BUCKLE
 REPLACED DRIVERS SIDE SEAT BELT BUCKLE(BUCKET SEATS) PER RECAL L,TECH 836
 REPL RT FRT SEAT BELT BUCKLE.REMOVE SEAT REPL BUCKLE.
 SEATBELT BUCKLE INOP REPLACED SEATBELT BUCKLE
 21004 7861203 CC 42 VERIFY CONCERN,R& R DRIVERS SEAT TO GAIN ACCESS AND REPLACED DRIVERS SEAT BELT BUCKLE,VERIFY REPA
 13644 W INSP AND FOUND PASS SEAT BELT TO BE STICKING WHEN RELEASED CHECKED SEAT BELT W SEAT TOOL BUT PASSED REPLACE
 VERIFIED CUSTOMERS CONCERN, REMOVED & REPLACED SEAT BELT BUCKLE, RETESTED, PASSED...
 REPLACED SEATBELT BUCKLE
 SEAT BLET HARD TO UN SNAP REPLACE BOTH SEAT BLET BUCKLES
 FAILED BUCKLE REPLACED BUCKLE
 R&R RT FRONT SEAT. REPLACED SEAT BELT BUCKLE ASSY....
 5834 REPLACE FRT BUCKLES AS PER RECALL
 6208 INOP 61203 42 WARR REPLACE LEFT SEAT BBELT BUCKLE 61202A
 BINDING (41) HAD TO ACCESS REAR MIDDLE SEAT & REPLACE CENTER SEATBELT BUCKLE, TK8562
 SEAT BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE
 INOP,WOULD NOT LOCK IN PLACE REPLACED SEATBELT BUCKLE.
 SOP M TIME TO REPLACE LEFT BUCKLE
 61230 M TIME TO REPLACE LEFT SEAT BELT BUCKLE
 REPLACE BOTH SEAT BELT BUCKLES
 42 REMOVED RITE FRONT SEAT FOR ACCESS TO BELT BUCKLE REPLACED BUCKLE AND REINSTALLED SEAT
 SEATBELT ASSEMBLY FRONT REPLACE (611A72 611A73) DRIVERS FRONT SEAT
 REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH
 TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE
 REPLACED THE LEFT FRONT SEAT BELT ASSEMBLY. CHECKED OPERATION, OKAY NOW.
 BUCKLE & SWITCH BAD SEATBELT ASSEMBLY FRONT REPLACE
 REPLACED BUCKLE
 CK OASIS,FOUND RECALL WAS PERFORMED AT ANOTHER DEALER.TEST SEAT BELT WITH TOOL AND IT DID NOT HOLD.REPLACE RF SEAT E
 INSTALLED NEW LEFT FRONT SEAT BELT
 18583 BELT RELEASE INT 1.3 CK BELTS,REPLACE BOTH BUCKLES AND DRIVERS BELT AND RETEST OK
 LEFT FRONT SEAT BELT BUCKLE NOT LATCHING CC 42 BPW7861203 BUCKET SEATS CHECKED OPERATION OF LEFT FRONT SEAT BELT BUC
 NECC TO REPLACE RIGHT SIDE SEAT BELT

REPLACE SEAT BELT BUCKLE
LEFT SEAT BELT BUCKLE INOP REPLACED BUCKLE
RT SEAT AND REPLACE DRIVERS SEAT BELT BUCKLE CHECK OP, OK
REPLACED LEFT FRONT SEAT BELT
DEFECTIVE CHECK BELT OPERATION, ORDER PART REMOVE D S SEAT REPLACE LATCH REASSEMBLE CHECK OPERATION OK
REPLACE DRIVERS SIDE SEAT BELT BUCKLE PER RECALL
660 LEFT FRONT SEAT BELT LATCH NOT OPERATING PROP 42 MT61203 VERIFIED CUSTOMER COMPLAINT THAT THE SEAT BELT LATCH ON
REPLACE RIGHT FRONT SEAT BELT BUCKLE
SEAT BELT COMES LOOSE INTERMITTENTLY, REPLACED LEFT FRONT SEAT BELT ASSEMBLY. RECHECKED, OK.
REPLACE LT FRT SEATBELT ASSY
WILL NOT LATCH. REPLACED RIGHT FRONT SEAT BELT.
DR SEAT BELT BUCKLE TESTED & REPLACED BUCKLE
COMPLETED RECALL
REPLACE DR SIDE SEAT BELT FOR RECALL
REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES
CHECKED AND CONFIRMED CONCERN. REPLACED SEAT BELT TO FIX REPAIR.
19565 INOP WAR REPLACT HE DR SIDE SEAT BELT BUCKLE, RETETS O
REPLACED LEFT DRIVERS SEAT BELT
HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.
REPLACE DRIVERS SEAT BELT
9808 REPLACED SEAT BELT BUCKLE TESTED ALL WORKS PROPERLY
LEFT FRT SEAT BELT BUCKLE SWITCH FAILED. VERIFIED CONCERN, TEST AND REPLACED LEFT FRONT SEAT BELT BUCKLE CLOSED BY W
REPLACED DRIVERS SIDE SEAT BELT BUCKLE
11848 SOP PART 0.8MT REMOVED AND REPLACED FEMALE SEAT BELT BUCKLE AFTER DUPLICATING CONCERN RETESTED QUALITY OK
FOUND SEAT BELT BUCKLE NOT LATCHING REPLACE SEAT BELT BUCKLE
BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
NA REMOVE AND REINSTALL SEAT, REMOVE AND REPLACE BUCKLE.
REPLACED BELT DUE TO BEING BROKEN
INOP SEATBELT ASSEMBLY FRONT REPLACE
INSPECTED AND FOUND PASS FRONT SEAT BELT BUCKLE FIT LOOSE REPLACE SEAT BELT VERIFY REPAIR
VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED NEW BUCKLE & RE CK OK
REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE
10521 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC 42 (
16980 ACCESS STEERING COLUMN & REPAIRED LOCK ACTUATOR BINDING
IT WOULD WORK SOMETIMES THEN GET HUNG UP REPLACED SEAT BELT BUCKLE WITH NEW
REPLACE SEAT BELT
REMOVED AND INSTALL DRIVER SEAT BELT BUCKLE (SOP OPERATE THE SEAT BELT AND BUCKLE TO VERIFY OPERATION.

18339 R&R L F SEAT, TEST & REPLACE SEAT BELT BUCKLE R&R R F SEAT, TEST & REPLACE SEAT BELT BUCKLE
REPLACED 2 FRONT SEAT BELT BUCKLES. RECALL HAD PREVIOUSLY BEEN DONE, CALLED RECALL HOTLINE AND TOLD TO SUBMIT AS A RECALL
A SEAT BELT BUCKLE
CC 42 BVA3IC 7861203 M O 22082 REMOVED AND REPLACED BOTH FRONT SEAT BELT RECEIVERS, RETESTED OK
NA REPLACED DRIVERS SIDE SEATBELT BUCKLE MILEAGE IS CORRECT ENTERED INCORRECTLY AT SPALDING FORD ON 01/01/01
SEATBELT BUCKLE ASSY. M TIME R R SEAT AND REPLACED IMPROPERLY LATCHING SEAT BUCKLE ASSY.
INOP REPLACE DRIVERS SIDE SEAT BELT BUCKLE
NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY
REPLACE INOP BUCKLE
INSTALL S.O.P SEAT BELT BUCKLE
VERIFIED CONCERN, INSPECTED AND FOUND FAULTY SEAT BELT BUCKLE..... REMOVED AND REPLACED SEAT BELT BUCKLE TO CORRECT
12498 FP 81203 CC 42 MT 61203 4 * ALTH 3131 REPLACED THE DRIVERS SEAT BUCKLE
SEAT BELT BUCKLE REPLACED SETA BELT BUCKLE
REPLACE LEFT FRN SEAT BELT BUCKLE
REPL SEAT BELT LATCH REPL SEAT BELT LATCH ASSY
INOP SEATBELT ASSEMBLY FRONT REPLACE
3848 SEATBELTS PASSED 01621 TEST, CUSTOMER STATES DRIVERS SEATBELT BUCKLE WILL COME LOOSE AFTER DRIVING AWHILE, REPAIR
9121 RECALL WARRANT VERIFY PERFORM RECALL RR PASSENGER BELT RECHECK OK
REPLACE LEFT FRN SEATBELT BUCKLE
BAD SEAT BELT TONGUE AND ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE
2413 ERRATIC W 42 REMOVE RT AND LEFT FRONT SEATS AND REPLACE SEAT BELT BUCKLES ON BOTH SEATS, ERRATIC
CUST STATE THE LEFT FRONT SEAT BELT BUCKLE WONT LATCH CAUSE: SEAT BELT CORRE: REPLA
REMOVED DRIVERS SIDE SEAT. R&R SEATBELT LATCH AND VERIFIED REPAIR.
9400 REPLACED DRIVERS SEAT BELT LATCH. *** QUALITY CONTROL BY JOHN MEDROW ***
INSPECT LF BELT BUCKLE BINDING DOES NOT LATCH REPLACE, INSPECT LEFT REAR 2ND ROW SEAT BELT OPERATION FOUND BINDING, REPAIR
REPLACE LEFT FRONT SEAT BELT BUCKLE
44788 REMOVE AND INSTALL SEATBELT ON PASSENGER SIDE
REPLACE SEAT BELT
REPLACE LEFT FRN SEATBELT
SEAT BELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE
ERRATIC OPERATION (33) ACCESS LF SEAT & REPLACE SEATBELT BUCKLE, TK0562
1 REPLACED L F SEAT BELT BUCKLE
98 01S21D 0.8 REPL D SIDE SEAT BELT
DEFECTIVE BUCKLE REPLACED SEATBELT BUCKLE CC42
REPLACE INOP SEATBELT INSTALLED SEAT BELT BUCKLE

7108 R&R SEAT AND SEAT BUCKLE
7881202 CODE 89 7448 M O RT BOTH FRONT BUCKET SEATS,REPLACED BOTH FRONT SEATBELTS. RETEST PASS.
1006 W 302 VERIFIED CONCERN,REPLACE DRIVER SEAT BELT RECIEVER DUE TO INOP,RETEST,OK AT THIS TIME. QUALITY INSPECTED BY 5
SEAT BELT BUCKLE REMOVED PASS SEAT AND REPLACED SEAT BELT BUCKLE.
3436 BROKEN 01 REPLACED LT FT SEAT BELT ASSY
REPLACED THE FRONT DRIVER SIDE SEAT BELT BUCKEL, THE DRIVER SIDE SEAT BLET BUCKLE WAS DEFECTIVE.
1 TECH REMOVED AND REPLACED DRIVER SIDE SEAT BELT ASY ALL OK AT THIS TIME
REPLACED SEAT BELT BUCKLE WITH NEW ONE
INSP AND VERIFY FRONT CENTER SEAT BELT BUCKLE INOP, REPLACED CENTER SEAT BELT BUCKLE, CHECK OPERATION OK. COND CODE
INSPECT LEFT FRONT TEAT BELT WITH TESTER, REPLACE LEFT FRONT SEAL BELT BUCKLE
REMOVED AND INSTALLED FRONT SEAT BELT
REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY
INOP SEATBELT ASSEMBLY FRONT REPLACE
INSTALLED DRIVERS SEAT BELT LATCH
LEFT FRT SEAT BELT INOP WILL NOT BUCKLE REPLACE
DOESNTOPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE
CHECKED OPERATION OF BUCKLE REPLACED DRIVERS SEAT BUCKLE ASSY AND QUALITY CHECKED OPERATION
CP 7881203 CC 42 DRIVERS SIDE SEATBELT TEST SEATBELT OPERATION, REPLACED SEATBELT
REPLACED BUCKLE
REPLACE DRIVERS SEAT BELT BUCKLE
33072 MT 7881203 .6 .6 REPLACED DRIVER SEAT BELT BUCKLE.
REPLACED BELT BUCKLE
CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.
REPLACE PASS SIDE SEAT BELT BUCKLE
1 DIAG UPON INSP REVEALED INTER MIT NO LATCH CAUSED BY BUCKLE INTERNAL DAMAGED BROKE REPLACED BUCKLE ASMPLY & CKD F
E VERIFIED COMPLAINT REPLACED FRONT BUCKLE ASSEMBLYS
823 42 REPLACED DRIVERS SIDE SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES
INSPECT AND REPLACE DRIVER SIDE SEAT BELT
REPLACED ALL FRONT SEAT BELT BUCKLES
DIAG AND RR SEATBELT
CHECK SEAT BELT PASS FRONT COME OUT AT WILL COULD NOT CONFIRM RECAA WAS PERFORM AND PASSED REMOVE AND REPLACE SE
SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
TRACK ASSEMBLY FRONT SEAT REPLACE
REPLACE LEFT FRONT SEATBELT END
VERIFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY, OK AT THIS TIME
SEAT BELT BROKE SEATBELT ASSEMBLY FRONT REPLACE

REPLACED DRIVER SIDE SEAT BELT CP 81203 CC 42
31170 BUCKLE R/L FT SEAT TO REPLACE SEAT BELT BUCKLE
RT FRT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
RENEW DRIVER SEAT BELT ASSY
RUN BCE DIAG. W NGS. RUN PINPOINT TEST. REPLACE LF FT SEAT BELT BUCKLE.
DRIVERS SEAT BELT WILL POP LOOSE REPLACE DRIVERS SEAT BELT WAITING.....
INSPECT. REPLACED L F SEAT BELT BUCKLE
SEAT BELT BUCKLE DEFECTIVE REPLACE DRIVER SIDE SEAT BELT BUCKLE
DEFECTIVE REPLACED DEFECTIVE DRIVERS SEAT BELT BUCKLE MILEAGE ERROR ON PRIC
VERIFY SEAT BELT BUCKLE INOP, R&R PASSENGER SEAT ASSEMBLY, REPLACED SEAT BELT BUCKLE, CHECK OPERATION
PERFORMED RECALL 01821, REPLACED DRIVERS SIDE SEAT BELT. 01821D...0.8...
BROKEN, CRACKED SEATBELT ASSEMBLY FRONT REPLACE
VERIFY CONCERN REPLACE SEAT BELT BUCKLE CORRECTED
1 R&R DRIVERS SEAT BELT BUCKLE ASSEMBLY. R&R SEAT TO ACCESS. RETEST. CC42
RPL DEFECTIVE SEAT BELT FOUND BY SEATBELT ASSEMBLY FRONT REPLACE
PERFORMED RECALL
1 DRIVERS SEAT BELT BUCKLE WILL NOT HOLD. CK AND REPLACED SEAT BELT. RETEST
RECALL REPLACE BOTH ISDES BUCKLES PER 01821
RECALL 01821 TECH 14507 MO 11714 REMOVED AND REPLACED DRIVERS SIDE SEAT BELT LATCH BUCKET POWER SEAT
PASS FRONT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
REPLACE PASSENGER SIDE SEAT BELT BUCKLE
10112 42 81384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE
1 REPLACED DRIVERS SIDE SEAT BELT BUCKLE
DOES NOT WORK PROPERLY. REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY.
14007 RECALL 01821O 0.4 REPLACE PASSENGER SIDE SEATBELT BUCKLE PER RECALL
REPL BUCKLE ASSY
15265 MT 81202 0.8 INSPECTED AND REPLACED RT. FRONT SEATBELT BUCKLE, R AND R RT. SEAT FOR ACCESS
RECALL INSPECT PER RECALL, R&R RT. FT. SEAT REPLACE BUCKLE
E COMPLETED ABOVE
SEAT BELT BUCKLE REPLACED LEFT SIDE SEAT BUCKLE
BROKEN SEATBELT ASSEMBLY FRONT REPLACE
INOP SEATBELT ASSEMBLY FRONT REPLACE
REPLACED SEAT BELT
REPLACED DRIVERS SEAT BELT
REPLACED SEAT BELT LATCH
7124 W INSP AND REPLACED PASS SIDE SEAT BELT RETESTED ALL OK

25688 SEATBELT ON DRIVERS SIDE FOUND FAULTY WARR VERIFIED CONCERN, FOUND SEATBELT BUCKLE FAULTY, REMOVED SEATBELT
REPLACE DRIVERS SIDE SEAT BELT BUCKLE
REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD
5190 42 W R&R DRIVERS SEAT FOR ACCESS, INSTALL DRIVERS BELT BUCKLE
BROKEN SEATBELT ASSEMBLY FRONT REPLACE
REPALCED DRIUVERS SIDE SEAT BELT BUCKLE
REPLACED SEAT BELT 01S21
REPLACE SEAT BELT ASSY
R&R SEAT CAPTAINS CHAIR TO REPLACE SEAT BELT AS SEMBLY, LOOSE
DRV SEAT BELT BUCKLE INOP CHECK AND NECESS TO REPL INOP DRV SEAT BELT BUCKLE
4860 61202 33 RIGHT FRONT SEAT BELT BUCKLE WAS LOOSE R I RIGHT FRONT SEAT TRACK TO REPLACE SEAT BELT BUCKLE. 81172A .4 6
A REPLACE LEFT SEAT BELT BUCKLE
REPL SEAT BELT BUCKLES
CC487 REPLACED BOTH SEAT BELT BUCKLES
CC487 REPLACED BOTH SEAT BELT BUCKLES
RF SEAT BELT WONT STAY LATCHED SEATBELT ASSEMBLY FRONT REPLACE
REPLACE RF SEATBELT BUCKLE
NO OPERATING PROPERLY REPLACE DRIVER SEAT BELT BUCKLE ASSY
18228 01S21D 0.8 9287 REPLACED DRIVERS SEATBELT BUCKLE PER RECALL
SEAT BELT INSP AND REPLACE SEATBELT BUCKLE
REPLACED LF SEATBELT.
01S21 INSPECT AND REPLACE ONE BUCKLE PER RECALL
SEATBELT RECEIVER INOP CK REPLACED DRIVERS SEATBELT BUCKLE RECEIVER
CC487 REPLACED SEAT BELT BUCKLE
REPLACED LEFT FRONT SEAT BELT BUCKLE ASSY. 03 18 13.32 14.31.

2001 Exped repeat repair TECH_TXT2

AT THIS TIME

IME

PLACED PASSENGER BUCKLE PER RECALL 01821 SEE RO 361719 FOR DRIVERS BUCKLE REPLACMENT.

MILEAGE ON RO 224538 SHOULD HAVE BEEN 2420 NOT 24206.

REPAIR ALL TO SPEC AT THIS TIME

SEAT

ASSY RETEST OK
QUALITY CHECKED BY MJM

VERIFY REPAIR..

TEST DID NOT PASS REPLACED DRIVERS SEATBELT BUCKLE AND RETEST

BUCKLE,REPLACED SEATBELT BUCKL E, VERIFIED REPAIR

1704AC .8

2001 Exped repeat repair. CUST TXT
 INSTALL S.O. PART FOR SEAT BELT BUCKLE (POSS RECALL)
 DRIVERS SEAT BELT BUCKLE INOP
 SO PART SEAT BELT INSTALL
 DRIVERS SEAT BELT COMES UNBUCKLED.
 S40 STATES THAT THE PASS SIDE SEATBELT IS NOT LATCHING PROPE
 CHECK SEAT BELT SOP
 REPLACE SEAT BELT (SOP) STICKS
 DRIVER SEAT BELT BUCKLE INOP
 CUST STATES THE DRIVERS SEAT BELT UNLATCHES WHILE DRIVING. CONCERN OCCURS INTERMITTENTLY..CK & ADVI

 INSTALL SPECIAL ORDER PARTS RELATED TO SEAT BELT RECALL ON PREVIOUS RO.
 DRIVERS SEAT BELT WONT LATCH
 CUST STATES DSIDE SEATBELT BUCKLE COMES LOOSE
 SEATBELT NOT STAYING ENGAGED
 DRIVERS SEAT BELT CAME UNLATCHED WHILE DRIVING..S40
 CK CAN NOT SECURE DRIVER FRONT SEATBELT
 CUSTOMER STATES SEATBELT RECALL INSTALL SOP
 LT FRONT SEAT BELT WONT LATCH AT TIMES S O
 FRONT SEAT BELT BUCKLES DO NOT FULLY LATCH
 LEFT FRONT SEAT BELT INTERMIT STICKS

 LEFT FRONT SEAT BELT UNHOOKS WHILE DRIVING
 CERTAIN 2001 GRAND MARQUIS, NAVIGATOR, AND TOWNCAR VEHICLES SEAT BELT BUCKLE RETENTION SEE RECA
 S28 CUST STATE LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING & LATCH ON BELT IS BACKWARD
 REPLACE LEFT AND RIGHT FRONT SEAT BELT BUCKLES S.O.PARTS
 SEAT BLET INOP
 CHECK SEAT BELT ON DRIVER SIDE WONT LATCH EASLY

 OWNER STATES LT FRT SEATBELT COMES OUT OF BUCKLE WHILE DRIVING
 CUSTOMER STATES SEAT BELT ON DRIVERS SIDE UN LATCHES ITSELF
 SEATBELTS DO NOT LATCH PROPERLY WITH TOOL
 CUSTOMER STATED THE DRIVERS SEAT BELT HAS COME UNLOCKED THREE DIFFERNET TIMES
 CUST STATES TO PERFORM SEAT BELT RECALL 01S21
 DRIVERS SEATBELT BUCKLE INOP
 FRONT SEAT BELT WONT LATCH
 SEAT BELT COME UN BUCKLED WHILE DRIVING

THE RIGHT FRONT SEAT BELT BUCKLE WILL NOT ENGAGE.
 PARTS REPLACE SEAT BELT ON THE DRIVERS SEAT
 CUSTOMER STATES DRIVERS SEAT BELT DOES NOT LATCH
 CUST STATES DRIVERS SEATBELT UNLATCHES ITSELF
 CUST STATES DRIVERS SEAT BELT WILL NOT CLIP SOP HERE
 CUSTOMER STATES DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH
 LEFT FRONT SEAT BELT WILL NOT BUCKLE AND CHIME STAYS ON
 RIGHT FRONT SEAT BELT BUCKLE INOP
 DRIVERS SIDE SEAT BELT LATCH NOT WORKING AT TIMES
 VEH SEATBELT LATCH INOP
 L F SEAT BELT W N LATCH
 C S THAT LEFT FRONT SEAT BELT RECIMER WILL NOT LOCK CHECK AND ADVISE

 CK RIGHT FORMT SEATBELT BUCKLE INTERMITTANTLY WILL NOT LATCH
 INSTALL SOP SEAT BELT BUCKLE.
 CHECK DRIVERS SEAT BELT COMES UNLATCHED S40
 RECALL 01S21 REPLACE SEATBELT
 PASSENGER SIDE SEATBELT BUTTON STICKS SOP IN
 RIGHT FRONT SEATBELT BUCKLE JAMS
 REPLACE RIGHT FRONT SEAT BELT BUCKLE WITH NEW WILL NOT LATCH PARTS IN STOCK TO REPLACE
 CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED

 PASSENGER FRONT SEAT BELT HARD TO CLASP IN
 CHECK PASS SIDE COMES UNLATCHED
 DRIVER SIDE SEAT BELT INOP
 C S THE DRIVERS SEAT BELT WILL NOT STAY LATCHED
 DRIVER S SEAT BELT KEEPS UNLOCKING WHILE DRIVING SEE FILE
 CUSTOMER STATES DRIVER SEAT BELT COMES OUT WHILE DRIVING SOP IN
 CUSTOMER STATES DRIVERS SEAT BELT WILL COME UNLATCHED BY ITSELF WHILE DRIVING.CC 826

 CUSTOMER STATES THE RIGHT FRONT SEAT BELT DOES NOT LATCH
 SPECIAL ORDERED PARTS ORDERED FOR RECALL, PREVIOUS RO 41082, TECH # 12, L F DRIVERS SEAT BELT, R F PASS SEAT SIDE, AND R
 SPECIAL ORDERED PARTS ORDERED FOR RECALL, PREVIOUS RO 41082, TECH # 12, L F DRIVERS SEAT BELT, R F PASS SEAT SIDE, AND R
 CUSTOMER STATES DRIVERS SEAT BELT INDICATOR INOP
 CUSTOMER STATES LEFT FRONT SEATBELT WONT LATCH
 S25 LEFT FRONT SEAT BELT WONT STAY LATCHED AT TIMES SPECIAL ORDER SEAT BELT LATCH HERE
 RECALL 01S21 SEAT BELT BUCKLE SOP HERE PASSENGER SIDE

SPO HERE FOR RECALL # 02S21 INSPECTED ON 12 19 01 RO# 10564 LEFT FRONT FAILED
 C S DRIVER SEAT BELT WONT LATCH
 CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.

 BOTH FRONT SEAT BELT DONT SNAP TOGETHER GOOD
 REPLACE DRIVERS SEAT BELT BUCKLE INOP
 CUST STATES PERFORM RECALL ON SEATBELT ASSY
 CK CUST STATES DRIVERS SEAT BELT WILL COME LOOSE FROM BUCKLE INTERMITTANTLY. S40

 PASS FRT SEAT BELT INSPECTION
 CK PASSENGER FRONT SEAT BELT WONT LATCH
 CUST STATES CK PASS FT SEAT BELT BUCKLE INOP
 CUST STS DRIVERS SEATBELT WONT LATCH
 CK PASS FRT SEAT BELT LATCH WONT STAY UP SOP IN
 DRIVERS BELT WILL NOT CLOSE
 LEFT FRONT DRIVER SEAT BELT INOP
 CUSTOMER STATES PASSENGER FRONT SEAT BELT WILL NOT CLICK IN BUCKLE
 SEAT BELT BUCKLE

 LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIMES
 LEFT SEAT BLET NOT LATCHING AT TIMES
 LEFT FRONT SEAT BELT COMES UNBUCKLED BY ITSELF AT TIMES
 CUST STATES L F SEAT BELT KEEPS COMING UNBUCKELED
 SEAT BELT INOP

 SOP SEAT BELT IN
 RF SEAT BELT WONT BUCKLE

 CHECK SEAT BELT P O
 DRIVERS SEAT BELT WILL NOT UNBUCKLE, SOMETIMES
 CHECK AND ADVISE CUST STATES DRIVER SIDE SEAT BELT DOES NOT LOCK IN TO BUCKLE. S40
 LEFT FRONT SEAT BELT WONT BUCKLE
 THE RIGHT FRONT SEAT BELT BUCKLE IS INOPERATIVE.
 CUST STATES DRIVERS SIDE FRONT SEAT BELT POPS OUT OF LOCK
 CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.
 CS DRIVER SIDE SEAT BELT BUCKLE KEEPS UNBUCKLING
 S25 LY FT SEAT BELT WONT STAY LATCHED

SEAT BELT BUCKLE RETENTION
 INSTALL S.O.P BUCKLE DRIVERS SEAT AS PER RECALL 01S21
 CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PPC PARTS HERE.
 RIGHT FRONT SEAT BELT WILL NOT CONNECT
 S40 CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING
 O R L F SEATBELT BUCKLE COME LOOSE
 S40 RIGHT FRONT SEAT BELT WAS ORDERED FOR RECALL BUT NEVER REPLACED IN STOCK
 RECALL SEAT BELT BUCKLE, REFER TO RO 961713
 PASS SIDE SEAT BELT DOESN'T WORK
 CUSTOMER STATES R F SEAT BELT NOT HOLDING ADVISE
 CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED RECALL WAS CHECKED NO PROBLEM B S 01 BY TECH
 PASSENGER SEATBELT COMES UNBUCKLED SOMETIMES
 S40 OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED AT TIMES, RED CAP DOESNT COME BACK UP PROPERL
 REPLACE DR. FT. SEATBELT SOP USE SPO 02128003
 CUST STATES CHECK FRONT SEATBELT BUCKLES

VERIFY THE SEAT BELT RECALL WAS PERFORMED CORRECTLY CUST THOUGHT A PART HAD TO BE ORDERED LAST VISIT BUT NO SOP IS I
 WARRANTY REPAIR DRIVER SIDE SEAT BELT BUCKLE WILL NOT HOLD
 DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING
 C S THAT THE DRIVER S SEAT BELT IS INOP
 DRIVERS FRONT SEAT BELT BUCKLE DOES NOT LATCH INTERM. WHEN IT DOES IT IS HARD TO GET BELT UN LACTCHED
 LEFT FRONT SEAT BELT DOES NOT STAY LATCHED. CHIME FOR SEAT BELT GOES OFF EVEN AFTER SEAT BELT IS BUCKLED
 DR FRT SEAT BELT COMES UNLATCHED WONT LATCH AT TIMES S39
 SEAT BELT ORDERED ON RECALL RO #13422

CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES LOCK
 CS DR SEAT BELY WONT LATCH S26
 S26 CUST STS LEFT FRONT SEATBELT UNLATCHES BY ITSELF SOP RO#329063 MI 13720 1 2 02
 S40 DRIVERS SEAT BELT WILL NOT LATCH
 CUSTOMER STATES THE DRIVERS SEAT BELT DOES NOT ALWAYS LOCK IN 3
 CK FOR DRIVER SIDE SEATBELT INOP FEMALE PART
 PASS FRONT SEAT BELT INOP
 DR. SEAT BELT BUCKLE HAS COME LOOSE TWICE SINCE RECALL PERFORMED.
 DRIVERS SEAT BELT
 L.F. SEAT BELT BUCKLE WONT LATCH SOP IN
 INSTALL SOP PASS FRONT SEAT BELT INOP
 CUSTOMER STATES: DRIVERS SEAT BELT COMES UNBUCKLED WHILE DRIVING.

CHECK SEATBELTS
 S40 CK MID SEAT AND DRIVERS SEAT BELTS WILL COME UNBUCKLED. RELATED TO 01S21 IF SO REFERENCE BACK.
 C 8 LF SEAT BELT WONT LOCK CK AND ADVISE
 T80 SEE DUANE DRIVERS FRONT SEAT BELT WONT LATCH INT TRIM TAN 1H
 CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED
 DRIVERS SEAT BELT INOP PART HERE REF.RO#4092, TECH 117 BY NOON
 S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIVE..
 SEAT BELT BUCKLE INSTALL SOP
 CUSTOMER STATES RIGHT SEATBELT DOES NOT ALWAYS LATCH
 CUSTOMER STATES DRIVERS SEAT BELT BUCKLE INOP
 S28 DRIVERS SIDE FRONT SEAT BELT UNBUCKLES BY ITSELF
 CUST STATES PASS FRIT SEAT BELT WILL NOT LATCH
 S40 CUSTOMER STATES PASSENGER SIDE SEAT BELT BUCKLE STICKING, STATES NOT LATCHING...
 SEATBELT BUCKLE UNLATCHES
 CK BOTH DRIVER AND PASSENGER SEAT BELT HARD TO UNSNAP
 CUST STATES PASS FRIT BELT WONT LATCH CHECK AND ADVISE
 CUST SAYS RIGHT FRONT SEAT BELT DOES NOT HOLD AND COMES UNLATCHED
 REPAIR RIGHT AND LEFT FRIT SEAT BELT BUCKLES DO NOT CATCH AT TIMES. ** PARTS ORDERED & HERE ** TECH# 8370 **
 CUST STATES LEFT SEAT BELT GET LOOSE WHEN DRIVING
 CUST STATES MIDDLE SEAT CENTER SEAT BELT WONT LATCH
 SEAT BELT CHIMES SEAT BELT DOESNT CLICK IN ALL THE WAY
 SEAT BELT BUCKLE INOP. SERVICE INSTALL PART
 INSTALL SOP SEAT BELT BUCKLE
 DRIVERS SEAT BELT WILL NOT BUCKLE
 FRONT SEAT BELT BUCKLES ERRATIC WONT LATCH.
 CUST STATES THAT PASS SIDE FRIT SEAT BELT WILL NOT LOCK S28
 CUST ST THE DRIVERS SIDE BUCKLE IS COMING LOOSE SEATBELT POPS OPEN BY ITSELF
 DRIVER SIDE SEATBELT DONT HOLD
 CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE
 CUSTOMER STATES THE DRIVERS SEAT BELT WILL POP OUT (UNLATCH) WHILE DRIVING.
 CK DRIVERS SIDE FRONT SEAT HAS COME LOOSE WHILE DRIVING
 CUSTOMER STATES DRIVERS SEATBELT DOESNT LOCK CLICK SHUT
 RF SEAT BELT DOES NOT ALWAYS LATCH
 CUSTOMER STATES: DRIVER SEAT BELT IS INOPERATIVE; PER S.O.P INSTALL SEAT BELT PART. INSPECT AND ADVISE
 CUSTOMER STATES DRIVERS SIDE SEAT BELT RECEPTICLE DOES NOT ALWAYS LATCH. BUCKLE WAS INSPECTED LAST MONTH PER RECA
 CUST STATES SEAT BELT INOP

SEAT BELT INOPP

O S DRIVERS SIDE SEAT BELT BUCKLE INOP. INSTALL SPEC ORDERED PART

LEFT FRONT SEAT BELT WILL NOT STAY LATCHED

DS SEATBELT INOP

DRIVERS SEAT BELT DOES NOT ALWAYS LATCH SOP HERE

S40 CUS STS THAT THE LF SEAT BELT WONT LATCH, S O PART

CK R FRT SEAT BELT BUCKEL WONT LATCH

CUST STATES DRIVERS SEATBELT KEEPS COMING UNHOOKED

LEFT FRONT SEAT BELT WONT LATCH

C S RIGHT FRONT SEAT BELT WILL NOT LOCK INTO RECEIVER

DRIVER SEAT BELT STICKS OR DOESNT MAKE A CLICKING NOISE TO LOCK IN

PERFORM RECALL 01S21 SEAT BELT BUCKLE

S O PART SEAT BUCKLE DRIVERS FT

USE SPO 01267005

REPAIR FOR DRIVER SEAT BELT COMES UNDONE AT TIMES.INSTALL SOP.

DRIVER SEAT POSITION THE MALE END OF SAFETY BELT KEEPS POPPING OUT.

ADD ON WARRANTYDRIVER SEATBELT DOES NOT ALWAYS STAY SECURE

CUSTOMER STATES, DRIVERS SIDE SEAT BELT FAILED INSTALLED SOP SEAT BELT (DRIVERS)

CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART

THE DRIVERS SEATBELT IS NOT WORKING PROPERLY SOP HERE

CUSTOMER STATES DRIVERS SEATBELT BUCKLE NOT WORKING PROPERLY

CHECK AND ADVISE IN SEATBELT

CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING

CUSTOMER SAYS THE PASSENGER SEAT BELT WONT LOCK

CUSTOMER STATES THAT THE PASS SEAT BELT WILL NOT LOCK INTO PLACE

INSTALL SPO # 01281014 CUSTOMER STATES PASSENGER SIDE SEAT BELT IS NOT WORKING , TECH # 110 PART #7861202 AAA

CUST STATES FRONT SEAT RIGHT OUTER BELT DOESNT LATCH

DRIVERS SEAT BELT UNBUCKLES

PASSENGER FRONT SEAT BELT COMES UNLATCHED WHEN DRIVING

3 38

RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK

S40 PER CUST, THE DRIVERS SEAT BELT COMES UNLATCHED. SEE HISTORY

T60 C S DRIVERS SEAT BELT WONT STAY LATCHED SOP

DRIVERS SEATBELT KEEPS COMING UNLATCHED.

DRIVER SIDE SEAT BELT WON T LOCK

CUST STATES D S SEATBELT BUCKLE WONT LATCH

REPLACE DRIVERS SEAT BELT (FINISH LINE A

CHECK SEAT BELT OPERATION
RECALL 01S21 SEAT BELT BUCKLE RETENTION BOTH SIDES FAILED
01S21 SEAT BELT BUCKLE SOP
CUSTOMER STATES DRIVERS SEATBELT INOPERATIVE S O PART IN ? SEE HISTORY
SEAT BELT ON DRIVERS SIDE WILL NOT STAY LOCKED
INSTALL S.O.P#02117011 CUSTOMER STATES RIGHT FRONT SEAT BELT INOP
CUST STATES DRIVER SIDE SEATBELT KEEPS COMING UNBUCKLED SOP PART IN STOCK
DRIVERS SEATBELT UNBUCKLES WHILE DRIVING
RIGHT FRONT SEAT BELT INOP
LEFT SEAT BELT BUCKLE IS NOT WORKING
C S DRIVER SEAT BELT INOP.....
S40 C S THE DRIVERS SEAT BELT POPS LOOSE WHEN DRIVING
CUS STATES D SIDE SEAT BELT COMES UNDONE RO 96954 RECHECK TECH 160
L F SEAT BELT BUCKLE WONT RELEASE
SEAT BELT ON DRIVERS SIDE WILL NOT BUCKLE
CUSTOMER STATES THAT AFTER THE SEAT BELT RECALL WAS DONE THE PASS FRONT SEAT BELT POPS OFF
S25 DRIVERS SEAT BELT WILL NOT STAY BUCKLED (01S21?)
ADD SOP SEAT BELT IN PASSENGERS SIDE BUCKLE FOR RECALL
OWNER STATES DRIVERS SEATBELT COMES UNLATCHED WHEN PULLED ON
DRIVERS SEAT BELT DOESNT LATCH, INSTALL SOP PARTS USE SOP 01188002
S40 DRIVERS SIDE SEAT BELT UNCLICKED OVER BUMP TWICE
CUSTOMER STATES THE LEFT FRONT SEAT BELT BUCKLE WONT LATCH (GRAY)
DRIVER SEATBELT INOP
CHECK DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING CHECK OTHER SEAT BELTS FOR PROPER OPERATION
C S DRIVER SEAT BELT BUCKLE INOP ALSO LEFT REAR SEAT BELT KEEPTS TIGHTING UP
CHECK AND ADVISE ON DRIVERS SEAT BELT WILL COME UNLOCKED WHEN DRIVING SOP HERE
RT FT SEATBELT WONT HOLD IN BUCKLE ASY
CUSTOMER STATES RIGHT FRONT SEAT BELT IN OP REPORT
CUST STATES SEAT BELT DRIVERS SIDE WILL COME LOOSE
S40 CUST STATES FRONT PASS BUCKLE WILL NOT LATCH. (SOP HERE)
LEFT FT SEAT BELT SEAT BELT COMES UNBUCKLED FOR NO REASON
CHK FOR D SEATBELT COMING UNLATCHED WHILE DRIVING.
S40 CUST STATES LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIME POPS OUT WHILE DRIVING
CK SEATBELT WONT LATCH
INSTALL SOP HERE FOR SEATBELT

S40 CUST STATES PASS SEAT BELT DOES NOT LATCH EVERY TIME
 CUSTOMER STATES DRIVERS SEAT BELT KEEPS COMING UNLATCHED PLS RECHECK PASSENGERS AS WELL
 S40 CUST CONCERN DRIVER SIDE SEAT BELT NOT WORKING CORRECTLY
 SEAT BELT INOP (PARTS HERE)
 S05 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES
 S40 D S F RESTRAINT UNLOCKS WHILE DRIVING
 CUST STATES INNT THE DRIVER SEAT BELT WILL POP OUT FROM THE BUCKLE CHECK AND ADVISE
 DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING LIGHT TAN
 CUST STATES FRONT SEAT CENTER SEAT BELT INOP, PLEASE INSTALL SOP SEAT BELT, SEE PHIL IN PARTS

 INSTALL SPECIAL ORDERED BELT BRAKES FRONT SEATBELT BROKEN REFER BACK TO RO 142840
 CUST STATES PASS FRONT SEAT BELT BUCKLE WILL NOT ACCEPT BELT INTO RECEPTACLE WITHOUT DEPRESSING BUTTON AND FORCIN
 DRIVER SEATBELT WILL NOT BUCKLE AT TIMES USE SPO 02058001
 DRIVERS SEATBELT WILL NOT STAY LATCHED INSTALL SOP
 DR SEATBELT WONT FASTEN
 CK THE SEAT BELT DRIVER SIDE NOT LATCHING PROPERLEY
 S28 CUST STATES DRIVERS SEAT BELT WONT STAY LATCHED
 C S THE SEAT BELT WILL COME UNLATCHED
 CUST HAS RETURNED TO HAVE SOP INSTALLED. (REFER TO HISTORY RO#: 68917)
 C S TYHAT THE DRIVER SEAT BELT ENTERPRISE D#278635
 THE DRIVERS SEAT SEATBELT RECIEVER KEEPS LETTING LOOSE OF THE BELT, CHECK AND ADVISE

 CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...

 DRIVER SEAT BUCKLE WILL NOT ALWAYS LATCH
 CUST STATES SEAT BELST WONT LATCH INSTALL S.O.P.
 DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED AT TIMES
 CUST STATES THE DRIVERS SEAT BELT WILL NOT STAY LOCKED POPS OFF WHILE DRIVING

 S40**DRIVERSIDE DEAT BELT LATCH WILL NOT STAY LATCHED
 CUSTOMER STATES SEAT BELT WILL NOT LATCH SOP HERE
 PASS SEAT BELT WILL NOT LOCK CK ALL SEAT BELTS
 PASSENGER FRONT SEATBELT DOESNT LATCH
 C S DRIVERS FRONT SEAT BELT UNBUCKLES WHEN STOPPING
 CUSTOMER STATES DRIVERS SEATBELT WILL NOT LATCH SOMETIME
 A99 DRIVER SIDE SEAT BELT WILL NOT STAYED BUCKLE
 LEFT SEAT BELT WILL NOT LATCH

PARTS REPLACEMENT SEAT BELT
 INSP. L F SEAT BELT WILL NOT BUCKLE AT TIMES AND IS HARD TO BUCKLE AT OTHER TIMES
 CUSTOMER STATES RIGHT FRONT SEAT BELT INOP SOP
 CUST STATES DRIVERS SEAT BELT COMES UNHOOKED
 CUST STATES SOP IS IN FROM FRI SEAT BELT
 CUST STATES DRIVERS SEAT BELT WILL POP LOOSE WHEN DRIVING, REBUCKLE AND WILL POP LOOSE AGAIN
 CUSTOMER STATES DRIVERS SEATBELT BUCKLE DOES NOT HOLD BELT AT TIMES. CHECK AND ADVISE.
 SEAT BELT N DR SIDE COMES APART WHILE DRIVING WILL NOT STAY LATCHED
 REPLACE DEFECTIVE SEATBELT BUCKLE SPW
 CUSTOMER STATES PASSENGER FRONT SEAT BELT WASNT BUCKLEY CORRECTLY
 PERFORM 01S21 SEATBELT BUCKLE
 PASS SEAT BELT WILL NOT LATCH PART HERE
 PASS. SIDE SEAT BELT INOP WILL NOT LATCH AT TIMES
 CUSTOMER STATES DRIVER SEATBELT LATCH INOP.SOP ORDERED BY CS.SEE DENNIS IN PARTS.
 REPLACE DEFECTIVE SEAT BELT FOUND BY SEAT BELT RECALL INSPECTION
 SEAT BELT RECALL .01S21.SPECIAL ORDERED PARTS HERE
 CUST STATES DRIVERS SEAT BELT BUCKLE WONT HOLD, IF BUMP IT WILL LET GO
 RECALL 01S21 BOTH FAILED CUS
 T90 RT FRT DRIVERS SEAT BELT BUCKLE FAILS RECALL TEST 01S21 ON RO 85231 INSTALL SOP DRIVERS SEAT BELT BUCKLE
 PASS FRONT SEAT BELT INOP PARTS IN \$16
 FAULTY SEAT BELT BUCKLES
 CK DRIVERS SEAT BELT WONT STAY ATTACHED
 DRIVERSIDE SEAT BELT WILL NOT OPERATE INSTALL SPECIAL ORDER PART
 CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE DOES NOT WORK PROPERLY
 01S21 REPLACE PASSENGER SIDE SEAT BELT BUCKLE SOP IN
 SOP HERE FOR SEAT RECALL 01S21 REF RO 200456
 CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE INOP.
 840 PASS SIDE MIDDLE SEAT BELT LATCH COMING APART
 CUST STATES PASS FRONT SEAT BELT WILL NOT STAY LATCHED UNBUCKLES WHEN DRIVING DOWN THE ROAD AND LEFT
 CUSTOMER STATES THAT THE FRONT SEAT BELT ARE NOT LOCKUNG IN NEEDS LEFT AND RIGHT SIDE BELT TRIM CODE 12
 CUST STATES DR SIDE SEAT BELT INOP SOP IN
 CUST STATES DRIVER SEAT BELT SNAPS LOOSE BY ITSELF POPS OUT BY ITSELF
 CUSTOMER STATES DRIVERS SEAT BELT KEEP COMING UNBUCKLED
 SEAT BELT ON DRIVERS SIDE INOP
 CS THAT THE DRIVERS SEAT BELT WILL NOT FASTEN AT TIMES
 DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED
 SOP IN CUST STATES VEH HAS SEAT BUCKLE WILL NOT LATCH.

CUST STATES THAT THE DRIVERS SIDE SEAT BELT COMES UNBUCKLED WHILE DRIVING
REPLACE SOP SEAT BELT
S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING
S40 DRIVER SEAT BELT NOT CLICKING TO LOCK
CUSTOMER STATES RIGHT FRT SEATBELT**** FEMALE SIDE WONT LATCH
DIAG DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES CUST HAS TO FIRST PUSH RELEASE AND THEN IT WILL BUCKLE CHECK ALL O
RECALL 01S21 DRIVER FRONT SEAT BELT USE SPO 01309037
CHECK SEAT BELT
THE DRIVERS SEAT BELT RELEASES WHILE DRIVING
SOP SEAT BELT
PASSENGER SIDE FRONT SEAT BELT BUCKLE CLICKS.
S26* DRIVERS SEAT BELT KEEPS COMING LOOSE
LEFT SEAT BELT BUCKLE COMES LOOSE BY SELF
REPLACE CENTER ROW RIGHT SEAT BELT BUCKLE PER TOM PEELER FOE
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/ 139533
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/ 139533
CUSTOMER STATES SEAT BELT KEEPS UN LOCKING
STATES SEAT BELT WILL NOT LATCH S40
CUST STATES SEAT BELT IS INOP (SOP IN STOCK)
SEAT BELT WILL NOT CONNECT PROPERLY USE SPO 01212002
DRIVER SEAT BELT LATCH HANGS AT TIMES
RECALL 01S21
CK DRIVERS SIDE SEATBELT UNBUCKLES ON ITS OWN
S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE
CHECK LEFT FRONT SEAT BELT BUCKLE IN OP AT TIMES WONT POP UP

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair_AREA_CD	2001 Exped repeat repair_COUNTRY_CD	2001 Exped repeat repair_SLS_DLR_CD
609	USA	315040
*	USA	342574
952	USA	343008
783	USA	343318
423	USA	348235
608	USA	315040
201	USA	314340
*	USA	355836
908	USA	354172
313	USA	345345
714	USA	354285
616	USA	345160
732	USA	314378
208	USA	351077
970	USA	355491
781	USA	312888
508	USA	312190
925	USA	351078
847	USA	342412
889	USA	345237
518	USA	314361
810	USA	345275
757	USA	328837
818	USA	353559
724	USA	318309
847	USA	342535
615	USA	322320
518	USA	314361
808	USA	351484
303	USA	355115
314	USA	383197
558	USA	351048
914	USA	314541
*	USA	355836
620	USA	383174
873	USA	314474

01_Exped_NavFrontBuckle_Query

617	USA	312388
270	USA	348688
641	USA	
904	USA	325082
303	USA	356120
281	USA	387032
803	USA	312483
301	USA	328488
410	USA	328057
*	USA	355838
*	USA	355838
480	USA	354289
518	USA	314381
847	USA	342535
610	USA	315304
713	USA	387288
423	USA	326105
757	USA	328278
703	USA	328008
810	USA	345358
516	USA	383588
781	USA	312288
913	USA	383407
843	USA	328223
770	USA	326140
770	USA	328233
407	USA	325188
901	USA	322884
407	USA	326218
310	USA	354280
714	USA	354015
925	USA	351024
925	USA	351024
714	USA	354015
407	USA	325132
613	USA	325189
619	USA	354800

01_Expnd_NavFrontBuckle_Query

407	USA	325184
407	USA	325032
214	USA	327510
605	USA	354290
813	USA	325007
334	USA	326332
205	USA	326378
770	USA	326057
605	USA	354290
334	USA	326135
702	USA	354137
281	USA	367023
818	USA	354301
681	USA	354041
767	USA	328278
205	USA	326075
770	USA	326057
909	USA	354263
512	USA	367036
682	USA	322423
405	USA	367235
818	USA	354301
912	USA	326218
908	USA	354015
605	USA	354290
305	USA	325044
713	USA	367023
310	USA	354100
812	USA	325182
688	USA	354565
562	USA	354061
803	USA	326218
404	USA	326135
281	USA	367023
714	USA	354015
203	USA	124009
713	USA	152031

01_Exped_NavFrontBuckle_Query

972	USA	152525
706	USA	121214
660	USA	172013
919	USA	121019
214	USA	152003
407	USA	124224
713	USA	152031
281	USA	152054
770	USA	121025
813	USA	124449
770	USA	121022
409	USA	152052
281	USA	152026
210	USA	152058
770	USA	121024
415	USA	172013
941	USA	124402
854	USA	124009
281	USA	152052
972	USA	152017
281	USA	152054
979	USA	152734
972	USA	152017
940	USA	152414
813	USA	124451
305	USA	124901
318	USA	123038
407	USA	124227
713	USA	152049
949	USA	171034
770	USA	121480
305	USA	124012
972	USA	152017
972	USA	152017
512	USA	152303
407	USA	124226
281	USA	152046

01_Exped_NavFrontBuckle_Query

626	USA	171083
913	USA	153008
958	USA	152104
949	USA	171074
580	USA	152588
770	USA	148208
972	USA	152509
954	USA	124009
915	USA	152540
210	USA	152067
817	USA	152018
817	USA	152020
628	USA	171073
210	USA	152063
228	USA	
714	USA	171057
972	USA	152013
405	USA	152684
306	USA	124007
817	USA	152018
979	USA	162134
979	USA	152134
714	USA	171082
803	USA	121274
818	USA	124208
704	USA	121212
808	USA	116445
805	USA	171488
412	USA	144017
201	USA	113147
704	USA	121213
516	USA	113083
570	USA	116574
.	USA	
760	USA	171079
810	USA	146048
201	USA	113154

01_Exped_NavFrontBucks_Quary

412	USA	144007
732	USA	113588
206	USA	174024
708	USA	
302	USA	127588
248	USA	148439
812	USA	147527
873	USA	113048
810	USA	148048
703	USA	127049
201	USA	113147
310	USA	171208
818	USA	171251
301	USA	127047
816	USA	172202
703	USA	127081
248	USA	148028
803	USA	111582
317	USA	147027
816	USA	153015
225	USA	123203
405	USA	152208
819	USA	171102
760	USA	171078
361	USA	152069
407	USA	124476
714	USA	171052
826	USA	171097
281	USA	152047
819	USA	171080
209	USA	172514
512	USA	162302
504	USA	123009
713	USA	152024
770	USA	121025
305	USA	124003
650	USA	172024

01_Expnd_NavFrontBuckle_Query

504	USA	123008
480	USA	171175
708	USA	121205
841	USA	184480
770	USA	121488
582	USA	171104
854	USA	124010
210	USA	152007
780	USA	171430
818	USA	171058
805	USA	171452
830	USA	152719
601	USA	123205
210	USA	152057
561	USA	124218
404	USA	121007
407	USA	124215
713	USA	152049
854	USA	124015
281	USA	152037
702	USA	171187
407	USA	124227
582	USA	171058
252	USA	121848
817	USA	152018
828	USA	171178
908	USA	171108
308	USA	141078
610	USA	172013
409	USA	152754
214	USA	152003
704	USA	121213
817	USA	152013
817	USA	152009
836	USA	152188
908	USA	171087
310	USA	171015

01_Exped_NavFrontBuckle_Query

561	USA	124224
941	USA	124480
954	USA	124015
910	USA	121225
972	USA	152002
305	USA	124001
408	USA	172039
835	USA	152168
719	USA	158481
818	USA	171019
910	USA	121225
780	USA	171430
910	USA	121028
708	USA	141052
954	USA	124015
337	USA	123271
601	USA	123309
318	USA	123223
323	USA	171022
972	USA	152012
938	USA	152166
310	USA	171029
915	USA	152018
805	USA	171452
281	USA	152024
310	USA	171016
972	USA	152482
681	USA	171491
818	USA	171019
214	USA	152003
770	USA	121405
281	USA	152044
702	USA	171167
813	USA	124208
915	USA	152573
281	USA	152032
626	USA	171072

01_Exped_NavFrontBuckle_Query

305	USA	124003
817	USA	152020
881	USA	171491
813	USA	124445
228	USA	124017
251	USA	124017
916	USA	172201
985	USA	123050
843	USA	121281
727	USA	124202
817	USA	152019
808	USA	152578
872	USA	152525
254	USA	152504
252	USA	121644
865	USA	121889
251	USA	124017
727	USA	124454
727	USA	124202
258	USA	121108
940	USA	152529
872	USA	152014
813	USA	124488
812	USA	124482
849	USA	171082
872	USA	152012
826	USA	171040
214	USA	152003
256	USA	121717
252	USA	121647
714	USA	171057
770	USA	121025
770	USA	121059
828	USA	121810
582	USA	171051
229	USA	121408
817	USA	152020

01_Exped_NavFrontBuckle_Query

757	USA	127060
703	USA	127009
210	USA	152063
407	USA	124227
949	USA	171095
405	USA	152603
770	USA	121080
614	USA	147030
2B1	USA	152052
908	USA	171150
619	USA	171080
214	USA	152003
706	USA	121205
404	USA	121001
818	USA	171040
818	USA	171040
386	USA	124200
818	USA	171043
912	USA	121209
908	USA	171152
919	USA	121019
602	USA	171173
770	USA	121007
919	USA	121026
818	USA	171040
628	USA	171031

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair_TXN_CD	2001 Exped repeat repair_CNTRY_SOLD	2001 Exped repeat repair_QRT_CD
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
2	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21

01_Exped_NavFrontBuckle_Query

2	USA	Q21
E83	USA	Q21
E84	USA	Q21
E84	USA	Q21
1	USA	Q21
E84	USA	Q21
1	USA	Q21
2	USA	Q21
E84	USA	Q21
E84	USA	Q21
E90	USA	Q21
1	USA	Q21
1	USA	Q21
E84	USA	Q21
2	USA	Q21
1	USA	Q21
E84	USA	Q21
E84	USA	Q21
E84	USA	Q21
E84	USA	Q21
2	USA	Q21
1	USA	Q21
E84	USA	Q21
1	USA	Q21
2	USA	Q21
E84	USA	Q21
1	USA	Q21
1	USA	Q21
E84	USA	Q21
2	USA	Q21
E84	USA	Q21
E84	USA	Q21
E84	USA	Q21
2	USA	Q21
E84	USA	Q21
E84	USA	Q21
1	USA	Q21
1	USA	Q21
E84	USA	Q21
2	USA	Q21
E84	USA	Q21
E84	USA	Q21
1	USA	Q21
1	USA	Q21

01_Exped_NavFrontBuckle_Query

EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB3	USA	Q21
2	USA	Q21
2	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21

01_Exped_NavFrontBuckle_Query

EB4	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21

01_Exped_NavFrontBuckle_Query

1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21

01_Exped_NavFrontBuckle_Query

EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
2	USA	Q21
2	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
2	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB1	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21

01_Exped_NavFrontBuckle_Query

EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB1	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21

01_Exped_NavFrontBuckle_Query

2	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
2	USA	Q21

01_Exped_NavFrontBuckle_Query

EB3	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
2	USA	Q21
EB1	USA	Q21
1	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21

01_Exped_NavFrontBuckle_Query

EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
1	USA	Q21
1	USA	Q21
2	USA	Q21
2	USA	Q21
2	USA	Q21
1	USA	Q21
2	USA	Q21
2	USA	Q21
EB4	USA	Q21
EB4	USA	Q21
1	USA	Q21
EB4	USA	Q21
2	USA	Q21
2	USA	Q21
1	USA	Q21
2	USA	Q21
1	USA	Q21
EB4	USA	Q21

01_Exped_NavFrontBuckle_Query

V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V06	B3	S08
V05	B3	S08
V05	B3	S08
V06	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V83	B3	S08
V05	B3	S08
V05	B3	S08
V74	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V08	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V06	B3	S08
V06	B3	S08
V06	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08
V05	B3	S08

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair_TIS_FLAG	Days Between Repair	Miles Between Repair
	44	1425
0	252	10998
	20	7948
0	224	9714
	28	1760
	78	3379
	28	1015
	3	421
0	230	-18416
	4	1
	213	14267
	278	18932
0	224	7729
	15	218
	24	3118
	286	14500
	121	4802
	113	4787
	14	261
	108	6135
	217	7871
	55	1227
	81	1352
	105	8847
	78	1806
	28	1428
	118	2207
	78	2469
0	275	3889
	46	488
	77	244
	0	0
0	261	10690
	63	8509
	160	4193
0	283	17845

01_Exped_NavFrontBuckle_Query

			28	9
			22	514
0			36	472
			279	20993
			230	9371
			147	4541
			80	4592
0			226	8297
0			245	18144
			87	12405
			130	14490
			170	2580
			3	3
			70	7294
			22	687
			12	205
			65	2987
			35	1517
			0	0
			52	1188
			2	49
			12	581
0			295	16885
			70	2654
			48	2784
			157	6485
			14	990
			26	3335
0			209	10798
			189	4489
			4	204
			109	5684
			0	0
			8	347
			107	8512
			6	96
			22	248

01_Expd_NavFrontBuckle_Query

			88	8178
			281	6907
			138	11454
			180	8588
			11	847
			21	531
			82	3190
			122	581
			27	2001
6			258	10593
			183	14153
			38	1841
			84	1884
			221	13488
			9	142
			187	2084
			128	5115
			151	7584
			141	11884
			70	5163
			120	8241
			184	9444
6			294	9828
			58	2888
			22	831
			147	4872
			48	200
			231	5118
			81	2378
			85	1754
			151	6783
6			273	8802
			74	5032
			0	0
			182	10588
6			32	15
			14	484

01_Expnd_NavFrontBuckle_Query

			172	8677
			8	786
			28	592
			122	-8525
			5	120
			34	1457
			148	5051
			0	-1
			182	8104
			23	664
			48	3885
●			317	13799
			35	-20615
●			37	2842
			165	2258
			91	5928
			92	3880
			0	0
			29	1638
●			210	18670
			149	8858
			34	2109
●			0	0
			85	6577
			15	5
			19	715
			272	11089
			224	-32785
			80	848
			24	780
●			232	8736
			182	7291
			40	308
			0	0
			8	758
			12	22
			85	8648

01_Expel_NavFrontBuotle_Query

			8	1109
⓪			89	4185
			234	9784
			140	558
			18	903
			50	2298
			15	710
			22	1003
			164	11749
			184	8147
			225	13378
			0	0
			137	5972
			39	784
			63	2034
			20	1884
			8	119
			23	1003
			148	3347
			0	0
			171	10579
			12	8
			10	163
⓪			327	21229
			89	2458
			188	13288
⓪			294	8758
			1	50
			57	805
			48	1397
			0	0
			135	4091
			240	8706
			20	2117
			103	5748
			29	1958
			212	5848

01_Expd_NavFrontBuckle_Query

			189	9104
			133	4222
			237	5558
			17	1219
			196	7460
			123	6860
			118	552
			127	4282
			0	0
			33	969
			73	5838
			14	958
			6	106
			26	2081
			240	11506
●			202	7421
●			285	12788
			162	13881
			17	518
●			319	11829
			2	14
			223	11390
			0	0
			201	-31721
			282	10177
			29	238
			40	443
			0	0
●			241	15247
●			210	4653
●			168	8243
			70	8364
			81	5075
●			240	9458
			29	1162
			127	4918
			160	7721

01_Exped_NavFrontBuckle_Query

			153	8610
●			210	6839
			28	1628
			107	6288
			33	-74632
			132	6628
			104	7048
			238	5130
			35	2192
●			41	1094
			7	220
			167	5450
			8	423
			14	844
●			231	10243
			18	973
			14	854
			21	1277
			6	198
			88	637
			0	0
			10	465
●			118	11972
			13	492
●			252	6704
			161	2305
			0	0
			170	17358
			31	1257
●			234	6328
			14	4472
			184	7327
●			35	3321
			249	13843
			83	89
			15	439
			143	4245

01_Exped_NavFrontBuckle_Query

			89	1
			10	319
			74	983
e			41	4173
			0	0
			29	1485
e			195	9957
			11	260
			178	10337
			109	2856
			95	5188
			134	2108
			235	13439
			184	4803
e			303	11898
			104	6847
e			145	6352
			21	458
			41	1182
			114	3780
			273	23706
			147	4543
			86	2539
			138	10848
			197	8431
e			208	6087
			50	801
			21	802
			73	4191
			41	875
			82	6625
			289	17390
e			288	8088
			30	3812
e			247	14935
			20	438
			252	9302

01_Exped_NavFrontBuckle_Query

			0	0
			2	132
			21	1034
			141	7679
			108	2596
			6	10245
●			250	11789
			220	6963
			66	-26298
			70	2165
●			293	12490
			42	1401
			164	2953
●			307	26384
			89	5734
			11	531
			166	16798
			18	1878
			197	7125
			18	459
			182	11118
			9	803
●			268	8962
			213	7046
			22	1169
			75	2623
●			209	3424
			0	0
			42	918
			45	471
			272	6381
			0	0
			28	710
			43	1904
			0	0
			5	218
			4	90

01_Exped_NavFrontBuckle_Query

			253	18319
			7	0
			90	4568
			29	1251
			117	4753
			157	6392
			10	652
			8	488
			139	128
			153	4106
			113	4650
			285	9160
			288	11308
			143	2
			29	1252
			141	1434
			103	8167
			184	7948
			58	2451
			62	2518
			21	520
			127	441
			22	1
			15	480
			142	5812
			129	5265