

RQ04-011

FORD

APRIL 26, 2005

REQUEST 8

PART 2 OF 6

BOOK 13 OF 43

2581203	CAA	S26	42	3/15/2002	7486014	18728	20.42
7861202	AAA	S40	42	7/26/2001	2866354	9	20.27
7861202	AAA	S26	1	4/17/2002	8197575	11492	20.27

2581203	CCD	840	42	7/16/2001	2852888	2124	15.2	
								1
2581203	CCD	840	1	5/26/2001	1702027	164	15.2	

7881202	AAA	S25	69	8/3/2001	3283208	10	15.65	
7881202	AAA	S26	42	2/28/2002	7745097	9345	20.27	
7881202	AAB	S40	42	#####	5423313	4410	20.27	
7881202	AAA	S40	42	3/12/2001	1844328	4892	13.42	

7881202	AAB	S40	41	#####		5219072	8637	20.27
2561203	CAC	S40	42	#####		5474120	8949	19.05
2561203	BAC	S28	41	2/15/2002		7052388	8174	43.43

2581203	CCD	S40	42	5/7/2001		1803991	5899	15.2
2581203	CCD	S40	41	6/23/2001		2047902	1486	0

2561203	CCD	S25	42	8/29/2001	4255219	3458	15.2
2561203	CCD	S40	42	6/5/2001	1862318	1012	15.2
7861202	AAA	S40	42	10/3/2001	4147358	2312	39.32
2561203	LLJ	S25	42	11/9/2001	5041414	5149	19.67
2561203	CCD	S40	1	8/25/2001	2107413	1460	15.2

2581203	CCD	S25	41	6/25/2001	2277894	2528	15.2	
2581203	CAA	S40	33	5/29/2002	9037205	6625	42.14	

2561203	CCD	S40	33	5/23/2001		1698097	5086	15.2
2561203	CCD	S40	33	6/25/2001		2388566	7887	15.2

2561203	CAA	S26	42	2/26/2002	7100399	2609	18.05
2561203	CAA	S40	42	#####	5715399	5438	19.05
2561203	CCD	S40	42	5/14/2001	1923846	877	15.2
2561203	CAA	S15	42	1/8/2002	6343111	16857	18.05

2561203	CAA	S25	42	#####	5288747	10856	19.05
2561203	BAC	S25	1	#####	5284348	3185	43.43
2561203	BAC	S28	42	5/8/2002	8044735	4811	23.18

2561203	CAA	S40	42	7/17/2001	3819483	22	19.05
7861202	AAA	S40	42	7/17/2001	3819492	31	20.27
7861202	AAA	S25	42	7/17/2001	2469850	1070	20.27
7861202	AAA	S25	1	8/27/2001	3962692	8131	15.85

2561203	CAA	S40	42	7/23/2001	5461090	38	0
7861202*		S25	7	3/21/2002	7566941	9476	0
2561203	CCD	S40	41	2/21/2001	903279	912	15.2

2561203	CAC	S40	42	7/19/2001	3303320	20	39.32
2561203	CAC	S40	42	#####	5883438	1968	19.05
2561203	MMM	S40	69	7/12/2001	2302426	5380	131.4

2561203	CAA	S15	42	#####	8341819	3273	19.05	
7861202	AAA	S40	69	3/11/2001	1078480	2479	15.65	
2561203	CAA	S40	42	1/25/2002	6488750	8887	18.85	

7881202	AAA	S40	1	7/28/2001	3204854	64	0
2561203	CAA	S40	42	7/19/2001	2928434	13	0
7881202	AAA	S40	41	11/9/2001	6086225	3815	20.27

2581203	CAA	S25	42	7/19/2001	4196802	5	39.32
2581203	*	S25	82	7/17/2001	3709028	2985	0
2581203	*	S25	82	8/2/2001	3709028	5472	0
7881202	AAA	S40	33	7/23/2001	2791053	13	15.85
2581203	CAA	S40	41	10/4/2001	4276892	821	19.05
2581203	CAA	S28	69	1/28/2002	6851960	12865	19.05

7881202	AAA	S40	42	2/18/2002	7573735	3398	30.44
2561203	CAA	S40	42	7/28/2001	3313728	10	39.32
2561203	CAA	S28	41	3/30/2002	7761284	3378	39.32
2561203	CAA	S25	42	9/4/2001	5228717	76	45.1
7881202	AAA	S40	42	7/18/2001	2383954	134	39.32

1881202	AAA	S25	42	7/11/2001	1	3801734	4382	109.56
5481202	*	S40	42	37115	10	5088080	25513	0
5481202	*	S40	42	37144	12	5085470	20161	0
5461202	AAC	S40	42	37146	7	6030612	11218	0
5461202	*	S40	42	37115	10	5088080	25513	0
5461202	*	S40	42	37144	12	5085470	20161	0

7881202	AAA	S25	42	4/2/2001		1428810	14922	15.65
2581203	CAC	S40	42	#####		8874185	13785	18.33
2581203	MMM	S25	42	5/14/2001		1616157	15487	,19.05

7861202	AAA	S40	41	6/11/2001	1869766	11571	15.65
2561203	CAA	S26	42	2/25/2002	7188589	20237	19.05
2561203	MMM	S26	42	7/10/2001	2293587	6302	18.05
2561203	CCD	S40	42	6/24/2001	4214210	1400	15.2

2561203	CCD	S25	42	4/19/2001	2012273	1216	15.2
7881202	AAA	S40	42	6/29/2001	2310824	1168	20.27
2561203	CAA	S40	42	1/23/2002	8488330	5315	19.05

2561203	CCD	S40	42	8/14/2001	4274972	4267	15.2
2561203	CCD	S40	81	4/27/2001	1428847	12	15.2
2561203	CCD	S25	42	7/26/2001	4987078	602	16.2
2561203	*	S40	33	2/13/2001	932753	5323	.0

7881202	*	S25	42	9/13/2001	3707317	6042	2.8	
2581203	CCD	S40	69	6/11/2001	1921123	3001	15.2	

2001 Expe	2001 Expe	2001 Expe	2001 Expe	2001 Expe	2001 Expe	2001 Expe	Rating	
								...BUCKLES ARE NOT HOLDING AT TIMES... ...INSPECTED WITH TOOL BOTH FRONTS FAILED. R REPLACED. OK
84.88	0.8	5513	*	NA	CA	11001	d	
45.85	0.4	978	*	NA	NC	12001	a	
46.48	0.4	4617	*	NA	TX	12001	e	
								3391 DRIVERS SEAT BELT DOES NOT LATCH AT TIMES. R R DRIVERS SEAT TO GAIN ACCESS TO SEAT BELT ANCHOR. REMOVE AND REPLACE SEAT BELT BUCKLE ASSY. CONFIRM PROPER LATCH AFTER REPLACEMENT. OK
71.05	0.7	6042	*	NA	TX	11001	a	

								17088 DR LF SEAT BELT INOP W CC42 INSP AND RR DR SEAT TO ACCSSE SEAT BELT BUCKLE ASSY REPLACE D LF DR SEAT BELT BUCKLE ASSY RETEST OK
51.61	0.4	3073 *	NA	FL	11001	c		
								11849 SOP PART 0.8MT REMOVE D AND REPLACE D FEMALE SEAT BELT BUCKLE AFTER DUPLICA TING CONCER N RETESTE D QUALITY OK
70.57	0.6	889 *	NA	CA	11001	d		

							NA REPLACE D DRIVERS SIDE SEATBEL T BUCKLE MILEAGE IS CORREC T ENTERE D INCORRE CTLY AT SPALDIN G FORD ON 071901
61.85	0.4	284 *	NA	GA	11001	b	
							DEFECTI VE REPLACE D DEFECTI VE DRIVERS SEAT BELT BUCKLE MILEAGE ERROR ON PRIOR TICKET CAR HAS 8707
85.38	0.6	1028 *	NA	SC	11001	e	
125.42	1	8737 *	NA	WA	11000	e	REPLACE D FRONT SEAT BELT BELT LATCHES

								REPLACE D DRIVERS SEATBEL T RECEPTA CLE.
83.08	0.8	8888 *	NA	MI	11001	a		
								WPG40.5 28.CUST OMER SAYS SEAT BELTS COME UNLATCH ED WHILE DRIVING. POSSIBL E PART #1C3Z 2581203 CA
78.87	0.8	11609 *	NA	FL	12001	d		
206.45	1.4	1759 *	NA	AZ	11001	e		RECALL #01821 SOP HERE
								CUSTOM ER STATES CHECK DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING. CHECK AND ADVISE
48.48	0.4	1412 *	NA	CA	11001	d		
75.99	0.3	6249 *	NA	WI	11001	e		
								SEAT BELT LATCH NOT WORKIN G
65.82	0.4	4845 *	NA	FL	11001	e		

74.83	0.3	2960 *	NA	NY	11001	e	INSTALL INSTALL SOP SEATBEL T
72.31	0.3	2732 *	NA	MI	11001	b	C C PASSEN GER FRONT SEAT BELT WILL NOT STAY LATCHED
115.47	1.1	8541 *	NA	ID	11001	a	SEAT BELT BUCKLE HARD TO SNAP IN
27.34	0.2	4492 *	NA	TX	12001	a	RT SEAT BELT WONT BUCKLE
89.56	0.6	1661 *	NA	OR	12001	e	REPLACE SEAT BELT
89.35	0.7	8155 *	NA	IL	11001	a	SEAT BELT BUCKLES
102.68	0.7	4280 *	NA	CT	11001	a	REPLACE DRIVERS BUCKLE AND MIDDLE SEAT BUCKLE PARTS ARE HERE
146.34	0.8	10431 *	NA	PA	11001	e	REPLACE 2 SEATBEL T BUCKLES IN AN F250

64.04	0.2	6778 *	NA	NC	12001	a	SEAT BELT WONT ENGAGE PROPERLY PASS SIDE
50.04	0.7	4184 *	NA	MT	11001	b	BUCKLE COMES UNDONE
125.13	1.4	3585 *	NA	OH	11001	b	CRK SEAT BELT WONT HOLD
147.95	1	1827 *	NA	MA	12001	e	TECH 23 INSTALL PASSENGER SEAT BELT AND COVER
47.47	0.4	2163 *	NA	OH	12001	c	CUSTOMER STATES THAT THE FRONT SEATBELT ON THE PASSENGER SIDE POPS OUT OF THE BUCKLE S40
164.26	0.4	4219 *	NA	NJ	11001	e	INSTALL ORDERED SEAT BELTS

							REPLACE THE RIGHT SIDE SEAT BELT ASSEMBLY AS PER PREVIOUS DIAGNOSIS.
112.43	1.1	2188 *	NA	OH	11001	e	
46.4	0.6	3544 *	NA	IA	12001	s	PASSENGER SIDE SEAT BELT WONT LATCH.
73.7	0.3	7882 *	NA	NV	11001	e	INSTALL SOP RT SEAT BELT RECEPTACLE
67.60	0.5	144 *	NA	MD	11001	e	RECHECK SEAT BELTS
78.56	0.4	225 *	NA	AL	12001	b	S25 PASS SEAT BELT VIBRATE S LOOSE (2ND TRIP) 1ST TIME WRONG PART WONT STAY LOCKED.

								AFTER INTERIOR OF CAB IS HOT DRIVERS SEATBELT DOES NOT ALWAYS BUCKLE WILL POP OUT WHILE DRIVING
80.58	0.3	3182 *	NA	CO	11001	d		
94.91	1.1	20400 *	NA	AZ	11001	b		LF SEAT BELT COMES UNBUCKLED PART ON ORDER STEVE KRELL R 81 BUCKLE FROM STOCK UNIT 12223 TAG 3045
115.48	0.8	3821 *	NA	CA	12001	e		BOTH SEAT BELT BUCKLES ARE BAD SEAT BELTS IN VEHICLE STICK AND HARD TO REMOVE
83.51	0.5	4107 *	NA	ND	11001	e		

72.82	1	996*	NA	NC	11001	e	CS DRIVERS SEATBEL T BUCKLE MISSING
102.12	1	785*	NA	CA	12001	e	CUST STATES VEH SEAT BELT INOP
55.73	0.5	7841*	NA	CA	11001	e	INSTALL SPO SEAT BELT USE SPO 01254006
26.72	0.2	6856*	NA	OK	11001	e	DRIVERS SEAT BELT BUCKLE INSTALL, SOP HERE
69.21	0.3	1930*	NA	WV	11001	d	CUSTOM ER STATES P SIDE SEATBEL T COMES UNLATCH ED WHILE DRIVING PARTS IN
53.57	0.6	978*	NA	NC	11001	e	DRIVERS SEATBEL T BUCKEL INOP
51.87	0.7	3544*	NA	IA	11001	c	SEAT BELT ON DRIVERS SIDE KEEPS COMING UNLATCH ED.

								CUSTOM ER STATES PASS SIDE SEAT BELT COMES UNDONE BY ITSELF
46.93	0.5	5503 *	NA	CA	12001	b		
84.01	0.4	8364 *	NA	MN	11001	a		DRS FRONT SEAT BELT WONT LATCH
35.99	0.4	8217 *	NA	WI	11001	a		CHECK AND REPAIR DRIVERS SEATBEL T DOES NOT LATCH
58	0.6	1678 *	NA	OH	11001	e		INSTALL SOP SEATBEL T BUCKLES
53.98	0.5	3567 *	NA	TX	12001	b		CHECK FOR SEATBEL T ON DRIVERS SIDE WON T LOCK WHEN IT DOES IT WILL UNLOCK ITSELF
84.56	0.5	4398 *	NA	WY	11001	e		REPLACE DRIVERS SIDE SEAT BELT

87.13	0.5	8088 *	NA	VT	11001	a	PERFORM RECALL 01S21
89.16	0.3	485 *	NA	GA	12001	a	
39.44	0.5	10431 *	NA	PA	11001	b	THE DRIVERS SEATBELT DOES NOT LATCH AND UNLATCH PROPERLY
85.9	0.5	5099 *	NA	MO	12001	b	PASSENGER SEAT BELT WILL NOT STAY LATCHED
33.47	0.3	3797 *	NA	KY	11001	b	DRIVERS SEAT BELT WONT STAY LATCHED
70.45	0.7	48337 *	NA	CA	11001	a	REPL SEAT BELT BUCKLE
78.82	0.7	10810 *	NA	TX	11001	a	REPLACE D RIGHT FRONT SEATBELT.

								LEFT FRONT SEAT BELT BUCKLE FAULTY REPLACE LEFT FRONT BUCKLE
45.98	0.2	10867	*	NA	*	11001	8	REPLACE D SEAT BELT PASS SIDE MISSING
75.18	0.7	10864	*	NA	GA	11001		PERFORMED THE RECALL AS OUTLINED
19.2	0.3	45847	*	NA	MS	11001		INSPECTED AND ORDERED SEATBELT BUCKLE AS PER RECALL #01 § 21
27.09	0.5	12046	*	NA	AL	11001		REPLACE D RIGHT FRONT SEAT BELT BUCKLE
79.76	0.7	11404	*	NA	TX	11001	9	

								9733 07 WARRL ROAD TEST, NESS TO UNTWIST BUCKEL INSERT ON BELT. RETEST BELT RETRACT OR AND LOCK, OK.
12.88	0.2	12039	*	NA	LA	11001		
								PERFOR MED DIAG PULLED CODE P1280 REPROG RAM HYELEC INSTRUM ENT CLUSTER WITH 2 KEYS
174.54	3	13005	*	NA	WA	11001		
								DRIVERS SIDE SEAT BELT BUCKLE REPLACE SEAT BELT BUCKLE
92.32	0.7	10581	*	NA	NY	11001	e	
								DEFECTI VE PARTS SEATBEL T ASSEMBL Y FRONT REPLACE
175.95	1.3	13316	*	NA	NY	11001	e	REPLACE
88.10	0.7	45235	*	NA	GA	11001	e	D THE BUCKLE

205.98	0.3	12813	*	NA	KS	11001	e	INSPECT AND REPL SEATBELT
64.21	0.8	2282	*	NA	CA	11001		SEAT BELT LOOSE AT BEGINNING OF BELT
147.8	1	10712	*	NA	MI	11001		22858 01921 RECALL W. INSPECTED AND REPLACED BOTH FRONT SEAT BELT BUCKLES WITH NEW. RETESTED ALL OK AT THIS TIME. 2286
10	0.3	45281	*	NA	TX	11001		PERFORMED THE RECALL AS OUTLINED

							WIRING HARNES & LOOSE AND SEAT BELT BUCKLE HAD HIGH RESISTA NC REPLACE D SEAT BELT BUCKLE AND REPAIRE D HARNES & 15850E .1 15850E1 .2 15850E1X 1.1 15850E2 .3 14200A .4
319.12	.4	10009	*	NA	VA	11001	
147.1	1.8	1131	*	NA	NC	11001	REPLACE PERFOR MED
98.38	0.5	10577	*	NA	IL	11001	1 INSTALLE D SEATBEL T RECEPTI CLES
148.07	2.2	11828	*	NA	FL	11001	BINDS SEATEBEL T ASSEMBL Y FRONT REPLACE

							PERFORM THE RECALL AS OUTLINED
18.78	1.9	46238	*	NA	SC	11001	
							INSPECT AND REPLACE RIGHT FRONT BUCKLE
170.88	2.2	1650	*	NA	MI	11001	
							PERFORM THE RECALL AS OUTLINED
19.32	0.3	45184	*	NA	GA	11001	
							PERFORM DIAG FOR INTERMITTANT AIR BAG LIGHT CODE B2438 PINPOINT TESTS CONCLUDE BUCKLE DEFECTIVE REPLACE AND RECHECK OK
288.76	3.7	13119	*	NA	CT	11001	
143.2	2.2	46578	*	NA	TX	11001	

							R&R DRIVERS SEAT TO DISCONE CT WIRE CONNEC TOR FOR SEAT WARNIN G IN BUCKLE R&R BUCKLE
84.58	0.5	10313	*	NA	SC	11001	
							1 DIA NOI SE ELECTRI CAL SYSTEM REPLACE LEFT FRONT SEAT BELT ASSEMBL Y
88.7	0.7	10290	*	NA	*	11001	
							PERFOR MED THE RECALL AS OUTLINE D
18.8	0.3	45893	*	NA	TN	11001	
							PERFOR MED THE RECALL AS OUTLINE D
183.2	2.1	45414	*	NA	SC	11001	
							PERFOR MED THE RECALL AS OUTLINE D
21.8	0.3	45282	*	NA	TX	11001	

							42 TESTED BOTH FT SEAT BELT BUCKLES AS PER RECALL BOTH FAILED TEST REPLACE D BOTH FT SEAT BELT BUCKLES AS PER RECALL
180.92	2.1	10855	*	NA	TX	11001	
							PERFOR MED THE RECALL AS OUTLINE D
16.8	0.3	45899	*	NA	TN	11001	
							VERIFIED CONCER N, DIAG AIR BAG SYSTEM, PINPOINT TEST. R&R LF SEAT & REPLACE D SEAT BELT BUCKLE. NES ON DEMAND TEST, CLEAR CODES.
153.95	1.8	10083	*	NA	TX	11001	

119.2	0.3	45414	*	NA	SC	11001	PERFORMED THE RECALL AS OUTLINED
193.2	2.1	12712	*	NA	CA	11001	REPLACE SEAT BELT BUCKLES
19.56	0.3	45291	*	NA	GA	11001	PERFORMED THE RECALL AS OUTLINED
199.92	2.1	45255	*	NA	FL	11001	SAFETY RECALL COMPLETE
100.46	1	10083	*	NA	TX	11001	REPLACE RIGHT FRONT SEAT BELT FOR SOLD UNIT STOCK NO. 12827 SEAT BELT DISCOLORED OR BINDING
21.6	0.3	45282	*	NA	TX	11001	PERFORMED THE RECALL AS OUTLINED

								PERFORM THE RECALL AS OUTLINED
19.2	0.3	45847	*	NA	MS	11001		
19.52	0.3	45281	*	NA	LA	11001		PERFORM THE RECALL AS OUTLINED
62.4	0.7	45240	*	NA	AL	11001	b	REPLACE DRIVERS SEAT BELT BUCKLE ASSY
67.43	0.7	1646	*	NA	TN	11001	c	REPLACE SEAT BELT ON OR SIDE
74.33	0.7	2283	*	NA	OH	11001	b	REPLACE SEAT BELT AND PASS FRONT SIDE.
61.66	0.5	1738	*	NA	IL	11001	b	DIAG AND REPLACE SEAT BELT LATCH ASSY
61.66	0.7	10008	*	NA	VA	11001	b	END WONT HOLD REPLACE WITH NEW OP#61172 A

								WONT LATCH SEATBEL T ASSEMBL Y FRONT REPLACE
94.32	0.7	10432	*	NA	NJ	11001	b	INSTALL D NEW SEAT BELT BUCKEL QC#3164 4
87.82	0.7	10473	*	NA	CA	11001	c	REPLACE D RIGHT FRONT SEATBEL T.
78.82	0.7	10810	*	NA	TX	11001	a	1 REPLACE DRIVERS SEAT BELT
86.22	0.7	9331	*	NA	MN	11001	b	REPLACE D DRIVERS FRONT SEAT BELT BUCKLE ASSEMBL Y.
78.85	0.7	1358	*	NA	PA	11001	c	

								LATCH INOP VERIFY CONCER N SEAT BELT DOES NOT LATCH AT TIMES REPLACE D DRIVERS
58.00	0.4	7714	*	NA	CA	11001	a	
82.74	0.9	8305	*	NA	WI	11001	a	20798 0.8 DIAGNOI SE,HAD TO REMOVE L F SEAT TO TAKE SEAT BELT OUT,STU D WAS CROSS THREDE D,RE TAP STUD AND INSTALL NEW BUCKEL TURN IN OLD SEAT BELT BUCKEL FOR WF.

80.88	0.7	13017	*	NA	WA	11001	a	REPLACE D SEAT BELT BUCKLE.
53.14	0.3	2584	*	NA	TX	11001	a	REPLACE D PASSAN GERS FRONT SEAT BELT BUCKLE.
75.28	0.7	8235	*	NA	IL	11001	b	SEAT BELT DOES NOT STAY BUCKLED R&R BUCKLE RECHEC K GOOD
88.8	0.6	45250	*	NA	FL	11001	b	R&R DRIVERS SEAT BELT LATCH

								SEAT BELTS RELEASE INTERMITTENTLY, SEAT BELT LOOSE REPLACE BOTH FRONT SEAT BELTS 840 5461202 42
158.88	1.3	1304	*	NA	PA	11001	c	
								CHECKED FOUND BUCKLE ON ONE BELT HARD TO LOCK AND THE OTHER THE TENSION IS NOT HOLDING REPLACE D BOTH
219.3	3.3	48149	*	NA	IN	11001	a	
150.44	1.3	4892	*	NA	FL	11001	c	REPLACE SEATBELTS BINDING
82.87	0.6	8199	*	NA	MO	11001	a	REPLACE SEAT BELT BUCKLE

								LATCH INOP SEATBELT ASSEMBLY FRONT REPLACE
79.69	0.7	2519	*	NA	TX	11001	D	
								30143 DRIVERS BELT BUCKLE INOP PERFOR MED TEST ON BUCKLE, BUCKLE NOT WORKIN G, DISCONN ECTED WIRING, R&R BUCKLE, CODE 42, PART# 2561203, BUCKLE NOW WORKIN G
80.79	1	310	*	NA	GA		A	

							D SEAT BELT LATCH BUCKLE FROM BORROWED EXCURSION AND TEMPORARLY INSTALLED TO THIS R.O. DEFECTIVE LATCH BUCKLE IS ON MY TOOLBOX WHILE WAITING FOR ORDERED BUCKLE. REMOVE D BORROWED SAFETY BUCKL
63.92	0.5	7737 *	NA	CA		A	
46.34	0.5	3127 *	NA	CO		A	REMOVE D AND REPLACE D DRIVERS SIDE REM OVED AND REPLACE D DRIVERS SIDE SEAT BELT BUCKLE.

83.22	0.8	1571 *	NA	L		A	REPL BUCKLE ASSY WPI
78.01	0.8	5512 *	NA	CA		A	REPLACE D RIGHT SEAT BELT BUCKLE.
58.98	0.7	5880 *	NA	AL		A	TEST ALL SEAT BELTS PASSEN GER SIDE FAILED R AND R SEAT TO INSTALL NEW SEAT BELT BUCKLE ASY DUE TO BEING BROKEN

								VERIFIED THAT THE DRIVERS SEATBELT BUCKLE NOT LATCHING ALL OF THE TIME, FOUND IT NECESSARY TO REMOVE D DRIVERS SEAT FOR ACCESS AND REPLACE D BUCKLE, RETEST OK. HAD TO ORDER ONE SEAT BOLT
68.34	0.7	20913 *	NA	AZ			A	
41.69	0.4	4437 *	NA	TX			A	BROKEN SEATBELT ASSEMBLY FRONT REPLACE

							FAILED BUCKLE TEST REMOVE D RT FRT SEAT TO GAIN ACCESS & REPLACE D SEAT BELT PASSEN GER
<u>37.2</u>	<u>0.4</u>	<u>6053 *</u>	<u>NA</u>	<u>AR</u>		<u>A</u>	
<u>83.27</u>	<u>0.9</u>	<u>20328 *</u>	<u>NA</u>	<u>AZ</u>		<u>A</u>	R AND I PASS SEAT AND REPLACE BUCKLE
<u>45.58</u>	<u>0.5</u>	<u>1259 *</u>	<u>NA</u>	<u>PA</u>		<u>A</u>	REPLACE D FAULTY PASSEN GER BUCKLE
<u>35.5</u>	<u>0.4</u>	<u>45237 *</u>	<u>NA</u>	<u>MA</u>		<u>A</u>	REPLACE RS SEAT BELT BUCKLE

							1 VERIFIED COMPLAIN T. REPLACE D BUCKLE WITH NEW ONE. RETEST OK. WORKIN G PROPERL Y.
48.71	0.4	3314 *	NA	UT		A	
							1 REPLACE D DRIVERS SIDE SEAT BELT AND PULLED CENTER SEAT BELT OUT OF COVER AND REPAIRE D
58.85	0.5	8619 *	NA	AK		A	
							REMOVE BOTH FRONT SEATS AND REPLACE D BOTH SEAT BELT BUCKLES RETEST OK
109.14	0.8	5408 *	NA	CA		A	

							VERIFIED CONCERN AND INSPECT ED THE SEAT BELT ASSEMBL Y FOUND THE DRIVERS SEAT BUCKLE TO BE INOP NOT ALLOWIN G THE BELT TO LATCH REPLACE THE DRIVERS SEAT BELT BUCKLE ASSEMBL Y ON CAPTIAN S CHAIR AND RETE
40.51	DA	4572*	NA	TX		B	
0	0	5432*	NA	CA		B	SEAT BELT DEFECTI VE REPLACE SEAT BELT BUCKLE ASSY

36.34	0.3	8463 *	NA	WI		B	REPLACE LT SEAT BELT BUCKLE
42.26	0.4	829 *	NA	GA		B	REPL SEAT BELT
53.05	0.3	6000 *	NA	FL		B	BUCKLES DEFECTI VE NECESSA RY TO REPLACE
48.26	0.4	5458 *	NA	CA		B	DRIVERS SEATBEL T WILL UNLATCH AT TIMES BY ITSELF. REPLACE SEAT BELT, RETEST, OK
27.19	0.2	4492 *	NA	TX		C	BROKEN LATCH REPLACE L F SEAT BELT LATCH

43.84	0.4	42°	NA	MD				SOMEONE ORDERED LF SEAT BELT BUCKLE 7173 INSTALLED NEW BUCKLE SEAT BELT IS WORKING PROPERLY AT THIS TIME NOTE HAD TO REMOVE CHILD SEAT BEHIND DRIVER SEAT TO GET UNDER SEAT DID NOT REINSTATE
73.34	0.4	1527°	NA	EL				REPLACE BOTH FRONT SEATBELT LATCHES FOR CUSTOMER SAFETY CONCERN

38.15	0.3	1545*	NA	IL			C	CHECK DRIVERS SEAT BELT DIAGNOSIS AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE COMES LOOSE
88.47	0.9	3176*	NA	WY			D	INSPECTED AND FOUND LOOSE DRIVERS SIDE SEAT BELT BUCKLE. REPLACED BUCKLE. IN TIME USED AS NO OPS AVAILABLE FOR BUCKLE. OK PER PA.

54.31	0.7	402 *	NA	GA		D	SEAT BELT TONGUE WILL NOT HOLD REPLACE SEAT BELT TONGUE ON DRIVERS SEAT
55.35	0.4	689 *	NA	CA		D	REPLACE D DRIVERS SIDE SEAT BELT BUCKLE
44.97	0.4	5583 *	NA	CA		D	E VERIFIED COMPALI NT REPLACD DRIVERS SEIDE SEAT BELT BUCKLE
138.85	0.9	4814 *	NA	FL		D	NOT LOCKING PROPERLY REPLACE OR SIDE SEAT BELT BUCKLE

							10856 2561203 CC 42 VERIFY CONCER N.REPLA CED DRIVERS SEAT BELT BUCKLE. VERIFY REPAIR TECH 4441
45.66	0.4	2413 *	NA	TX		D	
85.54	0.8	6947 *	NA	TX		D	REPLACE D BOTH FRONT BUCKLES
47.7	0.4	4864 *	NA	FL		D	FOUND SEATBEL T WILL NOT ALWAYS LATCH CORREC TLY. REPLACE LEFT FRONT SEATBEL T

								DIAG INSP M TIME TO REPLACE SEAT BELT BUCKLES
73.2A	0.7	7704*	NA	CA			X	
74.4B	0.7	7704*	NA	CA			X	DIAG INSP M TIME TO REPLACE SEAT BELT BUCKLE
72.8B	0.8	2519*	NA	TX			X	RECALL RECALL
44.1B	0.4	149*	NA	MD			X	WOULD NOT RETRACT SEATBELT ASSEMBLY FRONT REPLACE

0	0	3140 *	NA	CO			X	MT TIME TO REPLACE LEFT FRONT SEAT BELT BUCKLE
13.83	0.2	2490 *	NA	TX			X	9476 OUT OF ALIGNMENT WARRANT REALIGN SLEEVE FOR 2ND ROW, MIDDLE SEAT BELT.
40.21	0.4	6902 *	NA	TX			X	

							20 RECALL 01B21 INSPECT ED BOTH FRONT SEAT BELT BUCKLES . BOTH FAILED. REMOVE D AND INSTALLE D BOTH FRONT SEAT BELT BUCKLES . POWER BUCKETS . NO SIR
<u>75.06</u>	0.6	20313 *	NA	AZ		X	
<u>83.58</u>	0.2	3170 *	NA	CO		X	1 REPLACE D DR SEAT BELT LATCH.
<u>88.09</u>	0.4	3888 *	NA	CT		X	LOCK SIEZED R&R SEAT BELT LOCK RETEST OK

							DIAGNOSE FOUND THAT THE SWITCH IN BUCKLE IS NOT WORKING. DOESNT OPEN CIRCUIT WHEN BELT IS INSERTED. REPLACED BUCKLE. NO LABOR OP USED IN TIME
44.7	0.4	4078 *	NA	ND		X	
66.25	0.9	3768 *	NA	NY		X	VERIFIED CONCERN, FOUND RIGHT FRONT SEAT BELT BINDING R&R BUCKLE ASSEMBLY NOW OPS NORMALLY
43.33	0.4	6358 *	NA	WI		X	7100 REPLACE DL SEAT BELT BUCKLE

0	0	978*	NA	NC		X	BUCKLE INSTALL BOTH SEATBELT BUCKLE
0	0	1587*	NA	IL		X	3 SEATBELT WAS CHECKED AND FAILED THEN WAS REPLACED AND RETESTED AND PASSED THE MILEAGE SHOULD BE 13
49.3	0.4	1884*	NA	CA		X	RIGHT FRONT SEAT BUCKLE INOP REPLACE BELT BUCKLE ASSEMBLY. BINDING INOP

							5 RECALL 01821 REPLACE D L AND R SEAT BELT BUCKLES PER RECALL POWER BUCKET SEATS.
80.51	0.8	801 *	NA	NY		X	
83.99	0	2519 *	NA	TX		X	RENTAL RENTAL
83.99	0	2519 *	NA	TX		X	RENTAL RENTAL
85.39	0.7	8278 *	NA	MO		X	NEC TO REPLACE SEAT BELT
48.76	0.4	3182 *	NA	CO		X	
48.43	0.4	9441 *	NA	MN		X	12883 REMOVE DRIVER SEAT AND REPLACE BELT.

							RR B PILLAR TRIM. RR SEAT BELT INSTALL SLIDDER TRIM. ALSO REPL BELT BUCKLE INOP
98.89	0.9	3845 *	NA	IL		X	
99.44	0.8	998 *	NA	NC		X	REPLACE D SEAT BELT PER ED KARAZIN
101.41	0.8	3783 *	NA	NY		X	61203 41 REPLACE FRONT SEATBEL T BUCKLES
103.79	0.8	7941 *	NA	CA		X	01S21 01S21
107.11	0.8	1131 *	NA	NC		X	REPLACE SEATBEL T ASSEMBL Y FRONT REPLACE

								RT AND LT SEATBEL T BUCKLES WILL NOT STAY LATCH ONTO BELT
160.62	0.8	61	*	NA	VA	11001	b	
20	0.3	45277	*	NA	TN	11001		PERFOR MED THE RECALL AS OUTLINE D
19.32	0.3	45164	*	NA	GA	11001		PERFOR MED THE RECALL AS OUTLINE D
11.04	0.2	62630	*	NA	MI	11001		LUBED HOOD AND DOOR HINGES
20	0.3	45277	*	NA	TN	11001		PERFOR MED THE RECALL AS OUTLINE D
19.32	0.3	45164	*	NA	GA	11001		PERFOR MED THE RECALL AS OUTLINE D

43.85	0.4	5574 *	NA	CA		A	REPLACE R FRONT SEAT BELT BUCKLE ASSY FOR WILL NOTLATC H CONCER N	
42.08	0.5	45236 *	NA	MD		A	REPLACE D SEAT BELT BUCKLE	
44.83	0.4	460 *	NA	GA		A	BROKEN SEATBEL T ASSEMBL Y FRONT REPLACE	

							REPLACE D RIGHT FRONT SEAT BELT BUCKLE. BINDING 41.
29.74	0.2	5842 *	NA	TN		A	
64.05	1	3110 *	NA	CO		B	REPLACE SEAT BELT ASSY
43.59	0.4	20910 *	NA	AZ		B	REMOVE D SEAT R&R SEAT BELT ASSY. RECHEC KED OK
31.53	0.4	5861 *	NA	TN		C	REPLACE D RIGHT SEATBELT BUCKLE

<u>67.47</u>	0.7	4219 *	NA	NJ			C	REPLACE D SEAT BELT ASSY
								TEST AND FOUND PASS SEAT BELT BUCKLE INOP. DISENGA GES, WON'T LATCH PROPERL Y. REMOVE AND REPLACE PASS SEAT BELT BUCKLE OK. RETEST OK.
<u>69.4</u>	0.6	20443 *	NA	AZ			C	
<u>42.75</u>	0.4	6481 *	NA	LA			C	DOENST OPERAT E PROP SEATBEL T ASSEMBL Y FRONT REPLACE

46.1	0.4	2722*	NA	MO		D	REPLACE D SEAT BELT AND BUCKLE
32.78	0.4	5744*	NA	TN		X	REPLACE D BELT & BUCKLE
41.75	0.4	7788*	NA	GA		X	1 REPLACE D LEFT FRONT SEAT BELT BUCKLE
12.68	0.2	3144*	NA	CO		X	TIGHTEN ED ALL BELT BOLTS 1

								INSPECT BELTS, BELT RETRACTED INTO SEAT BELT COVER, R R SEAT BELT ASSEMBLY, DRILL OUT RIVETS THAT HOLD COVER TO BELT
28.4	1.2	1770*	NA	NJ			X	
51.32	0.4	3889*	NA	NY			X	OPENS REPLACE R SEAT BELT

	S26 CUST	407	USA	124227	EB4	USA	Q21	V05
	CUSTOME	780	USA	171078	2	USA	Q21	V05

	SEAT BEL	770	USA	121488	2	USA	Q21	V05
	REPLACE	843	USA	121281	1	USA	Q21	V03
	FRONT SE	509	USA	183000	2	USA	Q21	V05

	PASSENG	231	USA	148644	E84	USA	Q21	V05
	1324 42 WPG40 ROA	407	USA	124226	2	USA	Q21	V05
	PERFORMED RECAL	820	USA	127042	E84	USA	Q21	V05
	INSPECTED AND RE	209	USA	172918	2	USA	Q21	V05
	ORDERED PART. RE	920	USA	141353	1	USA	Q21	V05
	REPLACE SEAT BEL	813	USA	124547	2	USA	Q21	V05

15933	INSTALL SOP	716	USA	144117	1	USA	Q21	V05
		517	USA	148018	2	USA	Q21	V05
	REPLACED PASS SIB	208	USA	174447	2	USA	Q21	V05
	SEAT BELT WONT LE	830	USA	162148	1	USA	Q21	V05
		541	USA	174487	1	USA	Q21	V05
	REPLACE BOTH SEA	618	USA	127636	2	USA	Q21	V05
42		860	USA	113540	2	USA	Q21	V05
	REPLACED BOTH SE	717	USA	116459	1	USA	Q21	V05

SEAT BELT WILL NO	252	USA	121644	1	USA	Q21	V05
REPLACE BUCKLE	406	USA	174634	1	USA	Q21	V05
REPLACE PASS SIDE	740	USA	147045	1	USA	Q21	V05
REPLACED BELT AN	508	USA	111063	2	USA	Q21	V05
GAUS 7861202 CCC	330	USA	144059	2	USA	Q21	V05
8102 SEAT BUCKLE	609	USA	113524	E84	USA	Q21	V05

REPLACE THE RIGHT	330	USA	144099	E54	USA	Q21	V05
PASS FRONT SEAT B	712	USA	158687	2	USA	Q21	V05
10055 REPLACED PA	702	USA	172404	2	USA	Q21	V05
SEAT BELT ASSEMB	410	USA	127037	2	USA	Q21	V05
9012 R R R FRT SEAT	205	USA	121015	2	USA	Q21	V05

REPLACE LF SEAT B	970	USA	153875	2	USA	Q21	V05
REMOVED DRV. SEA	602	USA	171172	1	USA	Q21	V05
1 REPLACED LFT AN	408	USA	172038	2	USA	Q21	V05
REPLACED BELTS A	701	USA	118088	2	USA	Q21	V05

REMOVE DRIVERS S	252	USA	124008	2	USA	Q21	V05
CHECK AND REPLAC	760	USA	171428	E84	USA	Q21	V05
INSTALLED LT SEAT	209	USA	172300	E84	USA	Q21	V05
INSTALLED DRIVERS	918	USA	152400	E84	USA	Q21	V05
3184 PASSOK.	304	USA	147545	2	USA	Q21	V05
BUCKLE BROKEN	919	USA	121019	1	USA	Q21	V05
CK SEAT BELT, DOES	712	USA	158557	2	USA	Q21	V05

R AND R PASS SIDE	601	USA	171446	2	USA	Q21	V05
REPLACE DRIVER SEAT	763	USA	158843	2	USA	Q21	V05
REMOVE AND REPL	606	USA	141153	1	USA	Q21	V05
REMOVE LEFT FRONT	440	USA	144043	2	USA	Q21	V05
SEAT BELT BUCKLE	972	USA	152520	2	USA	Q21	V05
REPLACED DRIVERS SIDE SEAT		USA	158408	604	USA	Q21	V05

COMPLETE AND INS	802	USA	111535	1	USA	Q21	V05
REPLACE SEATBELT	706	USA	121446	2	USA	Q21	V05
REPLACED SEAT BE	717	USA	116458	1	USA	Q21	V05
REPLACED PASSENGER	818	USA	153404	1	USA	Q21	V05
571 LATHED WONT F	606	USA	147497	1	USA	Q21	V05
		* USA	364749	2	USA	Q21	V05
RIGHT FRONT SEATBELT NOT LOCKING	958	USA	367080	2	USA	Q21	V05

DRIVER'S SEAT BELT WILL NOT LOCK		601 *		322821	1	USA	Q21 V05
		706	USA	326046	2	USA	Q21 V05
SEAT POSITION		*	USA	345741	E84	USA	Q21 V05
		205	USA	326378	1	USA	Q21 V05
		817	USA	367355	1	USA	Q21 V05

			504 USA	322800	1	USA	Q21	V05
			509 USA	357413	2	USA	Q21	V42
			914 USA	314555	E84	USA	Q21	V05
	NEW HELLER BOP		631 USA	314067	2	USA	Q21	V06
			* USA	345741	2	USA	Q21	V05

	PROPERTY NUMBER	913	USA	363425	2	USA	Q21	V05
		682	USA	354170	2	USA	Q21	V05
		313	USA	345070	E84	USA	Q21	V05
	PROPERTY NUMBER	*	USA	387745	E84	USA	Q21	V05

			703	USA	328085	2	USA	Q21	V05
			338	USA	354708	EB4	USA	Q21	V05
			217	USA	342808	2	USA	Q21	V05
			904	USA	312341	2	USA	Q21	V05

	REGAL OVER ELC		* USA	367749	2	USA	Q21	V05
			989 USA	342767	EB4	USA	Q21	V05
	REGAL OVER ELC		* USA	345741	2	USA	Q21	V05
			860 USA	312230	EB4	USA	Q21	V05
			* USA	315727	EB4	USA	Q21	V05

			* USA	325182	1	USA	Q21	V05
			**	314314	2	USA	Q21	V05
			* USA	345741	E84	USA	Q21	V05
			* USA	367748	2	USA	Q21	V05
			* USA	367748	E84	USA	Q21	V05