

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 5 OF 6
BOOKS 21 OF 43

W indstar Repests_LBR_HPS	W indstar Repests_DLR_CD	W indstar Repests_DLR_SUB_CD	W indstar Repests_REGION_CD	W indstar Repests_ST_PROV_CD	W indstar Repests_DPSC_CD_#
0 0 000	.	.	NA	VA	11001
0 4 3023	.	.	NA	NJ	11001
0 0 0770	.	.	NA	KY	11001
0 0 7007	.	.	NA	OH	11001
0 4 00304	.	.	NA	NE	11001
1 5 4005	.	.	NA	CA	11001
0 4 7013	.	.	NA	CA	11001
0 4 4402	.	.	NA	TX	11001
0 5 1107	.	.	NA	FL	11001
1 5 0010	.	.	NA	CA	11001
0 3 0043	.	.	NA	LA	11001
0 4 0000	.	.	NA	AL	11001
0 5 0000	.	.	NA	CA	11001
0 0 0134	.	.	NA	CO	11001
0 4 40	.	.	NA	VA	11001
0 0 000	.	.	NA	CA	11001
0 4 4000	.	.	NA	FL	11001
0 5 2700	.	.	NA	MI	11001
0 0 2700	.	.	NA	MI	11001
0 3 1002	.	.	NA	NC	11001
0 0 000	.	.	NA	WA	11001
0 4 0010	.	.	NA	MN	11001
0 4 0000	.	.	NA	NY	11001
0 4 0000	.	.	NA	MI	11001
1 10140	.	.	NA	IN	11001
0 4 7000	.	.	NA	CA	11001
0 7 1010	.	.	NA	TX	11001
0 0 0000	.	.	NA	WA	11001
0 5 0040	.	.	NA	TX	11001
0 0 0000	.	.	NA	MI	11001

W 1984-1985, TECH, TX11

INTERNAL PROBLEM WITH PASSENGER SIDE FRONT SEATBELT BUCKLE OCC 840 CC 41 VERIFIED CONCERN FOUND PASSENGER SIDE FRONT SEAT BELT WOULD NOT BUCKLE CONSISTANTLY. PROBLEM IS INTERNAL TO BUCKLE EN
N/O P DOESNT LOCK SEATBELT ASSEMBLY FRONT REPLACE

VERIFY RP SEAT BELT BUCKLE (N/O P VERIFY CONCERN FOUND BROKEN BUCKLE E/OO 42 REPLACE RP SEAT BELT BUCKLE AND VERIFY REPAIR

8786 SEAT BUCKLE E/OO W REPLACE BELT BUCKLE

REPLACED RIGHT FRONT SEATBELT BUCKLE

(N/O P)OT SEAT BELT BUCKLE ON PASS SIDE IS BROKEN R/L SEAT TO REPLACE BUCKLE AND ROUTE AIRBAG WIRING REASSEMBLE SEATBELT WORKS PROPERLY NOW

22583 DEFECTIVE PASS FRONT SEAT BELT BUCKLE 87 H/R R/L PASS FRONT SEAT TO GAIN ACCESS TO SEAT BELT BUCKLE WIRE HARNESS REPLACED AND CHECKED FOR PROPER OPERATION OK

18013 W/P 81202 33 REPLACED RIGHT SIDE SEAT BELT BUCKLE 1086 FT

DOES NOT OPERATE PROPERLY REPLACED RIGHT FRONT SEAT BELT BUCKLE

8003 81202 42 RIGHT FRONT SEAT BELT BUCKLE DOES NOT HOLD 81784A 1 1 81172A, 4 286 RIGHT FRONT SEAT TRACK FOR ACCESS TO REPLACE RIGHT FRONT SEAT BELT BUCKLE SEAT BELT BUCKLE NOW OPERATES PROPERLY

8894 W/P DO 42 VERIFIED CONCERN NECESSARY TO REMOVE AND REPLACE PASSENGER FRONT SEAT BELT BUCKLE CHECK OPERATION AND CONCERN RESOLVED

REPLACED SEAT RECHECKED

NEED TO REPLACE SEAT BELT BUCKLE ASSEMBLY (42)

TESTED RIGHT FRONT SEAT BELT BUCKLE WITH TESTER FAILED REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSM

INSTALLED THE SOP PASSENGER FRONT SEAT BELT BUCKLE W/WRP 42

8017 3 REPLACED PASS SIDE SEAT BUCKLE ORDERED AS PER W/P PRICE 8120A 2

PASS SIDE FEMALE BELT BROKEN AT LATCH REMOVED PASS SEAT AND REPLACED FEMALE SIDE SEAT BELT

1 REPLACE DEFECTIVE SEAT BELT LATCH (NOT HOLDING) DRIVERS POWER SEAT

1 REPLACE DEFECTIVE SEAT BELT LATCH (NOT HOLDING) DRIVERS POWER SEAT

R & R DRIVER SEAT BELT BUCKLE ASY

INSPECTED AND RECOMMEND THE DRIVERS SEAT BELT BUCKLE SHOULD BE REPLACED SENT OVER P AND A INSTALLED DRIVER SIDE SEAT BELT

LATCH (N/O P SEATBELT ASSEMBLY FRONT REPLACE

REPLACED DRIVER SEAT BELT

127

8283 REPLACED PASS SIDE FRONT SEAT BELT FOR COMING U/L DONE WHILE DRIVING INTERNETLY CC42

REPLACE RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY AT NO LABOR TIME IN SLTS

SEAT BELT CONSTANTLY POPPING OUT OF BUCKLE. REMOVED AND REPLACED O/U L FRT SEAT BELT BUCKLE ASSY AND RPT EST ALL OK

42 REPLACE FRONT SEATBELT BUCKLES

REPLACE RT AND LEFT BUCKLE ONLY BELT

7284 R/L DRIVERS SIDE SEAT AND REPLACED THE SEAT BUCK EL

CC 42 R/P 81802, OCC 868 TESTED SEAT BELT BUCKLE, FAILED WITH AND WITHOUT TESTER REMOVE AND REPLACE BUCKLE RPT EST CLK

Windsor Receipts_AREA_CD	Windsor Receipts_COUNTRY_CD	Windsor Receipts_SLS_DLR_CD	Windsor Receipts_TXN_CD	Windsor Receipts_ONTRY_CD	Windsor Receipts_DRT_CD	Windsor Receipts_VFB_CD
646	USA	127106	EM	USA	Q21	V08
702	USA	613857	1	USA	Q21	V05
776	USA	123993	EM	USA	Q21	V06
748	USA	747935	2	USA	Q21	V06
802	CAN	482864	EM	CAN	Q25	V08
818	USA	571088	1	USA	Q21	V05
828	USA	170488	EM	USA	Q21	V02
713	USA	102029	1	USA	Q21	V05
841	USA	134402	EM	USA	Q21	V03
818	USA	571078	2	USA	Q21	V05
828	USA	182178	1	USA	Q21	V03
268	USA	121108	EM	USA	Q21	V03
518	CAN	448008	EM	CAN	Q21	V02
718	USA	196201	3	USA	Q21	V03
708	USA	127042	1	USA	Q21	V05
788	USA	171102	2	USA	Q21	V03
254	USA	184002	1	USA	Q21	V03
248	USA	148006	1	USA	Q21	V03
248	USA	148005	1	USA	Q21	V03
336	USA	121786	1	USA	Q21	V03
508	USA	174808	EM	USA	Q21	V03
328	USA	188828	2	USA	Q21	V03
848	USA	127871	2	USA	Q21	V03
548	USA	148808	1	USA	Q21	V74
818	USA	141778	EM	USA	Q21	V03
880	USA	171185	EM	USA	Q21	V03
748	USA	141165	EM	USA	Q21	V03
880	USA	118822	EM	USA	Q21	V03
881	USA	152862	EM	USA	Q21	V03
810	USA	148848	1	USA	Q21	V03

Windsor Recall Performance_CD	Windsor Recal Performed_MDL_YR	Windsor Recall Performed_VIN_CD	Windsor Recall Performance_BRL	Windsor Recal Performed_VEH_LI_NE_CD
27	2001	3FMZAR54110	21.4 2002	
28	2001	3FMZAR54110	20.5 2006	
29	2001	3FMZAR54110	18.20 2005	
30	2001	3FMZAR54110	20.20 2005	
31	2001	3FMZAR54110	24 20 2005	
32	2001	3FMZAR54110	14.20 2005	
33	2001	3FMZAR54110	24 20 2005	

Window Recd Performed_TRANS_CD	Window Recd Performed_PLANT_CD	Window Recd Performed_PRODLOT	Window Recd Performed_MFRY_START_DT	Window Recd Performed_NAME
TRXX	AS	1288001	8/8/80	8888001 HAWK FORD, INC
TRXX	AS	8260000	12/18/80	12888001 HOFFEL FORD OF MINNEAPOLIS
TRXX	AS	1/27001	4/1/80	4918001 PKY & DAN DEL SALVO FORD
TRXX	AS	80001	10/28/80	1028001 GENERALTE FORD, INC
TRXX	AS	1/78001	3/8/80	380001 SAS VALLEY FORD
TRXX	AS	12/18000	8/28/80	8828001 VENTURE FORD SALES LIMITED
TRXX	AS	12/18000	1/28/80	1/28001 SOUTH BAK FORD, INC

Windex Recd- Performed_DOC_NUM

8842831
8870898
8884104
8889034
43142881
8843301
7885158

Windex Recd- Performed_PH_NUM

7746141
2884821
7857007
8704428
2447728
8448811

Windex Recall Performed_WCC_CD

Windex Recall Performed_PART_NUM_CAUSE_PREF

Windsor Recall Performed_PART_NUM_CAUS_BASE

.....

Windsor Recall Performed_PART_NUM_CAUS_BUFF

.....

Windsor Recall Performed_CUST_COND_CD

.....

Windsor Recall Performed_COND_CD

.....

Widener Recall Performed_RPR_DT	Widener Recall Performed_LYR_WED	Widener Recall Performed_CLM_KEY	Widener Recall Performed_MLGE	Widener Recall Performed_MTEL_DCS
3/27/2002	18	2702880	34827	
		3211805		
		2857827		
		2481181		
		827-081		
		425-081		
		7980111		

Windsor Recall Performed_TOT_COST_1

28.8
35.39
22.11
30.01
30.89
15.28
32.88

Windsor Recall Performed_LSR_HRS

0.5 8789
0.5 2822
0.5 8848
0.5 7787
0.5 7743
0.5 8189
0.5 898

Windsor Recall Performed_DLR_CD

Windsor Recall Performed_DLR_BUS_CD

Windsor Recall Performed_REGION_CD

NA
NA
NA
NA
NA
NA
NA

Whether Recall Performed_ST_PROV_CD

WA
NY
PA
CA
OH
CA

Whether Recall Performed_CRSC_CD_5

Whether Recall Performed_TECH_TXT1

PERFORMED RECALL
MANUFACTURER RECALL, SEATBELT INSPECTION
INSPECTED FOR RECALL, NOT NEEDED
1 SYSTEMS PLEASE PERFORM INSPECTION PER FORD INSTRUCTIONS. BOTH OUTBOARD SEATBELTS CHECKED
RECALL PERFORMED RECALL TEST AND INSPECTION (66866)

Welding Record Performed, TECH, TXZ

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

RQ04-011 06558

Windsor Recall Peronnes_CLUST.TXT

RECALL # 01881

SAFETY RECALL 01881

01881 SAFETY RECALL CERTAIN 2004 MODEL YEAR CROWN VICTORIA EXCURSION, EXPEDITION, F150 F150, GRAND MARQUIS, NAVIGATOR, RANGER, TOWN CAR AND WINDSTAR VEHICLES SEAT BELT RETENTION
INSPECT THE FRONT DRIVER SEAT AND OUTBOARD FRONT PASSENGER BELT BUCKLE FOR PROPER LATCH PERFORMANCE.

RECALL: SEAT BELT

Windsor Recall Performed_AREA_CD	Windsor Recall Performed_COUNTRY_CD	Windsor Recall Performed_BLS_DUR_CD	Windsor Recall Performed_TXL_CD	Windsor Recall Performed_CNTRY_SOLD
300	USA	11484	0001	USA
300	USA	11890	0001	USA
300	USA	17698	0001	USA
300	USA	12684	0001	USA
400	USA	12488	0001	USA
400	USA	06488	0001	USA
400	USA	08682	0001	USA

Welder Recall Performed, ORT_CD	Welder Recall Performed, VPS_CD	Welder Recall Performed, ANS_M_CD	Welder Recall Performed, WRT_CD	Welder Recall Performed, TB_FLAG	Welder Recall ID
100	AS	AS	AS		148
100	AS	AS	AS		150
100	AS	AS	AS		147
100	AS	AS	AS		142
100	AS	AS	AS		148
100	AS	AS	AS		145
100	AS	AS	AS		135

Windsor Reports_MDL_YR	Windsor Reports_VIN_CD	Windsor Reports_LBF_COST	Windsor Reports_VEH_LINL_CD	Windsor Reports_MKT_DERIVED	Windsor Reports_ROD_CAR_STL
2001	2FMZAS7411E		107 01 T/A3	*	T/WB
2001	2FMZAS7411E		0 T/A3	*	T/WB
2001	2FMZAS7411E		28 1 T/A3	*	T/WB
2001	2FMZAS2421E		48 3 T/A3	*	T/WB
2001	2FMZAS0401E		32 35 T/A3	*	T/WB
2001	2FMZAS0401E		18 32 T/A3	*	T/WB
2001	2FMZAS1431E		25 19 T/A3	*	T/WB

Windsor Reports_VER_SERIES_CD	Windsor Reports_DRVE_CD	Windsor Reports_RNG_CD	Windsor Reports_TRANS_CD	Windsor Reports_PLANT_CD	Windsor Reports_PROD_DT
.	TA	TLM	TDX	AG	1/22/2001
.	TA	TLM	TDX	AG	3/22/2000
.	TA	TLM	TDX	AG	1/17/2001
.	TA	TLM	TDX	AG	1/9/2001
.	TA	TLM	TDX	AG	1/17/2001
.	TA	TLM	TDX	AG	12/12/2000
.	TA	TLM	TDX	AG	12/12/2000

Warranty Report_WRTY_START_DT	Warranty Report_NAME	Warranty Report_DOC_NUM	Warranty Report_PL_NUM	Warranty Report_WDC_CD	Warranty Report_PART_NUM_CAUS_PREF
3099001	HARRIS FORD INC.	5774001	7744141 6F02		1FEZ
12992000	PHILSON MOTORS INC.	1E79300	4817200 6F02		1FEZ
47112001	PAT & DAN DEL BRISQ FORD	3317300	3954801 6F02		1FEZ
10622001	ARMSTRONG FORD INC.	0451200	7627807 6F02		1FEZ
8622001	BIG VALLEY FORD	6820700	8704400 6F02		1FEZ
3622001	CRUISE-HANK MOTORS LTD	7243001	2460401 6F02		1FEZ
17122001	CLAREMONT FORD	1302001	6921000 6F02		1FEZ

W. dealer Reports_PART_NUM_CAUS_BASE	W. dealer Reports_PART_NUM_CAUS_SUFF	W. dealer Reports_CUST_CONC_CD	W. dealer Reports_COND_CD	W. dealer Reports_RPT_DT
1001202 AAB		540	42	3/28/2001
1001202 AAB		540	42	10/11/2001
1001202 AAB		540	42	1/8/2002
1001202 AAA		540	42	11/26/2001
1001202 AAB		540	42	4/18/2002
1001202 AAB		538	43	5/14/2002
1001202 AAB		540	42	5/9/2002

Windsor Reports_TIS_WED	Windsor Reports_CLM_KEY	Windsor Reports_MLISE	Windsor Reports_NTFL_CST	Windsor Reports_TOT_COST_GROSS	Windsor Reports_LBR_HRB
7	4781114	4473	44.8	181.81	1.8
10	4878808	8082	0	0	0
10	8784370	11485	22.4	44.2	0.4
2	8878180	8882	22.4	82.7	0.4
15	8124707	18304	22.4	84.88	0.4
8	8832827	8872	18.78	43.24	0.4
17	8804828	87887	22.4	83.28	0.4

Windsor Reports_DLR_CD	Windsor Reports_DLR_SUB_CD	Windsor Reports_REGION_CD	Windsor Reports_ST_PROV_CD	Windsor Reports_CPSC_CD_S
8738	.	NA	WA	11001
3604	.	NA	NY	11001
3940	.	NA	PA	11001
7737	.	NA	CA	11001
7742	.	NA	CA	11001
A1183	.	NA	CA	11001
1761	.	AA	CA	11001

W repair Reports TECH_TXT1

REMOVE BOTH SEATS AND REMOVE ALL SEATBELT BUCKLES REPLACE WITH BOTH NEW, REPLACE BOTH SEATS AND TEST ALL OPERATION

REPLACE FRONT SEAT BELTS

FAILED BELT BUCKLE ASSEMBLY REPLACE SEAT BELT

INSPECTED THE PASSENGER SEAT BELT AND THAT FEMALE SIDE OF THE BELT IS NOT WORKING FROM OASIS AND FOUND NO INFO FOR THIS CONCERN REMOVED THE SEAT TO GAIN ACCESS TO THE SEAT BELT ASSEMBLY AND I

REPLACE RIGHT FRN SEAT BELT BUCKLE ASSY 1861888 BUCKLE WONT OPERATE POPS LOOSE WHEN DRIVING

REPLACE RF SEAT BELT BUCKLE @ 1730 / 4 HRS / RF SEAT BELT BUCKLE WOP AT TIMES @ 1200 42

BUCKLE NOT WORKING CORRECTLY REPLACED ASSEMBLY

Windsor Response_TECH_TXT2

ED THE SEAT BELT, REBUILT CALLED ALL PARTS REMOVED AND REINSTALLED THE SEAT BELT AND IT IS WORKING

Warranty Reports_CUST_TKT

CUSTOMER REPORTS THAT THE PASS SIDE FRONT SEAT BELT BUCKLE WILL RELEASE WHILE DRIVING INSTALL S.O PARTS TO REPAIR
CUSTOMER STATES PASS SIDE FRONT SEAT BELT POPPED OPEN WHILE DRIVING
CUSTOMER REPORTS THE SEAT BELT DISCONNECTS WHILE DRIVING. DIAG AND REPORT
REPAIR PASSENGER FRONT SEAT BELT WONT LATCH AT TIMES.POPS OUT WHILE DRIVING
CUSTOMER STATES KY FRONT BELT POPS LOOSE WHEN DRIVING.
CUSTOMER REPORTS PASSENGER SIDE FRONT SEAT BELT HAS LB BUCKLE WHEN D
CUST STATES DRIVERS SEAT BELT POPS OUT OF PLACE WHILE DRIVING S40

Field	Warranty Reports_AREA_CD	Warranty Reports_COUNTRY_CD
D		388 USA
D		518 USA
D		570 USA
D		550 USA
D		308 USA
D		418 CAN
D		508 USA

Whistar Reports_RLS_DLR_CD	Whistar Reports_TICK_CD	Whistar Reports_CNTRY_BOLD	Whistar Reports_CRT_CD	Whistar Reports_VPS_CD	Whistar Reports_AWB_VL_CD	Whistar Reports_VRT_CD
176054	1	USA	Q21	V05	AS	808
143089	2	USA	Q21	V05	AS	808
116281	1	USA	Q21	V05	AS	808
178024	1	USA	Q21	V05	AS	808
175465	884	USA	Q21	V05	AS	808
491253	2	CAN	Q21	V05	AS	808
158507	E21	USA	Q21	V05	AS	808

Winter Break_TTB_FLAG

Days Between Paper

Message Between Receipt

89
103
108
132
142
228
43

1780
1105
5436
3806
3753
5945
2590

0

Windsor Recall Performed_ID	Windsor Recall Performed_MDL_YR	Windsor Recall Reference_VIN_CD	Windsor Recall Performed_L	COST	Windsor Recall Performed_VEN_LINE_CD
74	2001	2FMDA8491R		37.94 TMS	
75	2001	2FMDA8491R		38.08 TMS	
76	2001	2FMDA8491R		38.08 TMS	
77	2001	2FMDA8491R		38.08 TMS	
78	2001	2FMDA8491R		38.08 TMS	
79	2001	2FMDA8491R		38.08 TMS	
80	2001	2FMDA8491R		38.08 TMS	
81	2001	2FMDA8491R		38.08 TMS	
82	2001	2FMDA8491R		38.08 TMS	
83	2001	2FMDA8491R		38.08 TMS	
84	2001	2FMDA8491R		38.08 TMS	
85	2001	2FMDA8491R		38.08 TMS	
86	2001	2FMDA8491R		38.08 TMS	
87	2001	2FMDA8491R		38.08 TMS	
88	2001	2FMDA8491R		38.08 TMS	
89	2001	2FMDA8491R		38.08 TMS	
90	2001	2FMDA8491R		38.08 TMS	
91	2001	2FMDA8491R		38.08 TMS	

W/Order Recall Performed_TRANS_CD	W/Order Recall Performed_PLANT_CD	W/Order Recall Performed_PROD_CD	W/Order Recall Performed_WRTY_START_DT	W/Order Recall Performed_PARTNAME
17110001				FORD MOTOR CO
17110002				FORD MOTOR CO
17110003				FORD MOTOR CO
17110004				FORD MOTOR CO
17110005				FORD MOTOR CO
17110006				FORD MOTOR CO
17110007				FORD MOTOR CO
17110008				FORD MOTOR CO
17110009				FORD MOTOR CO
17110010				FORD MOTOR CO
17110011				FORD MOTOR CO
17110012				FORD MOTOR CO
17110013				FORD MOTOR CO
17110014				FORD MOTOR CO
17110015				FORD MOTOR CO
17110016				FORD MOTOR CO
17110017				FORD MOTOR CO
17110018				FORD MOTOR CO
17110019				FORD MOTOR CO
17110020				FORD MOTOR CO
17110021				FORD MOTOR CO
17110022				FORD MOTOR CO
17110023				FORD MOTOR CO
17110024				FORD MOTOR CO
17110025				FORD MOTOR CO
17110026				FORD MOTOR CO
17110027				FORD MOTOR CO
17110028				FORD MOTOR CO
17110029				FORD MOTOR CO
17110030				FORD MOTOR CO
17110031				FORD MOTOR CO
17110032				FORD MOTOR CO
17110033				FORD MOTOR CO
17110034				FORD MOTOR CO
17110035				FORD MOTOR CO
17110036				FORD MOTOR CO
17110037				FORD MOTOR CO
17110038				FORD MOTOR CO
17110039				FORD MOTOR CO
17110040				FORD MOTOR CO
17110041				FORD MOTOR CO
17110042				FORD MOTOR CO
17110043				FORD MOTOR CO
17110044				FORD MOTOR CO
17110045				FORD MOTOR CO
17110046				FORD MOTOR CO
17110047				FORD MOTOR CO
17110048				FORD MOTOR CO
17110049				FORD MOTOR CO
17110050				FORD MOTOR CO
17110051				FORD MOTOR CO
17110052				FORD MOTOR CO
17110053				FORD MOTOR CO
17110054				FORD MOTOR CO
17110055				FORD MOTOR CO
17110056				FORD MOTOR CO
17110057				FORD MOTOR CO
17110058				FORD MOTOR CO
17110059				FORD MOTOR CO
17110060				FORD MOTOR CO
17110061				FORD MOTOR CO
17110062				FORD MOTOR CO
17110063				FORD MOTOR CO
17110064				FORD MOTOR CO
17110065				FORD MOTOR CO
17110066				FORD MOTOR CO
17110067				FORD MOTOR CO
17110068				FORD MOTOR CO
17110069				FORD MOTOR CO
17110070				FORD MOTOR CO
17110071				FORD MOTOR CO
17110072				FORD MOTOR CO
17110073				FORD MOTOR CO
17110074				FORD MOTOR CO
17110075				FORD MOTOR CO
17110076				FORD MOTOR CO
17110077				FORD MOTOR CO
17110078				FORD MOTOR CO
17110079				FORD MOTOR CO
17110080				FORD MOTOR CO
17110081				FORD MOTOR CO
17110082				FORD MOTOR CO
17110083				FORD MOTOR CO
17110084				FORD MOTOR CO
17110085				FORD MOTOR CO
17110086				FORD MOTOR CO
17110087				FORD MOTOR CO
17110088				FORD MOTOR CO
17110089				FORD MOTOR CO
17110090				FORD MOTOR CO
17110091				FORD MOTOR CO
17110092				FORD MOTOR CO
17110093				FORD MOTOR CO
17110094				FORD MOTOR CO
17110095				FORD MOTOR CO
17110096				FORD MOTOR CO
17110097				FORD MOTOR CO
17110098				FORD MOTOR CO
17110099				FORD MOTOR CO
17110100				FORD MOTOR CO

RC04-011 06675

Windsor Recall Performed_PART_NUM,CASE,SUFF	Windsor Recall Performed_CUST_CONC_CD	Windsor Recall Performed_COND_CD	Windsor Recall Performed_RFR_DT	Windsor Recall Performed_TIS_WSD
				07
				08
				09
				10
				11
				12
				13
				14
				15
				16
				17
				18
				19
				20
				21
				22
				23
				24
				25
				26
				27
				28
				29
				30
				31
				32
				33
				34
				35
				36
				37
				38
				39
				40
				41
				42
				43
				44
				45
				46
				47
				48
				49
				50
				51
				52
				53
				54
				55
				56
				57
				58
				59
				60
				61
				62
				63
				64
				65
				66
				67
				68
				69
				70
				71
				72
				73
				74
				75
				76
				77
				78
				79
				80
				81
				82
				83
				84
				85
				86
				87
				88
				89
				90
				91
				92
				93
				94
				95
				96
				97
				98
				99
				00

Windsor Recall Performed_CLU_KEY	Windsor Recall Performed_MLSS	Windsor Recall Performed_MTR
000000		
000001		
000002		
000003		
000004		
000005		
000006		
000007		
000008		
000009		
000010		
000011		
000012		
000013		
000014		
000015		
000016		
000017		
000018		
000019		
000020		
000021		
000022		
000023		
000024		
000025		
000026		
000027		
000028		
000029		
000030		
000031		
000032		
000033		
000034		
000035		
000036		
000037		
000038		
000039		
000040		
000041		
000042		
000043		
000044		
000045		
000046		
000047		
000048		
000049		
000050		
000051		
000052		
000053		
000054		
000055		
000056		
000057		
000058		
000059		
000060		
000061		
000062		
000063		
000064		
000065		
000066		
000067		
000068		
000069		
000070		
000071		
000072		
000073		
000074		
000075		
000076		
000077		
000078		
000079		
000080		
000081		
000082		
000083		
000084		
000085		
000086		
000087		
000088		
000089		
000090		
000091		
000092		
000093		
000094		
000095		
000096		
000097		
000098		
000099		
000100		

Windsor Recall Performed_TOT_COST_GROSS	Windsor Recall Performed_LBR_MIS
000000	
000001	
000002	
000003	
000004	
000005	
000006	
000007	
000008	
000009	
000010	
000011	
000012	
000013	
000014	
000015	
000016	
000017	
000018	
000019	
000020	
000021	
000022	
000023	
000024	
000025	
000026	
000027	
000028	
000029	
000030	
000031	
000032	
000033	
000034	
000035	
000036	
000037	
000038	
000039	
000040	
000041	
000042	
000043	
000044	
000045	
000046	
000047	
000048	
000049	
000050	
000051	
000052	
000053	
000054	
000055	
000056	
000057	
000058	
000059	
000060	
000061	
000062	
000063	
000064	
000065	
000066	
000067	
000068	
000069	
000070	
000071	
000072	
000073	
000074	
000075	
000076	
000077	
000078	
000079	
000080	
000081	
000082	
000083	
000084	
000085	
000086	
000087	
000088	
000089	
000090	
000091	
000092	
000093	
000094	
000095	
000096	
000097	
000098	
000099	
000100	

Windsor Recoll Performed TECH TKT

Windsor Recoll Performed TECH TKT

PERFORM RECALL 01821, REPLACE RIGHT FRONT BEAT BELT, REMOVE BEAT TO ACCESS BOLT AND CONNECTER.
PERFORM RECALL 01821
REPLACE ONE BOLT
PERFORM BUCKLES
RECALL COMPLETED, NO FURTHER ACTION REQUIRED
PERFORM RECALL 01821, REPLACE BOTH END BELTS
CHECK RE-TENSIONING BELT BUCKLE
PERFORM RECALL 01821, PERFORM RECALL 01821, PERFORM RECALL 01821
PERFORM RECALL 01821, PERFORM RECALL 01821, PERFORM RECALL 01821, PERFORM RECALL 01821

Whistar Recall Performed_CUST_TXT	Whistar Recall Performed_AREA_CD	Whistar Recall Performed_COUNTRY_CD	Whistar Recall Performed_BLS_DLR_CD	Whistar Recall Performed_TOT_CD
001	001	USA	112146	01001
002	001	USA	186104	01001
003	001	USA	184188	01001
004	001	USA	541884	01001
005	001	USA	100455	01001
006	001	USA	171136	01001
007	001	USA	112146	01001
008	001	USA	112146	01001
009	001	USA	112146	01001
010	001	USA	112146	01001
011	001	USA	112146	01001
012	001	USA	112146	01001
013	001	USA	112146	01001
014	001	USA	112146	01001
015	001	USA	112146	01001
016	001	USA	112146	01001
017	001	USA	112146	01001
018	001	USA	112146	01001
019	001	USA	112146	01001
020	001	USA	112146	01001

Welder Reports_ID	Welder Reports_MOL_YR	Welder Reports_VEH_CD	Welder Reports_ID	DOBT	Welder Reports_VEH_LINE_CD	Welder Reports_MCT_DEFRSED	Welder Reports_BOD_CAR_STL
48	2001	2FMZAS2401B		89 2	NS	*	TWB
17	2001	2FMZAS2401B		89 44	TAB	*	TWB
18	2001	2FMZAS14X1B		28 05	TAB	*	TWB
27	2001	2FMZAS14B1B		71 23	TAB	*	TWB
48	2001	2FMZAS1471B		27	TAB	*	TWB
72	2001	2FMZAS24B1B		81 04	TAB	*	TWB
54	2001	2FMZAS2411B		14 8	TAB	*	TWB
8	2001	2FMZAS2411B		24 13	TAB	*	TWB
1	2001	2FMZAS1471B		28 03	TAB	*	TWB
68	2001	2FMZAS2442B		30 07	TAB	*	TWB
28	2001	2FMZAS14B1B		28 44	TAB	*	TWB
4	2001	2FMZAS14B1B		14 81	TAB	*	TWB
30	2001	2FMZAS14B1B		20 21	TAB	*	TWB
78	2001	2FMZAS2471B		24 09	TAB	*	TWB

Welder Reports_SERIES_CD	Welder Reports_DRIVE_CD	Welder Reports_DASL_CD	Welder Reports_TRANS_CD	Welder Reports_PLANT_CD	Welder Reports_PROD_DT	Welder Reports_WRTV_START_DT
.	TA	TLM	TCK	A5	1/11/2001	11/7/2001
.	TA	TLM	TCK	A5	1/22/2001	2/7/2001
.	TA	TLM	TCK	A5	1/23/2001	3/2/2001
.	TA	TLM	TCK	A5	1/16/2001	3/3/2001
.	TA	TLM	TCK	A5	1/18/2001	4/1/2001
.	TA	TLM	TCK	A5	4/6/2001	4/22/2001
.	TA	TLM	TCK	A5	1/21/2001	1/21/2001
.	TA	TLM	TCK	A5	2/12/2001	3/22/2001
.	TA	TLM	TCK	A5	2/22/2001	5/6/2001
.	TA	TLM	TCK	A5	2/25/2001	2/22/2001
.	TA	TLM	TCK	A5	2/28/2001	5/21/2001
.	TA	TLM	TCK	A5	1/5/2001	2/22/2001
.	TA	TLM	TCK	A5	2/1/2001	2/12/2001
.	TA	TLM	TCK	A5	2/21/2001	2/12/2001

Wrcater Repairs_NAME	Wrcater Repairs_DQC_NUM	Wrcater Repairs_PH_NUM	Wrcater Repairs_WCC_CD	Wrcater Repairs_PART_NUM_CAUS_PREF	Wrcater Repairs_PART_NUM_CAUS_BASE
CAUSEWAY FORD & MERCURY	12362301	8678000	8902	1F22	1861202
ROBERTS MOTORS, INC.	147384A	4887228	8902	1F22	1861202
THOMASVILLE FORD, INC.	6702101	4727731	8902	1F22	1861202
JAY WOLFE FORD	292200A	7332148	8902	1F22	1861202
BENEFROM HEENAN-MENASHA FORD	8802001	7078008	8902	1F22	1861202
OTIS FORD, INC.	8703004	8804000	8902	1F22	1861202
PARKVIEW FORD SALES, INC.	1547882	8802001	8902	1F22	1861202
HILL FORD LINCOLN MERCURY, INC.	6173881	7427141	8902	1F22	1861202
ACE MOTOR SALES, INC.	11387803	3488000	8902	1F22	1861202
BROOKDALE FORD, INC.	16881901	8818008	8902	1F22	1861202
CENTURY FORD OF MT ARRY, INC.	181281A	6210200	8902	1F22	1861202
VILLAGE FORD INC	6685381	4883000	8902	1F22	1861202
APPLE VALLEY FORD	23188203	4316000	8902	1F22	1861202
ANDERSON FORD OF ST JOSEPH	1412728	2707426	8902	1F22	1861202

Wincor Reports_PART_NUM_CAUS_SUFF	Wincor Reports_CUST_CONC_CD	Wincor Reports_COVD_CD	Wincor Reports_RPT_DT	Wincor Reports_TEL_WSD	Wincor Reports_CLI_KEY	Wincor Reports_MLGE
AAA	000	42	2/10/2002	4	7430475	3718
AAS	000	42	1/24/2002	12	6400015	18741
AAS	000	42	4/12/2002	15	8087768	28165
AAA	000	42	4/10/2002	18	7917117	18854
AAS	040	42	10/28/2001	7	4892291	3705
AAS	040	39	02/12/2001	8	0000235	11557
AAA	000	41	10/12/2001	0	4200000	23
AAA	040	42	11/03/2001	8	0542864	23745
AAS	040	42	11/21/2001	7	0278147	10009
0AS	000	42	1/24/2002	8	0518163	8801
0AS	000	42	02/25/2002	10	7090885	31470
AAS	000	42	4/8/2002	8	7794271	4375
0AS	000	42	4/12/2002	14	0081287	28161
AAA	000	41	4/24/2002	18	0016444	17800

Welder Reports_MT	2015T	Welder Reports_TOT_COST_GROSS	Welder Reports_LBR_HRS	Welder Reports_DLR_CD	Welder Reports_DLR_SVR_CD	Welder Reports_REGION_CD	Welder Reports_ST_PROV_CD
65.0		117.78	0.0	0000		NA	W
24		64.44	0.4	0001		NA	IL
22.4		61.26	0.0	000		NA	NC
22.4		55.75	1.1	2000		NA	ME
22.4		49.4	0.4	0020		NA	WI
22.4		63.44	0.4	0700		NA	NY
22.4		57.3	0.0	7000		NA	CA
22.4		46.51	0.4	0004		NA	WI
22.4		55.42	0.4	1400		NA	NJ
22.4		52.47	0.4	0001		NA	MI
22.4		52.84	0.4	00		NA	MO
22.4		56.71	0.3	0707		NA	MI
22.4		52.61	0.4	0027		NA	MI
22.4		47.22	0.4	1745		NA	MO

W 48867 Repair TECH_TXT1

HAD TO REPLACE SEATBELT ASSYS

18741 WOULDNT BUCKLE. REMOVED SEAT, REMOVED AND REPLACED RIGHT SIDE BUCKLE ASSY, REINSTALLED SEAT

BUCKLE NOT LATCHING. DIAGNOSE CONDITION. REPLACED SEAT BELT BUCKLE

22854 SEAT BELT WOULD NOT LATCH WARR FOR SEAT AND REPLACED LATCH

SEATBELT BUCKLE WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE

81233 23 REPLACED L P SEAT BELT, BUCKLE WONT CLIP 1

OK DR SEAT BUCKLE REPLACE SEAT BUCKLE BRADS

REPLACED L SIDE SEAT BELT LATCH WOULD NOT HOLD CLOSED BY WPI

1 848 48 (1881808) INSTALLED ORDERED PARTS OK OPERATION WHEN DONE SEAT BELT BUCKLE DRIVERS SEAT

1 REPLACED SEAT BELT BUCKLE ASSEMBLY,

EXPECTED BELT BUCKLE WILL NOT HOLD IN CLASP REPLACED DRIVERS SEAT BELT BUCKLE

TEST DRIVE SEAT BELT OPERATION AND FOUND BUCKLE WAS BAD. NCC TO REMOVE FRONT SEAT ASY TO INSTALL NEW SEAT BELT BUCKLE ON POWER SEAT. RETEST AFTER REPAIR. OKAY AT THIS TIME

48 UNB1208 VERIFIED CONCERN. P AND I DRIVERS SEAT TO MAIN ADDRESS. P AND R BUCKLE ASSEMBLY AND FOUND GOOD.

17822 RIGHT SEAT BELT WONT BUCKLE PART TRUE.239 REPLACE RIGHT FRONT SEAT BELT BUCKLE ASSY 2ND8 41

Windstar Reports_TECH_TXT W Windstar Reports_CUST_TXT
 SEAT BELT BUCKLE LATCHING DOES NOT ALWAYS WORK
 CUST REPORTS RIGHT FRONT SEAT BELT WONT LATCH
 PASSENGER SIDE FRONT SEAT BELT DOES NOT LATCH SOP HERE
 CUST STATES SEATBELT DOES NOT LATCH SOP PART HERE
 DRIVERS SEAT BELT BUCKLE WONT HOLD
 CUSTOMER STATES THAT L S FRONT SEAT BELT WONT CLIP PROPERLY , PARTS ORDERED
 DRIVERS SEAT BELT BUCKLE FITS INCORRECTLY
 L H SEAT BELT LATCH IS INOP
 LEFT SEAT BELT HARD TO PUT BELT IN LATCH L P
 THE FRONT DRIVERS SIDE SEAT BELT WONT BUCKLE
 DRIVERS SIDE SEAT BELT LATCH WONT HOLD INTO RECEIVER
 3 BK CK AND ADV DRIVERS SIDE SEATBELT INOP WILL NOT LATCH (PART IN STOCK)
 CUSTOMER STATES PASS FRONT SEAT BELT DOES NOT LATCH INTERMITTENTLY PLEASE ADVISE
 CUSTOMER STATES RIGHT FRONT PASS SEAT BELT INOP

Prod38	Windstar Reports_AREA_CD	Windstar Reports_COUNTRY_CD
A	808 USA	
A	818 USA	
A	398 USA	
A	488 USA	
A	888 USA	
A	827 USA	
A	808 USA	
A	808 USA	
A	808 USA	
A	788 USA	
A	301 USA	
A	818 USA	
A	888 USA	
A	878 USA	

Windsor Reports_RLS_DLR_CD	Windsor Reports_TXN_CD	Windsor Reports_CNTRY_SOLD	Windsor Reports_ORI_CD	Windsor Reports_VFL_CD	Windsor Reports_AWS_VL_CD	Windsor Reports_VRT_CD
112148	S	USA	Q21	V05	A3	305
123104	ED4	USA	Q21	V05	A3	305
124125	ED4	USA	Q21	V05	A3	305
171210	ED4	USA	Q21	V05	A3	305
141581	1	USA	Q21	V05	A3	305
112485	1	USA	Q21	V05	A3	305
171159	1	USA	Q21	V05	A3	305
141134	ED4	USA	Q21	V05	A3	305
112042	1	USA	Q21	V05	A3	305
122014	2	USA	Q21	V05	A3	305
123285	ED4	USA	Q21	V05	A3	305
142048	2	USA	Q21	V05	A3	305
171227	ED4	USA	Q21	V05	A3	305
123234	ED4	USA	Q21	V05	A3	305

Winder Repeats_TIS_FLAG

Days Since Paper

Mergs Between Paper

100	3713
101	5212
103	5906
125	4385
42	880
60	3072
72	8
81	6487
86	5278
152	6888
186	21128
208	4149
298	10728
132	6645

Winter Recd Performed_ID Winter Recd Performed_MDLYR Winter Recd Performed_VIN_CD Winter Recd Performed_LE OST Winter Recd Performed_VEH_LINE_CD