

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 4 OF 6
BOOKS 23 OF 43

27	33.87	127.00	1	5538 *	NA	CA	11000 SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS	X
22	40.88	71.28	0.4	5538 *	NA	CA	11000 SEATBELT WONT LATCH REPLACE SEAT BELT SEATBELT ASSEMBLY	A
10573	23.16	84.71	0.7	348 *	NA	GA	11000 FRONT REPLACE	X
12	48.88	147.87	1.4	5538 *	NA	CA	11000 RECALL 01821	R
29	28.18	82.73	0.4	5538 *	NA	CA	CC3MS CLARM 898486 SHOULD BE A SPW	R
613	23.18	114.85	1.2	5538 *	NA	CA	CC350 DMG, REPLACE DRIVERS SEAT BELT BUCKLE	X
48	40.88	132.38	1.2	5538 *	NA	CA	11000 RECALL 01821	R
12	40.88	124.74	1.1	5538 *	NA	CA	11000 RECALL 01821	R
19	40.88	78.88	0.8	5538 *	NA	CA	11000 RECALL 01821	R
8083	18.61	88.44	0.7	80830 *	NA	AB	FAULTY BUCKLE. CHK OPER OF DR. SEATBELT BUCKLE/REPLACED BUCKLE ASSY. VERIFY REPAIR BY FUNCTIONALITY IN TIME TO REPLACE SEATBELT BUCKLE, NO	X
4880	37.8	88.18	0.5	45782 *	NA	AZ	12000 TIME IN LTS	X
10	40.88	78.88	0.5	5538 *	NA	CA	11000 RECALL 01821	R
114	23.87	32.11	0.2	83825 *	NA	MS	TECH REPLACED BELT BUCKLE PASS SEAT, WAS STUCK DOWN	X
8	0	0	0	82807 *	NA	PQ	VERIFIER FONCTIONNEMENT DES BOUCLES DE CEINTURE AVEC OUTIL OU RAPPEL 01821 - CEINTURE DEFECTUEUSE, REMPLACER CEINTURE GAUCHE	R
15	23.16	88.25	0.7	3882 *	NA	KY	01X00K CHECKED AND REPLACED LEFT SEAT BELT BUCKLE	X
15843	23.07	47.74	0.5	84808 *	NA	OK	01X00K LEFT FRONT SEAT BUCKLE DOES NOT BUCKLE PROPERLY. REPLACE LEFT FRONT SEAT BELT BUCKLE.	A

639	26.16	74.26	0.7	7022 *	NA	QA	SEAT BELT FAULTY SEATBELT ASSEMBLY 11000 FRONT REPLACE REPLACED DRIVERS SEAT	X
1084	43.86	73.57	0.5	4475 *	NA	TX	11000 BELT BUCKLE 85 REPLACE BOTH FRONT	A
25	50.87	127.53	1.2	2196 *	NA	OH	11000 SEAT BELTS AS PER RO	X
051	27.51	65.07	0.8	9675 *	NA	MI	85: BELT BUCKLE BROKEN AND MOUNT BOLT HEAD IS STRIKED TIME AS NEBBY. TO REMOVE BOLT AND REPLACE RF BUCKLE MT. 8 11000 HERE	A
4213	23.16	48.58	0.4	4786 *	NA	IN	TECH INSPECTED VEHICLE , CHECKED OPERATION AND SEAT BELT BUCKLE INOP WILL NOT LATCH. ORDERED NEW S.O.P* TECH REMOVED DRIVER SEAT REMOVED AND REPLACED SEAT BELT BUCKLE CHECKED OPERATION OKAY. REINSTALLE D DRIVERS SEAT. DEFECTIVE SEATBELT RECEIVER. DIAGNOSIS CHECKED AND REPLACED DRIVERS SEATBELT	A
3639	40.68	105.88	0.8	5016 *	NA	MO	11000 RECEIVER, VERIFIED CONCERN AND FOUND THAT RIGHT SEAT BELT LATCH WILL NOT LATCH REMOVED RIGHT SEAT REMOVED CENTER SEAT BELT UNIT	X
1176	0	0	0	48 *	NA	VA	11006 SEAT BELT UNIT CHECK FOR CONCERN & CHECK & REPLACE SEATBELT LATCH ASSEMBLY, RECHECK ALL	A
2182	18.41	30.23	0.2	A8817 *	NA	ON	11001 OK.	A
4777	23.07	65.34	0.7	A3846 *	NA	PQ	REPLACER CENTURE AV 11000 DRIVE	X
691	23.07	43.88	0.4	B1386 *	NA	ON	11000 REPLACE P/B SEAT BELT BUCKLE	A

4811	23.18	63.77	0.7	2986 *	NA	TX	4811 SEAT BELT BUCKLE NOP DIAGNOSE REPLACE LR FRONT SEAT BELT BUCKLE ASY CC42 487	A
84	87.61	88.61	1	2528 *	NA	VA	11000 SWAPPED SEATBELTS FOUND SEAT BELT LATCH CONNECTPOORRECONNECTED	A
11226	0	44.17	1	7452 *	NA	WV	01100X RMR DRIVERS SEAT, REPLACE SEATBELT	X
3291	23.18	68.01	1	2349 *	NA	WV	11001 BUCKLE BROKEN REPLACE FRONT SEAT	A
18958	39	68.8	0.7	5100 *	NA	MO	011000X BELT AND BUCKLE CHECK OUT CHECK OVER SEAT BELT BUCKLE BOTH ARE BROKEN ON PASSENGER SIDE NEED TO REPLACE REPLACED SEAT BELT BUCKLE	A
10880	27.51	69.89	0.7	1758 *	NA	AR	11000 MISSING BUCKLE ASBY. REPLACED DRIVERS SEAT SEAT BELT BUCKLE ASBY MISSING PART SABC 82103 CODE IN THIS VEHICLE WAS DEALER TRADE FROM ANOTHER DEAL WASNT CORRECTED AT THERE DEALERSHIP	A
186	23.18	63.94	0.7	1898 *	NA	OH	011000X REPLACE RIGHT FRONT SEAT BELT BUCKLE	X
28824	27.51	71.1	0.7	2824 *	NA	TX	11000 REPLACE SEATBELT	X
5383	43.94	60.46	0.4	30050 *	NA	IL	REPLACED L.P. SEAT BELT LATCH DE RECALL	X
5	26.05	74.92	0.7	7783 *	NA	CA	11001 INSPECT AND REPLACE SEAT BELTS BUCKLE	X
21	26.05	104.88	1.2	2518 *	NA	TX	11001 INSTALL SEAT BELT	R
103	26.05	69.47	0.7	340 *	NA	OK	11001 FAILED DRIVERS SEAT BELT BUCKLE TEST REPLACE DRIVER SIDE BELT BUCKLE NO RECALL	B
6	26.05	71.48	0.8	5401 *	NA	CA	11001 OP CODE REQ WARRANTY	R

								CK AND REMOVED DRIVERS SEAT BELT BUCKLE ASSY AND REPLACED RECHECKS	
1277	16.85	32.30	0.3	882 *	NA	SC	18001 FINE	X	
0	30.27	56.04	0.5	2877 *	NA	CA	11001	X	
49	55.58	107.05	0.7	5536 *	NA	CA	11001 SEAT BELTS WONT LATCH REPLACE SEAT BELTS NO SEAT BELT IN VEHICLE EXCHANGED PART FROM STOCK UNIT. PARTS ARRIVED AND A NEW SEAT BELT BUCKLE WAS	A	
181	43.34	79.38	0.4	3921 *	NA	CA	12001 INSTALLED. WONT HOLD	X	
31	27.51	52.57	0.4	1025 *	NA	SC	11001 SEATBELT ASSEMBLY FRONT REPLACE	A	
15	25.05	49.01	0.4	323 *	NA	TX	11001 REPLACE SEAT BELT BUCKLE	X	
15	20.27	57.53	0.7	3231 *	NA	CO	11001 REPLACE SEATBELT BUCKLE BINDING	X	
8	25.05	84.36	0.6	3035 *	NA	FL	11001 ON SEAT BELT RECALL A INSPECTED BOTH SEAT BELTS DRIVER FAILED. REPLACED DRIVERS SEAT BELT	R	
15	27.51	53.58	0.7	8217 *	NA	WI	11001 CHECK AND REPLACE RF SEATBELT BUCKLE PER RECALL	R	
323	16.85	51.49	1	402 *	NA	CA	12001 SEAT BELT FAILED BODY CHASSIS ELECTRIAL (BCE) TEST	X	
3985	27.51	71.81	0.7	6485 *	NA	LA	3885 RR FRONT PASS. SEAT BELT BUCKLE, ORDERED REAR PASS. 11001 SEAT BELT BUCKLE	X	
188	28.05	78.78	0.7	885 *	NA	NC	REPLACED LEFT SIDE SEAT	X	
1	27.51	78.88	0.7	5555 *	NA	CA	11001 BELT 11001 RECALL 01821 1 CHECK FRONT PASS SIDE SEAT BELT BUCKLE IS VERY HARD TO RELEASE.REMOVE AND REPLACE RIGHT FRONT	X R	
7408	41.36	84.34	0.7	2482 *	NA	TX	12000 SEATBELT BUCKLE. REPLACED BOTH SEAT	X	
15	53.58	112.54	0.7	7853 *	NA	CA	11001 BELT BUCKLES	X	
25	20.27	47.55	0.4	5432 *	NA	CA	11001 REPLACED SEAT BELT	X	

3453	27.81	58.85	0.8	4210 *	NA	TX	78612218 ANCHOR REPLACE SEAT BELT BUCKLE RIGHT FRONT	11001	A
10	52.68	106.9	0.8	7380 *	NA	CA	11 INSPECT AND REPLACE 2 SEATBELT BUCKLES. NO 40 SPLIT BENCH WITH NO POWER OR SIFL WONT HOLD	11001	R
11	27.51	52.57	0.4	1025 *	NA	SC	BEATBELT ASSEMBLY FRONT REPLACE	11001	A
15109	50.57	130.59	1	20303 *	NA	AZ	REPLACE COMPLETE	11001	X
3182	25.65	65.18	0.7	3100 *	NA	SD	VERIFIED CONCERN CHIME WENT ON WITH BUCKLE HOOKED CIRCUIT TEST SEAT BELT WARNING SYSTEM REPLACE DRIVERSEAT BELT BUCKLE OPEN CIRCUIT IN BUCKLE	11001	X
2	29.27	33.55	0.2	3140 *	NA	CO	WIRING WGA TIME TO REPLACE RIGHT FRONT SEAT BELT BUCKLE	11001	A
10	53.58	122.34	0.9	5538 *	NA	CA	SEAT BELTS WONT LATCH	11001	A
25387	20.27	46.07	0.4	11430 *	NA	TX	REPLACE SEAT BELTS INSPECTED AND REPLACED FAILED RF SEAT BELT BUCKLE.	11001	R
11	51.58	101.59	0.5	359 *	NA	CA	RECALL INSPECT AND REPLACED TWO SEAT BELT BUCKLES.	11001	R
8616	20.27	100.43	1.2	4320 *	NA	FL	RR RIGHT SEAT AND REPLACE BUCKLE ASSY DAG INSP VERIFIED CONCERN IN TIME TO REPLACE SEAT BELT BUCKLE	11001	X
14	27.51	68.47	0.4	7704 *	NA	CA	SEAT BELT WOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT	11001	X
7902	20.27	78.14	0.8	4902 *	NA	FL	REPLACE	11001	A
299	20.27	68.34	0.8	8199 *	NA	MO	REPLACE ONE SEAT BELT R SEAT TRACK TO	11001	R
11	20.27	68.71	0.8	3048 *	NA	TX	REPLACE SEAT BELT	11001	X

21	48.32	174.42	1.5	7777 *	NA	CA	21 CHECK AND INSPECT PERFORMED RECALL 01821 REMOVE AND REPLACE FAIL BOTH FRONT SEAT BELT BUCKLE END RELEASE ASSY. 21	R
6485	46.32	89.48	0.4	1616 *	NA	TX	SEATBELT ASSEMBLY FRONT REPLACE	X
5402	48.32	100.46	0.8	4877 *	NA	FL	PERFORMED RECALL 01821 REPLACED BOTH FRONT SEAT BELT BUCKLES OUT	R
300	0	26.86	0.4	2295 *	NA	OH	11001 MESSAGE 8404 11000 COMPLETE RECALL	R
4391	41.98	93.1	0.7	5428 *	NA	CA	REPLACE REAR BELT BUCKLE, PASSENGER SIDE. CHECK OUT, CONFIRMED SEAT BELT INOP, REPLACE AND RETEST	X
16308	60.28	106.13	0.8	3085 *	NA	WI	11001 SEATBELT ASSEMBLY FRONT REPLACE	X
18818	20.27	58.04	0.7	7018 *	NA	TX	11001 SEATBELT ASSEMBLY FRONT REPLACE 3911 WARR VERIFY CONCERN N08 DIAG TO MONITOR PIDS FOUND DRIVER SEAT BELT NOT SHOWING SEAT BELT NOT BUCKLED PERFORMED PPT. FOUND SEAT BELT BUCKLE INOP RR BUCKLE RETEST AND QUALITY INSPECTED BY	X
3911	20.06	58.92	0.5	4830 *	NA	FL	11001 8711 , 3911 VERIFY AND TEST NECESSARY TO REPLACE	X
3935	48.34	96.61	0.7	4820 *	NA	FL	12001 BUCKLE VERIFY CONCERN CENTER BUCKLE WOULD NOT LATCH AND RT REAR REPLACE CENTER BUCKLE AND RIGHT REAR	X
3914	60.05	106.85	0.7	4446 *	NA	TX	12000 SEATBELT BUCKLES	X
7607	20.27	67.24	0.7	4670 *	NA	FL	11001 REPLACE SEAT BELT.	X

0	27.51	53.05	0.4	5095 *	NA	FL	08 SEAT BELT RECALL, A INSPECTED BOTH SEAT BELTS PASS 11001 FAILED/REPLACED PASS SEAT BELT. CHECKED BUCKLES DID GEM TEST NEEDS DRIVERS FRONT SEAT BUCKLE/REPLACED THE BUCKLE OK NOW	R
3	17.38	61.81	1.1	8131 *	NA	WI	12001 180 CHIMING SEAT BELT WARR REPLACED SEAT BELT BUCKLE CHIMES WHEN SEAT BELT NOT BUCKLED DOES NOT CHIME WHEN SEAT BELT IS BUCKLED	X
189	18.83	65.45	0.7	88 *	NA	MD	12001 SEATBELT ASSEMBLY FRONT REPLACE SEATBELT INOP	X
10588	41.88	64.27	0.4	7015 *	NA	OK	11001 CENTER SEAT BELT ASSEMBLY BELT BUCKLE SEATBELT ASSEMBLY	X
11986	27.51	60.92	0.6	7015 *	NA	OK	11001 FRONT REPLACE REPLACE RIGHT HAND SEAT BELT BUCKLE, 42.	X
132	27.51	72.28	0.7	875 *	NA	NC	11001 SEAT BELT BUCKLE, 42. CK AND FOUND SEAT BELT BUCKLE BAD AND REPLACE SEAT BELT BUCKLE AND RECHECK	A
10	20.27	48.87	0.4	2511 *	NA	TX	11001 RECHECK	X
5182	26.05	62.84	0.5	8622 *	NA	LA	11001 11 INSPECT AND REPLACE 2 SEATBELT BUCKLES POWER BUCKLE, SLIDING BUCKET. NO BFL SEAT BELT NOT OPERATING PROPERLY VERIFIED AND R AND R SEAT BELT ANCHOR RETESTED AND CHECKED	X
10	45.22	121.44	0.7	7820 *	NA	CA	11001 OK AT THIS TIME FOUND INOP SEAT BELT HAD TO REMOVE DRIVERS SEAT TO REPLACE BELT	R
1845	25.05	58.45	0.5	7626 *	NA	TX	11001 BUCKLE	D
2048	25.05	102.85	1	7633 *	NA	CA	11001 BUCKLE	X
89	44.04	77.4	0.7	7941 *	NA	CA	11001 RECALL 01821	R

8687	14.88	41.87	0.5	B1007	-	NA	ON	12001	REPLACED DRIVERS SIDE SEATBELT BUCKLE	X
30	53.55	188.84	1.8	7841 *		NA	CA	11001	RECALLED BOTH FRONT SEAT BELT BUCKLES PER	R
20	58.88	128.88	1	7941 *		NA	CA	11001	INTERNAL FAILURE IN BUCKLE REPLACED RT AND LT SEAT BELT	X
18	53.98	117.13	1	1882 *		NA	CO	11001	BUCKLES	A
9043	25.27	68.72	0.7	20337 *		NA	AZ	11001	REPLACED SEAT BELT	X
8	21.27	61.38	0.8	8521 *		NA	LA	11001	REPLACED SEATBELT ALL	X
1	53.98	128.81	1	8523 *		NA	CA	11001	OK	R
10	0	0	0	2518 *		NA	TX	11000	RECALL 01821 NOT LATCHING	B
7	28.05	28.2	0.2	3048 *		NA	TX	11001	REPLACED PASSENGER SIDE BUCKLE	B
13	28.05	77.58	0.7	5475 *		NA	CA	11001	REPLACE SUPER CREW BUCKET SEAT BUCKLE	B
								11001	INOP	B
								11001	REPLACE ONE SEAT BELT	X
									CCR DOES NOT OPERATE PROPERLY MILES IN 1785 MILES OUT 1787 TEST FRONT CENTER SEATBELT BUCKLE OPERATION FOUND BUCKLE WOULD NOT EXCEPT THE SEATBELT INSERT	
1786	27.81	72.53	0.7	4482 *		NA	TX	11001	INSPECTED BUCKLE FOR	X
8	53.55	117.87	1	4482 *		NA	TX	11001	REPLACED SEAT BELT BUCKLES	X
1980	28.05	73.67	0.7	3287 *		NA	CO	11001	REPLACED FRONT SEATBELT ASSY	R
15	23.98	78.32	0.4	328 *		NA	TX	11001	REPLACE SEAT BELT BUCKLE	R
7886	20.27	34.81	0.3	2319 *		NA	IA	11001	REPLACE PASSENGER BUCKLE, RT NO PUBLISHED LABOR OP	B
9	26.05	74.01	0.7	5821 *		NA	LA	11001	INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL, REPLACED SEAT BELT	R
4	53.55	132.31	1	7734 *		NA	CA	11001	CONFIRMED NEC TO REPLACE OY CORRECT	X

Year	MPG	MSRP	MPG	Model	Make	State	Problem Description	Code
8	27.51	88.82	0.6	8821 *	NA	LA	INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL, REPLACED SEAT BELT	11001 R
20	23.16	45.84	0.4	2220 *	NA	FL	BROKEN REPLACE LEFT SEAT BELT BUCKLE	11000 A
16	30.27	82.82	0.7	2811 *	NA	TX	REPLACED SEAT BELT WITH NEW	11001 A
1999	27.51	78.86	0.7	3788 *	NA	AZ	2008 VERIFIED PASS FRONT SEAT BELT RECEIVER IS INOP, REPLACED PASS SEAT BELT RECEIVER (40 SEAT BELT RECEIVER) NORMAL REPAIR SUBMISSION DELAYED DUE TO PARTS NOT AVAIL. REPAIR COMPLETED 6/13/02 AT	11001 X
2	40.88	100.06	0.9	8179 *	NA	WI	2008 M1 RIGHT SIDE BUCKLE NOT LOCKING IN TIME TO REPLACE RIGHT SIDE BUCKLE ASSY	12000 A
2003	28.06	53.83	0.4	20400 *	NA	AZ	1 REPLACED DRV. BUCKLE, R & R R & LF SEATBELT	11001 X
3	33.58	77.28	0.5	8188 *	NA	WI	BUCKLES, WPL	11001 X
8	28.06	78.78	0.7	5414 *	NA	CA	REPLACED SEATBELT BUCKLE	11001 X
2004	23.18	53.06	0.5	11840 *	NA	FL	VERIFY FAULTY SEAT BELT BUCKLE REPLACED RIGHT SIDE SEAT BELT NOW	11001 A
2000	20.27	78.54	0.8	2001 *	NA	TX	OPERATING PROPERLY SEAT BELT RECEPTACLE PASSENGER BELT WONT STAYED LATCHED CC 42 REPLACED PASSENGER	11001 B
11	20.27	41.48	0.4	8108 *	NA	MO	SEAT BELT	11001 B
10	8	28.88	0.4	2228 *	NA	OH	COMPLETE RECALL	11000 R
18	28.06	71.31	0.7	4728 *	NA	IN	MT; TIME TO REPAIR SEAT BELT BUCKLES ON SEATS. 01821B	11001 C
11	20.27	84.13	0.7	1088 *	NA	SD	01821B	11001 R
10	8	28.88	0.4	2228 *	NA	OH	COMPLETE RECALL	11000 R

RC04-011 07287

11110	41.00	100.07	0.0	0217 *	NA	MIN	11110 ORDERED SEAT BELT BUCKLE REMOVED OLD SEAT BELT AND INSTALLED NEW. TESTED AND FOUND GOOD.	X
1318	17.30	04.01	0.7	1032 *	NA	IL	SAFETY BELT CHINES INTERMITTENT REPLACED DRIVERS SIDE SAFETY BELT BUCKLE ASSEMBLY	X
20117	20.05	00.00	1	0005 *	NA	KY	TEST W NOS REPLACED 11001 SEAT BELT BUCKLE	X
10	20.27	00.00	0.7	2200 *	NA	OH	11001 01/01/01 COMPLETED	R
0	20.27	02.43	1.2	3000 *	NA	OK	REPLACED RIGHT FRONT SEATBELT BUCKLE	B
0013	17.30	00.72	0.7	0247 *	NA	MIN	4000 REPLACED SEAT BELT BUCKLE (NOT A RECALL)	A
7000	41.00	72.00	0.0	200 *	NA	AL	REPLACE RT FRONT SAFETY BELT BUCKLE ASSEMBLY. INOP INOP SEATBELT ASSEMBLY	X
1042	00.07	04.01	0.7	4040 *	NA	TX	11001 FRONT REPLACE	A
20	27.01	00.00	0.4	0000 *	NA	CA	0000L PERFORMED 01/02/01	R
13	00.00	100.00	1	0000 *	NA	CA	11001 SEATBELT RECALL SEAT BELTS WONT LATCH	A
00	27.01	74.00	0.7	0011 *	NA	TX	11001 REPLACE SEAT BELTS REPLACED SEAT BELT WITH NEW	A
0001	27.01	71.00	0.7	4074 *	NA	NM	BUCKLE JAMMED, WILL NOT ACCEPT BUCKLE TONGUE. REPLACE BELT ASSY.	A
10	00.00	100.00	1	0000 *	NA	CA	11001 SEAT BELTS WILL NOT LATCH REPLACE SEAT BELTS	A
7	27.01	04.00	1.0	0001 *	NA	WI	11001 REPLACED THE RIGHT SIDE SEATBELT BUCKLE THAT DOES NOT LATCH.	A
7	27.01	100.00	1.2	0044 *	NA	VA	11001	X
7000	10.00	44.41	0.4	00400 *	NA	AZ	12001 REPLACED SEATBELT. 1	X
0077	27.01	07.4	0.0	7000 *	NA	CA	BELT R OR BRKING PASSENGER FRONT BELT BUCKLE	X

							DEFECTIVE VERIFY CONCERN. INSTALL SPECIAL ORDERED SEAT BELT BUCKLE AND BOLT	
8	28.31	85.84	0.7	7826 *	NA	CA	11001	X
14340	27.51	75.48	0.7	2489 *	NA	TX	11001	A
10	27.51	78.04	0.7	8512 *	NA	CA	11001	R
3014	20.27	48.23	0.4	2483 *	NA	TX	11001	A
1418	28.08	48.01	0.4	325 *	NA	TX	11001	X
4730	28.05	83.43	0.8	7945 *	NA	CA	11001	X
15	28.05	72.43	0.7	4870 *	NA	FL	11001	X
14488	41.88	108.52	1.1	8373 *	NA	TX	12000	A
772	0	48	1	1437 *	NA	SC	11800	X
6597	17.38	41.13	0.4	4862 *	NA	FL	12001	X
3098	41.28	71.73	0.3	8032 *	NA	AR	12000	B
5	48.32	125.07	1	7734 *	NA	CA	11001	X

	8	27.51	63.25	0.5	2577 *	NA	CA	11001	REPLACED RIGHT SIDE SEAT BELT BUCKLE PER 01821.	R
	1558	17.35	64.41	0.7	3042 *	NA	TX	12001	DAMAGED WIRE ON SEAT BELT BUCKLE REPLACED SEAT BELT BUCKLE ON DRIVER SIDE SEAT	X
	2	46.32	125.57	1	7784 *	NA	CA	11001	NEED TO REPLACE BOTH TO CORRECT	X
	7284	41.59	55.99	0.3	4235 *	NA	ND	12000	CK OUT REPLACE BUCKLE	A
	4912	41.89	51.59	0.4	4235 *	NA	ND	12000	CK OUT REPLACE BAD LATCH ASSY	X
	12508	27.51	62.01	0.5	4235 *	NA	ND	11000	CK OUT REPLACE BAD SEAT BELT	X
	6	33.25	84.09	0.7	3229 *	NA	NJ	11001	REPLACED DRIVERS SEAT BELT	X
	14	27.51	64.52	0.4	4880 *	NA	FL	11001	14 VERIFIE FOUND PASS SEAT BELT INOP	X
	18	20.27	85.82	0.7	2511 *	NA	TX	11001	REPLACED SEAT BELT WITH NEW	A
	10	53.58	129.88	1	8839 *	NA	CA	11001	SEAT BELTS WONT LATCH	A
	40	47.78	200.82	2	5538 *	NA	CA	12001	REPLACE SEAT BELTS	X
	13	53.58	87.86	0.7	4570 *	NA	TX	11001	SEATBELTS WONT LATCH PROPERLY REPLACE	X
	2880	41.59	57.12	0.2	1412 *	NA	CA	12000	INSTALLED GOP SEAT BELT BUCKLE	X
	4178	87.51	80.47	0.7	1412 *	NA	GA	11000	REP BUCKLE ASSY	A
	10	53.58	122.34	0.9	8838 *	NA	CA	11001	SEAT BELTS WONT LATCH	A
	8051	27.51	40.5	0.2	2417 *	NA	TX	11000	REPLACE SEAT BELTS	A
	8030	17.35	54	1.3	485 *	NA	GA	12001	8851 REPLACED PASSENGER SEAT BELT LATCH + TEST. *** QUALITY CONTROL BY JOHN	A
	12	53.58	188.47	1.7	8838 *	NA	CA	11001	MEDROW *** CHECKED AND REPLACED LEFT FRONT SEATBELT BUCKLE TO CORRECT CONCERN.	X
	8588	41.59	75.8	0.5	5027 *	NA	AR	12000	SEAT BELTS WONT LATCH REPLACE SEAT BELTS CENTER BELT BUCKLE WONT LATCH TIME IN TO R/R NEW CENTER SEAT BELT BUCKLE ASSY.	A

16763	0	10.2	0.2	7016 *	NA	NC	11000 MIT TO REINSTALL CLIP	X
17076	26.06	50.00	0.4	4906 *	NA	FL	REPLACED DRIVER SIDE 11001 SEATBELT	C
18487	41.80	76.18	0.5	6113 *	NA	MO	REPLACE PASSENGER 12000 FRONT SEAT BELT BUCKLE REMOVE HAD REPLACE FAIL R.F SEAT BELT BUCKLE END RELEASE	X
26	27.51	87.20	0.7	7777 *	NA	CA	11001 ABBY.	A
10	62.50	114.7	0.8	5630 *	NA	CA	REPLACE SEATBELTS WILL 11001 NOT LATCH PROPERLY	X
13188	26.05	50.00	0.5	6416 *	NA	CA	REPLACE SEAT BELT 11001 BUCKLE. WILL NOT LATCH REMOVE RIGHT SEAT TO REPLACE RIGHT BUCKLE	A
3	16.53	64.50	0.7	6432 *	NA	CA	12001 PER RECALL SEAT BELTS WONT LATCH	R
12	53.06	120.06	1	5528 *	NA	CA	11001 REPLACE SEAT BELTS	A
5004	17.20	27.04	0.2	7563 *	NA	AR	ADDITIONAL MISC REPAIRS DO NOT USE WITH ANY OTHER 12001 LABOR OPERATIO N BUCKLE WILL NOT LATCH	A
9980	27.51	51.3	0.4	6485 *	NA	LA	REPLACED CENTER SEAT 11001 BELT BUCKLE REMOVED DRIVERS SIDE SEAT REPLACED SEAT BELT LATCH FOR HARD TO	X
16074	17.20	48.06	0.7	5237 *	NA	MO	12001 UNLATCH	X
9034	25.00	51.3	0.4	6900 *	NA	LA	11001 REPLACE DR SEATBELT CHECK AND REPLACE SEATBELT BUCKLE PER	B
5	26.06	63.43	0.7	6217 *	NA	WI	11001 RECALL DRAG INSP VERIFIED CONCERN M TIME TO REPLACE SEAT BELT	R
11	27.51	73.99	0.6	7704 *	NA	CA	11001 BUCKLE CHECK SEAT BELT OPERATION WILL NOT LATCH NCC TO REPLACE	X
21257	25.06	52.94	0.6	3627 *	NA	TX	11001 SEAT BELT LATCH REPLACE LEFT PRT SEAT	A
12	43.94	68.46	0.4	6513 *	NA	MN	12001 BELT WILL NOT LATCH	A

8408	25.05	84.84	0.8	4241 *	NA	TX	1 REMOVED AND REPLACED LEFT FRONT SEAT BELT	
8	25.05	87.13	0.7	429 *	NA	AL	11001 BUCKLE,RECHECKED OK REPLACED LEFT FRONT SEAT BELT BUCKLE	A R
1807	25.05	175.85	0.7	7729 *	NA	CA	REPLACED DRIVERS SEAT BELT BUCKLE	X
12	25.05	52.95	0.4	3648 *	NA	TX	SEAT BELT BUCKLE WILL NOT LATCH	A
7398	27.81	53.47	0.4	2290 *	NA	OH	INSPECTED AND DOES NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT BUCKLE AND	
8020	41.99	105.89	1	2292 *	NA	OH	RETESTED OK.	X
10638	28.05	89.5	0.7	7199 *	NA	IA	BUCKLE WILL NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT BUCKLE.	A
10	63.58	188.19	1.8	5538 *	NA	CA	REPLACED DR SIDE SEAT BELT DUE TO INSIDES	C
10	28.05	78.58	0.7	6612 *	NA	CA	11001 COMB OUT AT TIMES SEAT BELTS WONT LATCH	A
9890	41.99	81.48	0.3	2482 *	NA	TX	REPLACE LEFT SEATBELT	A
4	28.05	82.48	0.7	8217 *	NA	WI	BUCKLE D BUCKLE WILL NOT LATCH	A
4	25.05	71.31	0.7	402 *	NA	GA	FRONT RIGHT BUCKLE	A
18036	25.05	111.87	1.3	4479 *	NA	TX	12000 ASBY CHECK AND REPLACE LEFT	A
18	27.81	80.47	0.4	329 *	NA	TX	FRONT SEATBELT	X
3	47.78	112.43	1	402 *	NA	GA	REPLACED D SIDE SEAT BUCKLE	R
28138	17.98	63.36	0.7	4484 *	NA	TX	BCE DIAG, PINPOINT, REPLACED BUCKLE ASBY AND RETEST	X
10	27.81	88.03	0.8	2895 *	NA	FL	REPLACE SEAT BELT BUCKLE	X
856	17.98	86.48	0.7	4357 *	NA	TN	RECALL 01821 RECALL REPLACE SEAT BELT BUCKLE	R
							INOP SEATBELT ASSEMBLY	
							11000 FRONT REPLACE BROKEN	X
							REPLACE SEATBELT BUCKLE	A
							REPLACE SEATBELT SENSOR	
							12001 SEATBELT SENSOR	X

10024	25.05	54.21	0.4	6230 *	NA	CA	10024 M TIME , 8 M TIME NO OPS FOR SUPER CREW TO REPLACE DRIVERS SEAT BELT BUCKLE. BUCKLE IS INTERNALLY JAMMED CC	11001 BY TECH	A
8278	28.05	45.1	0.3	7192 *	NA	ME	2278 BASID 7861203 CONDITION 41 REPLACED THE INTERMITTANTLY STICKING L F SEATBELT	11001 BUCKLE	A
91802	28.05	65.51	0.0	478 *	NA	GA	31802 O K RMR LT FT SEAT TO REPLACE SEAT BELT VOC INSPECTED SEAT BELT FOUND THAT THE BUCKET WAS JAMMED. REMOVED FRONT SEAT AND REMOVED AND REPLACED LEFT FRONT SEAT BELT. CHECKED TO	11001	X
8808	43.34	110.67	1.8	2874 *	NA	TX	VERIFY REPAIR	12001	X
15	20.27	66.82	0.7	2511 *	NA	TX	REPLACED SEAT BELT WITH NEW	11001	A
4	28.05	108.11	1.1	3417 *	NA	CA	81	11001	A
10	0	28.88	0.4	2226 *	NA	OH	REPLACE BUCKLE	11000	R
11	25.27	89.00	0.8	4570 *	NA	TX	COMPLETE RECALL	11001	X
16	20.27	66.82	0.7	2511 *	NA	TX	1 REPLACE RIGHT FRONT SEAT BELT.	11001	A
30	20.27	48.16	0.4	1472 *	NA	TX	30 01521 O 0.4 INSP AND SPPL P SIDE SEAT BELT	11001	R
10	0	28.88	0.4	2226 *	NA	OH	COMPLETE RECALL VERIFY CONCERN FOR SEAT BELT RELEASE BUTTON STICKS. REMOVED & REPLACED SEAT BELT	11000	R
12588	26.05	48.57	0.4	812 *	NA	TX	BUCKLE.	11801	X
							1127 RAN M88 TO CHECK FOR CODE NO CODE. RAN ON DEMAND TEST PASSED. RAN FINPOINT CHECK SEAT BELT BUCKLE SWITCH AND FOUND ITS STICKING INTERMITTENTLY. REMOVE DRIVER SEAT. REPLACE DRIVER SEAT	12001	X
1127	16.89	80.1	1	4454 *	NA	TX	BELT BUC		KLE. RETEST,OK WFA

17381	28.05	39.84	0.2	20323 *	NA	AZ	11001	NGS BCE TEST NO CODES MONITORED PIDS FOUND DRIVERS BELT BUCKLE STUCK OPEN AND NOT WORKING PROPERLY RBR BUCKLE TESTED OPERATION GOOD	X
333	14.11	38.89	1.5	88802 *	NA	ON	12001	R & I LEFT FRONT SEAT & REPLACE BELT BUCKLE.	A
1281	28.05	108.57	1.4	20341 *	NA	NM	11001	FLIN WDS, PID MONITOR, DRIVERS SEATBELT NOT CORRESPONDING WITH ACTION GIVEN. REMOVE DRIVERS SEAT TO CHECK CONNECTIONS, GOOD. WDS TO CHECK SEATBELT MODULE ACTION, GOOD. COMPONENT TEST SEATBELT FAILED. R	EPLACED DRIVERS SEATBELT BUCKLE, OK AT THIS TIME. X
1882	43.34	86.07	0.8	8151 *	NA	WI	12001	RAN TESTS ON SYSTEM AND FOUND THE BUCKLE BAD ORDERED A NEW BUCKLE WE WILL CALL WHEN THE PART COMES IN REPLACED THE SEAT BELT BUCKLE OK NOW TESTED AND	X
3254	41.88	94.48	0.7	8808 *	NA	OR	12000	VERIFIED/REPLACED FAILED BUCKLE.	A
6717	27.51	98.87	0.8	8853 *	NA	OR	11001	6717 FEMALE END BROKEN W INSPECTED SEAT BELT AND FOUND IT BROKEN. PARTS ON ORDER FROM FORD. STILL WAITING ON RIGHT PARTS. PARTS CAME IN. RAN MIDDLE BELT FEMALE END. TESTED OK.	X
10	0	28.88	0.4	3235 *	NA	OH	11000	CHECKED ALL OTHER BEL. TB, OK. COMPLETE RECALL.	R
7	28.05	48.46	0.4	4893 *	NA	TX	11001	SEAT BELT BINDING. OK. OP OF SEAT BELT INTERMITTENT BINDING. REPLACE SEAT BELT ASSY.	D
14	27.81	60.47	0.4	323 *	NA	TX	11001	REPLACE SEAT BELT BUCKLE	X

10	0	28.08	0.4	2238 *	NA	OH	11000 COMPLETE RECALL	R
1488	25.05	73.45	0.7	543 *	NA	TX	11001	X
6308	17.39	50.29	0.5	2091 *	NA	TX	12001	C
32388	28.05	75.34	0.7	1230 *	NA	PA	11001	A
13589	28.05	88.08	1	5009 *	NA	MO	11001	X
3767	21.85	83.28	0.2 B9477	-	NA	OH	11001	X
2848	41.99	78.19	0.5	2279 *	NA	OH	12006	A
8469	30.87	80.13	0.8	5884 *	NA	AR	11001	A
13028	27.81	85.39	0.9	4315 *	NA	TX	11001	A
12626	0	12.46	0.2	4817 *	NA	TX	11000	X
12000	26.05	58.88	0.8	4448 *	NA	TX	11001	X
280	0	11.18	0.9	6418 *	NA	LA	01100X	X

VERIFIED CONCERN, SEAT BELT BUCKLE INOP, REPLACED LEFT FRONT SEAT BELT BUCKLE, FIXED VEHICLE
 SEAT BELT BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE
 13589 283 CHECK FOR CODES WITH WDS FOUND NO CODES PERFORMED ON DEMAND TEST FOR SEAT BELT FOR BENDER INTERMITTING IN SEAT BELT ORDERED SEAT BELT PART DID NOT HAVE PER MARK C 283 283 REMOVED
 SEAT AND
 INSTALL REAR SEATBELT. REPLACE SEAT BELT BUCKLE
 SEAT BELT RELEASE BINDING SEATBELT ASSEMBLY FRONT
 REPLACE INOPERATIVE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT
 REPLACE CENTER SEAT BELT NOT BOLTED TOP FLOOR 42
 INSTALL CENTER SEAT BELT AND LIGHT STAY ON
 REPLACED SEAT BELT BUCKLE DRIVER SIDE POOR CONNECTION AT SEAT BELT CONN CLEAN AND RECONNECT SEAT BELT CONNECTOR DRIVERS SIDE
 INSTALL NEW SEAT BELT WORKING CORRECT 283 WORK ALREADY BEEN DONE 385

								INSP RECEIVERS, PASS. SIDE DEFECTIVE. REPLACED BUCKLE, CHECKED OPERATION, MIDDLE LAP BELT HAD INCORRECT BELT. REPLACE BELT AND	
1022	88.02	123.78	0.7	4410 *	NA	TX	12000	FRIBST BELT OPERATION	R
18000	28.08	63.18	0.7	1080 *	NA	SC	11001	REPLACED DRIVERS SIDE SEATBELT BUCKLE	X
								SEAT BELT ALARM WAS GOING OFF WHEN SEAT BELT WAS PLUGGED IN, REPLACED DRIVERS SIDE	
2348	25.05	51.05	0.4	2824 *	NA	TN	11001	SEAT BELT LATCH.	X
								3788 812815 BUCKLE, 42 DINOZ CONFIRMED CONCERN OF PASSENGER SIDE SEAT BELT BUCKLE INOP ON 6040 SPLIT SEAT. REPLACED PASSENGER SIDE BUCKLE ASY. CLUST CONCERN NO LONGER	
2788	41.88	77.27	0.5	8017 *	NA	MO	12800	PRESENT.	A
								VERIFIED CONCERN, FOUND ALL THREE SEAT BELT BUCKLES IN REGULAR CAR FAILED SEAT BELT BUCKLE TESTS. REPLACED DRIVER SIDE, PASSENGER, AND CENTER SEAT BELT BUCKLE ASSEMBLIES. RETESTED	
8848	76.18	157.88	1.2	2511 *	NA	TX	11008	NORMAL AFTER REPAIRS OUT OF ADJUSTMENT	D
1432	0	10.34	0.2	1734 *	NA	AR	11008	ADDITIONAL MISC. REPAIRS	X
								1881 LOOSE REPLACE LOOSE LF SEAT BELT BUCKEL ---QUALITY CONTROL BY JAMES	
1881	26.06	38.34	0.2	2417 *	NA	TX	11007	PENNOCK---	D

RC004-011 07286

632	48.32	78.84	0.5	2417 *	NA	TX	11001	ISS NOT STAYING LATCHED REPLACED BOTH FRONT SEAT BELT BUCKLES DUE TO NOT STAYING LATCHED. ***QUALITY TESTED BY LOUIS TREMINO*****	B
8407	41.89	83.44	0.7	20330 *	NA	AZ	12000	42 TEST SEAT BELT BUCKLE INTERMITTENTLY NOT LOCKING CHANGED SEAT BELT OUT	A
8407	41.89	83.44	0.7	20330 *	NA	AZ	12000	62 6PW R&R SEAT BELT BUCKLE	X
11880	40.08	88.13	0.7	20337 *	NA	AZ	11000	BROKEN CC 01 REPLACED CENTER SEAT BELT	A
8400	28.06	82.11	0.4	8947 *	NA	TX	11001	REPLACED SEAT BELT BUCKLE	X
9	0	0	0	20428 *	NA	NM	11000	REMOVED PASSENGER BELT ONTO VEHICLE ST4087 TO FINISH DRIVER'S FAILED INSTALLED DRIVER BELT INSTALLED BELT ON PASSENGER SIDE THAT WAS ORDERED TECH 614	R
24	28.06	88.81	0.7	1900 *	NA	OH	11001	REPLACED DRIVER SIDE SEAT BELT BUCKLE	B
48	27.51	72.37	0.7	8180 *	NA	WI	11001	46 SEAT BELT BUCKLE REMOVED RIGHT FRONT SEAT BELT BUCKLE FROM STOCK UNIT # 121118 AND REINSTALLED IN VEHICLE. HAD TO ORDER SEAT BELT BUCKLE FOR # 121118	X
5	27.51	72.82	0.8	8401 *	NA	CA	11001	01821 O SEAT BELT BUCKLE REPLACED PASS. SEAT BELT BUCKLE	R
16301	27.51	82.85	0.8	3282 *	NA	TX	11001	CC 01 6PW 78812818 PASSENGER SEAT BELT BUCKLE WOULD NOT STAY LATCH. REPLACED BUCKLE AND RETEST PROVED OK.	D

Year	Month	Days	Hours	Minutes	Seconds	State	City	Code	Description	Notes
12	42	125.00	1.2	20837 *	MA	AZ	12001	OPEN CIRCUIT IN DRIVERS SEAT BELT ASSEMBLY NISS TEST PID MONITOR AND RECORD REMOVED DRIVER SEAT AND SEAT BELT ASSEMBLY	INSTALLED NEW ONE	X
2880	18.83	148.81	2	7212 *	NA	MA	12001	CHECKED CODES, NONE IN RESTRAINT SYSTEM. LIGHT FLASHED WITH BELT BUCKLED. CHECKED PIDS, ORDERED LEFT SEAT BELT LATCH ASSY. REPLACED LATCH ASSY WHEN PARTS CAME IN.	DIAGNOSE SEAT BELT LIGHT ON OPEN IN SEAT BELT BUCKLE ASSY R & L SEAT ASSY TO ACCESS AND REPLACED SEAT BELT BUCKLE ASSY	X
10013	28.05	72.74	0.7	1467 *	NA	NM	11001	CODE 28 SEAT BELTS WILL NOT LATCH PROPERLY	REPLACE SEATBELT	C
18	28.55	101.12	1.5	5230 *	NA	CA	11001	REPLACE BELT AND BUCKLE ASSY	BUCKLE MOP R R L H	X
5806	28.05	108.21	1.2	4437 *	NA	TX	11001	BUCKLE MOP R R L H	BUCKLE	A
18428	40.98	80.88	0.8	20307 *	NA	NM	11000	CHECK AND R AND R THE LF SEAT BELT BUCKLE	ASSY	X
3772	28.05	48.24	0.4	3374 *	NA	PA	11001	CHECK AND DIAG CONCERN REPL L F SEATBELT ASSY. RECHECK	OK NOW	X
2788	43.34	98.37	1	1831 *	NA	PA	12001	NBO TO REPLACE BOTH TO CORRECT	1 CHECK DRIVERS SEATBELT BUCKLE IS INTERMITTING MOP. REPLACE DRIVERS SEAT BELT BUCKLE.	X
7	53.58	92.94	0.5	7734 *	NA	CA	11001	RECALL REPLACE FEMALE END OF SEATBELT		X
12880	28.05	80.18	0.4	2452 *	NA	TX	11001			A
8885	28.05	32.55	0.4	3854 *	NA	FL	11001			X

4034	28.05	103.07	1.1	20305 *	NA	AZ	11001	DIAG GEM MODULE PINPOINT SYSTEM PASS (NO CODES) MONITOR BUCKLE PIN IS NOT SWITCHING REPLACE L.F SEAT BELT BUCKLE INOP	X
4686	28.05	88.78	0.8	3139 *	NA	CO	11001	WARNING SWITCH FAILURE TEST SYSTEM AND REPLACE DRIVERS SIDE SEATBELT BUCKLE 114 CHECK LEFT FRONT BELT BUCKLE HAS BRAKEN LATCH ME CHANISM REPLACE LATCH	X
114	18.93	48.08	6.4	8311 *	NA	WA	12001	ASSEMBLY AIR BAG RESTRAINT SYSTEM DIAGNOSIS DO NOT USE WITH OPERATION 128610 PINCHED DAMAGED WIRE BODY CHASSIS ELECTRAL (BCE) TEST	A
5201	28.05	100.49	1.5	903 *	NA	NC	11001	REPLACE SEAT BELT ASY	X
328	28.05	108.2	1.3	975 *	NA	NC	11001	REPLACE SEAT BELT ASY	X
582	41.98	65.2	0.4	652 *	NA	NY	12000	VERIFIED CUSTOMERS COMPLAINT, FOUND RIGHT SIDE SEAT BELT BUCKLE NOT CATCHING. REPLACED SEAT BELT BUCKLE.	A
18302	28.08	77.91	0.7	8880 *	NA	CA	11001	VERIFIED REPAIR FRONT BELT BUCKLE DOES NOT LOCK SEATBELT ASSEMBLY FRONT	A
505	48.34	148.74	1.8	3485 *	NA	TX	12001	REPLACE BUCKLE WAS SHORTED OUT. ABNORMAL DIAG. NBS TEST, PIN POINT TEST. TRACE THE WIRING FROM THE SEAT AREA TO THE GEM MODULE. ALL OF THE WIRING WAS	X
4575	28.05	78.51	0.5	182 *	NA	GA	11001	PINPT TEST PER MANUAL FOUND BUCKLE BAD RMR BUCKLE AND REPLACE	X
553	28.05	112.91	1.2	8838 *	NA	VA	11001	INSPECT TEST AND MONITOR AND REPLACE BUCKLE ASSY AND RETST	X

1188	27.51	52.12	0.4	4416 *	NA	TX	11001	1188 REPLACE PASS SIDE SEAT BELT BUCKLE R AND L LEFT SEAT BELT BUCKLE AND REPLACE	A
30471	28.05	58.88	0.7	20344 *	NA	NM	11001	0 CUSTOMER STATES SEAT BELT WILL NOT ENGAGE CONFIRMED CUSTOMER'S COMPLAINT SEAT BELT WILL NOT ENGAGE DUE TO SEAT BELT RETAINER IS JAMMED. REPLACED RETAINER AND CHECKED OPERATION O.K.	A
14888	41.88	73.88	0.5	861 *	NA	NY	12000	INSTALLED ORDE 10888 VERIFY CUSTOMER COMPLAINT. INSPECT RT FT SEAT BELT BUCKLE FOUND LATCH IN BUCKLE BAD. REMOVE AND REPLACE RT FT SEAT BELT BUCKLE. O.K.	FED SEAT BELT AND CHNBECKED OPPER O.K. A
10388	27.51	40.78	0.2	4017 *	NA	FL	11001	10888 REPLACE RT FT SEAT BELT BUCKLE. O.K.	A
8884	41.98	78.94	0.7	4329 *	NA	TX	12000	PASS. SEATBELT INOP SEATBELT ASSEMBLY FRONT REPLACE CHECK FOR RECALLS, NO RECALLS. SAFETY BELT LATCH SWITCH NOT WORKING PROPERLY,	A
3981	28.05	58.01	0.4	4408 *	NA	TX	11001	REPLACE SEAT BELT REPLACE SEAT BELT	X
5837	23.07	52.08	0.7	88070 *	NA	ON	11001	RELEASE ON RIGHT SIDE 7896 STICKING 81172AS A	A
7876	27.81	53.38	0.4	1472 *	NA	TX	11001	AD REPLACED R.F SEATBELT BUCKLE PASSENGER SIDE SEAT BELT FAILED, REPLACED SEAT BELT	X
7888	20.27	58.08	0.6	1472 *	NA	TX	11001	SEAT BELT	X
4005	41.98	94.81	0.7	9331 *	NA	MN	12000	1 REPLACED RIGHT FRONT SEAT BELT BUCKLE SEATBELT INOP.	X
7590	41.98	80.88	0.7	8008 *	NA	MO	12000	REPLACED RIGHT FRONT SEAT BELT BUCKLE.	X
13707	55.02	104.02 *	0.7	8008 *	NA	MO	11001	FRONT CENTER SEATBELT INOP. REPLACED FRONT CENTER SEATBELT AND BUCKLE.	X

							OKD AND FOUND SEATBELT WARNING CHIME STAY ON TESTED AND FOUND SEAT BELT BUCKLE SWITCH MOP R AND R BUCKLE AND	
7330	28.05	57.52	0.5	7888 *	NA	TN	11001 RETEST OK	X
							C SEAT BELT ASSEMBLY REAR	
2888	41.88	101.17	0.8	247 *	NA	GA	12000 RIGHT OR LEFT REPLACE	A
13288	38	53.52	0.8	3844 *	NA	CA	REPLACE SEAT BELT BUCKLE	A
882	17.58	77.14	0.7	7777 *	NA	CA	NEC OT REPLACE SEAT BELT	X
13	40.58	147.57	1.4	5536 *	NA	CA	SEAT BELT WONT LATCH	
							11000 REPLACE SEATBELT	A
							RFR SEAT TO REPLACE SEAT BELT ASSY INTERNAL	
6853	28.05	52.35	0.4	4448 *	NA	TX	11001 FAJ LURE	X
							12 REDALL 012210 0.4 HRS TECH 5170 INSPECT &	
3	28.05	75.34	0.7	5530 *	NA	CA	REPLACE DRIVERS SEAT BELT	R
17188	28.05	78.17	0.8	772 *	NA	OK	11001 REPLACE BELT BUCKLE ASSY ON DRIVERS SIDE	X
							INSPECT RIGHT FRONT SEAT BELT FOR WILL NOT BUCKLE. NEED BUCKLE SPRING IS JAM , REMOVE AND REPLACE SEAT BELT	
7088	41.88	88.52	0.5	7882 *	NA	CA	12000 BUCKLE DONE	A
							CHECKED FOR CODES PP TEST LEAD TO OPEN CIRCUIT AT DR SIDE BELT	
150	18.53	58.38	1	5385 *	NA	CA	12001 BUCKLE	X
4363	27.81	60.38	0.7	7885 *	NA	CA	11001 CHECK AND REPLACE BUCKLE	X
							NOT WORKING PROPERLY SEATBELT ASSEMBLY	
3	28.05	72.74	0.7	1457 *	NA	NM	11001 FRONT REPLACE	A

10330	26.06	280.63	2.7	3628 *	NA	CA	11001	VERIFIED CONCERN,REMOVED DRIVERS SEAT FOR ACCESS SUSPECTED WIRING FROM BUCKLE UNDER CARPET,FD W IRING INSULATION CUT SHORTED CUT BUCKLE,ORDERED NEW BUCKLE,VEHICLE SAFE TO DRIVE INSTALLED		
4288	27.61	59.8	0.4	30443 *	NA	AZ	11001	NEW BUC RIGHT FRONT SEAT BELT BUCKLE BINDING. REPLACE. RETEST. OK	KLE ABBY.RETESTED OK	X
11358	26.06	113.86	1.3	3608 *	NA	GA	11001	SEAT BELT CHIME STAYS ON ALL THE TIME WARR. CO SS TECH 108212 RELEASE CUT 1 1388 TEST WITH NOSS KOED NO CODES MONITOR PIDS FOUND DRIVERS SEAT BELT ON UNLATCHING LATCHED REPLACE DRIVERS SEAT BELT BUCKLE NOTE	BT	X
6177	26.06	66.32	0.6	1019 *	NA	TX	11001	SS RPL DRIVERS SEATBELT BUCKLE FOR OPEN RETEST		X
13	16.83	66.86	0.7	3864 *	NA	MO	12001	13 REPLACED SO SEAT BELT BUCKLE. CC SMC SS OPEN CIRCUIT. DIAGNOSIS TESTING WITH WDS ON SEAT BELTS AND CIRCUIT. SEFT TESTS.UTO ON DRIVER SIDE BELT		X
5577	26.06	66.41	1.1	33807 *	NA	NM	11001	CIRCUIT,OPEN AT TIMES. REPLACE RIGHT FRONT SEAT BELT BUCKLE		B
18900	20.27	48.27	0.4	20328 *	NA	AZ	11001	DIAG WHY RIGHT SEAT BELT WONT UNLATCH BUCKLE IS BROKEN REPLACE RIGHT FRONT SEAT BELT ASSEMBLY		A
1758	27.61	73.15	0.7	7714 *	NA	CA	11001	REPLACED THE SEAT BELT BUCKLE		X
1848	26.06	66.86	0.5	7888 *	NA	CA	11001	SEAT BELT CHIME REPLACE DRIVER BELT		X
10791	26.06	182.88	2.3	1854 *	NA	CA	11001	ABBY		X

4073	26.05	50.82	0.4	7873 *	NA	CA	11001 SEAT BELT REPLACED SEAT BELT BUCKLE	C
10183	26.05	43.76	0.3	1148 *	NA	TN	11001 10183 BELL RINGS FMR SEAT BELT BUCKLE ON DRIVERS SEAT 88 4811	X
838	27.51	21.94	0.9	5100 *	NA	MO	11800 INSTALL SEAT BELT	X
8390	28.05	125.24	1.5	5422 *	NA	CA	11001 NGS TEST NO CODE PINPOINT TEST, REPLACED SEAT BELT BUCKLE WIRING SHORTED TO SEAT TRACK IN TIME IS FOR REPLACING BUCKLE	X
8857	28.05	125.24	1.5	4118 *	NA	MO	11001 SEAT BELT PRETENSIONER BAD MIT TIME NGS TEST PID MONITOR R & R DRIVERS SEAT BELT BUCKLE	X
4488	17.38	76.33	0.8	4511 *	NA	TX	12001 4488 01202,01 BROKEN R R PASS FRONT SEAT REPLACED PASS SEAT BELT BUCKLE TEST,OK SEATBELT	X
16304	28.05	72.08	0.7	388 *	NA	GA	11001 SEATBELT ASSEMBLY FRONT REPLACE SEAT BELT ALARM INTERMITTENT AIR BAG RESTRAINT SYSTEM	A
8750	28.05	173.17	2	20573 *	NA	NY	11001 DIAGNOSIS	X
8451	35.24	82.82	0.8	8888 *	NA	AB	12000 REPLACE PASS SIDE SEAT BELT BUCKLE HAD TO SWITCH CENTRE BUCKLE OVER TO WORK IN NEW BUCKLE ASSEMBLY CHECK OPERATION AFTER REPAIR ALL O.K.	A
10454	17.38	30.85	0.2	4943 *	NA	FL	12001 10454 MO IN BUCKLE ELECT OK AND REPL DRIVERS SEAT BELT BUCKLE AND RECK	X

3341	41.89	87.15	0.4	4496 *	NA	TX	3341 SEAT BELT BUCKLE BROKEN ON WRT PERFORMED VERIFIED CONCERN AND PERFORMED REMOVED AND REPLACE SEAT BELT BUCKLE ADMP PART ORDERED	12000	X
215	28.05	58.4	0.5	1472 *	NA	TX	REPLACED L F SEATBELT BUCKLE. RETEST OK 8484 SEAT BELT LAMP FLASHING CHECKED AND VERIFIED SEAT BELT LAMP FLASHING WHEN SEAT BELT WAS LATCHED. PERFORMED NOIS HOOKUP. ACCESSED RESTRAINT MODULE AND PERFORMED SELF TESTS. ACCESSED GEM MODULE	11001	A
8415	28.05	116.43	1	7277 *	NA	CA	AM	11001	O PERFORMED SELF TESTS. FOUND NO DTCs PRESENT. PERFORMED VISUAL INSPECTION TO WIRING, CONNECTORS AND SEAT BELT SWITCH. DUE TO TIME CONSTRAINTS, PROBABLE CAUSE AND CUSTOMER
8023	28.05	84.57	0.7	8385 *	NA	LA	REPLACE FRT SEAT BELT BUCKLE	11001	A
12782	20.27	82.85	0.8	5298 *	NA	KS	42 REPL PASS SIDE SEATBELT BUCKLE	11001	A
2497	41.89	80.72	0.7	5287 *	NA	MI	BROKEN LATCH RT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE	12000	A
348	18.83	35.82	0.4	1179 *	NA	NC	REPLACED SEAT BELT BUCKLE	12001	X
12863	41.89	80.01	0.7	4373 *	NA	TX	VERIFIED CONCERN R R SEAT BELT BUCKLE TO FIX CONCERN ...	12000	X
10281	28.05	75.08	0.7	20308 *	NA	AZ	RR SEATBELT BOP	11001	X
3822	80.42	153.44	1.2	11087 *	NA	ND	8222 REMOVE REAR SEAT, REPLACE THE SEAT BELT BUCKLES REMOVE FRONT SEATS AND TURN TO THE SIDE, REPLACE BOTH FRONT SEAT BELT BUCKLES. RIGHT REAR BUCKLE WAS BROKE AND THE REST WERE STICKY	12041	X
10808	27.51	84.01	0.7	8803 *	NA	ME	10808 REM AND REP SEAT BELT BUCKLE	11001	X

1017	53.58	132.03	1	4485 *	MA	TX	11001	BRIDING BUCKLES. RM BOTH FRONT SEATS TO REPL BOTH SEAT BELT BUCKLES. REPLACE SEAT BELT BODY CHASSIS	A
7813	38.05	90.18	1	4485 *	MA	TX	11001	ELECTRICAL (BICE) TEST REPLACE DRIVER SEAT BELT BUCKLE W/PI	X
8021	18.8	68.98	0.7	518 *	MA	IL	11000	INSPECTED AND REPLACED DRIVERS SIDE SEATBELT BUCKLE AND RETESTED OK	X
7448	26.05	47.35	0.4	7578 *	MA	TN	11001	20041 VERIFY CUSTOMER CONCERN, TIME TO REMOVE PASSENGER SEAT TO GAIN ACCESS. TIME TO REPLACE PASSENGER SIDE SEAT BELT BUCKLE	X
23834	20.27	65.41	0.7	8192 *	MA	TX	11001	CCC 888 RIGHT FRONT SEAT BELT WONT LATCH, REMOVED SEAT REPLACED BUCKLE FOR BEING BROKEN, WORKING PROPERLY AFTER REPAIRS.	O
14880	30.27	68.87	0.7	80505 *	MA	AZ	11001	FOUND DRIVERS SEATBELT BUCKLE INTERMITTENTLY OPEN AND PARI BUCKLE TO CORRECT, RETEST OK	A
5159	27.51	83.34	0.7	3838 *	MA	TN	11001		X
15358	26.05	87.81	0.5	8508 *	MA	MN	11001	12889 REMOVED CENTER CONSOLE REMOVED DRIVER SIDE BUCKLE PART THAT ON ORDER WAS OK. INSTALLED RECALL BUCKLE WE HAD IN STOCK WIRE ON RECALL UPDATED BUCKLE WAS 1 IN LONGER. SHORTENED WIRE AND RETEST	ED OK A
6018	53.98	112.24	1	429 *	MA	AL	11001	R & R BOTH FRONT SEAT BELT BUCKLES	A

5517	20.27	61.88	1.1	4448 *	NA	TX	11001	VERIFY CONCERN PASSENGER SIDE BUCKLE WONT LATCH REPLACED BUCKLE BUCKET SEAT TYPE WITH SIR VERIFY REPAIR OK THIS TIME	A
3098	41.98	68.12	0.4	5419 *	NA	AZ	12000	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE	A
11184	31.83	61.82	0.4	4218 *	NA	NJ	11001	11184 CHECK AND CONFIRM ORDER SEAT BELT ASSY. INSTALLED NEW SEAT BELT BUCKLE, TESTED ALL, OK	X
3744	48.61	101.23	0.7	4218 *	NA	NJ	12000	3744 REPLACE PASS SIDE SEAT BELT AREA REMOVE SEAT TO ACCESS ANCHOR BOLT INSTALL AND TEST OK	X
2	28.05	37.19	0.2	8443 *	NA	LA	11001	1 REPLACED DRIVERS SEATBELT INOP CHIMING BUCKLE	X
14804	28.05	73.4	0.7	528 *	NA	GA	11001	SEATBELT ASSEMBLY FRONT REPLACE SEAT BELT BUCKLE	A
3384	41.89	58.21	0.3	323 *	NA	TX	12000	REPLACED SEATBELT BUCKLE	A
18707	27.51	72.85	0.7	11430 *	NA	TX	11001	REPLACED BROKEN RIGHT FRONT SEAT BELT BUCKLE ASSY	A
3783	27.51	72.24	0.7	5695 *	NA	KY	11001	REPL RIGHT FRT SEAT BELT BUCKLE RT SEAT BELT PRETENS, NOT CONNECTING,CONNECT RT SEAT BELT PRETENSION NOT CONNECTED,CONNECT & CLEAN	X
15	0	68.26	1	5038 *	NA	MO	11000	REPLACE SEAT BELT BUCKLE	A
7351	20.27	60.82	1	4212 *	NA	TX	11001	RECALL 01321	A
10	40.28	78.88	0.5	5536 *	NA	CA	11000	REMOVED SEAT BELTS REINSTALLED SEAT BELTS	R
12	63.62	107.7	1	193 *	NA	GA	11001	1 1 REPLACED BOTH FRONT SEATBELTS.	X
754	0	0	0	6887 *	NA	AR	11000		A

27	27.51	27.14	0.8	4817 *	NA	FL	27 TECH 22 REPLACED PASSENGER SIDE FRONT SEAT BELT	11000	A
30	40.68	34.87	0.7	5515 *	NA	TN	REPLACED RIGHT FRNT SEAT BELT BUCKLE, BUCKLE WOULD NOT LATCH	11000	A
48940	27.51	70.5	0.7	4770 *	NA	IN	84 REPLACE PASS SIDE BELT	11000	A
24	27.51	88.77	1	28 *	NA	MD	REMOVED SEATS AND REPLACED SEAT BELT BUCKLES THAT WERE TAKEN OUT OF STOCK UNIT	11000	R
175	55.87	81.29	0.2	1980 *	NA	TN	REPLACED BUCKLES IN STOCK UNIT	11000	X
11	55.18	112.05	0.8	1028 *	NA	SC	01821D	11000	R
10	27.51	75.38	0.7	7941 *	NA	CA	REPLACED RIGHT SEAT BELT BUCKLE PER RECALL. SEAT BELT BUCKLE WOULD NOT LATCH	11000	R
2758	27.51	33.19	0.2	2327 *	NA	OH	REPLACED RIGHT FRONT SEAT BELT BUCKLE	11000	A
12637	33.7	83.81	0.7	30821 *	NA	NJ	VERIFY CONCERN REMOVE AND REPLACE INOP ASY VERIFY CONCERN. RMR DRIVERS SEAT, REPLACE BUCKLE.	11000	A
4378	23.18	25.43	0.2	4584 *	NA	FL	01X00X COMPLETE RECALL	11000	A
28	0	20.88	0.4	2235 *	NA	OH	SEAT BELT RECALL	11000	R
7	40.88	62.88	0.3	7941 *	NA	CA	REPLACED LEFT SEAT BELT BUCKLE	11000	R
15	40.88	62.88	0.3	7941 *	NA	CA	INSPECTED AND TESTED SEAT BELT BUCKLES PER RECALL. REPLACED LEFT SEAT BELT BUCKLE PER RECALL.	11000	R
2636	22.4	42.04	0.3	4867 *	NA	FL	REPLACE BUCKLE	11000	X
2	0	35.88	0.4	2235 *	NA	OH	COMPLETE RECALL	11000	R
15	28.18	68.82	0.7	4483 *	NA	TX	REPLACED SEAT BELT VERIFIED CONCERN	11001	X
22	27.51	68.84	0.7	20249 *	NA	IL	REPLACED BUCKLE	11001	A
16788	147.35	209.53	1.2	8000 *	NA	MI	CHECKS BOOD. HAD TO REPLACE BOTH FRNT SEAT BELTS TO FX 42	12000	A

6091	0	88.84	1.4	4520 *	NA	TX	11001	R/R SEAT BELT ASSY AND REPAIR CHECK CONCERN AND FOUND DRIVERS SEAT BELT RECEPTACLE BAD. ORDER PART. INSTALL NEW SEATBELT RECEPTACLE AND VERIFY OPERATION.	X
2858	23.15	80.82	0.7	2188 *	NA	OH	11000	BUCKLE WILL NOT LATCH SEATBELT ASSEMBLY FRONT. REPLACE R/R PASSENGER FRONT SEAT BELT. LATCH WAS BAD.	X
2481	23.18	88.42	0.7	482 *	NA	GA	01X00X	TT # 817048 REPLACED PASSENGER SIDE SEAT BELT	D
12072	23.18	47.46	0.4	3888 *	NA	AR	11000	PERFORMED TESTING FOUND PRE TENSIONERS BAD REMOVED FROM ANOT HER STOCK UNIT AND INSTALLED NEW SEAT BELT BUCKLES OK NOW	A
3831	23.18	85.83	0.7	7738 *	NA	CA	11001	TECH 148 VERIFIED AND REPLACED SEAT BELT	X
15715	27.51	89.11	0.8	28380 *	NA	AZ	11000	RECHECKED OPERATION	X
10	34.19	193.86	2	20580 *	NA	NY	11001	COMPLETE RECALL	X
1789	128.1	188.4	0.7	7313 *	NA	PA	11006	4434 41 81178A 6.7 887 REPLACED RT. SEATBELT BUCKLE ASSY; O/C CHECK	X
2	0	28.88	0.4	2228 *	NA	OH	11000	BY TECH	R
12	88.18	88.71	0.5	4570 *	NA	TX	11000	RECALL 01821	X
4434	27.81	104.8	0.7	8638 *	NA	CA	11008	COMPLETED	X
10	0	88.88	0.4	2228 *	NA	OH	11000	REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE	R
8	23.18	88.88	0.7	348 *	NA	OK	01X00X	REPLACED SEAT BELT RETENTIONER	X
18	40.88	88.12	0.7	20387 *	NA	AZ	11000	INSPECT AND REPLACE BOTH SEAT BELT BUCKLES	X
17	83.84	105.17	0.8	8130 *	NA	MA	11000		X

4850	27.51	44.81	0.3	4857 *	NA	IN	FAULTY SEAT BELT BUCKLE REPLACED PASSENGER SIDE BEAT	11000	A
1838	40.88	55.48	0.9	6354 *	NA	LA	REPLACED LEFT SIDE LAP BELT WOOD NOT LATCH PARTS NUMBER 818818	11000	A
6	0	0	0	20488 *	NA	NM	REMOVED DRIVER SIDE BELT FOR COMPLETION INSTALL NEW PASSENGER SIDE BEAT BELT. INSTALLED DRIVER SIDE BEAT BELT THAT WAS BROKEN	11000	X
6573	27.51	48.23	0.4	798 *	NA	AL	FOUND BUCKLE NOT CATCHING, R AND R PASS SIDE BUCKLE TO CORRECT/READY.	11000	A
12771	27.51	55.08	0.5	798 *	NA	AL	COMPLETED INSTALLATION OF SPECIAL ORDERED PART AS REQUESTED.	11000	X
86	23.18	34.17	0.2	1983 *	NA	WV	INSTALL AND REPLACED DRIVER SIDE SEAT BELT DRIVERS SIDE SEAT BELT DOES NOT RECOGN. IT HAD	01X00X	X
15183	28.18	78.87	0.8	2488 *	NA	TX	TO BE REPLACED	11001	X
18	27.51	81.51	0.5	20089 *	NA	IL	REPLACE MIDDLE SEAT BELT BUCKLE	11000	X
3487	40.88	82.88	0.7	5734 *	NA	NC	REPLACE LEFT SEAT BELT WOULD NOT RELEASE ONCE IT WAS BUCKLED WITHOUT EXTREME DIFFICULTY	11800	X
28374	40.88	52.53	0.2	25 *	NA	MD	SEEN WARR CHECK FOR LEFT SEAT BUCKLE WON T LOCK RAR AND REPLACE LEFT SEAT BELT BUCKLE	11000	A
15888	40.88	82.05	0.7	832 *	NA	NC	PERFORM TEST REPLACE BUCKLE AND BEAT BELT	11009	A

CUST_TXT	AREA_CD	COUNTRY_G SLS_DLR_CCTON_CD	ONTRY_S0LJQRT_CD	VFB_CD	AWS_VL_CD	VRT_CD	TIS_FLAG		
	530	USA	172523	1 USA	Q21	V05	F5	308	
PERFORM RECALL 01821 LEFT BUCKLE FAILED, RIGHT BUCKLE PASSED	209	USA	172300	1 USA	Q21	V05	F5	308	
RECALL 01821 SEAT BELT BUCKLE REPLACEMENT BOTH FRONT TRIM CODE AT	941	USA	134436	1 USA	Q21	V05	F5	308	
INSTALL BOP THAT WAS REMOVED TO REPAIR SOLD UNIT FOR 286718	314	USA	153080	1 USA	Q21	V05	F5	308	
FOR VEHICLE IS JUST PAST DATE ON RECALL BUT DRIVERS BUCKLE FAILS	314	USA	153080	1 USA	Q21	V05	F5	308	
REPLACE DRIVERS BUCKLE									
PERFORM RECALL 01821 BOTH SEAT BELT BUCKLES FAILED INSPECTION	209	USA	172300	1 USA	Q21	V05	F5	308	
LEFT PRY SEAT BELT WONT LATCH FOR VEHICLE IS JUST PASSED	802	USA	171171	1 USA	Q21	V05	F5	308	
PRODUCTION DATE FOR RECALL 01821 BUT RIGHT SEAT BELT FAILED TEST	314	USA	153080	1 USA	Q21	V05	F5	308	
REPLACE									
CUSTOMER STATES DRIVERS SIDE FAILS AND PASSENGER SIDE PASSED BOP SEAT BELT IS HERE	817	USA	152020	1 USA	Q21	V00	F5	308	
DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	818	USA	171453	1 USA	Q21	V05	F5	308	
WHEN DRIVER SEAT BELT IS ON AND BUCKLED THE SEAT BELT LIGHT WILL STILL COME ON AND DINGER WILL DN G	417	USA	153489 E34	USA	Q21	V00	F5	308	8
SEAT BELTS WILL NOT LATCH PROPERLY	818	USA	171040	1 USA	Q21	V05	F5	308	
REPAIR SEAT BELT	218	USA	144805	1 USA	Q21	V74	F5	308	
DRIVER SIDE SEAT BELT DOES NOT LATCH PROPERLY	818	USA	171040	1 USA	Q21	V05	F5	308	
REPAIR AIR BAG LIGHT STAYING ON 01821 SEAT BELT	902	CAN	483231	1 CAN	Q21	V05	F5	308	
DRIVERS SEAT BELT FAILED T	740	USA	147128	2 USA	Q21	V75	F5	307	
SEATBELT IS NOT WORKING	770	USA	121005	1 USA	Q21	V05	F5	308	

SEAT BELTS WILL NOT LATCH PROPERLY	216 USA	171040	1 USA	Q21	V05	F5	505
PERFORM RECALL #01821	552 USA	171055	1 USA	Q21	V05	F5	505
RECALL 01821 SEAT BELT BUCKLE	216 USA	159013	1 USA	Q21	V74	F5	505
DRIVERS SEATBELT WILL NOT LATCH	301 USA	127021	1 USA	Q21	V05	F5	505
SEAT BELT WILL NOT LATCH IN BUCKLE	613 CAN	481355	1 CAN	Q21	V05	F5	505
525 OK LEFT SIDE SEAT BELT BUCKLE WILL NOT LATCH	713 USA	152155	2 USA	Q21	V05	F5	505
NECESSARY TO ORDER DRIVERS SIDE SEAT BELT BUCKLE FAILED TEST PER RECALL 01821	901 USA	125005	1 USA	Q21	V05	F5	505
CUSTOMER STATES AT TIMES SEAT BELT LIGHT STAYS ON	909 USA	118455	2 USA	Q21	V05	F5	505
RECALL 01821 SEAT BELT BUCKLE	215 USA	144805	1 USA	Q21	V74	F5	505
CUSTOMER STATES THE DRIVERS SEAT BELT HANGS UP WHEN UNBUCKLING	317 USA	147097	2 USA	Q21	V05	F5	505
RECALL 01821 ALL OK	215 USA	144059	2 USA	Q21	V74	F5	505
RECALL 01821 ALL OK	216 USA	171045	1 USA	Q21	V05	F5	505
RECALL 01821 ALL OK	216 USA	147030	1 USA	Q21	V74	F5	505
RECALL 01821 ALL OK	216 USA	144130	1 USA	Q21	V74	F5	505
RECALL 01821 SEAT BELT BUCKLE	215 USA	144805	1 USA	Q21	V74	F5	505
PASS SEAT BELT WONT RELEASE	318 USA	115555	2 USA	Q21	V05	F5	505
RECALL 01821	215 USA	144124	1 USA	Q21	V74	F5	505
PASS. SEATBELT WAS NOT UNCLIPPING PROPERLY.	505 CAN	455477	2 CAN	Q21	V05	F5	505

SEAT BELTS WILL NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	508
DRIVER SIDE SEAT BELT DOES NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	508
CUST SAYS THE SEAT BELT LIGHT STAYS ON, WILL NOT GO OFF	478 USA	121219	1 USA	Q21	V83	F5	508
DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	508
PERFORM 01821 RECALL SEATBELT	818 USA	171040	1 USA	Q21	V05	F5	508
CUST STATES SEAT BELT LIGHT COMES ON INTERMITTENTLY WHILE DRIVING AND GOES OUT WHEN PULL ON SHOULDER BELT AND DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V83	F5	508
DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	508
DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	508
SEATBELT CHIME NOT TURNING OFF ALL THE TIME WITH DRIVERS SEATBELT.	788 CAN	48220	2 CAN	Q21	V83	F5	508
	USA	171174	2 USA	Q21	V05	F5	508
DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	508
REPAIR SEAT BELT BUCKLE STAYS DOWN	808 CAN	48225	1 CAN	Q21	V05	F5	508
VERIFIER RAPPEL 01821	458 CAN	48237	1 CAN	Q21	V05	F5	508
LEFT SEAT BELT NOT WORKING	270 USA	147051	1 USA	Q21	V85	F5	508
ANNC. TRIM 825 CORRECT LEFT FRONT SEATBELT DOES NOT BUCKLE	308 CAN	48488	E94 CAN	Q21	V05	F5	508

CUSTOMER STATES DRIVER'S SIDE SEAT BELT
WARNING LIGHT WILL NOT GO OFF PART
WAS ORDERED AT KEMP
1L3Z15B12088AB

805 USA 171447 1 USA Q21 V05 F5 808

DRIVERS SEAT BELT WONT LATCH

719 USA 162792 2 USA Q21 V05 F5 808

SEAT BELT COIL UNCOIL TROUBLES

814 USA 147018 1 USA Q21 V05 F5 808

RT FRT SEAT BELT WONT LATCH

818 USA 148078 2 USA Q21 V05 F5 808

CUSTOMER STATES DRIVER SEAT BELT
BUCKLE WILL NOT LATCH.1

813 USA 147615 2 USA Q21 V05 F5 808

CUSTOMER STATES THAT SEAT BELTS
ARE NOT WORKING CORRECTLY
DRIVERS SIDE

688 USA 189347 2 USA Q21 V05 F5 808

RIGHT SEAT BELT WILL NOT LATCH

708 USA 127042 1 USA Q21 V05 F5 808

CORRECT DRIVER SEAT BELT TO LATCH
REPLACER CEINTURE AVANT DROITE
P/O.16486
P/S FRONT SEAT BELT BUCKLE WILL NOT
LOCK

705 CAN 448017 2 CAN Q21 V05 F5 808

480 CAN 4A2048 2 CAN Q21 V05 F5 808

805 CAN 481388 2 CAN Q21 V05 F5 808

DRIVERS SEAT BELT WONT LATCH CUSTOMER STATES SEAT BELT WONT BUCKLE	803 USA	162482	2 USA	Q21	V05	F5	808
	540 USA	127484	1 USA	Q21	V05	F5	808
AIR BAG LIGHT IS ON	804 USA	144532	1 USA	Q21	V05	F5	808
SEAT BELT WILL NOT LATCH	804 USA	147288	2 USA	Q21	V05	F5	808
DMG. DRIVERS SEAT BELT, WONT LATCH	810 USA	163400 EB4	USA	Q21	V05	F5	808
CUSTOMER STATES SEAT BELT ON RIGHT FRONT WILL NOT CLIP INTO BUCKLE	870 USA	125885	2 USA	Q21	V05	F5	808
DRIVERS SEAT BELT BUCKLE AMPY MISSING. VEHICLE WAS DEALER TRADED FROM WEST VIRGINIA. CONCERN CODE B4	740 USA	144515	2 USA	Q21	V05	F5	808
() PASSENGER SIDE SEAT BELT IS NOT WORKING	314 USA	152812 EB4	USA	Q21	V05	F5	808
REPLACE SOP SEAT BELT	815 USA	141536	1 USA	Q21	V05	F5	808
DRIVERS SEAT BELT INOP	889 USA	172500	1 USA	Q21	V05	F5	808
NAC 01821 SEAT BELT BUCKLE RECALL INSPECTED LEFT SIDE FAILED	USA	162007	1 USA	Q21	V05	F5	808
WP SEAT BELT BUCKLE WONT STAY LATCHED	880 USA	162008	2 USA	Q21	V05	F5	808
PERFORM RECALL #01821 NOTE NO OPEN RECALL CAMPAIGN PER OASIS BUT FAILED TEST	882 USA	171085	1 USA	Q21	V05	F5	808

SEAT BELT CHIME STAYS ON	664 USA	121792	1 USA	Q21	V05	F5	808
DRIVERS AND PASSENGER SIDE SEAT BUCKLES WILL NOT LATCH PROPERLY	628 USA	171053	1 USA	Q21	V05	F5	808
	818 USA	171040	1 USA	Q21	V05	F5	808
ORDER AND INSTALL SEAT BELT LATCH FOR THE DRIVERS SEAT, DID NOT COME STOCK WITH THE VEHICLE	408 USA	172090	2 USA	Q21	V05	F5	808
OK FOR SEAT BELT BUCKLE WONT HOLD	843 USA	121291	1 USA	Q21	V05	F5	808
SEAT BELT BUCKLE INOP	408 USA	162189	1 USA	Q21	V05	F5	808
SEATBELT BUCKLE HARD TO UNLATCH	303 USA	166439	1 USA	Q21	V05	F5	808
SEAT BELT INSPECTION	407 USA	124805	1 USA	Q21	V05	F5	808
RECALL 01521 SEATBELT INSPECT CHECK SEATBELT BUZZER SOUNDS FOR 15 MIN AFTER STARTUP WITH ALL BELTS BUCKLED	906 USA	141343	1 USA	Q21	V05	F5	808
	770 USA	121490	1 USA	Q21	V05	F5	808
NO RECALL BUT HAS BAD SEAT BELT ON PASS SIDE	885 USA	123348	2 USA	Q21	V05	F5	808
CHECK SEAT BELTS	919 USA	121095	2 USA	Q21	V05	F5	808
RECALL 01521 RIGHT	808 USA	171108	1 USA	Q21	V05	F5	808
PASS SIDE FRT SEATBELT IS HARD TO RELEASE	284 USA	152488	2 USA	Q21	V05	F5	808
SEAT BELT BUCKLE BINDING	916 USA	172291	2 USA	Q21	V05	F5	808
SEAT BELT BUCKLE INOP	808 USA	171484	1 USA	Q21	V05	F5	808

RIGHT SEATBELT WONT LATCH	830 USA	158082	1 USA	Q21	V05	F5	808
CERTAIN 8001 MODEL YEAR CROWN VICTORIA, EXCURSION, F150, F250 THROUGH F350, GRAND MARQUIS, NAVIGATOR, RANG	825 USA	172022	1 USA	Q21	V05	F5	808
OK FOR SEAT BELT BUCKLE WONT HOLD SEATBELTS STRIKING	843 USA 802 USA	121291 171173 EB4	1 USA USA	Q21 Q21	V08 V05	F3 F5	808 808
WHEN USING SEATBELT THE SEATBELT WARNING CHIME WILL COME ON THEN BO OFF CHK OUT CUSTOMER STATES PASSENGER SEAT BELT WONT LATCH. COLOR CODE KH MANUAL BUCKET SEAT.	805 USA 718 USA	185430 158200	2 USA 1 USA	Q21 Q21	V05 V05	F5 F5	808 808
SEAT BELTS WILL NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	808
01821 RECALL CUSTOMER STATES PERFORM RECALL	210 USA	152300 EB4	USA	Q21	V05	F5	805
RECALL 01821 BAFTEY RECALL SEAT BELT BUCKLES	318 USA	171018	1 USA	Q21	V07	F5	808
RT FRONT SEATBELT BUCKLE NOT CLICKING PROPERLY INSTALL S O PART USE OPO 01300000	305 USA	124008	2 USA	Q21	V74	F5	808
	530 USA	172408	1 USA	Q21	V05	F5	808
RT SEAT BELT WILL NOT HOLD RIGHT FRONT SEAT BELT FAILED 01821	904 USA 314 USA	124223 153088	1 USA 2 USA	Q21 Q21	V05 V05	F5 F5	808 808
PASS SIDE INOP	281 USA	152047	2 USA	Q21	V05	F5	808

RECALL 01321	559 USA	179482	1 USA	Q21	V06	F5	808	
PASSIDE SEAT BELT INOP PWT	638 USA	162022	2 USA	Q21	V06	F5	808	
RECALL 01321 SEAT BELT BUCKLE	854 USA	124014	1 USA	Q21	V06	F5	808	
RECALL 01321 ALL O.K.	218 USA	144886	1 USA	Q21	V74	F5	808	
840 MUST STATES RIGHT REAR SEAT BELT WONT LATCH INSTALL SOP	909 USA	171054	2 USA	Q21	V06	F5	808	
DRIVERS SEAT BELT INOP	908 USA	168417 E34	USA	Q21	V06	F5	808	
Q B FRONT PASS SIDE SEATBELT INOP AT TIMES	855 USA	152067 E34	USA	Q21	V06	F5	808	0
Q28 CHECK CUST CONCERN FOR DRIVER SIDE SEAT BELT CHIRPS AFTER BUCKLING BELT.	954 USA	184015	1 USA	Q21	V06	F5	808	
CUST CONCERN FOR SEAT BELT LIGHT STAYING ON AFTER BUCKLED	854 USA	184015	1 USA	Q21	V06	F5	808	
Q B SEAT BELT NOT WORKING SOP PARTS HERE	998 USA	162104	1 USA	Q21	V74	F5	808	
CUSTOMER STATES BUCKLE FOR PASSENGER FRONT SEAT BELT IS MISSING	581 USA	124018	1 USA	Q21	V06	F5	808	0

SEAT BELT INSPECTION	407 USA	134920	1 USA	Q21	V05	F5	808	
SEAT BELT WARNING LIGHT STAYS ON AND ALARM SOUNDS EVEN WHEN BELT IS BUCKLED AT TIMES	320 USA	141100	1 USA	Q21	V83	F3	808	
SEATBELT WARNING CHIME CONTINUES TO CHIME AFTER SEATBELT IS LATCHED	410 USA	127030	1 USA	Q21	V05	F8	808	●
CUIS STATES PASS SIDE SEATBELT INOP	405 USA	132880	1 USA	Q21	V05	F5	808	
CUSTOMER SAYS THAT PASSENGER SIDE SEAT BELT BINDS	405 USA	132880	1 USA	Q21	V05	F8	808	
SEATBELT BUCKLE BROKEN	019 USA	121610	2 USA	Q21	V05	F8	808	
RIGHT FRONT SEAT BELT WILL NOT CATCH AT TIMES	017 USA	109080	2 USA	Q21	V05	F5	808	
SEATBELT LIGHT ON AND CHIME RINGS	337 USA	123700	1 USA	Q21	V05	F5	808	
CERTAIN 2001 MODEL YEAR CROWN VICTORIA, EXCURSION, F150, F250 THROUGH F350, GRAND MARQUIS, NAVIGATOR, RANG	828 USA	172020	1 USA	Q21	V05	F5	808	
DRIVERS SEAT BELT COMES UNLATCHED INTERMITT. WHILE DRIVING SCP IN	012 USA	152140	1 USA	Q21	V05	F5	808	
DRIVERS SEAT BELT BUCKLE IN OP. RECALL 01621	582 USA 309 USA	171020 172800	2 USA 1 USA	Q21 Q21	V05 V05	F5 F5	808 808	●

SEATBELT SENSOR HAS BEEN
DISCONNECTED...PLEASE CK TO SEE IF
PART IS NOW IN

905 CAN 4B1097 1 CAN Q21 V05 F5 908

PERFORM RECALL 01821 LEFT AND
RIGHT BUCKLE FAILED

309 USA 172300 1 USA Q21 V05 F5 908
308 USA 172300 1 USA Q21 V05 F5 908

FRONT DRIVERS SIDE AND FRONT
PASSENGER SIDE SEATBELT WILL NOT
LATCH
INSPECT FOR SEAT BELT CONCERN

970 USA 158485 1 USA Q21 V05 F5 908
620 USA 171204 1 USA Q21 V05 F5 908

SEATBELT IS INOP AT TIMES
RECALL 01821

225 USA 122903 1 USA Q21 V05 F5 908
909 USA 153201 1 USA Q21 V05 F5 908

RIGHT SEAT BELT WONT STAY LATCHED *

USA 152207 1 USA Q21 V05 F5 908

SEAT BELT DRIVERS SIDE FAILED
WONT STAY LATCHED

291 USA 152047 1 USA Q21 V05 F5 908

SEAT BELT BUCKLE DOES NOT WORK

790 USA 171190 1 USA Q21 V05 F5 908

CUST STATES FRONT MIDDLE SEAT BELT
WILL NOT STAY LATCHED
SEAT BELT BUCKLES NOT WORKING
PROPERLY

291 USA 152046 1 USA Q21 V05 F5 908

SEAT BELT PARTS ARE IN SEAT BELT
RECALL DRIVER B BELT IS BAD

291 USA 152046 1 USA Q21 V05 F5 908

SEAT BELT BUCKLE INOP21
CUSTOMER STATES PASSENGER FRONT
SEAT BELT BUCKLE WONT STAY
BUCKLED

303 USA 159012 1 USA Q21 V05 F5 908

409 USA 192199 1 USA Q21 V05 F5 908

641 USA 159003 1 USA Q21 V05 F5 908

INSPECT PER 01821 RECALL
INSTRUCTIONS

225 USA 122903 1 USA Q21 V05 F5 908

CUST STATES SEATBELTS INOP

559 USA 172491 1 USA Q21 V05 F5 908

INSPECT PER 01821 RECALL
INSTRUCTIONS

228 USA 122203 1 USA Q21 V05 F5 808

CUST STATES L FR S BELT LATCH WONT
HOLD

352 USA 124500 1 USA Q21 V05 F5 808

SEAT BELT WILL NOT LATCH

617 USA 152406 1 USA Q21 V05 F5 808

C S PASS FRONT SEATBELT
INOP,INSTALL SOP FROM RC492575

499 USA 171173 EBM USA Q21 V05 F5 808

REPAIR FOR RIGHT SIDE BUCKLE
FAILURE TRIM E H

606 USA 141182 1 USA Q21 V05 F5 808

SEAT BELT BUCKLE SOP IN

602 USA 171172 1 USA Q21 V05 F5 808

608 USA 141890 1 USA Q21 V05 F5 808
714 USA 171057 1 USA Q21 V05 F5 808

CST STATES SEAT BELT CHIMES COME
ON WHILE DRIVING SEE SOP

641 USA 124476 2 USA Q21 V05 F5 808

625 CUST STATES SEAT BELT RT FRONT
WILL NOT BUCKLE OR LATCH AT TIMES
RED BUTTON DOES NOT POP UP BAYS

691 USA 152022 1 USA Q21 V05 F5 808

PASSENGER SEAT BELT WONT STAY
LATCHED CDD 548
RECALL 01821 ALL OK

673 USA 162362 1 USA Q21 V05 F5 808
216 USA 144210 1 USA Q21 V74 F5 808

CK SEAT BELT BUCKLE WILL LATCH BUT
UNLATCHES WHEN BELT IS PULLED ON

317 USA 147618 1 USA Q21 V05 F5 808

CK FOR SEAT BELT WONT HOLD
RECALL 01821 ALL OK

843 USA 121291 1 USA Q21 V05 F5 808
218 USA 144905 1 USA Q21 V74 F5 808

SSR CUSTOMER STATES MIDDLE CENTER
SEATBELT UNABLE TO LATCH

652 USA 159080 1 USA Q21 V05 F8 808

OK SEAT BELT LAMP, & CHIMES GO ON
INTERMITTENT CLOSED
BY WPI

815 USA 141432 1 USA Q21 V05 F5 808

CUSTOMER STATES BELT CHIME KEEPS
RINGING OFF HAS SEAT BELT BUCKLE
ORDERED LEFT SIDE

502 USA 147022 534 USA Q21 V06 F8 808

RECALL 01821 LEFT SIDE OK, RIGHT
SIDE REPLACE 1L72 786LS02 B/B
RIGHT FRONT SEATBELT WON'T STAY
CONNECTED

218 USA 144805 1 USA Q21 V74 F5 808

405 USA 152213 2 USA Q21 V05 F8 808

SEATBELT ON THE DRIVERS SIDE
DIDN'T ALWAYS LATCH

218 USA 158408 1 USA Q21 V05 F5 808

ORDER RE SEAT BELT HARD TO LATCH

306 USA 121012 1 USA Q21 V05 F5 808

PASSENGER FRONT SEATBELT WONT
LATCH

210 USA 152774 2 USA Q21 V05 F8 808

PERFORM 01821 RECALL SEATBELT
SEAT BELTS WILL NOT LATCH
PROPERLY

818 USA 171040 1 USA Q21 V05 F5 808

818 USA 171040 1 USA Q21 V05 F5 808

SEAT BELT NOT LATCHING

817 USA 152009 1 USA Q21 V05 F5 808

FRONT PASS SEATBELT BUCKLE INOP

505 USA 158510 2 USA Q21 V05 F5 808

SEAT BELTS WILL NOT LATCH PROPERLY

818 USA 171040 1 USA Q21 V05 F5 808

THE RIGHT SEATBELT DOES NOT LATCH
REPLACE DEFECTIVE SEAT BELT
SEAT BELT BUCKLE IS NOT LATCHING
PROPERLY

580 USA 141837 1 USA Q21 V08 F5 808

757 USA 127488 1 USA Q21 V05 F5 808

802 USA 171172 1 USA Q21 V05 F5 808

CUSTOMER STATES PASSENGER SIDE
SEAT BELT BUCKLE INOP

310 USA 171089 1 USA Q21 V05 F5 808

LEFT FRONT SEAT BELT BUCKLE
INOPERATIVE

810 USA 179488 1 USA Q21 V05 F5 808

RIGHT SEAT BELT WILL NOT LATCH AT
TIMES

817 USA 152020 BBA USA Q21 V05 F5 808

FRONT PASSENGER SEAT BELT BUCKLE
FAILED RECALL TEST
SEAT BELT WILL NOT LATCH SOP HERE
SEE 87917 TECH 348 PASS SIDE
USE SPO 02040001

780 USA 171102 1 USA Q21 V05 F3 808

840 USA 152428 1 USA Q21 V05 F5 808

SEAT BELT BUCKLE INOP

408 USA 162185 2 USA Q21 V05 F5 808

DOOR SEAT BELT CHIME STAYS ON
WHILE DRIVING, SEAT BELT LIGHT STAYS
ON

910 USA 171688 2 USA Q21 V17 F5 808

SEAT BELT BUCKLE INOP
L SIDE FAILED

727 USA 134454 1 USA Q21 V05 F5 808

PASS SEAT BELT WONT CLIP IN BUCKLE
PART HERE

878 USA 152191 BBA USA Q21 V05 F5 808

SEAT BELT WARNING INDICATOR WONT
GO OUT

849 USA 121334 1 USA Q21 V88 F5 808

S O PART IN FOR SEAT BELT CHIME WILL
NOT SHUT OFF

880 USA 127845 2 USA Q21 V17 F5 808

840 PASS FRONT SEAT BELT DOES NOT
STAY LOCKED

881 USA 122855 1 USA Q21 V05 F5 808

CLUST STATES SEATBELTS INOP

888 USA 172491 1 USA Q21 V05 F5 808

PERFORM RECALL 01821 RT MR 80 40 N P	625 USA	171083	1 USA	Q21	V05	F5	808
840 CS SEAT BELT BUZZER STAYS ON. SOP PART HERE	512 USA	152784	2 USA	Q21	V05	F5	808
CUST STATES SEAT BELTS INOP	555 USA	172491	1 USA	Q21	V05	F5	808
CENTER SEAT BELT NOT LATCH	701 USA	188841	2 USA	Q21	V05	F5	808
REPAIR SEAT BELT NOT WORKING	701 USA	158841	2 USA	Q21	V05	F5	808
SEAT BELT CENTER WILL NOT WORK	761 USA	158841 E84	USA	Q21	V05	F5	808
NEEDS DRIVERS BELT	732 USA	113529	1 USA	Q21	V05	F5	808
CUSTOMER STATE SEAT BELT INOP NECAR REQUEST OK	964 USA	124015	1 USA	Q21	V05	F5	808
SEAT BELT WILL NOT LATCH SEAT BELTS WILL NOT LATCH PROPERLY	817 USA 815 USA	152005 171040	1 USA 1 USA	Q21 Q21	V08 V05	F5 F5	808 808
PASSANGER SIDE SEAT BELT WILL NOT LATCH PROPERLY	618 USA 830 USA	171059 152782	1 USA 1 USA	Q21 Q21	V05 V74	F5 F5	808 808
INSTALL SOP SEAT BELT LATCH RPTS CENTER SEAT BELT WILL NOT LATCH INSTALL SOP	309 USA 309 USA	172491 172491	1 USA 1 USA	Q21 Q21	V05 V05	F5 F5	808 808
SEAT BELTS WILL NOT LATCH PROPERLY	315 USA	171040	1 USA	Q21	V05	F5	808
PASSENGER SEAT BELT WILL NOT CLIP	817 USA	152005	2 USA	Q21	V05	F5	808
CHECK LEFT FRONT SEATBELT BUCKLE	812 USA	121741	2 USA	Q21	V05	F5	808
SEAT BELTS WILL NOT LATCH PROPERLY	815 USA	171040	1 USA	Q21	V05	F5	808
SEAT BELT WILL NOT LATCH USE SPO 02074015	479 USA	123229	2 USA	Q21	V08	F5	808

SEAT BELT CLIP FELL IN SLOT ON PASS
SIDE
CURT STATES DRIVERS SIDE SEATBELT
WILL NOT STAY LATCHED WHEN PULLED
ON.
REPLACE S.O.P. SEAT BELT REMEDY
SETS TO HIGH AND BANGS YOU IN THE
RIBS

810 USA	121789 EB4	USA	Q21	V05	F5	508
803 USA	124405 EB4	USA	Q21	V05	F5	508
818 USA	133005 EB4	USA	Q21	V05	F5	508

RIGHT FRONT SEAT BELT FEMALE END
DOES NOT HOLD

559 USA	179221	2 USA	Q21	V05	F5	508
818 USA	171040	1 USA	Q21	V05	F5	508
808 USA	171434 EB4	USA	Q21	V05	F5	508

PASS SEAT BELT DOESNT WORK DO NOT
RELEASE CAR UNTILL PART IS INSTALLED

908 USA	171079	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

SEAT BELTS WILL NOT LATCH PROPERLY

818 USA	171040	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

CURT STATES DRIVERSIDE SEATBELT
WILL NOT LATCH GOOD CC 840 SOP IN
PARTS

501 USA	152220	2 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

CENTER SEAT BELT WILL NOT BUCKLE

818 USA	123308	2 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

LEFT BET BELT HARD TO RELEASE
CHECK DN SEAT BELT WONT STAY
LATCHED

417 USA	133612 EB4	USA	Q21	V05	F5	508
818 USA	133371	1 USA	Q21	V05	F5	508

RECALL 01821 SEATBELT INSPECT

808 USA	141182	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

530 USA	179408	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

CHECK FOR DRIVER SEAT BELT NOT
LATCHING
CHECK DRIVERS SIDE SEAT BELT WONT
LATCH

408 USA	132758 EB4	USA	Q21	V05	F5	508
818 USA	138473	1 USA	Q21	V05	F5	508

LEFT FRONT SEAT BELT BUCKLE WAS NOT HOLDING	998 USA	162122	1 USA	Q21	V06	F5	306
01621 LFT FRT SEAT BELT BUCKLE BAD	205 USA	121407	1 USA	Q21	V06	F5	306
DRIVERS SEAT BELT IN OP REPORT	510 USA	173013	1 USA	Q21	V06	F5	306
DRIVER SIDE SEAT BELT WILL NOT HOLD	251 USA	182047	1 USA	Q21	V06	F5	306
CUSTOMER STATES THE FRONT MIDDLE SEAT BELT DOES NOT CLASP	330 USA	144219	1 USA	Q21	V08	F5	306
CUSTOMER STATES THE PASS FRONT SEAT BELT WONT LATCH	330 USA	144219	1 USA	Q21	V06	F5	306
DR SIDE SEAT BELT STICKY AND POPS OUT AT TIMES	712 USA	159693	1 USA	Q21	V06	F5	306
SEAT BELTS WILL NOT LATCH PROPERLY	518 USA	171040	1 USA	Q21	V06	F5	306
LEFT SEATBELT BUCKLE WONT LATCH @SEATBELT FRONT CENTER BUCKLE WILL NOT LATCH, SOP HERE SEE 91155 USE SPO 01338083	840 USA	183408	1 USA	Q21	V06	F5	306
LEFT FRONT SEATBELT DOES NOT LATCH PROPERLY	608 USA	158412	1 USA	Q21	V08	F5	306
01621 SEAT BELT BUCKLE	770 USA	121400	1 USA	Q21	V06	F5	306
SEATBELT CHIME KEEPS GOING OFF	713 USA	159032 ES4	USA	Q21	V06	F5	306
SEAT BELT BUCKLE INOP	409 USA	182185	1 USA	Q21	V06	F5	306
00821 SEAT BELT RECALL	770 USA	121400	1 USA	Q21	V06	F5	306
CUSTOMER IS CONCERNED SEAT BELT CHIME NEVER SOUNDS	281 USA	162130 ES4	USA	Q21	V17	F5	306
CUST STATES R FR @ BELT LATCH WONT HOLD	362 USA	124500	1 USA	Q21	V06	F5	306
SOP LF SEATBELT SENSOR	901 USA	123002	1 USA	Q21	V06	F5	306

CUST STATES THAT DRIVERS SEAT BELT WONT LATCH	808 USA	171182	1 USA	Q21	V05	F5	308	●
CUSTOMER STATES DRIVER SEAT BELT BUCKLE JAMMED IN THE RELEASED POSITION AND WOULD NOT ALLOW THE BELT TO BE LATCHED	402 USA	153085	2 USA	Q21	V05	F5	508	
DRIVERS SEATBELT INCP,INSTALL SOP	778 USA	124203 E34	USA	Q21	V05	F5	308	
CUST STATES DRIVERS SIDE SEAT BELT INOP	918 USA	152483	1 USA	Q21	V05	F5	808	
SEAT BELT WILL NOT LATCH	817 USA	153009	1 USA	Q21	V05	F5	508	
LEFT FRNT SEAT BELT WONT LATCH RECALL 01821 ALL OK	818 USA 218 USA 830 USA	171460 144128 152732	1 USA 1 USA 1 USA	Q21 Q21 Q21	V05 V74 V74	F5 F5 F5	308 508 508	
CUSTOMER STATES RIGHT FRONT SEAT BELT WILL NOT HOLD	917 USA	152009	1 USA	Q21	V05	F5	508	
01821 SEAT BELT RECALL RECALL 01821 ALL OK	838 USA 218 USA	152185 144605	1 USA 1 USA	Q21 Q21	V05 V74	F5 F5	308 508	
CHECK FOR SEAT BELT RELEASE BUTTON STICKS CHIME SOUNDS AT TIMES EVEN WHEN SEAT BELT IS LATCHED SOP HERE	903 USA	152717 E34	USA	Q21	V05	F5	308	●
D 8 WHEN SEAT BELT IS ON WHILE DRIVING SEAT BELT LIGHT FLASHES ON AND OFF	812 USA	152088	2 USA	Q21	V05	F5	308	

CS SEAT BELT CHIMES WILL NOT STOP
WITH BELT ON

808 USA 171178 EB4 USA Q21 V83 F5 808

DRIVERS SEAT BELT NOT LATCHING

807 CAN 488802 1 CAN Q21 V05 F5 808

SEAT BELT LITE COMES ON AT TIMES

808 USA 188988 1 USA Q21 V05 F5 808

SEAT BELT MINDER GOES OFF EVEN
WHEN BELT IS BUCKLED WILL GO OFF
IF YOU BOUNCE ON THE SEAT

829 USA 141880 2 USA Q21 V83 F3 808

CUSTOMER REPORTS RIGHT FRONT
WONT BUCKLE IN

803 USA 174013 1 USA Q21 V05 F3 808

REPAIR TO MIDDLE SEAT BELT BUCKLE
INOP
RECALL 01821 ALL OK

908 USA 174013 2 USA Q21 V05 F5 808
218 USA 144805 1 USA Q21 V74 F5 808

840 DRIVER SIDE SEAT BELT BUCKLE
KEEPS COMING UNLATCHED WHILE
DRIVING

218 USA 152718 1 USA Q21 V05 F5 808

SEAT BELT BUCKLE INOP

408 USA 152183 1 USA Q21 V05 F5 808

RECALL 01821 ALL OK
 2007 SEAT BELT WARNING LIGHT KEEPS
 COMING ON AND FLASHING, EVEN
 WHEN SEAT BELT FASTENED

216 USA	144806	1 USA	Q21	V74	F6	308
214 USA	162003	2 USA	Q21	V06	F6	308

840 SEATBELT ON DRIVERS SIDE LATCHES
 BUT DOES UNDONE

381 USA	162029	2 USA	Q21	V06	F6	308
---------	--------	-------	-----	-----	----	-----

CUSTOMER STATES DRIVERS SEAT BELT DOES
 NOT ENGAGE AND HOLD

610 USA	118025 E94	USA	Q21	V05	F6	308	0
---------	------------	-----	-----	-----	----	-----	---

THE SEAT BELT LIGHT AT TIMES WILL
 STAY ON EVEN WHEN THE SEAT BELT IS
 LATCHED, CORRECT FOR
 MISSING SEATBELT IN REAR SEAT.
 CUSTOMER STATES THE PASS SIDE SEAT BELT
 WILL NOT LOCK

318 USA	162900 E94	USA	Q21	V06	F6	308
305 CAN	488477	1 CAN	Q21	V06	F6	308
440 USA	144134	2 USA	Q21	V06	F6	308

SEAT BELT RELEASE NOT HOLDING

670 USA	122668	2 USA	Q21	V05	F6	308
---------	--------	-------	-----	-----	----	-----

PASSENGER SEAT BELT WILL NOT
 ENGAGE

366 USA	162067 E94	USA	Q21	V71	F6	308
---------	------------	-----	-----	-----	----	-----

CUSTOMER STATES CENTER SEATBELT
 NOT CONNECTED

408 USA	162785 E94	USA	Q21	V06	F6	308	0
---------	------------	-----	-----	-----	----	-----	---

CK SEAT BELT WARNING LIGHT STAYS
 ON

666 USA	132184	1 USA	Q21	V06	F6	308
---------	--------	-------	-----	-----	----	-----

CUSTOMER STATES THAT THE SEAT BELT
 WARNING CHIME DOESNT STOP WHEN
 SEAT BELT IS LATCHED

386 USA	123148	1 USA	Q21	V06	F6	308
---------	--------	-------	-----	-----	----	-----

D1821 SEAT BELTS PASS SEAT BELT
WONT FASTEN

210 USA

152063

1 USA

Q21

V05

F5

808

SEATBELT CHIME GOES OFF

803 USA

121274 E84

USA

Q21

V05

F5

808

CUSTOMER STATES ALARM WAS GOING
OFF WHEN SEAT BELT PULLING IN

819 USA

122069

1 USA

Q21

V17

F5

808

PASS SEAT BELT RECEIVER WILL NOT
LATCH (SOP) N

417 USA

153480

2 USA

Q21

V05

F5

808

CUSTOMER STATES ALL SEAT BELTS
WILL COME UNDONE WHILE DRIVING.

817 USA

152008

1 USA

Q21

V05

F5

808

CURT SAYS CENTER SEAT BELT ISNT
BOLTED DOWN

870 USA

125528

1 USA

Q21

V05

F5

808

DRIVER SEAT BELT COMES UNBUCKLED
WHEN DRIVING SOP PART IN

817 USA

152016

1 USA

Q21

V05

F5

808

SEAT BELT BUCKLE WONT STAY
LATCHED ON DRIVER SIDE OR THE
PASSENGER SIDE

817 USA 152018 1 USA Q21 V05 F5 808

CUSTOMER CONCERN IS THAT
PASSENGER FRONT SEAT BELT BUCKLE
IS NOT WORKING PROPERLY AND
SOMETIMES DOESNT LATCH AT ALL
SPW PASSENGER FRONT SEAT BELT
BUCKLE CAME

USA 171204 2 USA Q21 V05 F5 808

USA 171254 E83 USA Q21 V06 F5 808

BASE \$40 FRONT SEAT BELT WILL NOT
BUCKLE TOGETHER SOP BBS ALBERT

580 USA 171204 1 USA Q21 V05 F5 808

OK SEATBELT CHIME WONT CHIME

881 USA 152032 2 USA Q21 V05 F5 808

DRIVER & SIDE SEAT BELT FAILED
INSPECTION .
DRIVERS SEATBELT BUCKLE DOESNT
STAY LATCHED

506 USA 185545 1 USA Q21 V05 F5 808

613 USA 147880 1 USA Q21 V05 F5 808

CHECK PASSENGERS SIDE SEAT BELT
FOR ANY MALFUNCTIONS???

414 USA 141088 1 USA Q21 V03 F5 808

PERFORM SEATBELT RECALL PER OASMS

882 USA 171055 1 USA Q21 V05 F5 808

\$40 GC THE PASSENGER FRONT SEAT
BELT COMES UNDONE WHILE DRIVING

979 USA 152168 E84 USA Q21 V05 F5 808

BASE SEATBELT LIGHT STAYS ON EVEN
WHEN BELT'S BUCKLED 840

520 USA 171204 1 USA Q21 V05 F5 806

SEATBELT WARNING INDICATOR WILL
COME ON WHILE DRIVING, DOES NOT
SEEM TO COME ON WHEN BELT IS
UNHOOK

515 USA 152205 1 USA Q21 V03 F5 806

CUSTOMER STATES DRIVER'S SEAT BELT
CHIME STAYS ON AND BUCKLE
RELEASES

505 USA 155302 EB4 USA Q21 V05 F5 806 @

SEAT BELTS WILL NOT LATCH
PROPERLY
DRIVER SEAT BELT BUCKLE WONT
LATCH

515 USA 171040 1 USA Q21 V05 F5 806

CUSTOMER STATES DRIVER'S SEAT BELT
BUCKLE INOP, SOP PART

512 USA 152302 1 USA Q21 V05 F5 806

505 USA 155301 EB4 USA Q21 V05 F5 806

LEFT SIDE SEAT BELT BUCKLE S O PART

717 USA 115205 1 USA Q21 V05 F5 806

CUSTOMER STATES THAT THE SEAT
BELT CHIMES WILL NOT SHUT OFF
INTERIOR LIGHTS WILL NOT GO OFF

717 USA 115205 2 USA Q21 V05 F5 806

CUST STATES SEAT BELTS INOP

525 USA 172481 1 USA Q21 V05 F5 806

CUSTOMER STATES DRIVER SEAT BELT
WILL NOT LOCK AT TIMES.

354 USA 152481 EB4 USA Q21 V05 F5 806

SEATBELT PART IN

USA 124202 1 USA Q21 V05 F5 806

C B WITH BOTH SEAT BELTS ON THE
CHIME AND LIGHT STAY ON
INTERMITTENTLY

802 USA 171173 1 USA Q21 V83 F5 808

SEAT BELT ALARM AND LIGHT WILL NOT
GO OFF EVEN WHEN SEAT BELT IS
BUCKLED

870 USA 166443 1 USA Q21 V83 F5 808

DRIVER SEATBELT WONT BUCKLE

208 USA 174011 1 USA Q21 V05 F5 808

SEAT BELT PARTS HERE ORDERED ON
PO 89135 6 15 02

398 USA 121081 2 USA Q21 V08 F8 808

SEAT BELT CHIME AND LIGHT STAY ON

818 USA 121019 1 USA Q21 V17 F5 808

CUSTOMER STATES: RIGHT FRONT SEAT
BELT INOP

807 USA 113207 1 USA Q21 V05 F5 808

DIAG FRONT DRIVER SEAT BUCKLES
INOP

828 USA 171072 E84 USA Q21 V08 F8 808

CUST STATES CHECK SEAT BELT LIGHT
COMES ON EVEN WHEN BELTS BUCKLED
OK CUSTOMER STATES EVEN WITH SEAT
BELT LOCKED THE CHIME STILL SOUNDS
FOR SEVERAL MINUTES OK ADVISE CC
840

817 USA 152019 1 USA Q21 V17 F5 808

770 USA 121878 2 USA Q21 V05 F5 808

CUST STATES SEAT BELT SIGNAL IN
DASH WILL NOT GO OFF CHIME KEEPS
SOUNDING

757 USA 127021 1 USA Q21 V83 F5 808

PASSENGER SEAT SIDE SEAT BELT WILL
NOT CATCH IN BUCKLE
LT SEAT BELT BUCKLE NOT LATCHING
CONCERN CODE 840

281 USA	152130	1 USA	Q21	V74	F5	508
806 USA	155803 EB4	USA	Q21	V05	F5	508

PASS FRONT SEAT BELT WILL NOT
ENGAGE

718 USA	124902 EB4	USA	Q21	V05	F5	508
---------	------------	-----	-----	-----	----	-----

CUSTOMER STATES RIGHT FRONT SEAT
BELT INOP

613 USA	124402	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

CHECK FOR PASSENGER FRONT SEAT
BELT NOT LATCHING SOP IN

836 USA	102788	2 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

SEAT BELT WARNING LIGHT STAYS ON
AND BINGS UP TO 4 TIMES AFT
CHECK PASSENGER SIDE BELT WONT
ENGAGE

530 USA	152724	1 USA	Q21	V05	F5	508
705 CAN	422070	1 CAN	Q21	V05	F5	508

RIGHT FRONT SEAT BELT IS STICKING

536 USA	152188	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

PASSENGER SIDE SEAT BELT FAILED
(INSTALL SOP)

538 USA	152188	1 USA	Q21	V05	F5	505
---------	--------	-------	-----	-----	----	-----

INSTALL SOP SEAT BELT SEE PREV

763 USA	152014	2 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

CUSTOMER STATES REPLACE SOP
SEATBELT BUCKLE

573 USA	153782	1 USA	Q21	V05	F5	508
---------	--------	-------	-----	-----	----	-----

CUSTOMER STATES CENTER FRONT
SEAT BELT INOP INSTALL SOP

573 USA	153782 EB4	USA	Q21	V31	F5	501
---------	------------	-----	-----	-----	----	-----

C/S SEAT BELT LIGHT AND CHIME STAYS
ON WITH SEAT BELT ON.

901 USA 123002 2 USA Q21 V05 F5 908

PASS SIDE FRONT SEAT BELT WONT
BUCKLE

770 USA 121052 1 USA Q21 V05 F5 908

LEFT FRONT SEAT BELT BUCKLE WONT
LATCH

619 USA 172411 E34 USA Q21 V05 F5 908

CUSTOMER STATES SEAT BELT CHIMES STAYS
ON

569 USA 172491 2 USA Q21 V05 F5 908

DRIVERS SIDE SEAT BELT WILL NOT
LATCH PROPERLY

816 USA 171040 1 USA Q21 V05 F5 908

DRIVERS SIDE SEATBELT IS DIFFICULT
TO FASTEN

391 USA 182052 1 USA Q21 V05 F5 908

RECALL 01691 SEAT BELT

909 USA 171152 1 USA Q21 V05 F5 908

SEAT BELT MINDER WILL NOT GO OFF

520 USA 182951 E34 USA Q21 V05 F5 908

CUSTOMER STATES RIGHT FRONT SEAT
BELT WILL NOT LOCK PROPERLY, CHECK
OPERATION OF SEAT BELT.

916 USA 172209 2 USA Q21 V05 F5 908

CUSTOMER STATES SEAT BELT
WARNING CHIME WILL NOT GO OFF PART
IS HERE FOR DRIVER SIDE SEAT
REAR PASSENGER SEAT BELT BUCKLE IS
STICKING

809 USA 171151 1 USA Q21 V05 F5 908

DRIVERS FRONT SEAT BELT NOT
HOLDING DID NOT HAVE RECALL LISTED
ON QAS8

707 USA 172511 1 USA Q21 V05 F5 908

305 USA 168302 1 USA Q21 V05 F5 908

INSPECT DRIVERS SEAT
BELT,CUSTOMER STATES WHEN BELT
SECURED,BELL KEEPS RINGING,INSPECT
& REPORT

510 USA 172018 1 USA Q21 V05 F5 808

C @ PASS FRT SEAT BELT BUCKLE (NOF

928 USA 172220 2 USA Q21 V05 F5 808

CUST STATES SEAT BELT ONG HAPPENS
ALL THE TIME WHILE DRIVING AFTER IN
DRIVE (SEE JAMES HE SPOKE TO
CUSTOMER

779 USA 121021 1 USA Q21 V05 F5 808

CUST STATES SEATBELT LITE NOT
RESPONDING WHEN LATCHED

713 USA 152004 2 USA Q21 V05 F3 808

L F SEATBELT LOOSE

813 USA 163008 1 USA Q21 V05 F5 808

CUSTOMER STATES THAT DRIVERS SEAT
BELT WONT STAY BUCKLED CHECK AND
ADVISE
PASSENGER FRONT SEAT BELT WILL
NOT LATCH 3 30

805 USA 166301 1 USA Q21 V05 F5 808

802 USA 171179 884 USA Q21 V05 F5 808

CUSTOMER STATES PASSENGER SEAT
BELT IS LOCKING UP,
CUSTOMER STATES SEAT BELT LIGHT
COMES ON WHILE DRIVING, SOP

659 USA 172518 1 USA Q21 V05 F5 808

831 USA 172429 1 USA Q21 V05 F5 808

CUST STATES DRIVER SIDE SEATBELT
ALERT CHIME STAYS ON

881 USA 171491 1 USA Q21 V17 F5 808

CUST STATES DRIVER SEAT BELT BUCKLE COMES UNDOONE BELL STILL DINGS WITH DR SEAT BELT LOCKED G B HE CAN TWIST BASE OF BELT AND BELL WILL STOP	825 USA	172520	1 USA	Q21	V05	F5	808
INSTALL SOP SEAT BELT RIGHT REAR NEW CARS ORDERED	815 USA	123090	1 USA	Q21	V83	F5	808
	818 USA	163118	2 USA	Q21	V05	F5	808
DOOR CHIME COMES ON WHEN CUSTOMER DRIVING (INTERMITTANT)	808 USA	171424	1 USA	Q21	V08	F3	808
SEATBELT WARNING ALARMS WHEN SEAT BELT ARE LATCHED INTERMITTENT	838 USA	153244	1 USA	Q21	V83	F5	809
525 FT FT SEATBELT BUCKLE IS NOT WORKING	713 USA	159031	1 USA	Q21	V05	F5	808
CUST STATES DR. SEAT BELT WONT BUCKLE	770 USA	121018 E84	USA	Q21	V65	F5	808
CUSTOMER STATES THAT SEAT BELT ALARM OFTEN GOES OFF WHEN SEAT BELT IS ON	845 USA	113451	2 USA	Q21	V05	F5	808
REPAIR PASS SIDE SEAT BELT DOES NOT LATCH INTO PLACE BUCKLEW ORDERED AND IS IN PECIAL ORDER	780 CAN	486202	1 CAN	Q21	V05	F5	808
S21 INSTALL SOP PART FOR SEAT BELT LIGHT STAYING ON OK	737 USA	124202	2 USA	Q21	V05	F5	808

(828) CABT. STATES PASS. SIDE SEAT
BELT INOP.

868 USA 192772 1 USA Q21 V05 F5 806

RECOVER TO SEAT BELT INOP WILL NOT
CLICK OR HOLD

888 USA 192188 1 USA Q21 V05 F5 808

CK AND REPORT SEAT BELT WARNING
LIGHT STAYS ON THE CHIME RINGS ALL
THE TIMES
FRT DR SEAT BELT BUCKLE DOESNT
LATCH

810 USA 172483 2 USA Q21 V05 F5 808

897 USA 182274 1 USA Q21 V05 F5 808

PASS SEAT BELT BUCKLE DOES NOT
LATCH

813 USA 183116 E84 USA Q21 V05 F5 808

REPLACE RT FRONT SEATBELT WONT
LATCH
SEAT BELT REINFORCER KEEP ON AFTER
CONNECTED

808 USA 141818 1 USA Q21 V05 F5 808

888 USA 121895 2 USA Q21 V05 F5 808

O/S FRONT PASSENGER SEAT BELT
SOMETIMES INOP.....
SEAT BELT LIGHT IS ON AND STAYS ON
WILL GO OFF AND ON AND WILL DRG

830 USA 192719 E84 USA Q21 V05 F5 808 @

802 USA 171173 E84 USA Q21 V05 F5 808

CHECK REAR FEMALE SEATBELT ENDS,
ALL HAVE BEEN MESSING UP, ONE IS
JAMMED COMPLETELY.
GOD CHECK FOR PASSENGERS FRT
BUCKLE

701 USA 198402 2 USA Q21 V05 F5 806

807 USA 111947 1 USA Q21 V05 F5 806 @

SEAT LEFT SEAT BELT WILL NOT BUCKLE	812 USA	162300	1 USA	Q21	V05	F5	808
SEAT BELT WARNING LIGHT STAYS ON	908 USA	162104	2 USA	Q21	V05	F5	808
	847 USA	141418	1 USA	Q21	V05	F5	808
DRIVER SIDE SEATBELT BUCKLE INOP	423 USA	121480	1 USA	Q21	V05	F5	808
PASSENGER SEAT BELT INOP COMES UN BUCKLED	972 USA	158002 E84	USA	Q21	V05	F5	808
FRONT SEAT BELT WONT LATCH	480 USA	171178 E84	USA	Q21	V05	F5	808
PER CUSTOMER SEAT BELT CHAINS WILL NOT GO OFF AT TIMES UNLESS YOU HIT BUCKLE WITH YOUR HAND, DRIVER SIDE	423 USA	121887	1 USA	Q21	V05	F5	808
DRIVERS SEAT BELT WONT BUCKLE	612 USA	158009 E84	USA	Q21	V05	F5	808
DRIVERS SEAT BELT AT TIMES WILL NOT SNAP IN ADVISE GREG	205 USA	121016	2 USA	Q21	V05	F5	808

RIGHT FRONT SEAT BELT BUCKLE DOES NOT LOCK	558 USA	152184	1 USA	Q21	V05	F5	808
RT FRNT SEAT BELT WONT LATCH	528 USA	171483	1 USA	Q21	V05	F5	808
CUSTOMER STATES CENTER SEAT BELT DOESNT LATCH	808 USA	113480	1 USA	Q21	V05	F5	808
CUSTOMER STATES THAT THE PASSENGER SIDE FRONT SEAT BELT BUCKLE BUTTON IS HARD TO RELEASE	508 USA	113480	1 USA	Q21	V05	F5	808
DRIVERS SEATBELT CHIMES CONTINUOUSLY	397 USA	198221	1 USA	Q21	V55	F5	808
CUSTOMER STATES DRIVER SEAT BELT WONT FASTEN INTO BUCKLE	770 USA	121024 E94	USA	Q21	V05	F5	808
RIGHT FRONT SEAT BELT WONT LATCH	408 USA	182188	1 USA	Q21	V05	F5	808
CUSTOMER STATES THE PASS SIDE SEATBELT WILL NOT LATCH	210 USA	152732 E94	USA	Q21	V05	F5	808
PASS FORT SEAT BELT LOCKED WILL NOT RELEASE	508 USA	147022	1 USA	Q21	V05	F5	808
AIR BAG WARNING LIGHT ON	875 USA	153868	1 USA	Q21	V21	F5	810
PASS SIDE FRNT SEAT BELT WILL NOT LATCH 828	872 USA	152017	1 USA	Q21	V05	F5	808
DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	818 USA	171040	1 USA	Q21	V05	F5	808
REMOVE SEAT BELTS TO INSTALL IN VEHICLE THAT FAILED 01821 RECALL, REF. RO# 89287	708 USA	121444	1 USA	Q21	V05	F5	808
SEAT BELTS NOT LOCKING.	870 USA	123898	1 USA	Q21	V05	F5	808

C S PASSENGER SIDE FRONT SEAT BELT WILL NOT HOLD 840	813 USA	194802	1 USA	Q21	V05	F5	806
LF SEATBELT WILL NOT HOLD	881 USA	183888	1 USA	Q21	V05	F3	808
PASSENGER SIDE FRT SEAT BELT BUCKLE WILL NOT LATCH	788 USA	147118 EB1	USA	Q21	V05	F3	808
CAMPAIN 01821	410 USA	127547	1 USA	Q21	V05	F3	808
STATES THAT THE FRT SEATBELTS WILL NOT FASTEN PROPERLY	423 USA	147476	2 USA	Q21	V05	F5	806
OK FOR SEAT BELT WONT HOLD	943 USA	121821	1 USA	Q21	V05	F5	808
PERFORM RECALL 01821 LEFT BUCKLE PASSED, RIGHT BUCKLE FAILED.	208 USA	172300	1 USA	Q21	V05	F3	808
P S SEAT BELT DOES NOT LATCH PROPERLY	418 USA	148077	1 USA	Q21	V05	F3	808
CLST STATES PASS FRONT SEAT BELT BUCKE WILL NOT LATCH	782 USA	113148 EB4	USA	Q21	V05	F3	806
CLST STATES THAT THE DR SEAT BELT WILL NOT BUCKLE	804 USA	134805	1 USA	Q21	V05	F5	806
RECALL 01821 ALL OK	218 USA	144805	1 USA	Q21	V74	F5	806
PERFORM RECALL 01821 LEFT BUCKLE FAILED, RIGHT BUCKLE PASSED	208 USA	172300	1 USA	Q21	V05	F3	806
PERFORM RECALL 01821 LEFT BUCKLE FAILED, RIGHT PASSED	208 USA	172300	1 USA	Q21	V05	F5	806
C S SEAT BELT WWARNING CHIME KEEPS GOING OFF AFTER SEATBELT LOCKED	804 USA	194307	1 USA	Q21	V05	F3	806
RECALL 01821 ALL O.K.	218 USA	144805	1 USA	Q21	V74	F5	806
CHECK SEAT BELT IS HARD TO BUCKLE	612 USA	132754	1 USA	Q21	V05	F3	806
PASSENGER SEAT BELT DOES NOT LATCH SOMETIMES.	308 USA	141288	1 USA	Q21	V05	F5	808
SEAT BELT PASS SIDE NOT LOCKING IN 840	888 USA	148821 EB4	USA	Q21	V05	F5	808

PASS SEAT BELT LATCH ON WRONG SIDE	575 USA	132745	2 USA	Q21	V05	F5	808	
CUSTOMER STATES SEAT BELT LIGHT AND ALARM WILL GO OFF WITH SEATBELT FASTENED.	630 USA	144098	2 USA	Q21	V05	F5	808	
CUST STATES DRIVERS SEAT BELT HAS UNLATCHED 3 TIMES GOING DOWN HWY CK AND ADVISE WILL NOT LATCH AT THIS TIME	770 USA	121483	1 USA	Q21	V05	F5	808	
CUST STATES PASS SIDE SEAT BELT BUCKLE WILL NOT LATCH BOP IN DRIVERS SIDE SEAT BELT WILL NOT LATCH CORRECTLY	681 USA	123208 534	USA	Q21	V05	F5	808	●
	510 USA	172915	1 USA	Q21	V05	F5	808	
THE PASS SEAT BELT BUCKLE IS INOP NO RECALL	682 USA	171177 534	USA	Q21	V05	F5	808	●
AIR BAG LIGHT ON	518 USA	113158	1 USA	Q21	V05	F5	808	
CK FOR DRIVERS SIDE SEAT WILL RETRACK (LOW SPECIAL ORDER PARTS RECALL 01821 ALL O.K.	724 USA	144443	2 USA	Q21	V05	F5	808	
	216 USA	144805	1 USA	Q21	V74	F5	808	
	635 USA	183751	1 USA	Q21	V74	F5	808	
CUST STATES RIGHT FRONT SEAT BELT BUCKLE INOP.	808 USA	171182	1 USA	Q21	V05	F5	808	
RECALL 01821 ALL OK	216 USA	144805	1 USA	Q21	V74	F5	808	
WF SEATBELT WILL NOT LATCH PROPERLY	980 USA	153832	1 USA	Q21	V05	F5	808	
INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION DRIVERS SIDE NEEDS BUCKLE	520 USA	171204	1 USA	Q21	V05	F5	808	
CHECK SEAT BELTS NOT WORKING PROPERLY	761 USA	111067	1 USA	Q21	V05	F5	808	