

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 2 OF 6
BOOKS 26 OF 43

JOE MYER 388854	888200 8F02	1L7Z	7881202	AAA	Pass	13600 RIGHT FRNT SEAT BELT RECEIVER DOES NOT HOLD INSPECT FOUND CAN WIGGLE SEAT BELT AND WILL COME UNLATCHED. REPLACE SEAT BELT RECEIVER OK AFTER REPAIR. CO 42 INSPECTED AND REMOVED RIGHT SEAT TO REPLACE SEAT BELT BUCKLE AND RETESTED OK.
FRUTTS FC 9672581 *	8F02	1L7Z	7881202	AAA	Pass	
GUNSET F1384128	877888 8F02	1L7Z	7881202	AAA	Pass	REPLACE RIGHT FRONT SEAT BELT BUCKLE REMOVED SEAT FOR ACCESS AND REPLACED RIGHT FRONT SEAT BELT
MAXWELL 897084A	443800 8F02	1L7Z	7881202	AAA	Pass	PASS SIDE SEAT BELT INOP CHECK ALL BELT OPERATIONS, PASS BUCKLE INOP. REPLACED BELT BUCKLE
PERSON F 8533551	8887411 8F02	1L7Z	7881202	AAA	Pass	
BILL CUFF 48842101	878555 8F02	1L7Z	7881203	CAA	Drv	REPLACE LEFT SEATBELT BUCKLE 2044-42 CHECKED OPERATION OF LEFT FRONT SEATBELT BUCKLE, WILL NOT LATCH. REMOVED SEAT TO ACCESS. REPLACED SEATBELT BUCKLE, ASSEMBLED. RECHECKED. PASSED.
FRIENDLY 0851608	813500 8F02	1L7Z	7881203	BAB	Drv	
SUNSET F143841A	877888 8F02	1L7Z	7881203	CAB	Drv	REPLACE DRIVER SEAT BELT BUCKLE DRIVER SEAT BELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
MAGIC FC 1338731	286800 8F02	1L7Z	7881203	BAA	Drv	
BILL MOG 076434A	4281770 8F02	1L7Z	7881203	BAB	Drv	LF SEAT BELT COMES UNLATCHED TEST REPLACED BELT ASS
BABYLON 088860A	888322 8F02	1L7Z	7881203	BAB	Drv	REPLACED DRIVERS SIDE SEATBELT 784 PULLED B.O. PART, LEFT FRONT SEAT BELT BUCKLE. FRONT SEAT BELT BUCKLE. TESTED OPERATION, OKAY.
CUTTER F 884377A	4873811 8F02	1L7Z	7881203	CAB	Drv	
PIONEER 28003701	2571933 8F02	1L7Z	7881203	BAB	Drv	REPLACED SEATBELT. LATCH INOP AT TIMES, NOT HOLDING. REPLACED SEAT BELT LATCH.
LANDERS 11286001	888846 8F02	1L7Z	7881203	CAA	Drv	REPLACED DEFECTIVE LEFT FRONT SEATBELT BUCKLE THAT WOULD S OM TIMES UNLATCH ON ITS OWN 700 DRIVER INBOARD SEAT BELT BUCKLE RECEIVER WONT STAY LATCHED AT TIMES. FAILED TEST. INSTALLED NEW BUCKLE. TECH 4 COND CODE X2 BASKO 7881203
BELL FOR 7878001	8881776 8F02	1L7Z	7881203	BAB	Drv	BINDING. TEST AND REPLACE BOTH LEFT AND RIGHT SEATBELT BUCKLE ASSY REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE. ON 28 8802 0831.
SPALDING 138000A	2281800 8F02	1L7Z	7881203	BAB	Drv	LEFT SEATBELT WILL NOT STAY BUCKLED REPLACE BUCKLE END TO RESOLVE CONCERN
SOUTH PC 80888004	4471122 8F02	1L7Z	7881203	CAA	Drv	3181 DRIVERS BUCKLE NOT HOLDING FOUND DRIVERS BUCKLE NOT HOLDING BELT. REMOVED AND REPLACED SEAT BUCKLE (FEMALE END) CHECKS OK
ADVANTA 8100802	3084027 8F02	1L7Z	7881203	CAB	Drv	
FISHER-VI 2878501	8883541 8F02	1L7Z	7881203	CAA	Drv	
FREEDOM 2887288	8882871 8F02	1L7Z	7881203	CAA	Drv	
GILLESPIE 825851	5081000 8F02	1L7Z	7881203	BAB	Drv	SEAT BELT INOP REPLACED SEAT BELT
MOSS BRN 2142851	8881212 8F02	1L7Z	7881203	BAC	Drv	SEATBELT POPS OUT REPL. LH BUCKLE, NOT LATCHING

VILLA FOF	0150861	0378222	0902	1L7Z	7881208	BAA	Drvr	BELT INOP	M TIME TO TEST BUCKLE OPE REPLACE BUCKLE
SEGUN F	8066102	3031182	0902	1L7Z	7881208	BAA	Drvr	REMOVE REPLACE LEFT FRONT SEATBELT BUCKLE ASSEMBLY	
PLANET F	18044501	7183700	0902	1L7Z	7881203	BAB	Drvr	REPLACE DRIVERS SEAT BELT BUCKLE	
DON REID	1901851	8447111	0902	1L7Z	7881203	GAA	Drvr	INOP SEATBELT ASSEMBLY FRONT REPLACE	
DON BASH	31428901	8255141	0902	1L7Z	7881203	CAB	Drvr	INSPECTED AND REPLACED TWO SEATBELT BUCKLES REMOVED SEAT AND REPLACED THE SEATBELT FOR THE PASSENGER FRONT SEAT	
NORTH C	708084A		0902	1L7Z	7881202	AAA	Pagr	SEAT BELT REPLACED SEAT BELT BUCKLE	
KEN GROH	122552	8218881	0902	1L7Z	7881202	AAA	Pagr	R/R RIGHT FRONT SEAT R/R SEAT BELT BUCKLE REMOVED FRONT SEAT REPLACED SEATBELT LATCH ON PASS SIDE	
POLLARD	4418453	7973441	0902	1L7Z	7881202	AAA	Pagr	6608 REPLACED PASSENGER SEAT BELT RECEIVER AS PER MAINTENANCE, CCR37 TECH 307	
PALMETT	8484851	5713873	0902	1L7Z	7881202	AAA	Pagr	SEAT BELT INOP REPLACED PASSENGER SEAT BELT BUCKLE	
TOMMIE V	109043C	8084061	0902	1L7Z	7881202	AAA	Pagr	REP BELT BUCKLE RATTING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	
EL CENTR	8830851	3528000	0902	1L7Z	7881202	AAA	Pagr	SEAT BELT INOP REPLACED PASSENGER SIDE SEAT BELT	
SUNBELT	8981804	7787881	0902	1L7Z	7881202	AAB	Pagr	REPLACED SEAT BELT BUCKLE, NOISEY	
LANCERS	17288101	8822873	0902	1L7Z	7881202	AAA	Pagr	REPLACE SEAT BELT RT FRONT	
LIBERTY F	083043A	8481880	0902	1L7Z	7881202	AAA	Pagr	1 VERIFIED CONCERN, R AND R SEAT TO GAIN ACCESS, REPLACED BUCKLE, VERIFIED REPAIRS	
FOLSOM L	28377701	3532000	0902	1L7Z	7881202	AAB	Pagr	RR DRIVERS SIDE BUCKET ASSY PROBLEM WPI	
BUDGET F	84418801		0902	1L7Z	7881203	BAA	Drvr	ENTERED AT WPI	
BUDGET F	84074001		0902	1L7Z	7881203	BAA	Drvr	REPLACED THE BUCKLE	
HERTZ RA	51874901		0902	1L7Z	7881203	BAC	Drvr	REPLACED DRIVER SIDE SEAT BELT	
FORD MO	3888731		0902	1L7Z	7881203	CAA	Drvr	R AND R LF SEAT AND REPLACED SEAT BUCKLE	
MARONE	145501A	132	0902	1L7Z	7881203	CAA	Drvr	INSTALL MISSING DRIVERS SEAT BELT BUCKLE, O. C. S. M.	
WITT LINE	11490901	3588000	0902	1L7Z	7881203	CAB	Drvr	REPLACED SEAT BELT BUCKLE	
TODEY LI	6137001	8483333	0902	1L7Z	7881202	CAB	Drvr	RATTLE IN LEFT SEAT BELT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	
JOHN BLE	8047882	9418000	0902	1L7Z	7881203	BAA	Drvr	REPAIR DRIVER SEAT BELT TO LATCH	
BUERGER F	251371A	8282831	0902	1L7Z	7881203	CAA	Drvr	REPLACE ONE SEAT BELT BUCKLE	
AKINS FO	8280855	8878138	0902	1L7Z	7881203	BAA	Drvr	INSTALLED SOP FOR AIR BAG LIGHT	
TRI-COUN	61484301	2417333	0902	1L7Z	7881203	BAA	Drvr	18 W TECH 398, VERIFIED CONCERN, R/L DR SEAT TO GAIN ACCESS TO RR BAD SEAT BELT BUCKLE, R/T TEST, SEAT BELT LATCHES AND UNLATCHES AT THIS TIME QUALITY INSPECTED BY #888, 18	
MARCONI	323116A	8727200	0902	1L7Z	7881203	BAB	Drvr	SEAT BELT JAMMED	
KEYSTON	8448861	8880825	0902	1L7Z	7881203	CAB	Drvr	REPLACED DRIVERS SEAT BELT	

KRIEGER 3442868	8883320 BR02	1L7Z	7881208	BAC	Drvr
DOUG ST 144710A	2238850 BR02	1L7Z	7881203	BAA	Drvr
GREENW/ 108861	2783250 BR02	1L7Z	7881203	BAA	Drvr
LEE MOTT 254228A	2318000 BR02	1L7Z	7881203	BAB	Drvr
CARL GRI 3888101	8481101 BR02	1L7Z	7881208	BAB	Drvr
SUNBELT 0888703	7787881 BR02	1L7Z	7881203	BAB	Drvr
BAYVIEW 088754A	8387777 BR02	1L7Z	7881208	BAB	Drvr
DON KOT 8324883	8182800 BR02	1L7Z	7881208	BAA	Drvr
DOBBS FC 8001861	3885555 BR02	1L7Z	7881203	BAB	Drvr
DON DAM 424548B	2814881 BR02	1L7Z	7881203	BAA	Drvr
CHASE FC 038778C	2318100 BR02	1L7Z	7881208	BAC	Drvr
C. HARPE 044834A	9282900 BR02	1L7Z	7881203	BAA	Drvr
VANCOUV 390112A	8848501 BR02	1L7Z	7881208	BAA	Drvr
TED BRIT 3141881	8818484 BR02	1L7Z	7881203	BAB	Drvr
NORTH CI 88881501	2313491 BR02	1L7Z	7881203	BAB	Drvr
GARY EM 8885451	2444111 BR02	1L7Z	7881203	BAA	Drvr
GREEN W/ 8188783	4213300 BR02	1L7Z	7881203	BAC	Drvr
DOOK-W/ 14878401	7840405 BR02	1L7Z	78812818	AAB	Page
LLOVIO FC 888851	8877888 BR02	1L7Z	78812818	AAC	Page
ROUNTRE 18782501	7838830 BR02	1L7Z	78812818	AAA	Page

10180 CC B4 WARRANTY REPLACED DRIVER SIDE SEAT BELT BUCKLE AND SEATBELT WARNING PICTAL

1808 DRIVERS SIDE SEAT BELT BUCKLE SHORTED TO GROUND VERIFIED CONCERN. PERFORMED B O E SELF TEST. RECEIVED DRIVERS SIDE SEAT BELT BUCKLE CONCERN DTC. PERFORMED B G E PINPOINT TEST. FOUND DRIVE R8 COMING APART SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
REPLACED LEFT FRONT SEAT BELT ASSY
REPLACED BUCKLE ASSEMBLY

SEAT BELTS WILL NOT RETRACT
8071 REPLACE SEAT BELT BELT WAS BROKEN CODE 01 PART NO 1L7Z 7881203 BAB
CK LFT FT SEAT BELT OPER, FOUND FAULTY LFT FT SEAT BELT BUCKLE, REPLACED, RETEST, OK. NO CP CODE MT 81203 .7

INSTALLED SEATBELT REPLACED SEATBELT
3282 ELECTRICAL DIAG PIN POINT TEST RESTRAINT SYSTEM. FOUND DRIVERS SEAT BELT BUCKLE TO HAVE AN OPEN. R+R DRIVERS SEAT + REPLACE SEAT BELT BUCKLE. *** QUALITY CONTROL BY JOHN MEDROW ***
REMOVED & REPLACED LEFT FRONT SEAT BELT BUCKLE.
REPLACE DRIVER SEAT BELT

2077 WARR TESTED DR SEAT BELT BUCKLE ROAD TESTED 10 MILES LAMP WONT COME ON INSPECTED WIRE HARNESS AND NGS TESTED GEM NO CODES WORKS PROPERLY AT THIS TIME POSS INTERMITTLY SHORTING IN BUCKLE ORDER

INSTALL 80P SEAT BUCKLE LEFT FRT SEAT WARR 42
REPLACE DRIVERS SEAT BELT BUCKLE.
FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT
REPLACE SEAT BELT LIGHT COMES ON SEATBELT ASSEMBLY FRONT
REPLACE
1 INSPECT SEATBELTS REMOVE AND REPLACE RIGHT REAR SEATBELT
CUSTOM STATE THAT FRONT PASSENGER SIDE SEAT BELT BUCKLE IS INOP PART IS HERE..CAUSE: SEAT BELT BUCKLE..CORRE:
REPLACED DEFECTED SEAT BELT BUCKLE ..APROX TIME: 04 HR8
JOB STARTED 12.0123 ON 02 28 02
BROKEN LATCH. R & R PASSENGER FRONT SEATBELT LATCH.

SIDE SEAT BELT BUCKLE SHORTED TO GROUND, RM DRIVERS BUCKET SEAT FOR ACCESS. REPLACED DRIVER'S SIDE SEAT BELT BUCKLE. RETEST AND VERIFY REPAIR.

SEAT BUCKLE DR SIDE CUSTOM RETURNED FOR BUCKLE REPLACEMENT R R DR SEAT ASSY R R SEAT BELT BUCKLE ASSY REPLACED RETESTED OK AT THIS TIME CAUSAL # 7881203

RANCHO I 30587701	4501302	BR02	1L7Z	75512518	AAB	Page	REPLACED CENTER BUCKLE MISMATCHED.
PLANTATI 8652251	3643400	BR02	FM5Z	75512503	BBB	Drvr	REPLACE BOTH FRONT SEATBELT BUCKLES
ADVANTA 3853402	3054027	BR02	1L7Z	75512502	BAC	Page	REPLACE BOTH FRONT SEAT BELT BUCKLES FOUND STICKING.
FENTON F 0508208	4333800	BR02	1L7Z	75512502	AAC	Page	INSTALLED REVERSED SEAT BELT BUCKLES
JIM CLICK 37033501	7473000	BR02	1L7Z	75512502	AAB	Page	1 REPLACE SEAT BELT BUCKLES
WICKSTN 050807A	3810850	BR02	1L7Z	75512502	AAB	Page	1 INSTALL SOP SEAT BELT ENDS IN NEW CAR
MICALPINE 18157501	5410820	BR02	1L7Z	75512502	BAB	Page	DIAG & REPLACE RIGHT FRNT SEAT BUCKLE
ALBUQUE 3480001	2802200	BR02	1L7Z	75512502	BAB	Page	SEAT BELT BUCKLE VISIBLY BROKEN INTERNALLY. RMR SEAT
DON RICH 3000002	4525102	BR02	1L7Z	75512502	BAB	Page	BELT BUCKLE. 51172A.0.4
CERRITOS 9279001	0952025	BR02	1L7Z	75512502	BAB	Page	CK OUT INSP. TEST REPLACE FAULTY BELT
CERRITOS 25257402	0855554	BR02	1L7Z	75512502	AAA	Page	FAULTY RT SIDE BUCKLE SEATBELT BUCKLE DOESNT
KEN BRO1 4424251	4388171	BR02	1L7Z	75512502	BAB	Page	HOLD. REPLACED PASS SIDE BUCKLE NO RECALL ON VEHICLE
KEN BRO1 4424451	4388171	BR02	1L7Z	75512502	BAB	Page	WF DRND PERFORMED SEAT BELT RECALL RIGHT FRONT SEAT.
HLS CITY 5232052	2334520	BR02	1L7Z	75512503	BAA	Drvr	RIGHT SEATBELT WONT LATCH REPLACED RIGHT SEATBELT
NORTH BE 4378201	4211300	BR02	1L7Z	75512503	BAA	Drvr	BUCKLE
PALL MUF 3784250	9922151	BR02	1L7Z	75512503	BAA	Drvr	RIGHT SEATBELT WONT BUCKLE REPLACED RIGHT SEATBELT
NICHOLS 20348101	5353873	BR02	1L7Z	75512502	AAA	Page	BUCKLE
MIKE BRO 1273001	5731111	BR02	1L7Z	75512503	CAA	Drvr	INOP SEATBELT ASSEMBLY FRONT REPLACE
BOB TOM 11748501	8991010	BR02	1L7Z	75512503	CAA	Drvr	CO 42 ASG 75512503 REMOVED DRIVERS SIDE SEAT AND REMOVED
MULLINAX 332865A	4487500	BR02	1L7Z	75512503	CAA	Drvr	BUCKLE AND INSTALLED NEW AND RETESTED OK
GALPIN F 6286251	7573800	BR02	1L7Z	75512503	CAA	Drvr	BINDING REPLACED LEFT SIDE SEAT BELT BUCKLE
RED MCC 32850301	3484848	BR02	1L7Z	75512503	CAA	Drvr	REPLACE RT HAND SEATBELT.
GALPIN F 59873551	7573800	BR02	1L7Z	75512503	BAA	Drvr	CHGD OUT AND REPLACE SEAT BELT BUCKLE INOP WILL NOT
MIDDLEX 538822C	9453900	BR02	1L7Z	75512503	CAA	Drvr	LATCH
HALL FOR 295481A	8885700	BR02	1L7Z	75512502	AAA	Page	REPLACED SEAT BELT BUCKLE
HEINTZEL 198854A	2881000	BR02	1L7Z	75512503	BAB	Drvr	20503 INOP W 42 REMOVE DRIVERS SEAT AND REPLACE SEAT
ALLAN VIC 1620051	4717801	BR02	1L7Z	75512502	AAA	Page	BELT BUCKLE ASY. INOP
ADVANTA 5125801	3599588	BR02	1L7Z	75512503	BAA	Drvr	COCKS CHECKED OUT REPLACED DRIVERS SEAT BELT BUCKLE.
LAFAYET 8111851	4340851	BR02	1L7Z	75512503	BAA	Drvr	CO,01 BROKEN BASIC01203 REPLACE L F SEAT BELT
							REPLACE SEATBELTS WILL NOT LATCH
							5987 SEAT BELT LATCH INOP 51172A.4 REPLACED SEAT BELT
							LATCH
							PASSENGER SIDE SEATBELT WILL NOT HOLD, REMOVED
							PASSENGER FRONT SEAT TO ACCESS SEATBELT BUCKLE,
							REPLACED SEATBELT BUCKLE, NO LABOR OPG, USE M TIME
							11 SEAT BELT NOT LATCHING. 4 DR SEAT BELT BUCKLE NOT
							LATCHING. ORDERED NEW BUCKLE INSTALLED PROBLEM FIXED
							SEAT BELT BUCKLE INOP RMR PASS FRONT SEAT TO
							REPLACE SEAT BELT BUCKLE
							LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH. REPLACED
							SEAT BELT BUCKLE NOW OKAY. 04 03 08.21 08.49.
							REPLACED BUCKLE

NICHOLS 20347001	8563873	8F02	1L7Z	7881202	AAB	Pagr	REPLACE RIGHT SEAT BELT. FAULTY SEATBELT (81203) DIAGNOSIS AND REPLACED LF SET BELT BUCKLE
COVERT F 1042801	3454343	8F02	1L7Z	7881203	BAC	Drvr	R AND R DRIVERS SEAT FOR ACCESS, REPLACE BELT BUCKLE WONT LATCH.
BUNDET F 138880A	9778888	8F02	1L7Z	7881203	BAC	Drvr	RIGHT FRONT SEAT BELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
MEL CLAY 8208151	8828444	8F02	1L7Z	7881203	AAA	Pagr	OK AND REPLACED LEFT FRNT SEAT BELT BUCKLE ASSY.
FAIRWAY 187888A	2428888	8F02	1L7Z	7881203	CAB	Drvr	
CAPITRA 20162801	2407000	8F02	1L7Z	7881202	BAB	Pagr	INSPECT PASS SIDE SEAT BELT REPLACE DEFECTIVE SEAT BELT
TEXAN FC 248487A	8788100	8F02	1L7Z	7881202	AAA	Pagr	4828 FAULTY RT SIDE BUCKLE NEC TO REPLACE RT SIDE BUCKLE REPLACED SEAT BELT 01821 RECALL
KARL FLA 8823251	8375131	8F02	1L7Z	7881203	BAA	Drvr	7450 42 INOPERATIVE VERIFY RT SEATBELT NOT FASTENING REPLACE RT SEATBELT BUCKLE
CAMA FOF 288828A	7782272	8F02	1L7Z	7881202	AAA	Pagr	12182 W CHECKED DRIVERS SEAT SEATL OPERATION TO FIND FAULTY SEAT BELT BUCKLE ASY RLR BUCKLE ASY TO FIX CONCERN RETEST.
COURTES 084047A	5448111	8F02	1L7Z	7881203	BAC	Drvr	REPLACED LEFT FRONT SEATBELT
JENKINS J 078800A	8473883	8F02	1L7Z	7881203	BAC	Drvr	
BAY FOR 18187801	8784484	8F02	1L7Z	7881202	AAA	Pagr	FAULTY RECEIVER INSPECT AND REPLACE RECEIVER.
NICHOLS 20348801	8383873	8F02	1L7Z	7881202	AAA	Pagr	REPLACE RT HAND SEAT BELT.
NICHOLS 20353801	8383873	8F02	1L7Z	7881202	AAA	Pagr	REPLACE RT HAND SEAT BELT. 8687 DEFECTIVE SEAT BELT BUCKLE DRIVERS SEATBELT BUCKLE INTERMITTENTLY INOP. REMOVED AND REPLACED SEATBELT BUCKLE.
AUFFENB 088841A	2840330	8F02	1L7Z	7881203	CAA	Drvr	REPLACE RT HAND SEAT BELT.
NICHOLS 20428701	8383873	8F02	1L7Z	7881202	AAA	Pagr	INOPERATIVE REPLACE LEFT SEAT BELT BUCKLE
ASTRO FC 7888861	3888888	8F02	1L7Z	7881203	BAA	Drvr	
FRIENDLY 0871851	8707221	8F02	1L7Z	7881203	CAA	Drvr	BUCKLE SEATBELT ASSEMBLY FRONT REPLACE INSTALLED NEW SEATBELT BUCKLES
HERTZ RA 44888801		8F02	1L7Z	7881203	BAA	Drvr	8735 SOMETHING STICKY IN LATCH WARR REPLACE DRIVERS SEAT BELT BUCKLE
BEACH FC 447388A	4882717	8F02	1L7Z	7881203	BAB	Drvr	DRIVERS SIDE SEAT BELT BUCKLE WILL NOT LOCK REMOVED AND REPLACED. RECHECKED OPERATION. OK. USED M/TIME DUE TO NO LABOR OPERATION BEING FOUND.
CARL BLA 2538801	8873441	8F02	1L7Z	7881203	BAA	Drvr	0088 81202 42W R/L PASS SIDE SEAT AND REMOVED OLD SEAT BELT BUCKLE AND INSTALLED NEW ONE Y
WATSON 188244A	8887000	8F02	1L7Z	7881202	AAA	Pagr	DRIVERS SEAT BUCKLE STUCK REMOVE AND REPLACED BUCKLE
MOBBY FC 8848151	2788100	8F02	1L7Z	7881203	BAA	Drvr	REPLACE DRIVERS SEAT BELT BUCKLE
ASTRO LI 18888701	4788881	8F02	1L7Z	7881203	CAA	Drvr	6 TESTED SEAT BELTS AND INSTALLED BOTH LEFT AND RIGHT SIDE SEAT BELT LATCHES R/L'S
OKG AUTC 288432A	7388800	8F02	1L7Z	7881202	AAA	Pagr	REPLACE LEFT SEAT BELT BUCKLE NO TIME LISTED
SANTA FE 48888401	4882882	8F02	1L7Z	7881203	BAC	Drvr	REPLACE LF SEAT BELT BUCKLE 81172A (.4 HRS) LF SEAT BELT BUCKLE NOTHOLDING 81203 42
CRUICKS 10888002	2448881	8F02	1L7Z	7881203	CAB	Drvr	
GERMAIN 1887061	8878011	8F02	1L7Z	7881203	CAA	Drvr	BINDING TRACK ASSEMBLY FRONT SEAT REPLACE
DUB MILLI 7888482	2428811	8F02	1L7Z	7881202	AAA	Pagr	1 REPL BOTH FRONT SEAT BELT BUCKLES

JOE RIZZA/121231B	4020220	6R02	1L7Z	7861209	BAC	Drvr	REPL DRIVERS SEAT BELT BUCKLE W/1 ADD ON AUTHO BY AS NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
FAIRWAY 8410061	5841200	6R02	1L7Z	7861209	BAA	Drvr	
RAABE MK 043278A	6620035	6R02	1L7Z	7861202	AAO	Page	BUCKLE COMES LOOSE, REPLACE SO REPLACED PASSENGER FRONT SEATBELT THAT WAS BROK EN VERIFIED REPAIR CM
OKD AUTO 564062A	4762000	6R02	1L7Z	7861202	AAA	Page	
ANTELOPI 8762851	0463668	6R02	1L7Z	7861202	AAB	Page	BUCKLE FAILED REPLACED SEAT BELT 372 RECALL 02 TESTED AND REPLACED BOTH FRONT SEATBELTS
AUDUBON 186246A	2838900	6R02	1L7Z	7861202	AAB	Page	
FRIENDLY 7796561	8707221	6R02	1L7Z	7861209	BAB	Drvr	BUCKLE SEATBELT ASSEMBLY FRONT REPLACE VOLUNTARY FACTORY SAFETY RECALL. INSPECT AND REPLACE ONE SEAT BELT BUCKLE RIGHT RECALL 01821 01821 REPLACED PASS. SEAT BELT
LADIN LIN 4483201	4962189	6R02	1L7Z	7861202	BAB	Page	
ANTELOPI 8762461	0463668	6R02	1L7Z	7861202	BAB	Page	
CERRITCO 25476901	8656564	6R02	1L7Z	7861203	BAA	Drvr	01821 E BOTH BELT BUCKLES FAILED RPL BOTH BELT BUCKLES
CERRITCO 25477201	8656564	6R02	1L7Z	7861203	BAA	Drvr	01821 D DRIVER SIDE FAILED RPL DRIVER SIDE BUCKLE
CERRITCO 25483201	8656564	6R02	1L7Z	7861203	BAA	Drvr	01821 D DRIVER SIDE FAILED RPL DRIVER SIDE BELT BUCKLE
CERRITCO 25477301	8656564	6R02	1L7Z	7861202	AAA	Page	01821 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE PERFORM RECALL 01821D REPLACE PASSENGER SEAT BELT BUCKLE
CERRITCO 25706003	8656564	6R02	1L7Z	7861202	AAA	Page	01821 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE
CERRITCO 25477401	8656564	6R02	1L7Z	7861202	AAA	Page	38 01821D 0.8 INSP AND REPL FRONT SEAT BELT
GULLO FC 371104A	7587781	6R02	1L7Z	7861203	BAA	Drvr	
GALPIN FC 5825901	7873600	6R02	1L7Z	7861202	AAA	Page	RECALL 01821 SEATBELT PERFORMED 01821 SEATBELT RECALL 10 RECALL 01821D 0.8 PERFORM RECALL, INSPECT SEAT BELT BUCKLES AND REPLACE LEFT BUCKLE 30 01821D 0.8 INSP AND REPL SEAT BELT
GULLO FC 374825A	7587781	6R02	1L7Z	7861203	BAA	Drvr	
GULLO FC 371110A	7587781	6R02	1L7Z	7861203	BAA	Drvr	
GULLO FC 374808A	7587781	6R02	1L7Z	7861203	BAA	Drvr	31 INSTALL SEAT BELT LEFT SIDE 01821D 0.8 INSTALL SEAT BELT
TAMAM F 2845801	6433873	6R02	1L7Z	7861202	AAA	Page	1 INSPECT AND REPLACE R FRT SEAT BELT BUCKLE 14 INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL, REPLACED SEAT BELT RECALL 01821 RECALL PERFORMED RECALL, REPLACED SEAT BELT BUCKLE AT RIGHT FRONT AT TIME IS LBR TO REPLACE SEAT BELT BUCKLE ON DRIVERS SIDE PER 01821. NOTE VEHICLE NOT LISTED IN OASIS AS INVOLVED IN 01821 RECALL, BUT OPTED TO GO AHEAD AND REPLACE BUCKLE SINCE SAFETY ISSUE ON A NEW
AUDUBON 186252A	2838900	6R02	1L7Z	7861202	AAB	Page	
TEAM POF 4084551	3865100	6R02	1L7Z	7861203	BAB	Drvr	
SOUTH BV 8103351	6440211	6R02	1L7Z	7861202	AAA	Page	
LANDERS 5812701	8643873	6R02	1L7Z	7861203	BAC	Drvr	
HERITAGE 6181981	6295110	6R02	1L7Z	7861202	AAA	Page	REPLACED RIGHT SEAT BELT BUCKLE PER RECALL.
HERITAGE 6227651	6295110	6R02	1L7Z	7861202	AAA	Page	REPLACED RIGHT BIDE BUCKLE PER RECALL
NORTH ST 7773831	4738900	6R02	1L7Z	7861203	GAA	Drvr	REPLACE BOTH BELT BUCKLES BINDING

STOCK UNIT IS INVOLVED.

CLATHE L	5708151	7827820	6R02	1L7Z	7881203	CAA	Dvr
ALBUQUE	3061905	2802200	6R02	1L7Z	7881203	BAA	Dvr
BOMDEN	080270A	6848541	6R02	1L7Z	7881203	CAA	Dvr
RANCHO I	28198001	8891322	6R02	1L7Z	7881202	BAB	Page
NORTHWA	6483201	5394900	6R02	1L7Z	7881203	DAA	Dvr
NORTHWA	6483132	5394900	6R02	1L7Z	7881203	BAA	Dvr
WEST POI	33588301	5892811	6R02	1L7Z	7881202	BA5	Page
BANKSTO	2823504	2331441	6R02	*	7881203	*	Dvr
FT LAUDE	227783C	7798000	6R02	1L7Z	7881202	BAB	Page
KARL FLA	8829481	9378131	6R02	1L7Z	7881203	BAA	Dvr
LLOYD R	547251	8277888	6R02	1L7Z	7881203	BAA	Dvr
SANDERS	2878801	4661911	6R02	1L7Z	7881203	BAA	Dvr
COMMER	5482101	7888301	6R02	1L7Z	7881203	BAA	Dvr
KEN GRO	8333831	9218801	6R02	1L7Z	7881202	AAA	Page
GALPIN F	88719831	7873800	6R02	1L7Z	7881202	AAB	Page
DON DAVI	414804C	2814881	6R02	1L7Z	7881202	AAA	Page
MOSEY F	8570857	2788100	6R02	1L7Z	7881203	CAA	Dvr
CAPITAL F	1905751	7904800	6R02	1L7Z	7881203	BAA	Dvr
GALPIN F	8840871	7878800	6R02	1L7Z	7881203	BAA	Dvr
O. C. WEL	7360063	8243171	6R02	1L7Z	7881203	BAA	Dvr
GALPIN F	8858121	7873800	6R02	1L7Z	7881202	AAA	Page
WILLIAMS	222254A	2828411	6R02	1L7Z	7881202	AAA	Page
KARL FLA	8828081	8578131	6R02	1L7Z	7881202	AAA	Page
LDU BOB	8504851	6384005	6R02	1L7Z	78812516	AAC	Page
HOLMES T	23388201	2823800	6R02	1L7Z	7881203	BAA	Dvr
CROSSRC	28404801	4671851	6R02	1L7Z	7881202	AAB	Page
COLLEY	3688052	5834131	6R02	1L7Z	7881203	BAA	Dvr
ARMINST	8818252	9831831	6R02	1L7Z	7881203	BAA	Dvr

VERIFY CUSTOMER CONCERN SEATBELT ASSEMBLY FRONT
 REPLACE
 SEAT BELT IS BINDING DUE TO TWISTING REPAIR UNBIND LEFT
 FRONT SEAT BELT REEL

REPLACE SEAT BELT BUCKLE ASSY
 INSPECT,REPLACED R BUCKLE L BUCKLE OK.
 REPLACE BOTRH FRONT SEAT BELT BUCKLES
 SEAT BELTS INOP SEATBELT ASSEMBLY FRONT
 REPLACE
 SEAT BELT BUCKLE PASSENGER SIDE INOPERATIVE REPLACE
 PASSENGER SIDE SEAT BELT BUCKLE INOPERATIVE
 SEAT BELT BCKLE WRONG WAY, 07 81203 VERIFY CUSTOMERS
 CONCERN SEAT BELT BUCKLE TURN THE WRONG
 WAY,STRAIGHTEN OUT SEAT BELT BUCKLE.
 REPLACE SEAT BELT BUCKLE
 INOP REPLACED BOTH FRONT SEAT BELT
 BUCKLES
 GUST STATE THE DRIVER SIDE SEAT BELT BUCKLE IS INOP
 CAUSE: SEAT BELT CORRE: REPLACE
 SEAT BELT BUCKLE
 UNTWISTED SEATBELT AND REPLACED BUCKLE

GM REPLACE 2 BELTS
 BINDING SEAT BELT ASSEMBLY REAR RIGHT OR
 LEFT REPLACE
 REPLACE SEATBELTS WILL NOT LATCH PROPERLY
 5857 LOOSE REPLACE LOOSE RF SEAT BELT BUCKEL
 *****QUALITY CONTROL BY JAMES PENNOCK*****

SEAT BELT BUCKLE INOP LIGHT ON BODY CHASSIS ELECTRICAL
 (SCE) TEST REPLACED SEAT BELT BUCKL
 SEAT BELT REPLACED DRIVERS SEAT BELT
 ASSEMBLY
 CCF12 REPLACE SEATBELT BUCKLES
 REPLACED LEFT AND RIGHT SEATBELTS.
 SEAT BELTS WONT LATCH REPLACE BUCKLES
 REPLACE BROKEN SEAT BELT

REPLACED SEAT BELT

INOP SEATBELT ASSEMBLY FRONT REPLACE
 1 REPLACE BELT BUCKLE
 REPLACE SEAT BELT

PERFORMED RECALL: REPLACED AND RETEST LEFT HAND
 SEATBELT
 LFT FRT SEAT BELT BINDS SEATBELT ASSEMBLY FRONT
 REPLACE

APPROX TIME: 0.4 HRS
 JOB STARTED: 7:58.7 ON
 01 23 02

RC04-011 08441

SIM WALL 4777864	8830383 6R02	1L7Z	7881202	AAA	Page	RECALL	REPLACE RT FT BUCKLE
NICHOLS 20341101	8888878 6R02	1L7Z	7881202	AAB	Page	REPLACE RT SIDE BELT. 1216 7881203 28 WTY RAN BODY CHASSIS ELECTRICAL TEST AND PINPOINT TEST AND DIAGNOSE AND REPLACED DRIVERS SEAT END RELEASE SEAT BELT BUCKLE ASSY.FOUND THAT IT HAD INTERMITTENT INOP SWITCH INTERNALL	Y, RETEST AND OK
DON BOH 2808900	3477800 6R02	1L7Z	7881203	BAB	Drv	SEAT BELT WONT HOLD REPLACED DRIVERS SEAT BELT	
VELDE PD 18870101	8883400 6R02	1L7Z	7881208	BAB	Drv		
TAMMAM F 2836101	8433873 6R02	1L7Z	7881202	AAB	Page	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE SEATBELT MAKES NOISE SEATBELT ASSEMBLY FRONT REPLACE	
ORANGE 1 1828051	8533881 6R02	1L7Z	7881203	GAA	Drv		
TAMMAM F 2838801	8433873 6R02	1L7Z	7881202	AAC	Page	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE CC140 REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSY	
GALPIN FC 8088821	7873800 6R02	1L7Z	7881202	AAB	Page		
TAMMAM F 2834001	8433873 6R02	1L7Z	7881202	AAB	Page	1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE REPLACE BUCKLE	
BUDGET F 88488801	8R02	1L7Z	7881203	BAA	Drv	REPLACED SEAT BELT	
JENKINS J 738841	8473833 6R02	1L7Z	7881203	BAC	Drv	REPLACE SEAT BELT	
CLAUDE C 28488801	3753214 6R02	1L7Z	7881202	AAA	Page	CONFIRMED CUSTOMER CONCERN, REPLACED SEATBELT ASSEMBLY	
MILFORD 3488781	8731700 6R02	1L7Z	7881202	AAA	Page	NEC TO REPLACE SEAT BELT	
GREENE F 188882Z	8325820 6R02	1L7Z	7881202	AAA	Page	4170 R/R PASSENGER FRONT SEAT R/R FEMALE SEAT BELT B UCKLE REPLACED & REINSTALLED SEAT REMOVED SEAT AND REPLACED SEAT BELT LATCH REPLACED BUCKLE ASSY WIRES WERE PINCHED CUTTING INTO SEAT TRACK	
KIP KILLM 718828A	4480100 6R02	1L7Z	7881203	GAA	Drv	1 REPLACED SEAT BELT BUCKLE PER RECALL	
STONEHA 088888A	4380480 6R02	1L7Z	7881202	AAA	Page	REPLACED RIGHT SIDE SEAT BELT	
CAPISTRA 22147301	2407000 6R02	1L7Z	7881203	BAB	Drv		
HOLMES 1 23888801	2883800 6R02	1L7Z	7881203	BAA	Drv		
CROSSRC 22284201	4871881 6R02	1L7Z	7881202	AAA	Page		
SMITH MC 4288801	8883737 6R02	1L7Z	7881203	BAC	Drv	CHECK AND REPLACE SEAT BELT LEFT SIDE SEAT BELT BUCKLE	
DOMINO F 173733A	3883000 6R02	1L7Z	7881203	BAC	Drv	REPLACED LEFT FRONT SEAT BELT	
BAYVILLE 40172001	8884800 6R02	XL2Z	7881203	AAC	Drv	REPLACED DRIVERS SIDE SEAT BELT	
GALPIN FC 8383221	7873800 6R02	1L7Z	7881203	BAC	Drv	CC467 PERFORMED RECALL 01821D	
FORT DOX 114858C	8787303 6R02	1L7Z	7881202	AAB	Page	REPLACE SEAT BELT BUCKLE, PASSENGER SIDE.	
HERTZ NJ 83084801	8R02	1L7Z	78812816	AAA	Page	REPLACED THE BUCKLE DIAG INSP VERIFIED CONCERN AND REPLACED BOTH SEAT BELT BUCKLES	
LARRY GE 832801	8812121 6R02	1L7Z	7881203	BAB	Drv		
BOB TURP 27888801	7888800 6R02	1L7Z	7881203	BAB	Drv	REPLACED SEAT BELT	
GALPIN FC 88874401	7873800 6R02	1L7Z	7881203	BAB	Drv	REPLACE SEATBELT WILL NOT LATCH PROPERLY	
GALPIN FC 8818201	7873800 6R02	1L7Z	7881202	AAA	Page	CC008/121 REPLACE RT SIDE SEAT BELT BUCKLE	
CANADIAN 008288A	7880100 6R02	1F2Z	1881203	BAB	Drv	R/R THE LEFT FRONT SEAT BELT BUCKLE.	
PEARSON 3838801	4750480 6R02	1F2Z	1881203	AAB	Drv	DIAGNOSE AND REPLACE L/F SEAT BELT	
MCCOY & 818882A	8885501 6R02	1F2Z	1881202	AAB	Page	PASS FRT SEAT BELT WONT LATCH REPL BUCKLE AND TEST	
HERTZ NJ 88037701	8R02	1F2Z	1881203	AAB	Drv	REPLACED THE BUCKLE	

DAHL FOF118087A	3912800	8R02	1FZ2	1881202	AAA	Pagr	INSPECT. RELEASE BUTTON IS STUCK. REPLACE BUCKLE
BUDGET I 281381		8R02	1FZ2	1881202	AAB	Pagr	FOUND SEAT BELT DIF RR BUCKLE SEAT BELT
BUDGET F 88188201		8R02	1FZ2	1881202	AAA	Pagr	INTERNAL FAULT IN BUCKLE INSTALLED NEW BUCKLE ASSY
HERTZ RJ 44482701		8R02	1FZ2	1881202	AAB	Dvr	REPLACED SEAT BELT BUCKLE
HERTZ RA 48081801		8R02	1FZ2	1881202	AAA	Pagr	REPLACED THE BUCKLE
SIMMONS 070188A	3244444	8R02	1FZ2	1881202	BAB	Dvr	PER SEAT BELT BUCKLE NOT LATCHING
COLUMBI 017880A	4828891	8R02	1FZ2	1881202	AAA	Pagr	REPLACE BELT WONT LATCH
DON LAFF 8837281	4248580	8R02	1FZ2	1881202	AAA	Dvr	L RIGHT FRONT SEAT BELT BUCKLE
JOE MACI 31335801	4434411	8R02	1FZ2	1881202	BAB	Dvr	DIAG. CODE B2434, B2282, B2286. DIAG. AIR BAG SYSTEM.
WOLTZ & 7803861	2794551	8R02	1FZ2	1881202	AAB	Pagr	REPLACED LEFT SEATBELT. RETEST. TECH 147 VERIFY CONCERN PERFORM AIR BAG DIAG REPLACE SEAT BELT RECHECK OK
EDWARD E 8885701	5482211	8R02	1FZ2	1881202	BAB	Dvr	DUPLICATE FAULT, NGS, RETRIEVE DTC, RETEST, REPAIR OBSTRUCTIONS, PIN TEST, RE-REPLACE RR SEAT BELT BUCKLE ASSY OPEN CIRCUIT.
LASALLE F 8285001	3633673	8R02	1FZ2	1881202	BAB	Dvr	TEST PIN POINT TEST SHORT TO GROUND REPLACE BUCKLE
MONTMOR 125315A	8788940	8R02	1FZ2	1881202	BAB	Dvr	8885 VERIFIER BOUCLE DE CEINTURE AVANT GAUCHE NE OLENCHÉ PAS RAPPORT PRENDRE BOUCLE SUR AUTRE AUTO VEUNE ET REMPLACER VERIFIER OK
EASTWAY 10825201	8315080	8R02	1FZ2	1881202	AAA	Dvr	DIAG FOR AIR BAG LIGHT ON, CODE B2432, MTS1208 .8 HR TO TRACE OPEN CIRCUIT, DRIVERS SIDE BUCKLE SWITCH OPEN, REPLACED DRIVERS SEATBELT BUCKLE
NORTHPC 088041A	4825300	8R02	1FZ2	1881202	AAA	Dvr	
GORING B 213748B	8782200	8R02	1FZ2	1881202	AAB	Dvr	8241 PERFORMED AIR BAG DIAG RETRIEVED CODE B2432 PERFORMED DCL MONITOR TEST PERFORMED PINPOINT TEST ACCESS CARPET RR SEAT TRACED WIRING FROM ROM TO SEAT BUCKLE NO PROBLEM FOUND R&R SEAT BELT BUC HOOKED UP NGS AND FOUND CODE B2432 WENT THROUGH PINPOINT TEST DEACTIVATED AIR BAG LITE SYSTEM AND STARTING TO CK CONNECTIONS UNDER PASSENGER SEAT FOUND SEAT BELT BUCKLE CONNECTOR TO BE BROKEN NEEDS NE INSTALLED SEAT BELT BUCKLE
BILL BART 104758B	8639884	8R02	1FZ2	1881202	AAB	Pagr	
HERTZ RA 88018801		8R02	1FZ2	1881202	AAA	Dvr	KLE CLEARED CODE RETESTED VERIFIED REPAIR \$ 3810
PLAZA PO 138872A	2432721	8R02	1FZ2	1881202	AAB	Dvr	R AND R DRIVERS SEAT BELT ASSEMBLY
GALPIN FY 8072721	7873800	8R02	1FZ2	1881202	AAA	Dvr	SEATBELT WILL NOT LATCH PROPERLY REPLACE SEATBELT
ISLAND FC 148818A	7813673	8R02	1FZ2	1881202	AAA	Dvr	REPLACED SEAT BELT
TASGA FC 118288E	4387706	8R02	1FZ2	1881202	AAB	Pagr	8276 .8 REPLACED BOTTOM BUCKLE
MARCONI 087911A	2785888	8R02	1FZ2	1881202	AAA	Dvr	14279 184...CK AIR BAG SYSTEM PERFORM AIRBAG DIAGNOSTICS. PERFORM PIN POINT TESTS FOR CODE B2432. REPLACE DRIVER SEAT BUCKLE AND REPAIR PINCHED AND WITH SEAT TRACK, 42
SEXTON F 4482991	7973811	8R02		1881202		Pagr	CUT WIRES UNDER DRIVER SEAT. HARNESS MADE CONTACT 1881202
HERTZ RA 82884001		8R02	1FZ2	1881202	AAB	Pagr	AIR BAG RESTRAINT SYSTEM DIAGNOSIS R R RF SEAT BELT BUCKLE ASSY

COURTES 47824302	7944849	6R02	1FZ2	1881208	BAA	Drv
SPRONCE 8908791	4731411	6R02	1FZ2	1881208	AAB	Drv
HERTZ RJ 68084301 *		6R02	1FZ2	1881203	AAB	Drv
CROSBY 24868801	4871881	6R02	1FZ2	1881203	BAB	Drv
BUDGET F 981411 *		6R02	1FZ2	1881203	AAB	Drv
MEL CLAY 9448881	8822444	6R02	1FZ2	1881203	BAB	Drv
JOHN M. L0874030	8718800	6R02	1FZ2	1881208	BAA	Drv
HERTZ RJ 58083401 *		6R02	1FZ2	1881202	AAB	Page
BOFFICI 418818A	3444100	6R02	1FZ2	1881202	AAB	Page
HERTZ RJ 68089801 *		6R02	1FZ2	1881208	AAB	Drv
GUTTER F 288973A	4872811	6R02	*	1881203	*	Drv
MARSHAL 183882C	4481000	6R02	1FZ2	1881208	BAB	Drv
KENOSHA 30425301	8872134	6R02	1FZ2	1881202	AAB	Page
MILLER BF 4883801	4881300	6R02	1FZ2	1881202	AAB	Page
MILLER BF 4807901	4881300	6R02	1FZ2	1881202	AAB	Page
LUCAS MC 18740301	3883100	6R02	1FZ2	1881202	AAB	Page
UNIVERS/212383A	2812800	6R02	1FZ2	1881202	AAA	Page
SPRINGFI 18748201	6440700	6R02	1FZ2	1881203	AAB	Drv
MONAHAN 050818F	8834895	6R02	1FZ2	1881203	AAB	Drv
CAMERON 13888002	3803673	6R02	1FZ2	1881202	AAB	Page
FAMILY FC 7288861	3473000	6R02	1FZ2	1881202	AAA	Page
COLUMBI 018887D	8251880	6R02	1FZ2	1881203	BAA	Drv
CUTTER F288881A	4872811	6R02	1FZ2	1881203	BAB	Drv
RON BLAC 8140782	2738082	6R02	1FZ2	1881203	BAA	Drv

PERFORM DIAG FOR SEAT BELT LIGHT COMING ON UNMARRANTED WITH NGS MONITORED PIDS. REPLACED INOP SEAT BELT. 1
REPLACED DRIVER'S SEATBELT BUCKLE
REPLACED SEAT BUCKLE

AIR BAG DIAGNOSIS, CODE 1285, REMOVED AIR BAG MODULE, AND DRIVER'S SEAT ASSEMBLY TO PIN POINT TEST DRIVER'S SEAT OPEN OKT. CLEAR CODE
OPEN CIRCUIT IN LF SEATBELT BUCK BODY CHASSIS ELECTRICAL (BCE) TEST

REPLACED LT FRONT SEAT BELT
R AND R BUCKLE WITH NEW

TEST AIR BAG SYSTEM, PINPOINT AND FOUND PASS SIDE SEAT BELT REQUIRES REPLACEMENT, ORDER PART, REPLACE AS NEC.
REPLACED THE SEAT BELT BUCKLE
REMOVED LF SEAT BELT TO TAKE CARE OF CURT GUERRERO VIN # 18818750 RO # 288829 INSTALLED NEW SEAT BELT BUCKLE TEST OPERATION, O.K.

5108 BDC TEST NO LITE CODE B228R PINPOINT REPLACE LEFT SIDE BELT PRETENSIONER
TESTED TO FIND CODE B2258, REPLACED RIGHT SIDE FRONT SEATBELT ASSY. TESTED.O.KAY
NGS AIR BAG TESTS CODE B2282, PINPOINT TESTS, REPLACED PASS BUCKLE AND PRETENTIONER

NGS AIR BAG DIAG.CODE B2282, TEST PASS PRETENTIONER CIRCUITS, REPLACED PASS.BUCKLE AND PRETENTIONER, RETEST SEAT BELT. PERFORMED AIR BAG DIAGNOSTICS CODE B2282 PERFORMED PINPOINT TEST TRACED TO AND REPLACED PASSENGER SEAT BELT RETRACTOR

AIRBAG DIAG.MONITOR PIDS.REPLACED RIGHT FRONT SEAT BELT BUCKLE HIGH RESISTANCE.TIGHTENED TERMINALS IN CONNECTOR.RETEST
BEC TEST,MONITOR PIDS,PINPOINT TEST,REPLACE L S SEAT BELT BUCKLE,CLEAR CODE AND RERUN BELT TEST
13882 1H VERIFY, NEEDS LATCH ASSEM. REMOVE FROM NEW VEHICLE AND INSTALL ON UNIT. ORDER NEW ONE FOR UNIT THAT PARTS WAS ROBBED FROM. INSTALL NEW SEAT BELT LATCH ON NEW UNIT THAT PART WAS ROBBED FRO

M.

INSPECT AND REPLACE RIGHT FRONT SEAT BELT BUCKLE.
REPLACE SEAT BELT ASSY RP WONT LATCH
REPLACE BOTH SEAT BELT FOR INTER. OPER.

8834 REMOVE AND REPLACE LT FRN BUCKLE,QUALITY CHECK OK
REPLACE SEAT BELT BUCKLE ASSEMBLY

DI BLASI I	16971402	2868100	6F02	1FZZ	1661203	BAA	Drvr
MONTCLA	7849481	7488900	6F02	1FZZ	1661203	BAB	Drvr
JIM XAMIS	6864031	7822111	6F02	1FZZ	1661203	AAA	Drvr
TEAM FOF	4041281	8025100	6F02	1FZZ	1661203	AAA	Drvr
RANDALL	2179493	4469171	6F02	1FZZ	1661203	BAB	Drvr
BLUGWAT	4366102	7842223	6F02	1FZZ	1661202	AAB	Page
MIKE BAS	8610250	6948501	6F02	*	1661202	*	Page
MEGINNIS	4813201	4640661	6F02	1FZZ	1661203	BAB	Drvr
WELCOME	2294001	8083400	6F02	1FZZ	1661202	AAB	Page
DAMPDGI	2211001	4724123	6F02	1FZZ	1661203	AAB	Page
DELAQUA	4229702	7462057	6F02	1FZZ	1661203	AAB	Drvr
SUNSHINE	734101	6464488	6F02	1FZZ	1661202	AAB	Page
RICHPORT	665608A	2737231	6F02	1FZZ	1661202	AAB	Page
AVENUE F	6786401	6661220	6F02	1FZZ	1661203	BAB	Drvr
AUTO DEE	646401	3288044	6F02	1FZZ	1661203	BAA	Drvr
GEORGE I	14847102	4781606	6F02	1FZZ	1661203	BAA	Drvr
WORONA	9874701	3462310	6F02	1FZZ	1661203	BAA	Drvr
AUTOMOE	6691204	6716116	6F02	*	1661203	*	Drvr
P. E. BONS	260246A	6661301	6F02	1FZZ	1661203	BAA	Drvr
CHAREST	3318802	6673386	6F02	1FZZ	1661203	BAA	Drvr
AUTO VILL	2780601	6294823	6F02	1FZZ	1661203	BAB	Drvr
AUTO BOI	4167201	7734376	6F02	1FZZ	1661204	BAB	Drvr
HUNT CLL	6421301	7230850	6F02	1FZZ	1661203	BAB	Drvr
SHAMAMA	111217A	6038000	6F02	1FZZ	1661203	BAA	Drvr
PERNOVAL	1688682	5435410	6F02	1FZZ	1661203	BAA	Drvr

VERIFIED CONCERN FOUND BUCKLE PART NO GOOD JAMMED
 DRIVERS SEAT REPLACE SEAT BELT RETESTED OPERATION ALL
 OK
 REPLACE LEFT FRONT SEAT BELT BUCKLE

INOPERATIVE SEATBELT ASSEMBLY FRONT REPLACE
 BUCKLE REPLACED SEATBELT BUCKLE
 CHIR DOES NOT OPERATE PROPERLY MILES IN 8288 MILES OUT
 8230 TESTED DRIVERS SEATBELT BUCKLE FOUND BUCKLE WOULD
 NOT LATCH REPLACED BUCKLE AND RETESTED NOW BUCKLE
 WORKS PROPERLY
 CHECKED OUT PASS. FRNT SEATBELT WONT STAY LOCKED IN R/R
 NEW SEATBELT.CLIP.
 COMPLETE RECALL
 R/R SEAT FOR ACCESS BECAUSE OF CONVERSION. REPLACED
 SEAT BELT BUCKLE. REPLACED SHOULDER ADJUSTER FOR SAME
 SEAT. BROKEN.

NBS TESTED FROM CODE B648. DIAG AND REPLACE RIGHT FRNT
 SEATBELT BUCKLE. RETEST & CLEAR CODES
 TESTED SEAT BELT LATCH FEMALE END FOUND VERY HARD TO
 UNLATCH. INTERNAL PROBLEMS IN LATCH.REPLACED FEMALE
 LATCH ASSEMBLY.RETESTED OK NOW.

CODE CHECK B648 REPLACE RT SIDE SEAT BELT BUCKLE
 1120 NBS TEST B648 PINPOINT TEST PASS SEAT BELT BUCKLE
 SWITCH OKT OK RE AND RE PASS FRONT SEAT AND REPLACED
 SUSPECT BUCKLE CLEAR CODE RD TEST WITH SEAT BELT
 LATCHED UNLATCHED RETEST SYSTEM PASS
 164 VERIFIER PAS LA BONNE PIECE RECOMMANDER BUCKLE
 DRIVER SEAT. 129 CHANGER SEAT BELT ET VERIFIER OK
 REPLACE SEAT BELT GAUCHE NE RETRACTE PAS
 REPLACE BUCKLE ASSY
 DID SCE TEST, PIN POINT TEST,REPLACED DRIVER'S SEAT BUCKLE
 AND DID FINAL QUICK TEST

REINSTALLER LE TRIM DE BOUCLE
 TEST AND REPLACE DRIVER SEAT BELT BUCKLE DONG LIGHT SR8
 WARNING LIGHT

REMP LACER CEINTURE AVANT GAUCHE
 CHANGE LES 2 CEINTURES AVANT DEFECTUEUSE
 REMPLACER CEINTURE AVANT GAUCHE
 DIAG CODE B642 PINPOINT TEST RE RE SEAT REPLACED SEAT
 BELT BU CKLE(42)
 DIAG, REPLACE LEFT FRONT SEAT BELT BUCKLE
 AIR BAG SYSTEM DIAG REPLACE DRIVERS FRONT SEATBELT
 BUCKLE(42)

MIKE PRU 210507A	2243873	8F02	1F2Z	1881203	AAA	Dvr
COLE/STC 079817A	2785581	8F02	1F2Z	1881203	AAA	Dvr
NORTH ST148215B	7273873	8F02	1F2Z	1881202	AAA	Pgr
GRIFIN F 16701601	9864548	8F02	1F2Z	1881203	AAB	Dvr
ABLE FOR 140209B	7880700	8F02	1F2Z	1881202	AAA	Dvr
WEST-HE 127212B	8488840	8F02	1F2Z	1881203	AAA	Dvr
HAGERST 32002883	7388873	8F02	1F2Z	1881203	AAA	Dvr
ROSEMUF 11747882	8467337	8F02	1F2Z	1881203	BAA	Dvr
HERTZ RA 43288001 *		8F02	1F2Z	1881203	AAA	Dvr
MULLANE 8118101	3868500	8F02	1F2Z	1881202	AAA	Pgr
FRIED BEA 28888201	3482800	8F02	*	1881205	*	Dvr
CAPITAL C 081820B	8838460	8F02	1F2Z	1881203	BAB	Dvr
MIDDLEK 634808A	8833500	8F02	*	1881202	*	Pgr
MIDDLEK 388884A	8833500	8F02	1F2Z	1881202	AAA	Pgr
ANTIOCH 1414051	7571771	8F02	1F2Z	1881208	BAB	Dvr
BILL ESTE 038278A	8822231	8F02	1F2Z	1881202	AAB	Pgr
MCLARTY 1888888	7827121	8F02	1F2Z	1881203	BAA	Dvr
JIM BASS 8819401	8488821	8F02	1F2Z	1881203	AAA	Dvr
KIP KILLM 722418A	4480180	8F02	1F2Z	1881203	AAA	Dvr
TREADW 28888801	4783361	8F02	*	1881202	*	Pgr
RON TONI 084612A	2882800	8F02	1F2Z	1881203	BAB	Dvr
MONACO 170880C	8833000	8F02	1F2Z	1881203	BAA	Dvr
BEACH FC 1384782	8888888	8F02	1F2Z	1881203	BAB	Dvr
RON BLAC 8138881	3738882	8F02	1F2Z	1881202	AAA	Pgr

REPLACED DRIVERS SIDE SEAT BELT CHECKED FOR PRO PER OPERATION OK
 DIAG. REPALCE OPEN CIRCUIT IN DRIVER SEAT BELT
 8147 HAVE TO ORDER PARTS

DIAGNOSE AND REPLACE LOCK PAML
 OPEN CIRCUIT IN BUCKLE, AFTER PINPOINT TEST, REPLACED BUCKLE AND CLEARED AND RETESTED.
 3848 BUCKLE STICKS SEAT BELT BUCKLE ON DRIVERS SEAT STICKS AND HARD TO GET BELT OUT, REPLACED SEAT BELT BUCKLE 8 WAY POWER SEAT.

DIAGNOSIS REMOVED AND REPLACED DRIVERS SEATBELT

STRIP CAME OFF REPLACED NEW BELT
 REPLACED THE BUCKLE

TEST SYSTEM CODES B2438 REMOVE RT FRONT SEATTD ACES AND CHECK CIRCUIT FOR PINPOINT TEST RT FRONT BUCKLE OPEN CIRCUIT IN ATALL SEAT BELT BUCKEL CLEAR CODES
 81203 888 28 CHECKED OVER B REPLACED CONNECTOR AT R FRONT SEAT BELT BUCKL
 REPLACED SWITCH IN BUCKLE ASSEMBLY JAMMED
 4818 PASS. SIDE SEAT BELT BUCKLE SHORTED 140580 .5 HRS. 888A .2 HRS. .7 HRS. 80P
 8482 A BAG LIGHT FLASHES CODE B2 140580 81171A A BAG D.G. REPLACE PASS SEAT BELT
 CODE 81 RUN DIAG TEST DRIVERS SEAT BELT RECEIVER SWITCH OPERATION REPLACE
 8784 PASSENGER SEAT BELT SWITCH AND P VERIFIED CONCERN RESTRAINT DIAGNOSIS RETRIEVED 88488 PINPOINT TEST P
 REPLACED PASSENGER FRONT SEAT BUCKLE ASSEMBLY AND RETESTED
 NQS TEST, RETRIEVE CODES FROM AIR BAG SYSTEM, CODE E 8888, WENT TO PPM POINT TEST FOUND OPEN CIRCUIT ON DRIVERSIDE SEATBELT BUCKLE, REMOVE SEAT AND REPLACE BUCKLE
 1 REPLACE LEFT FRT SEAT BELT BUCKLE
 8888 ESC TEST DRIVERS SEAT SHOR TO GROUND R R DRIVER S POWER SEAT, R R TRIM PANNEL ON SIDE OF SEAT TO GET ACCESS TO FEMALE END OF SEAT BELT BUCKLE, FOUND SHORTED WIRE, R R SEAT BELT BUCKLE REPLACED
 GET SEAT BELT LATCH OUT OF SEAT ON 3RD ROW 1 VERIFIED, NEEDS SEAT BELT BUCKLE, REPLACE BUCKE L OK AT THIS TIME
 CHECK FOR CAUSE OF AIR BAG LAMP, PAN SYSTEM SELF TEST CODE 88488 FOLLOWED PINPOINT TEST AND REPLACED THE LF SEAT BELT BUCKLE.
 REPLACED SEAT BELT BUCKLE, TESTED SAT.
 TEST FOR CODES REPLACE SEAT BELT BUCKLE

WITH NEW ONE & REINSTALLED ALL PARTS REMOVED

HERTZ RA 4420001 *	0F02	1F2Z	1001203	AAA	Drv	REPLACED THE BELTS
IPSWICH 10641000	0042910 0F02	1F2Z	1001200	BAA	Drv	RUN AIR BAG DIAG, RUN PIN POINT TEST L., TEST AND REPLACE DRIVERS SEAT BUCKLE, CLEARED CODES RETEST ED OK VERIFY, SCAN CHECK, CODE B 0022, DRIVERS SEAT BELT BUCKLE SWITCH OPEN, REPLACE DRIVERS SEAT BELT BUCKLE, CLEAR CODES, TEST DRIVE OK.
WOLF FO1 1901	2333000 0F02	1F2Z	1001200	BAA	Drv	ROAD TESTED VEH. VERIFIED CONCERN, PERFORMED NBS DIAG MONITORED FIDS, FOUND DRIVERS SEAT BELT BUCKLE SHOWING REMOVED DRIVER SEAT, REPLACED SEAT BELT BUCKLE, RETEST OPS AS DESIGNED, CP 1001200
HUNTING 1070001	0320400 0F02	1F2Z	1001200	BAB	Drv	DRVR SEAT BELT BCKT SW OPEN CKT. REPL
BUDGET F 4144001 *	0F02	1F2Z	1001202	AAB	Pagr	MT TIME TO CHECK OUT REASON AND REPLACE BUCKLE
DUNPHY I 10187701	0240700 0F02	1F2Z	1001202	AAB	Pagr	REPLACED THE DRIVERS BUCKLE
HERTZ RA 42141401 *	0F02	1F2Z	1001200	AAA	Drv	OPEN RESISTOR. REPL BELT AND BUCKLE
BUDGET F 0810201 *	0F02	1F2Z	1001200	BAA	Drv	1001200 41 REMOVE DRIVER SEAT TO REPLACE DRIVER SEATBELT BUCKLE HAS BUCKLE HAS HARNESS NOT WORKING PROPERLY BODY CHASSIS ELECTRICAL (BCE) TEST
CROWN F 1600301	2443015 0F02	1F2Z	1001200	BAB	Drv	DIAGNOSE AIRBAG SYSTEM PINPOINT FOUND BAD SENSOR IN BUCKLE ASSEMBLY OF SEAT BELT REPLACED BUCKLE LATCH ASSEMBLY RETEST
L. B. SMITH 0644001	7010700 0F02	1F2Z	1001202	AAB	Pagr	FAULTY LFT.PRT. SEAT BELT BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS
PREMIER 101021A	0771204 0F02	1F2Z	1001200	BAB	Drv	BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS
STERLING 3334001	0255900 0F02	1F2Z	1001200	BAB	Drv	PUT ON WDS RUN TEST CODE B0432 PINPOINT TEST FO UND LEFT FRONT BUCKLE MISSING INSTALLED NEW BUD KLE RERUN TEST PASS
JAMES FC 0732001	7443311 0F02	1F2Z	1001200	BAB	Drv	COND CODE 42 TEST AIR BAG SYSTEM CODE FOR SEAT BELT SYSTEM PINPOINT TO RT FRONT SEAT BELT BUCKLE AND REPLACE
THOMAS / 080701A	0220000 0F02	1F2Z	1001200	BAB	Drv	T01 BUCKLE CK STUFF GONE INSIDE BUCKLE GET CODES O P #20 RNR LEFT FRONT SEAT BELT BUCKLE ASSEMBLY W/ POOR CONNECTION AT SEATBELT PERFORM BELTTEST, PINPOINT TEST, REPAIR CONNECTION AT SEATBELT BUCKLE
BOS THO 4421001	2017000 0F02	1F2Z	1001202	AAB	Pagr	REPL RH FT SEAT BELT BUCKLE
TOM BOL / 04027A	2210300 0F02	1F2Z	1001200	AAA	Drv	SEAT BELTS NOT WORKING MILEAGE
LYNCH FC 4707151	0200000 0F02	*	1001202	*	Pagr	ENTERED IN ERROR
LEWIS FO 724351	4420001 0F02	1F2Z	1001200	AA	Drv	REPLACED DRIVERS SEAT BELT
FORD OF 0030001	7320000 0F02	1F2Z	1001200	AAA	Drv	REPLACE SEATBELT BUCKLE
HERTZ CA 2100001 *	0F02	1F2Z	1001200	AAB	Pagr	
MOORVE 7000400	0001000 0F02	1F2Z	1001200	AAA	Drv	
POINT PL 0101001	0000000 0F02	1F2Z	1001202	AAA	Pagr	
AUBURN 140402A	7042321 0F02	1F2Z	1001200	BAB	Drv	10008 VERIFIED CONCERN REMOVED 2 BOLTS THAT HOLD DOWN LEFT SIDE OF DRIVERS SIDE SEAT BASE, TIPPED SEAT BASE TO UNPLUG WIRING TO SEAT BELT LATCH, AND REMOVED WIRING, REMOVED 1 BOLT THAT HOLDS LATCH
						REINSTALLED NEW SEAT BELT, REROUTED WIRING PLUGGED IN, REBOLTED SEAT DOWN, WORKS NORMALLY --LTS

TENVOOR 181888A	2810540 6R02	1LSZ	1081202	AAA	Page
T E CLAFS 414480D	6532121 6R02	1LSZ	1081203	AAA	Drv
KOCH FCJ 28455401	4348411 6R02	1LSZ	1081203	AAA	Drv
HANSEN F 818484A	7488411 6R02	1LSZ	1081203	AAA	Drv
AUFFENB 089008B	2340330 6R02	1LSZ	1081203	AAA	Drv
EBY FORI 151881A	2543873 6R02	1LSZ	1081202	AAA	Page
MARCOTT 172885A	5381803 6R02	1LSZ	1081203	AAA	Drv
WILLEY R 12411701	2240585 6R02	1LSZ	1081203	AAA	Drv
AL CIONI F 1808101	3382811 6R02	1LSZ	1081203	AAA	Drv
MCDONNE 8781801	2480840 6R02	1LSZ	1081203	AAA	Drv
COURTES 053847A	5448111 6R02	1LSZ	1081203	AAA	Drv
BUDGET F 673181 *	6R02	1LSZ	1081203	AAA	Drv
BO LOVEN 884481	2882058 6R02	1LSZ	1081202	AAA	Page
RAY WHI 088378A	8910800 6R02	1LSZ	1081203	AAA	Drv
MCCOY & 817084A	5286601 6R02	1LSZ	1081203	AAA	Drv
BUDGET F 78088101 *	6R02	1LSZ	1081203	AAA	Drv

8347 INSPECTED ALL SEAT BELTS AND BUCKLES FOR PROPER OPERATION COLD NOT VERIFY CONCERN ALL BELTS AND BUCKLES ARE OPERATING PROPERLY AT THIS TIME NO PROBLEM FOUND REPLACED RIGHT FRONT BUCKLE ASSY AS

PER SHOPFOREMAN

LED S.O.P. SEAT BELT BUCKLE W PYROTECHNIC DEVICE; DEACTIVATED SRS, REMOVED LH SEAT ASSY FOR ACCESS TO RESTRAINT BUCKLE. REMOVED AND INSTALLED NEW BUCKLE, SECURED ELECTRICAL AND

7777 INSPECTED LH FRONT SEAT ACTIVE RESTRAINT FOR ERRATIC BUCKLE OPERATION INTERMITTENT CONCERN VERIFIED AND APPROVED SVC DIR. FOR RECEIVER REPLACEMENT, S.O.P. RH 80 40 SEAT BELT BUCKLE. INSTAL INTERM WONT LATCH 41 REPLACED LF SEAT BUCKLE WITH PRETENSIONER C0407

DIAGNOSE INSPECT AND FOUND LEFT FRONT SEAT BELT BUCKLE WILL NOT CLIP AND LOCK, INSPECT FOR FOREIGN OBJECTS, NONE PRESENT, REMOVE LEFT F SEAT TO GAIN ACCESS TO REPLACE LEFT FRONT SEAT BELT BUCKLE AND 8802 LF SEAT BELT WILL NOT LATCH, CHECKED, FOUND BAD BUCKLE, ORDERED NEW BUCKLE. DEACTIVATED AIR BAG SYSTEM, REMOVED LF SEAT, R R SEAT BELT BUCKLE LF, REINSTALLED SEAT, REACTIVATED AIRBAG SYSTEM, O 1288 C042 REPLACED RIGHT FRONT PRETENSIONER SEAT BELT BUCKLE, OPERATED PROPERLY
REPLACED SEAT BELT, WONT LATCH
1 FOUND DRIVERS SIDE SEATBELT BUCKLE JAMMED, REMOVED DRIVERS SIDE SEAT FROM VEHICLE AND REMOVED AND REPLACED SEATBELT
REPLACED LEFT FRONT SEAT BELT BUCKLE. WILL NOT ALWAYS LATCH

REINSTALL ALL REMOVED COMPONENTS AND RECHECK FOR PROPER OPERATION, ALL OK USED MIT TIME AS NO LABOR OF IN SLTS FOR 81203

CHECKED,

REPLACE LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH
1188 W88 INSP VEHICLE FOUND R H SEAT BELT NOT LATCHING, REMOVED SEAT REPLACED SEAT BELT LATCH.
FOUND PART OF THE LATCHES MISSING PART FAILURE DUE TO PART FATIGUE REPLA
CK & FOUND SEATBELT BAD REPLACED & RECHECKED OK
8833 42 W PERFORMING AIR BAG DIAG, ON DEMAND, PID DATA MONITOR TESTS, NO COOKS. PERFORM PINPOINT TESTS FOUND LT FRT SEAT BELT WITH PRETENSIONER INOP. REMOVE LT FRT SEAT ASSEMBLY TO ACCESS AND REPLACE
DRIVERS BUCKLE INOP BROKEN. REMOVED DRIVERS SEAT
REMOVED OLD BUCKLE INSTALL NEW BUCKLE AND SEAT AND TEST

LT FRT SEAT BELT AND PRETENSIONER ASSEMBLY AND RETEST, OKAY,

INSTALLED THE NEW SEAT BELT BUCKLE

GORNO B 221307C	5752200 6R02	1LSZ	1061202	AAA	Page	9739 INSTALL NEW SEATBELT TESTED NEW SEATBELT DONE 0864
BILL SUDR 3282461	5322400 6R02	XL5Z	1061203	CEB	Drvr	REPLACED DRIVERS SIDE LATCH
KIBTLER P 18306802	5818911 6R02	1LSZ	1061203	AAA	Drvr	41 STICKING REPLACED SEAT BELT BUCKLE
FRONTIER 48251	393105 6R02	1LSZ	1061203	AAA	Drvr	INOP SEATBELT ASSEMBLY FRONT REPLACE
MTN. VIEW 225125A	7561331 6R02	1LSZ	1061203	AAA	Drvr	2897 DRIVERS SEAT BELT LATCH OKED THE SEAT BELT SYSTEM AND R THE DRIVERS SEAT AND REPLACED THE SEAT BELT LATCH
MAC HAK 187225A	8925500 6R02	1LSZ	1061202	AAA	Page	3089 C/O #1202 RR RIGHT FRONT SEAT REPLACE RIGHT SEAT BELT BUCKLE FOR BEING INOP
MEL CLAY 3462851	2841611 6R02	1LSZ	1061203	AAA	Drvr	REPLACE BROKEN DRIVER SIDE SEAT BELT BUCKLE
RICART F 406042C	3632673 6R02	1LSZ	1061202	AAA	Page	0153 42 REMOVED THE PASSENGER SEAT TO REPLACE THE SEAT BELT LATCH 8851
BAUDIN F 6287062	7312121 6R02	1LSZ	1061202	AAA	Page	SEAT BELT BUCKLE INOP REPLACE RIGHT FRT SEAT BELT BUCKLE
GENE MEI 13894801	3557471 6R02	1LSZ	1061202	AAA	Page	RAN DIAG ON SEAT BELTS. R&R RIGHT FRONT SEAT. REPLACED SEAT BELT BUCKLE ASSY. TECH 601
BOB TOW 070383A	4864014 6R02	1LSZ	1061203	AAA	Drvr	REPLACED SEATBELT ASSY
BLEVINS F 4582701	2570200 6R02	1LSZ	1061202	AAA	Page	INSTALLED PS STAT BUCKLE
NICHOLS 22768202	3983673 6R02	1LSZ	1061202	AAA	Page	1 REPLACED RIGHT SEAT BELT BUCKLE
HOLMES 1 3611052	2922600 6R02	1LSZ	1061203	AAA	Drvr	STICKS BINDS OR GRABS MECHANISM INSIDE OF BELT BUCKLE IS BROKEN REPLACED SEAT BELT WORKS GOOD
RIFON FO 4084401	7467777 6R02	1LSZ	1061203	AAA	Drvr	INSPECT AND REPLACE PASS. SEAT BELT BUCKLE RECH ECK OK VERIFY CONCERN IN TIME ID TO REPLACE DRIVER SEAT BELT BUCKLE REMOVE SEAT TO REPLACE REASSEMBLE AND VERIFY REPAIRS
DREW FO 3778862	4847777 6R02	1LSZ	1061203	AAA	Drvr	42 REP PRETENSIONER
OLATHE F 7233161	7620821 6R02	1LSZ	1061203	AAA	Drvr	SEATBELT WONT LATCH TRACK ASSEMBLY FRONT SEAT REPLACE
ORANGE I 2428051	5883581 6R02	1LSZ	1061203	AAA	Drvr	VERIFIED CONCERN BELT BUCKLE WONT STAY LATCHED ALL THE TIME REPLACED BUCKLE
ULTIMATE 1380701	5762385 6R02	1LSZ	1061202	AAA	Page	
SHEEHY F 20402104	2581018 6R02	1LSZ	1061202	AAA	Page	RR SEAT COVER TO REPL SEATBELT AND BUCKLE ARMY
SEGUN F 6173901	3031182 6R02	1LSZ	1061203	AAA	Drvr	1 REMOVE REPLACE LEFT FRONT SEATBELT ASSEMBLY
SEGUN F 6206801	3031182 6R02	1LSZ	1061202	AAA	Page	1 REMOVE REPLACE RIGHT SEATBELT BUCKLE ASSEMBLY LEFT SEATBELT REPLACED PREVIOUSLY
TULSA AU 61846803	6347101 6R02	1LSZ	1061203	AAA	Drvr	DRIVE SEAT BELT WILL NOT STAY BUCKLED CC 42 REMOVE DRIVE SEAT AND REPLACE BUCKLE ASSEMBLY PARTS TURNED INTO T.L. QUALITY CHECKED BY GARY H.
MOSSY FC 6810251	2760100 6R02	1LSZ	1061203	AAA	Page	REPL FRT SEAT BELT
DON SANI 87074822	6458800 6R02	1LSZ	1061202	AAA	Page	REPLACED SEATBELT ASSY AND USE IN TIME TO REPLACE BUCKLE RETEST OK AFTER REPAIR
HELFSAN 4825451	2403573 6R02	1LSZ	1061203	AAA	Drvr	REPLACE LF SEAT BELT WITH RECALL BUCKLE
WOODHO 161338A	4254129 6R02	1LSZ	1061202	AAA	Page	WDS AND TEST RUN PIN POINT TEST R&R RIGHT SIDE SEAT BELT ASSEMBLY.

BRONDEE 8836481	4731411 6R02	1LSZ	1081202	AAA	Drv
LATHAM I 7154202	7884101 6R02	1LSZ	1081202	AAA	Pagr
VALLEY P 12848801	7782801 6R02	1LSZ	1081202	AAA	Pagr
ATCHINSC 08121581	8878101 6R02	1LSZ	1081202	AAA	Pagr
GAYLORD 1881801	7325737 6R02	1LSZ	1081202	AAA	Drv
CAM CLAF 116784A	8373838 6R02	1LSZ	1081202	AAA	Pagr
COLUMBU 017104A	4833831 6R02	1LSZ	1081202	AAA	Drv
MCALLIST 080181A	8837344 6R02	1LSZ	1081302	AAA	Pagr
WEST-HE 100573A	8885484 6R02	1LSZ	1081202	AAA	Pagr
WANKATO 8744451	8873454 6R02	1LSZ	1081202	AAA	Drv
FARLEY & 8828101	4881220 6R02	1LSZ	1081202	AAA	Drv
BRIAN HO 10672301	3844242 6R02	1LSZ	1081202	AAA	Drv
BUDGET F 41883001 *	6R02	1LSZ	1081202	AAA	Pagr
SHELDON I 18800301	3822801 6R02	1LSZ	1081202	AAA	Drv
BUDGET F 88384301 *	6R02	1LSZ	1081202	AAA	Drv
RICART P 781547B	8385321 6R02	1LSZ	1081302	AAA	Pagr
SUBURBA 28178202	8744781 6R02	1LSZ	1081202	AAA	Drv
HALDEMA 18198201	8887800 6R02	1LSZ	1081202	AAA	Pagr
BUDGET F 80088801 *	6R02	1LSZ	1081202	AAA	Drv

ARI BAG RESTRAINT SYSTEM DIAGNOSIS
 REPLACED PASSENGERS SIDE SEATBELT
 REPL SEAT RETRACTOR AND HANDLE
 MT TIME TO REMOVE SEAT AND REPLACE SEAT BELT
 PRETENSIONER.

VERIFIED CONCERN. PERFORMED RESTRAINT CONTROL MODULE
 DIAG AND MONITORID PIDS AND PERFORMED PINPOINT TEST,
 FOUND LEFT FRONT BUCKLE ASSEMBLY NEEDED. REMOVED LEFT
 FRONT SEAT ASSEMBLY, DISASSEMBLED AND REP
 LACED PRETENSIONER,
 REASSEMBLED AND
 RETESTED OK.

REPLACED PASSENGER SIDE SEAT BELT BUCKLE.
 REPLACE BELT BUCKLE ASSEMBLY WIRE CIRCUIT OPEN
 REPLACED DRIVERS SEAT HANDLE TO CORRECT PROBLEM
 O CHECK PASS. SEAT BELT BUCKLE INOP., CHECK OPERATION OF
 PASS. SEAT BELT BUCKLE, VERIFIED COMPLAINT. BUCKLE IS
 BROKEN, REMOVED PASS. FRONT SEAT AND REPLACED SEAT
 BELT BUCKLE, ASSEMBLE AND CHECK OP

ERATION, OK.

SEAT BELT BUCKLE BAD 3RD (QUICK TEST) DIAGNOSIS

ROAD TESTED CONFIRMED PROBLEM PERFORMED ELECTRICAL
 SELF TEST ON RESTRAINT SYSTEM AND SYSTEM PASSED
 CHECKED OASIS FOUND NOTHING CALLED HOTLINE CHECK

SEATBELT PAGER DRIVER PRTEM OPEN AFAM CHCK AND TEST
 FUME BOTH SEAT BELT

HING. CHECK OPER OF
 SWITCH AT C3014 AND
 INTERNAL SWITCH IN
 BUCKLE. THERE WAS NO
 APARENT SHORTS IN
 HARNESS. SHORT IS
 INTERNAL TO DRIVERS
 SEATBELT BUCKLE
 ASSEMBLY. REPLACED.
 OPERATING PROPERLY
 NOW

INTERNAL SHORT OF CIRCUIT 85 IN DRIVERS SEATBELT BUCKLE
 ASSEMBLY VERIFIED CONCERN CHECKED FOR STORED
 CONTINUOUS CODES, NONE PRESENT. MONITORED SEATBELT
 BUCKLE SWITCH PID TO GEM NOT RESP TO BUCKLE LATO
 OPEN CIRCUIT CHECK OUT IN FOUND OPEN IN PRETENSIONER
 REPLACE DRIVER
 887 D AND L SEALERS REMOVE AND REPOSITION LEFT DOOR
 SEAL

WP INOP 42 1081202 REPLACE DRIVERS FRONT SEAT BELT
 BUCKEL PRETENSIONER
 R/R RIGHT FRONT SEAT AND REPLACE BUCKLE, AND CLEAR
 CODE. 1
 REPLACE PRETENSIONER ASSY WP1

CUTTER F 273958A	4573811	8F02	1L5Z	1081203	AAA	Drvr
YADKON V.091037A	8384165	8F02	*	1081202	*	Page
FOR-CAR 021777A	3318111	8F02	1L5Z	1081203	AAA	Drvr
WINDWAF 8588885	2887000	8F02	1L5Z	1081203	AAA	Drvr
BUDGET F 8888701 *		8F02	1L5Z	1081203	AAA	Drvr
HASTINGI 090707A	7580114	8F02	1L5Z	1081202	AAA	Page
BOB-BOYL 11831101	8641122	8F02	1L5Z	1081203	AAA	Drvr
FULLER P 181141A	8588500	8F02	1L5Z	1081203	AAA	Drvr
BUDGET F 8888121 *		8F02	1L5Z	1081203	AAA	Drvr
BUDGET F 8408171 *		8F02	1L5Z	1081203	AAA	Page
JOHN CHV 4634858	3784811	8F02	1L5Z	1081203	AAA	Drvr
LAMARQU 181205A	4432500	8F02	1L5Z	1081202	AAA	Page
FLAMMER 8888201	8888255	8F02	1L5Z	1081203	AAA	Drvr
HALL FOR 287818A	8888700	8F02	1L5Z	1081203	AAA	Drvr
BUDGET F 8008201 *		8F02	1L5Z	1081202	AAA	Page
SOUTHGA 8131240	8888535	8F02	1L5Z	1081202	AAA	Page
ATASCAD 5811101	4888484	8F02	1L5Z	1081203	AAA	Drvr
BUDGET F 81122801 *		8F02	1L5Z	1081203	AAA	Drvr
BUDGET F 8784081 *		8F02	1L5Z	1081202	AAA	Page
SANDERS 3218408	4381911	8F02	1L5Z	1081203	AAA	Drvr

6488 CUSTOMER STATES AIR BAG LIGHT COMES ON. PERFORM AIR BAG SYSTEM DIAGNOSIS, DTC B1877 DRIVERS SEATBELT PRETENSIONER CIRCUIT OPEN. CHECK WIRING AND CONNECTIONS TO PRETENSIONER, OKAY. REMOVE DRIVE AIR BAG DIAGNOSIS CODE B1877. PINPOINT TEST. REPAIR/LOOSE WIRE AT PRETENSIONER CONNECTOR

R8 SEAT AND REPLACE SEAT BELT BUCKLE PRETENSIONER ASSEMBLY. CLEARED CODES AND RETEST. OKAY. (28) PERFORM QUALITY CHECK.

888 DRIVERS PRE TENSIONER VERIFIED CUSTOMER CONCERN, HOOKED UP NGS TO PULL CODES FROM PCM, FOUND CODE B1877, PERFORMED PASSIVE RESTRAINT PINPOINT TEST T FROM SERVICE MANUAL, FOUND PRE TENSIONER DE NO AIRBAG LIGHT ON, TESTED AIRBAG SYSTEM WITH NGS, PULLED CODE B1877, CHECKED FAILURE CLEAR CODE, RETESTED ON DEMAND ALL PASS, MONITORED PID ALL WITHIN SPECS, ROAD TESTED AIRBAG LIGHT CAME ON, PULLED RR SEAT BELT BUCKLE ASSY

FECTIVE, RM LEFT FRONT SEAT, R/R BUCKLE PRE TENSIONER, CLEARED CODE FROM PCM, TESTED FOR PROPER OPERATION CODE B1877 LEFT PRETENSIONER CIRCUIT OPEN, REPLACED LEFT FRONT SEATBELT

100 PASS FRONT SEAT BELT INOP REPLACED PASS FRONT SEAT BELT BUCKLE DUE TO NOT WORKING PROPERLY 42 881202 CHECK OUT PROBLEM CODE B1885 PROBLEM IN DRIVER SEAT BUCKLE CHECK PIN POINT TEST REPLACE INSPECTED DRIVERS SIDE SEAT IT WAS LOOSE AND THE SEAT BELT BUCKLE WAS MISSING. NEEDED TO INSTALL A SEAT BELT BUCKLE AND PUT THE SEAT BACK SERP BELT INTERNAL FAILURE. REPL RF SEAT BELT INOP, LATCH INOP, REPLACED BUCKLE DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE

7009 28 WARR. VERIFIED CONCERN AIRBAG LIGHT ON. NGS TEST AND RETRIEVED CODE B1881 PASSENGER SEATBELT PRETENSIONER OPEN. R RIGHT FRONT SEAT AND REPLACED SEATBELT BUCKLE. CLEARED CODE. ALL OK. PRETENSIONER VERIFIED CONCERN, DIAG & TEST, NEG TO REPLACE SEATBELT PRETENSIONER, RETEST O.K. VERIFY CONCERN, 880 TEST CODE FOR OPEN IN SEAT BELT TENSIONER. MONITORED PIDS FOUND RESISTANCE AT 3.8OHMS. REMOVED DRIVERS SEAT BENCH. REPLACED SEAT BELT PRETENSIONER. NO LABOR OPS TO R AND R DRIVE AIRBAG LIGHT STAY ON SUSPECT PASS SEAT BELT INTERNAL FAILURE REPLACED BELT REPLACE RR FT BUCKLE WITH PRETENSIONER PERFORMED DIAGNOSIS AND REPLACED SEATBELT TRACED PROB TO AN INTERMITTANT FAULT IN DRIVER PRETENSIONER REPLACE PRETENSIONER FAULTY PAS PRETENSIONER. REPL BUCKLE REPLACED SEAT BELT

R BENCH SEAT FOR ACCESS

COURTES	8076102	588000	8R02	1L5Z	1061203	AAA	Drv
BULLMAN	4884401	3881100	8R02	*	1061202	*	Page
BUDGET F	83488201	*	8R02	1L5Z	1061202	AAA	Page
CENTER A	1810401	5883861	8R02	1L5Z	1061203	AAA	Drv
UNIVERS	8128452	8829171	8R02	1L5Z	1061203	AAA	Drv
MARCOONE	508885A	8727200	8R02	1L5Z	1061202	AAA	Page
BUDGET F	838801	*	8R02	1L5Z	1061203	AAA	Drv
TOWN & C	088888B	4725454	8R02	1L5Z	1061202	AAA	Page
BUDGET F	8880431	*	8R02	1L5Z	1061202	AAA	Drv
JOHN BLE	7874721	8418000	8R02	1L5Z	1061203	AAA	Drv
BUDGET F	88830001	*	8R02	1L5Z	1061202	AAA	Page
BOB TOW	8458851	3851414	8R02	1L5Z	1061203	AAA	Drv
TOWN EA	787874B	2788441	8R02	1L5Z	1061203	AAA	Drv
PLANET F	18288101	7183700	8R02	1L5Z	1061203	AAA	Drv
PARK GITI	17487801	3888800	8R02	1L5Z	1061202	AAA	Page
KENDALL	31848001	3422151	8R02	1L5Z	1061203	AAA	Drv
KENDALL	31188001	3422151	8R02	1L5Z	1061203	AAA	Drv

PERFORM DIAGNOSTIC TESTING CODE B1877 REPLACE DR SIDE PRETENSIONER AND RETEST
 VERIFIED CUST CONCERN OF AIR BAG LIGHT BEING ON, FOUND PROBLEM IN THE ELT PRETENSIONER; SEAT BELT HAD OPEN CIRCUIT, REATTACHED WIRING IN PRETENSIONER, AIR BAG LIGHT OUT NOW.

INSTALLED NEW SEAT BELT BUCKLE; ENTERED AT WPI
 SEAT BELT BUCKLE NOT OPERATING PROPERLY IN TIME TO REPLACE
 AIRBAG SYSTEM DIAGNOSTICS PINPOINT TEST OK REPLACED DRIVERS SIDE SEATBELT PRE TENSIONER, TEST DROVE RETEST, OK

IS OK AND VERIFY NECESSARY TO REPLACED BUCKLE
 INTERNAL PROBLEM, REPL BUCKLE
 TEST AIR BAG SYSTEM WITH PINPOINT TEST ON PASS SIDE PRETENSIONERS CIRCUITS REPLACE TENSIONER AND AIRBAG MODULE REMOVE CARPET TO TEST HARNESS FOR SHORT TO GROUND FOUND ONE SPOT THAT MAY HAVE OVERLAY RET OPEN CKT. REPL

EST REINSTALL CARPET

INOP SEATBELT ASSEMBLY FRONT REPLACE

RESISTANCE HIGH PERFORMED TO A DEFECTIVE RF BUCKLE ASSY
 INSTALL NGS RMR LB SEAT OPEN 88Y RMR SEAT, SEAT BELT, PRETENSIONER, REINSTALL SEAT RETEST

RTS TO POWER AND GROUND TIME TO TEST CIRCUIT IN PRETENSIONER LATCH (WHEN MOVED SHOWS OPEN IN LATCH EVEN WHEN LATCHED)
 TIME TO REPLACE PRETENSIONER LATCH
 TIME TO RR DRIVERS SEAT TO

8 OPEN 28 TIME TO DIAGNOSE RUN CODES ON SEM MOD WITH WDS (NO CODES) TIME TO MONITOR PIDS WITH WDS WHILE OPERATING BELT LATCH. TIME TO RUN PINPOINT ON BELT TIME TO RUN CONTINUITY AND CHECK FOR SHO
 AIR BAG DIAG DRIVER SEAT OPEN CKT IN PRETENSIONER REPLACED PRETENSIONER SEAT BELT BUCKLE CLEANED CODE NOW OPERATING PROPERLY
 ROAD TEST KODE FOUND CODE FOR PASS BUCKLE WDS PID MONITOR FOR ALL INPUT OUTPUT MONITOR ALL PASS REBRT LIGHT RETEST
 1 DIAG CODES, B1888, B1876, PINPOINT DEACTIVATED AIR BAGS, REPLACE DRIVERS PRETENSIONER ASSY, MT RMR MODULE AND RETESTED OK.

AIR BAG DIAGNOSIS MT PINPOINT TEST CODE B1877 & DRILL & REMOVE SEIZED SEAT PRETENSIONER BOLT, RMR DRIVE SEAT TO ACCESS & REPLACE PRETENSIONER. CLEAR CODE & RETEST.

CUTLER FE72691A	4373611 6R02	1LSZ	1081203	AAA	Drv
GILLESPIE 593851	5081600 6R02	1LSZ	1081203	AAA	Drv
DON BOH1276885A	3477000 6R02	1LSZ	1081203	AAA	Drv
ELDER FC187388B	6854000 6R02	1LSZ	1081203	AAA	Drv
GALPIN R 6420122	7573800 6R02	1LSZ	1081202	AAA	Page
NORTH PV 36914901	3418841 6R02	1LSZ	1081203	AAA	Drv
SANDERS 3863801	4551811 6R02	1LSZ	1081202	AAA	Page
NATIONAL 575019A	4772711 6R02	1LSZ	1081203	AAA	Drv
RED MCC 33291801	3484849 6R02	1LSZ	1081203	AAA	Drv
ROBIN MC 17832801	2764567 6R02	1LSZ	1081203	AAA	Drv
FIVE STAR 148676B	4886638 6R02	1LSZ	1081203	AAA	Drv
PACIFIC P 3083751	8278130 6R02	1LSZ	1081203	AAA	Page
DUNCAN F 4487101	2845128 6R02	1LSZ	1081203	AAA	Drv
SAN GALL 57894101	9363673 6R02	1LSZ	1081203	AAA	Drv
THOMPSON 14158801	4534564 6R02	1LSZ	1081202	AAA	Page

4847 PERFORM AIR BAG SYSTEM DIAGNOSIS, DTC B1877 OPEN IN DRIVERS SEAT BELT PRETENSIONER CIRCUIT. CHECK WIRING AND CONNECTIONS TO PRETENSIONER, OKAY. REMOVE LEFT FRONT SEAT AND REPLACE SEAT BELT BU OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS, WDS, PIN POINT TEST, R & L OF B1877 AIR BAG DIAG CODE B1877. PERFORMED PIN POINT TEST REMOVED DRIVERS SEAT TO REPLACE PRETENSIONER R SEAT BELT BUCKLE. RETEST ROADTEST OK CC 28

OKLE PRETENSIONER. CLEAR CODE AND RETEST, OKAY. (28) PERFORM QUALITY CHECK.

3083 CP81203 CC42 INSPECTED DRIVERS SEAT BELT. FOUND BUCKLE INOP. REMOVED AND REPLACED BUCKLE AND PRETENSIONER. NECESSARY TO DISABLE SUPPLEMENTAL RESTRAINT SYSTEM TO REMOVE PRETENSIONER. NECESSARY T

O REMOVE DRIVERS SEAT TO ACCESS BUCKLE. RECHECKED OPERATION. OK.

CCM01 NGS TEST, PINPOINT TEST FOUND AND REPLACED INOP RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY. NECESSARY TO REMOVE SEAT FOR ACCESS. REASSEMBLED AND RETESTED OK. PERFORMED BCE DIAGNOSIS, PINPOINT TEST AND AIRBAG DIAG CODE B1877. REMOVED LF SEAT TO REPLACE LEFT FRONT SEAT BELT PRETENSIONER. RETESTED OK. R AND L SEAT REMOVE FROM FRAME REPLACE SEAT BELT TRACK AND AND REINSTALL. REPLACED THE LEFT FRONT SEATBELT THAT HAD FAILED CAUSING CHIME TO STAY ON

REMOVED LEFT FRONT SEAT TO TRAXED OUT AND REPLACED LEFT FRONT PRETENSIONER ASSY. CLEARED CODES AND RETESTED.

CC28 SHORTED OUT CIRCUIT. BASIC # 81208 VERIFIED CONCERN, NOTE CUST HAS RIGHT AIR BAG IN OFF MODE NGS DIAGNOSIS/BUCE TEST. AIR BAG DIAGNOSIS, COMPLETED PIN POINT TEST. DTC 1877 CHECKED WIRING CIRCUITS. DIAGNOSIS AIR BAG RESTRAINT SYSTEM IN TIME TO REPLACE DRIVER SEAT BELT PRETENSION

I L F SEAT FOR ACCESS, RETESTED WITH NO FURTHER PROBLEMS, NGS SETUP & TEST, CHECKED & CLEARED ANY AIR BAG CODES.....

1800 L F SEAT BELT BUCKLE STICKING WARN INSPECTED L F SEAT BELT, FOUND L F SEAT BELT BUCKLE WAS STICKING, DEACTIVATED AIR BAG SYSTEM DUE TO PRETENSIONER, R&L L F SEAT BELT BUCKLE & PRETENSIONER, RA

REMOVED & REPLACED PRETENSIONER. INSTALL SEAT BELT PRETENSIONERS BOTH SIDES 1081203 28 M O 18818 AIR BAG LIGHT LFC 44 WDS START UP BCE SELF TEST C1877 PID MONITOR RECORD HIGH DRIVER RETRACT CIRCUIT OHMS HIGH 470HMS, PINPOINT TEST B1881 PASSENGER SIDE SEAT BELT BUTTON SHOWS OPEN FOUND PASSENGER SIDE BROKEN SHORT R&R SEAT AND REPLACED SELECT PROBLEM COMPLETED

GILLESPIE	461861	3691000	6F02	1L5Z	1061203	AAA	Drvr
TIPTON M	6038201	3605000	6F02	1L6Z	1061203	AAA	Drvr
KLAMEN F	38276701	6733136	6F02	1L6Z	1061202	AAA	Page
MIKE BHA	7667765	7773673	6F02	1L6Z	1061208	AAA	Drvr
ANTELOPI	318051	6463686	6F02	1L6Z	1061203	AAA	Drvr
RAVENEL	766502	6992241	6F02	1L6Z	1061203	AAA	Drvr
PARK CITY	16365101	3586600	6F02	1L6Z	1061203	AAA	Drvr
VANITY F	167466F	7790664	6F02	1L6Z	1061202	AAA	Page
CUTTER F	270716A	4873611	6F02	1L6Z	1061203	AAA	Drvr
CUTTER F	273229A	4873611	6F02	1L6Z	1061208	AAA	Drvr
HAROLD	230778A	6221536	6F02	1L6Z	1061209	AAA	Drvr
GULLO FC	340625A	7667761	6F02	1L6Z	1061203	AAA	Drvr
DON RICH	1482361	6447111	6F02	1L6Z	1061203	AAA	Drvr
LINK BPO	028661A	2346166	6F02	1L6Z	1061202	AAA	Page
BYERLY F	2614366	4461661	6F02	1L6Z	1061203	AAA	Drvr
MOORE R	066666A	2346661	6F02	1L6Z	1061502	AAA	Page

SEATBELT PRETENSIONER PERFORMED AIRBAG DIAGNOSIS, INSTALLED SEATBELT PRETENSIONER AIRBAG LIGHT DRIVER SEAT BELT BUCKLE ASSY HAS HIGH RESISTANCE REPLACED BUCKLE AS NEEDED CAUS 1 061202 CCC AS6 CC 42 VERIFY. PERFORM NCM BELT TEST. RECEIVED CODE B1861. PERFORM PINPOINT TESTS B1 861. DEACTIVATE SYSTEM AND REPLACED

REPLACE PRETENS. BAD PRETENSIONER AIR BAG RESTRAINT SYSTEM DIAGNOSIS

ELECTRIC TEST B1877 IN MEMORY ON DEMAND PARDED INTERMITTENT PROBLEM PINPOINT TEST, B1 86 REMOVED DRIVERS SEAT AND REPLACED PRETENSIONER AND RETEST OK 1061203 DRIVERS PRE TENSIONER F C 26 AIR BAG DIAG., LFO 48, DTC B 1877, PINPOINT TEST, FOUND DRIVERS PRE TENSIONER CKT OPEN, REPLACE PRE TENSIONER, CLEAR DTC, PERFORMED AIRBAG DIAGNOSTICS REPLACED PASSENGERS PRE TENSIONER.

2002 1 PERFORMED A SRS SYSTEM TEST, 1877 2 CHECKED OASIS. 3 PERFORMED A SRS SYSTEM PIN POINT TEST. 4 DEACTIVATE SRS SYSTEM 5 REMOVED DRIVER SEAT. 6 TEST DRIVER SRS PRE TENSIONER. 7 FOUND PRE TENS

3217 1 PERFORMED A SRS SYSTEM TEST. 1861 1877 2 DEACTIVATE SRS SYSTEM. 3 PERFORMED A SRS SYSTEM PIN POINT TEST. DRIVER 6.90 OHMS RESISTANCE. PASSENGER 7.8 OHMS RESISTANCE. 4 REMOVED DRIVER AND PASSE

INSPECTED AND INSTALLED NGS TO CHECK FOR ANY CODES IN SYSTEM AND RETRIEVED CODE 1877, TESTED AND FOUND INTERMITTENT PRETENSIONER CODE FOR DRIVERS SIDE, INSTALLED NEW DRIVERS SIDE PRETENS. CLEARED CODE 8 SEAT BELT LIGHT STAYS ON ALL THE TIME. 1 861D, DE, DK1, MT 61203AAA 1.0 1.8 PERFORMED NGS TEST, PINPOINT TEST, REPEAT QUICK TEST, R&I DRIVER SEAT, RII CARPET TO CHECK WIRING, REPLACED SEAT BELT BUCK INOP SEC (QUICK TEST) DIAGNOSIS FND SEAT BELT BAD RPLCD OK 4083 42 W RR LF SEAT, REPLACE LF SEAT BELT BUCKLE 2847 REPLACE TENSIONER

ONER RESISTANCE HIGH. 16.20 OHMS 8 REPLACED DRIVER SEAT BELT PRE TENSIONER. 9 REACTIVATE SRS SYSTEM. 10 RETEST SRS SYSTEM. 11 0.1 IF OASIS.

NGER SEATS. 6 REPLACED DRIVER AND PASSENGER SRS SEAT BELT PRETENSIONERS. 6 REINSTALL DRIVER AND PASSENGER SEATS. 7 REACTIVATE SRS SYSTEM. 8 PROVE OUT SRS SYSTEM. 8 RETEST SRS

AND RECHECKED DONE LE, RETEST OK. CAUSAL PART 1061203 CONDITION CODE X2.

CARDINAL	3103801	4722385	BR02	*	1061203	*	Drv	EEC TEST PINPOINT TEST WIGGLE TEST UNABLE TO DUPLICATE CONCERN
MOSSBY FC	0601561	2768100	BR02	1LSZ	1061203	AAA	Drv	LF SEAT BELT BUCKLE JAMMED REPLACED LF SEAT BELT BUCKLE
FAIRWAY	132415A	2254151	BR02	1LSZ	1061202	AAA	Page	RESTRAINT DIAGNOSIS CODE B1881, FAULTY PASS, PRE TENSIONER, REPLACE, CLEAR CODES AND RETEST.
COOK-WF-	14443401	7640400	BR02	1LSZ	1061203	AAA	Drv	INSPECT REPLACE SEAT BELT
AIRPORT	2062201	3714780	BR02	1LSZ	1061203	AAA	Drv	TEST AIR BAG SYSTEM REPLACE LEFT PRETENSIONER
RUPON PO	4000801	7487777	BR02	1LSZ	1061202	AAA	Page	INSPECT AND REPLACE DRIVERS SEAT BELT BUCKLE RECHECK OK
HEMBORC	3582854	7378181	BR02	*	1061203	*	Drv	OK FOR CODE GOT CODE 1877 PP LED TO DR BUCKLE FOUND IT NOT MATED, RECONNECT
JOHNSON	140676A	7682888	BR02	1LSZ	1061203	AAA	Drv	REPLACED DRIVERS SIDE PRE TENSIONER FOR SEATBELT ROAD TESTED TO VERIFY CONCERN, FOUND AIR BAG LIGHT ON, PERFORMED BCE DIAG, FOUND LOOSE GROUND TO AIR BAG AND SEAT BELT LIGHT, REMOVED AND REPLACED SEATBELT, RETESTED OK
MAXWELL O1	7228A	8818873	BR02	1LSZ	1061203	AAA	Drv	
OWATON	8600181	4817880	BR02	1LSZ	1061203	AAA	Drv	X SEATBELT ASSEMBLY FRONT REPLACE 42 DRIVERS SIDE SEAT BELT INOPERABLE FOUND
HELPMAN	7215751	8408673	BR02	1LSZ	1061203	AAA	Drv	AT TIME OF PDI
WALTER I	2874801	7742831	BR02	1LSZ	1061203	AAA	Drv	MTS1 208, TIME TO REPLACE 1 SEAT BELT BUCKLE THAT DOES NOT FASTEN CORRECTLY.
FAIRLANE	113173C	8488000	BR02	1LSZ	1061203	AAA	Dev	8809 41 81203 1.3 OK SEAT BUCKLE NISS TO R R SEAT AND REPLACE BUCKLE ASSY TO 40 WITH PRETENS THIS IS BUCKLE END NOT SEAT BELT ASSY
BUDGET F	8008471		BR02	1LSZ	1061203	AAA	Drv	DRIVER SEAT BELT BUCKLE WONT LOCK DUE TO INTERNAL MECHANISM FAILURE R AND R THE LF SEAT BELT BUCKLE ASSY DIAG AND REPLACED DRIVER SEAT BELT. PULLED SEATBELT FROM PDI
LONG-LEV	14328401	3887800	BR02	1LSZ	1061203	AAA	Drv	
SHARP FC	287051	7878801	BR02	1LSZ	1061203	AAA	Drv	COULD NOT LATCH CORRECTLY, CHECKED AND LUBED RAILS, REINSTALLED SEAT AND ASSY CHECKED SEAT ADJUSTING ALL FUNCTIONS WORKING CORRECTLY, NEW LATCH OPERATION OK.
EMPIRE F	128880A	8282127	BR02	1LSZ	1061203	AAA	Drv	INSPECTION OF DRIVERS SEAT BELT FOUND BUCKLE WOULD NOT LATCH, CHECKED CABLES FOR ACTIVE RECALL, FOUND NONE, REMOVED DRIVERS SEAT AND REPLACED DAMAGED BUCKLE UPON REINSTALLING SEAT FOUND SEAT RAIL ASSY W SEAT BELT WOULD NOT LATCH, REPLACED WITH NEW SEAT BELT, WORKS PROPERLY
WINNER F	8308861	7340444	BR02	1LSZ	1061202	AAA	Page	SEAT BELT BUCKLE JAMMED SEATBELT ASSEMBLY FRONT REPLACED
AL SPITZE	8138303	8281804	BR02	1LSZ	1061203	AAA	Drv	SOP SEAT BELT
TROTTER	1687701	8284321	BR02	1LSZ	1061203	AAA	Drv	REPLACED DRIVERS SIDE SEAT BELT
CAPITAL F	057308A	7258411	BR02	1LSZ	1061203	AAA	Drv	R&R SEATBELT ON DRIVER SIDE

MONTRON 22008504	6660711	6R02	1L5Z	1061202	AAA	Page	REPLACED RIGHT FRONT SEAT BELT WITH TENSIONER RETRACTOR.
ATASCAD 5262202	4866464	6R02	1L5Z	1061203	AAA	Drvr	REPLACED SEATBELT AND NOW OK.
MIKE PYNJ 2166796	2243253	6R02	1L5Z	1061203	AAA	Drvr	INSTALLED DRIVERS SIDE SEAT BELT BUCKLE CHECK OUT RIGHT SEAT BELT BUCKLE WILL NOT LATCH, CHECK OUT NOT INVOLVED IN RECALL 01321, REMOVE AND REPLACE SEAT BELT LATCH ASSEMBLY
LUNDE FC 048672A	8472901	6R02	1L5Z	1061202	AAA	Page	REPLACE SEAT BELT BUCKLES
PUNDAMA 24667301	9466611	6R02	1L5Z	1061202	AAA	Drvr	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
GALPIN R 5966061	7873900	6R02	1L5Z	1061202	AAA	Page	REPLACE RIGHT SEAT BELT, 42
NICHOLS 20662201	6363673	6R02	1L5Z	1061202	AAA	Page	DEACTIVATE AIR BAG SYSTEM DISCONNECT BATTERY FOR DRIVERS SEAT REPLACE SEAT BELT BUCKLE ASSEMBLY GAS CHARGED RETEST
WORLD F 671061	4437000	6R02	1L5Z	1061203	AAA	Drvr	
GALPIN R 6690461	7873900	6R02	1L5Z	1061202	AAA	Page	SEAT BELTS WONT LATCH PROPERLY REPLACE SEAT BELTS FOUND BAD SEAT BELT RECEPTICAL REMOVE AND REPLACE SEAT BELT RECEPTICAL
COURTES 7651401	4421040	6R02	1L5Z	1061203	AAA	Drvr	1. REPLACE BUCKLE, DOES NOT LATCH.
DEE THO 66666701	6666665	6R02	1L5Z	1061202	AAA	Page	
GALPIN FI 5676051	7673900	6R02	1L5Z	1061202	AAA	Page	SEAT BELTS WONT LATCH REPLACE SEAT BELTS SEAT BELT BUCKLE NOT CATCHING ALL THE TIME NEO TO REPLACE FRONT BUCKLE
HELFMAN 6121651	2403673	6R02	1L5Z	1061203	AAA	Drvr	REPL DEFECTIVE LF SEATBELT BUCKLE PRETENSIONER THAT WOULD NOT LATCH.
BELL FOR 6666202	6661776	6R02	1L5Z	1061203	AAA	Drvr	REPL RF SEAT PRETENSIONER
WESTERN 2140646	2430643	6R02	1L5Z	1061202	AAA	Page	
DREW FO 6667251	4647777	6R02	1L5Z	1061203	AAA	Drvr	VERIFY CONCERN LH SEAT BELT BUCKLES BINDING R&R L F SEAT BELT BUCKLES VERIFY REPAIRS L F SEAT BELT BUCKLES NORMAL RECALL. REPAIRED AS PER RECALL.
SMI VALL 4761762	5630363	6R02	1L5Z	1061202	AAA	Page	
BRAEGER 0646706	2616100	6R02	1L5Z	1061203	AAA	Drvr	MT EQUALS TIME TO REPLACE SEATBELT BUCKLE DRIVERS SIDE
LEBACY F 6316601	6632161	6R02	1L5Z	1061202	AAA	Page	
CHAMPLO 46136201	7663673	6R02	1L5Z	1061203	AAA	Drvr	R R L SEAT REPLACED L SEAT BELT BUCKLE TENSIONER INOP
SUSURBA 66904301	3317000	6R02	1L5Z	1061202	AAA	Page	TEST SEAT BELT FOUND WILL NOT LATCH REPLACED SEAT BELT. VERIFY CUSTOMER CONCERN REMOVE DRIVER SIDE SEAT AND REPLACE SEAT BELT BUCKLE
LEIF JOHN 54760702	3126600	6R02	1L5Z	1061203	AAA	Drvr	SEAT BELTS WONT LATCH REPLACE SEATBELTS
GALPIN R 5666141	7873900	6R02	1L5Z	1061202	AAA	Page	INOP. SEAT BELT BUCKLE REMOVE LEFT FRONT SEAT FROM VEHICLE. REPLACE SEAT BELT BUCKLE ASSEMBLY
RICHARDI 4473301	2620000	6R02	1L5Z	1061203	AAA	Drvr	10/14 DIAGNOSED AND REPLACED DRIVERS SEAT BELT BUCKLE AND PRETENSIONER QUALITY CHECKED RETESTED
CROWFO 066766A	2361116	6R02	1L5Z	1061203	AAA	Drvr	WONT LATCH VERIFY CONCERN REPLACED DRIVER SIDE BUCKLE OK THIS TIME
RAMIREZ 6666761	4672362	6R02	1L5Z	1061206	AAA	Drvr	6711 REPLACE DRIVERS SEAT BELT BUCKLE, WILL NOT LATCH, 6040 SEAT, WITH PRETENSIONER.
RUSTY EC 666317A	6663211	6R02	1L5Z	1061203	AAA	Drvr	

FRIENDLY 214882A	8694380 6R02	1L5Z	1001202	AAA	Pgr
GALPIN R 3088181	7873800 6R02	1L5Z	1001202	AAA	Pgr
ZEMMS FO 4000852	3281881 6R02	1L5Z	1001203	AAA	Dvr
WESTWA 03204801	6580333 6R02	1L5Z	1001203	AAA	Dvr
PRESTIGE 22703802	8843873 6R02	1L5Z	1001203	AAA	Dvr
PUNDMAN 28988802	8488811 6R02	1L5Z	1001203	AAA	Dvr
KEN GROF 8080761	4388171 6R02	1L5Z	1001203	AAA	Pgr
STARK HK 9674181	5388900 6R02	1L5Z	1001203	AAA	Dvr
GALPIN FI 0388871	7873800 6R02	1L5Z	1001203	AAA	Dvr
BILL ALEX 28987004	3442200 6R02	1L5Z	1001203	AAA	Dvr
CIFALDI M 443201	8284381 6R02	1L5Z	1001203	AAA	Dvr
HOMER H 3080261	7483381 6R02	1L5Z	1001203	AAA	Dvr
NELSON FO81781A	7384401 6R02	1L5Z	1001203	AAA	Dvr
ALVAREZ 888081	8871212 6R02	1L5Z	1001202	AAA	Pgr
CHARLE " 108730A	3714000 6R02	1L5Z	1001203	AAA	Dvr
LITHIA PD 133338A	4388400 6R02	1L5Z	1001203	AAA	Dvr
PEGUES- 550261	7888211 6R02	1L5Z	1001203	AAA	Dvr
COOK-WF 14128801	7840400 6R02	1L5Z	1001203	AAA	Dvr
OKC AUT 228880A	2327171 6R02	1L5Z	1001202	AAA	Pgr
HELFMAN 8088461	8403873 6R02	1L5Z	1001203	AAA	Dvr
TEAM FOF 4888151	3888100 6R02	1L5Z	1001202	AAA	Pgr
MEGINNIS 4320401	4840881 6R02	1L5Z	1001202	AAA	Pgr
JACK ROP 7281852	8888000 6R02	1L5Z	1001202	AAA	Pgr
KEN GROF 4887461	4388171 6R02	1L5Z	1001203	AAA	Dvr
COURT ST 341481	8888800 6R02	1L5Z	1001203	AAA	Dvr
INVER OR 39778101	4812201 6R02	1L5Z	1001203	AAA	Dvr

6888-81202 BUCKLE, 42 DMOP VERIFIED CONCERN OF PASS FRONT SEAT BELT NOT LATCHING PROPERLY. REMOVED PASS FRONT BUCKET SEAT AND REPLACED PRETENSIONED SEAT BELT BUCKLE REASSEMBLED VEHICLE AND VERIFIED SEAT BELTS WONT LATCH REPLACE SEAT BELT

PROPER OPERATION AFTER REPAIR.

LH FRONT BUCKLE JAMMED. DISABLE AIR BAG SYSTEM, REPLACED BUCKLE, RE ACTIVATE AIR BAG SYSTEM. 1 REMOVED D & SEAT FROM VEH. SEAT BELT BUCKLE BOLT STUCK IN SEAT TRACK. R R SEAT TRACK, INSTALLED NEW BUCKLE. DRIVERS SEAT BELT BUCKLE INOP INSPECT BUCKLE WOULD NOT LATCH R.R. DRIVER SEAT ASSY REPLACAE BINDING SEAT BELT BUCKLE. REPLACE LEFT FRONT SEAT BELT SEATBELT BUCKLE BROKEN SEATBELT ASSEMBLY FRONT REPLACE

108 DIAG AIR BAG SYS PINPOINT TEST CLEAR CODES & RERTEST SYS
R/R LEFT SEAT TO REPLACE BELT PRETENSIONER
CHECK CHECKED OUT REMOVED DRIVERS SEAT AND REPLACED SEAT BELT BUCKLE
VERIFY L FRONT BUCKLE BINDING REPLACE RERTEST OK
LATCH STICKS, PULLED SEAT, REPLACED BUCKLE & REINSTALLED SEAT
BUCKLE INOP HOUSING MATTER WILL NOT BUCKLE. R/R BUCKLE ASSY

REPLACE SEAT BELT BUCKLE
REMOVE & REPL FT FRT SEAT & REPL BUCKLE ASSY.
REPLACED SEAT BELT BUCKLE
VERIFIED CUST CONCERN REPLACED L F SEAT BELT BU CKLE
REINSPECTED ALL OK. 3.
REPLACE DRIVERS SIDE SEAT BELT ASSY

R/R LH SEAT BELT BUCKLE

INSPECTED SEATBELT BUCKLE, REPLACED R/R SEATBELT BUCKLE
NEC TO REPLACED SEAT BELT BUCKLE WONT LATCH

SEATBELT INOP REPLACED BUCKLE

REPLACED SEAT BELT
REPLACE FT FRT SEATBELT BUCKLE (WILL NOT STAY LATCHED AT TIMES PER CUST)
VERIFY CONCERN. REPLACED LEFT SEATBELT BUCKLE
TEST AND REPLACE SEAT BELT TEST O.K.
CONFIRMED CONCERN.INSPECTED AND FOUND THE PRETENSIONER BOUND UP. ORDERED PARTS. REMOVE DRIVER SEAT AND REPLACE SEAT BELT BUCKLE.

SOUTHLA	1318021	3328880	8F02	1LSZ	1081203	AAA	Drvr	CKED SEAT BELT OPERATION FD SEAT BELT WOULD NOT STAY BUCKLED FROM FRT SEA RMR ASSY REASSEMBLE & RECKED OK 748 DUPLICATE CLUST CONCERN. PROBLEM DETERMINED TO BE IN BUCKLE ASSY. ORDER REPLACEMENT. REMOVE SEAT ASSY, REMOVE AND REPLACE SEAT BLET BUCKLE ASSY. RETEST. ALL OKAY. NBS TEST SYSTEM DUE TO BUCKLE BE	ING PART OF SRS SYSTEM. CLEAR CODES. RETEST. ALL OKAY. 8828
BLOOMIN	1417208	3918200	8F02	1LSZ	1081203	AAA	Drvr		
VILLA FOF	7628751	8378222	8F02	1LSZ	1081202	AAA	Pagr	BUCKLE INOP M TIME TO RT BUCKLE BROKEN M TIME TO REPLACE LEFT SEAT BELT BUCKLE	
VILLA FOF	7528031	8378222	8F02	1LSZ	1081202	AAA	Pagr	REPLACERTFT SEAT BELT	
SUPERIOR	146601A	7828400	8F02	1LSZ	1081202	AAA	Pagr		
DAVE SIN	22801701	8822800	8F02	1LSZ	1081203	AAA	Drvr	REPLACED DRIVERS BUCKLE	
DAVE SIN	22811701	8822800	8F02	1LSZ	1081203	AAA	Drvr	REPLACED DRIVERS BUCKLE	
DAVE SIN	22803901	8822800	8F02	1LSZ	1081203	AAA	Drvr	REPLACED DRIVERS BUCKLE	
DAVE SIN	22808101	8822800	8F02	1LSZ	1081203	AAA	Drvr	REPLACED DRIVERS BUCKLE 1 INSPECTED BOTH FRONT SEAT BELTS ONE FAILED REPLACED ONE	
WOODY B	12484801	6416888	8F02	1LSZ	1081202	AAA	Pagr	6 RECALL W TECH S88, PERFORMED RECALL 01821, RR PASS FRONT SEAT BELT(FAILED), ALL OK AT THIS TIME 01821 COMPLETED	
MARCOONE	386387A	8727200	8F02	1LSZ	1081202	AAA	Pagr	INSPECT AND REPLACE PASSENGER SEAT BELT	
MIKE BASH	8790080	8948881	8F02	1LSZ	1081202	AAA	Pagr	REPLACE SEAT BELT, RT SIDE	
DELAND F	038888A	7731000	8F02	1LSZ	1081202	AAA	Pagr		
MEL CLAY	1888861	8841811	8F02	1LSZ	1081202	AAA	Pagr		
APPLE VA	881284A	4318900	8F02	1LSZ	1081202	AAA	Pagr	10 REPLACE PASSENGER FRONT SEAT BELT BOTH FRT SEATBELT BUCKLE ASSYS FAILED RECALL 01821 SEATBELT INSPECTION. OASIS DOESNT SHOW THIS VEHICLE AS BTING INVOLVED IN RECALL 01821. REPLACED BOTH FRT SEATBELT BUCKLE ASSYS AS SAFETY LIABILITY IS DRIVERS SEATBELT BUCKLE FAILED 01821 INSPECTION. OASIS NOT INVOLVED IN RECALL. RPL BUCKLE FOR SAFETY LIABILITY CONCERN. M TIME IS LBR TO REPLACE DRIVERS SEATBELT LBUCKLE. NO OP# PUBL.	SUE. LISTED AS M TIME. NO OP# PUBLISHED FOR BUCKLE REPLACEMENT.
LANDERS	8877501	8843873	8F02	1LSZ	1081202	AAA	Pagr		
LANDERS	8878101	8843873	8F02	1LSZ	1081203	AAA	Drvr	BOTH FRT SEATBELT BUCKLES FAILED RECALL INSPECTION. OASIS DOESNT SHOW VEHICLE INVOLVED IN RECALL. RPL BUCKLES DUE TO SAFETY LIABILITY ISSUES. LISTED AS M TIME. NO OP# PUBL.	
LANDERS	8877701	8843873	8F02	1LSZ	1081202	AAA	Pagr	RECALL	
MERIDIAN	8883851	8884408	8F02	1LSZ	1081203	AAA	Drvr	WE REPLACED THE RIGHT SEAT BELT	
DAVE SIN	22811101	8822800	8F02	1LSZ	1081203	AAA	Drvr	REPLACED DRIVERS BUCKLE	
GALPIN F	8888871	7878800	8F02	1LSZ	1081202	AAA	Pagr	RECALL 01821 SEATBELT PERFORMED 01821 SEATBELT RECALL	
GALPIN F	8888841	7878800	8F02	1LSZ	1081202	AAA	Pagr	RECALL 01821 SEATBELT PERFORMED 01821 SEATBELT RECALL	
HOLMES	123818701	8883800	8F02	1LSZ	1081202	AAA	Pagr	01821Q PERFORM RECALL SEAT BELTS AS PER RECALL	

ANDERSON 046907A	3841700 6R02	1LSZ	1061202	AAA	Page
DELAND F 036300A	7791000 6R02	1LSZ	1061209	AAA	Drvr
HELFMAN 5121851	3403579 6R02	1LSZ	1061202	AAA	Page
GALPIN FR 5898221	7673800 6R02	1LSZ	1061202	AAA	Page
GALPIN FR 5229101	7673800 6R02	1LSZ	1061202	AAA	Page
FORD CP 177578A	8489355 6R02	1LSZ	1061203	AAA	Drvr
ANDERSON 148984A	4788521 6R02	1LSZ	1061202	AAA	Page
JAMES MI 628820B	7214700 6R02	1LSZ	1061282	AAA	Page
JIM CLICK 23207501	7472000 6R02	1LSZ	1061202	AAA	Page
COURTES 43700701	7644363 6R02	1LSZ	1061202	AAA	Page
SWANSON 188478A	8884121 6R02	1LSZ	1061209	AAA	Drvr
GALPIN FR 6836851	7673800 6R02	1LSZ	1061202	AAA	Page
SUBURBA 38804401	3317800 6R02	1LSZ	1061202	AAA	Page
MARTIN - 184340B	3844800 6R02	1LSZ	1061209	AAA	Drvr
AUTOWAY 8738881	7473711 6R02	1LSZ	1061209	AAA	Drvr
GAMINO 8188461	8229181 6R02	1LSZ	1061209	AAA	Drvr
HOMER SI 124590A	8868700 6R02	1LSZ	1061209	AAA	Drvr
WYCOASSE 328853A	8829431 6R02	1LSZ	1061202	AAA	Page
DON REID 1808251	8447111 6R02	1LSZ	1061209	AAA	Drvr
BEAU TOY 23181801	8865841 6R02	1LSZ	1061209	AAA	Drvr
MIKE DAV 217348A	7383080 6R02	1LSZ	1061209	AAA	Drvr

17 PULLED THE PASSENGER SEAT OUT TURNED IT UP SIDE DOWN
 PULLED THE SEAT COVER BACK TOOK OLD BELT BUCKLE OUT
 REPLACE IT WITH A NEW ONE
 CHECK AND REPLACE BOTH FRONT SEAT BELTS
 SEAT BUCKLES NOT LATCHING CORRECTLY NEG TO REPLACE
 BUCKLES AND BUSHINGS

RECALL 01821 SEATBELT PERFORMED 01821 SEATBELT RECALL

RECALL 01821 SEATBELT PERFORMED 01821 SEATBELT RECALL
 PERFORM RECALL 01821

31 REPLACED THE RIGHT SIDE SEAT BELT BUCKLE. CUSTOMER
 STATES IT WAS NOT WORKING. FAILED TESTER FOR 01821.
 28 RECALL 01821. W/ PERFORM RECALL 01821. PERFORM
 INSPECTION ON SEAT BELT BUCKLES. PASS OK.
 RECALL. REPLACED SEAT BELT TENSIONER BUCKLE AS PER
 RECALL

1 REPLACED SEAT BELT AS PER RECALL.
 REPLACE LEFT AND RIGHT SEAT BELT BUCKLES

RECALL 01821 SEATBELT PERFORMED 01821 SEATBELT RECALL

REPLACED BOTH SEAT BELT BUCKLES WOULD NOT HOLD
 RR LEFT FRONT SEAT MAKE A SIMULATOR FOR SEAT BELT
 BUCKLE. 20 OHS REPLACE FRONT SEAT BELT BUCKLE AND
 PRETENSIONER

R OPEN CIRCUIT
 REACTIVATE SYSTEM
 MONITOR PID WHILE
 WIGGLING HARNESS FROM
 MODULE TO
 PRETENSIONER FAULT
 DUPLICATED R AND R
 DRIVER PRETENSIONER
 REINSTALL SEAT VERIFY
 REPAIR

NBS TEST B1877 DRIVERS SIDE PRETENSIONERS FAULT CLEAR
 CODES RETEST FAULTS INTERMITTENT NBS PLUS PINPOINT TEST
 REMOVE DRIVERS SEAT DISCONNECT HARNESS CHECK
 CIRCUITS 1080 AND 1079 FOR SHORTS O
 AIRBAG LIGHT ON AIR BAG RESTRAINT SYSTEM
 DIAGNOSIS

AIR BAG DIAG REPLACE PRE TENSIONER
 I CHECKED FRONT SEATBELTS AND FOUND RIGHT FRONT BAD, RR
 SEATBELT WITH PRETENSIONER FOR SPLIT BENCH SEAT. ALL
 OKAY NOW.

INOP SEATBELT ASSEMBLY FRONT REPLACE

VERIFY CONCERN AIR BAG DIAG SELF TEST B1877 PINPOINT TEST
 ELFC TEST T PRETENSIONER HIGH RESISTANCE DISCONNECT AIR
 NBS TEST DTC B1877 PINPOINT TEST REPLACE SEAT BELT BUCKLE
 PRETENSIONER RETEST OK

DRLUM HL	3437102	4323900	6R02	1L5Z	1001202	AAA	Pagr
R D BANNY	080342A	4732141	6R02	1L5Z	1001200	AAA	Drv
CAPITAL F	8338751	7604900	6R02	1L5Z	1001203	AAA	Drv
HILLSBORO	3870601	4044000	6R02	1L5Z	1001208	AAA	Drv
DOWNING F	4868261	3482240	6R02	1L5Z	1001203	AAA	Drv
PICKLEB9	713301	3483371	6R02	1L5Z	1001203	AAA	Drv
DOWNEY	1018801	6329000	6R02	1L5Z	1001208	AAA	Drv
ED MULLI	1801993	9842431	6R02	1L5Z	1001203	AAA	Drv
TORWNE F	1918823	8828500	6R02	1L5Z	1001208	AAA	Drv
MIKE PAT	086888A	7488113	6R02	1L5Z	1001208	AAA	Drv
KARL FLA	8916431	8073131	6R02	1L5Z	1001202	AAA	Pagr
WISCASSI	3306833	8829431	6R02	1L5Z	1001202	AAA	Pagr
FRIBEDON	278884A	8822671	6R02	1L5Z	1001208	AAA	Drv
JIM KESIM	1169300A	8823333	6R02	1L5Z	1001203	AAA	Drv
POWER P	4823701	2634801	6R02	1L5Z	1001202	AAA	Pagr
BUDGET F	82100801		6R02	1L5Z	1001203	AAA	Drv
HAGERST	3321301	7333673	6R02	1L5Z	1001203	AAA	Drv
MONTGOM	178828A	3721351	6R02	1L5Z	1001208	AAA	Drv
R E BARBI	109183A	3822351	6R02	1L5Z	1001208	AAA	Drv
CHAMPION	2701851	6841441	6R02	1L5Z	1001208	AAA	Drv

REPLACED SEAT BELT
TESTED & TRACED TO BAD PRETENSIONER. REPLACED TO
CORRECT.
OPEN CIRCUIT REPL TENSIONER AIR BAG RESTRAINT SYSTEM
DIAGNOSIS
VARIFIED LIGHT ON PERFORMED AIRBAG DIAG, RETRIEVED CODE
46, PERFORMED PINPOINT TEST, SOP PRETENSIONER

DATE WAS ENTERED WRONG. CORRECT DATE NOW ENTERED.
TEST AIR BAG SYSTEM, ACCESS AND PERFORM PPTS ON SEAT
BELT PRETENSIONER WHICH READ OPEN CIRCUIT.

B851 CODE 46. BAD DRIVERS SEAT BELT PRETENSIONER. LIGHT
WAS NOT ON. INSTALLED NBS AND CHECKED FOR CONT. AND ON
DEMAND CODES. ONLY STORED 1844 CONT. PERFORMED
PINPOINT TESTS FOR CODE 1844. WITH NBS W

ENT INTO PID DATA AND
CHECKED RESISTANCE OF
BOTH DRIVERS AND PASS.
PRETENSIONERS. BOTH
READ 2.1 OHMS. WIGGLED
DRIVERS WIRE AND DID
NOT CHANGE
RESISTANCE. REMOVED
DRIVERS ON BENCH SEAT

8000 HIGH RESISTANCE CHECKED AIR BAG LIGHT
INTERMITTENTLY FLASHING. PERFORMED RCM SYSTEM SELF
TESTS. RETRIEVED CODE B1677. PERFORMED PINPOINT TESTS.
MONITORED DRIVERS & PASSENGERS SIDE PRETENSION
TEST SYSTEM REPLACED SEAT BELT ASSEMBLY

ER CIRCUIT RE 882888
DRIVERS SIDE AT 11.3
OHMS. REMOVED DRIVERS
SIDE SEAT. REPLACED
SEAT BUCKLE PRE
TENSIONER &
REASSEMBLED. CLEARED
CODE & ROAD TESTED OK.
RERAN RCM BELT

REPLACED SEAT BELT
Q REMOVED PASSENGERS BUCKLE SEAT RR SOP SEATBELT
ASSEMBLED TOGETHER, WORKS FINE NOW.
6418 CHECKED THE AIR BAG LT BEING ON, GOT CODE B1677,
DRIVER SEAT BELT PRETENSIONER CRT. BAD. REPLACED THE
SEAT BELT PRETENSIONER ASSEMBLY. CLEARED THE CODE AND
RETESTED GOOD.
AIR BAG DIAG REPLACE BUCKLE

TEST AIR BAG SYSTEM CODE B1801 RAN PIN POINT TESTS FOUND
FAULTY RP PRETENSIONER RHP PRETENSIONER RETEST OK
REPLACED LF BUCKLE ASY
DIAGNOSIS, TESTED SYSTEM, REMOVED AND REPLACED DRIVERS
SIDE PRETENSIONER, RETESTED
REPLACED DRIVERS SIDE SEAT BELT...
DIAGNOSIS AND REPLACED SEAT BELT
DIAG AIR BAG LIGHT ON AIR BAG RESTRAINT SYSTEM
DIAGNOSIS

TED RUSE	30588002	8807811	8R02	1LSZ	1081203	AAA	Drv	INSTALL BUCKLE HIGH RESISTANCE AIR BAG RESTRAINT SYSTEM DIAGNOSIS	
SUN STAT	4887751	2885800	8R02	1LSZ	1081203	AAA	Drv	DIAGNOSE AIR BAG LIGHT CIRCUIT SELF TEST B1877, PINPOINT TEST Y1, CHECK WIRING TO RETRACTOR, OK, REPLACE RETRACTOR HAS INTERMITTENT OPEN, RECHECK OK	
NORTHGA	7763001	7227288	8R02	1LSZ	1081203	AAA	Drv	8781 81208 42 140880 0A 81172A 0.4 PERFORMED 8R8 DIAG REMOVED SEAT ON DRIVER'S SIDE REPLACED SEAT BELT PRETENSIONER RETEST OK	
MARGATE	303081A	8782277	8R02	1LSZ	1081203	AAA	Drv	REPLACE L.F SEAT BELT AIRBAG LIGHT IS ON 850 (QUICK TEST) DIAGNOSIS CONFIRMED, FOUND FEMALE RECEPTICAL NOT WORKING PROPERLY REMOVED AND REPLACED TO CORRECT	
EAST-COL	6783181	2821171	8R02	1LSZ	1081203	AAA	Drv	11487MO 42 BUCKLE ELECT AIR BAG OK OUT HAD TO DRIVE TO GET TO ACT UP HAD CODE 47 81881 REPL PASS SEAT BELT PRETENSIONER AN RECK	
WICHTA I	8884851	8821181	8R02	1LSZ	1081203	AAA	Drv	1 STEERING COLUMN DIAG, AIR BAG DIAG, PINPOINT TEST, E80. FOUND BOTH PASSENGER AND DRIVER PRETENSIONERS TO BE BAD.	
BAYVILLE	40801301	8884800	8R02	1LSZ	1081203	AAA	Drv	INSTALL NGS AND TEST SYS REMOVE PASS SEAT AND REPLACE BUCKLE ASSY AND RETEST	
WALKER I	10317401	8883873	8R02	1LSZ	1081202	AAA	Page	DR BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS	
WESTVA*	87044301	8880833	8R02	1LSZ	1081202	AAA	Page	8880 OPEN PASS. SEATBELT PRETENSIONER 1.J 140880.8, 81704.4, PRETENSIONER .J AIR BAG SYSTEM DIAGNOSIS FOUND OPEN PRETENSIONER RAN PASS. SEAT TRACK TO GAIN ACCESS, REPLACED PASSENGER SIDE SEATBELT PRETEN 7088 DRIVER SIDE SEAT BELT BUCKLE 28 W CK AIR BAG LIGHT STARTS BLINKING AND THEN STAYS ON PERFORM QUICK TEST WITH N88 P1038 OPEN ON SEAT BELT BUCKLE R/R SEAT BELT BUCKLE RECHECK AND ROAD TESTED OK	BLOWER, RETEST PASSED, ROADTESTED OK
FRIENDLY	088888A	8438800	8R02	1LSZ	1081202	AAA	Page	INSPECTED AND REPLACE LEFT FRN SEAT BELT SEAT BELT BUCKLE REPLACE NOT WORKING CORRECTLY ROAD TEST FLASH CODE 46 N88 TEST DTC 1877, PINPOINT TEST REPAIRED HIGH RESISTANCE IN CIRCUIT 1078 LB PID UNDER SEAT REPLACED DRIVER PRETENSIONER CLEARED CODES AND ROAD TEST AFTER REPAIRS OK.	
KEN GROU	333453	8818881	8R02	1LSZ	1081203	AAA	Drv	REPLACED PASS SEAT BELT 8843 R R RIGHT FRONT SEAT REPLACE SEAT BELT ASSY. TEST RCM CODE B1877 PIN POINT TEST REPLACED LEFT FRONT SEAT BELT BUCKLE AND RETEST PASS	
NORTH CX	257180A	8488800	8R02	1LSZ	1081202	AAA	Page		
SAMES MK	844443A	7214700	8R02	1LSZ	1081203	AAA	Drv		
SANTA AN	288211B	4888800	8R02	1LSZ	1081203	AAA	Drv		
DEE THOR	87113301	8883888	8R02	1LSZ	1081203	AAA	Drv		
VENUS FC	2108051	4818800	8R02	1LSZ	1081203	AAA	Drv		
WENDLE I	178820A	4844800	8R02	1LSZ	1081202	AAA	Page		
ERWALD'S	128880A	8738180	8R02	1LSZ	1081202	AAA	Page		
LA PORTE	1357180	4711842	8R02	1LSZ	1081203	AAA	Drv		

PADRE FC 28587A 8848900 8R02 1LSZ 1081202 AAA Pagr
 CARTER 448901 8832171 8R02 1LSZ 1081203 AAA Dvr

REYNOLD 28219101 7828930 8R02 1LSZ 1081203 AAA Dvr
 VALLEY IS 20628801 8773873 8R02 1LSZ 1081203 AAA Dvr
 VALLEY IS 20628901 8773873 8R02 1LSZ 1081203 AAA Dvr

CAPITOL I 2808051 2483800 8R02 1LSZ 1081202 AAA Pagr

APPLE VA 881238A 4815900 8R02 1LSZ 1081202 AAA Pagr
 RANDALL 28701001 4888171 8R02 1LSZ 1081203 AAA Dvr

HUDSPET 2840382 7433200 8R02 1LSZ 1081202 AAA Pagr
 HOLMES 1 24013401 2823800 8R02 1LSZ 1081203 AAA Dvr

TROPICAL 288779C 8913800 8R02 1LSZ 1081203 AAA Dvr
 DELAND F 038440A 7781000 8R02 1LSZ 1081202 AAA Pagr

CROSSFC 208828B 8617800 8R02 1LSZ 1081203 AAA Dvr
 GALPIN FI 88488581 7873800 8R02 1LSZ 1081202 AAA Pagr

SKYLINE E 2147851 8812411 8R02 1LSZ 1081203 AAA Dvr

AUTOWA 1 11580801 8233400 8R02 1LSZ 1081203 AAA Dvr
 DOUG ST 1 28412AA 2838000 8R02 1LSZ 1081202 AAA Pagr

TREADWE 28851301 4783881 8R02 1LSZ 1081203 AAA Dvr

RACEWA 1447388A 7841000 8R02 1LSZ 1081202 AAA Pagr

8882 VERIFY CUSTOMERS CONCERN CONNECTED NGS FOUND
 CODES B1871 DRIVER SIDE PRETENSIONER OPEN CIRCUIT AND
 B1891 DRIVER SIDE PRETENSIONER OPEN CIRCUIT. USED
 MULTIMETER TO PERFORM PINPOINT TEST M FOR B187
 REPLACE L SEAT BELT INOP

1 REPLACED DRIVERS PRETENSIONER HIGH RESISTANCE.
 REPLACE LF SEAT BELT BUCKLE.
 M TIME TO REPLACE FRT SEAT BELT BUCKLES.
 FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT
 REPLACE

REPLACED PASSENGER SIDE SEAT BELT
 REPLACED ONE SEAT BELT BUCKLE
 EXTENSIVE DIAG. BELT RETRACT, BAD AIR BAG RESTRAINT
 SYSTEM DIAGNOSIS
 REPLACED SEAT BELT BUCKLE

18336 SEAT BELT BUCKLE 28 CHECK AIR BAG LIGHT FLASH
 ON, PERFORMED NGS AND DIAGNOSTIC FROM MODULE MEMORY
 CODE B1877 SEAT BELT DRIVE PRETENSIONER OPEN CKT, CLEAN
 CODE AND PERFORMED ON DEMAND SELF TEST SA
 REPLACED BOTH DRIVERS AND PASSENGER BUCKLES

28178 W F USE NGS TO RUN QUICK TEST B1877, RUN DCL TO
 CHECK SYSTEM, INTERMITTENT IN DRIVERS SIDE PRETENSIONER,
 REPLACE DRIVER SIDE PRETENSIONER RETEST PASS
 REPLACE SEATBELTS WILL NOT LATCH PROPERLY

INOP WIRING ASSEMBLY REPAIR
 AIR BAG DIAG, INSPECT SEAT BELT, REPLACE DRIVERS SIDE SEAT
 BELT BUCKLE
 REPLACE BELTS
 R R DRIVER FRONT SEAT AND REPLACED SEAT BELT BUCKLE
 WITH PRETENSIONER CAUSING AIRBAG LIGHT TO COME ON
 AIR BAG LIGHT CONCERN QUICK TEST TRACED TO INTERM OPEN IN
 RIGHT SEAT BELT BUCKLE

1 AND POINT TEST
 B1881 ALSO INSTALL THE
 SIMULATOR TO PERFORM
 PINPOINT, FOUND BOTH
 CIRCUIT GOOD REPLACE
 BOTH PRETENSIONER, HAS
 TO REMOVE BOTH FRONT
 SEAT TO GAIN ACCESS TO
 PRETENSIONERS.

ME CODE ON DRIVE
 SIDE, PERFORMED
 DIAGNOSTIC PIN POINT
 TEST DRIVE SIDE BUCKLE
 CONNECTOR FOUND
 OPEN CIRCUIT. REPLACED
 NEW DRIVE SIDE SEAT
 BELT BUCKLE AND CLEAN
 MEMORY CODE AND
 PERFORMED ON

LEE BAPP 20031701	9443957 BR02	1L5Z	1081208	AAA	Dvr
DEE THOA 67129101	8453368 BR02	1L5Z	1081208	AAA	Dvr
BROWN W 9826001	4298673 BR02	1L5Z	1081208	AAA	Dvr
HUNTING 17657801	8428811 BR02	1L5Z	1081208	AAA	Dvr
NORTH CE 57463401	2318481 BR02	1L5Z	1081208	AAA	Dvr
SEGUIN F 8489102	3031182 BR02	1L5Z	1081202	AAA	Pgr
RANCHO I 28180401	8981302 BR02	1L5Z	1081202	AAA	Pgr
RANCHO I 28180301	8981302 BR02	1L5Z	1081202	AAA	Dvr
FRIENDLY 4304291	8707221 BR02	1L5Z	1081202	AAA	Pgr
RACEWA\431418A	7841000 BR02	1L5Z	1081202	AAA	Dvr
ADVANTA 3884401	8599889 BR02	1L5Z	1081208	AAA	Dvr
CRAIN PO 38827802	3154700 BR02	1L5Z	1081202	AAA	Pgr
COURTES 8288001	2361800 BR02	1L5Z	1081202	AAA	Pgr
MARCOE 458738E	3578500 BR02	1L5Z	1081208	AAA	Dvr
RACEWA\458317D	7841000 BR02	1L5Z	1081202	AAA	Pgr
ENGLAND 9781108	3328341 BR02	1L5Z	1081208	AAA	Dvr
HERITAGE 14780001	9877800 BR02	1L5Z	1081208	AAA	Dvr
BUDGET F 21554401 *	BR02	1L5Z	1081202	AAA	Pgr
SAM PAC 323318A	3428418 BR02	1L5Z	1081208	AAA	Dvr
EL CAJON 8803452	5798888 BR02	1L5Z	1081202	AAA	Pgr
ENGINITA 4838451	7838288 BR02	1L5Z	1081202	AAA	Pgr
WED BLUF 1757801	8272818 BR02	1L5Z	1081202	AAA	Pgr

TEST DRIVE TO VERIFY AIR BAG LIGHT FLASHES/EEC TEST
 RECAL/PINPOINT TEST. MONITOR REPLACE DRIVERS SIDE SEAT BELT
 PRETENSIONER. CLEAR CODES TEST DRIVE.
 REPAIR AND REPLACE THE SEAT BELT BUCKLE
 WDS TEST AND RECEIVED CODE B1877. PERFORM PINPOINT TEST
 AND FOUND DRIVERS SEAT BELT BUCKLE PRE TENSIONER
 FAULTY. REMOVE DRIVERS SEAT AND REPLACE BUCKLE
 ASSEMBLY. CLEAR CODES AND RETEST.
 DIAGNOS FOR AIR BAG HAD DTC B1877. REPLACE DRIVER SEAT
 BELT PRETENSIONER THAT HAS AN OPEN CIRCUIT. 1
 VERIFIED CONCERN HOOKED UP NGS AND PERFORMED BODY
 CHASSIS ELECTRICAL TEST. PERFORMED PINPOINT TEST AND
 DCL DISPLAY. REPLACED OPEN DRIVER B SIDE PRETENSIONER.
 CLEARED CODES AND
 1 SUPPLEMENTAL RESTRAINT SYSTEM DIAGNOSTICS CODE B1081
 PINPOINT TEST REPLACE RIGHT SEATBELT PRETENSIONER
 RETEST
 REPLACE SEAT BELT
 REPLACE SEAT BELTS
 REPLACE SEAT BELT
 PIN POINT TEST MONITOR PDS OHMS ON LEFT PRETENSIONER
 GOOD SVATER LIGHT ONLY COMES ON AT TIMES REPLACED L/
 SEAT BELT BUCKLE PRETENSIONER RETEST OK
 REPLACED 2 SEAT BELT BUCKLES
 BROKEN LATCH REPLACE SEAT BELT
 REPLACED BOTH FRONT SEAT BELTS
 VERIFY CONCERN, NGS DIAG CODE B1877, PINPOINT TEST HIGH
 RESISTANCE, REPLACED DRIVERS SEATBELT BUCKLE
 RETRIEVE CODES PINPOINT TEST TEST CIRCUITS TO HIGH
 PRETENSIONER REPAIR LOCKING DOWN RETEST CODE STILL PRESS
 REPL. RIGHT FRONT PRETENSIONER

PERFORMED SRS SYSTEM DIAGNOSIS AND FAULT CODE
 RETRIEVAL, FAULT LFC 48, DRIVERS SIDE SEATBELT
 PRETENSIONER FAULT. REMOVED AND REPLACED DRIVERS SIDE
 SEATBELT PRETENSIONER ABSY ROAD TESTED, ALL SYSTEMS ARE WORKING PROPERLY.
 VERIFY CONCERN PERFORM DIAGNOSTICS CODE 48 PRESENT
 PERFORM PINPOINT TESTS
 PERFORM PINPOINT TEST R I SEAT REMOVE AND REPALOE
 11878 28 PRETENSIONER 12851D 2, DX1 .1, D2 3, M1 .7 1.3 WDS TO
 SOE. PINPOINT P1877. RSR SEAT REPLACE DRIVERS
 PRETENSIONER.
 LATCHES INTERMITTENTLY SEATBELT ASSEMBLY FRONT
 REPLACE
 REPLACE BOTH SEAT BELTS

ROAD TEST LIGHT DID NOT COME ON, HOOKED NGS HAS CODE
 P1877 IN MEMORY. PASS ON DEMAND PINPOINT TEST T1
 THROUGH T6 HAD REMOVED DRIVERS SEAT TO ACCESS
 PRETENSIONER, REPLACED PRETENSIONER, ROAD TEST, RECH ECK OK.

LONG MOT	10421	8432821	6R02	1L5Z	1061203	AAA	Drv	REMOVE AND INSTALL DRIVERS SEAT BELT ASSEMBLY
KESTLER, F	16621201	3918811	6R02	1L5Z	1061203	AAA	Drv	41 STICKING REPLACED BELT 30223 838 28 WDS START UP BELF TEST,MONITOR SENSOR INPUTS DTC 1877 OPEN CIRCUIT DRIVER SIDE PRE TENSIONER REMOVE SEAT,REPLACE PRETENSIONER,CLEAR CODE RE TEST 18600.2 14068.D 8 61173A-4 INOP REMOVED SEAT AND RELPACED BELT BUCKLE ASSEMBLY REPLACE SEAT BELT
COASTAL 218298A	2546285	6R02	1L5Z	1061208	AAA	Drv		
VENUS FC	2539862	4618500	6R02	1L5Z	1061208	AAA	Drv	
ENCINITA	4844851	7238286	6R02	1L5Z	1061208	AAA	Drv	
REYNOLD 007709B	3212411	6R02	1L5Z	1061202	AAA	Page		RUN AIR BAG DIAG,CODE B1877,PIN POINT TEST OPEN CIRCUIT PRETENSIONERS,REPLACE DRIVER AND PASS SEAT BELT ASSY 1 TESTED AIR BAG SYS CODE B1877 MTB1203 AIR BAG SYS PPT FOUN INT INOP DRIVERS SEATBELT PRETENSIONER R R SEAT TO REPLACE 8273 C.C #1203 AIR BAG DIAG RETRIEVE CODE B1877 DRIVER PRETENSIONER OPEN REPLACE DRIVER PRETENSIONER BUCKLE RE TEST OK OPEN CIRCUIT VERIFY CUSTOMER CONCERN, RD TEST ABS TEST CODE B1881 R/R SEAT TO REPLACE PRETENSIONER. OPEN CIRCUIT SEATBELT BUCKLE INOP REPLACED BUCKLE REPLACE LATCH DOESN,T WORK 7 REPLACED DRIVERS SEAT BELT BU CKLE WITH PRETENSION ER REPLACE ONE SEAT BELT FAULTY DR SIDE SEATBELT PRETENSIONER,CC48 CK AIRBAG LIGHT OPER,PERFORMED AIRBAG DIAGNOSED HOOK NGS TO RETRIVE CODES,PULLED CODE B1877 OPEN CIRCUIT AT PRETENSIONER, REPLACED PASS SIDE SEAT BELT BUCKLE W TIME TO REPLACE NO LABOR OPS
HUNTING 17810601	3428811	6R02	1L5Z	1061203	AAA	Drv		
MAG HAIK 168861A	8323000	6R02	1L5Z	1061208	AAA	Drv		
NORTHBE 33680401	5258800	6R02	1L5Z	1061202	AAA	Page		
JIM CLICK 28882802	7472800	6R02	1L5Z	1061203	AAA	Drv		
TOULSBY 306521A	4847231	6R02	1L5Z	1061202	AAA	Page		
DON BOHI 285571A	3477000	6R02	1L5Z	1061208	AAA	Drv		
ENCINITA 4889151	7638288	6R02	1L5Z	1061202	AAA	Page		
CERRITO 28820002	8668654	6R02	1L5Z	1061203	AAA	Drv		
BYCAMOF 8622801	8254884	6R02	1L5Z	1061202	AAA	Page		
TOLBIE V 183808A	8664861	6R02	1L5Z	1061202	AAA	Page		
HILL-TERR 8388851	4881801	6R02	1L5Z	1061202	AAA	Page		
COURTES 43700801	7844343	6R02	1L5Z	1061202	AAA	Page		1 REPLACED PASS SEAT BELT
COURTES 43701001	7844343	6R02	1L5Z	1061202	AAA	Page		1 REPLACED PASS SEAT BELT.
COURTES 43700801	7844343	6R02	1L5Z	1061203	AAA	Drv		1 REPLACED BOTH SEAT BELTS,
ENCINITA 5184751	7638288	6R02	1L5Z	1061202	AAA	Page		REPLACE ONE SEAT BELT 13 FOUND UNIT APART AIR BAG LIGHT ON, CONNECT NGS RETEIVE CODE B1891 ,INSTALL SEAT BELT TENSIONER AND CLEAR OEM CODES , REPL SEATBELTS CC 01 NEW SEATBELT BUCKEL INSTALLED REPALCED SEAT BELT BUCKEL
MINAR FO 106788A	8338010	6R02	1L5Z	1061202	AAA	Page		
COURTES 43700801	7844343	6R02	1L5Z	1061203	AAA	Drv		
METROPC 4388301	8438000	6R02	1L5Z	1061203	AAA	Drv		
GORDIE B 22738005	2568010	6R02	1L5Z	1061203	AAA	Drv		

SANTA M	229787A	4698800	6R02	1L5Z	1081208	AAA	Drvr
GALPIN R	6845871	7873800	6R02	1L5Z	1081202	AAA	Page
ASTRO FC	8638861	3828350	6R02	1L5Z	1081203	AAA	Drvr
HOOD RN	0587048	3882277	6R02	1L5Z	1081202	AAA	Page
SARABOT	3888151	3888673	6R02	1L5Z	1081202	AAA	Page
BILL UTTE	9630281	3217400	6R02	1L5Z	1081208	AAA	Page
FIVE STAR	198848A	4888638	6R02	1L5Z	1081202	AAA	Page
DAVID WIL	8448281	8781880	6R02	1L5Z	1081203	AAA	Drvr
JOE COOF	1472501	3541111	6R02	1L5Z	1081203	AAA	Drvr
SULLIVAN	1290201	5442134	6R02	1L5Z	1081203	AAA	Drvr
WALKER F	8680601	5353673	6R02	1L5Z	1081203	AAA	Drvr
GRESHAM	309744A	8888101	6R02	1L5Z	1081202	AAA	Page
ELDER FC	183210A	5854000	6R02	1L5Z	1081203	AAA	Drvr
WAYNE A	218181B	5824444	6R02	1L5Z	1081202	AAA	Page
COVE POW	4441251	5474226	6R02	1L5Z	1081203	AAA	Drvr
PARK CITI	17248701	3888800	6R02	1L5Z	1081203	AAA	Drvr
ORCHID II	3088831	8881891	6R02	1L5Z	1081203	AAA	Drvr
HACIENDV	8688001	3881815	6R02	1L5Z	1081203	AAA	Drvr

1138L CC 42 CP 81203 MTS1203 2.0 2.0 FLAG 112 TEST DROVE TO VERIFY AIR BAG LIGHT CONCERN. UNABLE TO VERIFY. HOOKED UP NGS TO PULL CODES. PULLED CODE 1877 DRIVERS TENSIONER CIRCUIT OPEN, HOOKED UP

SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELT INOPERATIVE BODY CHASSIS ELEDTRIAL (BCE) TEST PERFORMED AIR BAG DIAG DTC 48 PRESENT, R AN R SEAT BELT BUCKLES, RETEST OK

INOP AIR BAG RESTRAINT SYSTEM DIAGNOSIS AIRBAG LIGHT ON NGS TESTS, CODES 81881, REPLACED PASS BUCKLE, RETEST

2001S 42 W DIAG USE NGS NGS START UP PULLED CODES DO PIN POINT TEST PULLED PASS SEAT REPLACED PRETENSIONER RETEST CLEAR CODES ALL OK AFTER REPAIR

LEFT SEAT BELT REPLACED DEFECTIVE LEFT SIDE SEAT BELT BUCKLE

DRIVERS SEAT BELT BUCKLE VERIFIED AIR BAG LITE ON. HOOK UP NGS AND PERFORMED BOE DIAG RETRIEVED CODE 81877 FROM RCM. PERFORMED PPT TO DRIVERS SEA

REMOVE DRIVERS SEAT REPLACE BUCKLE PRETENSIONER ASSEMBLY

48 SHORTED 5731 AIR BAG DIAG REMOVE DRVR SEAT REPLACE AIR BAG PRETENSIONER RETEST OK

INSPECTED AND VERIFIED, REPLACED RIGHT SIDE FR CNT SEAT BELT

3830 RMR LEFT FRONT SEAT ASSY, REPLACE PRETENSIONER SEAT BELT END. SEAT BELT WORKING NOW. CC 42 CP 1081203

4488 42 W 7855 AIRBAG LIGHT FLASHING RETRIEVE CODE WITH NGS CODE 1881 INCLUT IN RT PRETENSIONER PINPOINT TEST

REPLACE RT PRETENSIONER

POOR CONTACT EEC TESTED KOEO B1877, B1888, B1877 PINPOINT TESTED REMOVE

CHECKED AIR BAG B1877 FOLLOW PINPOINT TEST TO CHECK RESIST. AT DRIVERS SIDE SEAT BELT. 2.1 4.0 OHMS. REPLACED

DRIVERS SIDE OPEN CIRCUIT

AIR BAG RESTRAINT SYSTEM DIAGNOSIS MY TO PIN POINT TEST 61 82 3 7 REPL FRONT SEAT BELT

PRETENSIONER FAILED VERIFIED CONCERN PIN POINT TEST TO PRETENSIONER REPRGM PCM AND REINSTALLED NEW TENSIONER

A JUMPER TO IT AND VERIFIED HAVING A FAULTY SEAT BELT BUCKLE TENSIONER. REPLACED FAULTY SEAT BELT BUCKLE TENSIONER AND CLEARED CODES. NORMAL OPERATION AT THIS TIME MY AUTH #

WESTWA 87113701	8690333 8F02	1LSZ	1081202	AAA	Drvr	1 VERIFIED CONCERN PERF 819 SYSTEM TEST RETEST CODE FOR DRIVE SEAT BELT HIGH RESISTOR PERF PINPOINT TEST PID MONITOR FOLN PERFORM DIAG WDS DCL PPT FAILED SEAT BELT TENSIONER TO BE INSTALLED AT S SHOP
CHPOLA 5724001	4884043 8F02	1LSZ	1081202	AAA	Patr	
JEFF SCH 300128A	8880000 8F02	1LSZ	1081203	AAA	Drvr	1124 DRIVERS SEATBELT BUCKLE HAS INTERNAL SHORT WARRANTY R&I DRIVERS SEAT REPLACED SEAT BELT LATCH
TYLER FO 47731	8762313 8F02	*	1081202	*	Drvr	AIR BAG LIGHT ON DIAG CODE B2282 LFC 33 SEAT BELT UNPLUG L NOT FAIL REMOVE CARPET TRACE WIRES TO RCM NPF REMOVE RF SEAT PULL AND TWIST LOOM AND CONNECTO R SITLL WILL NOT FAIL ORDER PRETENSIONER INSTALL PRETENSIONER RE TEST
BEUCKMA 105503A	2276700 8F02	1LSZ	1081202	AAA	Patr	515 SET UP WDS PERFORM RCM SELF TEST 1811 HARD FAULT HIGH RESISTANCE IN RF PRETENSIONER PERFORM RCM DCL CAN GET RF TO FAIL BY MOVING SEAT FORWARD AND BACK WIGGLE LOOM TAP ON PRETENSIONER NOW IT WILL DOES NOT OPERATE PROPER SEATBELT ASSEMBLY FRONT REPLACE DR SIDE OPEN PRETENSIONER AIR BAG RESTRAINT SYSTEM DIAGNOSIS INOP AIR BAG RESTRAINT SYSTEM DIAGNOSIS
ORCHID K 5723151	8351181 8F02	1LSZ	1081202	AAA	Drvr	REPLACE LEFT SIDE AIR BAG PRETENSIONER
JORDAN F 7282061	8533873 8F02	1LSZ	1081203	AAA	Drvr	1 PERFORMED AIR BAG DIAG, PID MONITOR, TEST, PINPOINT TEST AND REPLACED DRIVER SEAT BELT PRETENSIONER
MIKE FITZ 9002461	8082873 8F02	1LSZ	1081203	AAA	Drvr	
WESTWA 86633801	8580333 8F02	1LSZ	1081203	AAA	Drvr	
BOBBY FC 165825A	2954224 8F02	*	1081202	*	Patr	11542 28 1081202 HOOK UP M.G.S., RETRIEVE COMT. DTCS, B1881 PRESENT, PASS SEATBELT PRETENSIONER OPEN CKT. PERFORMED DAJB. & PINPOINT TEST, R&I PASS SEAT AND INSPFT 80 40 SEATING. PRETENSIONER BUCKL REPL UP SEAT BELT.
HILLSIDE 1148188A	8233100 8F02	1W1Z	5481202	AAC	Unknown	
HILLSIDE 1137428A	8233100 8F02	1W1Z	5481202	AAC	Unknown	REPL BELT ASSY.
HERITAGE 089384A	* 8F02	1W1Z	5481202	AAD	Unknown	REPLACE LEFT FRT SEAT BELT BUCKLE 1223 LATCH ON SEAT BELT BROKEN INSIDE REMOVE DRIVED FRONT SEAT REPLACE SEAT BELT LATCH
NICH MOF 172888B	7884000 8F02	1W1Z	5481202	AAB	Unknown	21 41 WARR FOUND THAT THE LEFT FRONT SEAT BELT BUCKLE BOUND UP, R & R LEFT FRONT SEAT BELT BUCKLE ASSY, CHECKED FOR OPERATION OK AT THIS TIME. 5574
JACK DEL 188453C	2748800 8F02	1W1Z	5481202	AAB	Unknown	REPLACE BUCKLE REPLACED BUCKLE ASSY
GEORGE 11258001	7475400 8F02	1W1Z	5481202	AAD	Unknown	INSPECTED AND REPLACED SEAT BELT BUCKLE
HERTZ P 43718901	* 8F02	1W1Z	5481202	AAC	Unknown	81202 42 REPLACED PASSENGER BELT BUCKLE AND RE TEST OK
UPTOWN 143125A	7718000 8F02	1W1Z	5481202	AAE	Unknown	TJK
AUTOWAY 11431801	4882000 8F02	1W1Z	5481202	AAD	Unknown	

PENNSA	3738801	9520600	6R02	1W1Z	5461202	AAB	Unknown
ANAHEIM	9821651	3359100	6R02	1W1Z	5461202	AAB	Unknown
MITCHELL	031165A	3473481	6R02	1W1Z	5461202	AAE	Unknown
WORLD P	560891	3449900	6R02	1W1Z	5461202	AA5	Unknown
HUNTER	1087455A	6672222	6R02	1W1Z	5461202	AAD	Unknown
PASADEN	3375581	6633573	6R02	1W1Z	5461202	AAB	Unknown
ALTON BL	167713A	6758181	6R02	1W1Z	5461202	AAD	Unknown
DECKER F	1189988	2912881	6R02	1W1Z	5461202	AA5	Unknown
DIFFEE PC	054829A	2884548	6R02	1W1Z	5461202	AAB	Unknown
AURORA I	4366801	6670707	6R02	1W1Z	5461202	AAE	Unknown
FORD MO	2841882 *	6R02	6R02	1W1Z	5461202	AAB	Unknown
FORD MO	3418651 *	6R02	6R02	1W1Z	5461202	AAD	Unknown
GALPIN LI	3766821	6623600	6R02	1W1Z	5461202	AAD	Unknown
BARON LI	5896601	6319800	6R02	1W1Z	5461202	AAC	Unknown
W/TT UNC	12885801	6629000	6R02	*	5461202	*	Unknown
CHAMPIC	14318801	6630012	6R02	1W1Z	5461202	AAD	Unknown
CALLARE	1048301	6608200	6R02	1W1Z	5461202	AAD	Unknown
POMPAN	276800A	7828110	6R02	1W1Z	5461202	AAD	Unknown
MCNELLY	128018A	4632833	6R02	1W1Z	5461202	AAD	Unknown
PURCHAS	6167101	6478900	6R02	1W1Z	5461202	AAD	Unknown
PINES LN	144705A	6602000	6R02	1W1Z	5461202	AAD	Unknown
BUDGET F	9867441 *	6R02	6R02	1W1Z	5461202	AA5	Unknown
BUDGET F	7925341 *	6R02	6R02	1W1Z	5461202	AAC	Unknown
FREEDOM	163675A	4241100	6R02	1W1Z	5461202	AAD	Unknown

VERIFIED CONCERN, SEAT BELT BUCKLE LATCH BROKEN INTERNALLY REMOVED AND REPLACED BUCKLE
PASS FRNT SEAT SHOULDER BELT TRACK ASSEMBLY FRONT SEAT REPLACE
BUCKLE NOT LATCHING REPLACED DRIVER'S BUCKLE TRACK ASSEMBLY FRONT SEAT REPLACE
PASS FRONT SEATBELT WONT LATCH, REPALCED PASS FRONT SEATBELT BUCKLE AND RETESTED. OK
REPLACED RIVER SEAT BELT BUCKLE WILL NOT LATCH NECC R R SEAT
REPLACED DRIVER SEAT THAT WOULD NOT LATCH, R PASS. FRONT SEAT BELT BUCKLE WILL NOT LATCH R/R SEAT TO REPLACE BUCKLE ASSY.

13 CAUSE: AIR BAG LIGHT FLASHING CORR: VERIFIED CONCERN, BOE DIAG B2496, B2496, CONT, B2496 HARD FAULT, PID DATA MONITOR, PPT P1 P6, REPLACED PASSENGER SEAT BUCKLE, CLEARED CODES, RETEST OK BPN 3
FOUND SEATBELT BUCKLE IS BUNING. RR SEAT AND REPL RB SEATBELT BUCKLE. CLOSED AT WP1.
XXXXXXXXXXXXXXXXXXXX
REPLACED SEAT BELT LATCH
. REPLACED A FAULTY SEAT BELT BUCKLE ASSEMBLY TO CORRECT CONCERN
REPLACE DRIVER SIDE SEAT BELT ASSY
REMOVED BUCKLES FOR CUSTOMER CAR. REPLACED BOTH FRONT SEAT BUCKLES. OCS

461202 CC25-OC325

FOUND SEAT BELT BUCKLE SWITCH DEFECTIVE REPLACE DRIVER SEAT BELT BUCKLE AND RETEST S38 42
B105 42 W AIR BAG DIAGNOSTIC CODE B2496 DEACTIVATE AIR BAG SYSTEM PINPOINT TEST 2432 1 RESULT OPEN CIRCUIT TO SEAT SWITCH REPLACE SEATBUCKLE REACTIVATE SYSTEM
REPIN TEST SA
REPLACE R SIDE SEAT BELT BUCKEL
REPLACED D SIDE SEAT BELT BUCKLE M TIME FOR NO LABOR OCS
2855 W ROAD TEST PERFORMED AIR BAG DIAG NO CODES CALLED HOT LINE CONTACT 28063087 WAS TOLD PASS SEAT BELT SWITCH HAS INTERMETTING OPEN TO REPLACED SEAT BELT BUCK AND SWITCH ASY REMOVED D SEAT TO R PASS. PRETENSIONER FAILURE. REPL BUCKLE
LF SEAT BELT BUCKLE (NOP, FOUND LF SEAT BUCKLE JAMMED, REPLACED
6645 CHECK SEAT BELT OPERATION FOUND SEAT BELT BUCKLE LOCK UP RR BOTH FRONT SEAT TO REPLACE BOTH BUCKLES AND REASSEMBLE

EPLACE SEAT BELT SWITCH RETESTED OK

MOFFITT 0730868	4386396	6F02	*	5481202	*	Unknown
HERTZ RV 45721501		6F02	1W1Z	5481202	AAC	Unknown
DUNN FO 5480052	9874321	6F02	1W1Z	5481202	AAC	Unknown
WESTWO 3482102	2057700	6F02	1W1Z	5481202	AAC	Unknown
CHEMNER 147880C	8930800	6F02	1W1Z	5481202	AAA	Unknown
EAGLE LI 4088901	3570481	6F02	1W1Z	5481202	AAE	Unknown
PLAZA LN 1487181	7871255	6F02	1W1Z	5481202	AAD	Unknown
NORTH FI 5003151	6484160	6F02	1W1Z	5481202	AAD	Unknown
HERTZ RV 54478101		6F02	1W1Z	5481202	AAD	Unknown
LONG BE 5128382	4283301	6F02	1W1Z	5481202	AAB	Unknown
GREGG M 9004001	7250850	6F02	1W1Z	5481202	AAE	Unknown
HARBOR I 7923301	4574400	6F02	1W1Z	5481202	AAD	Unknown
HARBOR I 7780801	4374400	6F02	1W1Z	5481202	AAD	Unknown
AL PADKE 0887178	4868100	6F02	*	5481202	*	Unknown
BROWN L 12024101	3535500	6F02	1W1Z	5481202	AAB	Unknown
BROWN L 11678002	3525500	6F02	1W1Z	5481202	AAB	Unknown
CONDITS 2090000	3832800	6F02	1W1Z	5481202	AAD	Unknown
BARANCC 2880301	4878800	6F02	1W1Z	5481202	AAC	Unknown
BUDGET F 5738851		6F02	1W1Z	5481202	AAE	Unknown

CHECKED AIR BAG LIGHT ON TEST WITH NBS TESTER FOUND FAULT IN DRIVERS SEAT BELT SHOWS OPEN REMOVED SEAT FOUND WIRE TO SEAT BELT SENSOR BAD REPAIRED RETEST OK REPALCE BUCKLE ASSY

UP SEAT LATCH NOT WORKING REMOVE LEFT SEAT ASY AND REPLACE SEAT LATCH

1 PERFORM WDS DIAGS PERFORM AIR BAG DIAGS PERFORM PIN POINT TEST REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY

3 28 WDS START, SELF TEST AIR BAG, CODE B203A, PINPOINT TEST, DISABLE AIR BAG SYSTEM AND PERFORM AIR BAG DIAG, R-R DRIVER SEAT, ATTEMPT TO LOCATE INTER SHORT TO DRIVER SEATBELT BUCKLE, REPLACE BUC

LEFT FRONT SEAT BELT WOULD NOT MOVE WAS BINDING REPLACED LEFT SEAT BELT

STICKS REPLACED SEAT BELT BUCKLE ON DRIVERS FRONT

OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS

REPLACED SEAT BELT ASSY

PERFORM AIR BAG RESTRAINT SYSTEM DIAGNOSIS, PIN POINT TEST FOUND FAULTY DRIVER SIDE SEAT BELT BUCKLE ASSEMBLY OPEN, REMOVE AND REPLACE DRIVER SEAT BELT BUCKLE (M TIME TO REPLACE), ROAD TEST, OKAY

VERIFY CONCERN AND REPLACE RIGHT FRONT SEAT BELT RECEPTACLE RECHECK OK

GAP ON BUCKLE END LOOSE RESECURED

BEG TESTED FOUND CODE B2032, PERFORMED PINPOINT TEST PER SHOP MANUAL, R/R BOTH AIR BAGS TO INSTALL SHORTING BARS, PERFORMED, GOP INSTALLED

EEO TESTED AND FOUND CODE B2032, PERFORMED PINPOINT TEST, R AND R DRIVERS SEAT TO TEST WIRE TO SAFETY BELT PRETENSIONER ALL OK, DEACTIVATED RESTRAINT SYSTEM TO R AND R AIR BAGS TO INSTALL DIAG TOO

CHECK FOR CODES AIR BAG LIGHT ON B2032 PERFORM DIAGNOSIS CHECK AND DIAG REMOVED DRIVER SEAT AND REPLACED DRIVER SEAT BELT ASSEMBLY RECHECK AND REASSEMBLE RECHECK ALL PASS

R AND R SEAT BELT AND REPLACED TO CORRECT DRIVE SIDE SEAT BELT BUCKLE STUCK LOCK SPRING INSIDE INTERNAL BUCKLE, REPL NEW BUCKLE

KLE. RE ACTIVATE SYSTEM AND RETEST, OK

. PERUN FINAL QUICK TEST, PASS (OKAY).

L. DCL DIAG TO WATCH PIDS. FOUND PRETENS IONER AT 0 OHMS. NECESSARY TO SPECIAL ORDER PRETENSIONER,

JACK DEN	145372A	2745500	6R02	1W1Z	5481202	AAD	Unknown
DELRAY L	6316091	2762411	6R02	1W1Z	5481202	AAB	Unknown
AUDUBON	2058750	2288900	6R02	1W1Z	5481202	AAC	Unknown
BUDGET F	9242721		6R02	1W1Z	5481202	AAE	Unknown
VISTA LD	5822651	3488900	6R02	1W1Z	5481202	AAB	Unknown
SUNFLOW	1077802	7808700	6R02	1W1Z	6481202	AAE	Unknown
RIVERTON	873051	6537420	6R02	F81Z	2681203	CGD	Drvr
PITTS FOR	7902002	5884541	6R02	1G3Z	2681203	AAA	Drvr
FORD OF	4854851	7394800	6R02	F81Z	2681203	CGD	Drvr
FORD OF	4882851	7394800	6R02	F81Z	2681203	CGD	Drvr
GRAF FOR	4483802	7757481	6R02	F81Z	2681203	CGD	Drvr
MAG HAK	1452800	9303573	6R02	YC3Z	7881202	AAA	Pagr
ACADIAN	108751A	5437125	6R02	YC3Z	7881202	AAA	Pagr
FREEDOM	22871161	4868411	6R02	F81Z	2681203	JJ	Drvr
TEAM FOR	3508761	4828900	6R02	1L7Z	7881202	AAA	Pagr
FORT MO	5344001	7330861	6R02	1L7Z	7881202	AAB	Pagr
RIC JOHN	1883001	4239211	6R02	1L7Z	7881202	AAD	Pagr
COVERT F	727401	3538000	6R02	1G3Z	2681203	CAA	Drvr
JACK FOR	7838251	5855000	6R02	1G3Z	2681203	CAA	Drvr
LUMPS FOR	3038802	9821122	6R02	1G3Z	2681203	CAA	Drvr

3847 EXAMINE CONCERN, TESTED PASSENGER SEAT BELT FOR OPERATION, AT THIS TIME CAN NOT VERIFY ANY PROBLEM WITH PASSENGER FRONT SEAT BELT. TESTED DRIVER FRONT SEAT BELT BUCKLE, FOUND THAT THE SEAT BURNED OUT AIR BAG RESTRAINT SYSTEM DIAGNOSIS, REPLACE LEFT FRONT SEAT BELT BUCKLE PRETENSIONER
 11088 PERFORM AIR BAG SYSTEM DIAG, CODE 51, TRACE AND REPAIR DAMAGED CONNECTOR AND RETEST, REPLACE ONE FLUGE AND RETEST, R AND R DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE AND RETEST OK
 BELT BUCKLE INOP REMOVED RF PASS SEAT TO GAIN ACCESS TO BUCKLE REPLACED BELT BUCKLE
 INSPECT & REPLACE RT FRNT SEAT BELT BUCKLES WONT LATCH, BUCKLE BIND

A REPLACED SEAT BELT BUCKLE
 REPLACE TAILGATE LOCK ASSEMBLY.

INOP ADDITIONAL MISC. REPAIRS

INOP SEATBELT ASSEMBLY FRONT REPLACE
 1 REPLACE SEAT BELT BUCKLE

R/R SEAT BELT BUCKLE
 PASS FRNT SEAT BELT DOESNT LATCH. REPLACED SEAT BELT BUCKLE ASSY, FSA 01821 CHECKED REQUIRED SEAT BELT BUCKLES WITH TOOL

15737 LEFT FRONT SEAT BELT BUCKLE NOT LATCHING CODE 42
 CHECK SEAT BELT BUCKLES FOUND LEFT FRONT NOT LATCHING
 REMOVE LEFT FRONT SEAT REMOVE RT SIDE SEAT TRACK
 REMOVE BUCKLE REINSTALL NEW BUCKLE RE

BELT BUCKLE WILL NOT LATCH WITH SEAT BELT, REMOVE OLD SEAT BELT BUCKLE, INSTALL REPLACEMENT SEAT BELT BUCKLE, TESTED, DRIVER FRONT SEAT BELT BELT BUCKLE WORKING PROPERLY AT THIS TIME.

REINSTALL TRACK AND REINSTALL SEAT MIT TIME REQUIRED NO PUBLISHED OP FOR REPAIR

REINSTALLED PASS SIDE SEAT BELT BUCKLE
 DIAG FOR RIGHT SEAT BELT WILL NOT LATCH. R/R FAULTY LATCH ASSY. TST PASS
 RH FRONT SEAT BELT BUCKLE WONT LATCH, R/R SEAT AND REPLACE BUCKLE
 REPLACED THE L F SEAT BELT BUCKLE
 REPLACE LEFT FRNT SEATBELT ASSY, WOULD NOT LATCH
 R & R LEFT FRONT SEAT & TRACK ASSEMBLY & REPAIR SEAT BELT ANCHOR REPLACE SEAT BELT BUCKLE ASSEMBLY

LONG MC	6482	8432221	6R02	1C3Z	2581203	CAC	Drv	REPLACE LEFT SEAT BELT BUCKLE ASSEMBLY REPLACE DRIVERS SEAT BELT INSTALLED DRIVER SIDE FRONT SEAT BELT, IT WAS MISSING.
BUTTERF	439123	8888441	6R02	1C3Z	2581203	CAA	Drv	INSTALL SPO PART INSTALLED SEATBELT BUCKLE
JIM CLICK	32194801	7472000	6R02	1C3Z	2581203	CAA	Drv	102 SEAT BELT BUCKLE, CODE 42 REPLACED DRIVERS SEAT BELT BUCKLE DUE TO ERRATIC OPERATION NEEDED TO LOOSEN SEAT CUSHION TO THREAD SEAT BELT WIRING THRU FRAME SEATBELT WILL NOT LATCH PROPERLY REPLACED LEFT FRONT SEATBELT RETEST, CHECKS GOOD (R)
PARKWAY	171801A	7248221	6R02	1C3Z	2581203	CAA	Drv	STICKS BINDS OR GRABS REPLACED SEAT BELT 40 20 40 DRIVERS SIDE BELT FAILED
BURT'S AF	380308A	8430000	6R02	1C3Z	2581203	CAA	Drv	
HOLMES 1	34770101	2323800	6R02	1C3Z	2581203	CAA	Drv	
TOM JOH	3888401	3884428	6R02	1C3Z	2581203	CAC	Drv	TEST DRIVERS SIDE BUCKLE OPERATION BUCKLE WILL NOT LATCH BELT INTERNAL DAMAGE TOBUCKLE R/R SEAT AND REPLACE SEATBELT BUCKLE ASSY RETEST OK
SEWELL F	21281801	3880421	6R02	1C3Z	2581203	CAA	Drv	LATCH DOES NOT HOLD SEATBELT ASSEMBLY FRONT REPLACE
HOBLET M	8538021	4882161	6R02	1C3Z	2581203	CAC	Drv	REMOVE LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH REINSTALL NEW BUCKLE ASSY CHECK OPERATION OK MY NO PUBLISHED LABOUR OPERATION FOR THIS REPAIR
FREEDOM	23887403	4889411	6R02	1C3Z	2581203	BAC	Drv	REPLACER CREATURE DEFECT
GARAGE I	2888802	8810120	6R02	1C3Z	2581203	BAD	Drv	REMOVE SEAT BELT AND REINSTALL NEW ONE
FREEDOM	23888931	4889411	6R02	1C3Z	2581203	BAD	Drv	INSPECT AND REPLACE DRIVERS SIDE SEATBELT BUCKLE ASSY.WILL NOT HOLD BELT IN PLACE.MY TIME NO LAB OP IN SLTS TO REPLACE BUCKLE ASSY
WINDSON	3780801	5829530	6R02	1C3Z	2581203	BAD	Drv	
JIM HANB	065802A	6884044	6R02	1C3Z	2581203	BAD	Drv	VERIFIED FOUND DRIVERS SIDE SEATBELT LATCH NOT LATCHING.NO DEBRIS IN BUCKLE ORDERED AND REPLACED OK NOW
MANKATO	6288731	3873454	6R02	F31Z	2581203	MMM	Drv	FEMALE END OF SEAT BELT BAD SEATBELT ASSEMBLY FRONT REPLACE
UHLMANN	321813A	7483355	6R02	F31Z	2581203	JJJ	Drv	REPLACED DRIVERS SEATBELT ASSEMBLY. HAD TO REMOVE DRIVERS SEAT FOR ACCESS. REASSEMBLED AND RECHECKED OPERATION, OK
BLUE SPR	458888A	2284400	6R02	F31Z	2581203	MMM	Drv	REPLACE SEAT BELT BUCKLE
FRIENDS-	030281	2581284	6R02	F31Z	2581203	JJJ	Drv	REPLACE DRIVERS SEAT BELT BUCKLE MY USED NO LABOR OPP
MCKAY FC	063888A	2588485	6R02	1L7Z	7881202	AAA	Page	VERIFIED CONCERN FOUND RIGHT FRONT SEAT BELT LATCH BROKEN REPLACED SEAT BELT LATCH
GENE LAT	18884801	0381289	6R02	1L7Z	7881202	AAA	Page	1 REPL D R F SEAT BELT BUCKLE
DON DAVI	428251B	2514281	6R02	1L7Z	7881202	AAA	Page	4375 RIGHT SEAT BELT WILL NOT BUCKLE DIAGNOSE AND TESTED SEAT BELT BUCKLE. FAILURE TO OPERATE REPLACE SEAT BELT BUCKLE,PART # REPLACE RIGHT SIDE SEATBELT BUCKLE AND LEFT SIDE PAST TEST. C.C. BY BEN
MIDWAY F	188508E	4883000	6R02	1L7Z	7881202	AAA	Page	1025 DEFECTIVE PASS SIDE SEAT BELT LATCH ASSM.
GOLDING	8013351	3787907	6R02	1L7Z	7881202	AAA	Page	180.ORDERED PASS SIDE SEAT BELT LATCH ASSEMBLY. R/R PASS SIDE SEAT LATCH ASSEMBLY.180.
BOWDEN	081389B	8848541	6R02	1L7Z	7881202	AAA	Page	INSPECT AND TEST SEATBELT BUCKLES DRIVER AND PASSENGERS HAD TO REPLACE PASSENGERS SIDE BUCKLE
								REPLACE RH SEAT BELT ASSY

NY LOPEZ

NEY MOT	50821	4534581	6R02	1L7Z	7881202	AAB	Pagr
HOLMES 1	88862201	2922800	6R02	1L7Z	7881202	AAD	Pagr
BICKFORD	645439A	6882122	6R02	1L7Z	7881202	AAA	Pagr
HEMBORC	3363851	7378161	6R02	1L7Z	7881202	AAD	Pagr
UTAH AUT	58304804 *		6R02	1L7Z	7881202	AAB	Pagr
WASHING	2420151	2285100	6R02	1L7Z	7881202	AAB	Pagr
LAGRANG	30142803	4837108	6R02	1L7Z	7881202	AAA	Pagr
COURTES	4762801	7842348	6R02	1L7Z	7881202	AAD	Pagr
BETHLEH	3773431	8678641	6R02	1L7Z	7881202	AAA	Pagr
RAGEWA1	438477A	7841000	6R02	1L7Z	7881202	AAD	Pagr
KUMER' G	2812851	7286544	6R02	1L7Z	7881202	AAD	Pagr
GEWEKE	13808201	3348800	6R02	1L7Z	7881202	AAD	Pagr
NORTH B/	14848201	4234650	6R02	1L7Z	7881202	AAD	Pagr
FRITTS FC	5788553 *		6R02	1L7Z	7881202	AAB	Pagr
CENTRAL	8008882	8688600	6R02	1L7Z	7881202	AAA	Pagr
SEWELL F	21048001	3320421	6R02	1L7Z	7881202	AAF	Pagr
MASSUOC	29831	4881184	6R02	1L7Z	7881202	AAD	Pagr
JIM BASS	7518801	8484821	6R02	1L7Z	7881202	AAB	Pagr
BYKORA F	6676451	8283314	6R02	1L7Z	7881202	AAA	Pagr
TOWN & C	040188A	5880088	6R02	1L7Z	7881202	AAD	Pagr
WOODVIL	2822551	2822628	6R02	1L7Z	7881202	AAD	Pagr
MISSION 1	134888C	4382820	6R02	1L7Z	7881202	AAA	Pagr
BOUND B/	9794001	3880072	6R02	1L7Z	7881202	AAA	Pagr
FRIENDLY	8830054	9248888	6R02	1L7Z	7881202	AAA	Pagr
MAC FORI	5028881	8022111	6R02	1L7Z	7881202	AAD	Pagr
SEGUIN F	5885101	3031188	6R02	1C3Z	2881203	CAD	Dvr
PAUL GEF	0788858	8382400	6R02	1C3Z	2881203	CAD	Dvr
BOB PERF	8228752	7748878	6R02	1C3Z	2881203	BAA	Dvr

CC01 REPLACED RIGHT FRONT SEAT BELT BUCKLE INT TRIM 3E BUCKET SEATS GRAY
10188 PASSENGER SIDE SEAT BELT WILL NOT LATCH. REPLACED WORKS NOW.
REPL PASS SIDE FRONT SEAT BELT BUCKLE NOT LATCHING AT TIMES

1 VERIFY CONCERN. CHECK BUCKLE FOR OBSTRUCTIONS. NONE REMOVE SEAT AND REPLACED BUCKLE AND REINSTALL SEAT TECH 151 VERIFIED CONDITION. REPLACED RIGHT FRONT SEAT BELT BUCKLE AND RETESTED. SEAT BELT OPERATING PROPERLY AT THIS TIME
CP7881202 828 42. REPLACED RF SEATBELT

1 REPLACED BUCKLE.
INOP REPLACE R S SEAT BUCKLE
REMOVE AND REPL. RIGHT FRONT SEAT BELT BUCKLE DUE TO NOT WORKING PROPERLY AT THIS TIME
ACCESS AND REPLACE SEATBELT ASSY SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

ORDERED AND INSTALLED NEW PASS FRONT SEAT BELT BUCKLE REPL. SEAT BELT.

INOP SEATBELT ASSEMBLY FRONT REPLACE
42 REPLACE RF SEATBELT BUCKLE RATTLING
INTERNALLY RETEST
REPLACE R H SEAT BELT BUCKLE BINDING INTERNALLY AND NOT LATCHING
REPLACE RT FRONT SEAT BELT.

1 REPLACED RIGHT FRIT SEAT BELT BUCKEL DONE
RH SEAT BELT BUCKLE DEBATIVE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

REMOVED AND REPLACED PASSENGER SIDE SEAT BELT BUCKLE OK SEAT BELT FOR BEING BROKE REM AND REPLACED RIGHT SIDE LOWER SEAT BELT
INSPECT AND ORDERED NEW BUCKLE REPLACED SEAT BELT BUCKLE RECHECKS GOOD
WILL NOT LATCH. REPLACE FRONT PASSENGER SEAT BELT CHECK AND REPLACE RIGHT FRONT SEAT BELT BUCKLE
3 38 WARRANTY SEATBELT ASSEMBLY FRONT REPLACE

1 REMOVE REPLACE LEFT FRONT SEATBELT BUCKLE
ORDERED SEAT BELT LATCH. REPLACED DRIVER'S SIDE SEAT BELT LATCH AND VERIFIED REPAIR.
DEF BUCKLE REPLACED DR8 SEAT BELT BUCKLE

JACKY JO	4467301	5306873	6R02	1C3Z	2561203	BAA	Drvr	REMOVED SEAT AND SEAT TRACK AND REPLACED SEAT BELT BUCKLE
WENDLE I	198825A	4844300	6R02	1C3Z	2561203	BAA	Drvr	SE HAD TO ORDER LF SEAT BELT STOCK
HAWKINS	022014A	6274881	6R02	1C3Z	2561203	BAA	Drvr	REPLACED SEATBELT ASSY
VALUE FO	3547661	4522241	6R02	1C3Z	2561203	BAC	Drvr	INOP REPLACED DRIVERS SEATBELT BUCKLE VERIFIED CONCERN. FOUND BUCKLE INOP. REMOVED SEAT TO ACCESS AND REPLACED ORDERED BELT BUCKLE. VERIFIED REPAIR.
UTAH ALJ	58281301 *		6R02	1C3Z	2561203	BAC	Drvr	10000 DRIVER SEAT BELT WILL NOT LATCH REPLACE DRIVER SIDE SEAT BELT BUCKLE AND RETEST OK.
RON-OAR	0248008	3318111	6R02	1C3Z	2561203	BAA	Drvr	
DOWNTON	1736408	4488981	6R02	1C3Z	2561203	GAD	Drvr	REPLACED SEAT BELT RECEPICAL
ATASCAD	5813801	4882484	6R02	1C3Z	2561203	BAA	Drvr	REPLACED SEATBELT AND NOW OPERATION OK. TECH VERIFIED CONCERN. ACCESS DRIVERS SEAT, REMOVE AND REPLACE SEAT BELT. OK AT THIS TIME
MATTHEW	185288A	2532731	6R02	1C3Z	2561203	GAD	Drvr	INSTALL DEFECTIVE SEAT BELT BUCKLE
BURCH FC	7345401	6813225	6R02	1C3Z	2561203	BAC	Drvr	VERIFIED THAT DRIVERS SEAT BELT BUCKLE WOULD NOT LATCH. REMOVED DRIVERS SEAT AND REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE. REINSTALLED DRIVERS SEAT AND CHECKED OPERATION OF NEW BUCKLE.
BITTERFC	187338A	2512525	6R02	1C3Z	2561203	BAA	Drvr	
MCKE FO	28408803	3481400	6R02	1C3Z	2561203	BAD	Drvr	NECESSARY TO REPLACE RIGHT SIDE SEAT BELT BUCKLE CHECKED OPERATION. REMOVED THE SEAT TO ACCESS & REPLACED A BINDING SEATBELT.
HAMPTON	8108335	6845771	6R02	1C3Z	2561203	GAD	Drvr	BUCKLE INOP WONT LATCH REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSY.
SMITH GO	2711251	6843191	6R02	1C3Z	2561203	BAA	Drvr	
BLUE SPR	488194A	2294400	6R02	1C3Z	2561203	BAD	Drvr	REPLACE SEAT BELTS
TIFFANY A	4177002	6374481	6R02	1C3Z	2561203	BAA	Drvr	(INOP INSPECTED DRIVERS SEAT BELT. DOES NOT SECURE PROPERLY. REPLACED SEATBELT AND VERIFIED REPAIRS.
GEWISKE I	14822102	3348500	6R02	1C3Z	2561203	BAC	Drvr	REPLACED DRIVER SEAT BELT BUCKLE END
HEBERLE	1582501	3552221	6R02	1C3Z	2561203	GAD	Drvr	REPLACED DRIVERS SIDE SEAT BELT. INSPECT AND VERIFY LEFT FRONT SEAT BELT WONT LATCH. BUCKLE BROKEN, REPLACE LEFT FRONT SEAT BELT AND RECHECK OPERATION
JUETTMEI	074387A	7639128	6R02	1C3Z	2561203	BAD	Drvr	REPLACE LEFT SEAT BUCKLE LATCH
KERLIN W	344311	3822182	6R02	1C3Z	2561203	BAA	Drvr	MT REPLACED SEAT BELT BUCKLE.
KENDALL	81388001	3432151	6R02	1C3Z	2561203	GAD	Drvr	REPLACED DRIVERS BUCKLE MM
TEXAS MC	18658301	2484821	6R02	1C3Z	2561203	GAD	Drvr	
GRASS VJ	277881A	2733385	6R02	1C3Z	2561203	BAD	Drvr	REPLACED SEAT BELT BUCKLE
ED SCHM	68803001	78851	6R02	1C3Z	2561203	GAD	Drvr	REPLACED DRIVER SEAT BELT END
PRIDE-ON	4680501	8298282	6R02	1C3Z	2561203	GAD	Drvr	BUCKLE FAULTY REPLACED LF BUCKLE AND RECHECKED OKAY SEAT BELT BUCKLE MALFUNCTIONING R/R DR SEAT REPLACED
CYPRUS	1812801	5725488	6R02	1C3Z	2561203	BAA	Drvr	SEAT BELT BUCKLE NO 2220
HAWKINS	021828A	6274881	6R02	1C3Z	2561203	BAA	Drvr	REPLACED DRIVERS SEATBELT

TOMBALL 294870A	3515427 6R02	1LJZ	7881202	AAA	Page
WEST CO. 7434802	4856434 6R02	1C3Z	2881203	AAA	Drvr
MERLIN M 1788801	8914811 6R02	1C3Z	2881203	AAA	Drvr
BIG M FOF 8177301	5274408 6R02	1C3Z	2881203	AAA	Drvr
PEACHTR 4231351	4657673 6R02	*	2881203	*	Drvr
CHIPOLA I 5480103	4824043 6R02	1L3Z	1881202	AAA	Page
SEWELL F 882203	3380421 6R02	1L3Z	1881202	AAA	Page
NORTHWN 2184201	5822434 6R02	1L3Z	1881202	AAA	Page
DON SMT 04884C	7881200 6R02	1L3Z	1881202	AAA	Page
PALS FOR 1708801	7722181 6R02	1L3Z	1881202	AAA	Page
HACKETT: 2801400	8521083 6R02	1L3Z	1881202	AAA	Page
NORTHERN 1377802	8736641 6R02	1L3Z	1881202	AAA	Page
LEN STOL 081884C	3887000 6R02	1L3Z	1881202	AAA	Page
JIM SKINN 073800A	8542222 6R02	1L3Z	1881202	AAA	Page
WINCHES 491518A	8874434 6R02	1L3Z	1881202	AAA	Page
JOHN ELY 388848D	8888800 6R02	1L3Z	1881202	AAA	Page
JIM SKINN 070803B	8542222 6R02	1L3Z	1881202	AAA	Page
KARL KLE 1573102	8871101 6R02	1L3Z	1881202	AAA	Page
COWLES I 8280301	8808200 6R02	1L3Z	1881202	AAA	Page
G. STONE 054011A	2886718 6R02	1L3Z	1881202	AAA	Page
PETTJON 2888801	4882344 6R02	1C3Z	2881203	AAA	Drvr
BURCHET 8884401	4448221 6R02	1C3Z	2881203	AAA	Drvr
KENDALL 30879801	3482151 6R02	1C3Z	2881203	AAA	Drvr
SPRADLE 8241951	8383385 6R02	1C3Z	2881203	AAA	Drvr
SPRADLE 2123751	2888873 6R02	1C3Z	2881203	AAA	Drvr
JULES HA 1857482	7388480 6R02	1C3Z	2881203	AAA	Drvr
PRESTON 058888A	8818140 6R02	1C3Z	2881203	AAA	Drvr

7380 ACCESS THE REAR SEAT AND REPLACED THE REAR C P I
 LLAR. R&R FRONT PASS SIDE SEAT AND REPLACED THE
 DEFECTIVE SEAT BELT BUCKLE.
 CHECK AND REPLACE SEATBELT ASBY, RETEST , OK
 DTC 48 FLASH. NGS BODY TEST. DTC B1886. R&R D&B SEAT
 DEACTIVATED AND REPLACED THE D&B SEAT PRETENSIONER.
 CLEARED THE CODES AND RE TESTED SYSTEM PAS
 CHECK FOR FEMALE END OF DR SEAT BELT NOT HOLDING
 SEATBELT, YES, REMOVE SEAT AND SEATBELT LATCH, REPLACE
 LATCH WITH UPDATED VERSION, REINSTALL SEAT,CHECK
 OPERATION, GOOD NOW.
 TOPIN SEAT BELT ASSEMBLY REAR RIGHT OR LEFT
 REPLACE
 BUCKLE REPLACE RIGHT SIDE SEAT BELT BUCKLE
 TEST BOTH FRONT SEAT BUCKLES WONT DRIVERS SIDE OK
 PASSENGER SIDE WONT STAY BUCKLED REPLACED PASSENGER
 SIDE SEAT BELT BUCKLE
 REPLACE BELT REMOVE SEAT FOR ACCESS
 CHK AND FIND RF SEAT BUCKLE OPEN REPLACE BUCKLE AND
 RECHECK OK

RUN AIRBAG SYSTEM DIAG. REPLACE SEATBELT PRETENSIONER.
 REPLACE PASSENGER SIDE SEAT BELT HAD TO REMOVE SEAT TO
 GAIN ACCESS TO BUCKLE
 REPLACE LATCH, RI SEAT TO ACCESS. OK

148 R&R R FRONT SEAT ASSEMBLY, REPLACE SEAT BELT LATCH
 ASSEMBLY. CUST COULD GET SEAT BELT TO POP APART
 TESTED AIRBAG LIGHT ON, TEST CODE B1886, PIN POINT TESTED
 AND REPLACED RT FRN SEAT BELT RETRACTOR
 AND PRETENSIONER...
 REPLACED BAD SEAT BELT TENSIONER
 B127 RI RF SEAT AND REPLACED INOP SEAT BELT BUCKLE

REPLACE PASSENGER REAR SEATY BELT REEFICULE. INOP

REPLACED PASS SEATBELT
 FOUND SEAT BELT NOT LATCHING REMOVED AND REPLACED
 RIGHT PASSENGER FRONT BUCKLE

TENSION OHM SHORTED D&B BODY ELEC R&R DRIVERS SEAT
 AND REPLACED SEAT BELT BUCKL, ASBY ON 40 39 40 SUPER D&B
 AIRBAG TESTS. REPLACED LEFT SEAT BELT BUCKLE
 MT REPLACED DRIVER SIDE SEAT BUCKLE
 SEAT BELT (INOP) REPLACED SEAT BELT BUCKLE
 DRIVERS FRONT BUCKLE WAS NOT ACCEPTING THE BUCKLE
 REMOVED NAD REPLACED THE BUCKLE
 STRONG DRIVERS SEATBELT BUCKLE. REPLACED DRIVERS
 SEATBELT BUCKLE TO REPAIR.
 REPLACE DRIVERS SIDE SEAT BELT

DAVID WIL	8852051	9781850 8R02	1C3Z	2881203	AAA	Drv	DEFECTIVE SEAT BELT BUCKLE	M TIME TO REPLACE BUCKLE
MAGUIRE	098370A	8343111 8R02	1C3Z	2881203	AAA	Drv	REPLACED LEFT SEAT BELT BUCKLE	
HASTINGS	083808B	7580114 8R02	1C3Z	2881203	AAA	Drv	78 DRIVERS SIDE PRETENSIONER LOW RESISTANCE AIR BAG	
TEXOMA F	9067881	4858871 8R02	1C3Z	2881203	AAA	Drv	DIAG AND REPLACED PRETENSIONER	
ELVIN HA	4861851	8288855 8R02	1C3Z	2881203	AAA	Drv	INTERNAL	REPLACED BUCKLE ASSY
							INSPECT SEAT BELT WILL NOT WORK PROPERLY DISARM AIRBAG	
							SYSTEM REMOVED AND REPLACED DRIVERS SIDE PRETENSIONER	
							SEATBELT OK GOOD	
RAY MOY	5870501	7328119 8R02		1881202	*	Pgr	CAUSAL PART 1881202 PERFORMED AIR BAG DIAG, CKED AND	
EMMETT F	1889901	8084801 8R02	1L3Z	1881202	AAA	Pgr	REPLACED SEAT BELT AND BUCKLE ASSY. CONDITION CODE 82	
							DIAGNOSE, REPLACE BELT AND BUCKLE	
							BUCKLE WONT ACCEPT BELT	REPLACED SEAT BELT BUCKLE
ROME FO	1883861	3878830 8R02	1C3Z	2881203	BAD	Drv	NO LOPS	
ENGEL SP	025788A	2458851 8R02	1L3Z	1881202	AAA	Pgr	REPLACE BOTH FRONT SEAT BELT BUCKLES	
							REPLACED BOTH SEAT BELT BUCKLES ON PASS FRONT	
FENTON F	082878A	4282800 8R02	1C3Z	2881203	AAA	Drv	SEATWERE NOT RELEASING PROPERLY	
WILLEY R	1215301	2240886 8R02	1L7Z	7881202	AAD	Pgr	WARRANTY, I RAN OASIS, I THEN RAN SEAT BELT DIAG I FOUND THE	
							PASSENGERS FRONT SEAT BELT RETRACTOR IS BRAKEN ALSO	
							8827 WARRANTY RIGHT FRONT SEATBELT WOULD NOT LATCH AT	ECKED OPERATION, OK
							TIMES. REMOVED PASSENGER SIDE SEAT ASSEMBLY TO ENABLE	ACTUAL CLOCK TIME. J
							REPLACEMENT OF RECEIVER BUCKLE ASSEMBLY. R/R RECEIVER	HAD PROBLEMS WITH
							BUCKLE ASSEMBLY. REINSTALLED SEAT CH	CLOCK TIME ON R.O.
							VERIFIED CONCERN, LF SEAT BELT WILL NOT LATCH. REPLACED	
							BUCKLE ASSY	
BAYWAY I	5781851	8288800 8R02	1W1Z	5481202	AAD	Unknown	BUCKLE WONT SNAP TOGETHER. REPL BUCKLE ASSY	
BUDGET F	4828881	8R02	1W1Z	5481202	AAD	Unknown	REPLACE BUCKLE	
OCALA LF	7783881	7822888 8R02	1W1Z	5481202	AAD	Unknown	1 VERIFIED CONCERN, R/R PASSENGER SEAT REPLACED BUCKLE	
DAVID MC	210401	8548800 8R02	1W1Z	5481202	AAC	Unknown	NOT LATCHING; VERIFIED REPAIR, OK	
BOB MAX	8748101	8854000 8R02	1W1Z	5481202	AAD	Unknown	5481202 FAILED INSPECT REPLACE DRIVERS SEAT BELT	
							VERIFY. PINPOINT TEST; BUCKLE BROKEN. R/R SEAT TO ACCESS.	
SUPERIOR	8283101	8388800 8R02	1W1Z	5481202	AAD	Unknown	REPLACE BUCKLE, RETEST; O.K.	
CAPITAL	L072810A	7288100 8R02	1W1Z	5481202	AAD	Unknown	REPLACED RIGHT FRONT SEAT BELT BUCKLE.	
AVIS CAR	18782701	8R02	1W1Z	5481202	AAC	Unknown	LF SEAT BELT DOESNT LOCK RE RE BELT AND REPL BUCKLE	
FREEDOM	1818888	4341100 8R02	1W1Z	5481202	AAD	Unknown	1488 REPLACE RIGHT FRONT SEAT BELT, COMP	
SERMAIN	030437B	8878011 8R02	1W1Z	5481202	AAD	Unknown	REPLACE RF SEATBELT BUCKLE	
							84787 41 W VERIFIED CONCERN. INSPECTION FOUND RT FRNT	
							SEAT BELT BUCKLE INTERNALLY BINDING, REPL. AGED BUCKLE	
							AND RETST, OK	
JACK DEN	187845A	2748800 8R02	1W1Z	5481202	AAD	Unknown		
MERIDIAN	251351	8884403 8R02	1W1Z	5481202	AAD	Unknown	X	REPLACED LEFT FRONT SEAT BELT BUCKLE
BUDGET F	5888881	8R02	1W1Z	5481202	AAD	Unknown	BUCKLE WONT SNAP THE SEAT BELT. REPL NEW BUCKLE	
NORTHW	8488051	5384800 8R02	1W1Z	5481202	AAD	Both	TESTED AND REPLACED BOTH SEAT BELTS AND BUCKLES	
							VERIFY CONCERN REPLACED RIGHT FRONT SEATBELT WEAK AND	
							NOT HOLDING	
BAYWAY I	5202251	8288800 8R02	1W1Z	5481202	AAD	Pgr		
MANHATT	137088A	4847000 8R02	1W1Z	5481202	AAD	Drv	4830 REPLACED SEAT BUCKLES AS PER RECALL 01882	

CHEBROV 018535A	3887877 6R02	1W1Z	5481202	AAD	Both	REPLACED LEFT AND RIGHT SEAT BELT BUCKLES WERE INOP FOUND BUCKLE ON DRIVERS SIDE BROKEN. REPLACED DRIVERS SIDE SEAT BELT	
CHARLES 9545301	3489441 6R02	1W1Z	5481202	AAB	Drvr	REPLACE SEAT BELT BUCKLES	
REGENCY104820A	5801811 6R02	1W1Z	5481202	AAD	Unknown	APPROVAL R27PZ	
EAST WEI 34818101	4891780 6R02	1W1Z	5481202	AAD	Unknown	1298 61203, 41 MT81203 0-8 REPLACE RIGHT FRONT SEATBELT BUCKLE, BINDING	
TEXAN LP132816A	5804000 6R02	1W1Z	5481202	AAD	Unknown	REPLACE LEFT FRONT SEAT BELT BUCKLE DEACTIVATE BRB	
HARTER L 10187701	8813681 6R02	1W1Z	5481202	AAB	Unknown	REMOVE LEFT FRONT SEAT BELT BUCKLE REACTIVATE BRB	
OCALA LP 7783851	7322888 6R02	1W1Z	5481202	AAD	Unknown	REPLACE BELT	
POMODO 888704A	8358180 6R02	1W1Z	5481202	AAB	Unknown	14 RECALL 01821N REPLACED BOTH FRONT SEAT BELTS RECALL 01821 WITH SIDE AIR BAGS.	
HERTZ RA 37812801 *	6R02	1W1Z	5481202	AAE	Unknown	REPL BUCKLE ASSY	
FRIENDS# 0888988	4884012 6R02	1W1Z	5481202	AAB	Unknown	REPOSITIONED SEAT BELT LATCH DUE TO NOT POSITIO MED CORRECTLEY	
COUNTRY 077838D	2880586 6R02	1W1Z	5481202	AAC	Unknown	TEST DIAG AND REPL SEAT BELT BUCKLE ASSEMBLY INCL REMOVAL OF SEAT TRACE AND REPAIR HARNESS	
REEDMAN 34883701 *	6R02	1W1Z	5481202	AAD	Unknown	DIAGNOSE BOTH FRONT SEATBELTS WILL NOT LATCH PROPERLY, REMOVED AND REPLACED BOTH FRONT SEATBELT BUCKLES	
BUDGET F 47184001 *	6R02	1W1Z	5481202	AAE	Unknown	REPLACE BUCKLE	
DELAND F 038857A	7781000 6R02	1W1Z	5481202	AAB	Unknown	REPLACE DRIVERS SEAT BELT	
HERTZ RA 40188801 *	6R02	1W1Z	5481202	AAC	Unknown	REPLACED BELT BUCKLE	
HERTZ RA 58818101 *	6R02	1W1Z	5481202	AAE	Unknown	REPLACE DRIVERS SEAT BELT BUCKLE	
							DUE IN MIDDLE OF CAR UNDER FLOOR MAT NEAR FRONT SEATS RUN POINT P2 TO P5 REMOVE RIGHT FRONT SEAT REPLACE BUCKLE
MONT-RO 11370801	8889111 6R02	1W1Z	5481202	AAB	Unknown	DIAG AIR BAG SYSTEM B2438 PIN POINT P1 P2 TRY TO FIND P0M, SUPPOSE TOBE IN RIGHT KICK PAD CHECK ALL OVER NOT THERE, CHECK OTHER E.V.T.M THE SAMECHECK IN DASH AND AT LEFT	
HERTZ RA 36006401 *	6R02	1W1Z	5481202	AAB	Unknown	KICK PAD NOT THERE LOCATE MD REPLACED RF SEAT BELT BUCKLE	
TOTEM AL 104887A	3270431 6R02	1W1Z	5481202	AAB	Unknown	CHECK AND REPLACE SEAT BELT	
WALL'S U 178881A	8873100 6R02	1W1Z	5481202	AAA	Unknown	8842 REPLACED SEAT BELT.	
							RS CHECKED WIRING AT RCM WAS OK, HOT LINE SAID TO REPLACE PASS SIDE SEAT BELT BUCKLE WITH SWITCH AND TEST DRIVE 30 MILES HAD TO ACCESS CAPRET TO GET TO RCM NEED M TIME FOR SOME OF
OKC AUTL 578788A	4783000 6R02	1W1Z	5481202	AAD	Unknown	10888 42 HOOKED UP H88 AND GOT CODE B2438 PIN POINT TEST R1 TO R8 SAID TO REPLACE RCM, CHECKED HISTORY RCM HAD BEEN REPLACED, CALLED HOT LINE AND TALKED TO MIKE, SAID TO CHECK WIRING AND CONNECTIO	

OKO ALU1673243A	4758000	8F02	1W1Z	5481208	AA0	Unknown	7547 42 VERIFY CONCERN AIR BAG LIGHT COMES ON WHILE DRIVING, CHECK CODES B0438 (PASSENGER SAFETY BELT BUCKLE SHORT TO GROUND), PERFORMED PIN POINT TEST R1: CHECK FOR A HARD OR INTERMITTENT DTC (C00	R PRESENT IN ON DEMAND TEST), DEACTIVATE SYSTEM, ACCESS CARPET TO ACCESS ROM (RESTRAINT CONTROL MODULE), R2: CHECK FOR SHORT TO GROUND ON CIRCUIT 1514(OK NO SHORT TO GROUND), R3: CHECK
GRAY-DW 181387A	8282801	8F02	1W1Z	5481202	AAC	Unknown	8482 PERFORMED ELEC DIAG FOUND AIR BAG LIGHT BLINKS ON AND OFF TESTED RESTRAINT CONTROL MODULE HAVING CODE B2286 RCM HAVING INTERNAL SHORT REPLACED MODULE AND RETESTED NEW CODE WAS FOUND B0434	DR SEAT BELT BUCKLE HAVING INTERNAL SHORT REPLACED AND RETESTED FOUND NEW CODE B2286 PASS SEAT AIR BAG MODULE LOW RESISTANCE REPLACED MODULE AND RETESTED CLEARED CODES AND RETESTED
BUDGET F 1839801 *		8F02	1W7Z	5481202	AAB	Unknown	HOOK UP NGS, RUN SELF TEST, RUN DCL DISPLAY, RUN PINPOINT TEST ON PASSENGER SIDE SEAT BELT BUCKLE, FOUND BUCKLE BAD, R AND R PASSENGER SIDE SEAT, REPLACE BUCKLE, CLEAR CODES, RETEST.	
JAMES HC 277054A	8821345	8F02	1W1Z	5481202	AAB	Unknown	TECH INSTALLED DRIVERS FRONT SEATBELT BUCKLE DUE TO NOT LOCKING INTO PLACE PROPERLY	
BRONHT B 17813802	8888720	8F02	1W1Z	5481202	AAB	Unknown	REPLACED SEAT BELT BUCKLE	
HERTZ RJ 41812701 *		8F02	1W1Z	5481202	AAE	Unknown	1386 REPLACE DRIVERS SEAT BELT BUCKLE	
LYNNHAW13820808	3400800	8F02	1W1Z	5481202	AAD	Unknown	REPL R/F SEAT BELT BUCKLE	
HERTZ RJ 88438701 *		8F02	1W1Z	5481202	AAA	Unknown	TESTED BOTH FRONT SEAT BELT BUCKLES DRIVER SEAT FAILED	
CAL WOR 18882801	2786300	8F01	1C3Z	2881203	AAA	Dvr	REPLACED SEAT BELT RECEIVER	
ED KENLE 8768801	7784801	8F02	1LXZ	1881202	AAA	Pagr	R & R RIGHT SEAT BELT BUCKLE LOCKS UP, R & R LEFT FRONT SEAT RETRACTRO	
JIM FUGA 084833E	8287731	8F02	1L7Z	7881202	AAB	Pagr	10821 REPLACED PASS SIDE SEAT BELT BUCKLE RECEIVER NOTE VEHICLE HAS 40 20 40 SPLIT BENCH AND IS A CREWCAB	
DREW FO 888481	8847777	8F02	1L7Z	7881202	AAA	Pagr	INSPECT AND REPLCE BOTH FRONT SEAT BELT BUCKLES W O SIR BUCKETS	
DECKER F087787A	2818881	8F02	1L7Z	7881202	AA0	Pagr	REPLACED RIGHT FRONT BUCKLE	
RAY BKLL 272881	8812841	8F02	1C3Z	2881203	CAC	Dvr	MT; TIME TO PERFORM REPAIR ON SEATBELT BUCKLES ON BOTH FRONT SEATS.	
SUBURBA 41847708	3317800	8F02	1C3Z	2881203	CAA	Dvr	VERIFIED CONCERN REPLACED THE SEAT BELT LATCH	
LONG FOF 5401001	8284278	8F02	1C3Z	2881203	BAC	Dvr	REPLACED RIGHT FRONT	
ST. GEOR 30482501	8743800	8F02	1C3Z	2881203	CAC	Dvr	REPL. ON SIDE SEAT BELT LATCH ASSY	
CAPTAL F 3888081	7804800	8F02	1C3Z	2881203	BAA	Dvr	LATCH SEAT BELT ASSEMBLY REAR RIGHT OR LEFT	
TIFFANY B 3872802	8374481	8F02	1C3Z	2881203	BAA	Dvr	REPLACE	
DAVE BIN 28734801	8828800	8F02	1L7Z	7881202	AA0	Pagr	BELT NOT SECURED. REPLACED BELT ASSEMBLY	
							REPLACED RIGHT FRONT SEAT BELT BUCKLE	

HAGGIN-V 105735A	8857771	8R02	1C3Z	2581203	AAA	Drv	258 BCE TEST B1885 PPT REPLACE DRIVER SIDE PRETENSIONER CLEAR CODES RETEST OK SEAT BELT & CLOCK SPRING FAILED AIR BAG RESTRAINT SYSTEM DIAGNOSIS
AKINS FOI 1814051	8879135	8R02	1C3Z	2581203	AAA	Drv	
COLUMBA 1328651	4282200	8R02	1C3Z	2581203	AAA	Drv	
BURNHAM 1271101	2282547	8R02	1L3Z	1881202	AAA	Page	
PIONEER 25773108	8571833	8R02	1C3Z	2581203	AAA	Drv	DIAG AND REPLACED BELT ASSY REPLACED LT SEATBELT. CHECKED & VERIFIED SEAT BELT ON PASSENGER SIDE INOP REPLACED BUCKLE & RECHECKED & OK WONT STAY BUCKLED SEATBELT ASSEMBLY FRONT REPLACE
SHAMROK 3288050	8298211	8R02	1L3Z	1881202	AAA	Page	
SCOTT PE 3317551	8922844	8R02	1C3Z	2581203	BAA	Drv	NOTE NO RECALL BUT FAILED TEST PASS BUCKLE RPL PASS SIDE BELT BUCKLE NO RECALL OPERATION REG WARRANTY REPLACED LOWER DRIVER SEAT BELT REPLACED LEFT SEAT BELT REPLACED BUCKLE
CERNITO 25453401	8833354	8R02	1L7Z	7881202	AAA	Page	
WOODVIL 1880261	2838588	8R02	1C3Z	2581203	CAA	Drv	
DAVIDS FC 7850001	8282730	8R02	1C3Z	2581203	BAA	Drv	
WENDLE 1173288A	4844800	8R02	1C3Z	2581203	GAC	Drv	REPLACED BUCKLE VERIFIED CONCERN DIAG. FOUND DRIVER SEAT BUCKLE INOP. R/R DRIVER SEAT BELT BUCKLE. RETESTED OK. VERIFIED REPAIR. CCC \$40
BERGE FC 12484401	4871111	8R02	1C3Z	2581203	CAA	Drv	
STEAMBO 4848301	8791289	8R02	1L7Z	7881202	AAA	Page	INTERNAL DEFECTIVE REPLACED RT SEAT BELT BUCKLE VERIFIED CONCERN, REPLACED BOTH SEAT BELT BUCKLE ASSY RECHECKED ALL GOOD AT THIS TIME.
EDDIE YAI052848A	5922861	8R02	1C3Z	2581203	BAA	Drv	
HERITAGE #180051	8288110	8R02	1C3Z	2581203	BAA	Drv	INSTALL NEW SEAT BELT IMPROPER SEAT BELT BUCKLE FUNCTION REPLACED BUCKLE ASSY DRIVERSIDE
COUNTY 1 10457401	2588121	8R02	F81Z	2581203	CCD	Drv	TEST AND REPLACED DRIVESIDE BELT
P. M. STO 2888901	8282270	8R02	1C3Z	2581203	BAC	Drv	
SWANSON 187522A	2584121	8R02	1C3Z	2581203	BAA	Drv	REPLACE RIGHT AND LEFT SEAT BELT BUCKLES PERRECALL VEHICLE MISSING DRIVERS SIDE SEAT BELT LATCH. REPLACED LATCH
RAZZARI F 14735402	3833873	8R02	F81Z	2581203	CCD	Drv	REPLACE RIGHT FRONT SEAT BELT ASSY
STEAMBO 4848301	8791289	8R02	1L7Z	7881202	AAA	Page	
KINSEL FC 1198858	8388511	8R02	1C3Z	2581203	CAA	Drv	REPLACE LEFT FRT SEATBELT WONT LATCH
TEXSTAR 00018682	8887000	8R02	1C3Z	2581203	CAA	Drv	REPLACE L/R BELT
BROWNW 8348251	8431881	8R02	1C3Z	2581203	CAA	Drv	VCC REPLACED DRIVERS SEAT BELT BUCKLE. IN AND R SEAT FOR ACCESS 40 28 40 NO SIR
FORD COI 8488651	5883673	8R02	1L7Z	7881202	AAA	Page	BELTS FAILED INSPECT AND REPLACE BOTH FRONT SEAT BELT BUCKLES
WILLEY, P 8730408	2821813	8R02	1L7Z	7881202	AAE	Page	PASSENGER SIDE SEAT BELT BUCKLE WEAK, BINDS CHECKED SEAT BELTS, REPLACED PASSENGER SIDE SEAT BELT BUCKLE, RETESTED TO VERIFY, PASSED
FALLOTT/087880A	3458800	8R02	1C3Z	2581203	BAA	Drv	6 REMOVED SEAT FROM TRUCK CHANGED SEAT BELT THEN BOLTED SEAT BACK IN TRUCK
NEW FOA 0308048	8888041	8R02	1C3Z	2581203	CAA	Drv	2614 VERIFIED CONDITION FOUND BOTH FRONT SEATBELT WILL NOT HOLD THE SEAT BELT IN PLACE WITH MINIMAL FORCE
FALLOTT/088844A	3458800	8R02	1C3Z	2581203	BAC	Drv	APPLIED. REPLACED BOTH FRONT SEAT BELT BUCKLES. THIS VEHICLE DOES NOT SHOW TO HAVE THE RECAL
GALPIN R 8881551	7873800	8R02	1C3Z	2581203	BAA	Drv	REPLACE BOTH FRT SEAT BELTS REPLACE SEATBELT WILL NOT LATCH PROPERLY

L 01881 BUT HAS THE
SYMPTOMS. RECHECK
WHEN COMPLETE FIN.

BLUEBON 18887201	6088011	8F02	1C3Z	2581203	BAC	Drvr	INSTALLED NEW SEAT BELTS REMOVE FROM STOCK UNIT AND REPLACE ON CUSTOMER'S VEHICLE
BLUE SPRING 2284400	2284400	8F02	*	2581203	*	Drvr	VERIFIED CONCERN, REMOVED AND REPLACED SEAT BELT BUCKLE. REPLACED BUCKLES
PORT LAY 140182A	6521165	8F02	1C3Z	2581203	BAC	Drvr	
JIM CLICK 28879401	7472000	8F02	1L7Z	7881202	AAA	Page	
NICHOLS 20379601	5253873	8F02	1C3Z	2581203	GAA	Drvr	1 REPLACE BOTH FRONT SEAT BELTS.
WILSON-C 1505350	6432511	8F02	1C3Z	2581203	BAA	Drvr	INSTALL SOF SEAT BELT ASSEMBLY
JOE MAC 29887501	4434411	8F02	1C3Z	2581203	BAA	Drvr	1 REPLACE DRIVER SEAT BELT BUCKLE, NORMAL AFTER REPAIRS.
SHAMALE 31713001	5818820	8F02	1L3Z	1881202	AAA	Page	REPLACED PASS SIDE SEAT BELT BUCKLE WONT LATCH
RON-CAR 0195409	2518111	8F02	1L3Z	1881202	AAA	Page	FROM SERVICE MANUAL FOUND PASSENGER PRETENSIONER ASSEMBLY FAULTY, R&I RIGHT FRONT SEAT, RR PRETENSIONER ASSEMBLY CLEARED CODE FROM ECS, TESTED FOR PROPER OPERATION
ERLEN MC 6088281	7433421	8F01	1C3Z	2581203	AAA	Drvr	30540 PASSENGER PRETENSIONER ASSEMBLY VERIFIED CUSTOMER CONCERN, PERFORMED AIR BAG DIAGNOSTICS, HOOKED UP NBS TO PULL CODES FROM ECS, FOUND CODE 81888, PERFORMED PASSIVE RESTRAINT PINPOINT TEST H
STOTT'S F 478571	6688827	8F02	1C3Z	2581203	AAA	Drvr	CHECK & REPLACED SEAT BELT BUCKLE
RICHARD 2988201	2880008	8F02	1L7Z	7881202	AAB	Page	RECALL INSTALLED PASS. SIDE BELT AS PER RECALL 01821
COURTES 5883601	3288006	8F02	1L7Z	7881202	AAA	Page	FAILED BELT CHECK, REPLACE SEAT BELT 30089 REPLACE PASS SIDE SEAT BELT BUCKLE SEAT BELTS WILL COME UNLATCHED. REPLACED BOTH SEAT BELT BUCKLES.
TERRERO 283838A	5818833	8F02	1L7Z	7881202	AAA	Page	REPLACED PASS FRONT SEAT BELT BUCKLE, FOUND WHEN INSPECTING STOCK UNIT# FOR RECALL 01821, RECALL NOT OPEN ON THIS VEH
BARTOW 24838401	5330425	8F02	1C3Z	2581203	BAC	Drvr	REC TO REPLACE BOTH
TENNESSE 148318A	2823000	8F02	1L7Z	7881202	AAA	Page	
SWANSON 167240A	6884121	8F02	1C3Z	2581203	BAC	Drvr	
ADVANTA 2303201	3288888	8F02	1C3Z	2581203	BAC	Drvr	
FAULKNER 212229A	6388800	8F02	1C3Z	2581203	AAA	Drvr	REPLACE SEATBELT ASSY AS PER RECALL 01821 15 INSTALL BELT#1L7Z 7881202 AAB #1C3Z 2581203 CAC DUE TO SEAT BUCKLES FAILURE OF THE SEAT BELT TEST USING THE TESTER REPLACE THE BUCKLES THE VEHICLE IS OK
FAULKNER 214882A	5388800	8F02	1L7Z	7881202	AAB	Page	INSPECTED, REPLACED DRIVER'S SIDE SEAT BELT & BUCKLE, TEST & RETEST.
GEORGE 103038A	2234351	8F02	1C3Z	2581203	BAA	Drvr	CONFIRM & REPLACED RIGHT SEATBELT ASSEMBLY
PRINCE G 12305001	5838111	8F02	1L3Z	1881202	AAA	Page	SEATBELT BUCKLE'S FALL OFF SEATBELT ASSEMBLY FRONT REPLACE
WICHITA F 6818551	6321121	8F02	1L3Z	1881202	AAA	Page	VERIFIED, RR FRONT LR SEAT BELT BUCKLES, NOW OPS NORM
PINE PLAJ 3487221	3887733	8F02	1C3Z	2581203	AAA	Drvr	
COURTES 5883701	3288000	8F02	1C3Z	2581203	AAA	Drvr	REPLACE SEATBELT, FAILED CHECK DONE SAME AS FOR RECALL

HALL FOR 290607A	8686700 6R02	1C3Z	2881203	AAA	Drvr	TECH INSPECTED AND REPLACED DRIVER SIDE SEATBELT DUE TO DEFECT WAS INOPERATIVE
GAL WOR 15863601	2786360 6R01	1C3Z	2881203	AAA	Drvr	TESTED BOTH FRONT SEAT BELTS DRIVERS SEAT RECEIVER
GALPIN R 69408851	7873800 6R02	1C3Z	2881203	AAA	Drvr	FAILED RRW SEAT BELT RECEIVER REPLACE SEATBELT WILL NOT LATCH PROPERLY INSPECT AND REPLACED R BUCKLE FAILED. L BUCKLE OK PASSED.
RANCHO I 28188701	6991302 6R02	1L7Z	7881202	AAA	Page	
MILPETI 8687882	7886113 6R02	1L7Z	7881202	AAB	Page	X REPLACED BUCKLE ASY WOULD NOT LATCH INSPECT FRONT SEAT BELT BUCKLES HARD TO CLIP & HOLD REPLACE BOTH BUCKLES
CARSTAF 60225601	3373383 6R02	1C3Z	2881203	BAA	Drvr	FAILED BUCKLE ASBY PASS FRW REPLACED FAILED PASS FRW SEAT BELT BUCKLE ASSEMBLY, RETEST OK NOW
VICTORY I 5878601	8817035 6R02	1L7Z	7881202	AAA	Page	38883 REMOVE L F POWER SEAT TO GAIN ACCESS REPLACE B O BUCKLE AS NEEDED REINSTALL SEAT REPLACED SEAT BELT PER ED KARAZIN
ELK RIVER 062285A	4412900 6R02	P81Z	2881203	BBC	Drvr	
CROSSRC 89388001	4871881 6R02	1L7Z	7881202	AAB	Page	RF SEATBELT BUCKLE STUCK FOUND DEBRIS POSSIBLE BUR IN BUCKLE REMOVE RF SEAT TO GAIN ACCESS TO RF SEAT BELT BUCKLE REPLACE BUCKLE RETEST NORMAL LATCH OPERATION ON SEAT BELT RECALL 1.1 INSPECTED BOTH SEAT BELTS PASS FAILED. REPLACED PASS SEAT BELT. REMOVED PASSENGER SIDE SEAT AND REPLACED BUCKLE, RECHECK OPERATION HAD TO INSTALL SEAT BELT ASSEMBLY. MT TIME TO CHECK SEAT BELT OPERATION AND TO REPLACE BOTH BELTS DIAG. RRW RIGHT FRONT SEAT BELT TO REPAIR. CC118 REPLACE RIGHT SEAT BELT BUCKLE REPLAE LEFT AND RIGHT SEAT BELT BUCKLES STICKS BINDS OR GRASS TESTED SEAT BELT BUCKLE AND FOUND THAT PASSENGER SIDE IS BINDING INTERNALLY R AND R PASSENGER SIDE SEAT BELT. 1 REPLACED BOTH SEAT BELTS, WORKING GREAT TESTED THE SEAT BELTS, REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE SIDE.
NYE FROF 7481101	3785858 6R02	1L7Z	7881202	AAB	Page	
HEINTZEL 165800A	2881000 6R02	1L7Z	7881202	AAA	Page	
MAGUIRE 080844A	8343111 6R02	1L7Z	7881202	AAA	Page	
GRIFFITH 041181A	8982284 6R02	1C3Z	2881203	CAA	Drvr	
VAN CLEV 1834101	4885888 6R02	1L7Z	7881202	AAB	Page	
GALPIN R 5254521	7873800 6R02	1L7Z	7881202	BAC	Page	
BWANSOP 167828A	8984121 6R02	1C3Z	2881203	BAA	Drvr	
HOLMES T 41488501	2822800 6R02	1L7Z	7881202	AAA	Page	
COURTES 43371801	7844843 6R02	1C3Z	2881203	BAC	Drvr	
BARTON 28888101	6230485 6R02	1C3Z	2881203	CAC	Drvr	
CAPITAL F 1803751	7804800 6R02	1L7Z	7881202	AAB	Page	INOP REPLACE BELT PASS SIDE SEAT BELT DOESNT HOLD
TENNESSE 148328A	2822800 6R02	1C3Z	2881203	AAA	Drvr	REPLACED LEFT FRONT SEAT BELT BUCKLE
JIM CLUCK 23259001	7478000 6R02	1L8Z	1881202	AAA	Page	RECALL 01821 REPLACE L AND R BUCKLES AS PER RECALL BAD BUCKLE TENSIONER MT TO R R DRIVERS SEAT BELT BUCKLE
KEN BROE 8284851	8218881 6R02	1C3Z	2881203	AAA	Drvr	

CURRY FC 24621 BA	7281300	8R02	1C3Z	2881208	AAA	Drvr
MAGUIRE 088277A	8888300	8R02	1L3Z	1881202	AAA	Pagr
PETERSO 888382	8488288	8R02	1C3Z	2881203	AAA	Drvr
NASSIF I 2883301	8781010	8R02	1C3Z	2881203	AAA	Drvr
PETERSO 884882	8482288	8R02	1C3Z	2881203	AAA	Drvr
PETERSO 884883	8482288	8R02	1C3Z	2881203	AAA	Drvr
WEST BEI 2810801	8874181	8R02	*	2881208	*	Drvr
CONDIT F-134470A	2822800	8R02	1L3Z	1881202	AAA	Pagr
LARRY GE 808401	8212121	8R02	1C3Z	2881203	AAA	Drvr
COURTES 4308801	7944343	8R02	1C3Z	8881208	AAA	Drvr
WENDLE I 178885A	4844800	8R02	1C3Z	2881208	AAA	Drvr
PRISTINE 028885A	8676622	8R02	1L7Z	7881202	AAB	Pagr
SANFORD 884488A	7782221	8R02	1C3Z	2881203	AAA	Drvr
SANFORD 888888A	7782221	8R02	1C3Z	2881203	AAA	Drvr
JERRY FC 3488882	7284441	8R02	1C3Z	2881203	AAA	Drvr
BOB LIER 1001002	7642728	8R02	1C3Z	2881203	AAA	Drvr
CAPITAL F 2881481	7804800	8R02	1C3Z	2881203	AAA	Drvr
CROGARC 22278301	4871881	8R02	1L3Z	1881202	AAA	Pagr
ELDON FC 5488301	3823145	8R02	1C3Z	2881203	AAA	Drvr
THE A. Q. 108401	8788221	8R02	1L3Z	1881202	AAA	Pagr
METRO FI 18778801	2884630	8R02	1L3Z	1881202	AAA	Pagr
MCKE FC 2888203	3481400	8R02	1L3Z	1881202	AAA	Pagr
FALLOTT/088841A	3488800	8R02	1L3Z	1881202	AAA	Pagr
PARIS FCI 8884401	7842588	8R02	1L3Z	1881202	AAA	Pagr
NICHOLS 80427301	5888873	8R02	1C3Z	2881203	AAA	Drvr
WICHITA I 8841781	8821121	8R02	1L3Z	1881202	AAA	Pagr
WICHITA I 8814851	8821121	8R02	1L3Z	1881202	AAA	Pagr
PARIS FCI 8881501	7842588	8R02	1L3Z	1881202	AAA	Pagr
TREADWE 27744801	4788381	8R02	1C3Z	2881203	AAA	Drvr

13028 HARNESS OPEN AND BELT NOT HOLDING CHECKED AND FOUND SEAT BELT WOULD NOT HOLD IN THE BUCKLE R-R BUCKLE ASSEMBLY AND LIGHT STILL STAYED ON AND CHIMING CHECKED OEM MODULE AND IT PASSED CHECKED W INSPECTED AND REPLACED BOTH BUCKLES
 REPLACED THE LEFT SEATBELT BUCKLE THAT DOES NOT HOLD
 REPLACE SEATBELT
 REPLACED THE LEFT SIDE SEATBELT BUCKLE
 REPLACED THE SEATBELT BUCKLES THAT DID NOT HOLD.
 TEST BUCKLE REMOVE AND REPAIR INSTALL.
 REPLACE SEAT BELT
 DIAG INSP VERIFIED CONCERN MT TIME TO REPLACE SEAT BELT BUCKLE
 1 REPLACED SEAT BELT
 REPLACED BOTH SEAT BELTS
 TEST AND REPLACE BOTH SEAT BELT ASSEMBLIES
 REPLACE SEAT BELT BUCKLE, LEFT FRONT
 REPLACE SEAT BELT BUCKLE ASSY
 TEST THE AIR BAG SYSTEM FOUND AND REPLACED THE FAULTY DRIVERS SEAT BELT BUCKLE ASSEMBLY.
 REPL SEAT BELT ASSY

BELT INOP SEATBELT DOESNT HOLD
 REPLACED RIGHT SIDE SEAT BELT
 CCC S38 TESTED SYSTEM RAN PIN POINT TEST CC 42 REPLACED DRIVER SEAT BELT
 REPLACED THE FAULTY SEAT BELT.
 SEATBELTS CHECKED UNDER 01821 IN ERROR BUT FOUND THAT P/B SEATBELT FAILED. REPLACED BELT

PULLED WIRE AND BUCKLE INSTALLED NEW AND REASSEMBLED CHECK OK
 PERFORMED RECALL FOR SEATBELTS
 OBSERVE SEAT BELT INOP WILL NOT LATCH REPLACE SEAT BELT BUCKLE
 REPLACE LT SEAT BELT.
 AIRBAG LIGHT IS ON AIR BAG RESTRAINT SYSTEM
 DIAGNOSIS
 AIRBAG LIGHT FLASHES AIR BAG RESTRAINT SYSTEM
 DIAGNOSIS

REPLACE PASS SEAT BELT BUCKLE WONT NOT STAY LATCH
 R R DRIVERS FRT SEAT BUCKLE INSTALL DRIVERS SEAT BELT BUCKLE MISSING WHEN DEALER TRANSFER HAS TENSIONER

IRING FROM SEAT BELT TO GEM AND FOUND OPEN IN BR BL WIRE REMOVED L H SEAT AND FUSE BOX ALONG WITH TRIM PANELS ON L H SIDE AND FOUND WIRE OPEN IN THE KICK PANEL RAN NEW WIRE FROM GEM TO SEAT

MIKE BRD	1285702	8731111	6R02	*	2881203	*	Dvr
BURT'S AJ	3833085	8438000	6R02	F81Z	2881203	JUJ	Dvr
BOBCH FR	24310201	8583181	6R02	1L7Z	7881202	AAA	Pgr
RAY SKILL	2720651	8812541	6R02	1L7Z	7881202	AAA	Pgr
JENNINGS	3137161	3482636	6R02	1L7Z	7881202	AAA	Pgr
LARRY GE	683701	8212121	6R02	1L7Z	7881202	AAB	Pgr
TRANUM I	2889703	4487377	6R02	F81Z	2881203	B8D	Dvr
HERITAGE	8181051	6285110	6R02	1C3Z	2881203	CAC	Dvr
AKINS FOR	8884031	8879188	6R02	1L7Z	7881202	AAA	Pgr
ELK GROV	20196701	8867000	6R02	1C3Z	2881203	BAA	Dvr
R. M. STO	2548801	2822270	6R02	1L7Z	7881202	AAA	Pgr
PIONEER	23003201	2871933	6R01	*	2881203	*	Dvr
HELFMAN	6128831	2403673	6R02	1C3Z	2881203	CAA	Dvr
BROWN MC	3686801	7372643	6R02	1L7Z	7881202	AAB	Pgr
R. M. STO	2587301	2822270	6R02	1C3Z	2881203	BAC	Dvr
BEAUDRY	3612151	860873	6R02	1C3Z	2881203	CAC	Dvr
GNONITA	5788831	7538288	6R02	1C3Z	2881203	BAC	Dvr
MCCAFFE	080780A	7884783	6R02	1L7Z	7881202	AAA	Pgr
TOM JONE	3788401	3884488	6R02	1L7Z	7881202	AAA	Pgr
FORD APF	1288801	3883413	6R02	1C3Z	2881203	BAB	Dvr
SARABOT	1888801	3888873	6R02	F81Z	2881203	CCD	Dvr
SAYVILLE	41327301	8884800	6R02	1L7Z	7881202	AAA	Pgr
MOPAC A	14884201	2452873	6R02	1C3Z	2881203	BAA	Dvr
BOBCH FR	24887501	8583181	6R02	1L7Z	7881202	AAA	Pgr
HERITAGE	8181781	8285110	6R02	1L7Z	7881202	AAB	Pgr
HENSON I	12310304	3488810	6R02	1L7Z	7881202	AAB	Pgr
BAYWAY I	6488831	8286500	6R02	1C3Z	2881203	CAC	Dvr
HUNTINGI	080888A	9888882	6R02	1C3Z	2881203	BAC	Dvr
R. M. STO	2888801	3822270	6R02	1L7Z	7881202	AAA	Pgr
ADVANTA	3388701	3588889	6R02	1C3Z	2881203	CAA	Dvr

CKED OUT TWIST LEFT SEAT BELT BUCKLE ON STRAP TO
OPERATE PROPERLY IMPROPERLY INSTALLED
REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY
REPLACED SEIZED SEAT BELT BUCKLES

MT; TIME TO REPAIR SEAT BELT BUCKLES.
SEAT BELT BUCKLE BINDING REPLACED BUCKLE
DIAG INSP VERIFIED CONCERN AND REPLACED PASS SIDE SEAT
BELT INOP
FOUND PASSENGER SEAT BELT BUCKLE WOULD NOT LATCH
PERFORMED RECALL 01821 ON DATE 7 28 01 CHECK SEAT BELTS
AND THEY PASSED REPLACED SEAT BELT BUCKLE

SEAT BELT RECALL FOR LEFT BUCKLE
SEAT BELT BUCKLE FAILED SEATBELT ASSEMBLY FRONT
REPLACE
REPLACED AS PER FORD
TEST NISS TO REPLACE SEAT BELT
FRONT LEFT SEAT BELT BUCKLE FROM STOCK 11888
NEG TO REPLACE FRONT SEAT BELT BUCKLES NOT WORKING ALL
THE TIME
REPLACED RT FRONT SEAT BELT BUCKLE 4827
INSPECT AND REPLACED WITH NEW
REPL SEATBELT ASSY SEATBELT ASSEMBLY FRONT
REPLACE

BINDING SEATBELT ASSEMBLY FRONT REPLACE
INSPECT AND REPLACED STICKING SEAT BELT

DIAG REPLACED BUCKLE DE CEINTURE AVANT LH BRISSE

DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT
REPLACE

VERIFIED CONCERN FOUND AND TRACED BUCKLE ASSY FAULTY
REMOVED AND REPLACED BUCKLE ASSY RETESTED ALL OK
LEFT SEAT BELT BUCKLE SEIZED, REPLACE LEFT SEAT BELT
BUCKLE.
REPLACED SEIZED SEATBELT BUCKLE

REPLACED RIGHT SEAT BELT BUCKLE PER RECALL.
CHECKED SEAT BELT FUNCTION NECESSARY TO REPLACE
DRIVERSIDE SEATBELT BUCKLE
LEFT FRONT SEATBELT BUCKLE NOT FUNCTIONING PROPERLY, R
AND R BUCKLE
REPLACED SEATBELTS
CHECK AND REPLACED WITH NEW ONE RETEST

REPLACED LEFT AND RIGHT SEAT BELT BUCKLE PER 01821.

FAIRWAY	7482161	8841200 0R02	1C3Z	2581203	GAC	Drv	BUCKLE NOT HOLDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
BULLO FC	387414A	7887781 0R02	1C3Z	2581203	BAC	Drv	8418 SEAT BELT BUCKLE INOP MTR1208 1.0 TEST AND DIAG SEAT BELT BUCKLE. ACCESS LEFT FRONT SEAT AND REPLACE SEAT BELT BUCKLE. INOP. RETEST. CODE 4R CAUSAL PART 61203 NEG TO REPL DRIVERS FRNT SEAT BELT ASY PASS SEAT BELT BUCKLE UNBUCKLES INSPECT & REPLACE PASS SEATBELT BUCKLE
RUSTON F	8780601	8582680 0R02	1C3Z	2581203	BAC	Drv	
GAUDIN F	8384361	7312121 0R02	1L7Z	7881202	AAA	Page	FOUND INTERNAL FAILURE OF RT SEAT BELT BUCKLE 40 20 40 FT SEAT ASBY REMOVED AND REPLACED RT FT SEAT BELT BUCKLE NEG TO REPLACE SEAT BELT DIAG AND RR SEAT BELT CHECK BELT OPERATION WILL NOT LATCH REMOVE DRIVERS SEAT INSTALL NEW BUCKLE AND REINSTALL SEAT RETEST OK
RUSSELL	8881361	8884111 0R02	1L7Z	7881202	AAB	Page	REPLACED SEATBELT BUCKLE FAILED SEATBELT ASSEMBLY DRIVERS FRONT REPLACE REPLACE SEAT BELTS DO NOT LATCH
GREENE F	188130A	9328820 0R02	1C3Z	2581203	CAC	Drv	
GREENE F	183848Z	8328820 0R02	1L7Z	7881202	AAB	Page	
PLANET F	16838201	7183780 0R02	1C3Z	2581203	BAC	Drv	
RED SMOOR	4785A	3838100 0R02	1C3Z	2581203	BAC	Drv	
AKINS FO	8856865	8878135 0R02	1C3Z	2581203	BAA	Drv	
WHITESH	2884701	8843884 0R02	1C3Z	2581203	BAC	Drv	
FREEDOM	8838888	8388282 0R02	F81Z	2581203	BBC	Drv	REPLACED SEAT BELT WPI R&L LF SEAT & TRACK ASBY REPLACE ROEVER 12 REPLACED SEAT BELT REPLACED FAULTY RT SIDE SEATBELT (REGULAR CAB) REPLACE SEAT BELT FOUND BUCKLE STICKS SOME PREPALS AND RETESTED REPLACE LEFT FRONT SEAT BELT BUCKLE REPLACED SEAT BELT REPLACED SEAT BELT INSPECTED AND REPLACED DRIVERS BIDE SEAT BELT BUCKLE RETESTED OK MIT NO LABOUR OPERATIONS CODE IN SLTS FOR REPAIRS DASH TRIM AND WEATHERSTRIP TO GET TO RETRACTOR REMOVED AND REROUTED BELT BACK IN AND CUT TO MAKE SURE IT WORKED. REMOVED PANELS JAMMED BAD UNSTUCK AND RECHECK OK.
PRAIRIE F	88501	8818200 0R02	1C3Z	2581203	BAA	Drv	
WICKSTP	048517A	8818850 0R02	1L7Z	7881202	AAB	Page	
HAROLD	2883888A	8878431 0R02	1L7Z	7881202	AAB	Page	
WILLIAMS	282848A	2888411 0R02	1C3Z	2581203	BAC	Drv	
GALPIN FC	3888801	4483875 0R02	F81Z	2581203	JJJ	Drv	
CLARKE M	188738A	4781180 0R02	1C3Z	2581203	BAC	Drv	
MT ORAB	43181	7214484 0R02	1C3Z	2581203	AAA	Drv	
PHIL LOM	31888301	8383873 0R02	1L7Z	7881202	AAB	Page	
WINDBOR	3188801	8383820 0R02	1C3Z	2581203	BAC	Drv	
DONLEY F	1883401	4884382 0R02	*	7881203	*	Drv	
INTEGRIT	3484841	3882855 0R02	*	1881203	*	Drv	
BLUE STA	28817701	4883873 0R02	*	1881202	*	Page	REPAIR WHITE WIRE AT PASS BELT CONNECTOR
LAKE CITY	1485881	3743843 0R02	*	1881202	*	Page	FCM BODY CHASSIS ELECTRICAL (BCE) TEST DIAGNOSED AND REMOVED RIGHT FRONT SEAT BELT COVER AND UNTWISTED SEAT BELT. RETESTED AND VERIFIED SEAT BELT NOW RETRACTING. REPAIRED AND REPLACED SCREW. TRIM PIECE THAT IS AROUND BELT ON PASS SIDE IS NOT ON DRIVERS SIDE THAT IS NORMAL CHECKED OTHER VEHICLES
KEN DIEPI	047011A	3483829 0R02	*	1881202	*	Page	
PHILAN L	2885702	8588862 0R02	*	7881281B	*	Page	
HAAG FO	8121202	8218248 0R02	*	1881203	*	Drv	
VALLEY R	13384801	7783881 0R02	*	7881203	*	Drv	

MOSS BR	1707140	0251212	0R02	1L3Z	10012019	AAF	Drvr	REMOVE SEAT BELTS FROM THIS STOCK UNIT TO USE TO REPAIR A CUSTOMERS VEHICLE AND REINSTALL BACK IN THIS UNIT FOUND SEATBELT TWISTED FROM FACTORY REINSTALLED CORRECTLY
WENDEL J	201701	2000501	0R02	"	1001202	"	Pagr	3570 REPLACE RT SIDE SEAT BELT ANCHOR BOLT BEZEL WAS MISSING
TOMBALL	237403C	3015427	0R02	"	1001202	"	Pagr	
MALL OF	1000177B	0004000	0R02	"	1001202	"	Drvr	7100 S3 SECURED SEAT BELT TO FLOOR MOUNT
BILLINGS	172740A	2000000	0R02	"	1001203	"	Drvr	DIAG AND REPOSITION SEAT BELT BUCKLE LATCH
LAKELANI	7201002	0021102	0R02	P05Z	1001001	DDO	Drvr	BELT TWISTED R/R BUCKLE
HOMETON	670771	5400010	0R02	"	70012018	"	Pagr	
JACKY W	0000001	0002100	0R02	"	1001202	"	Drvr	USED STOCK UNIT PART DUE TO HANDICAP CUSTOMER REPLACED SEATBELT BACK AS PER LAST ROADTEST WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT.
THOMPSC	11747001	7000000	0R02	1L7Z	7001002	BAD	Pagr	
NEDFEAR	4000701	4000124	0R02	P05Z	7001003	BBD	Drvr	WIRE PINCHED & BROKEN REPL DR SIDE SEAT BELT BUCKLE
MOHAWK	17140701	0001711	0R02	1L3Z	1001202	AAB	Drvr	INSTALL SPO BELT BUCKLE DRIVERS SIDE NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT
RICK HUN	0070001	3471204	0R02	1L7Z	7001202	BAB	Pagr	REPLACED RIGHT USED M TIME TO REPLACE RH FNT BUCKLE. RETEST OK AFTER REPAIR
DON SANI	0000002	0420000	0R02	1L7Z	7001202	BAD	Pagr	STICKING SEAT BELT BUCKLE REPLACE
GARY SM	120201	2444111	0R02	1L7Z	7001202	BAB	Pagr	CUSTOMER STATES THE RIGHT FRONT SEAT BELT WONT HOLD OR LOCK SEE JO...CORRE:REPLACED RIGHT FRONT SEAT BELT BUCKLE A ON 05 01 02
LLOYD F	1070001	0277000	0R02	1L7Z	7001202	BAC	Pagr	SEAT BELT BUCKLE RETENTION REPLACE ONE SEAT BELT BUCKLE
JEROL HC	0172702	4707111	0R02	1L7Z	7001202	BAB	Pagr	
RICK RIDI	0000001	7002001	0R02	1L7Z	7001202	BAB	Pagr	REPLACE SEAT BELT ASSY
RODEO R	007421B	0000777	0R02	1L7Z	7001203	CAA	Drvr	0000 REPLACED SEAT BELT BUCKLE DRIVERS FRONT. ALL GOOD. 7001200
LAMB FOF	0077701	0700411	0R02	1L7Z	7001203	CAB	Drvr	REPLACE THE DRIVERS SIDE SEATBELT BUCKLE
CROWFO	000000A	2001115	0R02	1L7Z	7001203	CAA	Drvr	0000 REPLACED DRIVERS SEAT BELT BUCKLE QUALITY CHECKED
BUDGET F	0077171		0R02	1L7Z	7001203	CAA	Drvr	RETESTED FOUND L FRT SEAT BELT PRETENSIONER REPLACED BUCKLE
BUDGET F	0100001		0R02	1L7Z	7001203	CAA	Drvr	VEHICLE IN FRONT LH SEAT BELT IS INOP, FOUND FAULTY BUCKLE ASSY DUE TO INTERNAL MALF, REPLACED
BUDGET F	04100001		0R02	1L7Z	7001203	CAA	Drvr	RECEIVER JAMMED REPLACED BUCKLE
DON DAVI	417004B	0014001	0R02	1L3Z	1001203	AAB	Drvr	1010 SHORTED CHECK WITH MIKE Z FOR M TIME TEST SYSTEM R/R GEM TO TEST WIRES R/R SEATS R/R CARPET TO ACCESS WIRES FOUND SHORT WHERE CUSTOMER HAD A SPEAKER BOX WIRED IN DIRECT TO THE SEAT BELT HARNESS
MOOLINE	4202001	0000000	0R02	1L3Z	1001203	BAB	Drvr	DONE DIAG FOUND SEAT BELT WONT LATCH REPLACED BUCKLE FIXED PROBLEM

S WIRES DISCONNECTED
WIRES REINSULATED
WIRES, RETEST SYSTEM.
*** QUALITY CONTROL BY
TIM HUDSON ***

CARLEMAN	5489601	8853101	6R02	1L3Z	1581208	AAB	Drvr	REPLACED DRIVERS SEAT BELT ASSEMBLY, 3387 SEAT BELT CHIME STAYS ON 12881.D 2 D2 .3 IX1 .1 61203 M TIME .5 1.1 HRS NGS BODY & ELECTRICAL. DIAGNOSIS REPLACE LT SEAT BELT BUCKLE & RETEST CODE 42 CP 61203 SWITCH IN BUCKLE NOT WORKING PROPER	LY
GULLO FC	382771A	7857781	6R02	1L3Z	1681208	BAB	Drvr	REPLACED THE SEAT BELT	
ADVANTA	5412303	3348761	6R02	1L3Z	1681208	AAC	Drvr		
TOWNSE	1641588	7620401	6R02	1L3Z	1581208	AAC	Drvr	IN TIME TO REPLACE DRIVER SEATBELT BUCKLE NO OPP#	
FAIRWAY	8442201	5753000	6R02	1L3Z	1681208	AAC	Drvr	REPLACED THE SEAT BELT BUCKLE ASSY. 1672 41 WARR 7866 L SEAT BELT WONT STAY FASTENED BUCKLE RELEASE BINDING REPLACE L BUCKLE & TEST	
WAYNE A	1221311B	5824444	6R02	1L3Z	1581208	AAC	Drvr	6513 W 5121 REPLACE DRIVERS SEAT BELT CLASP OK	
WAYNE A	1233341A	6824444	6R02	1L3Z	1681208	AAC	Drvr	CHECK AND REPLACE BELT STICKING	
SOUTH-CA	2786788	3778100	6R02	1L3Z	1681208	BAC	Drvr	INSTALLED NEW SEAT BELT BUCKLE AND RE TEST. OK. AE	
AUTOWA\	11788801	3283400	6R02	1L3Z	1681208	AAB	Drvr	11406 INSTALL DRIVER SEAT BELT BUCKLE RETEST VERIFY REPAIR	
BRYAN E	148111A	8824281	6R02	1L3Z	1581208	AAB	Drvr	REPL SEAT BELT BUCKLE	
BLUESON	31088804	8088011	6R02	1L3Z	1681208	AAC	Drvr	CHECKED SEATBELT RMR RT SEAT AND REPLACED SEATBELT BUCKLE	
BARKHOL	1800058	7931112	6R02	1L3Z	1681202	AAD	Page		
COVERT F	889102	3858000	6R02	1L3Z	1581208	AAC	Drvr	REPLACED THE L F SEAT BELT BUCKLE	
A C COLL	285382	8043878	6R02	1L3Z	1581208	BAC	Drvr	CAME APART SEATBELT ASSEMBLY FRONT REPLACE IN TIME TO REPLACE DRIVERS SEAT BELT BUCKLE DUE TO NOT LATCHING AT TIMES. 1	
DON RANI	88018502	8438900	6R02	1L3Z	1681208	AAC	Drvr	1 REPLACE SEATBELT BUCKLE	
JOHN KER	13808001	4887172	6R02	1L3Z	1681208	AAB	Drvr	TEST AND REPLACE DRIVERS SEAT BELT BUCKLE, BROKEN	
NORTHER	34887801	8288900	6R02	1L3Z	1681208	AAC	Drvr	REPLACE DRIVER SIDE SEAT BELT BUCKLE	
KNOX PO	7481101	8422383	6R02	1L3Z	1681208	AAC	Drvr	REMOVED AND INSPECT DRIVERS SEAT AND BUCKLE INSTALLED NEW BUCKLE NON SIR	
SHAMALE	32185701	5818800	6R02	1L3Z	1581208	AAC	Drvr	REPL LEFT SEAT BELT	
GRANT C	4833301	8438188	6R02	1L3Z	1681208	AAC	Drvr		
CHAMPLO	2778151	6841441	6R02	1L3Z	1581208	AAC	Drvr	DIAG SEATBELT REPLACE RECEIVER	
GRASS W	277380A	3733386	6R02	1L3Z	1681208	AAC	Drvr	SEAT BELT BUCKLE RELEASES ON ITS OWN AT TIMES THE L F SEATBELT BUCKLE WOULD COME LOOSE REPLACE THE BUCKLE TO CORRECT	
TEXAN FC	22388801	4673873	6R02	1L3Z	1681208	AAC	Drvr	CHECK OUT AND REPLACE LEFT FRONT RIGHT SIDE SEAT BELT WOULD NOT LATCH	
B & B FOR	4478201	4674682	6R02	1L3Z	1681208	AAB	Drvr	REPLACED LEFT FRONT SEAT BELT BUCKLE ASSEMBLY.	
WESTWA	88901201	8890333	6R02	1L3Z	1681208	AAC	Drvr	REPLACED DRIVERS SEAT BELT	
FLANDER	3884201	4483383	6R02	1L3Z	1681208	AAB	Drvr		
MIKE CAS	14088401	8317010	6R02	1L7Z	7881202	BAB	Page	REPLACE PASSENGER SIDE FRONT SEATBELT R/R BELT ASSY TESTED	
BUDGET F	80027001		6R02	1L3Z	16812016	AAA	Page	1841 REMOVED PASSENGER SEAT AND INSTALLED MISSING SEAT BELT. REINSTALLED SEAT AND TESTED ALL OK. CMD TECH 64	
REYNOLD	081382A	7882411	6R02	F85Z	7881802	B8E	Page		

O'NEARA 080443D	4511931 6R02	1L7Z	7861203	CAB	Dvr
EIDE FOR 844904A	2223600 6R02	1L7Z	7861203	GAG	Dvr
JACK DEL 284201A	7212800 6R02	1L7Z	7861203	GAG	Dvr
METROPC 4894302	9439000 6R02	1L7Z	7861203	CAB	Dvr
REYNOLD 008108A	3212411 6R02	1L7Z	7861203	CAB	Dvr
TOM JONE 4102801	3884428 6R02	1L7Z	7861203	GAA	Dvr
PAYTON V 6286401	6481111 6R02	1L7Z	7861203	DAB	Dvr
TEAM FOF 6878781	4221100 6R02	1L7Z	7861203	GAA	Dvr
TEAM FOF 6828652	4221100 6R02	1L7Z	7861203	GAA	Dvr
ROBIN FO 6818801	6852800 6R02	1L7Z	7861203	GAC	Dvr
ALTONWA 7838881	7473711 6R02	1L7Z	7861203	CAB	Dvr
BILL GRAP 881201	2287871 6R02	1L7Z	7861203	CAB	Dvr
ERENKSEI 243052	4552751 6R02	1L7Z	7861203	CAB	Dvr
VERMILLK 3255141	6248821 6R02	1L7Z	7861203	CAB	Dvr
BILL MACI 5213201	3388801 6R02	1L7Z	7861203	GAA	Dvr
WAY AREA 3881251	4888800 6R02	1L7Z	7861203	GAA	Dvr
AKINS FO 888055	8578138 6R02	1L7Z	7861203	GAA	Dvr
DON KOT 4188053	8182500 6R02	1L7Z	7861203	GAC	Dvr
LARRY MC 2882201	8350798 6R02	1L7Z	7861203	CAB	Dvr
EARNHAR 877312A	6880000 6R02	1L7Z	7861203	GAA	Dvr
HUB CITY 6821351	2334500 6R02	1L7Z	7861203	CAB	Dvr
PADRE FC 2833738	9948200 6R02	1L7Z	7861203	GAA	Dvr
GARBER I 083818A	2843882 6R02	1L7Z	7861203	GAA	Dvr
SANTOS F 4718801	6284821 6R02	1L7Z	7861203	CAB	Dvr
TED RUS 32010401	6887811 6R02	1L7Z	7861203	GAA	Dvr
TRANUM I 3087701	4487377 6R02	1L7Z	7861203	CAB	Dvr

0886 4488 P1 01172A .3 12881D .2 CK1 .1 D2 .3 GEM SYSTEM TESTS,
KOED B1428, B1480, KOED B1428 DOL DISPLAY, RECORD &
MONITOR PIDS, PERFORM PINPOINT TESTS & ACTIVE COMMAND
TESTS, REPLACED DRIVERS SID

E BUCKLE ASSY.

M TIME TO REPLACE BUCKLE ASSY
2 INSTALLED SEAT BELT WILL NOT STAY BUCKLED

CC01 REPLACE SEAT BELT BUCKLE WAS BROKEN WORKS OK
8728 REPLACED DRIVERS SEATBELT PER FSA LABON OP 00881B
0.8 HRS

CCN 840 CC 42 BPN07861203 DIAG REPLACED SEATBELT BUCKLE
ASSL
SEAT BELT WILL NOT FASTEN, REPLACE DRIVERS SEAT BELT
BUCKLE
NECC TO REPLACED DRIVER SEAT BELT BUCKLE DUE TO IT
BROKE.

REPLACED BUCKLE ASSEMBLY
BINDING REPLACE SEAT BELT
REMOVE SEAT AND REPLACE BUCKLE, REINSTALL SEAT AND
RETEST, OK

RUN CHECK ON WOB, GOT CODE ON SEATBELT SHORT. ROR
SEATBELT BUCKLE
REPLACE SEAT BELT BUCKLE.
REPLACE LF SEAT BELT BUCKLE

INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT
REPLACE
SEAT BELT BUCKLE FAILED SEATBELT ASSEMBLY DRIVERS
FRONT REPLACE

SEAT BELT BUCKLE INOP REPLACE DRIVERS SIDE BUCKLE

6 VERIFIED CONCERN, BCE TEST, BCE PIN POINT TEST SHOWED
FAULTY SEAT BELT RECEIVER, REPLACED RECEIVER (40 80) BCE
RETEST, ALL FUNCTIONS NORMAL
DOES NOT OPEATE PROPERLY SEATBELT ASSEMBLY FRONT
REPLACE

6371 VERIFY CONCERN HAD TO REPLACE REMOVE SEAT TO
REPLACE SEAT BELT BUCKLE, FOUND SEAT BUCKLE NOT
WORKING SEAT BELT IS WORKING NORMAL.
SEATBELT BUCKLE INOP, WILL NOT LATCH, REPLACE WITH NEW,
RECHECK OK
CONFIRM DRIVERS SEATBELT DOESNT STAY LATCHED REPLACE
DEFECTIVE LATCH M781203 NO SLT8

REPLACE BUCKLE
FOUND DRIVERS SIDE SEAT BUCKLE WOULD NO LATCH REPLACE
SEAT BELT BUCKLE LATCHES OK

CLEVENO	7813061	7848000	6R02	1L7Z	7881203	GAB	Drvr	VERIFIED SEAT BELT WARNING LIGHT & CHIME STAYS ON WITH SEAT BELTS BUCKLED. REMOVED DRIVERS SEAT TO INSPECT WIRING, OK. DISCONNECTED SEAT BELT SENSOR TO TEST. FOUND SENSOR HAS CLOSED SHORT CIRCUIT CAUSING 7788 (CODE 48) REMOVED D SIDE FRONT SEAT TO ACCESS. REMOVED AND REPLACED D SIDE FRONT SEATBELT RETRACTOR AND REASSEMBLED. RETESTED OK.	NG LIGHT TO STAY ON. REPLACED SEAT BELT BUCKLE & RETESTED, REINSTALLED DRIVERS SEAT.
FRIENDLY	084300C	6135000	6R02	1L7Z	7881203	CAA	Drvr	488 SEAT BELT NOT STAYING ATTACHED FOUND DRIVERS SEAT BELT NOT STAYING ATTACHED FOUND SEAT BELT BUCKLE NOT WORKING REMOVE SEAT TO ACCESS THE BUCKLE REMOVE OLD BUCKLE INSTALL NEW BUCKLE REINSTALL SEAT Q.	QUALITY TESTED OK
NORTH CH	246872A	8458800	6R02	1L7Z	7881203	CAC	Drvr	D S BUCKLE COMES UNLATCHED WHILE DRIVING. INSPECT & REPLACE BUCKLE. WEAK LATCH SPRING.	
BLUEBON	20825704	8088011	6R02	1L7Z	7881203	CAA	Drvr	M TIME TO TEST & REPLACE DRIVERS SEAT BELT BUCKLE FOR WILL NOT LATCH CONCERN	
PALM SPR	100331A	3282102	6R02	1L7Z	7881203	GAB	Drvr	5051 WAFFR REMOVED AND INSTALLED DRIVERS FRONT SEAT BELT ASSEMBLY RECALL 01621	
CHARLES	181481A	2780707	6R02	1L7Z	7881203	CAC	Drvr		
LEGACY	P078781A	2289141	6R02	1L7Z	7881203	CAC	Drvr	1778 INSTALLED DRIVER SIDE FRONT SEAT BELT BUCKLE 10318 AIR BAG LIGHT FLASHING W REPLACE DRIS SIDE SEAT BELT LATCH SOP PRETENSIONER FOR DRIS SIDE 01878 CODE PRETENSIONER SHORTED TO BATTERY POWER	
MCCOTTE	138833A	2872112	6R02	1L7Z	7881203	GAA	Drvr	4018 R/R DRIVERS SEAT, INSTALLED NEW SEAT BELT BUCKLE TESTED WORKS FINE AT THIS TIME	
TOMBALL	238885A	3516427	6R02	1L7Z	7881203	GAB	Drvr	R/R FRONT CAPTAIN S CHAIR, REPLACED LEFT BUCKLE.	
LOHE STA	38483701	8813800	6R02	1L7Z	7881203	CAA	Drvr	REPLACED JAMMED BUCKLE	
BLUEBON	21048801	8088011	6R02	1L7Z	7881203	GAB	Drvr	NA	CHECK OPERATION REMOVE & REPLACE SEATBELT BUCKLE.
PACIFIC F	2800761	8278130	6R02	1L7Z	7881203	CAC	Drvr	REPLACE DRIVER SIDE SEAT BELT AND LATCH ASSY	
GREG JAA	3136101	8832204	6R02	1L7Z	7881203	GAB	Drvr	5118 NGS TEST OK PID TEST RR DR SEAT AND REPLACE SEAT BELT BUCKLE WAS INOP	
TOMBALL	340684A	3816427	6R02	1L7Z	7881203	GAB	Drvr	2887 61203 C.D. 42 RESTRAINT SYS. DIAG. ACCESS DRIVER SEAT	
MAC HAIK	154832A	8825000	6R02	1L7Z	7881203	GAB	Drvr	REPLACED DRIVER SEAT BELT BUCKLE	
LEWIS FD	888061	4485301	6R02	1L7Z	7881203	GAA	Drvr	BINDING	REPLACED SEAT BELT ON DRIVER SIDE
DAVE BIN	23088001	8822800	6R02	1L7Z	7881203	CAC	Drvr	REPLACE SEAT BUCKLE USED IN CUST REPAIR	
TOMBALL	238828C	3816427	6R02	1L7Z	7881203	GAB	Drvr	8717 PERFORMED SEAT BELT DIAG-BUCKLE BROKEN; R/R SEAT BELT BUCKLE; ADJUSTED PASS REAR DOOR STRIKER; RETESTED DOOR AND BUCKLE OK	
RUJIDOMO	008184A	8784400	6R02	1L3Z	18812818	AAC	Pagr	NGS TO RR CENTER AND PASS BUCKLE ASSY	
ESTABRO	18887201	7888541	6R02	1L3Z	18812818	AAC	Drvr	REPLACE FRONT CENTER SEAT BELT.	
NICHOLS	22883001	8353873	6R02	1L3Z	18812818	AAC	Pagr	1 REPLACED SEATBELT	
BAYTOWN	14508203	8388300	6R02	1L3Z	18812818	AAC	Pagr	REPLACED RIGHT SIDE SEATBELT BUCKLE	
MIKE CAS	14483701	8317010	6R02	1L3Z	18812818	AAB	Drvr	REPLACED SEAT BELT T	
SAM PACI	318808A	2488415	6R02	1L7Z	78812818	AAC	Pagr	3229 42 M1 .3.3 REPLACE CENTER BUCKLE ASSY.	
DAVE BIN	25706701	8882800	6R02	1L7Z	78812818	AAC	Pagr	SEATBELT ASSEMBLY FRONT REPLACE (811A72 811A73)	

EL CERRY 0915731	338030 6R02	1L7Z	78612B16 AAA	Pagr
VALLEY P.318892A	7780078 6R02	1L7Z	78612B16 AAC	Pagr
VALLEY P.317088A	7780075 6R02	1L7Z	78612B16 AAB	Pagr
ALLAN VK 3625383	4717801 6R02	1L3Z	15812B16 AAA	Pagr
DUTRO PK 12784301	4588394 6R02	1L3Z	15812B16 AAC	Pagr
BOGGUS I 8839451	8667411 6R02	1L3Z	15812B16 AAA	Pagr
MIAMI FCF 4900151	5423341 6R02	1L3Z	15812B16 AAB	Drvr
CHARLIE * 1281885	3714000 6R02	1L3Z	15812B16 AAB	Pagr
LEE MOTC 282880A	2916000 6R02	1L3Z	15812B16 AAC	Drvr
SKYLINE F 108414A	3274600 6R02	1L3Z	15812B16 AAB	Pagr
VOGLER B 2885601	4578136 6R02	1L7Z	7861203 CAA	Drvr
AUFFENBU 070902A	8330080 6R02	1L7Z	7861203 CAB	Drvr
BETHLEHI 4003851	8578841 6R02	1L7Z	7861203 CAB	Drvr
WINDSOR 2828802	3329050 6R02	F85Z	15812B16 HHH	Drvr
BARRY'S F 12408801	2844386 6R02	F85Z	78612B16 CCC	Pagr
PONKA I 2388301	7835301 6R02	F85Z	78612B16 CCC	Pagr
BUDGET F 8881451 *	6R02	YL1Z	78612B16 AAA	Pagr
LOU GRUE 4791351	8618833 6R02	XL3Z	1581203 AAC	Drvr
DON DAVI 423078C	2814281 6R02	1L3Z	15812B19 AAF	Drvr
TERREBO 233308B	3615839 6R02	1L3Z	15812B19 AAF	Drvr
JENNINGS 3788451	2492888 6R02	1L3Z	15812B19 AAD	Drvr
KEN GPOI 8870881	9218881 6R02	F85Z	15812B19 GGG	Drvr
ERNIE HA 6718651	8838671 6R02	1L3Z	15812B19 AAF	Drvr
KRIEGER 327872A	8883380 6R02	1L3Z	15812B19 AAF	Drvr
BOB BELL 275088A	7883800 6R02	1L3Z	15812B19 AAF	Drvr
CENTURY 151016A	8815282 6R02	1L3Z	15812B19 AAF	Drvr
SAM PAO 315833B	2428415 6R02	F85Z	78612B16 CCC	Pagr
DREW PO 3688451	4847777 6R02	F85Z	78612B16 DDD	Pagr

R/R RIGHT FRONT BUCKLE ASSEMBLY

FLAWED REPLACED RIGHT REAR SEAT BELT BUCKLE
 REPLACE PASS SEAT BELT BUCKLE ASS FOR WILL NOT LATCH INOPERATIVE TRACK ASSEMBLY FRONT SEAT
 REPLACE
 FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT
 REPLACE
 REPLACED SEAT BELT BUCKLE

CHECK AND REPLACED LEFT FRONT SEAT BELT BUCKLE

REPLACED LEFT FRONT DRIVER'S SEAT BELT BUCKLE THAT KEEPS THE BELT MINDER LIGHT ON
 REMOVED DRIVERS SIDE SEAT BELT BUCKLE AND REPLACED WITH NEW ONE. RECHECKED OK.
 SEAT BELT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

INSPECT, CENTER SEATBELT WILL NOT LATCH CORRECTLY, REPALCE SEATBELT ASSY AND RE TEST OPERATION OK. MT TIME NO LAB OP IN SLTS TO REPL CENTER BELT ASSY
 REPLACE RIGHT SEAT BELT BUCKLE
 (4) VERIFY CUSTOMER CONCERN REMOVE OLD BELT BUCKLE AND INSTALLED NEW ONE AND CK OPERATION GOOD
 BUCKLE JAMMED WONT BUCKLE TO BELT DEFECTIVE SEAT BELT BUCKLE REPLACED PAA SIDE BUCKLE
 VERIFIED CONCERN TESTED SEAT BELT WIRING FOUND SEAT BELT BUCKLE INTERNALLY OPEN R/R BUCKLE AND TESTED OPERATION NORMAL. M/TIME REQUESTED FOR ALL THE MENTIONED REPAIRS DONE DUE TO NO LABOR OPPS FOUND
 8258 LOOSE PULL BENCH SEAT TO REPLACED DRIVERS SEAT BUCKLE TEST OK ***QUALITY CONTROL BY TIM HUDSON***
 18888 DR. SEATBELT LOCK BROKEN DIAG. SEATBELT BUCKLE INOP. REPL. DRIVER SEATBELT LOCK ASSY., RETESTED O.K.

LFT FRN SEATBELT BINDING REPLACED SEATBELT ASSY. CENTER SEAT BELT ADDITIONAL MISC. REPAIRS

RENEW DRIVERS SEAT BELT
 04 REPLACED SEAT BELT SPECIAL ORDERED
 89 SEAT BELT ASS WARR REMOVED AND REPLACED LEFT SIDE BUCKLE ASS.
 REPLACE DRIVER SEAT BELT BUCKLE WILL NOT LATCH
 1845 49 Mt. 2 2 2 REPLACE BUCKLE
 VERIFY CONCERN REPALCE PASSENGER SEAT BELT BUCKLE
 VERIFY REPAIR

BLYTHEVI 4443002	7834463 6R02	YL1Z	78812818 AAA	Page
TEXAN FC360025A	6798100 6R02	F85Z	78812818 CCC	Page
RED 68MO D07834C	3638100 6R02	F85Z	78812818 CCC	Page
MAGIC FO 1628782	2568800 6R02	F85Z	78812818 CCC	Page
MONACO 168507A	8623000 6R02	F85Z	7881208 88E	Drvr
GRENE F189619A	6328820 6R02	1L7Z	7881208 CAC	Drvr
SAWYRAI 38918001	8518000 6R02	1L3Z	15812818 AAA	Page
FIVE STAR180088C	4988838 6R02	1L7Z	7881203 CAB	Drvr
WELCOME 2768801	8883400 6R02	1L3Z	15812818 AAF	Drvr
SHAKER'E 11438102	9454800 6R02	1L3Z	1581203 AAC	Drvr
FOUNTRE 12948801	7888830 6R02	1L3Z	15812818 AAC	Page
VALLEY P.818608A	7780078 6R02	F85Z	15812818 HHH	Drvr
DYER88AU 5202801	3882800 6R02	1L3Z	15812818 AAB	Drvr
MAGIC FO 1888881	2888800 6R02	F85Z	78812818 CCC	Page
ANDER8C 5574801	8863108 6R02	F85Z	78812818 CCC	Page
SOUTH S1288442A	3808000 6R02	1L3Z	15812818 AAB	Page
HUDGEOP 3840101	7285470 6R02	1L7Z	7881208 QAA	Drvr
FERMAN F 13188301	7734118 6R02	1L3Z	15812818 AAC	Page
STAR POF288388A	4988800 6R02	1L7Z	7881208 QAA	Drvr
LARRY GE 828801	8212121 6R02	1L3Z	15812818 AAC	Page
HERITAGE 8202051	6286110 6R02	1L3Z	15812818 AAF	Drvr

P.O.O.3 18 02 SEAT BELT ASSEMBLY
 8283 CC41 RIGHT FRONT BUCKLE WILL NOT LATCH. REMOVE AND
 REPLACE BUCKLE.

REPLACED SEAT BELT BUCKLE PASSENGER SIDE
 RT FRONT SEAT BELT WONT LATCH SEATBELT ASSEMBLY
 FRONT REPLACE
 REMOVED LF SEAT AND REPLACED LF SEAT BELT BUCKLE,WOULD
 NOT LATCH.
 NED TO REPLACE SEAT BELTS

INSTALLED LEFT & RIGHT SIDE SEAT BUCKLE ASSEMBLIES,TESTED
 ALL FUNCTIONS AFTER THE REPAIR,ALL TO SPEC AT THIS TIME
 3310 TESTED BOTH FRT SEAT BELT BUCKLES,VERIFIED CONC
 ERN,ACCESS BOTH FRT SEAT & REPLACED BOTH FRT SE AT BELT
 BUCKLES.

TEST OPERATION OF SEAT BELTS REMOVE AND REPLACE SEAT
 BELTS
 . INSTALLED SEAT BELTS BUCKLES
 REPLACE MISSING LAP BELT AND BUCKLE
 REPLACE SEAT BELT BUCKLE AND LAP STRAP.

BOTH SEAT BELTS INOP REPLACE BOTH SEAT BELTS

SEAT BELT BUCKLE LATCHES BROKEN

SEATBELT LOCKS UP WHEN TRAVELING, REPLACED SEATBELT
 INSPECTED DRIVERS SEAT BELT. CONNECTOR IS BROKEN.
 REPLACED SEAT BELT AND BUCKLE ASSEMBLIES. RE TESTED, OK.
 MT78811808 TIME TO REPLACED DRIVERS SEAT BELT AND BUCKLE
 ASSY, NO LABOR OPS AVAIL.

BINDING COMPLETED INSTALL OF SEAT BELT PASSENGER SIDE

UND RESISTANCE AS3,
 AS4, AS8 FOUND
 INTERNAL CONCERN FROM
 MODULE REPLACED
 MODULE AND RETEST
 SYSTEM. REPLACED DRV
 SEAT BELT BUCKLE OPEN
 RESISTANCE. RETEST
 SYATEM CMDTC PASS, ON
 DEMAND

11078 42 W 148321, 7881203 VARIFIED AIR BAG M1 FLASHING. M38
 RETRIEVED B1921, B1878, B1888 CMDTC. ON DEMAND SELF TEST
 RCM MODULE B1921, B1878, B1888. PINPOINT TESTS AS1, AS2
 DEACTIVATE BRACKET GRO
 DIAG INSP M TIME TO REPLACE BOTH SEAT BELT BUCKLES

REPLACED LEFT SEAT BELT BUCKLE PER RECALL.

TAMMAM F	2940301	4488673	6R02	1L3Z	15812819	AAF	Drv	1 INSPECT AND REPLACE BOTH FRONT SEATBELT BUCKLES
DAVE SM	22842401	8922800	6R02	*	15812819	*	Drv	REPLACED DRIVERS BUCKLE
DAVE SM	22736501	8922800	6R02	1L3Z	15812819	AAF	Drv	REPLACED BOTH FRONT BUCKLES
HERITAGE	8233151	6285110	6R02	1L3Z	15812819	AAF	Drv	REPLACED BOTH SEAT BELT BUCKLES PER RECALL
DOM BASH	88813701	8428800	6R02	1L3Z	15812819	AAF	Drv	REPLACE DRIVERS LEFT FRONT SEAT BELT
DAVE SM	22723801	8922800	6R02	1L3Z	15812819	AAC	Page	REPLACED RIGHT FRONT SEAT BELT BUCKLE
FIVE STAR	136307A	4888638	6R02	1L3Z	1581203	BAA	Drv	800 W REPLACED DRIVER SIDE SEAT BELT RETESTED ALL OK
GALPIN FR	6027851	7873800	6R02	1L3Z	15812819	AAF	Drv	RECALL 01821
REPUBLIC	4134433	7322828	6R02	1L3Z	1581203	AAB	Drv	ASSEMBLY AS NEEDED
GALPIN FR	6887811	7873800	6R02	1L3Z	1581203	BAB	Drv	SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS
MIKE BAS	8772880	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL
GALPIN FR	6027821	7873800	6R02	1L3Z	15812819	AAF	Drv	RECALL 01821
KENMOUN	488801	3330771	6R02	1L3Z	1581203	AAC	Drv	TRACE CODE HAD CODE 48 B1877 INSTALL PRETENSIONER NEG TO R/R BACK OF SEAT DRIVERS SIDE & REPLACE BUCKLE
MATHEW F	4380230	3873673	6R02	1L3Z	15812819	AAF	Drv	01821 SEAT BELT RECALL 01821 SEAT BELT RECALL
TEAM FOR	8411801	6488100	6R02	1L3Z	1581203	BAC	Drv	547174 8328 MILES REPLACED SEAT BELT BUCKLE
GALPIN FR	6887811	7873800	6R02	1L3Z	1581203	BAB	Drv	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
CERRITOS	25463801	8545554	6R02	1L3Z	15812819	AAC	Page	01821 G PASS BUCKLE RPL PASS BELT BUCKLE
MIKE BAS	8772880	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL
DARCARE	18583301	4591100	6R02	1L3Z	1581203	BAB	Drv	SEATBELT BUCKLE IS BINDING. REPLACED SEAT BELT ASSEMBLY.
DOUG HU	4484001	4734238	6R02	1L3Z	15812819	AAB	Page	REPLACE SEAT BELT BUCKLE
JOE MYEF	363288A	8988200	6R02	1L3Z	15812819	AAF	Drv	10188 LEFT SIDE SEAT BELT RECEIVER IN OP INSPECT FOUND SEAT BELT RECEIVER IN OP REPLACE RECEIVER ASSEMBLY OK AFTER REPAIR. CO 42
LANDERS	6848301	8548873	6R02	1L3Z	15812819	AAD	Drv	LF SEATBELT BUCKLE FAILED TEST. OASIS SAYS NOT INVOLVED IN 01821 RECALL. REPLACED LF SEAT BUCKLE AS SAFETY LIABILITY ISSUE. LISTED LABOR AS M TIME. NO CP# PUBLISHED.
IRWIN LM	2813851	4821818	6R02	1L3Z	1581203	BAB	Drv	SEAT BELT LITE ON AT TIMES BODY CHASSIS ELECTRICAL (RCS) TEST
MIKE BAS	8773880	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL PER FORD
HUEBLER F	7303704	3622857	6R02	1L3Z	1581203	BAB	Drv	LEFT SIDE SEAT BELT BUCKLE STICKING REPLACED LEFT SIDE BELT BUCKLE
MIKE BAS	8788880	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL
GALPIN FR	6887851	7873800	6R02	1L3Z	1581202	AAE	Page	REPLACE SEATBELT WILL NOT LATCH PROPERLY
MIKE BAS	8783180	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL
MIKE BAS	8794630	8348891	6R02	*	1581202	*	Page	RECALL COMPLETE RECALL
MIKE BAS	8774180	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL PER FORD
BAILEY MK	051214A	4833300	6R02	1L3Z	15812819	AAC	Page	OK ORDER AND REPLACE BELT ASSY
MIKE BAS	8788850	8348891	6R02	*	1581202	*	Page	COMPLETE RECALL
WINEGAR	10188401	7854444	6R02	1L3Z	15812819	AAB	Page	REPLACE PASSENGER SEATBELT.

GALPIN R	5854541	7873900	8F02	1L3Z	1881203	BAB	Drw	SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS
GALPIN R	8027811	7873900	8F02	1L3Z	18812818	AAF	Drw	SEATBELT WONT LATCH REPLACE SEAT BELT
RIVERSID	1871451	7486771	8F02	1L3Z	1881203	BAB	Drw	SEATBELT ASSEMBLY FRONT REPLACE
GALPIN R	8027881	7873900	8F02	1L3Z	18812818	AAF	Drw	RECALL 01821
GALPIN R	8027841	7873900	8F02	1L3Z	1881203	BAB	Drw	DOORS CLAM 5854541 SHOULD BE A 8PW
GALPIN R	8027883	7873900	8F02	1L3Z	1881203	BAB	Drw	CCD30 DIAG, REPLACE DRIVERS SEAT BELT BUCKLE
GALPIN R	8027881	7873900	8F02	1L3Z	18812818	AAF	Drw	RECALL 01821
GALPIN R	8027881	7873900	8F02	1L3Z	18812818	AAF	Drw	RECALL 01821
GALPIN R	8027871	7873900	8F02	1L3Z	18812818	AAF	Drw	RECALL 01821
KENTWCK	29727804	4788900	8F02	1L3Z	1881203	BAB	Drw	FAULTY BUCKLE. CHK OPER OF DR SEATBELT BUCKLE,REPLACED
SOUTHWY	5182701		8F02	1L3Z	18812818	AAA	Page	BUCKLE ASBY, VERIFY REPAIR BY FUNCTIONALTY
GALPIN R	8027941	7873900	8F02	1L3Z	18812818	AAF	Drw	TIME TO REPLACE SEATBELT BUCKLE, NO TIME IN LTS
TUSKET S	034851A	6482900	8F02	1L3Z	18812818	AAB	Page	RECALL 01821
OHOMEDI	1188401	8888800	8F02	1L3Z	1881203	AAB	Drw	TECH REPLACED BELT BUCKLE PASS SEAT, WAS STUCK DOWN
BILLIE HY	7881201	8512125	8F02	1L3Z	1881203	AAB	Drw	VERIFIER FONCTIONNEMENT DES BOUCLES DE CEINTURE AVEC
LAKELAN	1118880	8521025	8F02	1L3Z	18812818	AAB	Drw	OUTIL DU RAPPEL 01821... CEINTURE DEFECTUEUSE , REMPLACER
BMI VALL	3852552	8890333	8F02	1L3Z	1881203	BAB	Drw	CEINTURE GAUCHE
CHARLIE	110585A	3714000	8F02	1L3Z	18812818	AAF	Drw	CHECKED AND REPLACED LEFT SEAT BELT BUCKLE
KRISTIER	817854A	8882320	8F02	1L3Z	1881203	BAB	Drw	LEFT FRONT SEAT BUCKLE DOES NOT BUCKLE PROPERLY.
BORGMAN	084817A	8347851	8F02	1L3Z	18812818	AAC	Page	REPLACE LEFT FRONT SEAT BELT BUCKLE.
RENNER I	8183801	8721281	8F02	1L3Z	1881203	AAB	Drw	SEAT BELT FAULTY SEATBELT ASSEMBLY FRONT
MARGHAL	4830102	8783873	8F02	1L3Z	18812818	AAF	Drw	REPLACE
TED BRIT	28402201	5818484	8F02	1L3Z	18812818	AAB	Page	REPLACED DRIVERS SEAT BELT BUCKLE
MAITLANC	5488801	7884846	8F02	1L3Z	18812818	AAC	Drw	AS PER RO
MORLAND	803801	8321340	8F02	1L3Z	18812818	AAC	Page	REPLACE BOTH FRONT SEAT BELTS AS PER RO
BILL HOU	11478801	8404841	8F02	1L3Z	18812818	AAB	Page	DRIVER BELT BUCKLE BROKEN AND MOUNT BOLT HEAD IS STRIPPED
FAIRWAY	174835A	8878331	8F02	1L3Z	1881203	BAB	Drw	TIME AS NEBBY, TO REMOVE BOLT AND REPLACE RF BUCKLE MT
WINGMES	480748A	8874434	8F02	1L3Z	18812818	AAB	Page	.6 HRS
JENKINS F	1281281	4721700	8F02	-	1881203	-	Drw	TECH INSPECTED VEHICLE, CHECKED OPERATION AND SEAT
TURNPIKE	144881B	8250431	8F02	1L3Z	1881203	AAC	Drw	BELT BUCKLE INOP WILL NOT LATCH. ORDERED NEW S.O.P TECH
BLUE SPR	473184A	2284400	8F02	XL3Z	1881203	AAC	Drw	REMOVED DRIVER SEAT REMOVED AND REPLACED SEAT BELT
								BUCKLE CHECKED OPERATION OKAY. REINSTALL
								DEFECTIVE SEATBELT RECEIVER, DIAGNOSIS CHECKED AND
								REPLACED DRIVERS SEATBELT RECEIVER,
								VERIFIED CONCERN AND FOUND THAT RIGHT SEAT BELT LATCH
								WILL NOT LATCH REMOVED RIGHT SEAT REMOVED CENTER SEAT
								BELT UNIT
								CHECK FOR CONCERN & CHECK & REPLACE SEATBELT LATCH
								ASSEMBLY, RECHECK ALL OK.
								REPLACER CEINTURE AV DROITE
								REPLACE PAS SEAT BELT BUCKLE
								4811 SEAT BELT BUCKLE INOP DIAGNOSE REPLACE LR FRONT
								SEAT BELT BUCKLE ANY COAS 407
								SWAPPED SEATBELTS
								FOUND SEAT BELT LATCH CONNECTPOORRECONNECTED
								CONNECTION
								RMR DRIVERS SEAT, REPLACE SEATBELT BUCKLE BROKEN
								REPLACE FRONT SEAT BELT AND BUCKLE

PETRUS A 11676251	6734662 6R02	1LJZ	16612518	AAA	Page
CLEWELL 3577322	4307767 6R02	1LJZ	1661203	AAB	Drvr
RANDALL 136631A	6344600 6R02	1LJZ	16612518	AAO	Page
FAIRWAY 046685A	2326666 6R02	F85Z	7661203	BBE	Drvr
COUNTRY 076718A	5756673 6R02	1LJZ	7661203	CAC	Drvr
VILLAGE F 9747751 *	6R02	1LJZ	7661203	CAA	Drvr
ADA FORI 069160A	3326161 6R02	1LJZ	7661203	OAA	Drvr
GERRITTO 25463601	6656364 6R02	1LJZ	7661203	CAB	Drvr
BENSON F 10076601	6656364 6R02	F85Z	7661203	BBB	Drvr
ADVANTA 3306901	3366466 6R02	1LJZ	7661202	BAB	Page
GALPIN R 4654631	7673660 6R02	1LJZ	7661203	CAC	Drvr
FRIENDLY 24664602	6666600 6R02	F85Z	7661203	BBE	Drvr
JONES FC 8461061	7446311 6R02	1LJZ	76612518	AAC	Page
CALVIN FC 64251	6676663 6R02	1LJZ	7661203	GAA	Drvr
JOHN ELY 336614A	6666660 6R02	1LJZ	7661202	BAB	Page
HEINTZEL 166767A	2661000 6R02	1LJZ	7661203	CAC	Drvr
BUSHNELL 641101	6626276 6R02	1LJZ	76612518	AAA	Page
AIGNS FOI 4736466	6676136 6R02	F85Z	7661203	BBB	Drvr
TERREBO 212164A	6616663 6R02	1LJZ	76612518	AAC	Page
OROSBRC 22274601	4671661 6R02	1LJZ	7661203	CAA	Drvr
POND OF 177667A	6466666 6R02	1LJZ	76612518	AAB	Page
JOHNSON 1266262	7766266 6R02	YL1Z	76612518	AAA	Page
DOWNTOW 166663A	4426661 6R02	1LJZ	7661203	CAB	Drvr
RANCHO I 36166601	6661306 6R02	1LJZ	7661202	BAB	Page
CARAWAY 1007660A	6622611 6R02	1LJZ	76612518	AAA	Page
WALNUT 136643A	6622600 6R02	1LJZ	7661203	CAA	Drvr
JONES FC 8460661	7446311 6R02	1LJZ	76612518	AAA	Page
MEL CLAY 3663662	2641611 6R02	1LJZ	1561203	AAC	Drvr

CHECK OUT CHECK OVER SEAT BELT BUCKLE BOTH ARE BROKEN ON PASSENGER SIDE NEED TO REPLACE REPLACED SEAT BELT BUCKLE

MISSING BUCKLE ASSY. REPLACED DRIVERS SEAT SEAT BELT BUCKLE ASSY MISSING PART BASIC 62106 CODE 36 THIS VEHICLE WAS DEALER TRADE FROM ANOTHER DEAL WASNT

CORRECTED AT THERE DEALERSHIP
REPLACE RIGHT FRONT SEAT BELT BUCKLE

REPLACE SEATBELT

REPLACED LF. SEAT BELT LATCH DE

RECALL INSPECT AND REPLACE SEAT BELTS BUCKLE

INSTALL SEAT BELT

FAILED DRIVERS SEAT BELT BUCKLE TEST REPLACE DRIVER SIDE BELT BUCKLE NO RECALL OF CODE F85 WARRANTY OK AND REMOVED DRIVERS SEAT BELT BUCKLE ASSY AND REPLACED RECHECKS FINE

SEAT BELTS WONT LATCH REPLACE SEAT BELTS

NO SEAT BELT IN VEHICLE. EXCHANGED PART FROM STOCK UNIT. PARTS ARRIVED AND A NEW SEAT BELT BUCKLE WAS INSTALLED.

WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE

REPLACE SEAT BELT BUCKLE

REPLACE SEATBELT BUCKLE BINDING

ON SEAT BELT RECALL 4 INSPECTED BOTH SEAT BELTS DRIVER

FAILED. REPLACED DRIVERS SEAT BELT

CHECK AND REPLACE RF SEATBELT BUCKLE PER RECALL

SEAT BELT FAILED BODY CHASSIS ELECTRICAL (BCE)

TEST

3066 RR FRONT PASS. SEAT BELT BUCKLE, ORDERED REAR PASS.

SEAT BELT BUCKLE

REPLACED LEFT SIDE SEAT BELT

RECALL 01321

1 CHECK FRONT PASS SIDE SEAT BELT BUCKLE IS VERY HARD NO RELEASE.REMOVE AND REPLACE RIGHT FRONT SEATBELT BUCKLE.

REPLACED BOTH SEAT BELT BUCKLES

REPLACED SEAT BELT

76612518 ANCHOR REPLACE SEAT BELT BUCKLE RIGHT FRONT

11 INSPECT AND REPLACE 2 SEATBELT BUCKLES. 00 40 SPLIT BENCH WITH NO POWER OR SFR.

WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE

REPOE COMPLETE

MCKIE FO	2882402	2481400	6R02	1L7Z	7881203	CAA	Drvr
PHILLOW	53483001	6388861	6R02	1L7Z	7881202	BAB	Page
GALPIN R	5887581	7873800	6R02	1L7Z	7881208	CAC	Drvr
NORTH P/	36066801	3418841	6R02	1L7Z	7881202	BAC	Page
SOUTH BJ	8103751	6440211	6R02	1L7Z	7881203	CAB	Drvr
WORLD R	8206861	2388211	6R02	1L7Z	7881202	BAD	Page
LARRY GE	833601	5212121	6R02	1L7Z	78812818	AAC	Page
MIKE SNA	4181651	2923325	6R02	1L7Z	7881202	BAA	Page
DAVE SIM	22804801	8223800	6R02	1L7Z	7881202	BAB	Page
BAY AREA	2880061	4886820	6R02	1L7Z	7881202	BAA	Page
DECKER F	068228A	2912881	6R02	1L7Z	7881203	CAD	Drvr
HILLCREE	608881	2853784	6R02	1L7Z	7881203	CAD	Drvr
WORLD R	8387851	4437800	6R02	1L7Z	7881203	CAC	Drvr
MIKE BAB	8888880	8948891	6R02	*	1681202	*	Page
CHINO HI	381888A	3888331	6R02	F86Z	78812818	000	Page
BRENEN	17846101	2888716	6R02	1L7Z	7881203	CAB	Drvr
PINECRE	658788	3274327	6R02	1L7Z	7881202	BAB	Page
MAROON	517222A	8727200	6R02	1L7Z	7881203	CAB	Drvr
MAROON	511484B	8727200	6R02	F86Z	7881203	B8E	Drvr
HACIEND	8376001	3881816	6R02	YL1Z	78812818	AAA	Page
AL PACKE	2388880	8848880	6R02	1L7Z	7881202	BAA	Page
HEINTZL	188772A	2881000	6R02	1L7Z	78812818	AAA	Page
RIPON FO	3887401	7487777	6R02	F86Z	7881203	B8D	Drvr
BOB BELL	273784A	7883800	6R02	F86Z	7881203	B8D	Drvr
THOMAS F	7888061	3727144	6R02	YL1Z	78812818	AAA	Page

VERIFIED CONCERN CHIME WENT ON WITH BUCKLE HOOKED
CIRCUIT TEST SEAT BELT WARNING SYSTEM REPLACE
DRIVERSEAT BELT BUCKLE OPEN CIRCUIT IN BUCKLE WIRING

088A TIME TO REPLACE RIGHT FRONT SEAT BELT BUCKLE
SEAT BELTS WONT LATCH REPLACE SEAT BELTS
INSPECTED AND REPLACED FAILED RF SEAT BELT BUCKLE
RECALL INSPECT AND REPLACED TWO SEAT BELT
BUCKLES.

RR RIGHT SEAT AND REPLACE BUCKLE ASSY
DIAG INSP VERIFIED CONCERN IN TIME TO REPLACE SEAT BELT
BUCKLE
SEAT BELT INOP SEAT BELT ASSEMBLY REAR RIGHT OR
LEFT REPLACE
REPLACE ONE SEAT BELT
R1 SEAT TRACK TO REPLACE SEAT BELT
21 CHECK AND INSPECT PERFORMED RECALL 01821 REMOVE
AND REPLACE FAIL BOTH FRONT SEAT BELT BUCKLE END
RELEASE ASSY. 21

SEATBELT ASSEMBLY FRONT REPLACE
PERFORMED RECALL 01821 REPLACED BOTH FRONT SEAT BELT
BUCKLES OUT MILEAGE 8404
COMPLETE RECALL

REPLACE REAR BELT BUCKLE PASSENGER SIDE.

CHECK OUT, CONFIRMED SEAT BELT INOP, REPLACE AND RETEST
SEATBELT ASSEMBLY FRONT REPLACE
3811 WARN VERIFY CONCERN NGS DIAG TO MONITOR PIDS
FOUND DRIVER SEAT BELT NOT SHOWNING SEAT BELT NOT
BUCKLED. PERFORMED PPT. FOUND SEAT BELT BUCKLE INOP RR
BUCKLE RETEST AND QUALITY INSPECTED BY #711

3911

VERIFY AND TEST NECESSARY TO REPLACED BUCKLE
VERIFY CONCERN CENTER BUCKLE WOULD NOT LATCH AND RT
REAR REPLACED CENTER BUCKLE AND RIGHT REAR SEATBELT
BUCKLES

REPLACE SEAT BELT.
08 SEAT BELT RECALL. 4 UNSPECTED BOTH SEAT BELTS PASS
FAILED. REPLACED PASS SEAT BELT.
CHECKED BUCKLES DID OEM TEST NEEDS DRIVERS FRONT SEAT
BUCKLEREPLACED THE BUCKLE OK NOW
188 CHIMING SEAT BELT WARN REPLACED SEAT BELT BUCKLE
CHIMES WHEN SEAT BELT NOT BUCKLED DOES NOT CHIME
WHEN SEAT BELT IS BUCKLED

BUNDS SEATBELT ASSEMBLY FRONT REPLACE

THOMAS I 7422631	3727144 6R02	1L7Z	7881291B AAA	Pagr	SEATBELT INOP	CENTER SEAT BELT ASSEMBLY
CAPITAL F 2172262	7904800 6R02	1L7Z	7881291B AAA	Pagr	BELT BUCKLE	SEATBELT ASSEMBLY FRONT REPLACE
NICHOLS 20368101	5253673 6R02	1L7Z	7881292 BAB	Pagr	REPLACE RIGHT HAND SEAT BELT BUCKLE, 42	OK AND FOUND SEAT BELT BUCKLE BAD AND REPLACE SEAT BELT BUCKLE AND RECHECK
BORDELO 4387001	9422886 6R02	1L7Z	7881293 GAA	Drvr		
WALNUT (325225A	8822900 6R02	1L7Z	7881293 CAB	Drvr	11 INSPECT AND REPLACE 2 SEATBELT BUCKLES, POWER BUCKET, SLIDING BUCKET. NO SIR.	
MAG HAK 141936A	8303873 6R02	1L7Z	7881293 GAA	Drvr	SEAT BELT NOT OPERATING PROPERLY VERIFIED AND R AND R SEAT BELT ANCHOR REGISTERED AND CHECKED OK AT THIS TIME FOUND INOP SEAT BELT HAD TO REMOVE DRIVERS SEAT TO REPLACE BELT BUCKLE	
WORTHIN 15772102	4203336 6R02	1L7Z	7881293 CAB	Drvr	RECALL 01821	
HERITAGE 8148251	5295110 6R02	1L7Z	7881293 GAA	Drvr		
SHANAHAN 111488C	8255000 6R02	F85Z	7881293 BBD	Drvr	REPLACED DRIVERS SIDE SEATBELT BUCKLE	
HERITAGE 8181231	5295110 6R02	1L7Z	7881293 GAA	Drvr	REPLACED BOTH FRONT SEAT BELT BUCKLES PER RECALL	
HERITAGE 8832751	5295110 6R02	1L7Z	7881291B AAC	Pagr		
STEAMBO 4845301	5781299 6R02	1L7Z	7881293 GAA	Drvr	INTERNAL FAILURE IN BUCKLE REPLACED RT AND LT SEAT BELT BUCKLES	
HOLMES T 28288401	2828800 6R02	1L7Z	7881292 BAC	Pagr	REPLACED SEAT BELT	
ALDUBON 187070A	2938900 6R02	1L7Z	7881292 BAB	Pagr	REPLACED SEATBELT ALL OK	
FORD OF 177078A	9485555 6R02	1L7Z	7881291B AAB	Pagr	RECALL 01821	
VILLAGE F 8812351	6R02	1L3Z	1881291B AAC	Pagr	NOT LATCHING	REPLACED PASSENGER SIDE BUCKLE
BAY AREA 2876751	4885220 6R02	1L7Z	7881293 CAB	Drvr	REPLACE SUPER CREW BUCKET SEAT BUCKLE INOP	
ENCINTA 4885751	7836386 6R02	1L7Z	7881293 BAB	Drvr	INOP	REPLACE ONE SEAT BELT
					CC42 DOES NOT OPERATE PROPERLY MILES IN 1706 MILES OUT 1787 TEST FRONT CENTER SEATBELT BUCKLE OPERATION FOUND BUCKLE WOULD NOT EXCEPT THE SEATBELT INSERT INSPECTED BUCKLE FOR	
RANDALL 21518303	4488771 6R02	1L7Z	7881291B AAA	Pagr	REPLACED SEAT BELT BUCKLES	
RANDALL 20548701	4488771 6R02	1L7Z	7881293 GAA	Drvr		
SILL-TERR 5187851	4881801 6R02	1L7Z	7881293 CAB	Drvr	REPLACED FRONT SEATBELT ASSY	
CALVIN R 88851	2873583 6R02	1L7Z	7881291B AAA	Pagr	REPLACE SEAT BELT BUCKLE	
PRITCHAF 1085478	8433871 6R02	1L7Z	7881292 BAB	Pagr	REPLACE PASSENGER BUCKLE, MT NO PUBLISHED LABOR OF 8 INSPECTED SEAT BELTS, FAULTY PERFORMED	
ALDUBON 188822A	2938900 6R02	1L7Z	7881293 GAA	Drvr	RECALL, REPLACED SEAT BELT	
SWANSON 188473A	8884121 6R02	1L7Z	7881293 GAA	Drvr	CONFIRMED NISC TO REPLACE OT CONNECT	
ALDUBON 188940A	2938900 6R02	1L7Z	7881291B AAB	Pagr	8 INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL, REPLACED SEAT BELT	
FORD OF 801715Z	7324800 6R02	1L3Z	1881293 BAC	Drvr	BROKEN	REPLACE LEFT SEAT BELT BUCKLE
NICHOLS 2036801	5253673 6R02	1L7Z	7881292 BAB	Pagr	REPLACED SEAT BELT WITH NEW	
EARNHAR 8140268	8830000 6R02	1L7Z	7881291B AAB	Pagr	20389 VERIFIED PASS FRONT SEAT BELT RECEIVER IS INOP, REPLACED PASS SEAT BELT RECEIVER (40 80) ALL FUNCTIONS NORMAL. REPAIR SUBMISSION DELAYED DUE TOPARTS NOT AVL. REPAIR COMPLETED 8 18 02 AT 20389 MI	LES

CAPITOLI	2507751	2462800	6F02	YL1Z	7881201B	AAA	Pagr	RIGHT SIDE BUCKLE NOT LOCKING M TIME TO REPLACE RIGHT
PICMEER	23083705	2571883	6F02	1L7Z	7881203	CAB	Drvr	SIDE BUCKLE ASSY
HELGESEN	33314801	8684700	6F02	1L7Z	7881203	CAA	Drvr	1 REPLACED DRV.BUCKLE
JOE MAGF	2255201	3322300	6F02	1L7Z	7881203	CAB	Drvr	R & R R & LF SEATBELT BUCKLES, WPT.
JENKINS L	12578201	8628151	6F02	1L3Z	1581203	BAB	Drvr	REPLACED SEATBELT BUCKLE
FLANET F	17880101	7183793	6F02	1L7Z	7881202	BAC	Pagr	VERIFY FAULTY SEAT BELT BUCKLE REPLACED RIGHT SIDE SEAT
ELDON PC	6305101	3883145	6F02	1L7Z	7881202	BAC	Pagr	BELT NOW OPERATING PROPERLY
MIKE BAS	8801050	8348531	6F02	*	1581202	*	Pagr	SEAT BELT RECEPTACLE PASSENGER BELT WONT STAYED
RAY SKILL	2721151	8512541	6F02	1L7Z	7881203	CAA	Drvr	LATCHED CC-42 REPLACED PASSENGER SEAT BELT
JONES FC	8807151	7443811	6F02	1L7Z	7881202	BAB	Pagr	COMPLETE RECALL
MIKE BAS	8792850	8348531	6F02	*	1581202	*	Pagr	M/T; TIME TO REPAIR SEAT BELT BUCKLES ON SEATS.
APPLE VA	663878A	4915800	6F02	F85Z	7881251B	COO	Pagr	01821B 01821B
ROM YIRA	8315151	7253083	6F02	F85Z	7881203	8BD	Drvr	COMPLETE RECALL
BILL COLL	27737202	4590550	6F02	1L7Z	7881203	CAA	Drvr	11110 ORDERED SEAT BELT BUCKLE REMOVED OLD SEAT BELT
MIKE BAS	8800650	8348531	6F02	1L7Z	7881202	BAB	Pagr	AND INSTALLED NEW. TESTED AND FOUND GOOD.
OKC AUTC	2291788	2927171	6F02	1L7Z	7881202	BAB	Pagr	SAFETY BELT CHIMES INTERMITTENT REPLACED DRIVERS SIDE
MILLS MO	133473A	6292293	6F02	F85Z	7881203	8BD	Drvr	SAFETY BELT BUCKLE ASSEMBLY
JIM SKINN	007308A	8542222	6F02	YL1Z	7881251B	AAA	Pagr	TEST W NGS REPLACED SEAT BELT BUCKLE
JORDAN F	8300651	8333873	6F02	1L7Z	7881202	BAB	Pagr	01821 COMPLETED
GALPIN R	6821281	7873800	6F02	1L7Z	7881202	BAB	Pagr	REPLACED RIGHT FRONT SEATBELT BUCKLE
GALPIN R	3988051	7873800	6F02	1L7Z	7881203	CAC	Drvr	4842 REPLACED SEAT BELT BUCKEL (NOT A RECALL)
NICHOLS	20398481	8363873	6F02	1L7Z	7881251B	AAA	Pagr	REPLACE RT FRONT SAFTY BVELT BUCKLE ASSY. INOP
CHUCK D	10247781	358354	6F02	1L7Z	7881251B	AAC	Pagr	INOP SEATBELT ASSEMBLY FRONT REPLACE
GALPIN R	6887781	7673800	6F02	1L7Z	7881203	CAC	Drvr	CC34L PERFORMED 01821 SEATBELT RECALL
PETERSO	882302	8482828	6F02	1L7Z	7881251B	AAA	Pagr	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
WILLIAMS	228022A	2282411	6F02	1L7Z	7881251B	AAA	Pagr	REPLACED SEAT BELT WITH NEW
PICMEER	23849102	2371883	6F02	F85Z	7881203	8BD	Drvr	BUCKLE JAMMED, WILL NOT ACCEPT BUCKLE TONGUE. REPLACE
KEN GRQI	8285481	8818881	6F02	1L3Z	1581251B	AAC	Pagr	BELT ASSY.
BROADW	7788751	8828800	6F02	1L7Z	7881203	CAC	Drvr	SEAT BELTS WILL NOT LATCH REPLACE SEAT BELTS
FIVE STAF	183671C	4888838	6F02	1L7Z	7881251B	AAC	Pagr	REPLACED THE RIGHT SIDE SEATBELT BUCKLE THAT DOES NOT
KEN GRQI	4380732	4388171	6F02	1L7Z	7881251B	AAC	Pagr	LATCH.

BILL UTTE	570851	3217400	6R02	1L7Z	7861202	BAD	Page
CALVIN FC	82761	2873553	6R02	1L7Z	7861203	CAA	Drv
KEN BRCH	6384451	3218081	6R02	1L7Z	7861203	CAA	Drv
KARL FLA	8840351	3375131	6R02	1L7Z	7861203	CAA	Drv
GULF COJ	4212501	6488351	6R02	F6Z	78612518	CCC	Page
STOKES-C	11101	4335400	6R02	*	15812518	*	Drv
WORLD R	3588551	4799050	6R02	F6Z	7861203	BB0	Drv
NORTH PC	230485C	8481200	6R02	YL1Z	78612518	AAA	Page
SWANSON	188478A	2254121	6R02	1L7Z	7861203	CAA	Drv
ADVANTA	3388301	3588889	6R02	1L7Z	78612518	AA0	Page
COVERT F	308301	3688000	6R02	F6Z	7861203	BB0	Drv
SWANSON	188473A	8894121	6R02	1L7Z	7861203	CAA	Drv
VISION FC	45251	6425345	6R02	F6Z	78612518	DD0	Page
VISION FC	38421	6425345	6R02	F6Z	78612518	CCC	Page
VISION FC	69881	6425345	6R02	1L3Z	15812518	AAC	Page
POINT PLJ	3161731	6824300	6R02	1L7Z	7861203	OAB	Drv
MARCOONE	385481A	8727200	6R02	1L7Z	78612518	AAC	Page
NICHOLS	3036001	3333473	6R02	1L7Z	7861202	SAB	Page
GALPIN FC	5887881	7873800	6R02	1L7Z	7861203	OAC	Drv
GALPIN FC	5888501	7873800	6R02	1L7Z	7861202	AAC	Page
BLUBSON	18418001	6088011	6R02	1L7Z	7861203	CAB	Drv
MANTECA	080823A	2383581	6R02	F6Z	78612518	CCC	Page
MANTECA	081854A	2383581	6R02	1L3Z	15812518	AA0	Page
GALPIN FC	6857571	7873800	6R02	1L7Z	7861203	OAC	Drv
DON DAVI	4158250	2914881	6R02	1L3Z	15812518	AAC	Page
BRENT W.	223002	8642161	6R02	F6Z	7861203	BB0	Drv
GALPIN FC	6887821	7873800	6R02	1L7Z	7861203	CAC	Drv
SPRINGD	0002161	7515788	6R02	YL1Z	78612518	AAA	Page
PERFORW	1884701	62841	6R02	-	1581202	-	Page
BARTOW	2766703	5380485	6R02	1L7Z	7861203	CAA	Drv
BOB BIGH	112031A	3288580	6R02	F6Z	78612518	DD0	Page
DECKER F	097748A	2913581	6R02	1L7Z	78612518	AAC	Page
GALPIN FC	6887881	7873800	6R02	1L7Z	78612518	AAC	Page
GOSCH FC	23482101	5389181	6R02	1L7Z	7861203	CAC	Drv

WOULD NOT LATCH SEATBELT ASSEMBLY FRONT
 REPLACE
 REPLACE SEAT BELT BUCKLE
 BAD SEAT BELT BUCKLE ROADTEST, PERFORMED
 ELECTRICAL TEST R & R BUCKLE, RETEST,

INOP REPLACED SEAT BELT BUCKLE
 SEAT BELT BUCKLE WONT LATCH REPLACED THE PASS SIDE FT
 SEAT BELT BUCKLE

DIAG AND REPAIRED OPEN CIRCUIT TO CONECTOR AT SEAT BELT
 OPEN SEATBELT ASSEMBLY FRONT REPLACE FRONT
 REPLACE
 10187 ***** GP REPLACE PASS FRONT SEAT BELT BUCKLE ASSY
 WOULD NOT BUCKLE
 NEG TO RPLCE BOTH TO CORRECT
 REPLACED RIGHT SIDE SEAT BELT BUCKLE PER 01821.
 DAMAGED WIRE ON SEAT BELT BUCKLE REPLACED SEAT BELT
 BUCKLE ON DRIVER SIDE SEAT
 NEG TO RPLCE BOTH TO CORRECT
 CK OUT REPLACE BUCKLE
 CK OUT REPLACE BAD LATCH ASSY
 CK OUT REPLACE BAD SEAT BELT
 REPLACED DRIVER'S SEAT BELT
 14 VERMIE POUND PASS SEAT BELT INOP REPLACED
 REPLACED SIDE BUCKLE WITH NEW
 SEAT BELTS WONT LATCH REPLACED SEAT BELTS
 SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELT

INSTALLED ROP SEAT BELT BUCKLE
 REP BUCKLE ASSEY
 SEAT BELTS WONT LATCH REPLACE SEAT BELTS
 B051 REPLACED PASSENGER SEAT BELT LATCH + TEST. ***
 QUALITY CONTROL BY JOHN MEDROW ***
 CHECKED AND REPLACED LEFT FRONT SEATBELT BUCKLE TO
 CORRECT CONCERN,
 SEAT BELTS WONT LATCH REPLACE SEAT BELTS
 CENTER BELT BUCKLE WONT LATCH TIME IN TO R&R NEW
 CENTER SEAT BELT BUCKLE ASSY.
 MT TO REINSTALL CLIP

REPLACED DRIVER SIDE SEATBELT

REPLACE PASSENGER FRONT SEAT BELT BUCKLE
 REMOVE NAD REPLACE FAIL R.F SEAT BELT BUCKLE END
 RELEASE ASSY.
 REPLACE SEATBELTS WILL NOT LATCH PROPERLY
 REPLACE SEAT BELT BUCKLE, WILL NOT LATCH

FRANCIS I 28229702	5891200 8F02	F85Z	7881202	B8D	Page	REMOVE RIGHT SEAT TO REPLACE RIGHT BUCKLE PER RECALL
GALPIN FC 5887541	7873800 8F02	1L7Z	7881203	CAC	Drvr	SEAT BELTS WONT LATCH REPLACE SEAT BELTS ADDITIONAL MISC REPAIRS DO NOT USE WITH ANY OTHER LABOR OPERATIO N
RISEB FO 8215801	5250800 8F02	F85Z	7881208	B8D	Drvr	
HEDGON A 22427001	3888800 8F02	1L3Z	18812818	AAA	Drvr	BUCKLE WILL NOT LATCH REPALCED CENTER SEAT BELT BUCKLE REMOVED DRIVERS SIDE SEAT REPLACED SEAT BELT LATCH FOR HARD TO UNLATCH
KENNY NE 52341002	5488341 8F02	F85Z	7881208	B8D	Drvr	REPLACE DR SEATBELT
MARLER F 5848351	4487888 8F02	1L7Z	7881208	GAA	Drvr	CHECK AND REPLACE SEATBELT BUCKLE PER RECALL
BUSHNELL 841201	8823278 8F02	1L7Z	7881208	CAC	Drvr	DIAG INSP VERIFIED CONCERN M TIME TO REPLACE SEAT BELT BUCKLE
LARRY GE 888001	8212121 8F02	1L7Z	78812818	AAA	Page	CHECK SEAT BELT OPERATION WILL NOT LATCH REC TO REPLACE SEAT BELT LATCH
EASTWAY 81D152	3882201 8F02	1L7Z	7881208	GAA	Drvr	REPLACE LEFT FRN SEAT BELT WILL NOT LATCH
NORTHWAY040212A	3823881 8F02	F85Z	7881208	B8E	Drvr	1 REMOVED AND REPLACED LEFT FRONT SEAT BELT BUCKLE,RECHECKED OK
VAN BURF 8112801	5882421 8F02	1L7Z	7881208	CAB	Drvr	REPLACED LEFT FRONT SEAT BELT BUCKLE
TOWNSEND 144732A	7880401 8F02	1L7Z	7881208	GAA	Drvr	REPLACED DRIVERS SEAT BELT BUCKLE
HAYWARD 38118481	8811280 8F02	1L7Z	7881208	GAA	Drvr	SEAT BELT BUCKLE WILL NOT LATCH
BAY AREA 2888881	4888880 8F02	1L7Z	7881208	CAB	Drvr	(INSPECTED AND DR) NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT BUCKLE AND RETESTED OK.
CROWN F 12018202	3888528 8F02	1L5Z	18812818	AAA	Page	BUCKLE WILL NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT BUCKLE.
CROWN F 11781301	3888825 8F02	YL1Z	78812818	AAA	Page	REPLACED DR SIDE SEAT BELT DUE TO INSIDES COMING OUT AT TIMES
TEAM POP 1888888	2778420 8F02	1L7Z	7881208	GAA	Drvr	SEAT BELTS WONT LATCH REPLACE SEAT BELTS
GALPIN FC 5887801	7873800 8F02	1L7Z	7881208	CAC	Drvr	REPLACE LEFT SEATBELT BUCKLE D
KEN GRD1 4454451	4388171 8F02	1L7Z	7881208	GAA	Drvr	
BILL UTTE 8811851	3217480 8F02	YL1Z	78812818	AAA	Page	BUCKLE WILL NOT LATCH RFR FRONT RIGHT BUCKLE ASSY
BUSHNELL 842401	8823278 8F02	1L7Z	7881208	CAC	Drvr	CHECK AND REPLACE LEFT FRONT SEATBELT
AKINS FO 8087140	8678188 8F02	1L7Z	7881208	GAA	Drvr	REPLACED D SIDE SEAT BUCKLE
CHARLIE 128878A	3714080 8F02	1L7Z	7881208	GAA	Drvr	BCE DIAG,PINPOINT,REPLACED BUCKLE ASSY AND RETEST
GALVIN FC 58751	2873888 8F02	1L7Z	78812818	AAA	Page	REPLACE SEAT BELT BUCKLE RECALL 01821 RECALL REPLACE SEAT BELT BUCKLE
AKINS FO 8007188	8678188 8F02	1L7Z	78812818	AAA	Page	
A Q COLLI 1188781	8043878 8F02	YL3Z	1881280	BAA	Drvr	INOP
FORD OF 8018882	7884880 8F02	1L3Z	18812818	AAB	Page	BEATBELT ASSEMBLY FRONT REPLACE BROKEN REPLACE SEATBELT BUCKLE
DOBBS FC 8878781	3888888 8F02	F85Z	7881208	B8D	Drvr	REPLACE SEATBELT SENSOR REPLACE SEATBELT SENSOR 18824 M TIME S M TIME NO OPS FOR BUFR OREN TO REPLACE DRIVERS SEAT BELT BUCKLE, BUCKLE IS INTERNALLY JAMMED CC BY TECH
SUNRISE 538188A	8284451 8F02	1L7Z	7881208	GAA	Drvr	
ANDERSC 1888888	4788881 8F02	1L7Z	7881208	CAB	Drvr	2278 BASIC 7881208 CONDITION 41 REPLACED THE INTERMITANTLY STICKING L F SEATBELT BUCKLE

WADE FO	162444A	4381206	6R02	1L7Z	7881203	CAB	Drvr
BROWAW	6313061	6431661	6R02	F86Z	7881203	BBE	Drvr
NICHOLS	20367601	5363873	6R02	1L7Z	7881202	BAB	Pagr
KEMP FO	6648861	6666126	6R02	1L7Z	7881203	CAB	Drvr
MIKE BAB	6806660	6346361	6R02	"	1681202	"	Pagr
BLUEBON	18464101	6038011	6R02	1L7Z	7881202	BAB	Pagr
NICHOLS	20867701	6363673	6R02	1L7Z	7881202	BAB	Pagr
GULLO FC	371141A	7367761	6R02	1L7Z	7881232	BAC	Pagr
MIKE BAB	6793360	6346361	6R02	"	1681202	"	Pagr
ALL STAR	10361501	7262171	6R02	1L7Z	7881203	CAA	Drvr
CROSSTC	166226A	6617600	6R02	F86Z	7881203	BBD	Drvr
LOU GRUE	6046161	6613666	6R02	1L7Z	7881203	CAA	Drvr
DINGWAL	18062301	4666443	6R02	F86Z	7881203	BBE	Drvr
ZIEMS FO	4413163	3351661	6R02	1L7Z	7881203	CAA	Drvr
RIFON FO	3666401	7467777	6R02	F86Z	7881203	BBE	Drvr
COURTES	7266004	2661771	6R02	YL1Z	78812618	AAA	Pagr
LANDMAR	442666A	6361131	6R02	1L7Z	78812618	AAA	Pagr
MIKE BAB	6793460	6346361	6R02	"	1681202	"	Pagr
CHAPARR	4636101	6654461	6R02	1L7Z	7881203	CAA	Drvr
CALVIN FC	66661	2673663	6R02	1L7Z	78812618	AAA	Pagr
MIKE BAB	6793660	6346361	6R02	"	1681202	"	Pagr
SKYLINE F	123066A	3274600	6R02	1L7Z	7881203	CAA	Drvr
PLANET F	16306601	7163700	6R02	F86Z	7881203	BBD	Drvr
MURPHY I	3617602	4946600	6R02	1L7Z	7881203	CAA	Drvr

31802 C K RMR LY FT SEAT TO REPLACE SEAT BELT

VCO INSPECTED SEAT BELT FOUND THAT THE BUCKLE WAS JAMMED. REMOVED FRONT SEAT AND REMOVED AND REPLACED LEFT FRONT SEAT BELT. CHECKED TO VERIFY REPAIR
REPLACED SEAT BELT WITH NEW
51 REPLACE BUCKLE
COMPLETE RECALL.

1 REPLACE RIGHT FRONT SEAT BELT.
33 D1 B21 O G4 INSP AND ERPL P SIDE SEAT BELT
COMPLETE RECALL.

VERIFY CONCERN FOR SEAT BELT RELEASE BUTTON STICKS. REMOVED & REPLACED SEAT BELT BUCKLE.
112Z RAN NGS TO CHECK FOR CODE NO CODE. RAN ON DEMAND TEST PASSED. RAN PINPOINT CHECK SEAT BELT BUCKLE SWITCH AND FOUND ITS STICKING INTERMITTENTLY. REMOVE DRIVER SEAT. REPLACE DRIVER SEAT BELT BUO
N88 BCE TEST NO CODES MONITORED PID8 FOUND DRIVERS BELT BUCKLE STUCK OPEN AND NOT WORKING PROPERLY RMR BUCKLE TESTED OPERATION GOOD
R & I LEFT FRONT SEAT & REPLACE BELT BUCKLE.

KLE. RETEST, OK. WF4

RUN WDS, PID MONITOR, DRIVERS SEATBELT NOT CORRESPONDING WITH ACTION GIVEN. REMOVE DRIVERS SEAT TO CHECK CONNECTIONS, GOOD. WDS TO CHECK SEATBELT MODULE ACTION, GOOD. COMPONENT TEST SEATBELT FAILED. R

EPLACED DRIVERS SEATBELT BUCKLE, OK AT THIS TIME.

RAN TESTS ON SYSTEM AND FOUND THE BUCKLE BAD ORDERED A NEW BUCKLE WE WILL CALL WHEN THE PART COMES IN
REPLACED THE SEAT BELT BUCKLE OK NOW
TESTED AND VERIFIED, REPLACED FAILED BUCKLE.
3717 FEMALE END BROKEN W INSPECTED SEAT BELT AND FOUND IT BROKEN. PARTS ON ORDER FROM FORD. STILL WAITING ON RIGHT PARTS. PARTS CAME IN. RMR MIDDLE BELT FEMALE END. TESTED OK. CHECKED ALL OTHER BEL
COMPLETE RECALL.
SEAT BELT BINDING. CK OP OF SEAT BELT INTERMITTENT BINDING.
REPLACE SEAT BELT ASSY.
REPLACE SEAT BELT BUCKLE
COMPLETE RECALL.

T6, OK.

VERIFIED CONCERN, SEAT BELT BUCKLE INOP, REPLACED LEFT FRONT SEAT BELT BUCKLE, FIXED VEHICLE

SEAT BELT BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE

MIDWAY F9018608	4853000 8R02	1L7Z	7881208 CAB	Drvr
WINDGAR 10528408	7854444 8R02	1L7Z	7881208 CAB	Drvr
LIBERTY F048808A	8882800 8R02	F85Z	78812818 CCC	Pagr
HJOSPET 4281351	7433200 8R02	1L7Z	78812818 AAC	Pagr
BOGGSU 8784251	8887411 8R02	1L7Z	78812818 AAA	Pagr
ENERGY (1545802	8882883 8R02	*	18812818 *	Drvr
RAMIREZ 5331852	4872882 8R02	1L7Z	7881203 CAA	Drvr
BILL HOOD 2216151	3481880 8R02	*	1881203 *	Drvr
NORTHERN 31438021	8382800 8R02	YL1Z	78812818 AAA	Pagr
MCLAUGHLIN 3128852	7731481 8R02	1L7Z	7881203 CAA	Drvr
HARPEY 18088201	7844885 8R02	1L7Z	7881203 CAB	Drvr
FRIENDLY 2188888	8834330 8R02	F85Z	78812818 CCC	Pagr
NICHOLS 22882801	8383873 8R02	1L3Z	18812818 AAB	Pagr
GOLDENH 8482852	8882100 8R02	*	18812818 *	Drvr
DON DAVIS 481288	8814881 8R02	1L7Z	7881203 CAA	Drvr
DON DAVIS 4842888	8814881 8R02	1L7Z	7881203 CAA	Drvr
HOLMES 1 34184801 *	8R02	F85Z	78812818 CCC	Pagr
HOLMES 1 38028801 *	8R02	F85Z	78812818 CCC	Pagr
HOLMES 1 37838801	8883880 8R02	F85Z	18812818 GGG	Drvr
LOVE STA 28288801	8813880 8R02	1L7Z	7881203 CAA	Drvr
BORMAN 1 27488801	8854880 8R02	1L3Z	18812818 AAF	Drvr
WALT SM 1782827A	8824880 8R02	1L7Z	7881203 CAB	Drvr

13889 288 CHECK FOR CODES WITH WDS FOUND NO CODES PERFORMED ON DEMAND TEST FOR SEAT BELT FOR SENSER INTERMITTING IN SEAT BELT ORDERED SEAT BELT PART DID NOT HAVE PER MARK C 288 288 REMOVED SEAT AND INSTALL REAR SEATBELT. REPLACE SEAT BELT BUCKLE SEAT BELT RELEASE BINDING SEATBELT ASSEMBLY FRONT REPLACE INOPERATIVE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE CENTER SEAT BELT NOT BOLTED TOP FLOOR 42 INSTALL CENTER SEAT BELT 846 LIGHT STAY ON REPLACED SEAT BELT BUCKLE DRIVER SIDE POOR CONNECTION AT SEAT BELT CLEAN AND RECONNECT SEAT BELT CONNECTOR DRIVERS SIDE INOP RECEIVERS, PASS. SIDE DEFECTIVE. REPLACED BUCKLE, CHECKED OPERATION, MIDDLE LAP BELT HAD INCOMPLETE BELT. REPLACE BELT AND RETEST BELT OPERATION REPLACED DRIVERS SIDE SEATBELT BUCKLE SEAT BELT ALARM WAS GOING OFF WHEN SEAT BELT WAS PLUGGED IN. REPLACED DRIVERS SIDE SEAT BELT LATCH. 3788 812818 BUCKLE, 42 INOP CONFIRMED CONCERN OF PASSENGER SIDE SEAT BELT BUCKLE INOP ON 80 40 SPLIT SEAT. REPLACED PASSENGER SIDE BUCKLE ASBY. CURB CONCERN NO LONGER PRESENT.

VERIFIED CONCERN, FOUND ALL THREE SEAT BELT BUCKLES IN REGULAR CAB FAILED SEAT BELT BUCKLE TESTS. REPLACED DRIVER SIDE, PASSENGER, AND CENTER SEAT BELT BUCKLE ASSEMBLIES. RETESTED NORMAL AFTER REPAIRS OUT OF ADJUSTMENT ADDITIONAL MISC. REPAIRS 1881 LOOSE REPLACE LOOSE LF SEAT BELT BUCKEL ****QUALITY CONTROL BY JAMES PENNOCK****

838 NOT STAYING LATCHED REPLACED BOTH FRONT SEAT BELT BUCKLES DUE TO NOT STAYING LATCHED. ****QUALITY TESTED BY LOUIS TREVINO*****

42 TEST SEAT BELT BUCKLE INTERMITTENTLY NOT LOCKING CHANGED SEAT BELT OUT 82 SPW RMR SEAT BELT BUCKLE

BROKEN CC 01 REPLACED CENTER SEAT BELT REPLACED SEAT BELT BUCKLE REMOVED PASSENGER BELT ONTO VEHICLE 274887 TO FINISH DRIVERS FAILED INSTALLED DRIVER BELT INSTALLED BELT ON PASSENGER SIDE THAT WAS ORDERED TECH 814 8211 REPLACED DRIVER SIDE SEAT BELT BUCKLE

INSTALL NEW SEAT BELT WORKING CORRECT 288 WORK ALREADY BEEN DONE 885

HILLER FC 055253A	4251000	6R02	1L7Z	78812B18	AAB	Page
GERRITCO 28581101	8855284	6R02	1L7Z	78812B18	AAC	Page
LAWRENCE 08873704	8288088	6R02	1L7Z	78812B18	AAA	Page
HOLMES T 25280501	2228600	6R02	F86Z	7881203	BBE	Drw
MID-STAT 040822A	2887381	6R02	F86Z	7881203	BBG	Drw
DOH CHAI 8828851	8872900	6R02	1L7Z	7881203	GAA	Drw
GALPIN M 8884821	7873800	6R02	1L7Z	7881203	CAC	Drw
COVERT F 8273201	8484848	6R02	1L7Z	7881208	CAB	Drw
RICHARDI 4445201	2220000	6R02	1L5Z	18812B18	AAD	Drw
BUTLIFF C 128888A	2284821	6R02	1L7Z	7881208	CAB	Drw
HOFFMAN 18042801	6571800	6R02	F86Z	7881203	BBE	Drw
SWANSON 187725A	8884121	6R02	1L7Z	78812B18	AAA	Page
JOHNSON 13573108	7788288	6R02	1L7Z	7881203	CAB	Drw
BILL CURT 4843802		6R02	1L7Z	7881203	GAA	Drw
MEL CLAY 4167851	2841811	6R02	1L7Z	7881203	CAB	Drw
SPRADLE 3847481	2283873	6R02	1L7Z	7881203	GAA	Drw
SOUND R 040128A	2281000	6R02	F86Z	7881208	B8D	Drw
ASHE COL 8841801	2487183	6R02	1L7Z	7881208	GAA	Drw
CAPITAL F 8443851	7884800	6R02	1L7Z	7881203	CAB	Drw
NORTHGA 7328801	7227288	6R02	F86Z	78812B18	DDI	Page
PUENTE P 5178182	8843873	6R02	1L7Z	7881203	GAA	Drw
TEXAN FC 20880501	4873873	6R02	F86Z	7881203	BBE	Drw

48 SEAT BELT BUCKLE REMOVED RIGHT FRONT SEAT BELT BUCKLE FROM STOCK UNIT # 121115 AND INSTALLED IN VEHICLE. HAD TO ORDER SEAT BELT BUCKLE FOR # 121115

01621 O SEAT BELT BUCKLE REPLACE PASS. SEAT BELT BUCKLE

CC 01 SPN 78812B18 PASSENGER SEAT BELT BUCKLE WOULD NOT STAY LATCH, REPLACED BUCKLE AND RETEST PROVED OK. OPEN CIRCUIT IN DRIVERS SEAT BELT ASSEMBLY NGS TEST PID MONITOR AND RECOULD REMOVED DRIVER SEAT AND SEAT BELT ASSEMBLY INSTALLED NEW ONE

CHECKED CODES, NONE IN RESTRAINT SYSTEM. LIGHT FLASHES WITH BELT BUCKLED. CHECKED PIDS, ORDERED LEFT SEAT BELT LATCH ASSY. REPLACED LATCH ASSY WHEN PARTS CAME IN.

DIAGNOSE SEAT BELT LIGHT ON OPEN IN SEAT BELT BUCKLE ASSY R & L SEAT ASSY TO ACCESS AND REPLACED SEAT BELT BUCKLE ASSY
CODE 28
SEAT BELTS WILL NOT LATCH PROPERLY REPLACE SEATBELT
REPLACE BELT AND BUCKLE ASSY

BUCKLE INOP R R L H BUCKLE
CHECK AND R AND R THE LF SEAT BELT BUCKLE ASSY
CHECK AND DIAG CONCERN REPL LF SEATBELT ASSY. RECHECK
OK NOW

NEED TO REPLACE BOTH TO CORRECT
1 CHECK DRIVERS SEATBELT BUCKLE IS INTERMITTING INOP.
REPLACE DRIVERS SEAT BELT BUCKLE.
RECALL REPLACE FEMALE END OF SEATBELT
DIAG OEM MODULE PINPOINT SYSTEM PASS (NO CODES)
MONITOR BUCKLE PIN IS NOT SWITCHING REPLACE L F SEAT BELT BUCKLE INOP

WARNING SWITCH FAILURE TEST SYSTEM AND REPLACE
DRIVERS SIDE SEATBELT BUCKLE
114 CHECK LEFT FRONT BELT BUCKLE HAS BRAKEN LATCH ME
CHANISM REPLACE LATCH ASSEMBLY

AIR BAG RESTRAINT SYSTEM DIAGNOSIS DO NOT USE
WITH OPERATION (2861D
PINCHED DAMAGED WIRE BODY CHASSIS ELECTRICAL
(BCE) TEST REPLACE SEAT BELT ASY

VERIFIED CUSTOMERS COMPLAINT, FOUND RIGHT SIDE SEAT BELT BUCKLE NOT CATCHING. REPLACED SEAT BELT BUCKLE, VERIFIED REPAIR.

FRONT BELT BUCKLE DOES NOT LOCK SEATBELT ASSEMBLY FRONT
REPLACE

BUCKLE WAS SHORTED OUT. ABNORMAL DIAG. NGS TEST, PIN POINT TEST, TRACE THE WIRING FROM THE SEAT AREA TO THE OEM MODULE. ALL OF THE WIRING WAS

FAMILY R 102867A	4488891 8R02	1L7Z	7801203	GAA	Drvr
CAVALIER 730728A	4241111 8R02	1L7Z	7801203	CAA	Drvr
RON-CAR 014867A	3318111 8R02	1L7Z	7801201	AAA	Pgrt
GURLEY & 12888101	7228021 8R02	1L7Z	7801203	CAA	Drvr
WEST-HEI 110483A	6488840 8R02	YL1Z	7801201	AAA	Pgrt
GATOR R 079711B	8503073 8R02	1L7Z	7801251	AAC	Pgrt
AL MEYER 8888851	6328811 8R02	F85Z	7801251	CCC	Pgrt
ALEXANDI 163881	5838514 8R02	1L7Z	7801203	CAA	Drvr
NORTHER 4341801	8881402 8R02	1L7Z	7801201	AAA	Pgrt
GIULLO FC 888788C	7857781 8R02	1L7Z	7801251	AAA	Pgrt
GIULLO FC 384880C	7887781 8R02	1L7Z	7801202	BAB	Pgrt
BROOKDA 18644102	5815500 8R02	F85Z	7801251	CCC	Pgrt
JOE MACH 31030701	4454411 8R02	F85Z	7801251	DDO	Pgrt
JOE MACH 31888001	4454411 8R02	1L7Z	7801251	AAC	Pgrt
PRICE FO 5200801	6733073 8R02	1L7Z	7801203	CAA	Drvr
CAROLYN 4808852	4811161 8R02	YL1Z	7801251	AAA	Pgrt
NATIONAL 570371B	4772711 8R02	XL8Z	1801203	AAC	Drvr
DECKER F 104303A	2812881 8R02	F85Z	7801203	BBB	Drvr
GALPIN F 4027881	7873800 8R02	1L5Z	1801251	AAF	Drvr
MCPREE R 432181C	3371988 8R02	1L7Z	7801203	CAA	Drvr
SUNRISE 512208A	8224401 8R02	1L7Z	7801203	CAA	Drvr
BARBER-L 1784801	2850480 8R02	1L7Z	7801203	CAA	Drvr
HARROLD 228178A	8221535 8R02	F85Z	7801251	COC	Pgrt
HEMBORC 1820151	7378181 8R02	F85Z	7801203	BBB	Drvr
RON DUP 030171A	8785555 8R02	1L7Z	7801251	AAC	Pgrt
DON CHAI 4283753	8872500 8R02	1L7Z	7801203	CAA	Drvr

FINPT TEST PER MANUAL FOUND BUCKLE BAD R/R BUCKLE AND REPLACE
INSPECT TEST AND MONITOR AND REPLACE BUCKLE ASSY AND RETST

1188 REPLACE PASS SIDE SEAT BELT BUCKLE
R AND L LEFT SEAT BELT BUCKLE AND REPLACE
O CUSTOMER STATED SEAT BELT WILL NOT ENGAGE CONFIRMED
CUSTOMER'S COMPLAINT SEAT BELT WILL NOT ENGAGE DUE TO
SEAT BELT RETAINER IS JAMMED REPLACED RETAINER AND
CHECKED OPERATION O.K. INSTALLED CRIDE
10888 VERIFY CUSTOMER COMPLAINT. INSPECT RT FT SEAT BELT
BUCKLE FOUND LATCH IN BUCKLE BAD REMOVE AND REPLACE RT
FT SEAT BELT BUCKLE CO 42
PASS. SEATBELT INOP SEATBELT ASSEMBLY FRONT
REPLACE

RED SEAT BELT AND
CHNBECKED OPPER O.K.

CHECK FOR RECALLS, NO RECALLS, SAFETY BELT LATCH
SWITCH NOT WORKING PROPERLY, REPLACE SEAT BELT
REPLACE SEAT BELT RELEASE ON RIGHT SIDE

7878 STICKING 811728B .4 .40 REPLACED R F SEATBELT BUCKLE
PASSENGER SIDE SEAT BELT FAILED, REPLACED SEAT BELT
1 REPLACED RIGHT FRONT SEAT BELT BUCKLE.
SEATBELT INOP, REPLACED RIGHT FRONT SEAT BELT BUCKLE.
FRONT CENTER SEATBELT INOP. REPLACED FRONT CENTER
SEATBELT AND BUCKLE.

CRD AND FOUND SEATBELT WARNING CHIME STAY ON TESTED
AND FOUND SEAT BELT BUCKLE SWITCH INOP R AND R BUCKLE
AND RETEST OK

SEAT BELT ASSEMBLY REAR RIGHT OR LEFT
C
REPLACE
REPLACE SEAT BELT BUCKLE
NEC OT REPLACE SEAT BELT

SEAT BELT WONT LATCH REPLACE SEATBELT
R/R SEAT TO REPLACE SEAT BELT ASSY INTERNAL FAI LURE
12 RECALL D18210 0.4 HRS TECH 8170 INSPECT & REPLACE
DRIVERS SEAT BELT
REPLACE BELT BUCKLE ASSY ON DRIVERS SIDE
INSPECT RIGHT FRONT SEAT BELT FOR WILL NOT BUCKLE. NEED
BUCKLE SPRING IS JAM. REMOVE AND REPLACE SEAT BELT
BUCKLE. DONE

CHECKED FOR CODES PP TEST LEAD TO OPEN CIRCUIT AT DR
SIDE BELT BUCKLE
CHECK AND REPLACE BUCKLE
NOT WORKING PROPERLY SEATBELT ASSEMBLY FRONT
REPLACE

THE FORI 3405818	3522000 6R02	1L7Z	7881203	CAB	Drvr	VERIFIED CONCERN,REMOVED DRIVERS SEAT FOR ACCES S,UNEXPECTED WIRING FRM BUCKLE UNDER CARPET,FD W IRUNG INSULATION CUT SHORTED OUT BUCKLE,ORDERE D NEW BUCKLE,VEHICLE SAFE TO DRIVE INSTALLED NEW BUC	KLE ASSY,RETESTED OK
BILL ALEX 25818202	3442200 6R02	1L7Z	78812518	AAC	Page	RUBHT FRONT SEAT BELT BUCKLE BINDING. REPLAGE. RETEST. OK SEAT BELT CHIME STAYS ON ALL THE TIME WARR CC 28 TECH 198212 MILEAGE OUT 11268 TEST WITH NBS KOEO MQ CODES MONITOR PIDS FOUND DRIVERS SEAT BELT ON SHOWING LATCHED REPLACE DRIVERS SEAT BELT BUCKLE RETE	ST
TEAM FOF 6291401	6485100 6R02	1L7Z	7881203	CAA	Drvr	28 RPL DRIVERS SEATBELT BUCKLE FOR OPEN	
CENTRAL 6407851	6002800 6R02	1L7Z	7881203	CAB	Drvr	RETEST	
EXTREME 176970A	7474760 6R02	F85Z	7881203	B8D	Drvr	13 REPLACED SO SEAT BELT BUCKLE. CC SMO 28 OPEN CIRCUIT. DIAGNOSIS TESTING WITH WDS ONSEAT BELTS AND CIRCUIT. SEFT TESTS.DTD ON DRIVER SIDE BELT CIRCUIT,OPEN AT TIMES.	
RICHARD 4416701	2820000 6R02	1L7Z	7881203	CAA	Drvr	REPLACE RIGHT FRONT SEAT BELT BUCKLE	
SUNSET F 186160C	8778808 6R02	1L7Z	7881202	BAB	Page	DIAG WHY RIGHT SEAT BELT WONT UNLATCH BUCKLE IS BROKEN REPLACE RIGHT FRONT SEAT BELT ASSEMBLY	
MONARCH 8480151	5823800 6R02	1L7Z	78812518	AAC	Page		
NORTH B 14148001	4234580 6R02	1L7Z	7881203	CAC	Drvr	REPLACED THE SEAT BELT BUCKLE	
MAGIC PO 2828861	2588800 6R02	1L7Z	7881203	CAB	Drvr	SEAT BELT CHIME	REPLACE DRIVER BELT ASSY
BILL BRAN 730251	8343631 6R02	1L7Z	7881203	CAB	Drvr	SEAT BELT	REPLACED SEAT BELT BUCKLE
PERFORM 1832058	2874111 6R02	1L7Z	7881203	CAA	Drvr	10183 BELL RINGS FRM SEAT BELT BUCKLE ON DRIVERS SEAT SS	
BLUE SPR 4649938	2884450 6R02	1L3Z	18812818	AAA	Page	4811 INSTALL SEAT BELT NBS TEST NO CODE PINPOINT TEST, REPLACED SEAT BELT BUCKLE WIRING SHORTED TO SEAT TRACK M TIME IS FOR REPLACING BUCKLE	
RANCHO 1 80481402	8081302 6R02	1L7Z	7881203	CAC	Drvr	SEAT BELT PRETENSIONER BAD	MT TIME NBS TEST PID
WARREN 3917861	4884306 6R02	1L7Z	7881203	CAA	Drvr	MONITOR R & R DRIVERS SEAT BELT BUCKLE	
MAC HAIR 188248D	8328000 6R02	F85Z	7881202	B8C	Page	4888 81202,01 BROKEN R R PASS FRONT SEAT REPLACED PASS SEAT BELT BUCKLE TEST,OK	
COURTES 8848851	9222700 6R02	1L7Z	7881203	CAA	Drvr	SEATBELT	SEATBELT ASSEMBLY FRONT REPLACE
LEO KAYT 8087851	8881132 6R02	1L7Z	7881203	CAA	Drvr	SEAT BELT ALRM INTERMITTENT	AIR BAG RESTRAINT SYSTEM DIAGNOSIS
OJK FORI 8797801	8234806 6R02	F85Z	78812818	CCC	Page	REPLACE PASS SIDE SEAT BELT BUCKLE HAD TO SWITCH CENTRE BUCKLE OVER TO WORK IN NEW BUCKLE ASSEMBLY CHECK OPERATION AFTER REPAIR ALL OJK	
WALKER F 8088201	8383873 6R02	F85Z	7881203	B8D	Drvr	10484 MO 84 BUCKEL ELECT CK AND REPL DRIVERS SEAT BELT BUCKEL AND RECK	
SAMES MI 8377885	7214760 6R02	YL1Z	78812818	AAA	Page	3841 SEZAT BELT BUCKLE BROKEN 01 WRT PERFORMED VERIFIED CONCERN AND PERFORMED REMOVED AND REPLACE SEAT BELT BUCKLE ADMP PART ORDERED	
GULLO FC383173A	7567781 6R02	1L7Z	7881203	CAA	Drvr	215 CC48 MT .6.80 REPLACED L F SEATBELT BUCKLE. RETEST OK	

MASRUSS 343208A	061000	0R02	1L7Z	7881208	CAA	Drvr
ARCENEA 043251	0049721	0R02	1L7Z	7881203	GAB	Drvr
OLATHE F 783335Z	782081	0R02	1L7Z	7881202	BAB	Page
COPPER I 3220851	4821800	0R02	YL1Z	78812815	AAA	Page
FRANK FR 274641	0000981	0R02	F65Z	7881208	BBD	Drvr
ANCIRA E 30280801	7876700	0R02	F64Z	78812815	GCC	Page
MEL CLAY 4833781	0541811	0R02	1L7Z	7881208	CAA	Drvr
LUNDE LI 305328A	2827800	0R02	F65Z	7881203	BBD	Drvr
WISCONSIN 348183A	0029491	0R02	1L7Z	78812818	AAA	Page
LEIF JOHN 31301701	4843711	0R02	1L7Z	7881203	GAB	Drvr
BOB BLU I 5480551	4232580	0R02	1L7Z	7881203	CAA	Drvr
TOM PICO 3073901	0000080	0R02	XL3Z	1881203	AAD	Drvr
SUPERIOR 030325A	7465701	0R02	1L7Z	7881203	CAA	Drvr
TOWN EA 7808780	2708441	0R02	1L7Z	7881202	BAB	Page
BERGE FC 1680801	4871111	0R02	1L7Z	7881202	BAB	Page
JACKY JO 077608A	587808	0R02	1L8Z	18812819	AAA	Drvr
SUPERIOR 318677B	5580111	0R02	1L7Z	7881203	CAA	Drvr
TOWNSH 158115B	7820401	0R02	1L7Z	7881203	CAA	Drvr
FAMIREZ 0287851	4872582	0R02	1L7Z	7881202	BAD	Page

6484 SEAT BELT LAMP FLASHING CHECKED AND VERIFIED SEAT BELT LAMP FLASHING WHEN SEAT BELT WAS LATCHED. PERFORMED NBS HOOKUP. ACCESSED RESTRAINT MODULE AND PERFORMED SELF TESTS. ACCESSED GEM MODULE AND REPLACED FRNT SEAT BELT BUCKLE
48 REPL PASS SIDE SEATBELT BUCKLE
BROKEN LATCH FT BUCKLE SEATBELT ASSEMBLY FRONT
REPLACE
REPALCED SEAT BELT BUCKLE

VERIFIED CONCERN R R SEAT BELT BUCKET TO FIX CONCERN ...

RR SEATBELT INOP
3028 REMOVE REAR SEAT, REPLACE THE SEAT BELT BUCKLES REMOVE FRONT SEATS AND TURN TO THE SIDE, REPLAC E BOTH FRONT SEAT BELT BUCKLES. RIGHT REAR BUCKLE WAS BROKE AND THE REST WERE STICKY
10008 REM AND REP SEAT BELT BUCKLE
BUNDING BUCKLES. RUN BOTH FRONT SEATS TO REPL BOTH SEAT BELT BUCKLES.
REPLACE SEAT BELT BODY CHASSIS ELECTRICAL (BCE) TEST
REPLACE DRIVER SEAT BELT BUCKLE WPI
INSPECTED AND REPLACED DRIVERS SIDE SEATBELT BUCKLE AND RETESTED OK
23841 VERIFY CUSTOMER CONCERN, TIME TO REMOVE PASSENGER SEAT TO GAIN ACCESS. TIME TO REPLACE PASSENGER SIDE SEAT BELT BUCKLE
CCC 288 RIGHT FRONT SEAT BELT WONT LATCH, REMOVED SEAT REPLACED BUCKLE FOR BEING BROKEN, WORKING PROPERLY AFTER REPAIRS.

FOUND DRIVERS SEATBELT BUCKLE INTERMITTENTLY OPEN AND 788 BUCKLE TO CORRECT, RETEST OK
16388 REMOVED CENTER CONSOLE REMOVED DRIVER SIDE BUCKLE PART THAT ON ORDER WAS D88. INSTALLED RECALL BUCKLE WE HAD IN STOCK WIRE ON RECALL. UPDATED BUCKLE WAS 1 IN LONGER. SHORTENED WIRE AND RETEST

D PERFORMED SELF TESTS. FOUND NO DTCS PRESENT. PERFORMED VISUAL INSPECTION TO WIRING, CONNECT D88 AND SETA BELT SWITCH. DUE TO TIME CONSTRAINTS, PROBABLE CAUSE AND CUSTOMER

ED OK.

R & R BOTH FRONT SEAT BELT BUCKLES
VERIFY CONCERN PASSENGER SIDE BUCKLE WONT LATCH
REPLACED BUCKLE BUCKET SEAT TYPE WITH 81R VERIFY REPAIR OK THIS TIME

PHIL WHIT	0147002	4740000 0F02	F05Z	70012010	CCC	Pagr	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE 11124 CHECK AND CONFIRM ORDER SEAT BELT ASSY. INSTALLED NEW SEAT BELT BUCKLE, TESTED ALL OK.
DITSCHM	0010600	7022073 0F02	1L7Z	70012010	AAA	Pagr	3744 REPLACE PASS SIDE SEAT BELT AREA REMOVE SEAT TO ACCESS ANCHOR BOLT INSTALL AND TEST OK
DITSCHM	073000A	7023073 0F02	YL1Z	70012010	AAA	Pagr	1 REPLACED DRIVER'S SEATBELT INOP CHIMING
BOLTON F	11110001	4740070 0F02	1L7Z	70012003	BAA	Drvr	BUCKLE SEATBELT ASSEMBLY FRONT REPLACE SEAT BELT BUCKLE
GENE EV	2072001	0040001 0F02	1L7Z	70012003	CAA	Drvr	REPLACED SEATBELT BUCKLE
CALVIN F	400401	2073003 0F02	F05Z	70012010	CCC	Pagr	
NORTH F	35007102	0410041 0F02	1L7Z	70012010	AAO	Pagr	REPLACED BROKEN RIGHT FRONT SEAT BELT BUCKLE ASSY
BILL COLL	20000002	4000000 0F02	1L7Z	70012010	AAC	Pagr	REPL RIGHT FRT SEAT BELT BUCKLE RT SEAT BELT PRETENS. NOT CONNECTING, CONNECT RT SEAT BELT PRETENSION NOT CONNECTED, CONNECT & CLEAN
MIKE KEH	0730001	0044444 0F02	*	10012010	"	Pagr	REPLACE SEAT BELT BUCKLE.
NORTH CI	00300001	0010401 0F02	1L7Z	70012002	BAB	Pagr	RECALL 01021
GAUPIN F	0007001	7070000 0F02	1L3Z	10012010	AAF	Drvr	
JACKY W.	0000001	0000100 0F02	1L7Z	70012003	CAC	Drvr	REMOVED SEAT BELTS REINSTALLED SEAT BELTS
BLACKWE	0110701	0720000 0F02	1L3Z	10012010	AAO	Drvr	1 1 REPLACED BOTH FRONT SEATBELTS.
GATOR F	074040A	0000073 0F02	1L3Z	10012010	AAB	Pagr	27 TECH 22 REPLACED PASSENGER SIDE FRONT SEAT BELT
JENKINS /	070000A	0470000 0F02	1L3Z	10012010	AAB	Drvr	
KOKOMO	4000401	4000111 0F02	1L3Z	10012010	AAB	Pagr	REPLACED RIGHT FRT SEAT BELT BUCKLE, BUCKLE WOULD NOT LATCH
PRESTON	100040A	0000171 0F02	1L3Z	10012010	AAC	Pagr	24 REPLACE PASS SIDE BELT REMOVED SEATS AND REPLACED SEAT BELT BUCKLES THAT WERE TAKEN OUT OF STOCK UNIT REPLACED BUCKLES IN STOCK UNIT
TRINIDAD	140000A	0000000 0F02	1L3Z	10012010	AAA	Pagr	01021D
JONES FC	0007001	7443311 0F02	1L3Z	10012010	AAF	Drvr	01021D
HERITAGE	0201101	0200110 0F02	1L3Z	10012010	AAO	Pagr	REPLACED RIGHT SEAT BELT BUCKLE PER RECALL. SEAT BELT BUCKLE WOULD NOT LATCH REPLACED RIGHT FRONT SEAT BELT BUCKLE
FINDLAY F	0000002	4001001 0F02	1L3Z	10012010	AAC	Pagr	
RITTENHC	4010002	0000000 0F02	1L3Z	10012010	AAC	Pagr	VERIFY CONCERN REMOVE AND REPLACE INOP ASSY
MIKE DAY	000000A	7000000 0F02	1L3Z	10012003	AAB	Drvr	VERIFY CONCERN. RAN DRIVERS SEAT, REPLACE BUCKLE.
MIKE BAS	0700400	0000001 0F02	*	10012002	"	Pagr	COMPLETE RECALL
HERITAGE	0000001	0000110 0F02	1L3Z	10012010	AAF	Drvr	SEAT BELT RECALL REPLACED LEFT SEAT BELT BUCKLE INSPECTED AND TESTED SEAT BELT BUCKLES PER RECALL.
HERITAGE	0000001	0000110 0F02	1L3Z	10012010	AAF	Drvr	REPLACED LEFT SEAT BELT BUCKLE PER RECALL.
MIKE SHA	0044400	7770070 0F02	1L3Z	10012003	BAA	Drvr	REPLACE BUCKLE
MIKE BAS	0700400	0000001 0F02	*	10012002	"	Pagr	COMPLETE RECALL
LEF JOHN	04070001	0100000 0F02	1L3Z	10012003	AAA	Drvr	REPLACED SEAT BELT
MANGOLF	2100001	4070000 0F02	1L7Z	70012010	AAA	Pagr	VERIFIED CONCERN REPLACED BUCKLE CHECKS GOOD.
DEAN ARE	0070701	0401000 0F02	F05Z	70012010	DDO	Pagr	HAD TO REPLACE BOTH FRT SEAT BELTS TO FIX 42
CHUCK BF	0104101	7404111 0F02	*	70012003	"	Drvr	RH SEAT BELT ASSY AND REPAIR

VILLAGE F 082708A	6742065 6F02	1L3Z	1681203	BAB	Drvr
AKINS FCI 847865	8679136 6F02	1L3Z	1581203	AAB	Drvr
LANCHES 12267801	9835848 6F02	1L3Z	1581202	AAD	Pagr
EAST BAY 102053AA	2724400 6F02	1L3Z	1581203	AAC	Drvr
BELL, FOR 6080802	8861778 6F02	1L3Z	15812818	AAC	Pagr
LATHAM I 6368004	7884161 6F02	YL3Z	1581202	AAC	Pagr
WASHING 1614881	2226100 6F02	1L3Z	15812816	AAA	Pagr
MIKE BAS 8798350	8848881 6F02	"	1581202	"	Pagr
BLUEBON 18844801	8088011 6F02	1L3Z	15812816	AAF	Drvr
SUNRISE 620345A	8204401 6F02	1L3Z	15812816	AAB	Pagr
MIKE BAS 8619880	8848881 6F02	"	1581202	"	Pagr
ADA FORI 070034A	3328161 6F02	1L3Z	1581203	AAB	Drvr
HOLMES 1 28082801	2823000 6F02	1L3Z	15812816	AAF	Drvr
JACK MAC 1810828	7884800 6F02	1L3Z	15812818	AAF	Drvr
BOB SCH 200223A	4728163 6F02	1L3Z	15812816	AAB	Pagr
WRAY FCI 2644101	8867800 6F02	1L3Z	15812816	AAD	Drvr
BORMAN I 27480401	2264600 6F02	1L3Z	15812816	AAC	Pagr
TIMBERLA 11740003	2734484 6F02	1L3Z	15812816	AAB	Pagr
TIMBERLA 11882203	2734484 6F02	1L3Z	15812816	AAB	Pagr
MIDWAY F 121806A	5823816 6F02	1L3Z	1581203	AAB	Drvr
JACK POY 030888A	3251301 6F02	1L3Z	1581203	AAC	Drvr
GARSON F032012A	3573154 6F02	1L3Z	15812816	AAC	Pagr
DON JEN# 8873801	8822228 6F02	1L3Z	15812816	AAF	Drvr
PRESTON 178387B	6737171 6F02	1L3Z	15812816	AAF	Drvr
YOUNG P 25810802	8882588 6F02	1L3Z	15812816	AAF	Drvr
COVERT F 3288801	3484343 6F02	1C3Z	2881202	CAA	Drvr
MARSHAL 4878402	8783873 6F02	YC3Z	7881202	AAA	Pagr
TULSA AU 81887102	2508600 6F02	1C3Z	2581203	CAA	Drvr

CHECK CONCERN AND FOUND DRIVERS SEAT BELT RECEPACLE BAD,ORDER PART,INSTALL NEW SEATBELT RECEPACLE AND VERIFY OPERATION.

BUCKLE WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE

R R PASSENGER FRONT SEAT BELT. LATCH WAS BAD.

TT J 8170448 REPLACED PASSENGER SIDE SEAT BELT PERFORMED TESTING FOUND PRE TENSIONERS BAD REMOVED FROM ANOT HER STOCK UNIT AND INSTALLED NEW SEAT BELT BUCKLES OK NOW
TECH 148 VERIFIED AND REPLACED SEAT BELT RECHECKED OPERATION
COMPLETE RECALL

4434 41 81172A 0.7 8857 REPLACED RT. SEATBELT BUCKLE ASSY;
QO CHECK BY TECH
RECALL 01821 COMPLETED
REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE

REPLACED SEAT BELT RETENTIONER
INSPECT AND REPLACE BOTH SEAT BELT BUCKLES
FAULTY SEAT BELT BUCKLE REPLACED PASSENGER SIDE SEAT BELT BUCKLE

REPLACED LEFT SIDE LAP BELT WOOD NOT LATCH PARTS
NUMBER 812816 AAD
REMOVED DRIVER SIDE BELT FOR COMPLETION, INSTALLE NEW PASSENGER SIDE SEAT BELT. INSTALLED DRIVER SIDE SEAT BELT THAT WAS BROKEN
FOUND BUCKLE NOT CATCHING. R AND R.PASS SIDE BUCKLE TO CORRECT,READY,

. COMPLETED INSTALLATION OF SPECIAL ORDERED PART AS REQUESTED.

INSTALL AND REPLACED DRIVER SIDE SEAT BELT
DRIVERS SIDE SEAT BELT DOES NOT RECOIL IT HAD TO BE REPLACED

REPLACE MIDDLE SEAT BELT BUCKLE
REPLACE LEFT SEAT BELT WOULD NOT RELEASE ONCE IT WAS BUCKLED WITHOUT EXTREME DIFFICULTY

28378 WARR CHECK FOR LEFT SEAT BUCKLE WONT LOCK R/R
AND REPLACE LEFT SEAT BELT BUCKLE RECHECK OK
PERFORM TEST REPLACE BUCKLE AND SEAT BELT

SEAT BELT LATCH REPLACE LATCH
SEAT BELT LATCH BROKEN, REPLACE RIGHT FRONT SEAT BELT BUCKLE

SEAT BELT BUCKLE LATCH BINDING REPLACED LF SEAT BELT BUCKLE LATCH,OK OPER,OK,QQ,DD

MERIDIAN	803881	8884403	8R02	1C3Z	2581203	CAD	Drv
GOSCH R	24784301	8883181	8R02	1C3Z	2581203	CAC	Drv
KEN GRO	8078853	4888171	8R02	1C3Z	2581203	CAA	Drv
VACAVILL	10301002	4887111	8R02	1C3Z	2581203	CAA	Drv
CHARLIE	1280880	3714800	8R02	1C3Z	2581203	BAA	Drv
KEMP FOX	7910861	8888120	8R02	1L7Z	7881202	AAA	Page
JOHNSON	450182E	7888288	8R02	1C3Z	2581203	CAA	Drv
RANDHO I	88057702	8881308	8R02	1L7Z	7881202	AAA	Page
FORD COI	1288851	8882878	8R02	1C3Z	2581203	CAA	Drv
APPEL FO	8170801	8883888	8R02	1C3Z	2581203	BAD	Drv
QENTURY	147882E	8818882	8R02	1C3Z	2581203	CAA	Drv
RON-CAR	0188888	8818111	8R02	1C3Z	2581203	CAA	Drv
GALPIN FK	8188442	7872800	8R02	1C3Z	2581203	CAA	Drv
EASTWAY	480451	8882881	8R02	1L7Z	7881202	AAA	Page
SJ BURBA	3842102	8888811	8R02	1C3Z	2581203	CAA	Drv
BOZARD F	8888801	8241841	8R02	1C3Z	2581203	CAA	Drv
BOWDEN	088881A	8848841	8R02	1C3Z	2581203	CAA	Drv
ABLE FOR	1414040	7880700	8R02	1C3Z	2581203	CAA	Drv
GALPIN FK	8072821	7872800	8R02	1C3Z	2581203	CAA	Drv
HARPER I	2888101	4887311	8R02	1C3Z	2581203	CAA	Drv
BROWN-C	4844881	7888800	8R02	1C3Z	2581203	CAA	Drv
MALOUF F	208883A	8810800	8R02	1L7Z	7881202	AA0	Page
YOUNG R	23880401	8882588	8R02	1C3Z	2581203	CAA	Drv
MOSSY FK	8081881	2788100	8R02	1C3Z	2581203	CAA	Drv
SANDERS	2883801	4881811	8R02	1C3Z	2581203	CAD	Drv

SEAT BELT BUCKLE REPLACED DRIVER SIDE SEAT BELT BUCKLE

SEATBELT BUCKLE JAMMED REPLACE BELT BUCKLE
SEAT BELT BUCKLE WILL NOT LATCH. VERIFIED CONCERN
REPLACED SEAT BELT LATCH RECHECKED OK.
REPLACED SEAT BELT BUCKLE

61 SEATBELT ASSEMBLY FRONT REPLACE

REPLACED DRIVERS SIDE BUCKLE
SEAT BELT DEFECTIVE. REP PASS BELT BUCKLE

VERIFY CONCERN. REMOVE SEAT TO ACCESS BUCKLE. REPLACE BUCKLE AND REINSTALL SEAT. DC CHECK, OPERATES PROPERLY.

1 REPLACED LEFT FRONT BUCKLE
DRIVER SEAT BELT WILL NOT LATCH PROPERLY REPLACE DRIVER SEAT BELT BUCKLE

488 DRIVER SIDE FRONT SEAT BELT BUCKLE NOT LATCHING
REPLACE DRIVER FRONT SEAT BELT BUCKLE AND TEST OK.
00888 REPLACED DRIVERS SEAT BELT
CHECK FOR LATCH OPERATION FOUND SEATBELT LATCH WITH FAULTY LATCH NEC TO REPLACE SEAT BELT LATCH ON PASSENGER SIDE

REPLACED BELT ASSY

REPLACED DRIVER SEAT BELT BUCKLE

REPLACE LEFT FRONT SEAT BELT

8881 REPLACED SEAT BELT BUCKLE
SEATBELT WILL NOT LATCH PROPERLY REPLACE SEATBELT

SEAT BELT DEFECTIVE INSTALLED SEAT BELT
NOP REPAIR HARNESS PINCHED BETWEEN HEATER BOX AND INSTRUMENT PANEL REMOVE AND INSTALL RADIO ACCESS INSTRUMENT PANEL PULL WIRE OUT REMOVE GLOVE BOX AND GEM

107 HOOKED UP NGS AND GOT CODE B1886 FROM PCM MODULE PERFORMED PINPOINT TESTS AND FOUND PASS SEATBELT PRETENSIONER BAD REMOVED B PILLAR MOUNTING AND REPLACED PRETENSIONER ASSEMBLY RETESTED AND CODE GONE
REPLACE BOTH FRONT SEAT BELT BUCKLES
OPEN IN SEAT BELT SWITCH REMOVE AND REPLACED SEAT BELT BUCKLE.
FOR BUCKLE JAMMED REPLACE BUCKLE ASSEMBLY

MIKE HAU	14088001	3431600	6R02	10SZ	2501203	DAA	Drvr	1 NO TIME LISTED NGS PULLED RCM CODES, B1677, RUN ELEC PP TEST E, TRACED TO DRIVER SEAT BELT PRETENSIONER, REMOVED DRIVER POWER SEAT
SUPERBOI	0674802	8300800	6R02	1W7Z	5481202	AAC	Unknown	VERIFIED CONCERN, R&R PASSENGER SEAT, REPLACED BUCKLE. 11548 FOUND LEFT FRT BUCKLE TO BE BROKEN AND SEAT BELT WOULD NOT INSERT, R&R FRT SEAT AND REPLACE BELT BUCKLE.
FREEDOM 280411A	6832671	6R02	1W7Z	5481202	AAC	Unknown	Unknown	POWER SEATS, LEATHER TRIM DRIVER SEAT BELT WONT LATCH, BUCKLE DEFECTIVE, REPLACED BUCKLE
BUDGET F	305401 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	BUCKLE DEFECTIVE RR BELT ASSEMBLY
BUDGET F	318021 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	1 1 REPLACE THE DEFECTIVE SEAT BELT BUCKLE
BAY STAT	6022201	6727800	6R02	1W7Z	5481202	AAB	Unknown	PASS SEATBELT BUCKLE WONT LATCH, BUCKLE DEFECTIVE, RR BELT BUCKLE
BUDGET F	322011 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	6310 61202,CC 42 VERIFIED DRIVERS SIDR FRONT SEAT BELT BUCKLE INOP,REPLACED LEFT FRONT SEAT BELT BUCKLE,OK NO W
BRIGHTON	134187A	2271171	6R02	1W7Z	5481202	AAB	Unknown	REPLACED THE SEATBELT BUCKLE
HERTZ RA	58700701 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	DEFECTIVE BUCKLE, RR BUCKLE
BUDGET F	201621 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	INTERNAL FAILURE WILL NOT LOCK. REPL DS BUCKLE
BUDGET F	7907361 *	6R02	1W7Z	5481202	AAB	Unknown	Unknown	BUCKEL DEFECTIVE RR BELT ASSEMBLY
BUDGET F	3241001 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	REPLACED D SIDE BUCKLE
HERTZ RA	40151801 *	6R02	1W12	5481202	AAB	Unknown	Unknown	DRIVER SEAT BELT WONT LATCH BUCKLE WONT LATCH REPLACED BUCKLE
BUDGET F	270401 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	6710 61202, 41 MTR1202 0.9 CHECK AND R I RIGHT FRONT SEAT AND REPLACE SEATBELT BUCKLE
TEKAN LI	143680B	6004000	6R02	1W7Z	5481202	AAC	Unknown	REPLACED SEATBELT BUCKLE
BEAMAN I	8408681	3838000	6R02	1W7Z	5481202	AAC	Unknown	BUCKLE FAILURE INTERNALLY. REPL
BUDGET F	3540041 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	REPLACE THE BUCKLE
HERTZ RA	64400701 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	2251 DOES NOT OPERATE PROPERLY 42 NONE REPL DRIVERS SEATBELT LATCH ASSY 61202
MARGATE 284318A	6762277	6R02	1W7Z	5481202	AAC	Unknown	Unknown	CHECKED DRIVERS SEAT BELT WONT LATCH, BUCKLE WONT HOLD REPLACED DRIVERS SEAT BELT BUCKLE ASM,WORKS OK NOW. REPLACED SEAT BELT MODULE
CAMPBELL	21405101	5812358	6R02	1W7Z	5481202	AAB	Unknown	REPLACE DRIVERS SEAT BELT LATCH
HERTZ RA	66201201 *	6R02	1W7Z	5481202	AAC	Unknown	Unknown	
MELROSE	8902401 *	6R02	1W7Z	5481202	AAD	Unknown	Unknown	
DANA MO'	7008951	6038700	6R02	1W7Z	5481202	AAB	Unknown	INOP M TIME TO REPLACE SEAT BLET CLASP FOUND INTERNAL FAULT IN SEATBELT ASSEMBLY REPLACED DRIVERS SEAT BELT
EASTSIDE	21417202	3602800	6R02	1W7Z	5481202	AAC	Unknown	REPLACE LEFT FRT BELT BUCKLE. (IMPROPER OPERATION)
COUNTRY	132923A	3484300	6R02	1W7Z	5481202	AAC	Unknown	REPL SEATBELT BUCKLE MT TIME
MURPHY I	3292201	4848000	6R02	1W7Z	5481202	AAB	Unknown	
ISLAND LI	434851	4328220	6R02	1W7Z	5481202	AAB	Unknown	RT FRT SEAT BELT WONT LATCH REPLACE SEAT BELT BUCKEL
WOOD MC	086680A	4521130	6R02	1W7Z	5481202	AAD	Unknown	SEAT BELT BUCKLE WILL NOT FASTEN REPLACED LEFT FRT BELT LATCH BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
METRO FC	3082861	5411000	6R02	1W7Z	5481202	AAC	Unknown	

CRUICKR 10002001	2448481	6R02	1W7Z	5481202	AAD	Unknown	REPLACE LF SEAT BELT @1172A (2-7 HR8) LF SEAT BELT BUCKLE INOP TO CONNECT @1202 42
MKE PRJ 210000A	2242573	6R02	1W7Z	5481202	AAC	Unknown	REPLACED SEAT BELT BUCKLE BECAUSE OLD ONE WOULD OT LATCH
CAREY PJ 0007751	0670000	6R02	1W7Z	5481202	AAC	Unknown	REMOVE INSPECT AND REPLACE D S SEAT BELT BUCKLE
LIBERTYV 20430001	2671700	6R02	1W7Z	5481202	AAD	Unknown	REPLACE FAULTY DRIVERS SIDE SEAT BELT BUCKLE
SPRINGR 10043001	7870000	6R02	1W7Z	5481202	AAB	Pagr	1 REMOVED PASSENGER SEAT AND REPLACED SEAT BELT RECEPICLE. TECH 32189.
DAYTONA 089184A	2550412	6R02	1W7Z	5481202	AAD	Drv	REPLACED LEFT FRONT SEATBELT BUCKLE ASSY
QUALITY I 5588702	0912204	6R02	1W7Z	5481202	AAC	Drv	CHECKED SEAT BELT BUCKLE, REPLACED SEAT BELT BUCKLE LOOSE
LUMBERT 15051	7805261	6R02	1W7Z	5481202	AAB	Drv	CHECK AND REPLACE DRIVERS SEATBELT BUCKLE
JM SUPK 0003451	2023000	6R02	1W7Z	5481202	AAC	Pagr	BUCKLE
FAIRWAY 2152400	2425000	6R02	1W7Z	5481202	AAD	Pagr	N TIME. REPLACE RIGHT FRN BELT BUCKLE
PALM BEP310000A	0830000	6R02	1W7Z	5481202	AAD	Drv	OK AND REPLACED FRN SEATBELT ASSY, RECHECKED
NORTH FL 4758732	7770000	6R02	1W7Z	5481202	AAB	Pagr	3004 01 5481202 WF TESTED DRIVERS SIDE SEAT BELT BUCKLE. LATCH WOULD NOT HOLD. RFR DRIVERS SEAT TO REPLACE SEAT BUCKLE. NOTE THIS VEHICLE IS A POLICE CAR AND HAD A PETITION BEHIND DRIVER'S SEAT.
WV OBMA 0001051	7251108	6R02	1W7Z	5481202	AAD	Both	42 WILL NOT CATCH
OGALA LI 0047051	7323000	6R02	1W7Z	5481202	AAD	Both	REPLACED R S SEAT BELT BUCKLE
CROSSRC 5811401	7831371	6R02	1W7Z	5481202	AAD	Unknown	INSPECT SEAT BELTS CAN NOT VERIFY CONCERN PWR 00M MAG BILL L.
HERTZ RA 21720001		6R02	1W7Z	5481202	AAC	Unknown	FOR CUSTM SATISFACTION REPLACED DRIVERS SEAT BELT BUCKLE
MILT TAYL 4018001	0532001	6R02	1W7Z	5481202	AAC	Unknown	101 0041
GATE CIT 10043000	2740100	6R02	1W7Z	5481202	AAD	Unknown	REPLACED BOTH SEAT BUCKLES
HERTZ RA 50032001		6R02	1W7Z	5481202	AAB	Unknown	BEAT BELT BUCKLE WDS TEST, REMOVE AND REPLACE SEAT BELT BUCKLE
HERTZ RA 52205101		6R02	1W7Z	5481202	AAB	Unknown	REPLACED DRIVER BUCKLE
BAY STAT 5070001	0727000	6R02	1W7Z	5481202	AAB	Unknown	WDS TEST CHECKED PCM MODULE CODE B8432 REPLACED
HERTZ RA 00003101		6R02		5481202		Unknown	DRIVERS SEATBELT BUCKLE
LOWMOU 2201404	0733000	6R02		5481202		Unknown	REPLACED THE SEAT BELT
JIM CLICK 33304401	0707000	6R02		5481202		Unknown	REPLACED THE BUCKLE
HERTZ RA 47000001		6R02	1W7Z	5481202	AAB	Unknown	1 TESTED AND FOUND TO BE INOP RFR LF BELT LATCH.
HERTZ RA 40000001		6R02		5481202		Unknown	RESECURED PIN INTO CONNECTOR
MCGARIT 10230001	0673513	6R02	1W7Z	5481202	AAC	Unknown	CODE B8438 SEAT BELT BUCKLE LOOSE CONNECTOR TO PASS
COON RA 12022001	4220000	6R02	1W7Z	5481202	AAB	Unknown	SEAT BELT TIGHTEN CONNECTOR RETEST
							CHECK AIR BAG LIGHT. MSB TEST. RETRIEVE DTC. B2438 & CLEAR C CODE. ON DEMAND TEST & SAME DTC & MONITOR PID & PINPOINT RECONNECT & RESECURE CONNECTION. SYSTEM PASS
							REPLACED THE BUCKLE
							REINSTALLD WIRE CONNECTOR
							INSPECT REPLACED FRONT SEAT BELTS
							CP 5481202;CC 26;CCC 230 AIR BAG RESTRAINT SYSTEM
							DIAGNOSIS REPLACED RIGHT FRONT SEAT BELT BUCKLE.

ALBUQUE 3301801	2802200	6R02	1W7Z	5481202	AAC	Unknown
HERTZ RA 64881801 *		6R02	1W7Z	5481202	AAA	Unknown
BUDGET F 08684001 *		6R02	1W7Z	5481202	AAC	Unknown
HERTZ RA 67188801 *		6R02	1W7Z	5481202	AAB	Unknown
BUDGET F 7775871 *		6R02	1W7Z	5481202	AAE	Unknown
GEORGE I 040005A	2294951	6R02	*	5481202	*	Unknown
GANLEY L 065283A	8458000	6R02	1W7Z	5481202	AAC	Unknown
MAPLECR 8488001 *		6R02	1W7Z	5481202	AAC	Unknown
PARIS FOI 8887102	7842888	6R02	1W7Z	5481202	AAB	Unknown
BUDGET F 83525001 *		6R02	1W7Z	5481202	AAC	Unknown
CERRITO I 10188301	8865025	6R02	1W7Z	5481202	AA5	Unknown
GANLEY L 061745A	8458000	6R02	1W7Z	5481202	AAC	Unknown
STU EVAN 48041401	4254300	6R02	*	5481202	*	Unknown
MARSHAL 0801428	8851880	6R02	1W7Z	5481202	AAB	Unknown
BUDGET F 80028401 *		6R02	1W7Z	5481202	AAC	Unknown
SPARTAN 23788301	0881845	6R02	1W7Z	5481202	AAB	Unknown
ROUTE 1 I 11887101	8152580	6R02	1W7Z	5481202	AAB	Unknown
HERTZ RA 43880301 *		6R02	*	5481202	*	Unknown
PFEIFFER 7318231	8487800	6R02	1W7Z	5481202	AAC	Unknown
WHITE BE 259124A	4832831	6R02	1W7Z	5481202	AAD	Unknown

STICKING REPLACED LEFT FRONT SEAT BELT BUCKLE THAT WAS STICKING AND WOULD NOT ALLOW BELT TO FASTEN. INSTALLED NEW DRIVERS BELT BUCKLE R AND R BUCKLE WPI
 REPLAC DRIVERS SEAT BELT BUCKLE
 WDS CAME UP WITH CODE B8432 DRIVERS BUCKLE CHECKED WIRES REPLACED BUCKLE
 INSPECTED RHP RP SEAT TO READJUST SEAT BELT BUCKLE TO CORRECT POSITION (TURNED AROUND) RECHECK.
 44 VERIFIED CONCERN PERFORMED AIR BAG DIAGNOSTICS FOUND DTC B8438 PERFORMED PINPOINT TESTS REPLACED DEFECTIVE PASSENGERS FRONT SEAT BUCKLE ASSY CLEAR CODES & RETEST OK
 1 PERFORM DIAGNOSIS ON AIR BAGS REPLACE SEAT BELT BUCKLE
 USE NGS CHECK CODES FIND DTC B2432 DRIVER SIDE SEAT BELT GO THROUGH MANUAL PINPOINT TEST FIND SEAT BELT BUCKLE BAD REPLACE BUCKLE (MT NO LABOR) CP
 REPL. FRON SEAT BELT. WPI
 81282 RF SEATBELT BUCKLE SWITCH, NOT OPERATING PROPERLY CC42 BICE TEST DTC B8438 HARD FAULT. PERFORM AIRBAG SYSTEM DIAG NOISS. PINPOINT TEST TO INTERNAL FAILURE IN RT FRT PASS

K OPEN REMOVED SEATS AND CARPET TRACED AND REPAIRED OPEN CIRCUIT 1588 APPROX 6 INCHES FROM C810A REASSEMBLE AND RETEST SYSTEM DTC B8438 STILL PRESENT PERFORMED PINPOINT TESTS REPLACED

108 VERIFIED AIR BAG LAMP ON PERFORMED AIR BAG DIAGNOSTICS FOUND HARD FAULTS B8438 AND B8432 DRIVERS AND PASSENGERS SEAT BELT CIRCUITS OPEN PERFORMED PINPOINT TESTS FOUND CIRCUIT 1588 TAN AND BLAC RIGHT FRONT SEATBELT BUCKLE BACKWARDS FROM FACTORY CC42 81282 REMOVE RIGHT FRONT BUCKLE AND REINSTALL CORRECT WAY
 88 PERFORMED PIN POINT TEST AND REPLACED LFT FRT SEATBELT BUCKLE CC 42
 CLOSED AT ALL TIMES ORDERS PART REMOVE SEAT DB R R SEAT BELT BUCKLE
 DIAG TEST 8438 62 PIN POINT TEST TIME TO TRACE HARNESS TO RF SEAT BELT SWITCH REPLACE SWITCH OPEN 38 TIME TO REPLACED SEATBELT BUCKLE THAT WA JAMMED
 SECURED HARNESS TO CONNECTOR
 DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
 38 AIR BAG DIAGNOSTICS. TRACED WIRING AND FOUND DRIVERS SEAT BELT BUCKLE SWITCH FAULTY. REPLACED SEAT BELT BUCKLE AND RETESTED.