

**RQ04-011**  
**FORD**  
**APRIL 26, 2005**  
**REQUEST 8**  
**PART 4 OF 6**  
**BOOKS 27 OF 43**

1114 41 INSPECTED & FOUND DRIVERS SEAT BELT LATCH CATCH SPRING & WILL NOT HOLD PROPERLY. NCC TO REPLACE LATCH ASSEMBLY. SYSTEM OK.

QUICK COOLER PERFORMED REPAIRS, RECONNECT PASSENGER SEAT BELT CONNECTOR.

MANUFACTURER RECALL SEATBELT INSPECTION

MANUFACTURER RECALL SEATBELT INSPECTION

12784 INSTALL L F SEAT BELT

REPLACED BOTH SEAT BELT BUCKLES

150 01 01302 01333 AIR BAG DIAG OF BUCKLES R R BOTH FT SEATS ACROSS

REPLACED BOTH FT SEAT BELT BUCKLES INOP

CHECKED HARNESSES AND FOUND OPEN IN DRIVERS SEAT BELT BUCKLE

REPLACED BUCKLE AND RETESTED ALL OK

MANUFACTURER RECALL SEATBELT INSPECTION

FT 01332 0148 V.C.C. FOUND DRIVERS SEAT BELT BUCKLE WOULD NOT

RELEASE ALL THE TIME. REPLACED DRIVERS SEAT BELT BUCKLE

REPLACED BOTH FRONT SEAT BELT BUCKLES

TEST BOTH USING NISS DTC 01332 0148 OD AND ODM ACCESS SEAT TO

PIRPOINT TEST BUCKLE OPEN REPLACE LP BUCKLE FINAL TEST AND

CLEAR CODES

CAUSAL 040102 CC 42 CDD 038 TEST AIR BAG SYSTEM AND REPLACE

SEAT BELT CODE 01

TEST & REPLACE SEAT BELT END

TEST & REPAIR LOCK & REPLACE BELT

R AND R PASS SEAT REPLACE SEAT BELT BUCKLE

REPLACE PASS SIDE SEAT BELT BUCKLE

AIR BAG WILL NOT OPERATE DUE TO THE TMM COVER FRONT SEAT BACK

REPLACE

REPLACE FAULTY DRIVERS SIDE SEAT BELT BUCKLE

28 REPAIRED OPEN TO WIRING ON LEFT FT SEAT BELT AIR

BAG LAMP ON

POLICE OFF WITH GAGE BEHIND FRONT SEAT AND HAVE DOUBLE IN

CENTER HOLE TO REMOVE BOTH FRONT SEATS TO REPLACE BELT

LATCHES BY NO LABOR OF

MANUFACTURER RECALL SEATBELT INSPECTION

PRODUCT MODIFICATION REPLACED SEAT BUCKLE AS PER RECALL

SEAT BELT BUCKLE FRONT RIGHT OR LEFT REPLACE

REPLACED BOTH FRONT BUCKLES

DIAGNOSIS AIR BAG RESTRAINT SYSTEM IN TIME TO REPAIR OPEN CIRCUIT

AT SEAT BELT BUCKLE

WDS TEST AND RECEIVED CODE B 2438 PERFORM PIRPOINT TEST AND

FOUND OPEN SEATBELT BUCKLE SWITCH. REMOVE RF SEAT AND REPLACE

PASS SIDE SEAT BELT BUCKLE ASSEMBLY. CLEAR CODES AND RECHECK

OKAY.

ISS BE 01302 01302 DIAG. REMOVED DRIVER SEAT PIRPOINT TEST. REPAIR

CONNECTOR UNDER SEAT AND RETEST. ALL OK.

MANUFACTURER RECALL SEATBELT INSPECTION

REPLACED BOTH FRONT SEAT BELT BUCKLES

1 REPLACE L F SEAT BELT BUCKLE AND REPAIR OPEN WIRE

TRACED CODE 01332 01332 REPLACED LP SEAT BELT BUCKLE

REPLACED BOTH FT SEAT BELT BUCKLES

REPLACE SEAT BELT BUCKLE ON THE DRIVERS SIDE DUE TO WOULD NOT

LATCH.

REPLACE DRIVERS SIDE SEAT BUCKLE

OK IN TIME D.C.S.

REPLACE BELT BUCKLE

X	Other	SAG DIAG DRIVERS SIDE SEAT BELT LATCH STUCKS DOWN	888
X	Other	CUSTOMER STATES AIR BAG LIGHT IS ON.	888
X	Other	SAFETY RECALL 01332	870
X	Other	SAFETY RECALL 01332	870
A	Work Latch	L F SEATBELT WONT BUCKLE	808
A	Work Latch	FRONT SEATBELTS WILL NOT BUCKLE	887
B	Work Stay Latched	ADD ON BAG THE DRIVERS AND THE PASSENGERS FRONT SEAT BELTS WILL NOT STAY LATCHED 01332 01332	713
K	Other	AIRBAG LIGHT IS ON	808
K	Other	SAFETY RECALL 01332	878
K	Other	01332 CUSTOMER STATES CHECK AND ADJUST ON DRIVERS SEAT BELT BUCKLE INOP.	497
A	Work Latch	BOTH FRONT SEATBELTS WILL NOT BUCKLE	881
X	Other	CUSTOMER STATES AIR BAG LIGHT ON	800
X	Other	AIR BAG LIGHT IS ON	410
X	Other	SEAT LIGHT IS ON	806
X	Other	SEAT LIGHT ON	804
X	Other	PASS SIDE SEAT BELT BUCKLE INOP	308
X	Other	RIGHT FRONT SEAT BELT PASS SIDE WONT BUCKLE	226
X	Other	AIR BAG LIGHT ON	708
A	Work Latch	SEAT BELT DONT LATCH, DRIVER SIDE (01332)	847
X	Other	AIR BAG LIGHT ON	616
X	Other	CUST STATES BOTH FRONT SEAT BELTS HARD TO LATCH	800
X	Other	SAFETY RECALL 01332	870
X	Other	RECALL 01332 SEAT BELT BUCKLE	882
X	Other	CHECK THE DRIVERS SEATBELT INOP LIGHT. BUTTON IS PUSHED. PARTS WERE ORDERED AND ARE IN.	708
A	Work Latch	BOTH FRONT SEATBELTS WILL NOT BUCKLE	881
X	Other	AIR BAG LIGHT BURNED	357
X	Other	AIRBAG LIGHT IS ON	381
X	Other	SAG CUSTOMER STATES AIR BAG LIGHT IS ON	818
X	Other	SAFETY RECALL 01332	870
A	Work Latch	BOTH FRONT SEATBELTS WILL NOT BUCKLE	881
X	Other	CUST STATES AIRBAG LIGHT ON 18 23 01 4 MILES NO 5888 WINTER FORD	881
X	Other	REPAIR AIR BAG MODULE	808
A	Work Latch	AIR BAG LIGHT ON	381
A	Work Latch	FRONT SEATBELT WILL NOT BUCKLE	813
A	Work Latch	DRIVERS SEAT BELT WONT LATCH	806
A	Work Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH ALL THE TIME	882
X	Other	CUSTOMER STATES LT FT SEAT BELT WILL NOT LATCH IN BUCKLE	415

22 VERIFY CONCERN AIR BAG LIGHT FLASHING CODES SR. USE WDS AND CH BOK FOR CODES, CODE D6480 (PA) AIRBAG SEATBELT BUOYLE CIRCUIT OPEN. REFER TO SERVICE MANUAL FOR PPT INFO, PERFORMED PPT01 PPT	OK, REMOVED AND REPLACED PASSENGER SIDE SEA TBELT BUCKLE. PERFORM ALL TESTS, AND PPT01 SYSTEM WORKED OUT. ALL OK. CC 62 00 PA. PA.						
OK AND REPLACED FRT SEATBELT ASSY. RECHECKED INOP SEATBELT ASSEMBLY FRONT REPLACE		X	Other	AIR BAG WARNING LIGHT TROUBLED	400		
CHECK OUT AIR BAG MONT FLASHES, TEST DRIVE, NOTE AIR BAG LIGHT ON/CONNECT HISS, RUN KORSQ, NOTE DTC B6334, PERFORM PIN POINT TEST IN AIR DRUMS SEAT ASSEMBLY PIN POINT TEST, REPLACE DRIVERS SEAT BELT BUCK	BLE DUE TO INTERNAL SHORT TO GROUND, CLEAR DTC, TEST DRIVE OK	X	Other	OK PASS SIDE FRONT SEAT BELT BUCKLE KEEPS POPPING OUT DRIVER SEAT BELT HOP SOP PART IS HEAR	884 913		
AIR BAG LIGHT FLASHING HISS TEST WIRING DIAG FOUND DRIVER SEAT BELT THROWING CODE ADDRESS DRIVER AND PASS SEAT ADDRESS GARFET CK FOR PINCHED WIRE UNDER SEAT NO WIRING DAMAGE REFL DRIVER SEAT BELT BUCKLE	BECAUSE SHORTED	X	Other	05 AIR BAG LIGHT FLASHES	408		
MANUFACTURER RECALL SEATBELT INSPECTION		X	Other	ABS AIR BAG LIGHT WAS FLASHING READ CODE B1	872		
MANUFACTURER RECALL SEATBELT INSPECTION		X	Other	SAFETY RECALL 01384	570		
78 CC 20,21,42 (PIN WIRE IMPACT CUSTOMERS) CONCERN OF AIR BAG LIGHT FLASHING CHECKED AND MARKED CONCERN, NECESSARY TO RETRIEVE LFD LFC (CODE) RETRIEVE BE NECESSARY TO PERFORM TEST AND RETRIEVE CODES		X	Other	SAFETY RECALL 01384	570		
628 BAD 1282 EVENTU OPERATION AHEAD DIAGNOSIS FLASH CODE B1, DTC 3638 PINPOINT TESTS ADDRESS DRIVERS SEAT TEST HISSING REPLACE SEAT BELT BUCKLE (SHATIC OPERATION CLEAR CODE RETEST CODE PAGE		X	Other	THE AIR BAG LIGHT IS FLASHING CODE B2	618		
DRIVERS SEAT BELT SWITCH INOP AIR BAG RESTRAINT SYSTEM DIAGNOSIS, REPAIR IT REFL SEAT BELT BUCK		X	Other	AIR BAG LITE ON	800		
REPLACE SEAT BELT		X	Other	AIR BAG LIGHT IS ON	878		
104 PERFORMED RECALL 01381 AS REQUIRED, TESTED BOTH SEAT BELTS AND BOTH FAILED, REPLACED BOTH SEAT BELTS IN 81/81 LABOR CP, TECH SET		X	Other	SEAT BELT INOP	806		
INSTALL SEAT BELT		C	Unlatched/Released	836 SEAT BELTS ON BOTH SIDES IN FRONT COME UNLATCHED SOMETIMES	718		
REPLACED DRIVER SIDE SEATBELT BUCKLE DUE TO INTERMITTENT CONCERN 01308		A	Wont Latch	ON DRIVERS SIDE SEAT BELT WILL NOT LATCH	808		
REPLACE SEAT BELT		X	Other	SEAT BELT CHIME AND WARNING LIGHT WILL COME ON WITH BELT BUCKLED AFTTIME..			
CONFIRMED AIR BAG LIGHT IS ON LFC 61 0148 W HISS TEST FROM E BMS8 DRIVERS SEAT BELT OPEN CIRCUIT PERFORMED AIR BAG PINPOINT TEST REPLACED SEAT BELT BUCKLE O.K.		X	Other	AIR BAG LIGHT ON	418		
CHECK DRIVERS SEAT BELT FOUND SEAT BELT DEFECTIVE WILL NOT LATCH REPLACED WITH NEW SEAT BELT ASSEMBLY.		X	Other	CHECK REASON FOR AIR BAG LIGHT FLASHING THEN STAYS ON COMITAN	688		
DRIVERS SEAT BELT WILL NOT LATCH, CHECK AND FOUND SEAT BELT DEFECTIVE REPLACED WITH NEW SEATBELT.		A	Wont Latch	O/S THE DRIVER SEAT BELT WONT LATCH			
VERIFIED REPLACED SEAT BELT		A	Wont Latch	O/S THE L F SEAT BELT WONT LATCH			
01874 REPLACE SEAT BELT IN 821 RECALL		A	Wont Latch	CUSTOMER STATES REFRONT SEAT BELT NOT LOCKING	802		
		X	Other	01882 BAD SEAT BELTS	858		
		X	Other	LEFT SEAT BUCKLE IS NOT WORKING	818		
HOOK UP HISS, RUN SELF TEST ON AIR BAG SYSTEM RUN DCL ON DISPLAY, JUMPER CONTACT ON LEFT FRONT SEAT BELT BUCKLE, REMOVE BUCKLE, SWITCH OPEN R AND R DRIVERS SEAT, REPLACED BUCKLE, CLEAR CODES AND RETEST.		X	Other	AIR BAG WARNING LIGHT TROUBLES	816		
ISSUING VERIFIED CONCERN DIAGNOSED AND REPLACED FAULTY SEAT BELT BUCKLE CHECKED OPERATION CONCERN CORRECTED		X	Other	DRIVERS SEAT BELT BUCKLE INOPER	716		
1 REPLACE RIGHT FRONT SEAT BELT W/ NEW SEAT BELT TO REPLACE BUCKLE		X	Other	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	783		
INOP SEATBELT ASSEMBLY FRONT REPLACE		X	Other	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	718		
INOP SEATBELT ASSEMBLY FRONT REPLACE		X	Other	LEFT SEAT BUCKLE IS NOT WORKING	818		
8 REPLACE ONE SEAT BELT IN BUCKLE BUCKING TESTED SEAT BELT BUCKLE WIREWAS BROKE, RAN SEAT BELT BUCKLE, INB		X	Other	DRIVERS SEAT BELT BUCKLE INOPER	716		
		X	Other	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	783		
		X	Other	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	718		
		X	Other	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	718		
		X	Other	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	410		
		X	Other	SEAT BELT WARNING LAMP COMES ON	708		

AIR BAG CLASH, REPLACE PASSENGER FRONT SEAT BELT & PERFORM RECALL BUSH ON DRIVERSIDE REPL. PNT PASS SEAT BELT BUCKLE BUCKLE	ESD (BUCK TEST) DIAGNOSIS	X	Other	CK FOR AIR BAG LIGHT STAYING ON	618
		X	Other	PERFORM RECALL BUSH	410
		A	Work Latch	PNT PASSENGER SEAT BELT FRONT LK FAILURE SEAT BELT BUCKLE	
		X	Other	REPORTS AIR BAG LIGHT KEEPS FLASHING	305
REMOVE INSPECT AND REPLACE O/S SEAT BELT BUCKLE		A	Work Latch	FRONT DRIVERS SIDE SEAT BELT IS NOT BUCKLING SEAT BELT INDICATOR	778
INSPECT BUCKLE		X	Other	CONTINUES TO DRAG (SAFETY BIBLE)	584
BELT LATCH	RAR LEFT CENTER SEATBELT LATCHES	X	Other	RECALL ON B21 WAS NEW AND WAS NOT YET ON DAME	525
REPL SEAT BELT BUCKLE		X	Other	CUSTOMER STATES CENTER SEAT BELT IN INOPERATIVE	
AIR BAG SYSTEM DIAGNOSIS	REPLACED DEFECTIVE FRONT SEAT (L FRONT) BELT BUCKLE	X	Other	DRY SEAT BELT BUCKLE INOP FAILURE SEAT BELT BUCKLE	
		X	Other		218
		X	Other	CUSTOMER STATES AIR BAG LIGHT ON	018
				PERFORM B1821 RECALL SEATBELT	
RECALL IN B21 SEATBELT PERFORMED 01821 (SEATBELT RECALL					
ISS CODE BASIC SERVICE CK OUT AIR BAG LIGHT ON INITIAL WDS AND CK					
DOORS CODE B2488 REMOVE DASH PANEL TO ACCESS MODUAL PERFORM					
IMPPOINT TEST REMOVE PASSENGER SEAT ASSEMBLY REMOVE SEAT BELT					
RECOVER ASSEMBLY		X	Other	CUSTOMER STATES THE AIR BAG LIGHT IS ON	815
BUCKLE BINDING		X	Other	C/S CAN NOT LATCH DRIVERS SIDE SEATBELT	816
REPLACED SEAT BELT BUCKLE BECAUSE OLD ONE WOULD OT LATCH		A	Work Latch	SEAT BELT DRIVERS SIDE	479
OTC WASH	AIR BAG REPAIRKIT SYSTEM DIAGNOSIS	X	Other	AIR BAG LIGHT KEEPS FLASHING	522
1. REPLACED THE DRIVER SIDE SEAT BELT BUCKLE		X	Other	DRIVERS SEAT BELT WILL NOT UNLATCH AT TIMES, PART DUE IN	888
REPLACE LF SEAT BELT (B1178A) (2 Y WBS) LF SEAT BELT BUCKLE INOP TO				CUSTOMER REPORTS DRIVERS SIDE FRONT SEAT BELT IS INOP, PLUS	
CONNECT B2826 42		A	Work Latch	CHECK F	436
				O/O AIR BAG LIGHT IS ON PANEL WILL NOT DIM WHEN AIR BAG LIGHT IS	
		X	Other	ON	817
		X	Other	RECALL IN B21 WAS NEW AND HAD NOT SHOWN UP ON OASIS	824
		A	Work Latch	CK RIGHT FRONT SEAT BELT WILL NOT LATCH	704
INSPECT BUCKLE					
REPLACED PASSENGER SEAT BELT BUCKLE					
LATCH BINDING	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT				
REPLACE		A	Work Latch	DIAG DRIVER SIDE SEAT BELT FRONT WILL NOT LATCH	822
REPLACED DRIVERS SEATBELT BUCKLE		X	Other	CK DRIVERS SEATBELT INOP	847
OPEN CIRCUIT	AIR BAG REPAIRKIT SYSTEM DIAGNOSIS	X	Other	AIR BAG LIGHT OCCURS ON SOMETIMES	816
REPLACED SEAT BELT LATCH		X	Other	PASS SEAT BELT FRONT SEAT NOT WORKING	781
ESD TEST, PNT POINT TEST, WBS, REPLACE SEAT BELT BUCKLE		X	Other	CK AIR BAG LIGHT IS ON	326
SEAT BELT BUCKLE WILL NOT FASTEN REPLACED LEFT PNT BELT		A	Work Latch	REPAIR LEFT PNT SEATBELT NOT FASTENING PROPERLY UNIT 4891 T8	802
CODE DOES NOT OPERATE PROPERLY MILES IN 2228 MILES OUT 2230					
TESTED DRIVERS SEATBELT BUCKLE FOUND BUCKLE WOULD NOT LATCH					
REPLACED BUCKLE AND RETESTED NOW BUCKLE WORKS PROPERLY		A	Work Latch	226 CK LEFT FRONT SEATBELT BUCKLE FRONT LATCH	284
1 HOUR WIRING CONCERN REMOVED 2 BOLTS THAT HOLD DOWN LEFT					
SIDE OF DRIVERS SIDE SEAT BASE, TIPPED SEAT BASE TO UNPLUG					
WIRING TO SEAT BELT LATCH, AND REMOVED WIRING, REMOVED 1 BOLT					
THAT HOLDS LATCH					
L, RIGHT FRONT SEAT BELT BUCKLE		X	Other	REINSTALLED NEW SEAT	
REPLACED FRONT BU	ONE	A	Work Latch	BELT, REROUTED WIRING	
ESD TEST, MONITOR PNT, PNT POINT TEST, REPLACE L/S SEAT BELT		X	Other	PLUGGED IN, REBOLTED SEAT	
BUCKLE, CLEAR CODE AND PERFORM SELF TEST		X	Other	DOWN, WORKS NORMALLY	
BUCKLE	REPLACED SEATBELT BUCKLE	A	Work Latch	"1, T8	
SEAT BELTS NOT WORKING	MILEAGE ENTERED	X	Other	DRIVERS SIDE SEATBELT INOP. SOP PARTS HERE.	207
IN BRNDR				CUSTOMER STATES DRIVERS FRONT SEAT BUCKLE WILL NOT BUCKLE	841
				NEEDS R BELT	782
REPL RH FT SEAT BELT BUCKLE		X	Other	AIR BAG LITE ON 226 R1	819
				DRIVERSIDE SEATBELT BUCKLE DOES NOT LATCH	727
		X	Other		821
		X	Other	PASS SEAT BELT REEL BUTTON STORING INTERNAL REEL COMPONENT FAILURE	
AIRBAG DIAGMONITOR IP208 REPLACED RIGHT FRONT SEAT BELT BUCKLE					
HIGH RESISTANCE TIGHTENED TERMINALS IN CONNECTOR RETEST		X	Other	AIRBAG LIGHT FLASHES 5 S	483
INOPERATIVE	SEATBELT ASSEMBLY FRONT	A	Work Latch	CUSTOMER STATES DRIVERS FRONT SEAT BELT BUCKLE WILL NOT LATCH	217
REPLACE SEAT BELT BUCKLE		X	Other	SEATBELT DO NOT WORK PROPERLY	382
REPLACE BELT FRONT LATCH		A	Work Latch	SOP SEAT BELT PART	330
BINDING	REPLACED DRIVERS SEAT BELT	X	Other	DRIVER SEAT BELT LATCH INOP	678

POOR CONNECTION AT SEATBELT REPAIR CONNECTION AT SEATBELT	X	Other	CUSTOMER STATES AIR BAG LIGHT WAS FLASHING, NOW IT IS STAYING ON	219
THE BUCKLE CK STUFF GOING INSIDE BUCKLE GET CODES 0 P 129 PER LEFT FRONT SEAT BELT BUCKLE ASSEMBLY W/	X	Other	DRIVER SIDE SEAT BELT WILL NOT HOOK	573
CORD CODE 41 TEST AIR BAG SYSTEM CODE FOR SEAT BELT SYSTEM	X	Other		200
PIPOUNT TO RT FRONT SEAT BELT BUCKLE AND REPLACE SEAT BELT PERFORMED AIR BAG DIAGNOSTIC CODE B220C PERFORMED	X	Other	CUSTOMER STATES AIR BAG LIGHT STAYS ON	600
PIPOUNT TEST TRACED TO AND REPLACED PASSENGER SEAT BELT RETRACTOR	X	Other	CUSTOMER STATES AIR BAG LIGHT STAYS FLASHING AND WILL NOT GO OUT SOMEWAYS	418
NISS AIR BAG TESTS CODE B220C, PIPOUNT TESTS, REPLACED PASS BUCKLE AND PRETENSIONER	X	Other	CUSTOMER STATES AIR BAG LIGHT COMES ON AND FLASHES FOR THE LAST COUPLE OF DAYS	418
NISS AIR BAG DIAG CODE B220C, TEST PASS PRETENSIONER CIRCUITS, REPLACED PASS BUCKLE AND PRETENSIONER/TEST	X	Other		
PUT ON W/DR H/AN TEST CODE B220C PIPOUNT TEST PO UND LEFT FRONT BUCKLE MISSING INSTALLED NEW BLAD BLE PERFORM TEST PASS	X	Other	CHECK AIR BAG LIGHT FLASHING	578
TESTED TO FIND CODE B220C. REPLACED RIGHT SIDE FRONT SEATBELT ASBY. TESTED OKAY	X	Other	AIRBAG LIGHT IS ON	414
REPLACE LEFT FRONT SEAT BELT BUCKLE	A	Wont Latch	CK L FRT SEATBELT WONT HOLD	573
BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS	X	Other	CK AIRBAG LIGHT ON	542
FAULTY LFT FRT. SEAT BELT BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS	X	Other	CHK AIR BAG LIGHT FLASHES	515
DIAGNOSIS AIRBAG SYSTEM PIPOUNT FOUND SMO SENSOR IN BUCKLE ASSEMBLY OF SEAT BELT REPLACED BUCKLE LATCH ASSEMBLY RETEST	X	Other	GS AIR BAG LIGHT ON PWRTR IN	232
W/DR ESC TEST NO LIFE CODE B220C PIPOUNT REPLACE LEFT SIDE W/RT PRETENSIONER	X	Other	RR AIRBAG LIGHT CAME ON & STAYED ON ALL DAY ON WEDNESDAY OF LAST WEEK PLEASE CHECK	218
NOT WORKING PROPERLY BODY CHASSIS ELECTRICAL (BCE) TEST	X	Other	CK CODE WAS PULLED ON 12/14/01 B220C FAILED SEAT BELT BUCKLE	717
REMOVED LF SEAT BELT TO TAKE CARE OF QUIET BURRUPRO VIN # 1M1L2P3 RD # 4 B220C INSTALLED NEW SEAT BELT BUCKLE TEST	X	Other	REMOVE LF SEAT BELT BUCKLE FOR RECALL 81821	553
OPERATION . O.K.	X	Other		
W/DR 41 REMOVE DRIVER SEAT TO REPLACE DRIVER SEATBELT BUCKLE HAS BUCKLE HAS HARNESSE	X	Other	DRIVERS SIDE SETA RECEIVER WOP CODES SOP IS HERE	813
	X	Other	DIAGNOSE AND ADVISE CUSTOMER STATES THAT THE DRIVERS SEAT BELT WILL NOT BUCKLE SHOULDER HARNESSE WILL NOT LOCK INTO BUCKLE	607
PER SEAT BELT BUCKLE NOT LATCHING.	A	Wont Latch	PASSENGER SEAT BELT WONT LATCH	.
REPLACED THE BUCKLE	A	Wont Latch	DRVR SEAT BELT BUCKLE JAMMED	.
REPLACED THE SEAT BELT BUCKLE	X	Other	AIR BAG LIGHT STAY ON	.
OPEN PRETENSOR. REPL BELT AND BUCKLE	X	Other	AIR BAG LIGHT IS ON	778
TEST AIR BAG SYSTEM, PIPOUNT AND FOUND PASS SIDE SEAT BELT	X	Other	R F SEAT BELT BUCKLE WOP	.
REQUIRES REPLACEMENT. ORDER PART, REPLACE AS NED	X	Other	AIR BAG LIGHT ON	.
R AND R BUCKLE WITH NEW	X	Other	AIR BAG LIGHT IS ON	218
REPLACED THE DRIVERS BUCKLE	X	Other	AIR BAG LIGHT ON	.
MT TIME TO CHECK OUT REMOVED AND REPLACE BUCKLE	X	Other		
DRVR SEAT BELT WOP OPEN OKT. REPL	X	Other		
ROAD TESTED VEH VERIFIED CORCORAN, PERFORMED NISS DIAG	X	Other	SEAT DRIVERS SIDE SEAT BELT BUCKLE RATTLES WHILE DRIVING AND	548
IDENTIFIED PMS, FOUND DRIVERS SEAT BELT BUCKLE SHOWING	X	Other	WHILE DRIVING WITH BELT LATCHED THE CHAIR AND WARNING	
REMOVED DRIVER SEAT, REPLACED SEAT BELT BUCKLE RETEST OKLAS	X	Other	CUSTOMER STATES DRIVERS SEAT BELT SOMETIMES WILL NOT LATCH ON UN	278
DIAGNOSIS, CP 181288	A	Wont Latch	LATCH CHECK ALL SEATBELTS	
VERIFIED CORCORAN FOUND BUCKLE PART NO GOOD JAMMED DRIVERS	X	Other	AIR BAG LIGHT COMES ON SOMETIMES	558
SEAT REPLACE SEAT BELT RETESTED OPERATION ALL OK	A	Wont Latch	DRIVERS SEAT BELT WILL NOT LOCK IN BUCKLE	.
VERIFY, BOAH CHECK, CODES B 220C, DRIVERS SEAT BELT BUCKLE SWITCH	A	Wont Latch	RIGHT FRONT SEAT BELT BUCKLE WILL NOT LATCH	.
OPEN, REPLACE DRIVERS SEAT BELT BUCKLE, CLEAR CODES, TEST DRIVE	A	Wont Latch	PASS SEAT BELT WONT LOCK	.
OK	X	Other		
REPLACED SEAT BELT BUCKLE	A	Wont Latch		
INTERVALA FALT IN BUCKLE INSTALLED NEW BUCKLE ASBY	A	Wont Latch		
FOUND SEAT BELT DIF RR BUCKLE SEAT BELT	A	Wont Latch		
RUN AIR BAG DIAG, RUN PIPOUNT TEST L., TEST AND REPLACE DRIVERS	X	Other	SEAT BELT CHIME NOT SOUNDING ON	578
SEAT BUCKLE, CLEARED CODES RETEST ED OK	X	Other		

REPLACED THE BELTS	X	Other	DRIVER SEAT BELT BUCKLE INOP	
REPLACE SEAT BELT BUCKLE ASSEMBLY	A	Worn Latch	SEAT BELT BUCKLE WONT HOLD	478
TEST FOR CODES REPLACE SEAT BELT BUCKLE	X	Other	AIRBAG LIGHT STAYS ON	478
REPLACED SEAT BELT BUCKLE. TESTED BATT.	X	Other		943
CHECK FOR CAUSE OF AIR BAG LAMP. RUN SYSTEM SELF TEST CODE B94E FOLLOWED PFPONT TEST AND REPLACED THE LF SEAT BELT BUCKLE	X	Other	AIRBAG LIGHT FLASHES WHILE DRIVING	683
VERIFIED NISSAN SEAT BELT BUCKLE. REPLACE BUCKLE L OR AT THE TIME REPLACED LT FRONT SEAT BELT	X	Other	CUSTOMER STATES THAT SEAT BELT IS INOP	833
OPEN CIRCUIT IN LF SEATBELT BUCKBODY CHASSIS ELECTRICAL (ECC) TEST	X	Other	CUSTOMER STATES DRIVER SIDE SEAT BELT MISSING FELT ADVICE	218
OPEN CRT. CLEAR CODE	X	Other	AIR BAG LIGHT ON	608
AIR BAG DIAGNOSIS, CODE 1233, REMOVED AIR BAG MODULE, AND DRIVERS SEAT ASSEMBLY TO PIN POINT TEST DRIVERS SEAT	X	Other	AIR BAG LAMP FLASHER	
REPLACED SEAT BUCKLE	X	Other	AIR BAG LIGHT IS ON	910
GET SEAT BELT LATCH OUT OF SEAT ON ROW 1	X	Other	AIR BAG LIGHT ON	
ISSUE SEAT TEST DRIVERS SEAT WHEN TO QUICKEN R R DRIVER & POWER SEAT. R R TRIM PANEL ON SIDE OF SEAT TO GET ACCESS TO FEMALE END OF SEAT BELT BUCKLE. PO LIND SHORTED WIRE R SEAT BELT BUCKLE. REPLACED	X	Other	SEAT BELT IS BURIED IN SEAT	281
REPLACED DRIVERS SEATBELT BUCKLE	X	Other	CUSTOMER STATED THE SEATBELT LIGHT STAYS ON AFTER SEATBELTS ARE FASTENED	752
PERFORM DIAG FOR SEAT BELT LIGHT COMING ON UNWARRANTED WITH JMS MONITORED PID. REPLACED INOP SEAT BELT. 1	X	Other	CUST STATED DR. FRST SEAT BELT BUCKLE INOP	418
1 REPLACE LEFT FRST SEAT BELT BUCKLE	X	Other	CUSTOMER STATES SEAT BELT LITE CHIRPS AND FLASHES BUT WHEN SEAT IS ON OR WHEN TURNING DRIVERS SEAT	303 814
MSR TEST. RETRIEVE CODES FROM AIR BAG SYSTEM. CODE B 12488. WENT TO PFP. POINT TEST FOUND OPEN CIRCUIT ON DRIVERSIDE SEATBELT BUCKLE. REMOVED SEAT AND REPLACE BUCKLE	X	Other	AIR BAG LIGHT COMING ON SOB	826
R R SEAT BELT BUCKLE ASBY	X	Other	AIR BAG LT FLASHES	
RFR PASSENGER SEAT BELT SWITCH INOP. VERIFIED CONCERN RESTRAINT DIAGNOSIS RETURNED B94E PFP. POINT TEST P REPLACED PASSENGER FRONT SEAT BUCKLE ASSEMBLY AND RETESTED CODE B1	X	Other	AIRBAG LIGHT IS ON.	287
RUN DIAG TEST DRIVERS SEAT BELT RECEIVER SWITCH OPERATION. REPLACE	X	Other	CUSTOMER STATES THE AIR BAG LIGHT IS FLASHING. REPORT	829
ISSUE REMOVE AND REPLACE LT PRT BUCKLE. QUALITY CHECK OK	A	Worn Latch	CRASH TECH. 2188 OWNER STATES LF SEAT BELT BUCKLE DONT LATCH	808
4818 PMS. SIDE SEAT BELT BUCKLE SHORTED 149883 3.5 HRS. WBA 2 HRS .7 HRS 30P	X	Other	ISS CHECK FOR AIR BAG LIGHT ON	872
ISSUE A BAG LIGHT FLASHES CODE B2 140883 01171A A BAG D R. REPLACE PASS SEAT BELT	X	Other	AIR BAG LIGHT ON SOP IN	872
REPLACED SWITCH IN BUCKLE ASSEMBLY. LAMBS	X	Other	INSPECT VEHICLE FOR AIR BAG LIGHT BOUND ON	808
REPLACE BOTH SEAT BELT FOR ENTER. OPER	A	Worn Latch	BOTH FRONT SEAT BELTS LATCHING ENTER.	978
ISSUE B98 88 CHECKED OVER & REPLACED CONNECTOR AT R FRONT SEAT BELT BUCKLE	X	Other	CUST STATES AIR LIGHT IS ON	216
TEST SYSTEM CODES B2488 REMOVE RT FRONT SEAT TO ACCESS AND CHECK CIRCUIT FOR PFP. POINT TEST RT FRONT BUCKLE OPEN CIRCUIT (UNTILL SEAT BELT BUCKLE. CLEAR CODES	X	Other	AIR BAG LIGHT ON S O PART	301
REPLACED THE BUCKLE	X	Other	LATCH BELT BUCKLE SOUNDS	
STRIP GAGE OFF. REPLACED NEW BELT	X	Other	CUSTOMER STATES DRIVERS SIDE SEAT BELT IS MISSING FELT PROTECTOR STRIP	718
INSPECT. RELEASE BUTTON IS STUCK. REPLACE BUCKLE	A	Worn Latch	RT FT SEAT BELT WILL NOT BUCKLE	318
REPLACED THE BUCKLE	A	Worn Latch	DRIVER SEAT BELT WONT FASTEN	
PASS FRST SEAT BELT WONT LATCH. REPL. BUCKLE AND TEST	A	Worn Latch	PASS SIDE SEAT BELT BUCKLE DOES NOT LATCH 80P IN 9088	714
DIAGNOSIS REMOVED AND REPLACED DRIVERS SEATBELT	X	Other	INSTALL S O REPLACEMENT SEAT BELT BUCKLE. THIS IS TO CORRECT AIR BAG LIGHT STAYING ON ALL THE TIME	321
AIR BAG RESTRAINT SYSTEM DIAGNOSIS	X	Other	AIR BAG LIGHT ON	388

14279 UNLCK AIR BAG SYSTEM/PERFORM AIRBAG							
DIAGNOSTICS PERFORM PIN POINT TESTS FOR CODE B843E/REPLACE							
DRIVER SEAT BUCKLE AND REPAIR PINCHED AND CUT WIRE UNDER							
DRIVER SEAT HARNESS MAKE CONTACT	WITH SEAT TRACK 4E 199403	X	Clear	530 CLUST STATES AIRBAG LIGHT STAYS LIT, ADVISE	591		
8276 8 REPLACED BOTTOM BUCKLE		X	Other	CK PASS SIDE FRONT SEAT BELT INCP	491		
8946 BUCKLE STAYS SEAT BELT BUCKLE ON DRIVERS SEAT STRONG AND							
HARD TO GET BELT OUT, REPLACED SEAT BELT BUCKLE 6 WAY POWER							
SEAT		X	Other	CUSTOMER STATES DRIVER SIDE SEAT BELT BUCKLE RELEASE VERY	716		
OPEN CIRCUIT IN BUCKLE, AFTER PINPOINT TEST, REPLACED BUCKLE AND		X	Other	G 3 AIRBAG LIGHT IS ON, LIGHT HAS BEEN ON FOR ABOUT 3 WEEKS	816		
CLEARED AND RETESTED		X	Other	CUSTOMER STATES THE SEAT BELT IS MISSING	718		
REPLACED SEAT BELT		X	Other	DRIVER SIDE SEAT BELT DOES NOT LATCH PROPERLY	848		
REBELT WILL NOT LATCH PROPERLY REPLACE SEATBELT		X	Other	DR. PASS SEAT BELT DOESNT LATCH	673		
REPLACE SEAT BELT ASSEMBLY IF WONT LATCH		A	Wont Latch	RECALL 94281 8 ALL OK	318		
COMPLETE RECALL		R	Recall Performed	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE INOPERATIVE	348		
R AND R DRIVERS SEAT BELT ASSEMBLY		X	Other	AIR BAG LIGHT ON			
INSTALLED SEAT BELT BUCKLE		X	Other	CUSTOMER STATES RESTRAMER LOCKS NOT ATTACH/TECHNICIAN STATES			
				LOCK FRONT BRKES	209		
DIAGNOSE AND REPLACE LOCK PAILL							
HOOKED UP NEW AND FOUND CODE B848 WHICH THROUGH PINPOINT TEST							
DEACTIVATED AIR BAG LIGHT SYSTEM AND STARTING TO CK CONNECTIONS							
UNDER PASSENGER SEAT FOUND SEAT BELT BUCKLE CONNECTOR TO BE	IF SEAT BUCKLE MT REMOVED						
BROKEN NEEDS BE	FLIGHT PRT SEAT AND						
5147 HAVE TO ORDER PARTS	REPLACED SEAT BUCKLE	X	Other	CK AIR BAG LITE FLASHING	701		
8941 PERFORMED AIR BAG DIAG RETRIEVED CODE B84E PERFORMED DCL		X	Other	SEATBELT REAR PASS DOESNT LATCH	318		
MONITOR TEST PERFORMED PINPOINT TEST ACCESS CHRYSLER SEAT	WLE CLEARED CODE						
TRACKED WIRING FROM ROM TO SEAT BUCKLE NO PROBLEMS FOUND PWR	REQUESTED VERIFIED REPAIR 8						
SEAT BE LT BRK	3810	X	Other	CLUST STATES THAT SOMETIMES AIR BAG LIGHT HAS BEEN COMING ON AND	794		
DIAG. REPLACE OPEN CIRCUIT IN DRIVER SEAT BELT		X	Other	STAYING ON, THEN AT TIMES LIGHT COMES ON THEN GOES OUT, LIGHT IS	517		
REPLACED DRIVERS SIDE SEAT BELT CHECKED FOR PRO PER OPERATION				OUT AT TIME OF WIRTE UP PLEASE CHECK			
OK				CHECK AIR BAG LIGHT ON			
		X	Other	DRIVERS SEAT BELT NOT WORKING PROPERLY JCP	410		
		X	Other	S.O.P SEAT BELT	431		
AIR BAG SYSTEM DIAG REPLACE DRIVERS FRONT SEATBELT BUCKLE(4E)		X	Other	SEAT BELT WARNING LIGHT STAYING ON (899)	300		
DIAG. REPLACE LEFT FRONT SEAT BELT BUCKLE		X	Other	AIR BAG LIGHT COMING ON	305		
DIAG CODE B84E PINPOINT RE RE SEAT REPLACED SEAT BELT BU				LIGHT BLINKED AND NOW ON CONSTANT REPLACE DRIVER SEAT BELT TO			
CKL94E		X	Other	CORRE	813		
CLAF FOR AIR BAG LIGHT CK. CODE B84E, MTP1209 8 HR TO TRACE OPEN							
CIRCUIT, DRIVERS SIDE BUCKLE SWITCH OPEN, REPLACED DRIVERS							
SEATBELT BUCKLE		X	Other	REPORT ON AIR BAG LIGHT ON	319		
REPLACE CEINTURE AVANT GAUCHE		X	Other	CEINTURE NE TRE PAS	418		
CHANGE LES 3 CEINTURES AVANT DEFECTUEUSE		X	Other	D18E1, POSITION DES BOUCLES DE CEINTURES DE SECURITE	418		
				LA CEINTURE AVANT GAUCHE BLOCUES/AVANT TIRER LE BOUTON NE FONC			
				PAS	418		
REPLACER CEINTURE AVANT GAUCHE		X	Other	VERIFIER LUMIERE AIR BAG FLASHING REF 280144 8 D. ARRIVEE	450		
TEST AND REPLACE DRIVER SEAT BELT BUCKLE COMB LIGHT BIRK		X	Other	PROTECTEUR CEINTURE AVANT GAUCHE CORRECTE REINSTALLE LE TIRAN	450		
WARNING LIGHT				DE BOUCLE			
		X	Other				
REINSTALLER LE TIRAN DE BOUCLE		X	Other	AIR BAG LIGHT RECES BLINKING	254		
DID BICE TEST, PIN POINT TEST, REPLACED DRIVERS SEAT BUCKLE AND DID		X	Other	DRIVERS SEAT BELT BUCKLE STICKY TO RELEASE	786		
PINL CHECK TEMP - - - -		X	Other	SEAT BELT GAUCHE DUNE A ATTACHER ET ENLEVER	810		
REPLACE BUCKLE ASSEMBLY							
REPLACE SEAT BELT BUCKLE NE RETRACTE PAS							
184 VERIFIER PAS LA BONNE PIECE RECOMMANDER BUCKLE DRIVER SEAT							
. 180 CHANGER SEAT BELT ET VERIFIER OK		X	Other	RECEIVED SEAT BELT BUCKLE (840)	814		
DIAGNOSE AND REPLACE LP SEAT BELT		A	Wont Latch	LP DRIVERS SEAT BELT WONT ENGAGE	813		
886 VERIFIER BOUCLE DE CEINTURE AVANT GAUCHE NE CLINQUE PAS							
RAIPORT PRINDRE BOUCLE SUR AUTRE AUTO NGUNG ET REMPLACER							
VERIFIER OK		X	Other	VERIFIER POUR SEAT BELT DU CHALUPPERU DU NE CLINQUE PAS SIGN	450		
				PASSENGERS SIDE FRONT SEAT BELT WILL NOT CLIP WITHOUT HOLDING			
		A	Wont Latch	TH	786		

CHECKED OUT PASS FRNT SEATBELT WONT STAY LOCKED IN REAR NEW SEATBELT CLIP  
 TEST IN VERIFY, NEEDS LATCH ASSY. REMOVED FROM NEW VEHICLE AND  
 INSTALLED ON UNIT. ORDER NEW ONE FOR UNIT THAT PARTS WAS BOBBED  
 FROM. INSTALL NEW SEAT BELT LATCH ON NEW UNIT THAT PART WAS  
 BOBBED FRD

TEST PIN POINT TEST SHORT TO GROUND REPLACE BUCKLE  
 1190 HISS TEST BASS PINPOINT TEST PASS SEAT BELT BUG KLS SWITCH  
 CXC OK BE AND REPAIR FRONT SEAT AND REPLACED SUSPECT BUCKLE  
 CLEAR CODES TEST WITH SEAT BELT LATCHED UNLATCHED PATENT  
 SYSTEM PASS

COOL CHECK BASS REPLACE RT SIDE SEAT BELT BUCKLE  
 TESTED SEAT BELT LATCH FEMALE END FOUND VERY HARD TO UNLATCH.  
 INTERNAL PROBLEMS IN LATCH, REPLACED FEMALE LATCH  
 ASSEMBLY, RETESTED OK NOW.  
 HISS TESTED PCM CODE BASS, DMC AND REPLACE RIGHT FRNT SEATBELT  
 BUCKLE. REWIRE & CLEAR CODES  
 RAN THE LEFT FRONT SEAT BELT BUCKLE

DUPLICATE FAULT, WIRE/RETRIEVE DTC/RETEST, WIRE CONSTRUCTIONS, PIN  
 TEST. REWIRE/REPLACE RT SEAT BELT BUCKLE ASSY OPEN CIRCUIT.

601 BELT BUCKLE BROKEN AND MOUNT BOLT HEAD IS STRIPPED TIME AS  
 NECESSARY. TO REMOVE BOLT AND REPLACE RT BUCKLE MT 4 HEM

REPAIR WHITE WIRE AT PASS BELT CONNECTOR  
 IN TIME TO REPLACE SEATBELT BUCKLE, NO TIME IN LTR  
 REPLACED DRIVERS SEAT BELT BUCKLE  
 INSPECT, CENTER SEATBELT WILL NOT LATCH CORRECTLY, REPLACE  
 SEATBELT ASSY AND RE TEST OPERATION OK, MT TIME NO LAB OF IN BELT  
 TO REPL CENTER BELT ASSY  
 OK ORDER AND REPLACE BELT ASSY  
 6013 W/ 0124 REPLACE DRIVERS SEAT BELT CLAMP OK  
 1572 48 WARR 7888 L SEAT BELT WONT STAY FASTENED BUCKLE RELEASE  
 SWINGING REPLACE L BUCKLE & TEST  
 FAULTY BUCKLE DRK OPER OF DR SEATBELT BUCKLE, REPLACED BUCKLE  
 ASSY. VERIFY REPAIR BY FUNCTIONALITY  
 REPLACE SEATBELT WILL NOT LATCH PROPERLY  
 REPLACE FR SEAT BELT BUCKLE

REPLACED THE SEAT BELT BUCKLE ASSY.  
 NEED TO RE DRIVER AND PASS BUCKLE ASSY  
 CHECKED AND REPLACED LEFT SEAT BELT BUCKLE

IN TIME TO REPLACE DRIVER SEATBELT BUCKLE NO OPP  
 TRACE CODES HAD CODE 48, 58, 62, INSTALL INSTRUMENTATION NEED TO REPAIR  
 BACK OF SEAT DRIVERS SIDE & REPLACE BUCKLE  
 REPLACE CENTURE AV DRONE  
 COMPLETE RECALL

INSTALL SPO BELT BUCKLE DRIVERS SIDE  
 VERIFY FUNCTIONEMENT DES BUCKLES DE CENTURE AVEC OUTIL DU  
 RAPPEL 01001, CENTURE DEFRUCTURISE, REPLACER CENTURE  
 GAUCHE

CHECK OUT CHECK OVER SEAT BELT BUCKLE BOTH ARE BROKEN ON  
 PASSENGER SIDE NEED TO REPLACE REPLACED SEAT BELT BUCKLE

B	Won't Latch	REPAIR PASS. SEATBELT TO STAY FASTENED.	519
A	Won't Latch	REPAIR FOR DRIVERS SEAT BELT WONT LATCH	780
X	Clear	LUMIERE AIR BAGS ALLIAGE BUCKLE COTE GAUCHE ENCLANCHE PMS	574
X	Clear	DMCL FOR AIRBAG LIGHT STAYING ON	804
X	Other	CHECK CALIB OF AIR BAG LIGHT WIRING COMING ON. 454 84 44	760
X	Other	CUSTOMER CONCERN SEAT LATCH STICKY REPAIR CAUSE OF AIRBAG LIGHT STAYING ON HAD FLASHED TWICE THEN 8	304
X	Other	DRIVERS FRONT SEAT BELT NOT LATCHING ALL THE TIME.	818
A	Won't Latch	CHECK FOR AIRBAG LIGHT FLASHING(CODES), THEN STAYS ON, NOT ON TODAY	304
X	Other		400
X	Other	IRS LIGHT FLASHING DIAGNOSIS & REPL. RT SEATBELT BUCKLE ASSY	815
A	Won't Latch	RT FRNT SEAT BELT WONT LATCH AIR BAG LIGHT ON CODE 01001 REPAIR WHITE WIRE AT PASS BELT CONNECTOR	816
X	Other		815
X	Other		
A	Won't Latch	DRIVERS SEAT BELT WONT LATCH	713
X	Other	CENTER SEAT BELT FRONT CLIP BROKEN	788
X	Other	PASS SEAT BELT WONT RELEASE	618
X	Other	SBS CLUST STATES DRIVER SEAT BELT INOP INSTALL SOP	661
D	Unlatches While Driving	SBS DRIVERS SEAT BELT COMES UNBUCKLED WHEN DRIVING SEATBELT CHIME NOT TURNING OFF ALL THE TIME WITH DRIVERS SEATBELT.	581
X	Other		788
X	Other		818
A	Won't Latch	FRNT FRONT SEAT BELT BUCKLE WILL NOT LOCK	606
D	Unlatches While Driving	(SBS) CLUST STATES THAT THE DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING	480
X	Other	PASS SEAT BELT INOP	506
X	Other	LEFT SEAT BELT NOT WORKING	273
D	Unlatches While Driving	DRIVERS SIDE SEAT BELT COMES UNLATCHED WHILE DRIVING	306
X	Other	REPAIR AIR BAG LIGHT STAYING ON	502
X	Other	REPLACER CENTURE AVANT DRONE P/O 18484	488
R	Recall Performed	RECALL 01001 ALL OK	318
X	Other	INSTALL SPO DRIVERS SEAT BUCKLE	608
R	Recall Performed	VERIFIER RAPPEL 01001 CUSTOMER STATES SEAT BELT ON RIGHT FRONT WILL NOT CLIP IN TO BUCKLE	430
A	Won't Latch		870
A	Won't Latch	REPAIR FOR PASSENGER SIDE SEATBELT WONT LOCK	400



10188 LEFT SIDE SEAT BELT RECEIVER IN OP INSPECT FOUND SEAT BELT RECEIVER IN OP REPLACE RECEIVER ASSEMBLY OK AFTER REPAIR. CC 42

TEST OPERATION OF SEAT BELTS REMOVE AND REPLACE SEAT BELTS REPLACED THE SEAT BELT REMOVED FINGER SPRING BAD. UNLATCH AND RECHECK OK. TECH REPLACED BELT BUCKLE PASS SEAT, WAS STUCK DOWN UNDER BUCKLE ASSEMBLY. REPLACED DRIVERS SEAT SEAT BELT BUCKLE ASSEMBLY PART BASIC 2208 CODE 29 THIS VEHICLE WAS DEALER TRADE FROM ANOTHER. DIAL, REARNT CONNECTED AT THESE DEALERSHIP. REPLACE SEAT BELT BUCKLE LEFT FRONT SEAT BUCKLE DOES NOT BUCKLE PROPERLY. REPLACE LEFT FRONT SEAT BELT BUCKLE. CHECK FOR CONCERN & CHECK & REPLACE SEATBELT LATCH ASSEMBLY. RECHECK ALL OK. TECH 147 VERIFY CONCERN PERFORM AIR BAG DIAG REPLACE SEAT BELT RECHECK OK. DIAG. CODE B0142RESEALING. DIAG. AIR BAG SYSTEM REPLACED LEFT SEATBELT. RETEST.

FOR SEAT FOR ACCIDENT BECAUSE OF CONVERSION REPLACED SEAT BELT BUCKLE. REPLACED SHOULDER ADJUSTER FOR SAME SEAT. BROKEN SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS RECALL 01821 4611 SEAT BELT BUCKLE NOT DIAGNOSE REPLACE LR FRONT SEAT BELT BUCKLE ASY CODE 407 SEATBELT BUCKLE IS BENDING. REPLACED SEAT BELT ASSEMBLY. RECALL 01821 RECALL 01821 64774 2228 MILES REPLACED SEAT BELT BUCKLE SEAT BELTS WONT LATCH REPLACE SEAT BELTS SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS RECALL 01821 SWAPPED SEATBELTS REPLACE FRONT SEAT BELT AND BUCKLE

2227 SEAT BELT CHIME STAYS ON 1200 D 2 DE 3 DK1 ( 01229 M TIME 2 1 1 HRS HRS BODY & SUBSTRAL DIAGNOSIS REPLACE LY SEAT BELT BUCKLE & RETEST CODE 42 CP 01821 SWITCH IN BUCKLE NOT WORKING PROPER LY

ASSEMBLY AS NEEDED COMPLETE RECALL LEFT SIDE SEAT BELT BUCKLE (STICKING) REPLACED LEFT SIDE BELT BUCKLE RECALL 01821 SEATBELT ASSEMBLY FRONT REPLACE

SEAT BELT FAULTY SEATBELT ASSEMBLY FRONT REPLACE COMPLETE RECALL PER FORD COMPLETE RECALL PER FORD 22 REPLACE BOTH FRONT SEAT BELTS AS PER PO

VERIFIED CONCERN AND FOUND THAT RIGHT SEAT BELT LATCH WILL NOT LATCH REMOVED RIGHT SEAT BELT REMOVED CENTER SEAT BELT UNIT RECALL 01821

SEAT BELT LITE ON AT TIMES BODY CHASSIS ELECTRICAL (ROR) TEST SEATBELT WONT LATCH REPLACE SEAT BELT

A	Wont Latch	SEE DR LEFT SIDE SEAT BELT BUCKLE WILL NOT LATCH	718
	Unlatches While	CUSTOMER STATES DRIVER SIDE SEAT BELT DOES NOT STAY CONNECTED	
D	Driving	DISCONNECTS WHILE DRIVING	305
E	Other	THE SEAT BELT LIGHT IS ON	410
X	Other	PASSENGER SEAT BELT DOESNT WORK	419
X	Other	REPAIR SEAT BELT BUCKLE STAYS DOWN	502
		DRIVERS SEAT BELT BUCKLE ASSEMBLY MISSING. VEHICLE WAS DEALER TRADED FROM WEST VIRGINIA. CONCERN CODE B4	740
X	Other	SEAT BELT WILL NOT LATCH IN BUCKLE	915
A	Wont Latch	MISC. TRM 225 CONNECT LEFT FRONT SEATBELT DOES NOT BUCKLE	306
A	Wont Latch	CORRECT DRIVER SEAT BELT TO LATCH	705
X	Other	CHECK FOR AIR BAG LIGHT IS STAYING ON	412
X	Other	CUSTOMER STATES AIR BAG LIGHT ON	573
X	Other	SEAT BELT REPLACED	432
X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	516
R	Recall Performed	DRIVER SIDE SEAT BELT DOES NOT LATCH PROPERLY	918
A	Wont Latch	DRIVERS SEAT BELT WONT LATCH	928
A	Wont Latch	DRIVERS SEATBELT WILL NOT LATCH	301
R	Recall Performed	DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	916
R	Recall Performed	DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	418
X	Other	SEATBELT IS NOT WORKING	770
A	Wont Latch	SEAT BELTS WILL NOT LATCH PROPERLY	915
X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	910
R	Recall Performed	DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	916
A	Wont Latch	CUSTOMER STATES SEAT BELT WONT BUCKLE	940
A	Wont Latch	DIAG. DRIVERS SEAT BELT. WONT LATCH	918
X	Other	220 D 8 SEAT BELT CHIME STAYS ON AT TIMES 18 MINS. DRIVING WHEN DRIVER SEAT BELT IS ON AND BUCKLED THE SEAT BELT LIGHT WILL STILL COME ON AND DRIVER WILL ON O	896
X	Other	RECALL 01821 SEAT BELT BUCKLE	417
R	Recall Performed	CUSTOMER STATES THE DRIVERS SEAT BELT HANGS UP WHEN UNBUCKLING	218
X	Other	DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	917
R	Recall Performed	DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	914
X	Other	CUSTOMER STATES SEAT BELT LIGHT STAYS ON WILL NOT GO OFF	478
		CUSTOMER STATES DRIVERS SIDE SEAT BELT BUCKLING LIGHT WILL NOT GO OFF	
X	Other	PART WAS ORDERED BY REPAIR (1/22/00) 2208	305
R	Recall Performed	RECALL 01821 SEAT BELT BUCKLE	516
R	Recall Performed	RECALL 01821 SEAT BELT BUCKLE	218
X	Other	SEAT BELT COIL UNCOIL, TROUBLE	614
A	Wont Latch	RIGHT SEAT BELT WILL NOT LATCH	783
R	Recall Performed	DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	916
X	Other	CUSTOMER STATES AT TIMES SEAT BELT LIGHT STAYS ON	896
A	Wont Latch	DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	915

00346 CLAMP BRASS SHOULDER AS A SPW

00386 DASH, REPLACE DRIVERS SEAT BELT BUCKLE  
COMPLETE RECALL

01821 B PASSENGER BUCKLE PNL PASS BELT BUCKLE  
RECALL 01821

REPLACE PASSENGER SEATBELT,  
AIR DRIVERS SEAT, REPLACE SEATBELT BUCKLE BROKEN  
DEFECTIVE SEATBELT MECHANISM DIAGNOSED CHECKED AND REPLACED  
DRIVERS SEATBELT RESENER,

01821 SEAT BELT RECALL 01821 SEAT BELT RECALL  
TECH INSPECTED VEHICLE, CHECKED OPERATION AND SEAT BELT BUCKLE  
NCP WILL NOT LATCH. ORDERED NEW B CUP TECH REMOVED DRIVER SEAT  
REMOVED AND REPLACED SEAT BELT BUCKLE CHECKED OPERATION  
OKAY, REINSTALL

D DRIVERS SEAT,

FOUND SEAT BELT LATCH CONNECTOR/CONNECTED CONNECTION  
RECALL COMPLETE RECALL

LF SEATBELT BUCKLE FAILED TEST, OWNER SAYS NOT INVOLVED IN 01821  
RECALL, REPLACED LF SEAT BUCKLE AS SAFETY LIABILITY ISSUE, LISTED  
LABOR AS TIME, NO OPS PUBLISHED.

COMPLETE RECALL

COMPLETE RECALL

CHECKED AND REPLACED LEFT FRONT SEAT BELT END LINK  
DASH/ON AND REPLACED BOTH FRONT SEATBELT BUCKLES DUE TO NOT  
LATCHING

LF SEATBELT WILL NOT LATCH REPLACED LEFT FRONT SEAT BELT  
BUCKLE DUE TO IT NOT LATCHING

PERFORM DND RESTRICTION CODE SEARCH FOR DRIVER SEAT BELT BUCKLE  
SWITCH FOLLOWED PINPOINT TEST, FOUND CONNECTOR UNDER SEAT  
BROKEN, REPLACED

DND TEST BASE PIN POINT TEST K TIME TO TRACE HARNESS TO LF SEAT  
BUCKLE REPL BUCKLE OPEN 26

INTERNAL DEFECT PERFORM DIAGNOSIS, REMOVE AND REPLACE LEFT SIDE  
SEATBELT BUCKLE RECHECK.

FOUND LEFT FRONT SEAT BELT BUCKLE JAMMED CHECK AND VERIFY LEFT  
FRONT SEAT BELT BUCKLE JAMMED REMOVE DEFECTIVE SEAT BELT AND  
REPLACE SEAT BELT ASSEMBLY

RIGHT SEAT BELT BUCKLE JAMMED CHECK AND VERIFY RIGHT FRONT  
SEAT BELT BUCKLE JAMMED REPLACE RIGHT FRONT SEAT BELT BUCKLE  
RECHECK OK

INSPECTED SEAT BELT

RELEASE JAMMED REPLACED RT FT SEAT BELT BUCKLE

877 REPLACE LT FRONT SEATBELT

REPLACED WEATHER STRIP AROUND DRIVERS WINDOW

742 SAME PERFORM AIRBAG DIAGNOSIS PINPOINT TEST CODE 81 81253  
TEMPORARILY FIX TEMPORARILY BUCKLE IN

11 OPEN IN DRIVERS SEAT BELT BUCKLE CODE 81 DISPLAYED, PAN NOW  
DOOR/AS LH SEAT BELT OPEN PAN PD TEST WAS OPEN NOW CLOSING  
CIRCUIT REPLACED BUCKLE ASBY CLEANED CODES RETEST OK ROAD  
TEST OK 45

INOPERATIVE REPLACED BELT BUCKLES

AIR BAG DND REPAIR OPEN CIRCUIT

RT FRNT SEAT BELT WONT LATCH REPLACE SEAT BELT BUCKLE  
REMOVE RIGHT AND LEFT SIDE SEAT TO REPLACE BOTH FRONT SEAT  
BELT BUCKLES

REPLACE DEFECTIVE SEATBELT

R	Recall Performed	PERFORM 01821 RECALL SEATBELT CUSTOMER STATES SEAT BELT LIGHT COMES ON INTERMITTENTLY WHILE DRIVING AND GOES OUT WHEN PULL ON SHOULDER BELT ASB	818
X	Other	REPAIR SEAT BELT	818
R	Recall Performed	PERFORM RECALL 801821	822
R	Recall Performed	DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY PASS. SEATBELT WAS NOT UNCLIPPING PROPERLY.	818
R	Recall Performed	SEAT BELT WILL NOT LATCH	806
X	Other	CUSTOMER STATES THAT SEAT BELTS ARE NOT WORKING CORRECTLY	828
A	Won't Latch	DRIVERS SEAT BELT	838
X	Other	DRIVERS BELT BELT	838
R	Recall Performed	01821 SEAT BELT RECALL FILED T	740
A	Won't Latch	CUSTOMER STATES DRIVER SEAT BELT BUCKLE WILL NOT LATCH *	812
X	Other	AIR BAG LIGHT IS ON	804
R	Recall Performed	RECALL 01821 ALL OK	218
R	Recall Performed	NECESSARY TO ORDER DRIVERS SIDE SEAT BELT BUCKLE FAILED TEST	801
R	Recall Performed	PER RECALL 01821	218
R	Recall Performed	RECALL 01821 ALL OK	218
X	Other	RECALL 01821 LEFT FRONT SEAT BELT IS INOPERATIVE	870
A	Won't Latch		
A	Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH BOP HERE	
X	Other	AIR BAG LIGHT ON CODE SEARCH SWITCHES PINPOINT TEST CONNECTOR BOP	801
X	Other	CUSTOMER STATES THAT THE AIR BAG LIGHT STAYED ON ALL DAY YESTERDAY	770
X	Other	CUSTOMER STATES AIR BAG LIGHT ON WHILE DRIVING	315
X	Other	CUSTOMER STATES DRIVERS FRONT SEAT BELT BOP	814
X	Other	CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE DOES NOT WORK	814
X	Other	SEAT BELT COILING PROBLEM	418
A	Won't Latch	RT FT SEAT BELT WONT LATCH	816
X	Other	RECALL 01821	770
X	Other	CUSTOMER STATES WIND NOISE FROM DRIVERS WINDOW WHILE DRIVING	315
X	Other	SEE AIR BAG WARNING LIGHTS 1 WAG	205
X	Other	AIR BAG LAMP CAME ON DRIVING CAR	767
X	Other	CUSTOMER STATES SEAT BELT BOP	881
X	Other	AIR BAG LIGHT IS ON/AS ON TODAY C 8 RT FRONT SEAT BELT WONT LATCH OK TO BOP OVER NIGHT IF NEEDED	808
A	Won't Latch	CUSTOMER STATES THAT SEAT BELT WILL NOT LATCH ALL THE TIME WHEN IT DOES LATCH IT WILL NOT STAY LATCHED	321
B	Won't Stay Latched		812
X	Other		781

WT REPLACE BOP LF SEAT BELT ASBY

R N R DRIVER SEAT. REPLACED LEFT FRONT SEAT BUC KLE ASBY. 0001.  
REPL SEATBELT BUCKLE AT TIME  
L F SEAT BELT BUCKLE LOOSE VERIFY CONCERN REATTACH L F SEAT  
BELT BUCKLE AND SECURE IN PLACE  
BOP CHECKED SYSTEM AND VERIFIED CONCERN, REMOVED AND  
INSTALLED NEW LEFT FRONT SEAT BELT BUCKLE ASSEMBLY, SYSTEM  
NOW WORKS CORRECTLY AT THIS TIME ALSO CHECKED RIGHT BUCKLE,  
AND FOUND THIS ONE TO BE  
AIR BAG DIAGNOSIS AND REPAIRED WIRING ON DRIVERS SIDE, MED TO RM  
SEATBELT AND BELT TO BEPWR  
DAG AIR BAG SYSTEM, CODE B986, PERFORM TEST. REPLACED DRIVERS  
SEAT BELT BUCKLE. OPEN CKT.

AIRBAG RESTRAINT SYS ED08 DTC RIGHT SEAT BELT BUCKLE SHORTED.  
R AND I SEAT TO INSPECT WIRING. REPL BUCKLE SHORTED INTERNALLY  
REPLACED LEFT FRONT SEATBELT BUCKLE ASBY  
CHECK FRONT DRIVER SIDE SEAT BELT BUCKLE WOULD NOT LATCH & OUT  
OF 18 TIME REPLACE BUCKLE SIDE OF DRIVER SIDE SEAT BELT.  
PERFORMED DIAGNOSIS, BOP DMO, FIDE MONITOR TEST, PMPPOINT TEST,  
AND CIRCUIT TEST CODE B986. REMOVED L F SEAT AND TRACED OUT OPEN  
CIRCUIT. REPLACED LEFT FRONT SEAT BELT BUCKLE. REINSTALLED SEAT.  
RETEST

W14 SAME REDALL REPLACED DRIVER SIDE SEAT BELT BUCKLE JH  
486 0186, 41 WITH B986 & REPLACE LEFT FRONT SEATBELT BUCKLE,  
REINSTALL WITH WARNING CHIME, REPAIRED WITH BUCKLE  
REPLACE LEFT FRONT BELT BUCKLE. (IMPROPER OPERATION)  
PERFORM DMO, INSPECT AND REPLACE FAULTY DRIVERS SEAT BELT  
BUCKLE B940  
FOUND INTERNAL FAULT IN SEATBELT ASSEMBLY REPLACED DRIVERS  
SEAT BELT  
AD BELT TEST B986 PMPPOINT TEST REPAIRED OPEN CIRCUIT AT SEAT  
BELT BUCKLE SWITCH CONNECTOR  
PULLED DOOR SEATBELT, A CHIME FOUND D R SEAT BELT BUCKLE  
UNPLUGGED, REINSTALLED PROPERLY, CLEARED CODES GOOD  
REPLACED BOTH FRONT SEAT BELT LATCHES  
DIAGNOSE LEFT FRONT SEATBELT IS PULLING AWAY FROM SEAT,  
REMOVED SEAT CUSHION COVER, REPOSITION BELT AND REPAD SEAT,  
REFT SEAT BELT

REPLACED BOTH SEAT BUCKLES

AIR BAG RESTRAINT SYSTEM DIAGNOSIS. REPLACE SEAT BELT BUCKLE  
CHECKED VEHICLE CONFIRMED CUSTOMER COMPLAINT PERFORMED  
PMPPOINT TESTING REPLACED DEFECTIVE BUCKLE REPEAT OK  
CHECK SEAT BELT OPERATOR AND REPLACE PASSENGER SIDE SEAT  
BELT

AIR BAG SYSTEM DIAGNOSIS, CONTINUOUS CODE B986. MED TO REPLACE  
R F SEAT BELT BUCKLE

BOP IN TIME TO REPLACE SEAT BELT CLASP  
DAG AND REPLACE FEMALE SEAT BUC  
REPLACE SEAT BELT BUCKLES NOT WORKING  
DUPLICATED CONCERN FROM ON INCS CODE B986 PERFORMED PMP POINT  
TEST FOUND B9 SEATBELT SWITCH CONNECTOR DISCONNECTED  
REINSTALLED CONNECTOR RECDER DEFERRATION OK REWASH BELT TEST  
SYSTEM PASSED.

X	Other	FAULTY DRV SIDE SEAT BUCKLE	518
X A	Other Wont Latch	B O P LEFT FRONT BELT AND BUCKLE ASBY. OR BUCKLE WONT LATCH	618
X	Other	THE DRIVERS SIDE SEAT BELT IS BOP	770
A	Wont Latch	DRIVERS FRONT SEAT BELT WILL NOT LATCH	601
X	Other	C BARRIAR LIGHT KEEPS FLASHING	313
X	Other	OK AIR BAG WARNING LIGHT ON	841
X B	Other Wont Stay Latched	AIR BAG WARNING ON B40 C S SEATBELT WILL NOT STAY LATCHED	888 864
X	Other	PER CUST. DASH DRIVERS SEAT BELT BUCKLE HARD TO LATCH AT TIMES	437
X A	Other Wont Latch	STAYS AIR BAG LIGHT KEEPS COMING OFF AND ON REPORT 288 DRIVERS SEAT BELT WONT SECURE WHEN B40 CUST REPORTS DRIVERS SEAT BELT WONT BUCKLE AND SEAT BELT CHIME BOP	318 888
A A	Wont Latch Wont Latch	DRIVER SEAT BELT BOP WONT LATCH	381 688
X	Other	CUSTOMER STATES LEFT FRONT SEAT BELT BOP B40	770
A	Wont Latch	CHECK DRIVERS SEAT BELT BOP. WILL NOT LOCK	513
X	Other	AIR BAG LIGHT ON	801
X X	Other Other	AIR BAG LIGHT FLASHING ON DASH CUST STATES BOTH FRONT SEATBELT HARD TO UNLATCH CC B40	301 770
X	Other Unlatched While Driving Other	FRONT SEAT BELTS COME UNBUCKLED BY THEMSELVES WHILE DRIVING	382 508
X	Other	AIR BAG LIGHT IS ON	368
X	Other	CUSTOMER STATES SEAT BELT DOES NOT BUCKLE PROPERLY	768
X	Other	INSPECT SEAT BELT BUCKLE	380
X	Other	CUSTOMER STATES AIR BAG LIGHT FLASHES CODE B2 JUST STAYS ON SOLID	810
A C X	Wont Latch Unlatches/Releases Other	REPLACE R FRONT OUTBOARD SEAT BELT CLASP DUE TO IT NOT LOCKING PART IS IN CAB SEAT BELT CAME LOOSE	718 818 781
X	Other	AIR BAG LIGHT IS ON	418

INTERNAL SHORT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT  
 REPLACE

BOTH FRONT SEATBELTS HARD TO FASTEN REPLACE BOTH FRONT SEAT  
 BELT BUCKLE (NDA) MISSING NO LABOR OPERATION IN ILSM  
 REPLACE INOP FIT SEAT BELT

SE AIR BAG DIAGNOSTIC TRACES WIRING AND FOUND DRIVERS SEAT  
 BELT BUCKLE SWITCH FAULTY. REPLACED SEAT BELT BUCKLE AND  
 TESTED

INSPECT SEAT BELTS CAN NOT VERIFY CONCERN FOR SBR AND BELL L  
 FOR CUSTOMER SATISFACTION REPLACED DRIVERS SEAT BELT BUCKLE  
 101 9041

REPLACE DRIVING SEAT BELT LATCH  
 REPLACE BELT PER RECALL 01821  
 REPL DRIVERS SEAT BELT BUCKLE

SEATBELT BUCKLE SWITCH OPEN PERFORMED PREPOINT TEST FOUND  
 OPEN IN RF SEAT BELT BUCKLE SWITCH R AND R RF BUCKLE  
 HOOKED UP WIRE TO PERFORM RCM TESTS SEARS RECHECKED DRIVERS SIDE  
 AND PASSENGER SEATS, LOOK PANEL WIRING AND PERFORMED OAM TESTS  
 ON WIRING PER SHOP MANUAL AFTER DEACTIVATING AIRBAG SYSTEM  
 REMOVED AIR BAGS-A

BUCKLE IN TIME REPLACE RIGHT FIT BELT BUCKLE  
 SRS RECEIVER INOP REPLACE LEFT FRONT SEAT BELT REARER ASSEMBLY  
 TUCKS CODE 42

WPS VERIFY COMPLAINT CODE SRS42 RMR FAULTY BUCKLE ASBY  
 1 REMOVE SEATBELT FROM THIS UNIT AND PUT ON SOLD UNIT PART  
 940822

SECURE LOOSE CONNECTION TO SENSOR  
 REPLACED SEAT BELT BUCKLE  
 REPLACED SEAT BELT MODULE

CHECKED DRIVING SEAT BELT WONT LATCH/BUCKLE WONT HOLD  
 REPLACED DRIVERS SEAT BELT BUCKLE ASSEMBLY ON NOW.  
 SRS1 DOES NOT OPERATE PROPERLY @ HOME REPL. DRIVING SEATBELT  
 LATCH ASBY 91596

REPLACE THE BUCKLE  
 BUCKLE FAILURES INTERNALLY. REPL.  
 DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT  
 REPLACE

1 DIAGNOSE SEAT BELT WILL NOT LATCH INTERNALLY COMING APART  
 REPLACE LATCH RETEST OK

1 INSPECT AND REPLACE LEFT AND RIGHT FRONT SEAT BELT BUCKLES  
 VEHICLE HAS NO OPEN RECALL NUMBER 01821 BUT REMINDER/NAME  
 REPAIRS

REPLACE BOTH SEAT BELTS  
 REPLACE 2 FRONT SEAT BELT BUCKLES  
 REPLACED SEATBELT

REPLACED R F SEAT BUCKLE  
 REPLACE THE BUCKLE

INSTALL BOMBED SEAT BELT RECEPTACLE FOR RFT, PARTS CHARGED  
 OUT ON RD 108918 ON 8/30/98

REPLACED SEATBELT BUCKLE  
 SECURED HARNESS TO CONNECTOR

REPLACED SEATBELT BUCKLE THAT WAS JAMMED  
 OAM TEST SRS @ PRE POINT TEST TIME TO TRACE HARNESS TO RF SEAT  
 BELT SWITCH REPLACE SWITCH OPEN @ TIME TO  
 CLOSED AT ALL TIMES EXCEPT PART REMOVE SEAT ON R SEAT BELT  
 BUCKLE

X	Other	CURT SET ABS LIGHT IS ON AND FLASHING	798
X	Other	BOTH FRONT SEATBELTS HARD TO FASTENED	713
X	Other	REPLACE THE SEAT BELT DUE TO THE PEDAL	818
X	Other	SRS AIR BAG LIGHT IS ON AND FLASHES	851
D	Unlatches While Driving	CUSTOMER STATES CHECK FOR BOTH FRONT SEATBELTS COME LOOSE WHILE DRIVING WILL NOT HOLD CUSTOMER STATES THAT THE DRIVERS SEAT BELT WILL AT TIMES NOT LATCH SRS	417
A	Won't Latch	01821 SEAT BELT RECALL	841
X	Other	D S SEAT BELT INOP	
X	Other	AIR BAG LIGHT ON	
X	Other	CUSTOMER STATES THAT AIR BAG LIGHT IS ON REPORTS PASS FRONT SEAT BELT BUCKLE REPEV COMING LOOSE BELT POPS OUT OF BUCKLE ASBY	818
D	Unlatches/Releases		808
A	Won't Latch	SRS CURT STATES THIS DRIVING SEATBELT WONT LATCH	817
X	Other	REMOVE SEATBELT FROM THIS STOCK UNIT TO PUT IN SOLD VEHICLE WITH A FAULTY SEATBELT SEE FOR 174282	270
X	Other	AIR BAG LIGHT ON	
X	Other	DRIVERS SEATBELT BUCKLE IN OP SRS	870
A	Won't Latch	L F SEAT BELT BUCKLE W M LATCH	
A	Won't Latch	C/S DRIVERS SEAT BELT WILL NOT FASTEN ONTO BUCKLE.	417
A	Won't Latch	SRS LEFT FRONT SEAT BELT WONT LATCH, HAS A BUCKLE	308
A	Won't Latch	DRIVERS SEATBELT BUCKLE NOT LATCHING	
A	Won't Latch	PASS FRONT SEAT BELT WONT BUCKLE	
X	Other	THE AIR BAG WARNING LIGHT FLASHES	818
X	Other	SRS CUSTOMER STATES DRIVERS SIDE FRONT SHOULDER BELT INTERM WILL NOT UNLATCH, CUSTOMER HAS TO WIGGLE LATCH & PRESS DOWN SEAT BELT BUCKLE INSPECTION AND OR REPLACEMENT FOLLOW @SPECIFIC INSTRUCTIONS TO PROPERLY TE	872
X	Other		
X	Other	01821 SEAT BELT BUCKLE RECALL SRS HERE	841
X	Other	INSPECT SEAT BELT BUCKLE	804
X	Other	PERFORM 01821 RECALL	314
X	Other	SEATBELT-COLLING/IMMATURE	432
X	Other	R F SEAT BUCKLE INOP	
X	Other	AIR BAG LIGHT IS ON	
X	Other	REINSTALL STOLLEN SEAT BELTS THAT WERE PART OF RECALL FOR DEL. RD 158618	878
A	Won't Latch	CHECK PASS FRONT SEATBELT WONT LATCH	818
X	Other	AIR BAG LITE ON	
X	Other	C S SEAT BELT NOT WORKING	808
X	Other	SRS AIRBAG LITE ON	770
X	Other	AIRBAG LIGHT ON	

80 PERFORMED PIN POINT TEST AND REPLACED LFT FRT SEATBELT BUCKLE CD 48  
 RIGHT FRONT SEATBELT BUCKLE BACKWARDS FROM FACTORY COAS 01288  
 REMOVE RIGHT FRONT BUCKLE AND REINSTALL CORRECT WAY  
 INSPECT SEAT BELT BUCKLE, NIG TO REPLACE SEAT BELT BUCKLE  
 PERFORMED 01281 RECALL FOUND FAULTY RF SEAT BELT BUCKLE  
 BUCKLE REPLACED RF SEAT BELT BUCKLE ASY AS PER RECALL  
 REPLACE SEAT BELT  
 REPLACED LFT FRONT SEAT BELT BUCKLE  
 REPLACE BUCKLE ASY BINSH REPLACE ONS BUCKLE  
 0740 0700, 41 MTR1282 88 CHECK AND R I RIGHT FRONT SEAT AND  
 REPLACE SEATBELT BUCKLE  
 DRIVER SEAT BELT WONT LATCH BUCKLE WONT LATCH REPLACED BUCKLE  
 48 WILL NOT CATCH REPLACED R & SEAT BELT BUCKLE  
 LOOSE CHECK AND REPLACE DRIVERS SEATBELT BUCKLE

K OPEN REMOVED SEATS AND CARPET TRACKED AND REPAIRED OPEN CIRCUIT 1388 APPROX 8 INCHES FROM CIRCUIT REASSEMBLE AND RETEST SYSTEM DTC 0848 STILL PRESENT PERFORMED PINPOINT TESTS REPLACED

188 VERIFIED AIR BAG LAMP ON PERFORMED AIR BAG DIAGNOSTICS FOUND HARD FAULTS BINSH AND BINSH DRIVERS AND PASSENGERS SEAT BELT CIRCUITS OPEN PERFORMED PINPOINT TESTS FOUND CIRCUIT 1388 TAN AND BLAC  
 STAYS RF SEATBELT BUCKLE SWITCH, NOT OPERATING PROPERLY DOOR BDE TEST DTC 0848 HARD FAULT. PERFORM AIRBAG SYSTEM DIAGNOSIS  
 PINPOINT TEST TO INTERNAL FAULTS IN RT FRT PASS  
 REPL. TRUCK SEAT BELT. WPI  
 BUCKLE ASSEMBLY OPERATING R AND R DRIVERS SEAT BELT BUCKLE REPLACED THE BUCKLE

USE WDS CHECK CODES FIND DTC0848 DRIVER SIDE SEAT BELT GO THROUGH MANUAL PINPOINT TEST FIND SEAT BELT BUCKLE BACI REPLACE BUCKLE W/ NO LABOR CP  
 1 PERFORM DIAGNOSIS ON AIR BAGS REPLACE SEAT BELT BUCKLE  
 1 REMOVE PASSENGER SEAT AND REPLACE SEAT BELT RECEPTACLE. TECH 32140  
 44 VERIFIED CONCERN PERFORMED AIR BAG DIAGNOSTICS FOUND DTC 0848 PERFORMED PINPOINT TESTS REPLACED DEFECTIVE PASSENGER'S FRONT SEAT BUCKLE ASY/CLASH CODES PRT TEST OK  
 INSPECT/TURN RF SEAT TO READJUST SEAT BELT BUCKLE TO CORRECT POSITION/TURNED AROUND/RECHECK.  
 WDS CAME UP WITH CODE 0848 DRIVERS BUCKLE CHECKED/WDS  
 REPLACED BUCKLE  
 REPLACED THE BUCKLE  
 ...

0848 REPLACED BOTH RIGHT AND LEFT FRT SEAT BELT BUCKLES. NOP ROAD TESTED VEHICLE TO CONFIRM AIR BAG LIGHT IN OILBU TECH 3800 ROAD TESTED NO LIGHT NO CODES. HELP TEST CAME UP GOOD MORE TESTING?? FOUND THAT THE PROBLEM IS SOMEWHERE IN THE PASSENGER'S SIDE SEAT  
 REPLACED BELT BUCKLE  
 REPLAC DRIVERS SEAT BELT BUCKLE  
 R AND R BUCKLE WPI  
 INSTALLED NEW DRIVERS BELT BUCKLE  
 VERIFIED CONCERN REMOVED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE

X	Other	SEAT BELT LIGHT STAYS ON	834
X	Other	PASS SIDE SEAT BELT BUCKLE IN BACKWARDS	318
X	Other	SEAT BELT BUCKLE NOP	718
X	Other	01281 SEAT BELT BUCKLE INSTALL BOP PART	487
X	Other	CUSTOMER CLAIMS SEAT BELT NOP	410
A	Wont Latch	LFT FRT SEAT BELT BUCKLE WONT LATCH	.
X	Other	DRIVERS SEAT BELT HARD TO CONNECT AND OPEN	451
A	Wont Latch	BIN CUST REPORTS R F SEATBELT WONT BUCKLE AND RED BUTTON BINSH	331
A	Wont Latch		.
D	Driving	CUST STATES R FRT SEAT BELT POPS LOOSE WHEN DRIVING ADVISE	844
C	Unlatched/Released	CHECK DRIVERS SEAT BELT COMES UNLATCHED PARTS HERE	910
X	Other	CUSTOMER STATES THAT AIR BAG LIGHT IS BLINKING ON AND OFF AT TIMES	218
X	Other	CUSTOMER STATED THAT AIR BAG LIGHT IS ON	714
X	Other		.
A	Wont Latch	DRIVERS SEAT BELT WONT LATCH	.
X	Other	AIR BAG LIGHT IS ON	912
X	Other		.
X	Other	CUST STATES AIR BAG LIGHT WONT GO OFF OK AND ADVISE, OWNER STATES AIR BAG LIGHT COMES ON AND STAYS ON	869
X	Other	OK PASSENGER SIDE SEATBELT RECEPTACLE, SEATBELT WONT STAY FASTENED	917
B	Wont Stay Latched		.
X	Other	AIR BAG LIGHT FLASHING ON VEHICLE IS BEING DELIVERED SOON	814
X	Other	OK RT FRT SEAT BELT BUCKLE TURNED AROUND	844
B	Other	AIR BAG LIGHT ON	.
X	Other	L F SEAT BELT BUCKLE NOP	.
X	Other	FRONT SEAT BELTS NOT OPERATING PROPERLY	480
X	Other		.
X	Other	WARNING LIGHTS CHIMER, AIR BAG WARNING LIGHT TROUBLE	207
X	Other	AIR BAG LIGHT IS ON	.
X	Other	DRIVERS SEAT BELT INOP	.
X	Other		.
X	Other	AIR BAG LIGHT IS ON	.
A	Wont Latch	CUSTOMER STATES DRIVERS SEAT BUCKLE WILL NOT LATCH CHK AND ADV	841

REPLACED PASSENGER SEAT BELT BUCKLES NOT LATCHING  
INTERNAL FAULT IN BUCKLE INSPECT AND REPLACE TEST OK NOW  
REPLACED SEATBELT LATCH  
REPLACED O SIDE BUCKLE  
BUCKLE DEFECTIVE RR BELT ASSEMBLY  
INTERNAL FAILING WILL NOT LOCK REPL DO BUCKLE  
STICKING REPLACED LEFT FRONT SEAT BELT BUCKLE THAT WAS  
STICKING AND WOULD NOT ALLOW BELT TO FASTEN  
OF 8495000 282000 808 AIR BAG RESTRAINT SYSTEM DIAGNOSIS  
REPLACED RIGHT FRONT SEAT BELT BUCKLE  
TESTED EJECT SYSTEM FOUND WIRE IN DRIVER SEAT BELT BAD  
REPLACED & RETESTED GOOD, NO CHARGE MT USED AS NO CP CODE  
REPLACE SEATBELT BUCKLE  
REPLACE BELT BUCKLE  
WPI FOUND BUCKLE WONT LOCK BELT REPL NT BELT  
DEFECTIVE BUCKLE, AIR BUCKLE  
REPLACED THE SEATBELT BUCKLE  
8018 878122 42 VERIFY DRIVER SIDE FRONT SEAT BELT BUCKLE  
NOP, REPLACED LEFT FRONT SEAT BELT BUCKLE, OK NO W  
INSPECT REPLACED FRONT SEAT BELT  
REPLACE PASSENGER SIDE SEAT BELT  
REPLACED PASSENGER SEAT BELT BUCKLE

CHECKED SEAT BELT BUCKLE, REPLACED SEAT BELT BUCKLE  
REINSTALL WIRE CONNECTOR  
REPLACED THE BUCKLE  
CHECK AIR BAG LIGHT, NOW TEST, RETRIEVE DTC, BASH & CLEAR C CODE  
ON DEMAND TEST & BASH DTC & MONITOR PID & PINPOINT RECONNECT &  
RESECURE CONNECTION, SYSTEM PASS  
PASS SPARINGLY BUCKLE WONT LATCH, BUCKLE DEFECTIVE, RR BELT  
BUCKLE  
CODE 8448 SEAT BELT BUCKLE LOOSE CONNECTOR TO PASS SEAT BELT  
TIGHTEN CONNECTION, RETEST  
RESECURED PIN INTO CONNECTOR  
CHECK AND REPLACE PASSENGER SEAT BELT  
. 887807940 61179A  
REPLACE R F SEATBELT BUCKLE  
MECHANISM DONT RELEASE COMPLETELY REPL. BUCKLE  
REPLACED L F SEAT BELT BUCKLE  
REPLACED DRIVERS SEAT BELT  
1 1 REPLACE THE DEFECTIVE SEAT BELT BUCKLE  
1 TESTED AND FOUND TO BE NOP FOR LF BELT LATCH  
REPLACED THE BUCKLE  
REPLACED THE SEAT BELT  
BUCKLE DEFECTIVE RR BELT ASSEMBLY

DRIVER SEAT BELT WONT LATCH, BUCKLE DEFECTIVE, REPLACED BUCKLE  
WPI TEST CHECKED FOR WIRE CODE 8448 8448 8448 8448 8448 8448  
SEATBELT BUCKLE

VERIFYED LEFT FRONT SEATBELT AND BUCKLE INOPERABLE REPLACED  
CHECKED RIGHT FRONT SEAT BELT BUCKLE DEFECTIVE, IT WILL NOT  
HOLD, NEED TO REPLACE RIGHT FRONT BUCKLE  
1775 BUCKLE NOP WARR VERIFY CONCERN REPLACED PASS FRONT SEAT  
BELT BUCKLE  
AIR BAG LIGHT COME ON, FOUND FAULTY SEAT BELT BUCKLE  
6 W INSTALL LEFT SEAT BELT BUCKLE 617224818248  
NOT INVOLVED IN PRECALL BUT WOULD NOT HOLD  
REINSTALL WIRE ON PASSENGER BELT BUCKLE

A	Wont Latch	FRONT PASSENGER SEAT BELT BUCKLE NOT LATCHING REPORT	818
A	Wont Latch	DRIVERS SEAT BELT WILL NOT BUCKLE INTO FEMALE PORTION	614
X	Other	PASSENGERS FRONT SEAT IS NOP	.
A	Wont Latch	L F SEAT BELT BUCKLE W H LATCH	.
A	Wont Latch	DRIVERS SEAT BELT WHT LATCH	.
A	Wont Latch	REPL DO BUCKLE	.
X	Other	CUSTOMER STATES DRIVER SEAT BELT INOP. PLEASE TEST ALL OTHER BELTS	806
X	Other	AIR BAG LIGHT COME ON AND DR FLASHES AT TIMES.	763
K	Other		806
A	Wont Latch	DRIVERS SEATBELT BUCKLE WONT LATCH	809
X	Other	AIR BAG LT STAYS ON	.
A	Wont Latch	DRIVER SEAT BELT WONT LATCH	.
A	Wont Latch	DRIVER SEATBELT WONT LATCH	.
A	Wont Latch	LT SEATBELT WONT BUCKLE PART HERE	610
X	Other		770
X	Other	INSPECT SEAT BELT BUCKLE	804
X	Other	SEAT BELT BUCKLE WRONG COLOR	804
X	Other	C C FRONT PASSENGER SEAT BELT BUCKLE NOP INT TR 22	617
		CUSTOMER STATES SEAT BELT AT DRIVER SIDE WILL COME LOOSE AT TIMES	804
C	Unlatched/Retracted	VEHICLE AIR BAG LIGHT STAYS ON	.
X	Other	R F SEAT BUCKLE INOP	.
X	Other	808 CUSTOMER STATES AIRBAG LIGHT ON	820
A	Wont Latch		.
X	Other	AIR BAG LIGHT HAS BEEN COMING ON AND STAYING ON NOW IT DOESNT COME ON AT ALL	643
X	Other	AIR BAG LIGHT IS ON	.
X	Other	INSPECT SEAT BELT BUCKLE	606
A	Wont Latch	LEFT FRONT (SEAT) BELT WILL NOT LATCH	618
X	Other	R F SEAT BELT BUCKLE TORN	.
X	Other	DRIVER IS SEAT BUCKLE INOP	.
X	Other	L F SEAT BELT W H BUCKLE	.
A	Wont Latch	CURT STATES DRIVERS SEATBELT WONT LATCH	223
A	Wont Latch	C S THAT THE DRIVERS SEAT BELT WILL NOT BUCKLE	608
X	Other	C S SEAT BELT LATCH INOP	608
X	Other	AIR BAG LIGHT ON	.
X	Other	AIR BAG LIGHT ON	.
A	Wont Latch	DRIVERS SEAT BELT WONT LATCH	.
A	Wont Latch		.
X	Other	CHECK AIR BAG LIGHT FLASHING CODE 5 1	810
X	Other	CUSTOMER STATES LEFT FRONT SEATBELT INOPERABLE	808
A	Wont Latch	CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE WILL NOT HOLD	812
A	Wont Latch	PASS SIDE SEATBELT WILL NOT LATCH	410
X	Other		288
X	Other	700 INSTALL LEFT REAR SEAT BELT BUCKLES ASSEMBLY	306
A	Wont Latch	SEAT BELTS WOULD NOT HOLD	281
X	Other		806

REPLACED DRIVER BUCKLE  
 11646 FOUND LEFT FRT BUCKLE TO BE BROKEN AND SEAT BELT WOULD NOT INSERT. RAR FRT SEAT AND REPLACE BELT BUCKLE. POWER SEATS, LEATHER TRIM  
 VERIFIED CONCERN. RAR PASSENGER SEAT. REPLACED BUCKLE SEAT BELT BUCKLE. VDS TEST, REMOVE AND REPLACE SEAT BELT BUCKLE

1 REPLACE DRIVER SEAT BELT BUCKLE. NORMAL AFTER REPAIRS.

INSTALL SOP SEAT BELT ASSEMBLY  
 1 REPLACE BOTH FRONT SEAT BELTS.  
 REPLACED BUCKLES  
 VERIFIED CONCERN, REMOVED AND REPLACED SEAT BELT BUCKLE

REMOVE FROM STOCK UNIT AND REPLACE ON CUSTOMER'S VEHICLE.

INSTALLED NEW SEAT BELTS  
 REPLACE SEATBELT WILL NOT LATCH PROPERLY  
 REPLACE BOTH FRT SEAT BELTS

3814 VERIFIED CONDITION FOUND BOTH FRONT SEATBELT WILL NOT HOLD THE SEAT BELT IN PLACE WITH MINIMAL FORCE APPLIED. REPLACED BOTH FRONT SEAT BELT BUCKLES. THIS VEHICLE DOES NOT SHOW TO HAVE THE RECALL  
 8 REMOVED SEAT FROM TRUCK CHANGED SEAT BELT THEN BOLTED SEAT BACK IN TRUCK  
 PASSENGER SIDE SEAT BELT BUCKLE WORK, BINS. CHECKED SEAT BELTS, REPLACED PASSENGER SIDE SEAT BELT BUCKLE, RETURNED TO VERIFY, PASSED

INSPECT AND REPLACE BOTH FRONT SEAT BELT BUCKLES  
 VERIFIED CONCERN FOUND RIGHT FRONT SEAT BELT LA. TCH BROKEN  
 REPLACED SEAT BELT LATCH  
 VDC REPLACED DRIVERS SEAT BELT BUCKLE. R AND R SEAT FOR ACCESS 40 20 40 NO BSN  
 REPLACE LF BELT

REPLACE LEFT FRT SEATBELT WONT LATCH  
 REPLACE LEFT FRT SEATBELT ASSY, WOULD NOT LATCH  
 REPLACE RIGHT FRONT SEAT BELT ASSY  
 VEHICLE MISSING DRIVERS SIDE SEAT BELT LATCH. REPLACED LATCH  
 REPLACE RIGHT AND LEFT SEAT BELT BUCKLES PER RECALL  
 RAR SEAT BELT BUCKLE  
 TEST AND REPLACE DRIVERS BELT  
 IMPROPER SEAT BELT BUCKLE FUNCTION. REPLACED BUCKLE ASSY DRIVERSIDE

INSTALL NEW SEAT BELT  
 VERIFIED CONCERN, REPLACED BOTH SEAT BELT BUCKLE ASSY  
 RECHECKED ALL GOOD AT THIS TIME.  
 INTERNAL DEFECTIVE. REPLACED RT SEAT BELT BUCKLE

VERIFIED CONCERN. DIAG. FOUND DRIVER SEAT BUCKLE WOP. RAR DRIVER SEAT BELT BUCKLE. RETURNED OK. VERIFIED REPAIR. COO 346  
 ORDERED SEAT BELT LATCH. REPLACED DRIVERS SIDE SEAT BELT LATCH AND VERIFIED REPAIR  
 REPLACED BUCKLE  
 REPLACED LEFT SEAT BELT  
 REPLACED LOWER DRIVER SEAT BELT

VERIFIED CONCERN. DIAG. FOUND DRIVER SEAT BUCKLE WOP. RAR DRIVER SEAT BELT BUCKLE. RETURNED OK. VERIFIED REPAIR. COO 346  
 ORDERED SEAT BELT LATCH. REPLACED DRIVERS SIDE SEAT BELT LATCH AND VERIFIED REPAIR  
 REPLACED BUCKLE  
 REPLACED LEFT SEAT BELT  
 REPLACED LOWER DRIVER SEAT BELT

X	Other			814
X	Other	AIR BAG LIGHT ON		
A	Won't Latch	PLEASE CK DRIVERS FRONT SEATBELT IS WOP		757
A	Won't Latch	R F SEAT BELT WONT LATCH		381
X	Other	CUSTOMER STATES AIR BAG LIGHT STAYED ON		317
A	Won't Latch	CUSTOMER STATED DRIVER SIDE SEAT BELT WILL NOT LATCH INTERMITTENTLY, SOP		578
R	Recall Performed	INSTALL SOP SEAT BELT. RECALL 01861		767
A	Won't Latch	CUSTOMER STATES THAT BOTH FRONT SEAT BELTS WILL NOT HOLD		517
B	Won't Stay Latched	SEAT BELT WILL NOT STAY LATCHED		606
A	Won't Latch	SEAT BELT WILL NOT BUCKLE		301
C	Unlatches/Releases	CORRECT DRIVERS SEAT BELT LATCH POP LOOSE WILL NOT STAY LATCHED		519
C	Unlatches/Releases	DRIVERS SEAT BELT KEYS COMING LOOSE		399
X	Other			519
X	Other	SEAT BELT NOT WORKING		300
C	Unlatches/Releases	CUSTOMER STATES THAT BOTH FRONT SEAT BELT BUCKLES WILL NOT LATCH PROPERLY		226
X	Other	FRT SEAT BELTS NOT WORKING		320
O	Unlatches/Releases	OWNER STATES THE PASSENGER SEAT BELT COMES UNLATCHED. ADVISE BELTS PAID FOR. REPLACEMENT OF SEAT BELT BUCKLE		518
X	Other	DRIVER AND PASS SIDE FAILING		702
X	Other	SEAT BELT WOP		380
C	Unlatches/Releases	CUST STATES DR SIDE SEAT BELT COMES UNLATCHED AT TIMES FOR NO REASON .		515
X	Other	SEAT BELT WONT WORK, LF		284
A	Won't Latch	CUST STATES LEFT FRONT SEAT BELT WILL NOT LATCH PROPERLY SOP		408
A	Won't Latch	CHECK DRIVERS SIDE SEATBELT WILL NOT LATCH		381
X	Other	RIGHT FRONT SEAT BELT WILL NOT LATCH PROPERLY		570
R	Other			309
R	Recall Performed	RECALL 01861 LEFT SIDE 40 20 40 LEFT SIDE MISC. PARTS		389
X	Other	PASSENGER SEAT BELT LOCKS AND WILL NOT RELEASE INTERNET		512
B	Won't Stay Latched	CHECK DRIVERS SIDE BELT DOESNT STAY LOCKED		701
D	Unlatches/Releases	CUSTOMER STATES THAT DRIVERS SIDE SEATBELT BUCKLE WILL POP OUT WHILE DRIVING		517
X	Other	SNAP SEAT BELT WITH A TRUCK THAT HAS GOOD SEAT BELTS THAT ARE NOT UNDER RECALL.		308
X	Other	CUSTOMER STATES CHECK BUCKLE ASSY WILL NOT LATCH PROPERLY		301
A	Won't Latch	RIGHT SIDE BUCKLE WILL NOT LATCH		570
D	Unlatches/Releases	DRIVERS SIDE SEAT BUCKLE RELEASES WHILE DRIVING		480
D	Other	CUST STATES DRIVERS FRONT SEAT BELT ON OCCASION WILL OTRUCKLE		
A	Won't Latch	CK & ADV		514
A	Won't Latch	SEAT BELT BUCKLE DOESNT LATCH		308
X	Other	LEFT BELT BELT NOISY INSIDE		724
B	Won't Stay Latched	CK FOR DRIVER SIDE SEAT BELT COMING LOOSE		429

NOTE NO RECALL BUT FAILED TEST PASS BUCKLE RPL PASS SIDE BELT BUCKLE NO RECALL OPERATION KGS WARRANTY

WONT STAY BUCKLED SEATBELT ASSEMBLY FRONT REPLACE TEST BOTH FRONT SEAT BUCKLES WONT DRIVERS SIDE OK PASSENGER SIDE WONT STAY BUCKLED REPLACED PASSENGER SIDE SEAT BELT BUCKLE CHECKED & VERIFIED SEAT BELT ON PASSENGER SIDE WOP REPLACED BUCKLE & RECHECKED & OK REPLACED SEATBELT. DIAG AND REPLACED BELT ASBY

SEAT BELT & CLOCK SPRING FAILED AIR BAG RESTRAINT SYSTEM DAMAGED  
SBI SCS TEST BYMS PPT REPLACE DRIVER SIDE PRETENSION OVER CLEAR CODES RETEST OK  
BUCKLE REPLACE FRONT SIDE SEAT BELT BUCKLE  
NEED TO REPLACE SEAT BELTS  
DIAGRAM TRIM AND WEATHERSTRIP TO GET TO RETRACTOR REMOVED AND REROUTED BELT BACK IN AND OUT TO MAKE SURE IT WORKED.  
REPLACED DRIVERS SEAT BELT ASSEMBLY  
DONE DIAG FOUND SEAT BELT WONT LATCH REPLACED BUCKLE FIXED PROBLEM

1018 SHORTED CHECK WITH MISS 2 FOR IN TIME TEST SYSTEM RAN OEM TO TEST WIRING RUN SEATS RUN CARPET TO ACCESS WIRES FOUND SHORT WHERE CUSTOMER HAD A SPRINGER BOX BURED IN DIRECT TO THE SEAT BELT HARNESS  
REPLACED FRONT FRONT SEAT BELT BUCKLE  
BELT NOT SECURED. REPLACED BELT ASSEMBLY  
1 REMOVE REPLACE LEFT FRONT SEATBELT BUCKLE  
REPLACED THE L/F SEAT BELT BUCKLE  
LATCH SEAT BELT ASSEMBLY REAR RIGHT OR LEFT  
REPLACE  
RPL DR SIDE SEAT BELT LATCH ASBY  
REPLACED RIGHT FRONT

VERIFIED CONCERN REPLACED THE SEAT BELT LATCH  
MT: TIME TO PERFORM REPAIR ON SEATBELT BUCKLES ON BOTH FRONT SEATS.

REPLACED RIGHT FRONT BUCKLE  
INSPECT AND REPLACE BOTH FRONT SEAT BELT BUCKLES W O AIR BUCKETS  
10021 REPLACED PASS SIDE SEAT BELT BUCKLE RECDNR NOTE VEHICLE HAS 40 28 40 SPLIT BENCH AND IS A CREW CAB  
R & R RIGHT SEAT BELT BUCKLE LOCKS UP. R & R LEFT FRONT SEAT RETRACTOR  
TESTED BOTH FRONT SEAT BELT BUCKLES DRIVER SEAT FAILED  
REPLACED SEAT BELT RECDNR  
REPLACED DRIVERS BUCKLE

REPLACED BOTH FRONT BUCKLES

1 INSPECT AND REPLACE BOTH FRONT SEATBELT BUCKLES

REPLACED LEFT SEAT BELT BUCKLE PER RECALL

REPLACED BOTH SEAT BELT BUCKLES PER RECALL

R	Recall Performed	PERFORM RECALL 01021 MORE NO OPEN RECALL CAMPAIGN PER CARR	502
B	Won't Stay Latched	LEFT FRONT SEAT BELT WONT STAY LATCHED.	605
B	Won't Stay Latched	CHECK SEAT BELT OPERATION SEAT BELTS WONT STAY LOCKED	915
C	Unlatches/Releases	CUSTOMER STATES PASSENGER SEAT BELT KEEPS COMING UNDONE	388
X	Other	CUSTOMER STATES DR SIDE SEATBELT LATCH WOP ADVISE	382
A	Won't Latch	BOTH FRONT SEAT BELTS WILL NOT LOCK	402
X	Other	Other	318
X	Other	AIR BAG LIGHT FLASHING AND THEN STAYING ON	778
X	Other	CUSTOMER STATES AIR BAG LT IS ON, REQ ADV	818
A	Won't Latch	SEAT BELT WILL NOT HOLD BUCKLE	830
X	Other	NEED SEAT BELT HAD TO ROB PARTS FROM NEW VEH	770
X	Other	DR SEAT BELT WILL NOT FULL OUT REMOVED SEAT BEL DR SIDE AND RELEASE BELT JAMS	618
C	Unlatches/Releases	DRIVERS SEAT BELT BUCKLE COMES UNBARRING BY ITSELF.	508
A	Won't Latch	SEAT BELT BUCKLE WONT BUCKLE	570
X	Other	SEAT BELT BUCKLE WONT BUCKLE	517
R	Recall Performed	SEAT BELT BUCKLE WONT BUCKLE	314
X	Other	SEAT BELT BUCKLE WONT BUCKLE	591
A	Won't Latch	SEAT BELT BUCKLE WONT BUCKLE	590
X	Other	SEAT BELT BUCKLE WONT BUCKLE	510
X	Other	SEAT BELTS WOP. S.O.P.	919
X	Other	SEAT BELTS WOP. S.O.P.	427
X	Other	NEED TO CHECK SEAT BELT	505
A	Won't Latch	CUSTOMER STATES CHECK LEFT FRONT SEAT BELT LATCH WOP NOT LATCHING	918
C	Unlatches/Releases	OK BOTH FRONT SEATBELT BUCKLES WILL LATCH BUT WILL COME OUT WHEN PULLED ON	317
A	Won't Latch	RIGHT FRONT SEAT BELT BUCKLE DOES NOT LOCK PROPERLY LIKE RECALL BEL	888
D	Unlatches/Releases	DRIVERS SIDE SEATBELT UNLATCHES WHEN DRIVING INTER	9
D	Unlatches/Releases	DRIVERS SIDE SEATBELT UNLATCHES WHEN DRIVING INTER	9
A	Won't Latch	PLEASE CHECK PASS SIDE AS WELL	918
A	Won't Latch	CUSTOMER STATES THAT PASSENGER SEAT BELT BUCKLE WILL NOT LATCH INTERMITTENTLY.	380
X	Other	RE SEAT BELT LOCKS UP, L/SEAT BELT WONT RETRACT PROPERLY	801
B	Won't Stay Latched	SEAT BELT WONT STAY LATCHED	807
X	Other	INSTALL S.O.P THAT WAS REMOVED TO REPAIR SOLD UNIT FOR SEAT 18	314
X	Other	POS VEHICLE IS JUST PAST DATE ON RECALL BUT DRIVERS BUCKLE FAILS	514
R	Recall Performed	REPLACE DRIVERS BUCKLE	514
R	Recall Performed	RECALL 01021 SEAT BELT BUCKLE REPLACEMENT BOTH FRONT TRIM CODES AT	541
R	Recall Performed	PERFORM RECALL 01021 LEFT BUCKLE FAILED, RIGHT BUCKLE PASSED	398
R	Recall Performed	PERFORM RECALL 01021 BOTH SEAT BELT BUCKLES FAILED INSPECTION	208



REPLACED FRONT FRONT SEAT BELT BUCKLE REPLACE DRIVERS LEFT FRONT SEAT BELT DIAO. WSP IN TIME TO REPLACE BOTH SEAT BELT BUCKLES	X A X	Other Went Latch Other	THE VEHICLE IS JUST PASSED PRODUCTION DATA FOR RECALL 01021 BUT RIGHT SEAT BELT FAILED TEST REPLACE LEFT FRNT SEAT BELT WONT LATCH	814 882 890
600 W REPLACED DRIVER SIDE SEAT BELT REINSTATED ALL OK	X	Other	CUSTOMER STATES DRIVER'S SIDE FALD AND PASSENGER SIDE PASSED BOP SEAT BELT IS HERE	817
DRIVERS TRACK ASSEMBLY FRONT SEAT REPLACE REPLACE SEAT BELT BUCKLE SEAT BELT BUCKLE WORKING WAY. 07 01029 VERIFY CUSTOMERS CONCERN SEAT BELT BUCKLE TURN THE WRONG WAY, STRAIGHTEN OUT SEAT BELT BUCKLE.	C X	(Unlatched/Released) Other	DRIVERS SEATBELT BUCKLE COMES UNDONE PART IN STOCK SEE TED PASS. FRONT IS FAILING ALSO	841 805
, VERIFIED CONCERN. INSPECTED SEAT BELT AND FOUND BUCKLE NOT HOLDING. REPLACED BUCKLE ASBY AND RETESTED. OK AT THIS TIME, REPLACED SEAT BELT BUCKLE. REPLACE BOTH FRONT SEAT BELT BUCKLES FOUND STICKING. RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	X	Other	CUSTOMER STATES R/F SEAT BELT TWISTED OR BUCKLE TURNED WRONG WAY	878
REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE. 07 07 05.00 00 01. REPLACE PASS SEAT BELT ASBY WORKING SEAT BELT ASSEMBLY FROM RIGHT OR LEFT REPLACE INSTALL MISSING DRIVERS SEAT BELT BUCKLE. D. C. E. M. FAULTY RT SIDE BUCKLE SEATBELT BUCKLE DOESNT HOLD. REPLACED PASS SIDE BUCKLE NO RECALL ON VEHICLE VOLUNTARY FACTORY SAFETY RECALL. INSPECT AND REPLACE ONE SEAT BELT BUCKLE RIGHT SEAT BELT BUCKLE PASSENGER SIDE INOPERATIVE REPLACE PASSENGER SIDE SEAT BELT BUCKLE INOPERATIVE SEAT BELTS BOP SEATBELT ASSEMBLY FRONT REPLACE	B X X R B	Went Stay Latched Other Other Reset Performed Went Stay Latched Unlatched/Released	LEFT FRONT SEAT BELT WILL NOT STAY LATCHED SEE CHARLIE FRONT SEATBELTS STICK WHEN LATCHING CUSTOMER RECALL 01021 PASS BELT DRIVERS FRONT SEAT BELT WILL NOT STAY LATCHED	818 805 825 805 880
REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE. 07 07 05.00 00 01. REPLACE PASS SEAT BELT ASBY WORKING SEAT BELT ASSEMBLY FROM RIGHT OR LEFT REPLACE INSTALL MISSING DRIVERS SEAT BELT BUCKLE. D. C. E. M. FAULTY RT SIDE BUCKLE SEATBELT BUCKLE DOESNT HOLD. REPLACED PASS SIDE BUCKLE NO RECALL ON VEHICLE VOLUNTARY FACTORY SAFETY RECALL. INSPECT AND REPLACE ONE SEAT BELT BUCKLE RIGHT SEAT BELT BUCKLE PASSENGER SIDE INOPERATIVE REPLACE PASSENGER SIDE SEAT BELT BUCKLE INOPERATIVE SEAT BELTS BOP SEATBELT ASSEMBLY FRONT REPLACE	D A	Doing Went Latch	DRIVERS SEAT BELT COMES UNBUCKLED WHILE CUSTOMER IS DRIVING CHECK PASS SEAT BELT WONT LATCH	820 840
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A X	Went Latch Other	CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT LATCH NEED TO CHECK ARM FOR DRIVER SIDE SEAT BELT PASSENGER SIDE SEAT BELT DOESNT HOLD FOR CASE NO OPEN CAMPAIGN BUT FAILED TEST	864 816
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A	Went Latch	CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT LATCH NEED TO CHECK ARM FOR DRIVER SIDE SEAT BELT PASSENGER SIDE SEAT BELT DOESNT HOLD FOR CASE NO OPEN CAMPAIGN BUT FAILED TEST	714
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	R	Reset Performed	CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT LATCH NEED TO CHECK ARM FOR DRIVER SIDE SEAT BELT PASSENGER SIDE SEAT BELT DOESNT HOLD FOR CASE NO OPEN CAMPAIGN BUT FAILED TEST	888
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	X X	Other Other	SEAT BELT BUCKLE INOPERATIVE SEAT BELTS BOP	713 821
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A	Went Latch	648 CUSTOMER STATES DRIVERS SEAT BELT FEELS END WONT LATCH CUSTOMER STATES THAT PASSENGER SIDE SEATBELT WILL COME UNLATCHED FOR NO REASON	881
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	C A	Unlatched/Released Went Latch	INSTALL BOP SEAT BELT REFER TO LAST FOR 112541	812 888
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A A B A	Went Latch Went Latch Went Stay Latched Went Latch	CUSTOMER STATES DRIVERS SEAT BELT WILL NOW BUCKLE OK (SEAT BELT WILL NOT BUCKLE) SEAT BELT BUCKLE WILL NOT HOLD CUSTOMER STATES PASS FRNT SEAT BELT WILL NOT LATCH PROP.	818 770 812 813
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	X	Other	626 CUSTOMER STATED UP SEATBELT RETRACTOR IS BOP INSTALL BOP	841
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A X X X	Went Latch Other Other Other	PASSENGER SEAT BELT BUCKLE WONT LATCH, BUCKLE IN PARTS SEAT BELTS NO WORKING CORRECTLY SEAT BELT NOT WORKING PROPERLY CUSTOMER STATES SEAT BELT BUCKLE ON DRIVER SIDE IS JAMMED	821 881 800 881
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A	Went Latch	CUSTOMER STATES THE DRIVER SIDE FRONT SEAT BELT LATCH BOP 5 000 CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT RETRACT PROPERLY	813 805
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	X B A	Other Went Stay Latched Went Latch	DRIVER SEAT BELT DOES NOT STAY LOCKED CUSTOMER STATES PASS FRONT SEAT BELT INTERMIT WONT BUCKLE	818 818
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	A	Went Latch	CUSTOMER STATES LEFT FRONT SEATBELT WONT LATCH INTO BUCKLE	804
RECALL 01021 CUSTOMER REPLACED PASS. SEAT BELT REPLACE DRIVERS SEAT BELT BUCKLE	X	Other	FRONT SEAT BELT IS BOP	913

SEAT BELT BUCKLE VISIBLY DAMAGED INTERNALLY RAR SEAT BELT  
 BUCKLE 81128A 84  
 REPLACE LF SEAT BELT BUCKLE 81128A (A H98) LF SEAT BELT BUCKLE  
 NOT HOLDING 84888 42  
 DAD 8 REPLACE RIGHT FRNT SEAT BUCKLE  
 REPLACE BOTH BELT BUCKELS 884888  
 DOES NOT OPERATE PROPERLY INSPECT RAR PASS FRONT SEAT BELT  
 BUCKLE

A	Went Latch	CUSTOMER STATES FRNT PASS SEAT BELT LATCH WOULD NOT LET YOU LATCH IT IN	806
C	Unlatching/Retracting	LEFT SIDE SEAT BELT KEEPS RELEASING	418
A	Went Latch	REPORT ON PASS SIDE FRONT SEAT BELT NOT LOCKING	808
X	Other	FRONT SEAT BELTS VERY HARD TO BUCKLE	031
B	Work Day Latched	PASS FRONT SEAT BELT DOES NOT ALWAYS STAY LOCKED	782

COUNTRY_CD	SUB_DUR_CD	TDL_CD	CNTRY_SOLD	CR1_CD	VR1_CD	ANL_VL_CD	VRT_CD	TLS_FLAG
CAN	484798	254	CAN	CR1	VR1	F7	808	0
CAN	488875	254	CAN	CR1	VR1	F7	808	
USA	127707		2 USA	CR1	VR1	F7	808	
USA	147968		2 USA	CR1	VR1	F7	808	
USA	141481		1 USA	CR1	VR1	F7	808	
CAN	488888		2 CAN	CR1	VR1	F7	808	
USA	123188		2 USA	CR1	VR1	F7	808	
USA	171471		1 USA	CR1	VR1	F7	808	
USA	121488		1 USA	CR1	VR1	80	808	0
USA	171488		1 USA	CR1	VR1	80	808	
USA	182882		1 USA	CR1	VR1	80	808	
USA	171170		2 USA	CR1	VR1	80	808	
USA	171885		1 USA	CR1	VR1	80	808	
USA	171177		1 USA	CR1	VR1	80	808	
USA	188880		2 USA	CR1	VR1	80	808	0
USA	175481		1 USA	CR1	VR1	80	808	
USA	188888	254	USA	CR1	VR1	80	808	0
USA	188808		1 USA	CR1	VR1	80	808	
USA	154888		1 USA	CR1	VR1	80	808	
USA	121437		2 USA	CR1	VR1	80	808	
USA	178840		1 USA	CR1	VR1	80	808	
USA	148811		2 USA	CR1	VR1	80	808	
USA	188803		1 USA	CR1	VR1	80	808	
USA	124888		2 USA	CR1	VR1	80	808	
USA	128888		1 USA	CR1	VR1	80	808	
USA	127732		1 USA	CR1	VR1	80	808	
USA	178807		1 USA	CR1	VR1	80	808	
USA	128888		1 USA	CR1	VR1	80	808	
USA	227888		1 USA	CR1	VR1	80	808	
USA	144217		2 USA	CR1	VR1	80	808	
USA	171178		1 USA	CR1	VR1	80	808	
USA	172284		1 USA	CR1	VR1	80	808	
USA	188887		2 USA	CR1	VR1	80	808	

USA	172300	1 USA	CR1	V05	L1	300
USA	182219	2 USA	CR1	V05	L1	300
USA	1827947 E04	USA	CR1	V05	L1	300
USA	181285 E04	USA	CR1	V05	L1	300
USA	184002	1 USA	CR1	V05	L1	300
USA	171102	1 USA	CR1	V05	L1	300
USA	171103	2 USA	CR1	V05	L1	300
USA	124000	2 USA	CR1	V05	L1	300
USA	123000 E04	USA	CR1	V05	L1	300
USA	162100	2 USA	CR1	V05	L1	300
USA	180414	1 USA	CR1	V05	L1	300
USA	127007 E04	USA	CR1	V05	L1	300
USA	184128 E04	USA	CR1	V05	L1	300
USA	184128 E04	USA	CR1	V05	L1	300
USA	171840	1 USA	CR1	V05	L1	300
USA	182100	2 USA	CR1	V05	L1	300
USA	124004 E04	USA	CR1	V05	L1	300
USA	123001	1 USA	CR1	V05	L1	300
USA	171104	1 USA	CR1	V05	L1	300
USA	171400 E04	USA	CR1	V05	L1	300
USA	184000 E04	USA	CR1	V05	L1	300
USA	184002 E04	USA	CR1	V05	L1	300
USA	118400 E04	USA	CR1	V05	L1	300
USA	180000	1 USA	CR1	V05	L1	300
USA	184125 E04	USA	CR1	V05	L1	300
USA	180017	2 USA	CR1	V05	L1	300
USA	180071 E04	USA	CR1	V05	L1	300
USA	127400	2 USA	CR1	V05	L1	300
USA	124000 E01	USA	CR1	V05	L1	300
USA	152000 E04	USA	CR1	V05	L1	300
USA	141078 E04	USA	CR1	V05	L1	300
USA	181200 E03	USA	CR1	V05	L1	300
USA	180400	2 USA	CR1	V05	L1	300
USA	171000	1 USA	CR1	V05	L1	300

USA	171800	EM4	USA	Q21	V05	L1	305
USA	148211		2 USA	Q21	V05	L1	305
USA	173060		1 USA	Q21	V05	L1	305
USA	171952		1 USA	Q21	V05	L1	305
USA	141088		1 USA	Q21	V05	L1	305
USA	181843		1 USA	Q21	V05	L1	305
USA	182019	EM4	USA	Q21	V05	L1	305
USA	171480		1 USA	Q21	V05	L1	305
USA	188826	EM4	USA	Q21	V05	L1	305
USA	174210	EM4	USA	Q21	V05	L1	305
USA	178378		1 USA	Q21	V05	L1	305
USA	174548		1 USA	Q21	V05	L1	305
USA	111212		2 USA	Q21	V05	L1	305
USA	182918		2 USA	Q21	V05	L1	305
USA	178412	EM4	USA	Q21	V05	L1	305
USA	171040	EM4	USA	Q21	V05	L1	305
USA	184824		2 USA	Q21	V05	L1	305
USA	188888		2 USA	Q21	V05	L1	305
USA	111882		1 USA	Q21	V05	L1	305
USA	184884	EM4	USA	Q21	V05	L1	305
USA	184884		2 USA	Q21	V05	L1	305
USA	188888		2 USA	Q21	V05	L1	305
USA	118470		1 USA	Q21	V05	L1	305
USA	184887	EM4	USA	Q21	V05	L1	305
USA	171481		2 USA	Q21	V05	L1	305
USA	171188		1 USA	Q21	V05	L1	305
USA	171838		2 USA	Q21	V05	L1	305
USA	188888		2 USA	Q21	V05	L1	305
USA	118881		1 USA	Q21	V05	L1	305
USA	188815		2 USA	Q21	V05	L1	305
USA	188888	EM4	USA	Q21	V05	L1	305
USA	118882	EM4	USA	Q21	V05	L1	305
USA	181218		1 USA	Q21	V05	L1	305
USA	171177		1 USA	Q21	V05	L1	305
USA	188885		1 USA	Q21	V05	L1	305
USA	182008		1 USA	Q21	V21	L1	510
USA	171434		1 USA	Q21	V05	L1	305
USA	182798		1 USA	Q21	V05	L1	305

USA	184644	1 USA	CR1	V08	L1	808
USA	183008	2 USA	CR1	V01	L1	801
USA	184288	2 USA	CR5	V05	L1	805
USA	171179	1 USA	CR1	V08	L1	808
USA	171400	1 USA	CR1	V08	L1	808
USA	182847 891	USA	CR1	V08	L1	808
USA	182547 894	USA	CR1	V08	L1	808
USA	182246	1 USA	CR1	V08	L1	808
USA	182120	2 USA	CR1	V08	L1	808
USA	182271	1 USA	CR1	V08	L1	808
USA	182784	1 USA	CR1	V08	L1	808
USA	184448	1 USA	CR1	V08	L1	808
USA	188880	1 USA	CR1	V08	L1	808
USA	184888	1 USA	CR1	V08	L1	808
USA	184818	1 USA	CR1	V08	L1	808
USA	184815	1 USA	CR1	V08	L1	808
USA	188782	1 USA	CR1	V74	L1	808
USA	188880	1 USA	CR1	V08	L1	808
USA	182884	1 USA	CR1	V08	L1	808
USA	184814 894	USA	CR1	V08	L1	808
USA	188882	2 USA	CR1	V07	L1	808
USA	171884	1 USA	CR1	V71	L1	808
USA	171888 894	USA	CR1	V08	L1	808
USA	171188	1 USA	CR1	V05	L1	808
USA	171888	1 USA	CR1	V08	L1	808
USA	182188 894	USA	CR1	V08	L1	808
USA	171178	2 USA	CR1	V08	L1	808
USA	181488 894	USA	CR1	V08	L1	808
USA	181884	1 USA	CR1	V08	L1	808
USA	171888 894	USA	CR1	V08	L1	808
USA	171818	1 USA	CR1	V08	L1	808
USA	172882	1 USA	CR1	V08	L1	808
USA	184888	2 USA	CR1	V08	L1	808
USA	171886	1 USA	CR1	V08	L1	808
USA	181288	1 USA	CR1	V08	L1	808
USA	181487	2 USA	CR1	V08	L1	808
USA	181881 894	USA	CR1	V76	L1	807
USA	181718	1 USA	CR1	V08	L1	808
USA	171782	1 USA	CR1	V08	L1	808

USA	182144	USA	CR1	V05	L1	895
USA	171488	1 USA	CR1	V05	L1	898
USA	171487	USA	CR1	V05	L1	898
USA	171887	1 USA	CR1	V05	L1	898
USA	171876	1 USA	CR1	V05	L1	898
USA	121884	USA	CR1	V05	L1	898
USA	122284	1 USA	CR1	V05	L1	898
USA	121881	1 USA	CR1	V05	L1	898
USA	18804L	USA	CR1	V05	L1	898
USA	112881	1 USA	CR1	V05	L1	898
USA	111488	1 USA	CR1	V05	L1	898
USA	141888	USA	CR1	V05	L1	898
USA	172284	2 USA	CR1	V05	L1	898
USA	172283	1 USA	CR1	V05	L1	898
USA	112883	2 USA	CR1	V05	L1	898
USA	118888	USA	CR1	V05	L1	898
USA	171884	1 USA	CR1	V17	L1	898
USA	127418	1 USA	CR1	V05	L1	898
USA	141801	1 USA	CR1	V05	L1	898
USA	173488	1 USA	CR1	V05	L1	898
USA	127088	1 USA	CR1	V08	L1	898
USA	127440	USA	CR1	V05	L1	898
USA	183271	USA	CR1	V05	L1	898
USA	148078	1 USA	CR1	V05	L1	898
USA	184218	2 USA	CR1	V05	L1	898
USA	188800	USA	CR1	V05	L1	898
USA	122428	2 USA	CR1	V05	L1	898
USA	188447	1 USA	CR1	V05	L1	898
USA	148881	USA	CR1	V05	L1	898
USA	183870	1 USA	CR1	V08	L1	898
USA	172208	USA	CR1	V08	L1	898
USA	188807	1 USA	CR1	V08	L1	898
USA	188807	1 USA	CR1	V05	L1	898
USA	173484	1 USA	CR1	V05	L1	898
USA	187088	2 USA	CR1	V05	L1	898
USA	179421	USA	CR1	V05	L1	898
USA	127088	2 USA	CR1	V05	L1	898
USA	144128	1 USA	CR1	V08	L1	898
USA	187088	USA	CR1	V05	L1	898

USA	171480	USA	Q21	V08	L1	808
USA	153888	USA	Q21	V05	L1	808
USA	127014	1 USA	Q21	V08	L1	808
USA	113488	1 USA	Q21	V05	L1	808
USA	181488	USA	Q21	V08	L1	808
USA	328881	1 USA	Q21	V05	L1	808
USA	177080	8 USA	Q21	V02	L1	808
USA	141888	1 USA	Q21	V05	L1	808
USA	121018	1 USA	Q21	V08	L1	808
USA	121208	USA	Q21	V05	L1	808
USA	171080	2 USA	Q21	V05	L1	808
USA	188427	1 USA	Q21	V05	L1	808
USA	188402	1 USA	Q21	V08	L1	808
USA	182211	USA	Q21	V08	L1	808
USA	178878	USA	Q21	V05	L1	808
USA	121088	1 USA	Q21	V08	L1	808
USA	188427	1 USA	Q21	V02	L1	808
USA	141888	1 USA	Q21	V08	L1	808
USA	152028	1 USA	Q21	V05	L1	808
USA	128848	1 USA	Q21	V08	L1	808
USA	181888	2 USA	Q21	V08	L1	808
USA	141842	1 USA	Q21	V05	L1	808
USA	188802	1 USA	Q21	V08	L1	808
USA	148878	2 USA	Q21	V05	80	808
USA	127854	1 USA	Q21	V05	80	808
USA	171848	1 USA	Q21	V08	80	808
USA	141078	1 USA	Q21	V05	80	808
USA	188808	1 USA	Q21	V05	80	808
USA	178428	1 USA	Q21	V08	80	808
USA	171827	USA	Q21	V08	80	808
USA	162788	USA	Q21	V08	80	808
USA	150888	1 USA	Q21	V74	80	808
USA	171228	1 USA	Q21	V05	80	808
USA	178880	2 USA	Q21	V02	80	808
USA	171840	1 USA	Q21	V05	80	808
USA	113405	1 USA	Q21	V05	80	808
USA	113487	2 USA	Q21	V05	80	808
USA	127081	1 USA	Q21	V02	80	808



USA	171178	2 USA	CP7	Y88	83	803
USA	188975 EM4	USA	CP7	Y88	88	803
USA	187942	1 USA	CP3	Y88	83	803
USA	188888 EM4	USA	CP1	Y85	83	806
USA	184488 EM4	USA	CP1	Y85	88	806
USA	141032	1 USA	CP1	Y85	88	806
USA	113887	1 USA	CP9	Y85	83	806
USA	121886	1 USA	CP1	Y88	83	806
USA	171894	1 USA	CP1	Y85	83	806
USA	171887 EM4	USA	CP1	Y85	83	806
USA	141743	2 USA	CP1	Y88	88	806
USA	113884	2 USA	CP7	Y85	83	806
USA	141743	2 USA	CP1	Y85	83	806
CAN	488422	2 CAN	CP1	Y85	83	806
USA	171178	2 USA	CP1	Y88	83	806
USA	188948	2 USA	CP1	Y88	83	806
USA	128874	1 USA	CP1	Y85	88	806
USA	111882 EM4	USA	CP1	Y85	83	806
USA	188814	1 USA	CP1	Y85	83	806
USA	188880	1 USA	CP1	Y88	83	806
USA	184478 EM4	USA	CP1	Y85	83	806
USA	221488	1 USA	CP1	Y88	83	806
USA	171188	1 USA	CP1	Y88	83	806
USA	118836	2 USA	CP1	Y88	83	806
USA	111880	1 USA	CP1	Y88	83	806
USA	188888	1 USA	CP1	Y88	83	806
USA	188918	1 USA	CP1	Y85	83	806
USA	487821	2 CAN	CP1	Y88	83	806
USA	188882	2 USA	CP1	Y88	83	806
USA	188848	2 USA	CP1	Y85	83	806
USA	171880	2 USA	CP5	Y85	83	806
USA	144484	1 USA	CP1	Y85	83	806
USA	163889	1 USA	CP1	Y85	83	806
USA	171488	1 USA	CP6	Y85	83	806
USA	173884	2 USA	CP1	Y88	83	806
USA	188879	1 USA	CP1	Y85	83	806
USA	188873	1 USA	CP1	Y88	83	806
USA	123887 EM4	USA	CP1	Y88	83	806
USA	123886	1 USA	CP1	Y88	83	806
USA	123888	1 USA	CP1	Y88	83	806

USA	127124	1 USA	Q21	V08	53	300	
USA	171178	1 USA	Q21	V08	53	300	
USA	134223 EM	USA	Q21	V08	53	300	
USA	171178	2 USA	Q21	V08	53	300	
USA	158219	1 USA	Q21	V77	59	300	
USA	124428	1 USA	Q21	V08	53	300	
USA	152018	1 USA	Q21	V07	54	300	
USA	122022	1 USA	Q21	V08	53	300	
USA	171040	1 USA	Q21	V08	53	300	
USA	171040	1 USA	Q21	V08	53	300	
USA	154428	1 USA	Q21	V05	53	300	
USA	152754	1 USA	Q21	V08	53	300	
USA	122854	1 USA	Q21	V74	53	300	
USA	124424	1 USA	Q21	V05	53	300	
USA	171018	1 USA	Q21	V07	53	300	
USA	152254	1 USA	Q21	V08	53	300	
USA	171288	1 USA	Q21	V05	53	300	
USA	124852	1 USA	Q21	V05	53	300	
USA	171427	1 USA	Q21	V08	53	300	
USA	171424	1 USA	Q21	V05	53	300	
USA	124878	1 USA	Q21	V08	53	300	
USA	121573	1 USA	Q21	V05	53	300	
USA	121573 EM	USA	Q21	V08	53	300	
USA	158211	1 USA	Q21	V08	53	300	
USA	124428	1 USA	Q21	V05	53	300	
USA	124424	1 USA	Q21	V06	53	300	
USA	122858	1 USA	Q21	V17	53	300	
USA	171028	2 USA	Q21	V05	53	300	
USA	171588	1 USA	Q21	V05	53	300	
USA	171423	1 USA	Q21	V08	53	300	
USA	152258	1 USA	Q21	V05	53	300	
USA	121788	1 USA	Q21	V08	53	300	
USA	124428	1 USA	Q21	V08	53	300	
USA	171028	1 USA	Q21	V08	53	300	
USA	171417 EM	USA	Q21	V08	53	300	

USA	121089	1 USA	Q21	V05	89	308	
USA	121095	1 USA	Q21	V05	89	308	
USA	121104	1 USA	Q21	V05	89	308	
USA	109892	1 USA	Q21	V05	89	308	
USA	124294	1 USA	Q21	V74	89	308	
USA	169016	1 USA	Q21	V05	89	309	0
USA	171087	1 USA	Q21	V05	89	309	
USA	121098	1 USA	Q21	V05	89	309	
USA	171094	1 USA	Q21	V05	89	309	
USA	171091	1 USA	Q21	V05	89	309	
USA	171179 EB4	USA	Q21	V05	89	309	
USA	121092	1 USA	Q21	V05	89	309	
USA	147018	1 USA	Q21	V05	89	309	
USA	121093	1 USA	Q21	V05	89	309	
USA	121096	1 USA	Q21	V05	89	309	0
USA	171071	1 USA	Q21	V05	89	309	
USA	121097	1 USA	Q21	V05	89	309	0
USA	121094	1 USA	Q21	V05	89	309	
USA	121095	1 USA	Q21	V05	89	309	
USA	141059 EB4	USA	Q21	V05	89	309	
USA	171093	1 USA	Q21	V05	89	309	
USA	121084	1 USA	Q21	V05	89	309	
USA	121091	1 USA	Q21	V05	89	309	
USA	171084	1 USA	Q21	V05	89	309	
USA	171083	1 USA	Q21	V05	89	309	
USA	109894	1 USA	Q21	V05	89	309	
USA	121092 EB4	USA	Q21	V05	89	309	
USA	121093	1 USA	Q21	V74	89	309	
USA	121018	1 USA	Q21	V05	89	309	
USA	121010	1 USA	Q21	V05	89	309	0

USA	184000	1 USA	CR1	V80	88	308
USA	124000	1 USA	CR1	V85	83	308
USA	171780	1 USA	CR1	V85	83	308
USA	152027	1 USA	CR1	V85	88	308
USA	127488	1 USA	CR1	V85	83	308
USA	115488	1 USA	CR1	V85	83	308
USA	128880 E94	USA	CR1	V85	83	308
USA	113080	1 USA	CR1	V85	83	308
USA	147488	1 USA	CR1	V85	83	308
USA	187080	1 USA	CR1	V88	84	308
USA	128881	1 USA	CR1	V85	83	308
USA	182081	1 USA	CR1	V88	83	308
USA	171080	1 USA	CR1	V85	83	308
USA	179488	1 USA	CR1	V85	88	308
USA	121481	1 USA	CR1	V88	84	308
USA	179488	2 USA	CR1	V85	83	308
USA	131248	2 USA	CR1	V85	83	308
USA	171480	2 USA	CR1	V85	83	308
USA	121480	1 USA	CR1	V88	83	308
USA	121274	1 USA	CR1	V87	83	308
USA	182241	1 USA	CR1	V85	83	308
USA	124389	1 USA	CR1	V88	83	308
USA	121019	1 USA	CR1	V85	83	308
USA	171081 E94	USA	CR1	V88	83	308
USA	168880	2 USA	CR1	V88	83	308
USA	127088	1 USA	CR1	V88	83	308
USA	124280	1 USA	CR1	V88	83	308
USA	182088	1 USA	CR1	V88	83	308
USA	182083 E94	USA	CR1	V88	83	308
USA	182100	1 USA	CR1	V85	88	308
USA	162218	1 USA	CR1	V88	83	308
USA	134488	1 USA	CR1	V88	83	308
USA	171540	1 USA	CR1	V88	83	308
USA	171040	1 USA	CR1	V88	83	308
USA	124010	1 USA	CR1	V85	83	308
USA	152080	1 USA	CR1	V85	83	308
USA	188148	1 USA	CR1	V85	83	308

USA	102185	200	USA	021	V02	01	300
USA	171889	1	USA	021	V05	00	300
USA	180703	2	USA	021	V05	00	300
USA	171089	1	USA	021	V74	00	300
USA	180204	2	USA	021	V05	00	300
USA	180207	1	USA	021	V02	00	300
USA	182402	1	USA	021	V05	00	300
USA	182100	1	USA	021	V02	00	300
USA	182400	1	USA	021	V05	00	300
USA	171164	1	USA	021	V05	00	300
USA	180202	1	USA	021	V05	00	300
USA	180213	2	USA	021	V05	00	300
USA	171084	2	USA	021	V05	00	300
USA	171040	2	USA	021	V05	00	300
USA	182202	2	USA	021	V05	00	300
USA	171040	1	USA	021	V02	00	300
USA	182205	1	USA	021	V05	00	300
USA	180404	1	USA	021	V05	00	300
USA	182100	1	USA	021	V05	00	300
USA	180800	1	USA	021	V05	00	300
USA	182010	1	USA	021	V05	00	300
USA	180018	1	USA	021	V05	00	300
USA	170055	1	USA	021	V05	00	300
USA	180010	2	USA	021	V77	00	300
USA	120643	1	USA	021	V02	00	300
USA	170820	1	USA	021	V05	00	300
USA	171026	1	USA	021	V02	00	300
USA	182071	1	USA	021	V05	00	300
USA	170052	1	USA	021	V05	00	300
USA	184484	1	USA	021	V05	00	300
USA	170100	1	USA	021	V05	00	300
USA	182021	1	USA	021	V05	00	300
USA	180201	1	USA	021	V05	00	300
USA	180204	1	USA	021	V05	00	300
USA	181000	1	USA	021	V74	00	300
USA	171102	1	USA	021	V05	00	300
USA	120641	2	USA	021	V74	00	300

USA	124212	1 USA	CR1	V08	83	808
USA	126214	1 USA	CR1	V71	83	806
USA	179088	1 USA	CR1	V05	83	808
USA	179088	1 USA	CR1	V05	88	808
USA	179087	1 USA	CR1	V08	83	808
USA	179088	1 USA	CR1	V08	88	808
USA	180470 EB4	USA	CR1	V05	L1	808
USA	188844	1 USA	CR1	V05	L1	808
USA	188880	1 USA	CR1	V08	L1	808
USA	171428	1 USA	CR1	V08	L1	808
USA	171428	1 USA	CR1	V05	L1	808
USA	171173	1 USA	CR1	V08	L1	806
USA	180888 EB4	USA	CR1	V05	L1	808
USA	188806	1 USA	CR1	V03	L3	808
USA	148844	2 USA	CR1	V06	L1	808
USA	188888 EB4	USA	CR1	V05	L1	808
USA	171881	2 USA	CR1	V08	L1	808
USA	188808	2 USA	CR1	V74	L1	808
USA	118442	2 USA	CR1	V06	L1	808
USA	188813 EB4	USA	CR1	V08	L1	808
USA	181213 EB4	USA	CR1	V08	L1	808
USA	184413	1 USA	CR1	V05	L1	808
USA	188886	2 USA	CR1	V05	L1	806
USA	188888	1 USA	CR1	V05	L1	806
USA	178880	1 USA	CR1	V08	L1	808
USA	18888K EB4	USA	CR1	V05	L1	808
USA	187414	1 USA	CR1	V05	L1	808
USA	127414	1 USA	CR1	V06	L1	808
USA	174488	2 USA	CR1	V05	L1	808
USA	181180	1 USA	CR1	V74	L1	808
USA	188813 EB4	USA	CR1	V05	L1	808
USA	179483 EB4	USA	CR1	V08	L1	808
USA	182417	1 USA	CR1	V05	L1	808

USA	148844 EB4	USA	CE1	V08	L1	804		
USA	147990	1 USA	CE1	V08	L1	805		
USA	189392 EB4	USA	CE1	V08	L1	808	6	
USA	189398	1 USA	CE1	V08	L1	809		
USA	191988 EB4	USA	CE1	V08	L1	816	6	
USA	193484	1 USA	CE1	V08	L1	820		
USA	199481	1 USA	CE1	V08	L1	828		
USA	199899	2 USA	CE1	V74	L1	828		
USA	121814	2 USA	CE1	V05	L1	808		
USA	121748 EB4	USA	CE1	V05	L1	808		
USA	183082	1 USA	CE1	V05	L1	808		
USA	193089	1 USA	CE1	V08	L1	808		
USA	192140	1 USA	CE1	V08	L1	808		
USA	198201	1 USA	CE1	V08	L1	808		
USA	179888	1 USA	CE1	V08	L1	808		
USA	183086	2 USA	CE1	V08	L1	808		
USA	121886	1 USA	CE1	V08	L1	808		
USA	174488	2 USA	CE1	V08	L1	808		
USA	187047	1 USA	CE1	V08	L1	808		
USA	148808 EB4	USA	CE1	V08	L1	808		
USA	147998 EB4	USA	CE1	V08	L1	808		
USA	147118 EB4	USA	CE1	V08	L1	808		
USA	18904L	EB4	USA	CE1	V08	L1	808	
USA	172413	1 USA	CE1	V08	L1	808	4	
USA	183088	2 USA	CE1	V08	L1	808		
USA	179488	2 USA	CE1	V08	L1	808		
USA	174882	2 USA	CE1	V08	L1	808	6	
USA	148877 EB4	USA	CE1	V08	L1	808		
USA	193007	1 USA	CE1	V08	L1	808		
USA	181871 EB4	USA	CE1	V08	L1	808		
USA	171840	1 USA	CE1	V08	L1	808		
USA	124888 EB4	USA	CE1	V08	L1	808		

USA	771101	2 USA	Q01	V05	L1	200
USA	790025 E24	USA	Q01	V05	L1	200
USA	902025	1 USA	Q01	V05	L1	200
USA	172402	1 USA	Q01	V05	L1	200
USA	172408	1 USA	Q01	V05	L1	200
USA	172405	1 USA	Q01	V05	F7	200
USA	182024	2 USA	Q01	V05	F7	200
USA	140020	1 USA	Q01	V05	F7	200
USA	141021	1 USA	Q01	V05	F7	200
USA	174010	2 USA	Q01	V05	F7	200
USA	140020	1 USA	Q01	V05	F7	200
USA	141020	2 USA	Q01	V05	F7	200
USA	127022	2 USA	Q01	V05	F7	200
USA	102777	2 USA	Q01	V05	F7	200
USA	102022	2 USA	Q01	V05	F7	200
USA	080027	1 USA	Q01	V05	F7	200
USA	102020	1 USA	Q01	V05	F7	200
USA	112016	1 USA	Q01	V05	F7	200
USA	121024	1 USA	Q01	V05	F7	200
USA	102025 E24	USA	Q01	V05	F7	200
USA	102100	2 USA	Q01	V05	F7	200
USA	102022	1 USA	Q01	V05	F7	200
USA	121402	1 USA	Q01	V05	F7	200
USA	121408	1 USA	Q01	V05	F7	200
USA	102022	1 USA	Q01	V05	F7	200
USA	080022	1 USA	Q01	V05	F7	200
USA	121022	1 USA	Q01	V05	F7	200
USA	171100	1 USA	Q01	V05	F7	200
USA	102470	1 USA	Q01	V05	F7	200
USA	102020 E24	USA	Q01	V05	F7	200
USA	102027	2 USA	Q01	V05	F7	200
USA	144020	1 USA	Q01	V05	F7	200
USA	102777	2 USA	Q01	V05	F7	200
USA	171020	1 USA	Q01	V05	F7	200
USA	171020	1 USA	Q01	V05	F7	200
USA	102022	1 USA	Q01	V05	F7	200
USA	102022	1 USA	Q01	V05	F7	200
USA	102022	1 USA	Q01	V05	F7	200
USA	172408	1 USA	Q01	V05	F7	200



USA	189419	2 USA	CR1	V05	F7	808	
USA	192499	2 USA	CR1	V05	F7	808	
USA	191818	1 USA	CR1	V05	F7	805	B
USA	189798	2 USA	CR1	V05	F7	805	
USA	183777	1 USA	CR1	V05	F7	806	
USA	179480	1 USA	CR1	V05	F7	808	
USA	179488	1 USA	CR1	V05	F7	808	
USA	179474	1 USA	CR1	V05	F7	808	
USA	184221 EM4	USA	CR1	V05	F7	808	
USA	183045	2 USA	CR1	V05	F7	808	
USA	174815	2 USA	CR1	V05	F7	808	
CAN	487241	2 CAN	CR1	V05	F7	808	
USA	194490	2 USA	CR1	V05	F7	808	
USA	171185	1 USA	CR1	V05	F7	808	
USA	173225	1 USA	CR1	V05	F7	808	B
USA	189882	2 USA	CR1	V05	F7	805	C
CAN	482541 EM4	CAN	CR1	V05	F7	808	
USA	188928 EM4	USA	CR1	V05	F7	805	
USA	175428	1 USA	CR1	V05	F7	808	
USA	149708	1 USA	CR1	V05	F7	808	
CAN	4A2817 EM4	CAN	CR1	V05	F7	805	
USA	171205	1 USA	CR1	V05	F7	805	
USA	144488	1 USA	CR1	V05	F7	808	
USA	171708	1 USA	CR1	V05	F7	808	
USA	181005	2 USA	CR1	V05	F7	805	B
USA	179488	2 USA	CR1	V05	F7	808	
USA	188708 EM4	USA	CR1	V05	F7	808	
USA	171954	1 USA	CR1	V05	F7	808	
USA	188821	1 USA	CR1	V05	F7	808	
USA	179871	1 USA	CR1	V05	F7	808	
USA	182825	2 USA	CR1	V05	F7	808	
USA	188853	2 USA	CR1	V05	F7	808	
USA	182572	1 USA	CR1	V05	F7	808	
USA	178219	2 USA	CR1	V05	F7	808	
USA	189188	2 USA	CR1	V05	F7	808	
USA	171175	1 USA	CR1	V05	F7	808	
USA	148225	1 USA	CR1	V05	F7	808	
USA	171432	1 USA	CR1	V05	F7	808	

USA	182078	1 USA	Q21	V85	F7	308
USA	178485	1 USA	Q21	V74	F7	308
USA	121489	1 USA	Q21	V85	F7	308
USA	171485	2 USA	Q21	V88	F7	308
USA	121880	2 USA	Q21	V85	F7	308
USA	182778 894	USA	Q21	V88	F7	308
USA	171488	1 USA	Q21	V88	F7	308
USA	174885 824	USA	Q21	V85	F7	308
USA	128448	2 USA	Q21	V86	F7	308
USA	173485	2 USA	Q21	V88	F7	308
USA	118284	1 USA	Q21	V85	F7	308
USA	188008 884	USA	Q21	V86	F7	308
USA	182789	2 USA	Q21	V85	F7	308
USA	178488	1 USA	Q21	V88	F7	308
USA	188001	1 USA	Q21	V86	F7	308
USA	182143	2 USA	Q21	V88	F7	308
USA	147813	1 USA	Q21	V85	F7	308
USA	178478	1 USA	Q21	V86	F7	308
USA	128278	2 USA	Q21	V83	F7	308
USA	171208	1 USA	Q21	V85	F7	308
USA	171488	2 USA	Q21	V88	F7	308
USA	182118	2 USA	Q21	V85	F7	308
USA	148211	2 USA	Q21	V88	F7	308
USA	171488 894	USA	Q21	V85	F7	308
USA	188488	2 USA	Q21	V85	F7	308
USA	138888	1 USA	Q21	V86	F7	308
USA	188418	1 USA	Q21	V88	F7	308
USA	128017	2 USA	Q21	V85	F7	308
USA	121281	1 USA	Q21	V85	F7	308
USA	128418	1 USA	Q21	V85	F7	308
USA	188808 894	USA	Q21	V85	F7	308

USA	70200	1 USA	Q21	V08	F7	308	
USA	70200	1 USA	Q21	V05	F7	308	
USA	70210	1 USA	Q21	V05	F7	308	
USA	110000	2 USA	Q21	V05	F7	308	
USA	70200	1 USA	Q21	V05	F7	308	
USA	144400	1 USA	Q21	V05	F7	308	
USA	127000 ED4	USA	Q21	V05	F7	308	
CAN	420000	1 CAN	Q21	V05	F7	308	
CAN	420000	1 CAN	Q21	V05	F7	308	
USA	121001	1 USA	Q21	V04	F7	311	*
USA	144001	1 USA	Q21	V05	F7	308	
USA	120702	2 USA	Q21	V05	F7	308	
USA	120300	1 USA	Q21	V05	F7	308	
CAN	420044	1 CAN	Q21	V05	F7	308	
USA	120000	2 USA	Q21	V05	F7	308	*
USA	120100	1 USA	Q21	V05	F7	308	
CAN	420040	1 CAN	Q21	V05	F7	308	
USA	110002	2 USA	Q21	V05	F7	308	
USA	120005	1 USA	Q21	V05	F7	308	
CAN	420040	2 CAN	Q21	V05	F7	308	
USA	120705	1 USA	Q21	V05	F7	308	
USA	120400	2 USA	Q21	V05	F7	308	
USA	120400	1 USA	Q21	V05	F7	308	
USA	140000	1 USA	Q21	V05	F7	308	*
CAN	444000	1 CAN	Q21	V05	F7	308	*
USA	144001	1 USA	Q21	V07	F7	308	
USA	120012	1 USA	Q21	V05	F7	308	
USA	120400	2 USA	Q21	V05	F7	308	*
USA	120707	1 USA	Q21	V05	F7	308	
USA	120707	1 USA	Q21	V05	F7	308	
USA	120400	1 USA	Q21	V05	F7	308	
USA	170001	1 USA	Q21	V05	F7	308	
USA	147000	2 USA	Q21	V05	F7	308	
USA	120000	1 USA	Q21	V05	F7	308	
USA	120012 ED4	USA	Q21	V05	F7	308	
USA	170007	1 USA	Q21	V05	F7	308	
USA	127004	1 USA	Q21	V05	F7	308	
USA	110000	1 USA	Q21	V05	F7	308	
USA	170000	1 USA	Q21	V05	F7	308	
USA	171004	1 USA	Q21	V05	F7	308	
USA	120000	2 USA	Q21	V05	F7	308	

USA	141827	1 USA	Q21	V05	F7	308	
USA	141827	1 USA	Q21	V05	F7	308	
CAN	427234	2 CAN	Q21	V05	F7	308	
USA	113480	1 USA	Q21	V05	F7	308	a
USA	111512	1 USA	Q21	V05	F7	308	
USA	144482	1 USA	Q21	V05	F7	308	
USA	141827	1 USA	Q21	V05	F7	308	
USA	118885	1 USA	Q21	V05	F7	308	
USA	118485	1 USA	Q21	V05	F7	308	
USA	181368	1 USA	Q21	V05	F7	308	
USA	111810	1 USA	Q21	V05	F7	308	
USA	143421	1 USA	Q21	V05	F7	308	a
USA	171889	1 USA	Q21	V05	F7	308	
USA	144881	1 USA	Q21	V05	F7	308	
USA	121384	1 USA	Q21	V05	F7	308	
USA	183000	2 USA	Q21	V05	F7	308	
USA	147476	1 USA	Q21	V05	F7	308	
USA	172815	1 USA	Q21	V05	F8	308	
USA	182007	1 USA	Q21	V05	F8	308	
USA	111522	1 USA	Q21	V05	F8	308	
USA	182000	1 USA	Q21	V05	F8	308	
USA	182013	1 USA	Q21	V05	F8	308	
USA	171040	1 USA	Q21	V05	F8	308	
USA	184788	1 USA	Q21	V05	F8	308	
USA	121824	1 USA	Q21	V05	F8	308	
USA	187417	1 USA	Q21	V05	F8	308	
USA	141824	2 USA	Q21	V05	F8	308	
USA	182824	1 USA	Q21	V05	F8	308	a
USA	184008	1 USA	Q21	V05	F8	308	
USA	182811	2 USA	Q21	V05	F8	308	a
USA	185434	1 USA	Q21	V05	F8	308	a
USA	172428	1 USA	Q21	V24	F8	308	
USA	187308	1 USA	Q21	V05	F8	308	
USA	147814	1 USA	Q21	V05	F8	308	
USA	189811	2 USA	Q21	V05	F8	308	
USA	182212	1 USA	Q21	V05	F8	308	
USA	147217	2 USA	Q21	V05	F8	308	

USA	100003	1 USA	Q21	V08	FB	300
USA	100048	1 USA	Q21	V05	FB	300
USA	100087	1 USA	Q21	V08	FB	300
USA	1437111	1 USA	Q21	V08	FB	300
USA	124288	1 USA	Q21	V05	FB	300
USA	121444	1 USA	Q21	V05	FB	300
USA	171171	1 USA	Q21	V05	FB	300
USA	122222	1 USA	Q21	V05	FB	300
USA	172200	1 USA	Q21	V08	FB	300
USA	140077	1 USA	Q21	V05	FB	300
USA	121000	2 USA	Q21	V05	FB	300
USA	147120	2 USA	Q21	V05	FB	300
USA	120206 ESM	USA	Q21	V05	FB	300
USA	113007	1 USA	Q21	V05	FB	300
USA	102704	2 USA	Q21	V05	FB	300
USA	107000	1 USA	Q21	V05	FB	300
USA	100702	1 USA	Q21	V74	FB	300
USA	147043 ESM	USA	Q21	V05	FB	300
USA	100000	2 USA	Q21	V08	FB	300
USA	104207	1 USA	Q21	V08	FB	300
USA	121002	2 USA	Q21	V08	FB	300
USA	102100 ESM	USA	Q21	V08	FB	300
USA	100704	1 USA	Q21	V08	FB	300
USA	122011	1 USA	Q21	V05	FB	300
USA	171000	1 USA	Q21	V05	FB	300
USA	171401	1 USA	Q21	V17	FB	300
USA	102000	1 USA	Q21	V08	FB	300
USA	100400	1 USA	Q21	V08	FB	300
USA	100000	1 USA	Q21	V08	FB	300
USA	102004	2 USA	Q21	V08	FB	300
USA	170400	1 USA	Q21	V05	FB	300
USA	140124	2 USA	Q21	V08	FB	300
USA	100000	2 USA	Q21	V08	FB	300
USA	100000	1 USA	Q21	V08	FB	300
USA	071170 ESM	USA	Q21	V08	FB	300
USA	100000	1 USA	Q21	V08	FB	300

USA	182440	3 USA	021	V08	FB	808	
USA	171682	2 USA	021	V88	FB	808	
USA	152793	1 USA	021	V74	FB	808	
USA	182923	1 USA	021	V88	FB	808	
USA	154883 E04	USA	021	V05	FB	808	
USA	154883	1 USA	021	V05	FB	808	
USA	182274	1 USA	021	V05	FB	808	
USA	182088	1 USA	021	V05	FB	808	
USA	141828	1 USA	021	V05	FB	808	
USA	124476	1 USA	021	V05	FB	808	
USA	152818	1 USA	021	V17	FB	808	
USA	134214	2 USA	021	V88	FB	808	
USA	128402 E04	USA	021	V88	FB	808	
USA	182025	2 USA	021	V88	FB	808	
USA	152807 E04	USA	021	V71	FB	808	
CAN	889477	1 CAN	021	V88	FB	808	
USA	171182	1 USA	021	V85	FB	808	
USA	171491	1 USA	021	V74	FB	808	
USA	171491	1 USA	021	V07	FB	808	
USA	144037	2 USA	021	V05	FB	808	
USA	182481 E04	USA	021	V05	FB	808	
USA	128286	2 USA	021	V05	FB	808	
USA	182011	2 USA	021	V05	FB	808	
USA	171430	1 USA	021	V05	FB	808	
USA	871888	1 USA	021	V08	FB	808	
USA	852873	1 USA	021	V05	FB	808	
USA	882788	1 USA	021	V08	FB	808	
USA	182782	1 USA	021	V88	FB	808	
USA	182828	2 USA	021	V88	FB	808	
USA	182788	2 USA	021	V85	FB	808	
USA	171152	1 USA	021	V88	FB	808	
USA	121022	1 USA	021	V88	FB	808	

USA	188259	1 USA	Q21	V08	F6	808
USA	184301	1 USA	Q21	V05	F6	808
USA	171102	2 USA	Q21	V05	F6	808
USA	185401	1 USA	Q21	V08	F6	808
USA	188228	1 USA	Q21	V05	F6	808
USA	175448	1 USA	Q21	V05	F6	808
USA	188288	1 USA	Q21	V05	F6	808
USA	188282	2 USA	Q21	V05	F6	808
USA	171040	1 USA	Q21	V05	F6	808
USA	172482	1 USA	Q21	V05	F6	808
USA	188220	2 USA	Q21	V05	F6	808
USA	124880	1 USA	Q21	V05	F6	808
USA	188488	1 USA	Q21	V05	F6	808
USA	188287	1 USA	Q21	V08	F6	808
USA	188182	1 USA	Q21	V05	F6	808
USA	188288	1 USA	Q21	V05	F6	808
USA	188282	1 USA	Q21	V05	F6	808
USA	181016	2 USA	Q21	V05	F6	808
USA	172480	1 USA	Q21	V05	F6	808
USA	182788	2 USA	Q21	V08	F6	808
USA	181480	2 USA	Q21	V05	F6	808
USA	181002	2 USA	Q21	V08	F6	808
USA	182047	2 USA	Q21	V08	F6	808
USA	188618	2 USA	Q21	V05	F6	808
USA	188047	1 USA	Q21	V05	F6	808
USA	181884	4 USA	Q21	V05	F6	808
USA	147088	1 USA	Q21	V08	F6	808
USA	182718	1 USA	Q21	V05	F6	808
USA	124444	1 USA	Q21	V05	F6	808
USA	178487	2 USA	Q21	V08	F6	808
USA	184455	2 USA	Q21	V05	F6	808
USA	188805	1 USA	Q21	V74	F6	808

USA	682985	1 USA	CR1	V05	F5	505	
USA	171088 E83	USA	CR1	V08	F5	505	
USA	171088 E83	USA	CR1	V05	F5	505	
USA	171088	1 USA	CR1	V05	F5	505	
USA	179451	1 USA	CR1	V08	F5	505	
USA	179481	1 USA	CR1	V08	F5	505	
USA	182764	2 USA	CR1	V08	F5	505	
USA	182762	1 USA	CR1	V74	F5	505	
USA	171040	1 USA	CR1	V08	F5	505	
USA	171089	1 USA	CR1	V05	F5	505	
USA	179013	1 USA	CR1	V08	F5	505	
USA	189085	8 USA	CR1	V05	F5	505	
USA	171085	3 USA	CR1	V05	F5	505	
USA	189394	1 USA	CR1	V05	F5	505	
USA	182148	1 USA	CR1	V06	F5	505	
USA	182718	1 USA	CR1	V05	F5	505	
USA	182682	2 USA	CR1	V05	F5	505	
USA	171055	1 USA	CR1	V05	F5	505	
USA	183050 E84	USA	CR1	V05	F5	505	
USA	171204	2 USA	CR1	V05	F5	505	
USA	171204 E83	USA	CR1	V08	F5	505	
USA	171204	1 USA	CR1	V05	F5	505	
USA	183480	2 USA	CR1	V05	F5	505	
USA	122518	1 USA	CR1	V05	F5	505	
USA	123282 E84	USA	CR1	V05	F5	505	
USA	171027 E84	USA	CR1	V08	F5	505	
USA	180508	1 USA	CR1	V08	F5	505	
USA	121648	1 USA	CR1	V05	F5	505	
USA	181381	1 USA	CR1	V08	F5	505	
USA	188882	4 USA	CR1	V05	F5	505	
USA	121334	1 USA	CR1	V05	F5	505	
USA	171089	1 USA	CR1	V05	F5	505	
USA	129481	1 USA	CR1	V08	F5	505	
USA	179048	1 USA	CR1	V05	F5	505	
USA	181687	1 USA	CR1	V05	F5	505	
USA	184125 E84	USA	CR1	V08	F5	505	
USA	171125	1 USA	CR1	V05	F5	505	



USA	184820	1 USA	021	V05	F5	300
USA	188124 E24	USA	021	V05	F5	300
USA	179940	1 USA	021	V05	F5	300
USA	178030	2 USA	021	V05	F5	300
USA	136220	1 USA	021	V05	F5	300
USA	162005	1 USA	021	V05	F5	300
USA	123140	1 USA	021	V05	F5	300
USA	171170 E24	USA	021	V05	F5	300
USA	123202	2 USA	021	V05	F5	300
USA	128002 E24	USA	021	V05	F5	300
USA	121024 E24	USA	021	V05	F5	300
USA	172430	2 USA	021	V05	F5	300
USA	162002 E24	USA	021	V05	F5	300
USA	171170	2 USA	021	V17	F5	300
USA	132832	1 USA	021	V05	F5	300
USA	171540	1 USA	021	V05	F5	300
USA	171800	1 USA	021	V05	F5	300
USA	172481	1 USA	021	V05	F5	300
USA	144805	1 USA	021	V24	F5	300
USA	171840	1 USA	021	V05	F5	300
USA	221810 E24	USA	021	V05	F5	300
USA	123221	1 USA	021	V05	F5	300
USA	123221	1 USA	021	V05	F5	300
USA	172430	2 USA	021	V05	F5	300
USA	124500	1 USA	021	V05	F5	300
USA	171888	1 USA	021	V05	F5	300
USA	162482	1 USA	021	V05	F5	300
USA	171424 E24	USA	021	V05	F5	300
USA	124210	1 USA	021	V05	F5	300
USA	124470	2 USA	021	V05	F5	300
USA	162410	1 USA	021	V05	F5	300
USA	144808	1 USA	021	V24	F5	300

USA	128801	2 USA	Q21	V88	FS	808
USA	182124	1 USA	Q21	V88	FS	808
USA	162847	1 USA	Q21	V88	FS	808
USA	171083	2 USA	Q21	V88	FS	808
USA	124823	2 USA	Q21	V88	FS	808
USA	171840	1 USA	Q21	V88	FS	808
USA	181783	1 USA	Q21	V88	FS	808
USA	162104	1 USA	Q21	V74	FS	808
USA	175484	1 USA	Q21	V88	FS	808
USA	182000	1 USA	Q21	V88	FS	808
USA	182801	1 USA	Q21	V88	FS	808
USA	178885 BSA	1 USA	Q21	V88	FS	808
USA	122886	1 USA	Q21	V17	FS	808
USA	188828 BSA	1 USA	Q21	V88	FS	808
USA	181877	2 USA	Q21	V88	FS	808
USA	171885	1 USA	Q21	V88	FS	808
USA	182888	1 USA	Q21	V88	FS	808
USA	188855	2 USA	Q21	V88	FS	808
USA	184818	1 USA	Q21	V88	FS	808
USA	184818	1 USA	Q21	V88	FS	808
USA	184484	1 USA	Q21	V88	FS	808
USA	173481	1 USA	Q21	V88	FS	808
USA	181487	1 USA	Q21	V88	FS	808
USA	141828	1 USA	Q21	V88	FS	808
USA	171181	1 USA	Q21	V88	FS	808
USA	163344	1 USA	Q21	V88	FS	808
USA	171484	1 USA	Q21	V88	FS	808
USA	188807	1 USA	Q21	V88	FS	808
USA	171848	1 USA	Q21	V88	FS	808
USA	178888	1 USA	Q21	V88	FS	808
USA	188800	1 USA	Q21	V88	FS	808
USA	171188	1 USA	Q21	V88	FS	808
USA	122888	1 USA	Q21	V88	FS	808
USA	188774	2 USA	Q21	V88	FS	808
USA	171878 BSA	1 USA	Q21	V88	FS	808
USA	121888	2 USA	Q21	V88	FS	808
USA	121488	1 USA	Q21	V88	FS	808
USA	181888	1 USA	Q21	V88	FS	808

USA	181488	2 USA	Q21	V05	F5	808
USA	182788	1 USA	Q21	V05	F5	808
USA	171884	1 USA	Q21	V05	F5	808
USA	182138 USA	USA	Q21	V77	F5	808
USA	123206	1 USA	Q21	V05	F5	808
USA	172221	2 USA	Q21	V05	F5	808
USA	172411 USA	USA	Q21	V05	F5	808
USA	172228	2 USA	Q21	V05	F5	808
USA	172210	1 USA	Q21	V05	F5	808
USA	162419	2 USA	Q21	V05	F5	808
USA	182200	1 USA	Q21	V05	F5	808
USA	123202	1 USA	Q21	V05	F5	808
USA	152202	1 USA	Q21	V05	F5	808
USA	134202	2 USA	Q21	V05	F5	808
USA	182207	1 USA	Q21	V05	F5	808
USA	162201	2 USA	Q21	V05	F5	808
USA	172201	2 USA	Q21	V05	F5	808
USA	121248	3 USA	Q21	V17	F5	808
USA	182208 USA	USA	Q21	V05	F5	808
USA	171227	1 USA	Q21	V05	F5	808
USA	171228	2 USA	Q21	V17	F5	808
USA	124428 USA	USA	Q21	V05	F5	808
USA	181728 USA	USA	Q21	V05	F5	808
USA	124018	1 USA	Q21	V05	F5	808
USA	182228	2 USA	Q21	V05	F5	808
USA	182228	1 USA	Q21	V05	F5	808
USA	121218	2 USA	Q21	V05	F5	808
USA	182128	2 USA	Q21	V05	F5	808
USA	682228	1 USA	Q21	V05	F5	808
USA	121218	1 USA	Q21	V05	F5	808
USA	171128	1 USA	Q21	V05	F5	808
USA	122228 USA	USA	Q21	V05	F5	808
USA	171128	1 USA	Q21	V05	F5	808
USA	121228	2 USA	Q21	V05	F5	808
USA	162228 USA	USA	Q21	V05	F5	808
USA	122228	1 USA	Q21	V05	F5	808

USA	102986	1 USA	Q21	V88	F5	580
USA	172488	1 USA	Q21	V86	F5	580
USA	171088	1 USA	Q21	V85	F5	584
USA	122548	2 USA	Q21	V88	F6	584
USA	124002	1 USA	Q21	V85	F5	588
USA	124002 ESM	USA	Q21	V85	F5	588
USA	141818	1 USA	Q21	V85	F5	595
DAN	484818	2 DAN	Q21	V85	F5	595
USA	148418	2 USA	Q21	V81	F5	595
USA	113297	1 USA	Q21	V85	F5	598
USA	121910	1 USA	Q21	V77	F5	598
USA	123882	1 USA	Q21	V88	F6	598
USA	123782	1 USA	Q21	V85	F5	598
USA	182782 ESM	USA	Q21	V81	F5	598
USA	142714	1 USA	Q21	V85	F5	598
USA	182703	1 USA	Q21	V85	F5	598
USA	182673	1 USA	Q21	V85	F5	598
USA	158852	1 USA	Q21	V85	F5	598
USA	182828	2 USA	Q21	V85	F5	598
USA	182828	1 USA	Q21	V85	F5	598
USA	174815	1 USA	Q21	V88	F5	598
USA	174815	2 USA	Q21	V88	F5	598
USA	121881	2 USA	Q21	V85	F5	598
USA	122803 ESM	USA	Q21	V85	F5	598
USA	112481	2 USA	Q21	V88	F5	598
USA	141478	1 USA	Q21	V85	F5	598
USA	174884	2 USA	Q21	V85	F5	598
USA	134825	2 USA	Q21	V85	F5	598
USA	143228	2 USA	Q21	V85	F5	598
USA	141258	1 USA	Q21	V85	F5	598
USA	123728	2 USA	Q21	V85	F5	598
USA	177048	1 USA	Q21	V85	F5	598
USA	162781 ESM	USA	Q21	V85	F5	598
USA	122715	2 USA	Q21	V85	F5	598

USA	174071	1 USA	CR1	V05	F5	308	
USA	170953	1 USA	CR1	V08	F8	308	
USA	171178 EBA	USA	CR1	V05	F5	308	
CAN	489988	1 CAN	CR1	V88	F8	308	
USA	132480	2 USA	CR1	V88	F5	308	
USA	136414	2 USA	CR1	V08	F8	308	
USA	139486	1 USA	CR1	V88	F8	308	
USA	132188	1 USA	CR1	V88	F8	308	
USA	138008	1 USA	CR1	V05	F5	308	
USA	132232	1 USA	CR1	V74	F3	308	
USA	131488	1 USA	CR1	V85	F5	308	
USA	138828	1 USA	CR1	V88	F8	308	
USA	136488	1 USA	CR1	V88	F8	308	
USA	162852	1 USA	CR1	V05	F5	308	
USA	168814	2 USA	CR1	V08	F8	308	
USA	188888	1 USA	CR1	V21	F8	310	
USA	148888 EBA	USA	CR1	V05	F5	308	
USA	118888	2 USA	CR1	V08	F8	308	
USA	487212	2 CAN	CR1	V08	F8	308	
USA	487212	2 CAN	CR1	V05	F5	308	
USA	130178	2 USA	CR1	V03	F5	308	
CAN	487220	EBA	CR1	V88	F8	308	
USA	771080	1 USA	CR1	V88	F8	308	
USA	111221	1 USA	CR1	V05	F5	308	
USA	188717 EBA	USA	CR1	V88	F8	308	
USA	127028	1 USA	CR1	V88	F8	308	
USA	113428	1 USA	CR1	V88	F8	308	
USA	178408	1 USA	CR1	V88	F8	308	
USA	178808	1 USA	CR1	V88	F8	308	
USA	144808	1 USA	CR1	V74	F3	308	
USA	158851 EBA	USA	CR1	V05	F5	308	
USA	142143	1 USA	CR1	V88	F8	308	
USA	138872	2 USA	CR1	V05	F5	308	
USA	121488	1 USA	CR1	V05	F5	308	
USA	172408	1 USA	CR1	V05	F5	308	
USA	138808	2 USA	CR1	V74	F3	308	
USA	141888	1 USA	CR1	V05	F5	308	
USA	172808	1 USA	CR1	V08	F8	308	
USA	123071	1 USA	CR1	V88	F8	308	

USA	18289	2 USA	CR1	V08	F5	808
USA	171772	1 USA	CR1	V08	F8	808
USA	147082 DM4	USA	CR1	V08	F8	808
USA	182130	1 USA	CR1	V74	F6	808
USA	152772	1 USA	CR1	V08	F8	808
CAN	448890	8 CAN	CR1	V08	F8	808
USA	182014	2 USA	CR1	V08	F8	808
USA	188074	2 USA	CR1	V08	F8	808
USA	141343	1 USA	CR1	V08	F5	808
CAN	481027	1 CAN	CR1	V02	F2	808
USA	178228	1 USA	CR1	V08	F8	808
USA	124600	1 USA	CR1	V08	F6	808
USA	182188	1 USA	CR1	V08	F8	808
USA	141432	1 USA	CR1	V08	F5	808
USA	187874 DM4	USA	CR1	V08	F8	808
USA	144009	1 USA	CR1	V74	F8	808
USA	187118 DM4	USA	CR1	V08	F8	808
USA	119428	1 USA	CR1	V08	F8	808
USA	113460	1 USA	CR1	V08	F5	808
USA	188028 DM4	USA	CR1	V08	F5	808
USA	147089	1 USA	CR1	V08	F8	808
USA	124608	2 USA	CR1	V08	F8	808
CAN	480047	2 CAN	CR1	V08	F8	808
USA	171818	1 USA	CR1	V07	F6	808
USA	182488	1 USA	CR1	V08	F8	808
USA	188088	1 USA	CR1	V08	F8	808
USA	177840	1 USA	CR1	V08	F5	808
USA	188018 DM4	USA	CR1	V08	F5	808
USA	171884	2 USA	CR1	V08	F8	808
USA	144828	1 USA	CR1	V74	F8	808
USA	168882	1 USA	CR1	V08	F8	808
USA	144128	1 USA	CR1	V74	F8	808
USA	148282	1 USA	CR1	V08	F8	808