

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
BOOK 39
PART 4 OF 6

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair_PA RT_NUM _CAUS_ BASE	2001 Exped repeat repair_PA RT_NUM _CAUS_ SUFF	2001 Exped repeat repair_C UST_CO NC CD	2001 Exped repeat repair_CO ND CD	2001 Exped repeat repair_RPR_ DT	2001 Exped repeat repair_T1 S WSD	2001 Exped repeat repair_C LM KEY	2001 Exped repeat repair_MI LGE	2001 Exped repeat repair_D LR_CD	2001 Exped repeat repair_D LR_SUB CD	2001 Exped repeat repair_R EGION_ CD
7861203	CAA	S25	42	12/6/2001	7	5618773	9359	10409	*	NA
7861203	CAA	S25	42	6/10/2002	16	9126266	17960	10279	*	NA
7861202	BAC	S25	41	10/22/2001	5	5517997	8005	2381	*	NA
7861203	CAB	S26	41	5/13/2002	13	8830287	16324	13208	*	NA
7861202	BAB	S40	42	1/10/2002	8	6168777	10534	1990	*	NA
7861203	CAA	S25	42	11/27/2001	5	5410865	7222	10409	*	NA
7861203	CAA	S25	42	10/24/2001	8	4664319	6236	11280	*	NA
7861203	BAB	S40	42	8/19/2001	8	4635869	7147	45246	*	NA
7861203	CAB	S25	42	5/24/2002	10	5998294	12811	5513	*	NA
7861203	CAB	S40	42	8/31/2001	6	3411624	9428	13928	*	NA
7861203	CAA	S40	1	4/26/2002	10	8389735	19691	11804	*	NA
7861203	CAA	S26	42	5/7/2002	11	8468031	21309	10939	*	NA
7861202	BAB	S40	33	6/3/2002	13	9028778	14409	11216	*	NA
7861203	CAA	S26	42	2/5/2002	8	8747966	4518	12701	*	NA
7861203	CAA	S40	42	8/9/2001	1	3284804	3123	3172	*	NA
7861203	CAB	S26	42	5/16/2002	8	8666266	14515	13139	*	NA
7861203	CAA	S26	42	1/18/2002	10	6382268	10755	10328	*	NA
7861203	CAA	S40	42	2/5/2002	11	6903421	15410	12716	*	NA

R024-011 15999

01_Exped_NavFrontBuckle_Query

7861202	BAC	S40	42	8/8/2001	5	3098277	5392	13678	*	NA
7861203	CAB	S40	42	12/7/2001	6	5781429	8773	9801	*	NA
7861203	CAB	S25	41	4/18/2002	10	8108547	10264	11270	*	NA
7861203	BAA	S40	1	9/12/2001	1	3727057	1237	10910	*	NA
7861203	CAA	S25	42	12/4/2001	5	5563252	2472	12380	*	NA
7861203	CAA	S28	42	1/9/2002	7	8158497	15884	12826	*	NA
7861203	CAA	S40	42	10/30/2001	6	4804867	4093	10638	*	NA
7861203	CAA	S40	42	9/27/2001	7	4836277	7563	10593	*	NA
7861203	CAA	S40	42	11/21/2001	1	5380434	2909	12010	*	NA
7861203	CAA	A85	41	11/14/2001	3	5233541	2504	11270	*	NA
7861202	BAC	S40	42	5/16/2002	14	8755678	7589	10325	*	NA
7861203	CAA	S40	42	10/11/2001	1	4358713	498	11056	*	NA
7861203	CAA	S40	42	2/28/2002	0	7226233	255	10470	*	NA
7861203	CAB	S50	33	12/17/2001	6	6906148	10275	7897	*	NA
7861203	CAB	S25	41	5/15/2002	14	8702343	15512	10089	*	NA
7861203	CAA	S40	42	10/31/2001	8	5852383	15047	45220	*	NA
7861203	CAA	S40	42	3/1/2002	1	8195884	4501	5247	*	NA
7861203	CAA	S28	42	5/21/2002	12	8714143	19711	1765	*	NA
7861202	BAC	S25	42	8/17/2001	-1	3371164	25	10233	*	NA
7861203	BAA	S40	28	12/8/2001	8	5699862	5774	5668	*	NA
7861203	CAA	S28	42	5/16/2002	14	8837087	11029	7945	*	NA
7861203	CAA	S40	33	5/2/2002	9	8495410	20994	11630	*	NA
7861203	CAB	S40	42	3/11/2002	9	7508304	9428	10472	*	NA

R004-011 15688

01_Expd_NavFrontBuckle_Query

7881203	CAB	S26	41	3/7/2002	14	7329791	9182	10093	*	NA
7881203	CAA	S40	42	12/3/2001	5	5659663	9501	8927	*	NA
7881202	BAC	S26	42	5/15/2002	10	8653398	10789	10018	*	NA
7881203	CAA	S26	42	6/4/2002	6	9176942	21648	10056	*	NA
7881203	BAB	S40	42	10/29/2001	7	6005055	18160	45246	*	NA
7881203	BAB	S40	42	12/11/2001	8	6725537	18225	45246	*	NA
7881203	CAA	S40	42	1/3/2002	2	8131315	2604	11896	*	NA
7881203	CAA	A85	41	10/29/2001	6	4764892	3592	11270	*	NA
7881202	BAB	S25	33	5/2/2002	8	8544665	19803	10593	*	NA
7881203	BAA	S25	41	12/12/2001	6	6774081	6319	1239	*	NA
7881203	CAA	S40	42	7/31/2001	2	2881304	2838	11458	*	NA
7881203	CAB	S40	42	10/17/2001	12	4525438	13740	10311	*	NA
7881203	CAA	S40	1	11/14/2001	2	5144110	13437	12314	*	NA
7881203	CAB	S40	42	9/19/2001	12	3823072	19694	10013	*	NA
7881202	BAA	S25	42	1/10/2002	15	6184512	5409	10909	*	NA
7881203	CAA	S25	41	8/10/2001	3	2915030	6173	12832	*	NA
7881203	BAA	S40	42	10/10/2001	4	4806468	3851	13138	*	NA
7881202	BAB	S25	42	5/31/2002	18	8958859	34405	12805	*	NA
7881202	AAA	S40	42	12/12/2001	3	5742183	2976	1018	*	NA
7881203	CAA	S25	42	10/3/2001	9	4258218	7416	10175	*	NA
7881203	CAA	S26	69	5/13/2002	12	8627755	24025	10188	*	NA
7881203	CAB	S40	42	7/31/2001	2	2731428	2660	10021	*	NA
7881203	CAA	S40	42	8/22/2001	3	3229233	9270	10198	*	NA

R084-011 15918

01_Exped_NavFrontBuckle_Query

7861203	CAA	S26	42	6/11/2002	14	9130656	20286	11657	*	NA
7861203	CAA	S40	41	3/9/2002	11	7814151	7316	11843	*	NA
7861202	BAC	S40	42	10/16/2001	12	4565000	22404	11907	*	NA
7861203	CAA	S25	42	1/15/2002	9	6300020	14187	12711	*	NA
7861203	CAA	S25	42	1/15/2002	9	6300020	14187	12711	*	NA
7861203	BAB	S40	42	9/18/2001	0	4498071	1112	11907	*	NA
7861203	CAB	S40	42	11/15/2001	6	5191148	13273	4922	*	NA
7861203	CAA	S25	42	5/16/2002	14	8678386	11985	11645	*	NA
7861202	BAB	S40	42	12/27/2001	8	5966559	3127	10473	*	NA
7861203	CAA	S25	42	3/16/2002	11	8927443	16991	11607	*	NA
7861203	CAA	S26	1	5/4/2002	14	8488489	12795	11612	*	NA
7861203	CAA	S40	42	12/10/2001	7	5793222	11789	10955	*	NA
7861203	CAA	S40	42	2/11/2002	6	6903055	6583	11803	*	NA
7861203	CAA	S26	42	4/23/2002	11	8757026	12624	11803	*	NA
7861203	CAA	S26	41	2/2/2002	11	6678580	5909	271	*	NA
7861203	CAA	S26	69	4/24/2002	12	9234634	12329	12048	*	NA

R004-011 10611

01_Exped_NavFrontBuckle_Query

7861203	CAA	S40	12	11/23/2001	1	5286780	588	10157	*	NA
7861203	CAA	S40	42	8/18/2001	6	3373082	8399	11803	*	NA
7861202	BAB	S25	42	5/21/2002	15	8977369	20248	8718	*	NA
7861202	BAC	S26	41	4/19/2002	12	8235646	28003	12739	*	NA
7861202	AAA	S40	42	11/6/2001	2	4990130	8332	10184	*	NA
7861203	CAA	S25	42	11/6/2001	5	5234331	6082	11820	*	NA
7861202	BAB	S40	1	2/28/2002	10	7149558	13511	10240	*	NA
7861203	CAB	S26	42	8/24/2001	1	3584688	783	12314	*	NA
7861203	CAB	S26	42	1/16/2002	2	8554688	2102	10123	*	NA
7861202	BAC	S40	42	1/23/2002	8	8567024	11114	10864	*	NA
7861203	CAA	S26	42	1/5/2002	7	8176707	11705	5432	*	NA
7861203	BAB	S25	42	12/7/2001	6	8578284	12001	4540	*	NA
7861203	CAB	S40	1	10/6/2001	8	4488908	10024	6828	*	NA
7861203	CAB	S26	42	3/27/2002	11	7847851	15226	10870	*	NA
7861203	CAA	S26	42	2/11/2002	7	8879554	9459	11822	*	NA
7861203	CAA	S26	42	6/6/2002	13	9178589	12234	11633	*	NA
7861203	BAA	S40	42	9/17/2001	2	4000522	2838	5432	*	NA
7861203	CAB	S40	42	8/28/2001	8	3441279	5249	11803	*	NA
7861203	CAB	S25	42	1/22/2002	15	8468851	15140	11836	*	NA
7861202	BAB	S40	42	9/17/2001	8	3883370	13152	11408	*	NA
7861203	CAA	S40	42	4/4/2002	19	7878491	14777	11843	*	NA
7861203	CAB	S40	89	11/30/2001	9	6444415	17402	11655	*	NA
7861203	CAA	S25	41	11/17/2001	10	5262347	6765	10836	*	NA
7861203	CAA	S40	41	12/28/2001	12	8026697	14144	10346	*	NA
7861203	CAB	S26	43	5/21/2002	20	9027640	16887	10360	*	NA

NOB-011 15812

01_Exped_NavFrontBuckle_Query

7861202	BAB	S26	42	5/8/2002	13	8727782	24691	10111	*	NA
7861203	CAA	T90	42	12/31/2001	11	8074780	28237	10184	*	NA
7861202	BAB	S26	42	3/20/2002	13	7534630	27120	11907	*	NA
7861203	CAA	S25	42	5/7/2002	12	8571444	8065	9185	*	NA
7861203	BAA	S25	1	10/24/2001	4	4652618	5326	4511	*	NA
7861203	BAA	S25	42	5/10/2002	14	8614100	15817	2441	*	NA
7861203	CAA	S40	42	10/11/2001	3	4335779	5300	229	*	NA
7861203	BAA	S40	12	9/18/2001	7	3656747	5706	7851	*	NA
7861202	AAA	S26	42	4/18/2002	10	8343385	14489	878	*	NA
7861203	CAA	S40	1	9/12/2001	4	3668833	5158	543	*	NA
7861203	BAA	T90	33	11/14/2001	6	5133647	6426	4822	*	NA
7861202	AAA	S40	42	3/6/2002	12	7266468	11967	4511	*	NA
7861202	AAA	S40	42	5/10/2002	11	8746808	14022	4617	*	NA
7861202	AAA	T90	42	1/22/2002	11	7107843	13270	3573	*	NA
7861202	AAA	S26	42	12/5/2001	7	6136307	11009	481	*	NA
7861203	BAA	S40	42	9/20/2001	5	4100563	8998	509	*	NA
7861202	AAA	S40	42	5/30/2002	10	8943388	13820	4458	*	NA
7861203	CAA	S40	42	9/21/2001	4	4387466	3391	6042	*	NA
7861203	BAA	T90	42	6/14/2002	7	9223838	16253	4546	*	NA
7861202	AAA	S40	42	3/12/2002	10	7547441	5417	3908	*	NA
7861203	CAA	S25	42	11/5/2001	9	8582414	16128	7877	*	NA

R004-011 15613

01-Exped_NavFrontBuckle_Query

7861203	BAA	S40	42	1/17/2002	8	6504679	10621	1167	*	NA
7861203	BAA	S25	42	5/18/2002	12	8693891	17723	4908	*	NA
7861203	CAA	S40	42	8/18/2001	1	8085298	1559	4443	*	NA
7861203	CAA	S26	42	8/18/2002	14	9250092	33362	4212	*	NA
7861203	BAA	S26	42	2/20/2002	8	6996098	14584	4817	*	NA
7861203	BAB	S40	42	9/8/2001	1	4684727	2395	4500	*	NA
7861203	BAA	S26	42	5/15/2002	12	8644462	17880	4212	*	NA
7861203	CAA	S25	42	10/1/2001	5	4310753	10703	3060	*	NA
7861203	BAA	S40	42	8/7/2001	0	2887508	50	4945	*	NA
7861203	BAA	D50	42	8/13/2001	1	3748216	802	4858	*	NA
7861203	CAA	S26	42	4/15/2002	10	8018514	11494	6654	*	NA
7861203	CAA	S26	42	3/19/2002	10	7468847	17098	3073	*	NA
7861203	CAA	S40	42	10/27/2001	1	4788738	865	4527	*	NA
7861203	BAA	S40	42	11/12/2001	8	5294613	13127	712	*	NA
7861203	BAA	S26	42	4/25/2002	15	8212614	18575	402	*	NA
7861202	AAA	S40	1	1/21/2002	14	6513618	18581	4332	*	NA
7861203	CAA	S25	42	1/15/2002	7	6457565	6329	4212	*	NA
7861203	CAA	S25	42	1/8/2002	2	6174192	1254	4212	*	NA
7861203	CAA	S40	41	11/27/2001	11	5364410	21741	2923	*	NA
7861203	CAA	S25	42	10/22/2001	7	5248261	11110	1626	*	NA

ROB-011 13614

01 Exped NavFrontBucks Query

7861203	BAA	S40	42	10/29/2001	2	5335638	2652	4452	*	NA
7861202	BAB	S40	41	8/16/2001	4	3088650	4361	2577	*	NA
7861203	CAA	S40	41	8/5/2002	9	9098122	14894	5157	*	NA
7861203	BAA	S26	42	3/9/2002	10	7636804	12924	4446	*	NA
7861203	BAA	S40	42	12/17/2001	9	5894580	10000	1587	*	NA
7861203	BAA	S26	42	3/29/2002	10	7733212	16626	2414	*	NA
7861203	CAA	S25	41	6/6/2001	5	3479179	6100	472	*	NA
7861203	BAA	S40	42	8/28/2001	6	3385367	11425	2531	*	NA
7861203	BAA	S25	42	8/24/2001	8	3255158	8457	4908	*	NA
7861202	AAA	S40	42	2/11/2002	15	6838980	32818	1118	*	NA
7861203	CAA	S40	42	2/1/2002	7	8681087	8547	4545	*	NA
7861203	BAA	S26	42	5/16/2002	12	8685120	21003	2413	*	NA
7861202	AAA	S40	42	12/17/2001	11	5807629	13543	2486	*	NA
7861202	AAA	S40	1	3/11/2002	15	7388534	14649	1733	*	NA
7861203	BAA	S40	42	12/28/2001	8	6067705	8038	4569	*	NA
7861203	CAA	S40	42	12/5/2001	14	5524060	12504	4831	*	NA
7861202	AAA	S26	41	1/8/2002	12	8280917	13119	5414	*	NA
7861202	AAA	S25	41	1/24/2002	7	6478927	10734	2586	*	NA

01_Exped_NavFrontBuckle_Query

7861202	AAA	S40	42	10/10/2001	4	4817900	5934	3555	*	NA
7861203	CAA	S40	42	1/10/2002	9	8175999	6206	4931	*	NA
7861202	AAA	S40	1	5/9/2002	13	8558601	12700	2488	*	NA
7861203	BAA	S40	1	1/14/2002	7	8998439	12390	4411	*	NA
7861203	BAA	S40	42	8/8/2001	2	2901035	1819	4411	*	NA
7861203	CAA	S25	42	8/17/2001	5	3088888	3589	5589	*	NA
7861203	BAA	S26	41	6/11/2002	10	9113856	21237	1078	*	NA
7861202	BAB	S40	42	1/9/2002	9	8183974	10543	8119	*	NA
7861202	AAA	S26	42	4/25/2002	13	8306821	28534	1057	*	NA
7861203	BAB	S26	41	5/7/2002	7	8834840	8768	8293	*	NA
7861203	BAA	S40	42	10/8/2001	1	4488798	621	5493	*	NA
7861203	BBE	S40	42	9/27/2001	1	6044811	816	7430	*	NA
7861203	BAB	S26	42	5/28/2002	8	8911648	4844	2724	*	NA
7861203	BAB	S25	42	12/3/2001	8	5487437	11787	1071	*	NA
7861203	BAC	S40	42	2/27/2002	13	7340928	12871	3869	*	NA
7861202	AAB	S26	42	4/24/2002	11	9114453	12382	1340	*	NA
7861203	BAA	S40	42	11/8/2001	9	8030784	10820	80340	*	NA
7861203	BAA	S40	42	5/8/2002	9	8528308	18593	869	*	NA
7861203	BAC	S40	41	10/11/2001	5	4343988	8383	3025	*	NA
7861202	AAC	S40	42	3/13/2002	15	7860369	12250	20518	*	NA
7861203	BAB	S25	41	2/18/2002	8	6861665	12093	7459	*	NA

01_Exped_NavFrontBuckle_Query

7861203	BAB	S25	42	1/10/2002	18	6212052	31818	20881	*	NA
7861203	BAA	S40	42	3/13/2002	5	7479986	5589	8738	*	NA
7861203	BAB	S40	42	9/27/2001	8	4008889	10497	10528	*	NA
7861203	CAA	S28	42	2/22/2002	12	7130737	18608	1229	*	NA
7861203	BBE	S25	42	11/27/2001	4	5391080	6885	1425	*	NA
7861203	BAB	S40	42	1/22/2002	1	6402478	590	4823	*	NA
7861202	AAC	S40	42	12/28/2001	8	6029560	5536	20599	*	NA
7861203	BAC	S40	42	8/20/2001	9	3282384	10828	2876	*	NA
7861203	BAC	S40	42	8/22/2001	1	3478281	412	67	*	NA
7861202	AAC	S28	41	1/10/2002	6	6255139	11836	2724	*	NA
7861203	BAB	S40	42	8/13/2001	9	3082657	7990	7948	*	NA
7861203	BAB	S25	42	4/30/2002	18	6600266	28503	10095	*	NA
7861203	BAB	S25	2	10/17/2001	7	4473975	11583	149	*	NA
7861202	AAC	S28	42	3/15/2002	7	7450871	11516	7862	*	NA
7861203	BAC	S28	42	6/13/2002	12	9200058	12819	6717	*	NA
7861203	BAB	S28	42	5/20/2002	16	8789320	19865	2750	*	NA
7861203	BAB	S25	69	2/27/2002	13	7160688	33448	1680	*	NA
7861203	BAB	S40	42	8/13/2001	9	2835140	9142	4871	*	NA

01_Exped_NavFrontBuckle_Query

7861203	BAC	S26	42	6/7/2002	7	9069874	11840	5113	*	NA
7861203	GAA	S25	42	11/21/2001	6	5700883	9808	6521	*	NA
7861203	BAA	S40		3/20/2002	9	7541435	14088	852	*	NA
7861203	BAC	S40	42	1/9/2002	9	6291687	11990	5579	*	NA
7861203	BAB	S40	42	3/25/2002	11	7804545	11849	869	*	NA
7861202	AAB	S25	42	4/22/2002	15	8222478	22732	4406	*	NA
7861202	AAA	S07	41	8/18/2001	1	3069851	241	4822	*	NA
7861202	AAA	S40	42	10/18/2001	3	4458248	1172	5412	*	NA
	AAA	S40	1	7/28/2001	1	2581287	744	4223	*	NA
7861203	BAB	S26	42	6/3/2002	13	9017202	22747	3048	*	NA
	AAA	S26	33	5/7/2002	11	9070331	9918	5485	*	NA
7861202	AAA	S26	42	3/4/2002	7	7209765	9421	827	*	NA
7861203	BAA	S40	42	4/1/2002	12	7833968	38907	3042	*	NA
7861203	BAA	T90	42	12/5/2001	7	5582288	10519	6582	*	NA
7861203	BAA	S26	42	5/30/2002	14	8970768	18990	4473	*	NA
7861203	BAA	T90	42	5/4/2002	8	8455350	9293	3573	*	NA
7861203	AAH	S40	42	12/11/2001	9	5724714	10225	4871	*	NA
7861203	BAC	S26	42	3/14/2002	11	8174202	14815	7737	*	NA

NO94-611 15618

01_Expnd_NavFrontBuckle_Query

7861203	BAA	S26	42	5/1/2002	10	8409784	18339	8444	*	NA
7861203	BAB	S26	42	5/29/2002	15	8900264	14486	20305	*	NA
7861203	BAA	S40	42	9/6/2001	7	4021881	8390	408	*	NA
7861203	BAC	S40	42	1/28/2002	11	8907613	22062	4845	*	NA
7861203	BAA	S40	42	8/23/2001	11	3276881	11268	284	*	NA
7861202	AAB	S40	1	5/8/2002	11	8555895	18327	2262	*	NA
7861203	BAB	S40	42	10/30/2001	4	4792194	7052	4989	*	NA
7861203	BAB	S25	42	3/28/2002	4	7857880	5158	4548	*	NA
	AAA	S25	42	8/29/2001	5	3819178	9587	5574	*	NA
7861203	BAB	S26	1	5/17/2002	14	9253210	20108	5598	*	NA
7861203	BAB	S25	42	8/28/2001	6	4248498	5860	5431	*	NA
7861203	BAA	S40	42	3/8/2002	8	7313997	5454	4373	*	NA
7861203	BAB	S40	42	9/7/2001	7	4858817	12496	6033	*	NA
7861203	BAA	G29	42	3/4/2002	13	7243689	18004	4645	*	NA
7861203	BAA	S40	41	5/16/2002	18	8870111	21971	4870	*	NA
7861203	BAA	S40	42	8/25/2001	8	3946756	13305	449	*	NA
7861202	AAB	T90	42	1/18/2002	15	8485458	28278	4822	*	NA
7861203	BAA	S25	42	8/21/2001	4	3184186	3848	4527	*	NA
7861202	AAA	S26	42	4/29/2002	12	8320320	9121	4820	*	NA
7861203	BAB	S40	41	10/19/2001	1	4549858	647	4590	*	NA

R004-011 15819

01_Exped_NavFrontBuckle_Query

7861203	CAA	S40	42	7/17/2001	2	2721149	1461	3915	*	NA
7861203	BAA	S40	42	8/17/2001	2	3117066	2413	3073	*	NA
7861203	BAC	S26	42	5/14/2002	12	8671170	33750	5449	*	NA
7861203	BAA	S25	41	8/14/2001	4	3169245	5636	6679	*	NA
7861203	BAB	S40	33	6/7/2002	12	9062617	9400	2417	*	NA
7861203	BAA	S40	41	1/10/2002	10	6272592	4567	20443	*	NA
7861203	CAA	S25	41	7/18/2001	4	2536369	6463	5555	*	NA
	AAC	S26	42	1/18/2002	14	6434420	44768	7116	*	NA
7861202	AAA	S25	42	10/30/2001	11	4892246	12712	7729	*	NA
7861203	BAC	S26	42	5/23/2002	12	8773035	10375	4413	*	NA
7861202	AAA	S25	41	10/1/2001	3	4100674	6478	543	*	NA
7861203	BAB	S25	42	4/20/2002	11	8151223	12156	1071	*	NA
7861203	BAA	S40	1	6/3/2002	13	9016349	28798	2486	*	NA
7861203	BAA	S40	42	3/25/2002	6	7625173	13947	2511	*	NA
7861203	BAB	S40	42	9/20/2001	0	4103538	98	1472	*	NA
7861202	AAA	S25	42	8/11/2001	4	3740610	2865	1761	*	NA
7861203	BAB	S40	42	1/17/2002	10	6374584	11592	6624	*	NA
7861202	AAB	S40	41	9/25/2001	6	4348734	7107	4839	*	NA
7861203	BAB	S40	69	10/26/2001	8	4720518	7448	4845	*	NA

R004-011 18629

01_Expd_NavFrontBuckle_Query

7861203	BAB	S40	42	10/2/2001	2	4113084	1008	4820	*	NA
7861202	AAC	S26	42	5/13/2002	12	8590192	34053	3924	*	NA
7861203	BAA	S25	1	11/13/2001	2	5283647	3431	6192	*	NA
7861203	CAC	S40	42	11/17/2001	3	5304003	3489	4039	*	NA
7861203	BAB	S40	42	8/4/2002	12	9041910	20473	3921	*	NA
7861203	BAA	S40	42	9/10/2001	5	4083702	7048	7018	*	NA
	CCC	S25	1	4/2/2002	17	7790257	29844	3134	*	NA
7861203	BAB	S25	42	11/17/2001	2	6255127	2671	5453	*	NA
	AAC	S40	42	11/17/2001	10	5280156	27252	3924	*	NA
7861202	AAB	S25	42	12/5/2001	13	5699537	11985	5674	*	NA
7861203	BAB	T90	42	3/8/2002	7	7305854	13458	980	*	NA
7861203	BAA	S40	42	1/17/2002	4	6364104	4864	1777	*	NA
7861203	BAA	S40	42	6/6/2002	14	9088678	16468	4843	*	NA
7861203	BAB	S07	41	11/12/2001	6	5137237	13986	6481	*	NA
7861203	AAF	S26	42	8/3/2002	13	8949409	21237	7358	*	NA
7861203	BAA	S40	42	8/30/2001	1	3458528	625	4158	*	NA
7861203	BAA	T90	1	12/12/2001	8	5785253	6879	5479	*	NA
7861203	BAB	S26	42	4/12/2002	13	7878493	12174	4212	*	NA
7861203	BAA	S26	42	5/1/2002	12	8344784	33072	1472	*	NA
7861203	BAB	S25	42	12/17/2001	4	5958499	4544	5492	*	NA
7861203	BBE	S40	42	11/2/2001	2	4978737	2559	2874	*	NA

R094-011 15621

01_Exped_NavFrontBuckle_Query

7861202	AAA	S40	42	2/19/2002	15	7000800	31380	5431	*	NA
7861203	BAA	S25	1	2/20/2002	9	7050124	13041	4480	*	NA
7861203	BAA	S28	42	5/21/2002	12	8749292	11096	5583	*	NA
7861203	BAC	S25	33	8/14/2001	1	4045134	623	6192	*	NA
7861203	BAB	S40	42	11/1/2001	8	4973937	5840	1864	*	NA
7861203	BAA	S40	42	1/18/2002	9	8838527	14408	5453	*	NA
7861203	BAA	S40	2	11/15/2001	1	5151213	888	543	*	NA
7861203	BAB	S25	41	4/8/2002	8	7855216	14120	290	*	NA
7861202	AAB	S28	42	5/15/2002	12	8644940	21284	4449	*	NA
7861202	AAC	S28	42	6/11/2002	15	9119771	15773	3915	*	NA
7861203	BAB	S25	42	12/27/2001	9	5989895	19899	4999	*	NA
7861203	BAA	S28	42	6/5/2002	15	9038881	26687	2403	*	NA
7861203	BAA	S25	42	10/23/2001	7	5031205	15008	2091	*	NA
7861203	BAC	S28	1	4/9/2002	11	7886821	11352	5550	*	NA
7861203	BAA	S40	1	8/27/2001	2	5270847	3576	4332	*	NA
7861203	BAB	S40	42	2/8/2002	18	6783873	31170	2488	*	NA
7861202	AAA	S25	1	8/22/2001	4	3207941	5119	1864	*	NA
7861203	BAA	S28	42	3/21/2002	10	7577139	14357	4999	*	NA
7861203	BAA	S40	42	11/5/2001	2	4890720	2601	6534	*	NA
7861203	CAA	S40	42	10/16/2001	6	4480658	18924	6529	*	NA
7861203	BAB	S25	41	5/15/2002	14	8778880	19711	7883	*	NA
7861203	BAA	S28	42	3/1/2002	8	7190573	5964	4127	*	NA
7861203	BAB	S06	42	10/30/2001	4	4842695	6707	1025	*	NA

R084-811 1982Z

01_Expd_NavFrontBuckle_Query

7861202	AAB	S40	41	11/13/2001	8	5103737	7891		4807	*	NA
7861203	BAB	S40	1	5/31/2002	16	9016344	23517		2488	*	NA
7861202	AAC	S40	1	11/8/2001	10	5003664	11936		2411	*	NA
7861202	AAA	S25	42	12/31/2001	10	6037902	7866		2441	*	NA
7861203	BAC	S28	42	6/10/2002	16	9090282	37782		2453	*	NA
7861202	AAB	S40	42	1/28/2002	8	6549911	9826		6778	*	NA
7861203	BAB	L29	42	11/20/2001	8	5225429	9508		5623	*	NA
7861203	BAA	S28	42	5/9/2002	12	8723343	26702		6529	*	NA
7861203	BAB	S40	42	8/11/2001	4	4041026	5172		4970	*	NA
7861203	BAA	T90	42	4/24/2002	13	8195065	11714		4947	*	NA
7861203	BAC	S25	42	8/14/2001	2	3744508	3254		3085	*	NA
7861202	AAA	S40	1	1/18/2002	8	7365062	11313		2410	*	NA
7861203	BAA	T90	42	12/29/2001	9	6013934	10112		2458	*	NA
7861203	BAB	S40	42	5/23/2002	14	8783855	12062		11645	*	NA
	AAA	S25	42	2/25/2002	9	7080614	9961		4847	*	NA
	AAB	S40	12	12/12/2001	14	6805709	14007		1697	*	NA
7861203	BAA	S40	42	11/10/2001	12	5097316	16425		2416	*	NA
7861202	AAA	S28	41	5/20/2002	19	8721727	15285		6620	*	NA
7861203	BAA	S40	1	11/13/2001	8	5092887	9790		543	*	NA
7861202	AAA	S40	42	12/6/2001	5	5929712	2800		6892	*	NA

K094-611 15623

01_Expd_NavFrontBuckle_Query

7861203	BAB	S25	41	8/31/2001	1	4874754	498	1191	*	NA
7861203	BAB	S40	42	4/24/2002	9	6286486	8403	5414	*	NA
7861203	BAB	S25	1	8/20/2001	1	3322469	416	3673	*	NA
7861203	BAA	S40	42	11/7/2001	6	5062706	6397	487	*	NA
7861203	BAA	S25	42	9/20/2001	2	4476588	1907	1140	*	NA
7861203	BAA	S25	42	8/10/2001	6	3560052	3959	7933	*	NA
7861203	BAB	S40	42	10/3/2001	5	4143588	5716	3832	*	NA
7861202	AAA	S25	42	1/11/2002	9	6196128	7124	2486	*	NA
7861203	BAC	S40	42	5/31/2002	14	9098548	25688	6642	*	NA
7861203	BAA	S21	41	8/8/2001	5	3570734	4598	141	*	NA
7861203	BAA	S40	42	2/11/2002	11	6844039	14641	4410	*	NA
7861203	BAA	S40	42	11/7/2001	4	4948204	5190	3073	*	NA
	AAC	S26	1	1/29/2002	14	6578459	13987	5508	*	NA
7861203	BAA	S40	42	1/4/2002	12	6114672	16577	1771	*	NA
7861203	BAA	T90	33	11/15/2001	14	6219463	28364	3573	*	NA
7861203	BAB	S40	42	12/14/2001	6	5806289	9571	1470	*	NA
7861203	BAB	S25	33	12/4/2001	1	5638366	149	4443	*	NA
7861203	BAC	S39	42	1/7/2002	4	6228138	4161	4356	*	NA
7861202	AAB	T90	33	11/7/2001	3	4963723	4880	5518	*	NA
7861203	CAB	S26	42	5/22/2002	8	8822478	9173	543	*	NA
7861203	BAB	S26	42	5/15/2002	10	8610026	11309	409	*	NA
7861202	AAB	S40	42	12/7/2001	0	5659834	10	449	*	NA

ROB-611 15624

01_Expd_NavFrontBuckle_Query

7861203	BAA	S40	1	12/14/2001	2	5815516	1440		5536	*	NA
7861203	BAA	S40	1	12/14/2001	2	5815516	1440		5536	*	NA
7861203	BAA	S40	42	3/25/2002	13	7801140	29445		3475	*	NA
7861202	AAB	S25	42	5/8/2002	13	8597258	18040		7923	*	NA
7861203	BAA	S40	42	2/18/2002	5	7182809	6719		4927	*	NA
7861203	BAC	S25	41	12/11/2001	9	5726234	18225		5539	*	NA
7861203	BAA	S40	42	8/21/2001	5	3480208	4183		878	*	NA
7861203	BAA	S25	41	11/30/2001	3	5446160	2137		20400	*	NA
7861203	CAB	S40	42	8/28/2001	0	3507967	10		277	*	NA
7861203	BAA	S40	42	10/25/2001	4	4689493	4810		8634	*	NA
7861203	BAB	S40	42	12/19/2001	7	5958789	7528		5536	*	NA
7861203	BAB	S40	42	3/18/2002	12	7495432	15559		2877	*	NA

NOB-011 15625

01_Expd_NavFrontBuckle_Query

2001 Expd repeat repair_ST _PROV_ CD	2001 Expd repeat repair_C PSC_CD 8	Ratings	2001 Expd repeat repair TECH TXT1
NJ	11001	e	9359 CK & REPLACED BOTH FRONT SEAT BELT ASSY.
IL	11001	e	REPLACED BUCKLE ASSY INOP
MN	11001	e	INSTALL PASS SIDE SEAT BELT LATCH
MN	11001	c	CP 7881203;CC 41;CCC \$28 REPLACED DRIVERS SEAT BELT BUCKLE ASSEMBLY. UTILIZED LABOR OPERATION FROM PROGRAM 01821
TN	11001	a	REPLACED RIGHT FRONT PASS SEAT BELT BUCKLE ASSY
NJ	11001	e	7222 REPLACE DRIVER FRONT SEAT BUCKLE
NJ	11001	e	1 REPLACE L FRONT SEAT BELT
CO	11001	e	REPL LF BELT BUCKLE
CA	11001	d	...BUCKLES ARE NOTS HOLDING AT TIMES... ...INSPECTED WITH TOOL BOTH FRONTS FAILED.REPLACED.OK
MI	11001	e	1 REPLACE DRIVERS SEAT BELT BUCKLE WITH NEW BUCKLE IN OP CC 42 BASIC#61203
CA	11001	e	SEAT BELTS IN OP REPLACE SEAT BELTS
MI	11001	e	DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
NJ	11001	c	PASS AND DSIDE SEATBELT BUCKLE FAULTY TECH REPLACED PASS AND DSIDE FRONT BUCKLE TO CORRECT CUST CONCERN
CA	11001	a	SEAT BELT NOT STAYING ENGAGED SEATBELT ASSEMBLY FRONT REPLACE
CO	11001	d	FOUND DRIVERS SIDE SEAT BELT BROKEN. R&R DRIVERS SEAT BELT. VERIFIED REPAIR
MA	11001	a	14815 REPLACED DRIVER SEATBELT RECEPT. RECEPT. WOULD NOT ACCEPT SEATBELT BUCKLE AND LOCK BELT OPERATED PROPERELY AT THIS TIME
MA	11001	e	PERFORMED RECALL AND REPLACED DRIVER SEATBELT BUCKLE RECHECKED OK
CA	11001	a	REPLACE BELT INOP

01_Exped_NewFrontBuckle_Query

IL	11001	a	REPLACE BOTH FRONT SEAT BELT BUCKLES
MI	11001	e	INSPECTED SEATBELTS, NEEDS DRIVERS BUCKLE, REQUEST MT INSPECT AND REPLACE DRIVER BELT AND BUCKLE
NY	11001	e	INSTALLED SOP SEATBELT
MI	11001	d	1237 01 INSPECTED ABD FOUND BAD SEAT BELT LATCH REPLACED DRIVER SEAT BELT LATCH RECHECKED GOOD
VA	11001	b	2472 INSPECT AND REPLACE DRIVER SIDE SEAT BELT
MO	11001	d	TESTED THE SEAT BELT CAME UNLATCHED PUT IN A NEW BUCKLE TESTED DID NOT COME UNDONE MOVED THE LATCH AROUND
PA	11001	e	SEAT BUCKLES NEED REPLACED REPLACED LEFT AND RIGHT FRONT SEAT BELT BUCKLES
IL	11001	e	REPLACED RIGHT FRONT SEAT BELT BUCKLE DUE TO INOP
TN	11001	a	MTIME TO REMOVE LEFT FRT SEAT AND LEFT FRT SEATBELT FEMALE END. REPLACED FEMALE END OF LEFT FRT SEATBELT. RETEST. OK.
NY	11001	e	REPLACE L FRONT SEATBELT BUCKLE
HI	11001	d	
CO	11001	c	REPL SEAT BELT
MO	11001	a	SEATBELT ASSEMBLY FRT REPLACED DUE TO LATCH INOP
CA	11001	c	83: VERIFY DRIVERS SEATBELT UNLATCHES, R&R FRONT SEAT AND REPLACED SEATBELT BUCKLE, REASSEMBLE, RECHECK OK AT THIS TIME
NY	11001	e	PERFORMED SEAT BELT RECALL
NM	11001	e	REPLACED THE BUCKLE
KS	11001	a	REPLACE LEFT FRONT SEAT BELT
NJ	11001	d	1 REPLACE DRIVERS SEAT BELT BUCKLE
MA	11001	a	VERIFIED RIGHT FRONT SEAT BELT BUCKEL WILL NOT LOCK. REPLACED THE BUCKLES AND RECHECKED TO CONFIRM REPAIR.
KY	11001	e	BUCKLE FAILED SEATBELT ASSEMBLY FRONT REPLACE
OR	11001	a	1 INSPECTED VEHICLE AND REPLACED LEFT FRONT BUCKLE
FL	11001	c	LOOSE SEATBELT ASSEMBLY FRONT REPLACE
CO	11001	a	BUCKLE WILL NOT OPERATE PROPERLY REPLACE LEFT SEAT BELT BUCKLE.

R084-011 15527

01_Exped_NavFrontBuckle_Query

TX	11001	a	INSPECT SEAT BELT REPLACE BELT AND BUCKLE ASSY BINDING
NH	11001	a	REPLACED DRIVERS SEATBELT
MD	11001	e	10789 16 WPC REPLAE RIGHT FRONTR SEAT BELT BUCKLE
MD	11001	e	AFTER TESTING SEVERAL TIMES VERIFIED CONECONR REMVOED AND REPALGED LEFT SIDE SEAT BELT
CO	11001	e	REPLACED THE BUCKLE
CO	11001	e	REPLACED THE BELT
AZ	11001	a	TECH 0468 BASIC7861203 CODE 42 CONFIRM DR SIDE SEAT BELT WONT LATCH AT TIMES RR DR SEAT ACCESS REPLACE SEAT BELT BUCKLE ASSY RETEST OK
NY	11001	e	REPLACE L FRONT SEATBELT BUCKLE
IL	11001	e	REPLACED SEATBELT RT FT SEATBELT
PA	11001	e	REPLACED SEAT BELTS
TX	11001	c	1 REPLACE DRIVERS SEAT BELT COMES UNLATCHED
TN	11001	e	PERFORMED RECALL AND REPLACED SEAT BLET
VA	11001	e	13437 REPLACED PASS SEAT BELT BUCKEL #29
VA	11001	e	19994 REPLACE RIGHT FRT SEAT BELT BUCKLE BUTTON STICK S AT TIMES
MI	11001	a	REPLACE RT FRONT SEAT BELT BUCKLE
IA	11001	b	WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE
MA	11001	e	REPLACE SEATBELT
KS	11001	e	34405 B1172A 0.4 0.4 REPLACED SEAT BELT BUCKLE
SC	12001	c	REPLACE PASS FRONT SEATBELT
GA	11001	e	REPLACED DRIVERS SIDE SEATBELT BUCKLE ASSY CC01
GA	11001	b	SEATBELT RECEIVER FAILURE SEATBELT RECEIVER FRONT REPLACE
FL	11001	d	UNLOCKS SEATBELT ASSEMBLY FRONT REPLACE
TN	11001	d	REPLACED LFT FRT SEAT BELT BUCKLE ASSY. COMES LOOSE WHILE DRIVING.

01_Exped_NavFrontBuckle_Query

FL	11001	d	7861203 7861202 C/C42 M20299 CHECK BOTH SEAT BELT OPERATION WITH RECALL TESTER FAIL REPLACED LEFT & RIGHT FRONT SEAT BELT BUCKLES RETEST OK
CA	11001	e	REPL L FRONT SEAT BELT BUCKLE
CA	11001	a	61202 M TIME TO REPLACE THE RIGHT FRONT SEAT BELT BUCKLE. STICKING, NOT RELATED TO RECALL
CA	11001	a	INSPECTED REAR MIDDLE SEAT BELT BUCKLE, WILL NO T LATCH, REPLACED SEAT BELT BUCKLE AND RETEST
CA	11001	a	INSPECTED REAR MIDDLE SEAT BELT BUCKLE, WILL NO T LATCH, REPLACED SEAT BELT BUCKLE AND RETEST
CA	11001	a	7861203 CC 42 0.8 TO REPLACE DRIVERS SEAT BELT BUCKLE. NGS BODY CHASSIS ELECTRICAL BCE START UP TEST NGS BODY CHASSIS ELECTRICAL DIAGNOSIS *NGS PIN POINT TEST FOUND.
FL	11001	a	BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE
FL	11001	b	1 VERIFIED CONCERN INSTALLED SOP THE DRIVER SEAT BELT BUCKLE RETESTED OK AT THIS TIME
CA	11001	e	PREVIOUSLY TEST SEAT BELT BUCKELS FOR LEFT AND RIGHT FRONT BUCKELS REPLACED LEFT LAST VISIT HAD TO ORDER RIGHT LAST REPLACED RIGHT SEAT BELT BUCKEL FAILED UNDER SEAT BELT BUCKEL TEST QC BF
FL	11001	e	REPLACED LEFT FRONT SEATBELT
FL	11001	a	BROKEN REPLACE LEFT FRONT SEAT BELT BUCKLE
TX	11001	b	DRIVERS SEAT BELT WOULD NOT LATCH,REPLACED SEAT BELT LATCH,RECHECKED OK
CA	11001	e	REPLACED DRIVERS SEATBELT BUCKLE
FL	11001	e	REPLACE BOTH FRONT SEAT BELT ASY
AL	11001	a	CHECK AND REPLACE DRIVERS SEAT BELT BUCKLE, WILL NOT FASTEN.
AL	11001	a	REPLACED FRONT SEATBELT AS PART OF RECALL

R02-011 15629

01_Exped_NevFrontBuckle_Query

GA	11001	c	REPLACED SEAT BELT LATCH TO CORRECT
CA	11001	e	1 DISCUSS WITH ERIC TAYLOR FORD CSM IN THE INTREST OF CUSTOMER SATISFACTION REPLACED FRONT SEAT BELT BUCKLES.
AL	11001	e	CHECK AND TEST WILL NOT CLICK REMOVE AND REPALCE ASSMY RETES T
NV	11001	a	BINDING REPLACED RIGHT FRONT SEAT BELT BUCKLE
TX	12001	e	REPLACE RT FT SEAT BELT
CA	11001	a	REPLACED DRIVERS SEAT BELT ASSEMBLY TO CORRECT CONCERN
CA	11001	b	SEAT BELT LATCH BROKEN M TIME TO REPLACE SEAT BELT LATCH
VA	11001	a	763 BELT WONT LATCH REPL DRS SEAT BELT LATCH *28
AL	11001	e	TECH VERIFIED COMPLIANT, REPLACED LEFT FRONT SEAT BELT BUCKLE, RETESTED, OK AT THIS TIME
GA	11001	a	11114 REPLACE BOTH FRONT SEAT BELT BUCKELS
CA	11001	e	REPLACE LEFT SEAT BELT BUCKLE
TX	11001	e	REPLACED FRONT BELT ASY
MS	11001	a	BROKEN NECESSARY TO REPLACE BROKEN SEAT BELT AND BUCKLE
OK	11001	a	R/R SEAT AND REPLACE LEFT FRONT SEAT BELT
CA	11001	c	1 REPLACE LEFT FRONT SEATBELT LATCH.
GA	11001	c	L F SEAT BELT COMES UNBUCKLED REPLACED
CA	11001	e	REPLACE LEFT AND RIGHT SEAT BELT BUCKLES.
CA	11001	e	BUCKLE REPLACED PASS SEATBELT BUCKLE.
FL	11001	e	15140 42 INOP INTALL SOP LF SEAT BELT BUCKLE
TX	11001	a	RIGHT FRONT SEAT BELT WONT BUCKLE REPLACE RIGHT FRONT SEAT BELT BUCKLE END INOPERATIVE NO LABOR OPERATION IN SLTSM
CA	11001	e	REPLACED LEFT FRT SEAT BELT BUCKLE
GA	11001	e	CHECKED LEFT FRONT SEAT BELT FOUND BUCKLE NOT WORKING PROPERLY REMOVED AND REPLACED BUCKLE
AZ	11001	a	REPL LEFT FRT SEAT BELT BUCKLE WONT RELEASE
CA	11001	a	VERIFY CONCERN FOUND DEFECTED SEAT BELT BUCKLE REMOVE SEAT AND REPLACE BUCKLE AND RETEST SYS O K AT THIS TIME.
SC	11001	a	INSTALLED SEAT BELT

01_Expd_NavFrontBuckle_Query

GA	11001	e	REPLACED SEAT BELT BUCKLE.
TX	11001	c	REPLACE DRIVERS SEAT BELT BUCKLE ASSY.
CA	11001	e	61202.CC42 REPLACE R F SEATBELT
CT	11001	c	DRIVER SEAT BELT DOESNT BUCKLE BROKEN REPLACED BUCKLE AND RETESTED OK
TX	11001	b	5326 01 61203 R R DRIVER SEAT ACCESS REPLACED DRIVER SEAT BELT BUCKLE BINDING
TX	11001	e	SEAT BELT REPLACED
GA	11001	e	REPLACED DRIVER SIDE SEAT BELT BUCKLE.
CA	11001	b	TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.
NC	12001	a	INOP REPL FR SEATBELT ASY SEATBELT ASSEMBLY FRONT REPLACE
TX	11001	d	
FL	11001	c	LOOSE SEATBELT ASSEMBLY FRONT REPLACE
TX	12001	e	11967 61202.42 DOES NOT OPERATE PROPERLY R R PASS FRONT SEAT REPLACED SEAT BELT BUCKLE
TX	12001	e	14022 ORIGINALLY TESTED FRONT BELT BUCKLES AND FOUND DRIVERS FAILED AND PASSENGERS PASSED LATER FOUND OUT SERVICE WRITER HAD TESTED BUCKLE WITH CUSTOMER AND DRIVERS PASSED AND PASSENGERS FAILED RE
GA	12001	e	INOP REPLACE RIGHT SEAT BELT
FL	12001	a	REPLACED SEAT BELT BUCKLE PER RECALL 01S21.
GA	11001	a	RECALL RECALL 01S21,REPLACED DRIVERS SEAT BELT BUCKLE
TX	12001	a	BUCKLE WOULDNT LATCH,REPLACED AND TESTED OK
TX	11001	a	3391 DRIVERS SEAT BELT DOES NOT LATCH AT TIMES. R R DRIVERS SEAT TO GAIN ACCESS TO SEAT BELT ANCHOR. REMOVE AND REPLACE SEAT BELT BUCKLE ASSY. CONFIRM PROPER LATCH AFTER REPLACEMENT. OK
TX	11001	e	INOP SEATBELT ASSEMBLY FRONT REPLACE
GA	12001	e	WARR 944247 TEST AND REPLACE BOTH FRONT SEATBELT BUCKLES
CA	11001	a	REPLACE BUCKLE, RECK OK

R094-811 15631

01_Exped_NavFrontBuckle_Query

FL	11001	e	INOP SEATBELT ASSEMBLY FRONT REPLACE
FL	11001	b	BUCKLE HAD A BROKEN & JAMMED PUSH BUTTON. REPLACED THE DRIVER SIDE SEAT BUCKLE ASSY, TESTED ALL FUNCTIONS AFTER THE REPAIR, ALL TO SPEC AT THIS TIME
TX	11001	d	R AND R SEAT T60 REPLACE DRIVERS SEAT BELT
TX	11001	e	REPLACE BUCKLE.
TX	11001	a	14584 DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH AND UNLATCH REPLACED BUCKLE AND RETESTED OK.
TX	11001	a	1 REPLACED SEAT BELT ASSEMBLY. RETEST: O.K.
TX	11001	c	REPLACE DRIVERS FRONT BUCKLE.
TX	11001	e	RECALL REPLACED SEAT BELT PER RECALL
FL	11001	e	REPLACE BOTH SEAT BELTS
FL	11001	a	802 DOES NOT OPERATE PROPERLY 01S210 0.4 ADMIN 0.1 0.5HRS LG R R DRIVERS SEAT BELT BUCKLE. TESTED, OK. REMOVED DRIVERS SEAT
LA	11001	a	REPLACED DRIVERS FRONT SEAT BELT BUCKLE ASSEMBLY 61203 CAUS 42
FL	11001	c	17098 DR LF SEAT BELT INOP W CC42 INSP AND RR DR SEAT TO ACCESS SEAT BELT BUCKLE ASSY REPLACED LF DR SEAT BELT BUCKLE ASSY RETEST OK
TX	11001	a	885 LEFT FRONT SEAT BELT WILL NOT LATCH. ACCESS LEFT FRONT SEAT AND REPLACED BUCKLE AND HARNESS ASSEMBLY. 1.0 CC 42 QUALITY CHECKED BY MJM
CA	11001	a	VERIFIED, NEED NEW BUCKLE.
GA	11001	e	BUCKLE FAILED REPLACE DRIVERS FRONT SEAT BELT BUCKLE
FL	12001	e	SEAT BELT BUCKLE BROKEN. PASS SIDE SEAT BELT BUCKLE INOP. REMOVED SEAT FOR ACCESS. R R BUCKLE, REINSTALLED SEAT AND VERIFY REPAIR..
TX	11001	c	REMOVE FRONT SEAT AND REPLACE BUCKLE
TX	11001	e	REPLACE SEAT BELT BUCKLE.
TX	11001	a	SEATBELT BINDING
FL	11001	e	REPLACED SEATBELT INOP

R004-011 15832

01_Exped_NayFrontBuckle_Query

TX	11001	d	CC42 DOES NOT OPERATE PROPERLY MILES IN 2652 MILES OUT, 2654 TESTED DRIVERS SEATBELT BUCKLE WITH RECALL TESTED FOUND IT DID NOT PASS- REPLACED DRIVERS SEATBELT BUCKLE AND RETEST
CA	11001	e	INSPECTED AND REPLACED BOTH FRONT SEAT BELT BUCKLES.
KS	11001	c	14894 CK BUCKLES REPLACE DR BUCKLE ORDERED MIDDLE SEAT BUCKLES
TX	11001	a	FAIL TO LOCK SEAT CLIP R R SEAT BUCKLE ASSY
CA	11001	a	10000 CP 61384 CC 38 PART REF. 892 61384A 0.4 0.4 REPLACE LH SEAT BELT BUCKLE WRONG COLOR
OK	11001	b	INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.
GA	11001	e	41 REPLACED BOTH FRONT SEATBELT BUCKLES
TX	11001	b	REPLACED SEAT BELT BUCKLE
FL	11001	e	REPLACED DRIVERS SIDE SEAT BELT BUCKLE(BUCKET SEATS) PER RECAL L TECH 638
TX	12001	e	REPL RT FRT SEAT BELT BUCKLE.REMOVE SEAT REPL BUCKLE.
TX	11001	e	SEATBELT BUCKLE INOP REPLACED SEATBELT BUCKLE
TX	11001	c	21004 7861203 CC 42 VERIFY CONCERN.R& R DRIVERS SEAT TO GAIN ACCESS AND REPLACED DRIVERS SEAT BELT BUCKLE,VERIFY REPAIR TECH 4441
TX	12001	a	13544 W INSP AND FOUND PASS SEAT BELT TO BE STICKING WHEN RELEASED CHECKED SEAT BELT W SEAT TOOL BUT PASSED REPLACED BAD PASS SIDE SEAT BELT
CA	12001	a	VERIFIED CUSTOMERS CONCERN, REMOVED & REPLACED SEAT BELT BUCKLE, RETESTED, PASSED...
TX	11001	c	REPLACED SEATBELT BUCKLE
GA	11001	c	SEAT BLET HARD TO UN SNAP REPLACE BOTH SEAT BLET BUCKLES
CA	12001	a	FAILED BUCKLE REPLACED BUCKLE
TX	12001	c	R&R RT FRONT SEAT. REPLACED SEAT BELT BUCKLE ASSY....

01_Exped_NavFrontBuckle_Query

OK	12001	a	5834 REPLACE FRT BUCKELS AS PER RECALL
FL	11001	d	6206 INOP 61203 42 WARR REPLACE LEFT SEAT BBELT BUCKLE 61202A
TX	12001	a	BINDING (41) HAD TO ACCESS REAR MIDDLE SEAT & REPLACE CENTER SEATBELT BUCKLE, TK6682
TX	11001	a	SEAT BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE
TX	11001	a	INOP, WOULD NOT LOCK IN PLACE REPLACED SEATBELT BUCKLE.
CA	11001	a	SOP M TIME TO REPLACE LEFT BUCKLE
SC	11001	a	61230 M TIME TO REPLACE LEFT SEAT BELT BUCKLE
IL	11001	a	REPLACE BOTH SEAT BELT BUCKLES
NC	12001	a	42 REMOVED RITE FRONT SEAT FOR ACESS TO BELT BUCKLE REPLACED BUCKLE AND REINSTALLED SEAT
NJ	11001	c	SEATBELT ASSEMBLY FRONT REPLACE (611A72 611A73) DRIVERS FRONT SEAT
CA	11001	b	REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH
PA	12001	b	TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE
NJ	11001	d	REPLACED THE LEFT FRONT SEAT BELT ASSEMBLY. CHECKED OPERATION, OKAY NOW.
NC	11001	d	BUCKLE & SWITCH BAD SEATBELT ASSEMBLY FRONT REPLACE
NY	11001	a	REPLACED BUCKLE
PA	12001	a	CK OASIS, FOUND RECALL WAS PERFORMED AT ANOTHER DEALER. TEST SEAT BELT WITH TOOL AND IT DID NOT HOLD. REPLACE RF SEAT BELT BUCKLE
MI	11001	e	INSTALLED NEW LEFT FRONT SEAT BELT
CA	11001	e	18583 BELT RELEASE INT 1.3 CK BELTS, REPLACE BOTH BUCKLES AND DRIVERS BELT AND RETEST OK
MI	11001	a	LEFT FRONT SEAT BELT BUCKEL NOT LATCHING CC 42 BP#7861203 BUCKET SEATS CHECKED OPERATION OF LEFT FRONT SEAT BELT BUCKEL INTERMITTLY WILL NOT LATCH CHECKED BELT FOR DAMAGE OK REMOVED AND REPLACED LEFT
NJ	12001	a	NECC TO REPLACE RIGHT SIDE SEAT BELT
PA	11001	e	REPLACE SEAT BELT BUCKLE

R004-811 19604

01_Expd_NavFrontBuckle_Query

NJ	11001	e	LEFT SEAT BELT BUCKLE INOP REPLACED BUCKLE
WA	11001	e	R I SEATAND REPLACE DRIVERS SEAT BELT BUCKLE CHECK OP, OK
IL	11001	a	REPLACED LEFT FRONT SEAT BELT
DE	11001	e	DEFECTIVE CHECK BELT OPERATION, ORDER PART REMOVE D S SEAT REPLACE LATCH REASSEMBLE CHECK OPERATION OK
MI	12001	b	REPLACE DRIVERS SIDE SEAT BELT BUCKLE PER RECALL.
IN	11001	a	590 LEFT FRONT SEAT BELT LATCH NOT OPERATING PROP 42 MT81203 VERIFIED CUSTOMER COMPLAINT THAT THE SEAT BELT LATCH ON LF SEAT WILL NOT LATCH MAJORITY OF THE TIME. REMOVED OLD LATCH AND INSTALLED NEW
NJ	12001	a	REPLACE RIGHT FRONT SEAT BELT BUCKLE
MI	11001	c	SEAT BELT COMES LOOSE INTERMITTENTLY, REPLACED LEFT FRONT SEAT BELT ASSEMBLY. RECHECKED, OK.
VA	11001	a	REPLACE LT FRT SEATBELT ASSY
NJ	12001	a	WILL NOT LATCH, REPLACED RIGHT FRONT SEAT BELT.
CA	11001	a	DR SEAT BELT BUCKLE TESTED & REPLACED BUCKLE
CA	11001	e	COMPLETED RECALL
MD	11001	e	REPLACE DR SIDE SEAT BELT FOR RECALL
CA	12001	a	REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES
VA	11001	c	CHECKED AND CONFIRMED CONCERN.REPLACED SEAT BELT TO FIX REPAIR.
MI	11001	a	19566 INOP WAR REPLACT HE DR SIDE SEAT BELT BUCKLE,RETETS O
NH	11001	e	REPLACED LEFT DRIVERS SEAT BELT
IN	11001	b	HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.

R004-011 15035

01_Exped_NavFrontBuckle_Query

MO	11001	e	REPLACE DRIVERS SEAT BELT
LA	11001	e	9808 REPLACED SEAT BELT BUCKLE TESTED ALL WORKS PROPERLY
OK	11001	e	LEFT FRT SEAT BELT BUCKLE SWITCH FAILED. VERIFIED CONCERN, TEST AND REPLACED LEFT FRONT SEAT BELT BUCKLE CLOSED BY WPI
CA	11001	e	REPLACED DRIVERS SIDE SEAT BELT BUCKLE
CA	11001	d	11849 SOP PART 0.8MT REMOVED AND REPLACED FEMALE SEAT BELT BUCKLE AFTER DUPLICATING CONCERN RETESTED QUALITY OK
TX	12001	a	FOUND SEAT BELT BUCKLE NOT LATCHING REPLACE SEAT BELT BUCKLE
FL	12001	a	BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE
CA	12001	e	NA REMOVE AND REINSTALL SEAT, REMOVE AND REPLACE BUCKLE.
CA	11001	b	REPLACED BELT DUE TO BEING BROKEN
TX	11001	c	INOP SEATBELT ASSEMBLY FRONT REPLACE
CA	11001	d	INSPECTED AND FOUND PASS FRONT SEAT BELT BUCKLE FIT LOOSE REPLACE SEAT BELT VERIFY REPAIR
CA	12001	b	VERIFIED CONCERN SEAT BELT WILL NOT STAY LATCHED INSTALLED NEW BUCKLE & RE CK OK
TX	11001	c	REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE
LA	11001	b	10521 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC 42 CASUAL PART 1L7Z 7861203 BAA
TX	11001	c	18980 ACCESS STEERING COLUMN & REPAIRED LOCK ACTUATOR BINDING
GA	11001	a	IT WOULD WORK SOMETIMES THEN GET HUNG UP REPLACED SEAT BELT BUCKLE WITH NEW
FL	11001	a	REPLACE SEAT BELT
CA	11001	e	REMOVED AND INSTALL DRIVER SEAT BELT BUCKLE(SOP OPERATE THE SEAT BELT AND BUCKLE TO VERIFY OPERATION.

R004-011 15636

01_Expd_NavFrontBuckle_Query

LA	11001	e	18339 R&R L F SEAT,TEST & REPLACE SEAT BELT BUCKEL R&R R F SEAT,TEST & REPLACE SEAT BELT BUCKEL.
AZ	11001	e	REPLACED 2 FRONT SEAT BELT BUCKLES. RECALL HAD PREVIOUSLY BEEN DONE, CALLED RECALL HOTLINE AND TOLD TO SUBMIT AS A REGULAR WARRANTY
GA	11001	e	A SEAT BELT BUCKLE
FL	11001	e	CC 42 B VASIC 7861203 M O 22062 REMOVED AND REPLACED BOTH FRONT SEAT BELT RECIEVERS,RETESTED OK.
GA	11001	b	NA REPLACED DRIVERS SIDE SEATBELT BUCKLE.MILEAGE IS CORRECT ENTERED INCORRECTLY AT SPALDING FORD ON 071901
CA	12001	a	SEATBELT BUCKLE ASSY. M TIME R R SEAT AND REPLACED IMPROPERLY LATCHING SEAT BUCKLE ASSY.
FL	11001	c	INOP REPLACE DRIVERS SIDE SEAT BELT BUCKLE
TX	11001	d	NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT REPLACE
CA	11001	e	REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY
CA	11001	e	REPLACE INOP BUCKLE
CA	11001	e	INSTALL S.O.P SEAT BELT BUCKLE
TX	11001	e	VERIFIED CONCERN,INSPECTED AND FOUND FAULTY SEAT BELT BUCKLE..... REMOVED AND REPLACED SEAT BELT BUCKLE TO CORRECT CONCERN....
AR	11001	d	12496 FP 81203 CC 42 MT81203 .4 * AUTH 3131 REPLACED THE DRIVERS SEAT BUCKLE
TX	11001	c	SEAT BELT BUCKEL REPLACED SETA BELT BUCKLE
FL	11001	e	REPLACE LEFT FRT SEAT BELT BUCKLE.
GA	11001	a	REPL SEAT BELT LATCH REPL SEAT BELT LATCH ASSY
FL	12001	c	INOP SEATBELT ASSEMBLY FRONT REPLACE
TX	11001	d	3848 SEATBELTS PASSED 01S21 TEST, CUSTOMER STATES DRIVERS SEATBELT BUCKLE WILL COME LOOSE AFTER DRIVING AWHILE, REPLACED DRIVERS SEATBELT BUCKLE FOR RECALL 01S21
FL	12001	e	8121 RECALL WARR VERIFY PERFORM RECALL RR PASSENGER BELT RECHECK OK
TX	11001	c	REPLACE LEFT FRT SEATBELT BUCKLE

R004-011 15637

01_Exped_NavFrontBuckle_Query

NV	11001	a	BAD SEAT BELT TONGUE AND ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE
FL	11001	d	2413 ERRATIC W 42 REMOVE RT AND LEFT FRONT SEATS AND REPLACE SEAT BELT BUCKLES ON BOTH SEATS,ERRATIC
CA	11001	a	CUST STATE THE ELFT FRONT SEAT BELT BUCKLE WONT LATCH CAUSE: SEAT BELT BELT BUCKLE DEFECTED CORRE: REPLACED LEFT FRONT SEAT
NC	11001	e	REMOVED DRIVERS SIDE SEAT. R&R SEATBELT LATCH AND VERIFIED REPAIR.
TX	11001	d	8400 REPLACED DRIVERS SEAT BELT LATCH. *** QUALITY CONTROL BY JOHN MEDROW ***
AZ	11001	a	INSPECT LF BELT BUCKLE BINDING DOES NOT LATCH REPLACE, INSPECT LEFT REAR 2ND ROW SEAT BELT OPERATION FOUND BINDING, REPLACE SEAT BELT AND RETEST OK
CA	11001	d	SREPLACE LEFT FRONT SEAT BELT BUCKLE
NE	11001	a	44788 REMOVE AND INSTALL SEATBELT ON PASSENGER SIDE
CA	12001	e	REPLACE SEAT BELT
TX	11001	c	REPLACE LEFT FRT SEATBELT
TX	12001	a	
NC	11001	c	SEAT BELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE
TX	11001	d	ERRACTIC OPERATION (33) ACCESS LF SEAT & REPLACE SEATBELT BUCKLE, TK8562
TX	11001	d	1 REPLACED L F SEAT BELT BUCKLE
TX	11001	a	98 01S21D 0.9 REPL D SIDE SEAT BELT
CA	12001	e	DEFECTIVE BUCKLE REPLACED SEATBELT BUCKLE CC42
CA	11001	a	REPLACE INOP SEATBELT INSTALLED SEAT BELT BUCKLE
FL	12001	a	7108 R&R SEAT AND SEAT BUCKLE
FL	11001	c	7881202 CODE 89 7448 M O R I BOTH FRONT BUCKET SEATS.REPLACED BOTH FRONT SEATBELTS. RETEST PASS.

ROB-011 15838

D1_Exped_NayFrontBuckle_Query

FL	11001	e	1008 W 302 VERIFIED CONCERN.REPLACE DRIVER SEAT BELT RECIEVER DUE TO INOP.RETEST,OK AT THIS TIME. QUALITY INSPECTED BY 302,1008.
NC	12001	e	SEAT BELT BUCKLE REMOVED PASS SEAT AND REPLACED SEAT BELT BUCKLE.
TX	11001	c	3438 BROKEN 01 REPLACED LT FT SEAT BELT ASSY
FL	11001	d	REPLACED THE FRONT DRIVER SIDE SEAT BELT BUCKEL. THE DRIVER SIDE SEAT BLET BUCKLE WAS DEFECTIVE.
CA	11001	c	1 TECH REMOVED AND REPLACED DRIVER SIDE SEAT BELT ASY ALL OK AT THIS TIME.
TX	11001	d	REPLACED SEAT BELT BUCKLE WITH NEW ONE
CO	12000	e	INSP AND VERIFY FRONT CENTER SEAT BELT BUCKLE INOP, REPLACED CENTER SEAT BELT BUCKLE, CHECK OPERATION OK, COND CODE 42
CA	11001	e	INSPECT LEFT FRONT TEAT BELT WITH TESTER, REPLACE LEFT FRONT SEAL BELT BUCKLE
NC	11001	e	REMOVED AND INSTALLED FRONT SEAT BELT
CA	12001	a	REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY
NC	11001	a	INOP SEATBELT ASSEMBLY FRONT REPLACE
IL	11001	a	INSTALLED DRIVERS SEAT BELT LATCH
FL	11001	a	LEFT FRT SEAT BELT INOP WILL NOT BUCKLE REPLACE
LA	11001	a	DOESNTOPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE
MS	11001	b	CHECKED OPERATION OF BUCKLE REPLACED DRIVERS SEAT BUCKLE ASSY AND QUALITY CHECKED OPERATION
LA	11001	c	CP 7861203 CC 42 DRIVERS SIDE SEATBELT TEST SEATBELT OPERATION, REPLACED SEATBELT
CA	11001	e	REPLACED BUCKLE
TX	11001	e	REPLACE DRIVERS SEAT BELT BUCKLE.
TX	11001	c	33072 MT 7861203 .6 .6 REPLACED DRIVER SEAT BELT BUCKLE.
CA	11001	e	REPLACED BELT BUCKLE
TX	12001	b	CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.

PROD-011 19839

01_Expd_NavFrontBuckle_Query

CA	12001	e	REPLACE PASS SIDE SEAT BELT BUCKLE
TX	11001	a	1 DIAG UPON INSP. REVEALED INTER MIT NO LATCH CAUSED BY BUCKLE INTERNAL DAMAGED BROKE REPLACED BUCKLE ASMBLY & CKD FOR PROP
CA	11001	a	E VERFIED COMPLAINT REPLACED FRONT BUCKLE ASSEMBLYS
TX	11001	c	623 42 REPLACED DRIVERS SIDE SEAT BELT BUCKEL DUE TO-COMING LOOSE AT TIMES
CA	11001	d	INSPECT AND REPLACE DRIVER SIDE SEAT BELT
CA	11001	e	REPLACED ALL FRONT SEAT BELT BUCKLES
TX	11001	a	
GA	11001	a	DIAG AND RR SEATBELT
TX	12001	a	CHECK SEAT BELT PASS FRONT COME OUT AT WILL COULD NOT CONFIRM RECAA WAS PERFORM AND PASSED REMOVE AND REPLACE SEAT BELT BUCKLE CHECK GOOD MT FOR NO LABOR OPPP
NV	12001	a	SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
FL	11001	d	TRACK ASSEMBLY FRONT SEAT REPLACE
TX	11001	a	REPLACE LEFT FRONT SEATBELT END
TX	11001	a	VERFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY , OK AT THIS TIME
CA	11001	a	SEAT BELT BROKE SEATBELT ASSEMBLY FRONT REPLACE
FL	11001	e	REPLACED DRIVER SIDE SEAT BELT CP 61203 CC 42
TX	11001	a	31170 BUCKEL R,I LT FT SEAT TO REPLACE SEAT BELT BUCKLE
CA	12001	e	RT FRT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
FL	11001	c	RENEW DRIVER SEAT BELT ASSY
MS	11001	e	RUN BCE DIAG. W NGS. RUN PINPOINT TEST. REPLACE LF FT SEAT BELT BUCKLE.
AL	11001	c	DRIVERS SEAT BELT WILL POP LOOSE REPLACE DRIVERS SEAT BELT WAITING.....
CA	11001	a	INSPECT. REPLACED L F SEAT BELT BUCKLE
LA	11001	d	SEAT BELT BUCKLE DEFECTIVE REPLACE DRIVER SIDE SEAT BELT BUCKLE
SC	11001	e	DEFECTIVE REPLACED DEFECTIVE DRIVERS SEAT BELT BUCKLE MILEAGE ERROR ON PRIOR TICKET CAR HAS 6707

R004-011 15849

01_Exped_NavFrontBuckle_Query

FL	12001	a	VERIFY SEAT BELT BUCKLE INOP, R&R PASSENGER SEAT ASSEMBLY, REPLACED SEAT BELT BUCKLE, CHECK OPERATION
TX	11001	e	PERFORMED RECALL 01S21, REPLACED DRIVERS SIDE SEAT BELT. 01S21D..0.8...
TX	12001	a	BROKEN, CRACKED SEATBELT ASSEMBLY FRONT REPLACE
TX	12001	a	VERIFY CONCERN REPLACE SEAT BELT BUCKLE CORRECTED
TX	11001	e	1 R&R DRIVERS SEAT BELT BUCKLE ASSEMBLY. R&R SEAT TO ACCESS. RETEST. CC42
NC	12001	e	RPL DEFECTIVE SEAT BELT FOUND BY SEATBELT ASSEMBLY FRONT REPLACE
TN	11001	e	PERFORMED RECALL
AL	11001	b	1 DRIVERS SEAT BELT BUCKLE WILL NOT HOLD. CK AND REPLACED SEAT BELT. RETEST
FL	11001	e	RECALL REPLACE BOTH ISDES BUCKLES PER 01S21
FL	11001	e	RECALL 01S21 TECH 14507 MO 11714 REMOVED AND REPLACED DRIVERS SIDE SEAT BELT LATCH BUCKET POWER SEAT
AL	11001	e	PASS FRONT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE
TX	12001	e	REPLACE PASSENGER SIDE SEAT BELT BUCKLE
TX	11001	b	10112 42 61384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE
FL	11001	e	1 REPLACED DRIVERS SIDE SEAT BELT BUCKLE
GA	11001	e	DOES NOT WORK PROPERLY. REPLACED RIGHT FRONT SEAT BELT BUCKLE ASSEMBLY.
CA	11001	e	14007 RECALL 01S21O 0.4 REPLACE PASSENGER SIDE SEATBELT BUCKLE PER RECALL
TX	11001	e	REPL BUCKLE ASSY
CA	12001	e	16285 MT 61202 0.6 INSPECTED AND REPLACED RT. FRONT SEATBELT BUCKLE, R AND R RT. SEAT FOR ACCESS
TX	11001	c	
AL	12001	d	RECALL BUCKLE INSPECT PER RECALL, R+R RT. FT. SEAT REPLACE

R004-011 12041

01_Expd_NavFrontBuckle_Query

NC	11001	a	E COMPLETED ABOVE
CA	11001	e	SEAT BELT BUCKLE REPALCE LEFT SIDE SEAT BUCKLE
GA	11001	c	BROKEN SEATBELT ASSEMBLY FRONT REPLACE
GA	11001	c	INOP SEATBELT ASSEMBLY FRONT REPLACE
NC	11001	e	REPLACED SEAT BELT
CA	11001	a	REPLACED DRIVERS SEAT BELT
GA	11001	b	REPLACED SEAT BELT LATCH
TX	12001	a	7124 W INSP AND REPLACED PASS SIDE SEAT BELT RETESTED ALL OK
VA	11001	d	26688 SEATBELT ON DRIVERS SIDE FOUND FAULTY WARR VERIFIED CONCERN, FOUND SEATBELT BUCKLE FAULTY, REMOVED SEATBELT BUCKLE, REPLACED SEATBELT BUCKL E, VERIFIED REPAIR
VA	11001	e	REPLACE DRIVERS SIDE SEAT BELT BUCKLE
TX	11001	b	REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD
FL	11001	e	5190 42 W R&R DRIVERS SEAT FOR ACCESS, INSTALL DRIVERS BELT BUCKLE
CA	11001	a	BROKEN SEATBELT ASSEMBLY FRONT REPLACE
OK	11001	a	REPALCED DRIUVERS SIDE SEAT BELT BUCKLE
GA	11001	e	REPLACED SEAT BELT 01521
OH	11001	e	REPLACE SEAT BELT ASSY
TX	11001	d	R&R SEAT CAPTAINS CHAIR TO REPLACE SEAT BELT AS SEMBLY, LOOSE.
CA	11001	e	DRV SEAT BELT BUCKLE INOP CHECK AND NECESS TO REPL INOP DRV SEAT BELT BUCKLE
CA	12001	e	4690 61202 33 RIGHT FRONT SEAT BELT BUCKLE WAS LOOSE R I RIGHT FRONT SEAT TRACK TO REPLACE SEAT BELT BUCKLE. 61172A .4 61704AC .6
TX	11001	c	
GA	11001	c	A REPLACE LEFT SEAT BELT BUCKLE
GA	12001	e	REPL SEAT BELT BUCKLES

N094-011 15642

01_Exped_NavFrontBuckle_Query

CA	11001	b	CC487 REPLACED BOTH SEAT BELT BUCKLES
CA	11001	b	CC487 REPLACED BOTH SEAT BELT BUCKLES
FL	11001	a	RF SEAT BELT WONT STAY LATCHED SEATBELT ASSEMBLY FRONT REPLACE
CA	12001	e	REPLACE RF SEATBELT BUCKLE
GA	11001	a	NO OPERATING PROPERLY REPLACE DRIVER SEAT BELT BUCKLE ASSY
CA	11001	e	16228 01S21D 0.8 9287 REPLACED DRIVERS SEATBELT BUCKLE PER RECALL
NC	11001	a	SEAT BELT. INSP AND REPLACE SEATBELT BUCKLE
AZ	11001	e	REPLACED LF SEATBELT.
GA	11001	e	01S21 INSPECT AND REPLACE ONE BUCKLE PER RECALL
NC	11001	c	SEATBELT RECEIVER INOP CK REPLACED DRIVERS SEATBELT BUCKLE RECEIVER
CA	11001	b	CC487 REPLACED SEAT BELT BUCKLE
CA	11001	e	REPLACED LEFT FRONT SEAT BELT BUCKLE ASSY. 03 18 13.32 14.31.

R094-011 15043

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair TECH_TXT2	2001 Exped repeat repair CUST_TXT	2001 Exped repeat repair_A REA_CD	2001 Exped repeat repair_C COUNTRY_CD	2001 Exped repeat repair_SL S_DLR_CD
	INSTALL S.O. PART FOR SEAT BELT BUCKLE (POSS RECALL)	609	USA	315040
	DRIVERS SEAT BELT BUCKLE INOP	*	USA	342574
	SO PART SEAT BELT INSTALL	062	USA	343008
	DRIVERS SEAT BELT COMES UNBUCKLED.	763	USA	343319
	S40 STATES THAT THE PASS SIDE SEATBELT IS NOT LATCHING PROPE	423	USA	346235
	CHECK SEAT BELT SOP	609	USA	315040
	REPLACE SEAT BELT (SOP) STICKS	201	USA	314340
	DRIVER SEAT BELT BUCKLE INOP	*	USA	358838
	CUST STATES THE DRIVERS SEAT BELT UNLATCHES WHILE DRIVING. CONCERN OCCURS INTERMITTENTLY...CK & ADVI	909	USA	354172
		313	USA	345345
	INSTALL SPECIAL ORDER PARTS RELATED TO SEAT BELT RECALL ON PREVIOUS RO.	714	USA	354265
	DRIVERS SEAT BELT WONT LATCH	616	USA	345180
	CUST STATES DSIDE SEATBELT BUCKLE COMES LOOSE	732	USA	314376
	SEATBELT NOT STAYING ENGAGED	209	USA	351077
	DRIVERS SEAT BELT CAME UNLATCHED WHILE DRIVING..S40	970	USA	355491
	CK.CAN NOT SECURE DRIVER FRONT SEATBELT	781	USA	312386
	CUSTOMER STATES SEATBELT RECALL INSTALL SOP	508	USA	312190
	LT FRONT SEAT BELT WONT LATCH AT TIMES S O	925	USA	351078

R004-011 19844

01_Exped_NavFrontBuckle_Query

	FRONT SEAT BELT BUCKLES DO NOT FULLY LATCH	847	USA	342412
	LEFT FRONT SEAT BELT INTERMIT STICKS	989	USA	346237
		516	USA	314361
	LEFT FRONT SEAT BELT UNHOOKS WHILE DRIVING	810	USA	346275
	CERTAIN 2001 GRAND MARQUIS, NAVIGATOR, AND TOWNCAR VEHICLES SEAT BELT BUCKLE RETENTION SEE RECA	757	USA	328837
	826 CUST STATE LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING & LATCH ON BELT IS BACKWARD	816	USA	963559
	REPLACE LEFT AND RIGHT FRONT SEAT BELT BUCKLES S.O.PARTS	724	USA	818309
	SEAT BLET INOP	847	USA	342535
	CHECK SEAT BELT ON DRIVER SIDE WONT LATCH EASILY	815	USA	322320
		518	USA	314381
	OWNER STATES LT FRT SEATBELT COMES OUT OF BUCKLE WHILE DRIVING	808	USA	951484
	CUSTOMER STATES SEAT BELT ON DRIVERS SIDE UN LATCHES ITSELF	303	USA	355115
	SEATBELTS DO NOT LATCH PROPERLY WITH TOOL	314	USA	363197
	CUSTOMER STATED THE DRIVERS SEAT BELT HAS COME UNLOCKED THREE DIFFERENT TIMES	559	USA	351048
	CUST STATES TO PERFORM SEAT BELT RECALL 01S21	914	USA	314541
	DRIVERS SEATBELT BUCKLE INOP	*	USA	355836
	FRONT SEAT BELT WONT LATCH	620	USA	363174
	SEAT BELT COME UN BUCKLED WHILE DRIVING	973	USA	314474
	THE RIGHT FRONT SEAT BELT BUCKLE WILL NOT ENGAGE.	617	USA	312396
	PARTS REPLACE SEAT BELT ON THE DRIVERS SEAT	270	USA	346688
	CUSTOMER STATES DRIVERS SEAT BELT DOES NOT LATCH	541	USA	
	CUST STATES DRIVERS SEATBELT UNLATCHES ITSELF	604	USA	325062
	CUST STATES DRIVERS SEAT BELT WILL NOT CLIP SOP HERE	303	USA	355120

01_Exped_NavFrontBuckle_Query

	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH	281	USA	387032
	LEFT FRONT SEAT BELT WILL NOT BUCKLE AND CHIME STAYS ON	603	USA	312483
	RIGHT FRONT SEAT BELT BUCKLE INOP	301	USA	328486
	DRIVERS SIDE SEAT BELT LATCH NOT WORKING AT TIMES	410	USA	326057
	VEH SEATBELT LATCH INOP	*	USA	355836
	L F SEAT BELT W N LATCH	*	USA	355836
	C S THAT LEFT FRONT SEAT BELT RECEIVER WILL NOT LOCK CHECK AND ADVISE	480	USA	364289
		516	USA	314381
	CK RIGHT FORNT SEATBELT BUCKLE INTERMITTANTLY WILL NOT LATCH	847	USA	342535
	INSTALL SOP SEAT BELT BUCKLE	610	USA	316304
	CHECK DRIVERS SEAT BELT COMES UNLATCHED 840	713	USA	367286
	RECALL 01821 REPLACE SEATBELT	423	USA	326106
	PASSENGER SIDE SEATBELT BUTTON STICKS SOP IN	757	USA	328278
	RIGHT FRONT SEATBELT BUCKLE JAMS	703	USA	328008
	REPLACE RIGHT FRONT SEAT BELT BUCKLE WITH NEW WILL NOT LATCH PARTS IN STOCK TO REPLACE	810	USA	345356
	CUSTOMER STATES DRIVERS SEAT SEAT BELT WONT STAY LATCHED	515	USA	363588
		781	USA	312288
	PASSENGER FRONT SEAT BELT HARD TO CLASP IN	913	USA	363407
	CHECK PASS SIDE COMES UNLATCHED	843	USA	326223
	DRIVER SIDE SEAT BELT INOP	770	USA	326140
	C S THE DRIVERS SEAT BELT WILL NOT STAY LATCHED	770	USA	326233
	DRIVER S SEAT BELT KEEPS UNLOCKING WHILE DRIVING SEE FILE	407	USA	325189
	CUSTOMER STATES DRIVER SEAT BELT COMES OUT WHILE DRIVING SOP IN	801	USA	322664

R004-011 15946

01_Exped_NavFrontBuckle_Query

	CUSTOMER STATES DRIVERS SEAT BELT WILL COME UNLATCHED BY ITSELF WHILE DRIVING.CC 626	407	USA	325216
		310	USA	354260
	CUSTOMER STATES THE RIGHT FRONT SEAT BELT DOES NOT LATCH	714	USA	354015
	SPECIAL ORDERED PARTS ORDERED FOR RECALL, PREVIOUS RO 41062, TECH # 12, L F DRIVERS SEAT BELT, R F PASS SEAT SIDE, AND RIGHT REAR OF MIDDLE ROW SEAT BELT WONT BUCKLE	925	USA	351024
	SPECIAL ORDERED PARTS ORDERED FOR RECALL, PREVIOUS RO 41062, TECH # 12, L F DRIVERS SEAT BELT, R F PASS SEAT SIDE, AND RIGHT REAR OF MIDDLE ROW SEAT BELT WONT BUCKLE	825	USA	351024
	CUSTOMER STATES DRIVERS SEAT BELT INDICATOR INOP	714	USA	354015
	CUSTOMER STATES LEFT FRONT SEATBELT WONT LATCH	407	USA	325132
	325 LEFT FRONT SEAT BELT WONT STAY LATCHED AT TIMES SPECIAL ORDER SEAT BELT LATCH HERE	813	USA	325169
	RECALL 01S21 SEAT BELT BUCKLE SOP HERE PASSENGER SIDE	619	USA	354600
	SPO HERE FOR RECALL # 02S21 INSPECTED ON 12 19 01 RO# 10564 LEFT FRONT FAILED	407	USA	325184
	C S DRIVER SEAT BELT WONT LATCH	407	USA	325032
	CUSTOMER STATED THE DRIVERS SEAT BELT WILL NOT STAY LATCHED.	214	USA	367510
		805	USA	354290
	BOTH FRONT SEAT BELT DONT SNAP TOGETHER GOOD	813	USA	325007
	REPLACE DRIVERS SEAT BELT BUCKLE INOP	334	USA	326332
	CUST STATES PERFORM RECALL ON SEATBELT ASSY	205	USA	326378

R004-011 15047

01_Expd_NavFrontBuckle_Query

CK CUST STATES DRIVERS SEAT BELT WILL COME LOOSE FROM BUCKLE INTERMITTANTLY. S40	770	USA	326057
	805	USA	354290
PASS FRT SEAT BELT INSPECTION	334	USA	326135
CK PASSENGER FRONT SEAT BELT WONT LATCH	702	USA	354137
CUST STATES CK PASS FT SEAT BELT BUCKLE INOP	281	USA	367023
CUST STS DRIVERS SEATBELT WONT LATCH	818	USA	354301
CK PASS FRT SEAT BELT LATCH WONT STAY UP SOP IN	681	USA	354041
DRIVERS BELT WILL NOT CLOSE	767	USA	328278
LEFT FRONT DRIVER SEAT BELT INOP	205	USA	326075
CUSTOMER STATES PASSENGER FRONT SEAT BELT WILL NOT CLICK IN BUCKLE	770	USA	326057
SEAT BELT BUCKLE	909	USA	354263
	512	USA	367036
LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIMES	662	USA	322423
LEFT SEAT BLET NOT LATCHING AT TIMES	405	USA	367235
LEFT FRONT SEAT BELT COMES UNBUCKLED BY ITSELF AT TIMES	618	USA	354301
CUST STATES L F SEAT BELT KEEPS COMING UNBUCKELED	912	USA	326216
SEAT BELT INOP	809	USA	354015
	806	USA	354290
SOP SEAT BELT IN	305	USA	325044
RF SEAT BELT WONT BUCKLE	713	USA	367023
	310	USA	354100
CHECK SEAT BELT P O	912	USA	325182
DRIVERS SEAT BELT WILL NOT UNBUCKLE, SOMETIMES	688	USA	354565
CHECK AND ADVISE CUST STATES DRIVER SIDE SEAT BELT DOES NOT LOCK IN TO BUCKLE. S40	562	USA	354061
LEFT FRONT SEAT BELT WONT BUCKLE	803	USA	326219

R004-011 12646

01_Exped_NavFrontBuckle_Query

	THE RIGHT FRONT SEAT BELT BUCKLE IS INOPERATIVE.	404	USA	326136
	CUST STATES DRIVERS SIDE FRONT SEAT BELT POPS OUT OF LOCK	281	USA	387023
	CUSTOMER STATES THAT PASS FRONT SEAT BELT BUCKLE IS INOP.	714	USA	354015
	CS DRIVER SIDE SEAT BELT BUCKLE KEEPS UNBUCKLING	203	USA	124009
	S26 LT FT SEAT BELT WONT STAY LATCHED	713	USA	162031
	SEAT BELT BUCKLE RETENTION	972	USA	162525
	INSTALL S.O.P BUCKLE DRIVERS SEAT AS PER RECALL 01S21	708	USA	121214
	CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PPC PARTS HERE.	650	USA	172013
	RIGHT FRONT SEAT BELT WILL NOT CONNECT	819	USA	121019
	S40 CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING	214	USA	152003
	O R L F SEATBELT BUCKLE COME LOOSE	407	USA	124224
	S40 RIGHT FRONT SEAT BELT WAS ORDERED FOR RECALL BUT NEVER REPLACED IN STOCK	713	USA	152031
PLACED PASSENGER BUCKLE PER RECALL 01S21 SEE RO 361713 FOR DRIVERS BUCKLE REPLACEMENT.	RECALL SEAT BELT BUCKLE,REFER TO RO 361713	281	USA	152054
	PASS SIDE SEAT BELT DOESN T WORK	770	USA	121025
	CUSTOMER STATES R F SEAT BELT NOT HOLDING ADVISE	813	USA	124449
	CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED RECALL WAS CHECKED NO PROBLEM 8 3 01 BY TECH	770	USA	121022
	PASSENGER SEATBELT COMES UNBUCKLED SOMETIMES	409	USA	152052
MILEAGE ON RO 224538 SHOULD HAVE BEEN 2420 NOT 24206.	S40 OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED AT TIMES, RED CAP DOESNT COME BACK UP PROPERL	281	USA	152020
	REPLACE DR. FT. SEATBELT SOP USE SPO 02128003	210	USA	152058
	CUST STATES CHECK FRONT SEATBELT BUCKLES	770	USA	121024
		415	USA	172013

K004-011 15049

01_Exped_NavFrontBuckle_Query

VERIFY THE SEAT BELT RECALL WAS PERFORMED CORRECTLY CUST THOUGHT A PART HAD TO BE ORDERED LAST VISIT BUT NO SOP IS IN FOR IT.	941	USA	124402
WARRANTY REPAIR DRIVER SIDE SESAT BELTR BUCKLE WILL NOT HOLD	954	USA	124009
DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING	281	USA	152062
C S THAT THE DRIVER S SEAT BELT IS INOP	972	USA	152017
DRIVERS FRONT SEAT BELT BUCKLE DOES NOT LATCH INTERM. WHEN IT DOES IT IS HARD TO GET BELT UN LACTCHED	281	USA	152054
LEFT FRONT SEAT BELT DOES NOT STAY LATCHED. CHIME FOR SEAT BELT GOES OFF EVEN AFTER SEAT BELT IS BUCKLED	979	USA	152734
DR FRT SEAT BELT COMES UNLATCHED WONT LATCH AT TIMES S39	972	USA	152017
SEAT BELT ORDERED ON RECALL RO #13422	940	USA	162414
	813	USA	124461
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES LOCK	305	USA	124901
CS DR SEAT BELY WONT LATCH S28	318	USA	123038
S26 CUST STS LEFT FRONT SEATBELT UNLATCHES BY ITSELF SOP RO#328063 MI 13720 1 2 02	407	USA	124227
S40 DRIVERS SEAT BELT WILL NOT LATCH	713	USA	152049
CUSTOMER STATES THE DRIVERS SEAT BELT DOES NOT ALWAYS LOCK IN 3	949	USA	171034
CK FOR DRIVER SIDE SEATBELT INOP FEMALE PART	770	USA	121480
PASS FRONT SEAT BELT INOP	305	USA	124012
DR. SEAT BELT BUCKLE HAS COME LOOSE TWICE SINCE RECALL PERFORMED.	972	USA	152017
DRIVERS SEAT BELT	972	USA	152017
L.F. SEAT BELT BUCKLE WONT LATCH SOP IN	512	USA	152303
INSTALL SOP PASS FRONT SEAT BELT INOP	407	USA	124226

R094-011 15025

01_Expad_NavFrontBuckle_Query

	CUSTOMER STATES:DRIVERS SEAT BELT COMES UNBUCKLED WHILE DRIVING.	281	USA	152048
	CHECK SEATBELTS	628	USA	171063
	S40 CK MID SEAT AND DRIVERS SEAT BELTS WILL COME UNBUCKLED. RELATED TO 01S21 IF SO REFERENCE BACK.	913	USA	153009
	C & LF SEAT BELT WONT LOCK CK AND ADVISE	958	USA	152104
	T90 SEE DUANE DRIVERS FRONT SEAT BELT WONT LATCH INT TRIM TAN 1H	949	USA	171074
	CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED	680	USA	162568
	DRIVERS SEAT BELT INOP PART HERE REF.RO#84032, TECH 117 BY NOON	770	USA	148209
	S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIVE..	972	USA	152509
	SEAT BELT BUCKLE INSTALL SOP	954	USA	124009
	CUSTOMER STATES RIGHT SEATBELT DOES NOT ALWAYS LATCH	915	USA	152540
	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE INOP	210	USA	152067
	828 DRIVERS SIDE FRONT SEAT BELT UNBUCKLES BY ITSELF	817	USA	152018
	CUST STATES PASS FRT SEAT BELT WILL NOT LATCH	817	USA	152020
	S40 CUSTOMER STATES PASSENGER SIDE SEAT BELT BUCKLE STICKING, STATES NOT LATCHING...	628	USA	171073
	SEATBELT BUCKLE UNLATCHES	210	USA	152063
	CK BOTH DRIVER AND PASSANGER SEAT BELT HARD TO UNSNAP	229	USA	
	CUST STATES PASS FRT BELT WONT LATCH CHECK AND ADVISE	714	USA	171057
	CUST SAYS RIGHT FRONT SEAT BELT DOES NOT HOLD AND COMES UNLATCHED	972	USA	162013

R004-911 13821

01_Expd_NavFrontBuckle_Query

	REPAIR RIGHT AND LEFT FRT SEAT BELT BUCKLES DO NOT CATCH AT TIMES. ** PARTS ORDERED & HERE ** TECH# 8370 **	405	USA	152884
	CUST STATES LEFT SEAT BELT GET LOOSE WHEN DRIVING	305	USA	124007
	CUST STATES MIDDLE SEAT CENTER SEAT BELT WONT LATCH	817	USA	152018
	SEAT BELT CHIMES, SEAT BELT DOESNT CLICK IN ALL THE WAY	979	USA	152134
	SEAT BELT BUCKLE INOP. SERVICE INSTALL PART	979	USA	152134
	INSTALL SOP SEAT BELT BUCKLE	714	USA	171082
	DRIVERS SEAT BELT WILL NOT BUCKLE	603	USA	121274
	FRONT SEAT BELR BUCKLES ERRATTIC WONT LATCH.	618	USA	124208
	CUST ATATES THAT PASS SIDE FRT SEAT BELT WILL NOT LOCK S26	704	USA	121212
	CUST ST THE DRIVERS SIDE BUCKLE IS COMING LOOSE SEATBELT POPS OPEN BY ITSELF	609	USA	116445
	DRIVER SIDE SEATBELT DOEN T HOLD	805	USA	171498
	CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE	412	USA	144017
	CUSTOMER STATES THE DRIVERS SEAT BELT WILL POP OUT (UNLATCH) WHILE DRIVING.	201	USA	113147
	CK. DRIVERS SIDE FRONT SEAT HAS COME LOOSE WHILE DRIVING	704	USA	121213
	CUSTOMER STATES DRIVERS SEATBELT DOESNT LOCK CLICK SHUT	616	USA	113083
	RF SEAT BELT DOES NOT ALLWAYS LATCH	670	USA	116574
		*	USA	
	CUSTOMER STATES: DRIVER SEAT BELT IS INOPERATIVE; PER S.O.P INSTALL SEAT BELT PART. INSPECT AND ADVISE	760	USA	171078
FRONT SEAT BELT BUCKEL. OK	CUSTOMER STATES DRIVERS SIDE SEAT BELT RECEPTICLE DOES NOT ALWAYS LATCH. BUCKLE WAS INSPECTED LAST MONTH PER RECALL AND PASSED INSPECTION	810	USA	148048
	CUST STATES SEAT BELT INOP	201	USA	113154
	SEAT BELT INOPP	412	USA	144007

R004-011 15832

01_Exped_NavFrontBuckle_Query

	O S DRIVERS SIDE SEAT BELT BUCKLE INOP. INSTALL SPEC ORDERED PART	732	USA	113568
		206	USA	174024
	LEFT FRONT SEAT BELT WILL NOT STAY LATCHED	708	USA	
	DS SEATBELT INOP	302	USA	127588
	DRIVERS SEAT BELT DOES NOT ALWAYS LATCH SOP HERE	248	USA	148438
ONE	S40 CUS STS THAT THE LF SEAT BELT WONT LATCH, S O PART	812	USA	147527
	CK R FRT SEAT BELT BUCKEL WONT LATCH	873	USA	113048
	CUST STATES DRIVERS SEATBELT KEEPS COMING UNHOOKED	810	USA	148048
	LEFT FRONT SEAT BELT WONT LATCH	703	USA	127049
	C S RIGHT FRONT SEAT BELT WILL NOT LOCK INTO RECEIVER	201	USA	113147
	DRIVER SEAT BELT STICKS OR DOENT MAKE A CLICKING NOISE TO LOCK IN	310	USA	171208
	PERFORM RECALL 01S21 SEAT BELT BUCKLE	818	USA	171251
	S O PART SEAT BUCKLE DRIVERS FT USE SPO 01287006	301	USA	127047
	REPAIR FOR DRIVER SEAT BELT COMES UNDONE AT TIMES.INSTALL SOP.	918	USA	172202
	DRIVER SEAT POSITION THE MALE END OF SAFETY BELT KEEPS POPPING OUT.	703	USA	127081
	ADD ON WARRANTYDRIVER SEATBELT DOEW NOT ALWAYS STAY SECURE	248	USA	148028
	CUSTOMER STATES, DRIVERS SIDE SEAT BELT FAILED INSTALLED SOP SEAT BELT (DRIVERS)	603	USA	111582
	CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART	317	USA	147027

R004-011 19823

01_Exped_NavFrontBuckle_Query

	THE DRIVERS SEATBELT IS NOT WORKING PROPERLY SOP HERE	818	USA	153015
	CUSTOMER STATES DRIVERS SEATBELT BUCKLE NOT WORKING PROPERLY	225	USA	123203
		405	USA	152206
	CHECK AND ADVISE IN SEATBELT	619	USA	171102
	CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING	760	USA	171078
	CUSTOMER SAYS THE PASSENGER SEAT BELT WONT LOCK	361	USA	152099
	CUSTOMER STATES THAT THE PASS SEAT BELT WILL NOT LOCK INTO PLACE	407	USA	124478
	INSTALL SPO # 01281014 CUSTOMER STATES PASSENGER SIDE SEAT BELT IS NOT WORKING . TECH # 110 PART #7881202 AAA USE SPO 01281014	714	USA	171052
	CUST STATES FRONT SEAT RIGHT OUTER BELT DOESNT LATCH	628	USA	171097
	DRIVERS SEAT BELT UNBUCKLES	281	USA	152047
	PASSENGER FRONT SEAT BELT COMES UNLATCHED WHEN DRIVING 3 36	619	USA	171080
	RIGHT SIDE MIDDLE SEAT BELT BUCKLE DOES NOT WORK	209	USA	172514
	S40 PER CUST, THE DRIVERS SEAT BELT COMES UNLATCHED. SEE HISTORY	512	USA	162302
	T90 C S DRIVERS SEAT BELT WONT STAY LATCHED SOP	504	USA	123009
	DRIVERS SEATBELT KEEPS COMMING UNLATCHED.	713	USA	152024
	DRIVER SIDE SEAT BELT WON T LOCK	770	USA	121026
	CUST STATES D S SEATBELT BUCKLE WONT LATCH	305	USA	124003
	REPLACE DRIVERS SEAT BELT (FINISH LINE A	550	USA	172024

R004-011 15884

01_Exped_NavFrontBuckle_Query

	CHECK SEAT BELT OPERATION	504	USA	123008
	RECALL 01S21 SEAT BELT BUCKLE RETENTION BOTH SIDES FAILED	480	USA	171175
	01S21 SEAT BELT BUCKLE SOP	706	USA	121205
	CUSTOMER STATES DRIVERS SEATBELT INOPERATIVE S O PART IN ? SEE HISTORY	941	USA	124480
	SEAT BELT ON DRIVERS SIDE WILL NOT STAY LOCKED	770	USA	121488
	INSTALL S.O.PW02117011 CUSTOMER STATES RIGHT FRONT SEAT BELT INOP	662	USA	171104
	CUST STATES DRIVER SIDE SEATBELT KEEPS COMING UNBUCKLED SOP PART IN STOCK	954	USA	124010
	DRIVERS SEATBELT UNBUCKLES WHILE DRIVING	210	USA	152007
	RIGHT FRONT SEAT BELT INOP	760	USA	171430
	LEFT SEAT BELT BUCKLE IS NOT WORKING	816	USA	171058
		805	USA	171452
	C S DRIVER SEAT BELT INOP.....	830	USA	152719
	S40 C S THE DRIVERS SEAT BELT POPS LOOSE WHEN DRIVING	501	USA	123206
	CUS STATES D SDIE SEAT BELT COMES UNDONE RO 96954 RECHECK TECH 160	210	USA	162067
	L F SEAT BELT BUCKEL WONT RELEASE	561	USA	124218
	SEAT BELT ON DRIVERS SIDE WILL NOT BUCKLE	404	USA	121007
	CUSTOMER STATES THAT AFTER THE SEAT BELT RECALL WAS DONE THE PASS FRONT SEAT BELT POPS OFF	407	USA	124213
	S25 DRIVERS SEAT BELT WILL NOT STAY BUCKLED (01S21?)	713	USA	152049
	A99 SOP SEAT BELT IN PASSENGERS SIDE BUCKLE FOR RECALL	954	USA	124015
	OWNER STATES DRIVERS SEATBELT COMES UNLATCHED WHEN PULLED ON	281	USA	152037

K004-011 15625

01_Exped_NavFrontBuckle_Query

	DRIVERS SEAT BELT DOESNT LATCH, INSTALL SOP PARTS USE SOP 01188002	702	USA	171187
	S40 DRIVERS SIDE SEAT BELT UNCLICKED OVER BUMP TWICE	407	USA	124227
APROX TIME: 0.4 HRS JOB STARTED 10.716.6 ON 05 16 02	CUSTOMER STATES THE LEFT FRONT SEAT BELT BUCKLE WONT LATCH (GRAY)	562	USA	171058
	DRIVER SEATBELT INOP	262	USA	121648
	CHECK DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING CHECK OTHER SEAT BELTS FOR PROPER OPERATION	817	USA	152016
	C S DRIVER SEAT BELT BUCKLE INOP ALSO LEFT REAR SEAT BELT KEEPS TIGHTING UP	928	USA	171178
	CHECK AND ADVISE ON DRIVERS SEAT BELT WILL COME UNLOCKED WHEN DRIVING SOP HERE	908	USA	171108
	RT FT SEATBELT WONT HOLD IN BUCKLE ASY	308	USA	141078
	CUSTOMER STATES RIGHT FRONT SEAT BELT IN OP REPORT	510	USA	172013
	CUST STATES SEAT BELT DRIVERS SIDE WILL COME LOOSE	409	USA	152754
	S40* CUST STATES FRONT PASS BUCKLE WILL NOT LATCH...(SOP HERE)	214	USA	152003
	LEFT FT SEAT BELT SEAT BELT COMES UNBUCLD FOR NO REASON	704	USA	121213
	CHK FOR D SEATBELT COMING UNLATCHED WHILE DRIVING.	817	USA	152013
	S40 CUST STATES LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIME POPS OUT WHILE DRIVING	817	USA	152008
	CK SEATBELT WONT LATCH	936	USA	152188
		909	USA	171097
	INSTALL SOP HERE FOR SEATBELT	310	USA	171015
	S40 CUST STATES PASS SEAT BELT DOES NOT LATCH EVERY TIME	581	USA	124224
	CUSTOMER STATES:DRIVERS SEAT BELT KEEPS COMING UNLATCHED PLS RECHECK PASSENGERS AS WELL	841	USA	124480

R034-011 12858

01_Exped_NavFrontBuckle_Query

	840 CUST CONCERN DRIVER SIDE SEAT BELT NOT WORKING CORRECTLY	954	USA	124015
	SEAT BELT INOP (PARTS HERE)	910	USA	121225
	805 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES	972	USA	152002
	S40 D S F RESTRAINT UNLOCKS WHILE DRIVING	305	USA	124001
	CUST STATES INNT THE DRIVER SEAT BELT WILL POP OUT FROM THE BUCKLE CHECK AND ADVISE	408	USA	172039
	DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING LIGHT TAN	938	USA	152158
	CUST STATES FRONT SEAT CENTER SEAT BELT INOP, PLEASE INSTALL SOP SEAT BELT, SEE PHIL IN PARTS	719	USA	156481
		818	USA	171019
	INSTALL SPECIAL ORDERED BELT BRAKES FRONT SEATBELT BROKEN REFER BACK TO RO 142840	910	USA	121225
	CUST STATES PASS FRONT SEAT BELT BUCKLE WILL NOT ACCEPT BELT INTO RECEPACLE WITHOUT DEPRESSING BUTTON AND FORCING IN CK AND ADVISE	780	USA	171430
	DRIVER SEATBELT WILL NOT BUCKLE AT TIMES USE SPO 02056001	910	USA	121028
	DRIVERS SEATBELT WILL NOT STAY LATCHED INSTALL SOP	708	USA	141062
	DR SEATBELT WONT FASTEN	954	USA	124015
	CK THE SEAT BELT DRIVER SIDE NOT LATCHING PROPERLEY	337	USA	123271
	828 CUST STATES DRIVERS SEAT BELT WONT STAY LATCHED	601	USA	123309
	C S THE SEAT BELT WILL COME UNLATCHED	318	USA	123223
	CUST HAS RETURNED TO HAVE SOP INSTALLED. (REFER TO HISTORY RO#: 68917)	323	USA	171022
	C S TYHAT THE DRIVER SEAT BELT ENTERPRISE D#278635	972	USA	152012
	THE DRIVERS SEAT SEATBELT RECIEVER KEEPS LETTING LOOSE OF THE BELT, CHECK AND ADVISE	938	USA	152166
		310	USA	171029
	CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...	915	USA	152016

R024-911 15897

01_Exped_NavFrontBuckle_Query

		806	USA	171452
	DRIVER SEAT BUCKLE WILL NOT ALWAYS LATCH	281	USA	152024
	CUST STATES SEAT BELST WONT LATCH INSTALL S.O.P.	310	USA	171015
	DRIVERS SIDE FRONT SEAT.BELT COMES UNLATCHED AT TIMES	972	USA	152462
	CUST STATES THE DRIVERS SEAT BELT WILL NOT STAY LOCKED POPS OFF WHILE DRIVING	661	USA	171491
		616	USA	171019
	S40**DRIVERSIDE DEAT BELT LATCH WILL NOT STAY LATCHED	214	USA	152003
	CUSTOMER STATES SEAT BELT WILL NOT LATCH SOP HERE	770	USA	121405
	PASS SEAT BELT WILL NOT LOCK CK ALL SEAT BELTS	281	USA	152044
	PASSENGER FRONT SEATBELT DOESNT LATCH	702	USA	171167
	C S DRIVERS FRONT SEAT BELT UNBUCKLES WHEN STOPPING	813	USA	124208
	CUSTOMER STATES DRIVERS SEATBELT WILL NOT LATCH SOMETIME	615	USA	152573
	A99 DRIVER SIDE SEAT BELT WILL NOT STAYED BUCKLE	281	USA	152032
	LEFT SEAT BELT WILL NOT LATCH	626	USA	171072
	PARTS REPLACEMENT SEAT BELT	305	USA	124003
	INSP. L F SEAT BELT WILL NOT BUCKLE AT TIMES AND IS HARD TO BUCKLE AT OTHER TIMES	817	USA	152020
	CUSTOMER STATES RIGHT FRONT SEAT BELT INOP SOP	661	USA	171491
	CUST STATES DRIVERS SEAT BELT COMES UNHOOKED	813	USA	124446
	CUST STATES SOP IS IN FROM FRI SEAT BELT	228	USA	124017
	CUST STATES DRIVERS SEAT BELT WILL POP LOOSE WHEN DRIVING, REBUCKLE AND WILL POP LOOSE AGAIN	251	USA	124017
	CUSTOMER STATES DRIVERS SEATBELT BUCKLE DOES NOT HOLD BELT AT TIMES. CHECK AND ADVISE.	916	USA	172201
	SEAT BELT N DR SIDE COMES APART WHILE DRIVING WILL NOT STAY LATCHED	985	USA	123060
	REPLACE DEFECTIVE SEATBELT BUCKLE	SPW 843	USA	121291

R004-011 15058

01_Expd_NavFrontBuckle_Query

CUSTOMER STATES PASSENGER FRONT SEAT BELT WASNT BUCKLEY CORRECTLY	727	USA	124202
PERFORM 01S21 SEATBELT BUCKLE	817	USA	152019
PASS SEAT BELT WILL NOT LATCH PART HERE	808	USA	152578
PASS. SIDE SEAT BELT INOP WILL NOT LATCH AT TIMES	872	USA	152525
CUSTOMER STATES DRIVER SEATBELT LATCH INOP.SOP ORDERED BY QS.SEE DENNIS IN PARTS.	254	USA	152504
REPLACE DEFECTIVE SEAT BELT FOUND BY SEAT BELT RECALL INSPECTION	252	USA	121844
SEAT BELT RECALL 01S21..SPECIAL ORDERED PARTS HERE	865	USA	121869
CUST STATES DRIVERS SEAT BELT BUCKLE WONT HOLD, IF BUMP IT WILL LET GO	251	USA	124017
RECALL 01S21 BOTH FAILED CUS	727	USA	124454
T90 RT FRT DRIVERS SEAT BELT BUCKLE FAILS RECALL TEST 01S21 ON RO 85231 INSTALL SOP DRIVERS SEAT BELT BUCKLE	727	USA	124202
PASS FRONT SEAT BELT INOP PARTS IN 315	256	USA	121108
FAULTY SEAT BELT BUCKLES	840	USA	152529
CK DRIVERS SEAT BELT WONT STAY ATTACHED	872	USA	152014
DRIVERSIDE SEAT BELT WILL NOT OPERATE INSTALL SPECIAL ORDER PART	813	USA	124486
CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE DOES NOT WORK PROPERLY	912	USA	124452
01S21 REPLACE PASSENGER SIDE SEAT BELT BUCKLE SOP IN	949	USA	171082
SOP HERE FOR SEAT RECALL 01S21 REF RO 200458	972	USA	152012
CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE INOP.	626	USA	171040
S40 PASS SIDE MIDDLE SEAT BELT LATCH COMMING APART	214	USA	152003
CUST STATES PASS FRONT SEAT BELT WILL NOT STAY LATCHED UNBUCKLES WHEN DRIVING DOWN THE ROAD AND LEFT	256	USA	121717

R084-011 15028

01_Expd_NavFrontBuckle_Query

	CUSTOMER STATES THAT THE FRONT SEAT BELT ARE NOT LOCKUNG IN NEEDS LEFT AND RIGHT SIDE BELT TRIM CODE 12	252	USA	121647
	CUST STATES DR SIDE SEAT BELT INOP SOP IN	714	USA	171057
	CUST STATES DRIVER SEAT BELT SNAPS LOOSE BY ITSELF POPS OUT BY ITSELF	770	USA	121025
	CUSTOMER STATES DRIVERS SEAT BELT KEEP COMING UNBUCKLED	770	USA	121059
	SEAT BELT ON DRIVERS SIDE INOP	828	USA	121610
	CS THAT THE DRIVERS SEAT BELT WILL NOT FASTEN AT TIMES	562	USA	171051
	DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED	228	USA	121408
	SOP IN CUST STATES VEH HAS SEAT BUCKLE WILL NOT LATCH.	817	USA	152020
	CUST STATES THAT THE DRIVERS SIDE SEAT BELT COMES UNBUCKLED WHILE DRIVING	767	USA	127080
	REPLACE SOP SEAT BELT	708	USA	127009
	S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING	210	USA	162083
	S40 DRIVER SEAT BELT NOT CLICKING TO LOCK	407	USA	124227
	CUSTOMER STATES RIGHT FRT SEATBELT**** FEMALE SIDE WONT LATCH	849	USA	171095
	DIAG DRIVERS SEAT BELT BUCKLE WONT LATCH AT TIMES CUST HAS TO FIRST PUSH RELEASE AND THEN IT WILL BUCKLE CHECK ALL OTHERS	405	USA	152803
	RECALL 01S21 DRIVER FRONT SEAT BELT USE SPO 01309037	770	USA	121080
	CHECK SEAT BELT	814	USA	147030
	THE DRIVERS SEAT BELT RELEASES WHILE DRIVING	281	USA	152052
	SOP SEAT BELT	909	USA	171150
	PASSENGER SIDE FRONT SEAT BELT BUCKLE CLICKS.	619	USA	171080
	S28* DRIVERS SEAT BELT KEEPS COMMING LOOSE	214	USA	152003
	LEFT SEAT BELT BUCKLE COMES LOOSE BY SELF	708	USA	121205
	REPLACE CENTER ROW RIGHT SEAT BELT BUCKLE.PER TOM PEELER FOE	404	USA	121001

R004-011 15688

01_Expd_NavFrontBuckle_Query

S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/ 139533	818	USA	171040
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 139534/ 139533	818	USA	171040
CUSTOMER STATES SEAT BELT KEEPS UN LOCKING	388	USA	124200
	818	USA	171043
STATES SEAT BELT WILL NOT LATCH S40	812	USA	121209
CUST STATES SEAT BELT IS INOP (SOP IN STOCK)	808	USA	171152
SEAT BELT WILL NOT CONNECT PROPERLY USE SPO 01212002	819	USA	121019
DRIVER SEAT BELT LATCH HANGS AT TIMES	602	USA	171173
RECALL 01S21	770	USA	121007
CK DRIVERS SIDE SEATBELT UNBUCKLES ON ITS OWN	919	USA	121028
S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE	818	USA	171040
CHECK LEFT FRONT SEAT BELT BUCKLE IN OP AT TIMES WONT POP UP	628	USA	171031

01_Exped_NavFrontBuckle_Query

2001 Exped repeat repair_T XN_CD	2001 Exped repeat repair_C NTRY_S OLD	2001 Exped repeat repair_Q RT_CD	2001 Exped repeat repair_V FG_CD	2001 Exped repeat repair_A WS_VL_ CD	2001 Exped repeat repair_V RT_CD	2001 Exped repeat repair_TI S_FLAG				Days Between Repair	Miles Between Repair
1	USA	Q21	V05	B4	S08					44	1425
E84	USA	Q21	V05	B4	S08	@				252	10898
2	USA	Q21	V05	B4	S08					20	7946
E84	USA	Q21	V05	B4	S08	@				224	9714
1	USA	Q21	V05	B4	S08					26	1750
1	USA	Q21	V05	B4	S08					75	3379
1	USA	Q21	V05	B4	S08					28	1015
2	USA	Q21	V05	B4	S08					3	421
E84	USA	Q21	V05	B4	S08	@				230	-18415
1	USA	Q21	V05	B4	S08					4	1
E84	USA	Q21	V05	B4	S08					213	14267
E84	USA	Q21	V05	B4	S08					278	18932
E84	USA	Q21	V05	B4	S08	@				224	7729
2	USA	Q21	V05	B4	S08					15	218
2	USA	Q21	V05	B4	S08					24	3118
E84	USA	Q21	V05	B4	S08					285	14500
1	USA	Q21	V05	B4	S08					121	4602
E84	USA	Q21	V05	B4	S08					113	4787

R004-011 12862

01_Exped_NavFrontBuckle_Query

1	USA	Q21	V05	B4	S08				14	261
2	USA	Q21	V05	B4	S08				108	6135
1	USA	Q21	V06	B4	S08				217	7871
2	USA	Q21	V05	B4	S08				55	1227
1	USA	Q21	V05	B4	S08				81	1352
E84	USA	Q21	V05	B4	S08				105	9847
1	USA	Q21	V05	B4	S08				76	1808
2	USA	Q21	V05	B4	S08				28	1428
1	USA	Q21	V05	B4	S08				118	2297
2	USA	Q21	V17	B4	S08				78	2488
E84	USA	Q21	V05	B4	S08	@			275	3899
1	USA	Q21	V05	B4	S08				49	488
1	USA	Q21	V06	B4	S08				77	244
1	USA	Q21	V03	B4	S08				0	0
1	USA	Q21	V05	B4	S08	@			261	10690
E84	USA	Q21	V05	B4	S08				93	8509
1	USA	Q21	V05	B4	S08				150	4193
E84	USA	Q21	V06	B4	S08	@			293	17845
2	USA	Q21	V05	B4	S08	@			28	9
E93	USA	Q21	V05	B4	S08				22	514
E84	USA	Q21	V06	B4	S08	@			36	472
E84	USA	Q21	V05	B4	S08				279	20993
1	USA	Q21	V05	B4	S08				230	8671

NOB-011 15983

01_Expd_NavFrontBuckle_Query

E84	USA	Q21	V05	B4	S08				147	4541
1	USA	Q21	V05	B4	S08				80	4502
2	USA	Q21	V05	B4	S08	Ⓢ			228	8297
E84	USA	Q21	V05	B4	S08	Ⓢ			248	16144
E84	USA	Q21	V05	B4	S08				87	12405
E90	USA	Q21	V05	B4	S08				130	14480
1	USA	Q21	V05	B4	S08				170	2580
1	USA	Q21	V17	B4	S08				3	3
E84	USA	Q21	V05	B4	S08				76	7294
2	USA	Q21	V05	B4	S08				22	887
1	USA	Q21	V05	B4	S08				12	205
E84	USA	Q21	V05	B4	S08				85	2987
E84	USA	Q21	V05	B4	S08				35	1617
E84	USA	Q21	V05	B4	S08				0	0
E84	USA	Q21	V05	B4	S08				52	1188
2	USA	Q21	V05	B4	S08				2	43
1	USA	Q21	V05	B4	S08				12	681
E84	USA	Q21	V05	B4	S08	Ⓢ			295	18685
1	USA	Q21	V05	B4	S08				76	2954
2	USA	Q21	V05	B4	S08				48	2784
E84	USA	Q21	V05	B4	S08				157	8495
1	USA	Q21	V05	B4	S08				14	990
1	USA	Q21	V05	B4	S08				28	3335

R094-911 15884

01_Exped_NavFrontBuckle_Query

E84	USA	Q21	V05	B4	S08	@			209	10798
2	USA	Q21	V05	B4	S08				169	4489
E84	USA	Q21	V05	B4	S08				4	204
E84	USA	Q21	V05	B4	S08				109	5684
E84	USA	Q21	V05	B4	S08				0	0
2	USA	Q21	V05	B4	S08				6	347
E84	USA	Q21	V05	B4	S08				107	8512
E84	USA	Q21	V05	B4	S08				6	96
1	USA	Q21	V05	B4	S08				22	246
E84	USA	Q21	V05	B4	S08				66	6178
E84	USA	Q21	V05	B4	S08				281	6907
1	USA	Q21	V05	B4	S08				138	11454
2	USA	Q21	V05	B4	S08				160	6568
E84	USA	Q21	V05	B4	S08				11	647
1	USA	Q21	V05	B4	S08				21	531
E84	USA	Q21	V05	B4	S08				92	3190

R001-011 15062

01_Expd_NavFrontBucks_Query

1	USA	Q21	V05	B4	S08				122	551
1	USA	Q21	V05	B4	S08				27	2001
E84	USA	Q21	V05	B4	S08	@			258	10583
E84	USA	Q21	V05	B4	S08				153	14153
1	USA	Q21	V05	B4	S08				36	1841
1	USA	Q21	V05	B4	S08				84	1884
E84	USA	Q21	V05	B4	S08				221	13498
E93	USA	Q21	V05	B4	S08				3	142
2	USA	Q21	V05	B4	S08				167	2084
2	USA	Q21	V05	B4	S08				126	5115
2	USA	Q21	V05	B4	S08				151	7684
E84	USA	Q21	V05	B4	S08				141	11684
1	USA	Q21	V05	B4	S08				70	5183
E84	USA	Q21	V05	B4	S08				120	6241
2	USA	Q21	V05	B4	S08				194	9444
E84	USA	Q21	V05	B4	S08	@			284	9628
2	USA	Q21	V05	B4	S08				56	2666
1	USA	Q21	V05	B4	S08				22	831
E84	USA	Q21	V05	B4	S08				147	4872
E84	USA	Q21	V05	B4	S08				48	200
E84	USA	Q21	V05	B4	S08				231	5119
E84	USA	Q21	V05	B4	S08				81	2378
1	USA	Q21	V05	B4	S08				95	1754
E84	USA	Q21	V05	B4	S08				151	6783
E84	USA	Q21	V05	B4	S08	@			273	8902

0004-011 15888

01_Expd_NavFrontBuckle_Quary

E84	USA	Q21	V05	B4	S08				74	5032
E84	USA	Q21	V74	B4	S08				0	0
E84	USA	Q21	V05	B4	S08				182	10588
2	USA	Q21	V05	B3	S08	@			32	15
1	USA	Q21	V05	B3	S08				14	464
E84	USA	Q21	V05	B3	S08				172	8877
1	USA	Q21	V05	B3	S08				8	796
2	USA	Q21	V05	B3	S08				28	582
E84	USA	Q21	V05	B3	S08				122	-8525
1	USA	Q21	V05	B3	S08				5	120
1	USA	Q21	V74	B3	S08				34	1457
1	USA	Q21	V05	B3	S08				148	5051
E84	USA	Q21	V05	B3	S08				0	-1
E84	USA	Q21	V74	B3	S08				182	8104
1	USA	Q21	V05	B3	S08				23	684
1	USA	Q21	V05	B3	S08				48	3685
E84	USA	Q21	V05	B3	S08	@			317	13799
2	USA	Q21	V05	B3	S08				35	-20816
E84	USA	Q21	V74	B3	S08	@			37	2842
2	USA	Q21	V05	B3	S08				165	2256
E84	USA	Q21	V05	B3	S08				81	5928

R004-011 15687

01_Expd_NavFrontBuckle_Query

2	USA	Q21	V05	B3	S08				23	1003
1	USA	Q21	V05	B3	S08				146	3347
E84	USA	Q21	V05	B3	S08				0	0
E84	USA	Q21	V05	B3	S08				171	10578
1	USA	Q21	V05	B3	S08				12	8
2	USA	Q21	V05	B3	S08				10	163
E84	USA	Q21	V05	B3	S08	@			327	21226
2	USA	Q21	V05	B3	S08				89	2458
E84	USA	Q21	V05	B3	S08				168	13286
1	USA	Q21	V05	B3	S08	@			294	8758
1	USA	Q21	V05	B3	S08				1	50
1	USA	Q21	V05	B3	S08				57	805
1	USA	Q21	V05	B3	S08				48	1397
1	USA	Q21	V05	B3	S08				0	0
2	USA	Q21	V05	B3	S08				135	4091
E84	USA	Q21	V05	B3	S08				240	9706
E84	USA	Q21	V05	B3	S08				20	2117
E84	USA	Q21	V05	B3	S08				103	5748
1	USA	Q21	V05	B3	S08				29	1958
E84	USA	Q21	V05	B3	S08				212	5646
E84	USA	Q21	V05	B3	S08				189	9104

R084-011 15676

01 Exped_NavFrontBuckle_Query

E84	USA	Q21	V05	B3	S08				133	4222
1	USA	Q21	V05	B3	S08				237	5558
2	USA	Q21	V05	B3	S08				17	1219
E84	USA	Q21	V05	B3	S08				196	7460
2	USA	Q21	V05	B3	S08				123	8860
1	USA	Q21	V05	B3	S08				116	662
2	USA	Q21	V05	B3	S08				127	4282
2	USA	Q21	V05	B3	S08				0	0
1	USA	Q21	V05	B3	S08				33	399
1	USA	Q21	V05	B3	S08				73	5636
2	USA	Q21	V05	B3	S08				14	966
E84	USA	Q21	V05	B3	S08				5	106
1	USA	Q21	V05	B3	S08				26	2081
1	USA	Q21	V05	B3	S08				240	11605
E84	USA	Q21	V05	B3	S08	@			202	7421
E84	USA	Q21	V05	B3	S08	@			285	12768
E84	USA	Q21	V05	B3	S08				162	13681
1	USA	Q21	V05	B3	S08				17	516

R004-011 19571

01_Exped_NavFrontBuckle_Query

2	USA	Q21	V05	B3	S08				319	11829
1	USA	Q21	V05	B3	S08				2	14
E84	USA	Q21	V05	B3	S08				223	11300
2	USA	Q21	V05	B3	S08				0	0
2	USA	Q21	V05	B3	S08				201	-31721
E84	USA	Q21	V05	B3	S08				262	10177
2	USA	Q21	V03	B3	S08				28	238
1	USA	Q21	V05	B3	S08				40	443
2	USA	Q21	V05	B3	S08				0	0
E84	USA	Q21	V05	B3	S08				241	15247
1	USA	Q21	V05	B3	S08				210	4653
1	USA	Q21	V05	B3	S08				166	6243
E81	USA	Q21	V05	B3	S08				70	8354
1	USA	Q21	V74	B3	S08				91	5075
E84	USA	Q21	V05	B3	S08				240	9456
2	USA	Q21	V74	B3	S08				29	1162
1	USA	Q21	V05	B3	S08				127	4918
E84	USA	Q21	V05	B3	S08				160	7721

MS94-011 15672

01_Exped_NavFrontBuckle_Query

E84	USA	Q21	V05	B3	S08			153	9610
E84	USA	Q21	V05	B3	S08	@		210	6939
1	USA	Q21	V05	B3	S08			26	1628
E84	USA	Q21	V05	B3	S08			107	6286
2	USA	Q21	V05	B3	S08			35	-74832
E84	USA	Q21	V05	B3	S08			132	6828
1	USA	Q21	V05	B3	S08			104	7048
2	USA	Q21	V05	B3	S08			239	5130
1	USA	Q21	V05	B3	S08			35	2192
E84	USA	Q21	V05	B3	S08	@		41	1094
1	USA	Q21	V05	B3	S08			7	220
1	USA	Q21	V05	B3	S08			187	5450
E84	USA	Q21	V05	B3	S08			8	423
E84	USA	Q21	V83	B3	S08			14	844
E84	USA	Q21	V05	B3	S08	@		231	10243
E84	USA	Q21	V06	B3	S08			18	973
E84	USA	Q21	V74	B3	S08			14	854
1	USA	Q21	V05	B3	S08			21	1277
1	USA	Q21	V05	B3	S08			8	196
1	USA	Q21	V05	B3	S08			86	637

R004-011 19673

01_Expd_NavFrontBuckle_Query

1	USA	Q21	V05	B3	S08				0	0
1	USA	Q21	V05	B3	S08				10	485
E84	USA	Q21	V05	B3	S08	Ⓢ			118	11972
1	USA	Q21	V05	B3	S08				13	492
1	USA	Q21	V05	B3	S08	Ⓢ			282	8704
2	USA	Q21	V05	B3	S08				181	2305
1	USA	Q21	V05	B3	S08				0	0
E81	USA	Q21	V05	B3	S08				170	17359
E84	USA	Q21	V05	B3	S08				31	1257
2	USA	Q21	V05	B3	S08	Ⓢ			234	8328
1	USA	Q21	V05	B3	S08				14	4472
E84	USA	Q21	V05	B3	S08				184	7327
E84	USA	Q21	V05	B3	S08	Ⓢ			35	3321
E84	USA	Q21	V05	B3	S08				249	13943
1	USA	Q21	V05	B3	S08				63	89
1	USA	Q21	V05	B3	S08				15	439
2	USA	Q21	V05	B3	S08				143	4245
2	USA	Q21	V05	B3	S08				33	1
1	USA	Q21	V05	B3	S08				10	319

R004-011 15874

01_Exped_NavFrontBuckle_Query

1	USA	Q21	V05	B3	S08			74	993
E84	USA	Q21	V05	B3	S08	@		41	4173
1	USA	Q21	V06	B3	S08			0	0
1	USA	Q21	V05	B3	S08			28	1485
E84	USA	Q21	V05	B3	S08	@		195	9957
2	USA	Q21	V05	B3	S08			11	250
E84	USA	Q21	V05	B3	S08			176	10337
1	USA	Q21	V05	B3	S08			108	2656
E84	USA	Q21	V05	B3	S08			95	5168
1	USA	Q21	V05	B3	S08			134	2108
E84	USA	Q21	V74	B3	S08			296	13436
2	USA	Q21	V05	B3	S08			184	4803
E84	USA	Q21	V05	B3	S08	@		303	11698
E84	USA	Q21	V03	B3	S08			104	6847
E84	USA	Q21	V05	B3	S08	@		145	6352
2	USA	Q21	V06	B3	S08			21	466
1	USA	Q21	V74	B3	S08			41	1182
E84	USA	Q21	V05	B3	S08			114	3760
E84	USA	Q21	V05	B3	S08			273	23706
1	USA	Q21	V05	B3	S08			147	4543
2	USA	Q21	V05	B3	S08			86	2538

ROSA-811 12678

01_Exped_NavFrontBuckle_Query

E84	USA	Q21	V05	B3	S08				136	10848
E84	USA	Q21	V05	B3	S08				197	8431
1	USA	Q21	V05	B3	S08	@			208	8067
2	USA	Q21	V05	B3	S08				60	801
1	USA	Q21	V05	B3	S08				21	802
E84	USA	Q21	V05	B3	S08				73	4181
1	USA	Q21	V05	B3	S08				41	875
E84	USA	Q21	V05	B3	S08				82	5825
E84	USA	Q21	V05	B3	S08				289	17390
E84	USA	Q21	V05	B3	S08	@			258	8088
E84	USA	Q21	V05	B3	S08				30	3812
E84	USA	Q21	V05	B3	S08	@			247	14935
E84	USA	Q21	V05	B3	S08				20	436
2	USA	Q21	V05	B3	S08				282	9302
E93	USA	Q21	V05	B3	S08				0	0
E84	USA	Q21	V05	B3	S08				2	132
1	USA	Q21	V05	B3	S08				21	1034
E84	USA	Q21	V05	B3	S08				141	7879
2	USA	Q21	V05	B3	S08				108	2585
E84	USA	Q21	V05	B3	S08				8	10245
E84	USA	Q21	V06	B3	S08	@			250	11789
1	USA	Q21	V05	B3	S08				220	5983
1	USA	Q21	V03	B3	S08				56	-28298

R004-011 15676

01_Exped_NavFrontBuckle_Query

1	USA	Q21	V05	B3	S08				70	2185
E84	USA	Q21	V05	B3	S08	@			293	12490
2	USA	Q21	V05	B3	S08				42	1401
2	USA	Q21	V05	B3	S08				184	2953
E81	USA	Q21	V05	B3	S08	@			307	25364
1	USA	Q21	V05	B3	S08				88	5734
1	USA	Q21	V77	B3	S09				11	531
E84	USA	Q21	V05	B3	S08				188	16788
1	USA	Q21	V05	B3	S08				18	1878
1	USA	Q21	V74	B3	S08				197	7125
1	USA	Q21	V05	B3	S08				18	459
2	USA	Q21	V05	B3	S08				182	11118
1	USA	Q21	V74	B3	S08				9	603
E84	USA	Q21	V05	B3	S08	@			266	8952
1	USA	Q21	V05	B3	S08				213	7046
E84	USA	Q21	V05	B3	S08				22	1189
E84	USA	Q21	V05	B3	S08				75	2623
E84	USA	Q21	V05	B3	S08	@			209	3424
1	USA	Q21	V05	B3	S08				0	0
1	USA	Q21	V05	B3	S08				42	916

01_Exped_NavFrontBuckle_Query

1	USA	Q21	V05	B3	S08				43	471
1	USA	Q21	V05	B3	S08				272	8381
2	USA	Q21	V05	B3	S08				0	0
1	USA	Q21	V05	B3	S08				28	710
1	USA	Q21	V05	B3	S08				43	1904
1	USA	Q21	V05	B3	S08				0	0
1	USA	Q21	V05	B3	S08				5	216
1	USA	Q21	V05	B3	S08				4	90
E84	USA	Q21	V05	B3	S08	②			283	18319
1	USA	Q21	V05	B3	S08				7	0
E84	USA	Q21	V05	B3	S08				98	4589
1	USA	Q21	V05	B3	S08				29	1261
E84	USA	Q21	V05	B3	S08				117	4753
E84	USA	Q21	V05	B3	S08				157	6392
E84	USA	Q21	V74	B3	S08				10	852
1	USA	Q21	V05	B3	S08				8	496
1	USA	Q21	V05	B3	S08				136	128
1	USA	Q21	V05	B3	S08				153	4106
2	USA	Q21	V74	B3	S08				113	4850
2	USA	Q21	V05	B3	S08	②			285	9160
2	USA	Q21	V05	B3	S08	②			288	11306
1	USA	Q21	V05	B3	S08				143	2

R004-911 15678

01_Expd_NavFrontBuckle_Query

2	USA	Q21	V05	B3	S08				29	1232
2	USA	Q21	V05	B3	S08				141	1434
EB4	USA	Q21	V05	B3	S08				103	8167
EB4	USA	Q21	V05	B3	S08				184	7846
1	USA	Q21	V05	B3	S08				58	2451
EB4	USA	Q21	V06	B3	S08				62	2519
2	USA	Q21	V05	B3	S08				21	520
2	USA	Q21	V05	B3	S08				127	441
1	USA	Q21	V05	B3	S08				22	1
2	USA	Q21	V05	B3	S08				15	480
1	USA	Q21	V05	B3	S08				142	5612
EB4	USA	Q21	V05	B3	S08				129	5265

R004-011 15679

FD-302 (Rev. 1-25-60)

Windsor Recall Performed_ID	Windsor Recall Performed_MDL_YR	Windsor Recall Performed_YR_CD	Windsor Recall Performed_VEH_LINE_C D	Windsor Recall Performed_MKT_DESRVE D	Windsor Recall Performed_SCO_CAS_B T	Windsor Recall Performed_VEH_BSRVB CD	Windsor Recall Performed_DRIVE_CD
118	2001	2FMZA014H1	[REDACTED]	T7A0	*	T7A0	T7A
218	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A
204	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A
221	2001	2FMZA01411	[REDACTED]	T7A0	*	T7A0	T7A
187	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A
211	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A
46	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A
182	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A
186	2001	2FMZA0170K1	[REDACTED]	T7A0	*	T7A0	T7A
51	2001	2FMZA02411	[REDACTED]	T7A0	*	T7A0	T7A
178	2001	2FMZA024H1	[REDACTED]	T7A0	*	T7A0	T7A

RCR-011 15983

137	2001	2FMZA51401B	[REDACTED]	TAS	*	TWS	*	T/A
138	2001	2FMZA517451B	[REDACTED]	TAS	*	TWS	*	T/A
139	2001	2FMZA519461B	[REDACTED]	TAS	*	TWS	*	T/A
140	2001	2FMZA511491B	[REDACTED]	TAS	*	TWS	*	T/A
141	2001	2FMZA5141X1B	[REDACTED]	TAS	*	TWS	*	T/A
150	2001	2FMZA51411B	[REDACTED]	TAS	*	TWS	*	T/A
141	2001	2FMZA51471B	[REDACTED]	TAS	*	TWS	*	T/A
154	2001	2FMZA51411B	[REDACTED]	TAS	*	TWS	*	T/A
141	2001	2FMCA52421B	[REDACTED]	TAS	*	TWS	*	T/A
149	2001	2FMCA52431B	[REDACTED]	TAS	*	TWS	*	T/A
141	2001	2FMZA5141X1B	[REDACTED]	TAS	*	TWS	*	T/A

FORM 911 1000Z

128	2001	2FMZAS1471	[REDACTED]	TAS	*	TWB	*	TJA
28	2001	2FMZAS7421	[REDACTED]	TAS	*	TWB	*	TJA
188	2001	2FMZAS1411	[REDACTED]	TAS	*	TWB	*	TJA
214	2001	2FMZAS2411	[REDACTED]	TAS	*	TWB	*	TJA
228	2001	2FMZAS3451	[REDACTED]	TAS	*	TWB	*	TJA
5	2001	2FMZAS74X1	[REDACTED]	TAS	*	TWB	*	TJA
147	2001	2FMZAS142	[REDACTED]	TAS	*	TWB	*	TJA
48	2001	2FMZAS243	[REDACTED]	TAS	*	TWB	*	TJA
179	2001	2FMZAS6491	[REDACTED]	TAS	*	TWB	*	TJA
80	2001	2FMZAS3471	[REDACTED]	TAS	*	TWB	*	TJA
100	2001	2FMZAS1481	[REDACTED]	TAS	*	TWB	*	TJA

FD-302 (Rev. 11-29-83)

185	2001	2FMZAS641B	[REDACTED]	TAS	*	TAB	*	TJA
200	2001	2FMZAS641B	[REDACTED]	TAS	*	TAB	*	TJA
2	2001	2FMZAS741B	[REDACTED]	TAS	*	TAB	*	TJA
150	2001	2FMZAS1421B	[REDACTED]	TAS	*	TAB	*	TJA
14	2001	2FMZAS741B	[REDACTED]	TAS	*	TAB	*	TJA
30	2001	2FMZAS241B	[REDACTED]	TAS	*	TAB	*	TJA
120	2001	2FMZAS241B	[REDACTED]	TAS	*	TAB	*	TJA
50	2001	2FMZAS1421B	[REDACTED]	TAS	*	TAB	*	TJA
54	2001	2FMZAS1421B	[REDACTED]	TAS	*	TAB	*	TJA
103	2001	2FMZAS241B	[REDACTED]	TAS	*	TAB	*	TJA
82	2001	2FMZAS1421B	[REDACTED]	TAS	*	TAB	*	TJA
104	2001	2FMZAS241B	[REDACTED]	TAS	*	TAB	*	TJA
7	2001	2FMZAS741B	[REDACTED]	TAS	*	TAB	*	TJA
110	2001	2FMZAS241B	[REDACTED]	TAS	*	TAB	*	TJA

RODA-011 15894

85	2001	2FMZAS1421B	[REDACTED]	TAS	*	TWS	*	T/A
86	2001	2FMZAS1401B	[REDACTED]	TAS	*	TWS	*	T/A
87	2001	2FMZAU7411B	[REDACTED]	TAS	*	TWS	*	T/A
88	2001	2FMZAS1441B	[REDACTED]	TAS	*	TWS	*	T/A
89	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
90	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
91	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
92	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
93	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
94	2001	2FMZAS1401B	[REDACTED]	TAS	*	TWS	*	T/A
95	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
96	2001	2FMZAS1441B	[REDACTED]	TAS	*	TWS	*	T/A
97	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	T/A
98	2001	2FMZAS1441B	[REDACTED]	TAS	*	TWS	*	T/A
99	2001	2FMZAS1471B	[REDACTED]	TAS	*	TWS	*	T/A

ROD-011 15883

76	2001	2FMZAS1441B	[REDACTED]	TAS	-	TWB	*	TJA
86	2001	2FMZAS1401B	[REDACTED]	TAS	-	TWB	*	TJA
6	2001	2FMZAS7441B	[REDACTED]	TAS	*	TWB	*	TJA
116	2001	2FMZAS2441B	[REDACTED]	TAS	*	TWB	*	TJA
58	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWB	*	TJA
41	2001	2FMZAS2431B	[REDACTED]	TAS	*	TWB	*	TJA
48	2001	2FMZAS14X1B	[REDACTED]	TAS	*	TWB	*	TJA
44	2001	2FMZAS3401B	[REDACTED]	TAS	*	TWB	*	TJA
57	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWB	*	TJA
901	2001	2FMZAS0421B	[REDACTED]	TAS	*	TWB	*	TJA
70	2001	2FMZAS7411B	[REDACTED]	TAS	*	TWB	*	TJA

RC9-011 15008

238	2001	2FMZAS481B	[REDACTED]	TAS	-	TWS	-	TA
112	2001	2FMZAS1451B	[REDACTED]	TAS	-	TWS	-	TA
78	2001	2FMZAS2401B	[REDACTED]	TAS	-	TWS	-	TA
77	2001	2FMZAS411B	[REDACTED]	TAS	-	TWS	-	TA
138	2001	2FMZAS1451B	[REDACTED]	TAS	-	TWS	-	TA
141	2001	2FMZAS1411B	[REDACTED]	TAS	-	TWS	-	TA
100	2001	2FMZAS1401B	[REDACTED]	TAS	-	TWS	-	TA
75	2001	2FMZAS411B	[REDACTED]	TAS	-	TWS	-	TA
107	2001	2FMZAS1471B	[REDACTED]	TAS	-	TWS	-	TA
137	2001	2FMZAS1431B	[REDACTED]	TAS	-	TWS	-	TA
63	2001	2FMZAS1481B	[REDACTED]	TAS	-	TWS	-	TA
24	2001	2FMZAS3451B	[REDACTED]	TAS	-	TWS	-	TA

RO04-011 12807

172	2001	2FMZAB0471B	[REDACTED]	TAS	*	TWB	*	T/A
62	2001	2FMZAB0491B	[REDACTED]	TAS	*	TWB	*	T/A
173	2001	2FMZAB0491B	[REDACTED]	TAS	*	TWB	*	T/A
142	2001	2FMZAB1481B	[REDACTED]	TAS	*	TWB	*	T/A
18	2001	2FMZAB7441B	[REDACTED]	TAS	*	TWB	*	T/A
18	2001	2FMZAB7471B	[REDACTED]	TAS	*	TWB	*	T/A
185	2001	2FMZAB1411B	[REDACTED]	TAS	*	TWB	*	T/A
43	2001	2FMZAB3451B	[REDACTED]	TAS	*	TWB	*	T/A

RC94-011 15858

189	2001	2FMZA81401E	[REDACTED]	TAS	*	TWB	*	TJA
186	2001	2FMZA88461E	[REDACTED]	TAS	*	TWB	*	TJA
88	2001	2FMZA814X1E	[REDACTED]	TAS	*	TWB	*	TJA
54	2001	2FMZA88461E	[REDACTED]	TAS	*	TWB	*	TJA
34	2001	2FMZA88431E	[REDACTED]	TAS	*	TWB	*	TJA
185	2001	2FMZA88411E	[REDACTED]	TAS	*	TWB	*	TJA
181	2001	2FMZA88421E	[REDACTED]	TAS	*	TWB	*	TJA
127	2001	2FMZA81481E	[REDACTED]	TAS	*	TWB	*	TJA
84	2001	2FMZA814X1E	[REDACTED]	TAS	*	TWB	*	TJA

FD-302 (Rev. 11-29-99)

18	2001	2FMZAS3491E	[REDACTED]	TJAS	*	TWBS	*	TJA
18	2001	2FMZAS3481E	[REDACTED]	TJAS	*	TWBS	*	TJA
42	2001	2FMZAS3421E	[REDACTED]	TJAS	*	TWBS	*	TJA
80	2001	2FMZAS1471E	[REDACTED]	TJAS	*	TWBS	*	TJA
29	2001	2FMZAS3401E	[REDACTED]	TJAS	*	TWBS	*	TJA
98	2001	2FMZAS3401E	[REDACTED]	TJAS	*	TWBS	*	TJA
75	2001	2FMZAS1431E	[REDACTED]	TJAS	*	TWBS	*	TJA
111	2001	2FMZAS3401E	[REDACTED]	TJAS	*	TWBS	*	TJA
78	2001	2FMZAS1441E	[REDACTED]	TJAS	*	TWBS	*	TJA
81	2001	2FMZAS1481E	[REDACTED]	TJAS	*	TWBS	*	TJA
72	2001	2FMZAS1441E	[REDACTED]	TJAS	*	TWBS	*	TJA
107	2001	2FMZAS3471E	[REDACTED]	TJAS	*	TWBS	*	TJA

ROD-811 15889

5	2001	2FMZAS74010	[REDACTED]	TAS	*	TAVB	*	TIA
27	2001	2FMZAS74110	[REDACTED]	TAS	*	TAVB	*	TIA
29	2001	2FMZAS74110	[REDACTED]	TAS	*	TAVB	*	TIA
28	2001	2FMZAS74110	[REDACTED]	TAS	*	TAVB	*	TIA
68	2001	2FMZAS24210	[REDACTED]	TAS	*	TAVB	*	TIA
176	2001	2FMZAS94010	[REDACTED]	TAS	*	TAVB	*	TIA
186	2001	2FMZAS94010	[REDACTED]	TAS	*	TAVB	*	TIA
78	2001	2FMZAS114310	[REDACTED]	TAS	*	TAVB	*	TIA
184	2001	2FMZAS94010	[REDACTED]	TAS	*	TAVB	*	TIA
78	2001	2FMZAS94010	[REDACTED]	TAS	*	TAVB	*	TIA

1004-613 10001

08	2001	2FMZAS14X1B	[REDACTED]	TAS	*	TWS	*	TIA
11B	2001	2FMZAS1481B	[REDACTED]	TAS	*	TWS	*	TIA
4	2001	2FMZAS1471B	[REDACTED]	TAS	*	TWS	*	TIA
28	2001	2FMZAS1491B	[REDACTED]	TAS	*	TWS	*	TIA
27	2001	2FMZAS1441B	[REDACTED]	TAS	*	TWS	*	TIA
30	2001	2FMZAS1401B	[REDACTED]	TAS	*	TWS	*	TIA
5	2001	2FMZAS1471B	[REDACTED]	TAS	*	TWS	*	TIA
08	2001	2FMZAS1441B	[REDACTED]	TAS	*	TWS	*	TIA

NOV-01 1997

85	2001	2FMZA61461B	[REDACTED]	TIA3	*	TAVB	*	TIA
12	2001	2FMZA67401B	[REDACTED]	TIA3	*	TAVB	*	TIA
88	2001	2FMZA61461B	[REDACTED]	TIA3	*	TAVB	*	TIA
48	2001	2FMZA63471B	[REDACTED]	TIA3	*	TAVB	*	TIA
201	2001	2FMZA66621B	[REDACTED]	TIA3	*	TAVB	*	TIA
6	2001	2FMZA67481B	[REDACTED]	TIA3	*	TAVB	*	TIA
86	2001	2FMZA60481B	[REDACTED]	TIA3	*	TAVB	*	TIA
43	2001	2FMZA614K1B	[REDACTED]	TIA3	*	TAVB	*	TIA
141	2001	2FMZA61431B	[REDACTED]	TIA3	*	TAVB	*	TIA
77	2001	2FMZAN1481B	[REDACTED]	TIA3	*	TAVB	*	TIA

NOB-811 15093

Windsor Recall Performed_ENG_CD	Windsor Recall Performed_TRANS_CD	Windsor Recall Performed_PLANT_CD	Windsor Recall Performed_PROD_DT	Windsor Recall Performed_WRTY_START_DT	Windsor Recall Performed_NAME	Windsor Recall Performed_DCC_NUM	Windsor Recall Performed_PH_NUM	Windsor Recall Performed_WCC_CD
TLM	TDX	AS	10/29/2000	11/14/2000	KISTLER FORD, INC.	15408001	5319811	*
TLM	TDX	AS	1/16/2001	4/16/2001	KRUG RIVERTOWN MOTORS	3639402	6279008	*
TLM	TDX	AS	10/2/2000	8/7/2001	AL PALLADINE FINE TREE FORD	32841401	7684777	*
TLM	TDX	AS	4/26/2001	7/20/2001	ED BLASK FORD INC	10015006	7363381	*
TLM	TDX	AS	8/26/2000	4/20/2001	LASALLE FORD INC.	7600501	3833873	*
TLM	TDX	AS	3/6/2001	4/30/2001	MATTHEWS BALNE CO	18227706	8444706	*
TLM	TDX	AS	4/8/2001	11/28/2001	PASTILLI FORD	8141108	8824808	*
TLM	TDX	AS	3/21/2001	7/19/2001	OTIS FORD, INC.	9830407	8834000	*
TLM	TDX	AS	1/19/2001	8/27/2001	BATTLEFIELD FORD	2102906A	3663184	*
TLM	TDX	AS	3/6/2001	8/11/2001	RIVERSIDE FORD SALES, INC.	8108004	8870280	*
TLM	TDX	AS	3/8/2001	5/27/2001	PEYTON CRAMER FORD	6518802	7844700	*

ROB-011 19994

TLM	TDX	AS	9/19/2001	9/21/2001	SHERWOOD FORD, INC.	112822A	8382901	*
TLM	TDX	AS	12/16/2000	8/8/2001	COASTAL FORD SALES LTD	088438A	8732354	*
TLM	TDX	AS	12/9/2000	1/8/2001	WESTWARD FORD SALES LTD	2784603	8579812	*
TLM	TDX	AS	9/19/2000	9/8/2001	JAY WOLFE FORD	217178C	7328100	*
TLM	TDX	AS	9/27/2001	4/12/2001	CHARLES WATERVILLE FORD LINC	338808	73758	*
TLM	TDX	AS	3/21/2001	2/9/2001	BUDGET PAC - RALEIGH/DURHAM	048881		*
TLM	TDX	AS	1/18/2001	8/18/2001	BOB ANDERSON FORD-MERCURY, INC	8188002	8422728	*
TLM	TDX	AS	11/29/2000	12/27/2000	FRIENDLY FORD, INC.	2088888	8894390	*
TLM	TDX	AS	1/4/2001	4/27/2001	WINDLE FORD SALES	183822A	4844800	*
TLM	TDX	AS	9/29/2001	7/14/2001	ACTION FORD-MERCURY INC	1101202	8835121	*
TLM	TDX	AS	9/26/2001	4/9/2001	TOWER FORD INC	142187A	4885400	*

FD-4-011 1995

T/LM	T/DX	AS	8/11/2000	1/16/2001	SAM DELL FORD	18992802	6220069	*
T/LM	T/DX	AS	8/28/2000	8/24/2001	FREEDOM FORD SALES LIMITED	22886602	4958411	*
T/LM	T/DX	AS	1/9/2001	4/27/2001	EGGLEFIELD BRACE INC	818405	5738851	*
T/LM	T/DX	AS	3/28/2001	3/8/2001	BLIND FORD, INC.	7434801	6428251	*
T/LM	T/DX	AS	4/22/2001	5/28/2001	SARASOTA FORD	9640640	5553879	*
T/LM	T/DX	AS	1/18/2001	8/18/2001	WORLD FORD/PEMBROKE PINES	8738651	4437003	*
T/LM	T/DX	AS	4/4/2001	4/17/2001	SHAWF FORD	6422032	7876201	*
T/LM	T/DX	AS	2/15/2001	10/5/2001	PALMETTO FORD, INC.	872501	8713875	*
T/LM	T/DX	AS	2/13/2001	8/27/2001	WAGNER FORD SALES, INC.	080128A	4380471	*
T/LM	T/DX	AS	10/19/2000	12/18/2000	ADAMS FORD BELTON, INC.	308844D	5229800	*
T/LM	T/DX	AS	1/18/2001	3/3/2001	HERTZ RAC - PALM SPRINGS	28672401		*

ROSA-811 10505

T/LM	T/DX	AS	8/18/2001	8/8/2001	TOMBALL FORD, INC.	228888F	3818427	*
T/LM	T/DX	AS	8/9/2001	10/31/2001	GRIMM FORD SALES LTD.	2887101	4888888	*
T/LM	T/DX	AS	1/28/2001	8/31/2001	BAW2RASS FORD	33288801	8818000	*
T/LM	T/DX	AS	8/18/2001	4/4/2001	ADVANTAGE FORD	0128828	2482010	*
T/LM	T/DX	AS	8/17/2000	3/31/2001	BERGSTROM MEEBAH-MENARNA FORD	8888783	7278000	*
T/LM	T/DX	AS	8/15/2000	8/8/2001	OLD FORDS LINCOLN MERCURY, INC	11084203	3884300	*
T/LM	T/DX	AS	1/15/2001	7/8/2001	JACK NETZER FORD-LINCOLN-MERCURY	8774402	2782212	*
T/LM	T/DX	AS	4/24/2001	5/24/2001	TOMBALL FORD, INC.	228428D	3818427	*
T/LM	T/DX	AS	12/7/2000	7/2/2001	JOHN STUCKREY FORD, INC.	8807888	8828882	*
T/LM	T/DX	AS	5/1/2001	8/14/2001	STADIUM FORD, L.L.C.	8837782	8882400	*
T/LM	T/DX	AS	12/18/2000	1/10/2001	SUNSET AUTO CO INC	2814888	8434431	*
T/LM	T/DX	AS	11/1/2000	2/9/2001	TIPTON MOTORS, INC.	8788801	8808880	*
T/LM	T/DX	AS	8/13/2000	10/13/2001	JACK ADKINS FORD, INC.	3478481	8348880	*
T/LM	T/DX	AS	4/8/2001	4/30/2001	WONDERFUL FORD	4273801	5482783	*

RO04-811 10887

T/LM	T/DK	AS	8/14/2000	8/16/2000	MALOUF FORD, INC.	1845080	8810300	*
T/LM	T/DK	AS	2/16/2001	3/4/2001	COURTESY MOTORS, INC.	058275A	5448111	*
T/LM	T/DK	AS	4/30/2001	8/28/2001	WEST COAST FORD LINCOLN	9760301	4865434	*
T/LM	T/DK	AS	8/26/2001	7/5/2001	SUTTON FORD, INC.	17278304	7288000	*
T/LM	T/DK	AS	1/21/2001	8/23/2001	ACTION FORD, INC.	105431B	5977000	*
T/LM	T/DK	AS	10/13/2000	11/23/2000	BARNHART FORD SALES COMPANY	420596C	6986000	*
T/LM	T/DK	AS	4/6/2001	1/12/2002	MAGNOLIA FORD-MERCURY	1388201	8466330	*
T/LM	T/DK	AS	10/11/2000	12/28/2000	J & B FORD INC	170424D	4387272	*
T/LM	T/DK	AS	3/15/2001	8/3/2001	TOMBALL FORD, INC.	232817B	5815427	*
T/LM	T/DK	AS	4/18/2001	5/19/2001	BRAD HOWELL INC	2749801	5203321	*
T/LM	T/DK	AS	5/11/2001	5/30/2001	WELLS FORD SALES LTD.	1001110E	5853875	*

FORM-011 15593

TLM	TDX	AS	10/7/2000	8/8/2001	WIDE FORD OF RUFORD	060854A	9324050	-
TLM	TDX	AS	1/2/2001	1/15/2001	FIVE STAR FORD	10712803	9483600	-
TLM	TDX	AS	4/7/2001	8/24/2001	GENE MESSER FORD	19270001	7992727	-
TLM	TDX	AS	10/4/2000	1/8/2001	DON HENDS FORD INC	139459D	9499000	-
TLM	TDX	AS	11/15/2000	12/1/2000	UNIVERSITY FORD, INC.	8276640	8828171	-
TLM	TDX	AS	8/18/2000	3/8/2001	FAIRWAY FORD	7369041	8241200	-
TLM	TDX	AS	9/27/2000	8/27/2001	SELLERS-BEXTON, INC.	2573754	3362000	-
TLM	TDX	AS	8/21/2000	4/20/2001	KINDLE FORD MERCURY-LINCOLN	18944604	4888000	-
TLM	TDX	AS	11/15/2000	12/1/2000	UNIVERSITY FORD, INC.	8389751		-
TLM	TDX	AS	11/22/2000	1/8/2001	LEWIS FORD	843218E		-
TLM	TDX	AS	4/30/2001	6/28/2001	WEST COAST FORD LINCOLN	7108202	4885884	-

K004-011 15099

TLM	TDX	AS	11/1/2000	7/22/2001	MASC CITY MOTOR CORP	6139801	3450011	*
TLM	TDX	AS	3/1/2001	3/17/2001	VALLEY VIEW FORD, INC.	6073101	7666673	*
TLM	TDX	AS	1/15/2001	6/7/2001	VARIETY FORD	13361101	0062300	*
TLM	TDX	AS	8/14/2000	7/27/2001	OWEN FORD, INC.	72961	8966518	*
TLM	TDX	AS	2/2/2001	2/15/2001	ANDREWS FORD INC	4872201	8261006	*
TLM	TDX	AS	12/19/2000	1/3/2001	BRAEGER FORD, INC.	0886405	2816100	*
TLM	TDX	AS	5/22/2001	6/15/2001	WEST-HEFF FORD, INC.	084725A	6460640	*
TLM	TDX	AS	2/2/2001	10/4/2001	OLIVER FORD SALES, INC.	0872775	8251001	*
TLM	TDX	AS	1/16/2001	10/6/2001	DALE JARRETT FORD	13361101	2836821	*
TLM	TDX	AS	5/16/2001	6/1/2001	BUGBET FORD - ROMULUS	28514801	*	*
TLM	TDX	AS	12/16/2000	1/12/2001	PHILPOTT FORD	181352B	7271451	*
TLM	TDX	AS	1/8/2001	6/6/2001	MARTIN - FEAGIN FORD LINCOLN	179210A	6644500	*

ROD-911 15789

TLM	TDX	AS	1/7/2001	3/30/2001	WHEELER MOTOR MILE	16247401	3822881	*
TLM	TDX	AS	1/8/2001	3/21/2001	LOMAN FORD, INC.	6810851	8363280	*
TLM	TDX	AS	1/7/2001	4/28/2001	PADUCAH FORD LINCOLN MERCURY,	8048001	4440011	*
TLM	TDX	AS	2/2/2001	3/26/2001	RICART FORD LINCOLN MERCURY-CH	3029982	7028000	*
TLM	TDX	AS	12/14/2000	1/30/2001	WOOD MOTORS FORD	0038100	4321130	*
TLM	TDX	AS	12/20/2000	10/1/2001	DREW FORD	5408251	4847777	*
TLM	TDX	AS	3/29/2000	1/13/2001	PATCHETT'S FORD- MERCURY	079230A	6082200	*
TLM	TDX	AS	1/18/2001	9/28/2001	JOE MYERS FORD, INC.	3853980	8998200	*

NOV-01 1 15781