vassels in that business, a waiver will not be granted. Comments should refer to the docket number of this notice and the vessel name in order for MARAD to properly consider the comments. Comments should also state the commenter's interest in the waiver application, and eddress the waiver criteria given in § 388.4 of MARAD's regulations at 46 CFR part 388.

DATES: Submit comments on or before January 30, 2006.

ADDRESSES: Comments should refer to docket number MARAD-2005-23445 Written comments may be submitted by hand or by mail to the Docket Clerk, U.S. DOT Dockets, Room PL-401. Department of Transportation, 400 7th St., SW., Washington, DC 20590-0001. You may also send comments electronically via the Internet at http:// dmses.dot.gov/submit/. All comments will become part of this docket and will be available for inspection and copying at the above address between 10 a.m. and 5 p.m., e.t., Monday through Friday, except Federal holidays. An electronic version of this document and all documents entered into this docket is available on the World Wide Web at http://duis.dot.gov.

FOR FURTHER REPORMATION CONTACT: Josun Spittle, U.S. Department of Transportation, Maritime Administration, MAR-830 Room 7201, 400 Seventh Street, SW., Washington, DC 20590. Telephone 202-366-5979.

SUPPLEMENTARY INFORMATION: As described by the applicant the intended service of the vessel ULTRA VIOLET is:

Intended Use: "They shorter

Intended Use: "Day charter, sightseeing voyages."

Geographic Region: Narraganesti Bay, KL

Dated: December 23, 2005.

By order of the Maritims Administrator.

Joel C. Richard,

Searctary, Maritime Administration. [FR Doc. E5-8061 Filed 12-28-05; 8;45 am] SELEM CODE 4019-81-9

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

Deniel of Motor Vehicle Defect Petition

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation. ACTION: Denial of petition for a defect investigation.

SUMMARY: This notice sets forth the reasons for the denial of a petition submitted by Mr. Chris Ruh, Mr. Don

Huston, Mr. Robert Guthrie, Mr. Jeff Babiak, Mr. J. A. Massey, Ms. Michele Brown, Ms. Mary Mabry, Mr. Chris Taylor, and Mr. Victor Aguiler (hereinafter, "Petitioners") to NHTSA's Office of Defects Investigation (ODI), received September 6, 2005, under 49 U.S.C. 30162, requesting that the agency communes a proceeding to determine the existence of a defect related to motor vehicle safety with respect to the cylinder head and spark plug assembly performance of model year (MY) 1997 through 2004 Ford vehicles with Triton V-8 and V-10 engines. After a review of the petition and other information, NHTSA has concluded that further expenditure of the agency's investigative resources on the issues raised by the petition does not appear to be warranted. The agency accordingly has denied the petition. The petition is hereinafter identified as DP05-005. FOR FURTHER INFORMATION CONTACT: Ms.

FOR FURTMER REFORMATION CONTACT: Ms. Cheryl Rose, Vehicle Control Division, Office of Defects Investigation, NHTSA, 400 Seventh Street, SW., Washington, DC 20590. Telephone: (202) 368—1869. SUPPLEMENTARY ENFORMATION:

On September 8, 2005, ODI received a patition submitted by Mr. Donald W. Ricketts of Santa Clarita, CA, on the behalf of the "Petitioners" requesting that the agency investigate allegations of angine sperk plug ejection in certain MY 1997 through 2004 Ford vehicles with Triton V-8 and V-10 engines (hereinafter, subject vehicles). The "Petitioners" allege the following regarding the subject vehicles:

(1) The spark plug-cylinder head assembly design is insufficient to retain the spark plugs in the cylinder heads for the life of the spark plug unless periodically inspected and, if necessary, traused.

(2) As the vehicle ages, the spark plugs loosen in the threaded head and/ or the metal fetigues causing the spark plugs to be blown out of the head.

(3) The millions of subject vehicles containing the Triton V-8 and V-10 engine present a safety hazard to occupants of the vehicle, nearby persons, and other motorists on the road.

(4) The spark plugs shoot out of the cylinder port suddenly and with great force damaging the engine and sometimes puncturing the bood.

(a) Fire and explosion are likely if the plugs puncture nearby fuel lines.

(b) Owners report a strong smell of geschine vapor after blowouts occur and the cylinder is open, presenting an additional danger of fire and explosion.

(c) The sudden expulsion of the plug out of the head often causes drivers to be startled and lose control of the vehicle momentarily.

(d) The vehicles always lose power, and often stell.

In response to NHTSA's request for whatever supporting information the "Petitioners" could provide, one petitioner and Mr. Donald Ricketts on behalf of the "Petitioners," submitted several complaints and repair involces concerning the subject of their allegations. NHTSA has carefully analyzed those submissions, as well as relevant complaints in its own database, interviewed many of the complainants, including some of the "Petitioners," and examined a vehicle containing the alleged defect.

ODI received a total of 474 nonduplicative complaints on the subject vehicles, including the several complaints submitted by Mr. Donald Ricketts on behalf of the "Petitioners" and some complaints received directly from the "Petitioners" where the complainant, or the dealer repairing the vehicle, reported that a spark plug detached from the cylinder and/or ejected from the engine (hereinafter, alleged defect). As of December 8, 2005, ODI is not aware of any allegations where the alleged defect resulted in a loss of vehicle control, a crash, an injury, or a fatality in any of the 10,319,810 subject vehicles. In addition, ODI is aware of only two incidents where the vehicle stalled without

Information contained in the ODI consumer complaints and obtained from 72 telephone interviews with complainants showed the following:

 99% of the complaints were on MY 1997 to 2002 subject vehicles.

(2) Most the complainants reported hearing a loud pop while driving or upon starting up the vehicle followed by a loud, repetitive clicking or popping sound,

(3) Many of the complements reported that the popping sound was accompanied by some loss of vehicle power; however, in 99% of the incidents reported, the vehicle did not stall. In the very few incidents where the vehicle did stall, most vehicles could be restarted.

(4) Only a small percentage of the completeants cited that they smalled gas or a slight huming small when the

incident occurred.

restart.

(5) In all but a very few incidents, vehicle damage was limited to the engine. In one incident, the compleint reported that the fuel rail was damaged and replaced after one of the spark plugs ejected from the engine; however, the complainant reported that the damage did not result in any type of fuel leak

or fire. In another incident, the only incident where a fire was alleged, the complainent reported that no fluid leak was observed, but that a fire resulted after the spark plug had ejected from the angine and he had restarted the vehicle and driven to another location. None of the complainants reported any damage to the vehicle hood.

(6) Only two complainants reported that they observed what appeared to be some drops of fuel coming from the cylinder where the sperk plug had failed or on the spark plug itself; however, each of these complainants reported that there was no smoke or flames as a result of his incident.

In addition to its complaint analysis, ODI also examined a subject vehicle containing the alleged defect and observed the following:

- One of the sperk plugs was detached from the cylinder threads.
- (2) The bracket securing the ignition coil and sperk plug assembly was broken and when the engine was running, the ignition coil, which was still attached to the engine via its wire harnas, would move up and down within the cylinder.
- (3) When the engine was running a loud popping or clicking noise was
- (4) No fluid leaks or fuel rail, smoke or flame damage was observed.

As the patitionar noted and ODI's analysis showed, it is possible for a spark plug to detech from the engine cylinder threads in the subject vehicles. However, ODI's analysis of 474 complaints describing such incidents found only a very few alleged any safety-related consequences. None of these showed any evidence of a serious safety consequence. Given the large population and relatively long exposure time of the subject vehicles, the complaint analysis indicates that the risk to motor vehicle safety from the alleged defect is very low.

In view of the foregoing, it is unlikely that the NHTSA would issue an order for the notification and remedy of the alleged defect as defined by Mr. Donald Ricketts, on behalf of the "Petitioners," at the conclusion of the investigation requested in the petition. Therefore, in view of the need to allocate and prioritize the NHTSA's limited resources to best accomplish the agency's safety mission, the petition is

Anthority: 49 U.S.C. 30182(d); delegations of authority at CFR 1.50 and 601.8.

Issued on: December 22, 2005. Daniel Smith,

Associate Administrator for Enforcement. [FR Doc. E5-8072 Filed 12-28-05: 8:45 am] BLUNG CODE 4910-88-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

(Docket No. NHTSA-2005-23381)

Notice of Receipt of Petition for Decision That Nonconforming 2006 Smart Car Passion, Pulse, and Pure (Coupe and Cabriolei) Passanger Cara Manufactured Prior to September 1, 2006 Are Eligible for Importation

AGENCY: National Highway Traffic Safety Administration, DOT. ACTION: Notice of receipt of petition for decision that nonconforming 2008 Smart Car Passion, Pulse, and Pure

(Coupe and Cabriclet) passenger cars manufactured prior to September 1, 2006, are eligible for importation.

SUMMARY: This document ennounces receipt by the National Highway Traffic Safety Administration (NHTSA) of a petition for a decision that 2006 Smart Car Passion, Pulse, and Pure (Coupe and Cabriolet) passenger cars, manufactured prior to September 1, 2006, that were not originally manufactured to comply with all applicable Federal motor vehicle safety standards (FMVS5) are eligible for importation into the United States because they have safety features that comply with, or are capable of being altered to comply with, all such standards.

DATES: The closing date for comments on the petition is January 30, 2005. ACCRESSES: Comments should refer to the docket number and notice number, and be submitted to: Docket Management, Room PL-401, 400 Seventh St., SW., Washington, DC 20590. [Docket hours are from B a.m. to 5 p.m.]. Anyone is able to search the electronic form of all comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the Federal Register published on April 11, 2000 (Volume 65, Number 70; Pages 19477→78) or you may visit http://dms.dot.gov. FOR FURTHER INFORMATION CONTACT:

Coleman Sachs, Office of Vehicle Safety Compliance, NHTSA (202-866-3151). SUPPLEMENTARY DEFORMATION:

Background

Under 49 U.S.C. 30141(a)(1)(A), a motor vehicle that was not originally manufactured to conform to all applicable FMVSS shall be refused. admission into the United States unless NHTSA has decided that the motor vehicle is substantially similar to a motor vehicle originally manufectured for importation into and sale in the United States, certified under 49 U.S.C. 30115, and of the same model year as the model of the motor vehicle to be compared, and is capable of being readily altered to conform to all applicable FMVSS. When there is no substantially storilar U.S.-certified counterpart, a nonconforming motor vehicle shall be refused admission into the United States unless NHTSA decides under 49 U.S.C. 30141(s)(1)(B), that the motor vehicle has safety features that comply with, or are capable of being altered to comply with, all applicable FMVSS based on destructive test data or such other evidence NHTSA decides to be adequate.

Petitions for eligibility decisions may be submitted by either manufacturers or importers who have registered with NHTSA pursuant to 49 CFR Part 592. As specified in 49 CFR 593.7, NHTSA publishes notice in the Federal Register of each patition that it receives, and affords interested persons an opportunity to comment on the petition. At the close of the comment period, NHTSA decides, on the besis of the petition and any comments that it has received, whether the vehicle is eligible for importation. The egency then publishes this decision in the Federal

G&K Automotive Conversion, Inc. of Santa Ana, California ("G&K") (Registered Importer 90–007) has petitioned NHTSA to decide whether nonconforming 2006 Smart Car Passion, Pulse, and Pure (Coupe and Cabriolet) passenger cars manufactured prior to September 1, 2008, are eligible for importation into the United States. In its petition, G&K noted that NHTSA has granted import eligibility to 2002–2004 and 2005 Smart Car Passion. Pulse, and Pure (Coupe and Cahriolat) passenger cars that G&K claims are identical to the 2008 Smart Car Passion, Pulse, and Pure (Coupe and Cabriolet) passenger care that are the subject of this petition. In its petitions for the 2002-2004 and 2005 vehicles, the petitioner claimed that the vehicles were capable of being altered to comply with all applicable FMVSS (see NHTSA Docket Nos. NHTSA-2003-1401 and NHTSA-2005-21334). Because those vehicles were not