

Memorandum

National Highway Traffic Safety Administration

Subject: EA05-020 Memo to File Date: March 16, 2006

From: John Abbott Reply to Attn of:

To: EA05-020 File

This memo contains 20 images sent to DaimlerChrysler in support of EA05-020



EA05-020 Jeep Grand Cherokee Engine Cooling Fan Failure

The following pages contain images of alleged damage caused by the cooling fan and provided to DaimlerChrysler (DCC) in response to a verbal request from Ms. Shelly Plaza of DCC.

VOQ 1014330 ____0315 Damage to hood liner





VOQ 1014330 0316 Damage to hood liner



VOQ 1014330_ Damage to hoo

_0317



VOQ 10132799 Fan Assembly Fan 009



VOQ 10132799 Fan Assembly



VOQ 10132799_ Crack in fan hub



VOQ 10132799_ Fan 033 Crack in fan hub



VOQ 10132799 Fan 003 Crack in fan hub



VOQ 10132799_ Fan 043 Crack in fan hub



DCC Hood_Insul 014
Dam liner






DCC Hood_Insul_ 016
Dama liner



VOQ 10149058 Damage to fan s



VOQ 10149058______ 4939 Damage to fan s




the orient admissibility of the originessor tailed, and it soft debins into the orient and expansion valve. Owner seeks assistance with the \$1400 repairs that were diagnosed by dealer 68550. Diana, operator, said Ed. service manager, was not answering his page. Agent left a massage with Diana for Ed.

7/26/04 Ed the service manager calls back stating the compressor and expansion valve need replaced. Foffered a 50/50 split for customer goodwill at warranty rates, PA provided.

7/27 Ed says that the customer is unhappy with the offer. Fig and IEB1 concurred with the customer. Agent made a goodwill offer of a \$50 copay due to age and mileage.


Criginal owner with one prior vehicle showing in the system states after vehicle was returned vehicle had a poor idle and then cooling fan came apart damaging the casing and hood insulation. Owner states now current repairs are estimated at \$555.60. Owner states dealership should have been able to diagnose concern on tast visit or feels repairs are related. Owner stoles customer service individual at dealership has disclined assistance on repairs or for repairs to be related to last repair. Writer speaks with service manager Ed who states repairs are not related. Writer declines any OCX assistance based on the time and miles outside of warranty and past goodwill assistance. Writer calls owner and

Copy of CAIRS 12495184



Copy of CAIRS 13026743_

CUSTOMER COMPLAINTS



AJR45 03 29 05

Customer states that the fan blade fell off the vehicle and hit the radiator. The customer states that this cost \$1500 for repairs. Writer advised of no recalls involving this component. Writer advised customer to contact DCCAC for further assistance.

Customer colling about the above issue. Customer says the cooling fan disengaged and caused damage to the radiator and hoses. Customer staking reimbursement for the damage caused to the radiator, hoses and towing. Customer states she took the vehicle to independent servicer before the trip to Florida for complete checkup and no problems were found with the Jeep Writer advised customer per BLJ9, DCX will not reimburse for the repairs caused by the cooling fan.

Copy of CAIRS 13356717

001








Jeep.

FIVE STAR

MV# 03528

DOSTROMER AU	36037		\$7	N MIZE	LL	35714	715	03725705	CHC\$168	981
			Çae	STABLE	CICENSE NO.	AULA.		RES/	stracy No	
			. 65	MEZE P	RAND CHEROI			DELIVERY DATE	DELIVERY DILES	
			102	/ 3201 / 0	MAND ENERGI	NCL.	201	EU-IND DEALCO M	C TPRODUCTION DAT	T
	61		18.00	e No	2	IPS NO		18 2 2AF 1 10 2		_
MANAGEMENT PRICES		LOUISINGS SPONE		MENTS				03/24/05		
ABOR & PART				P.E.Je. S					MO: 61	663
	DRIVE CUSTOMER STAT SHUT VEHICLE AND THEN CODE RADIATOR CODE DIAGNOSE AND RADIATOR HOSE	ES WHEN START OFF AND RESTA ANT STARTED L ING FAN CAME REPLACE DAMAS S TO REPAIR.	APART. SED RADIATOR.(S BAD VIBI DUD POPPI	N AND		314.50	and expense and disposal materials an used in vehic rapair order. will be 10% o	largo for supplies, mais related to the half or toxic and hazi- d wastes gonerated repair is made or The amount of this of the total labor char of \$10.00. This of	andir arcoi d ai d ai dhan dhan
98 (5・・・・・Q*) 08 番 1 08 番 1 18 番 1 18 番 1 08 番 1	1 520794 1 520795 1 520795 1 071993 1 E71991 1 506638 6 501345	28-AB 6-AA	RADIATOR 70 FAN CODLI 1 LAR HOSE UPPER HOS COOLANT C 1 GIL AUTOM 1	111 003 7002002	JDE # 1 TOTA	304.00 412.30 42.00 33.00 14.53 4.80	304.00 412.30 42.00 33.00 14.53 28.80 834.63	represents co	sts and profits to the facility and will appea repair invoice.	mot
				208 #	1 TOTAL LABOR		1149.13			
	CUSTOMER REQUI CHANGE FLUID / PERFORM CUSTOM	ESTS AUTOMATII AND FILTER MED REDUESTED	CEDUTEE	TECHT N SERVICE			62.95			
d-FS or	CUSTOMER REQUI CHANGE FLUID PERFORM CUSTOM PERFORM AUTOM CHANGE FLUID YFP-NUMBER PKOR-77	ESTS AUTOMATIC AND FILTER HER REQUESTED ATIC TRANSMISS AND FILTER 27 187-AA 24-AC	SERVICE SION SERVICE	N SERVICE	…⊗∵∾ักิพา.	T PRICE- 57.00	57.00 ****** *****			
*/5 or	CUSTOMER REQUI CHANGE FLUID I PERFORM CUSTOD PERFORM AUTOW CHANGE FLUID I Y FP-NUMBGR 15 950134 3 246433	ESTS AUTOMATIC AND FILTER HER REQUESTED ATIC TRANSMISS AND FILTER 27 187-AA 24-AC	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATF-4 GASKET 01 2	AL 1004003 1170001	JOB # 2 TOTAL	T PRICE- 57.60 **** **** PARTS	57.00 ******			
N/S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
N/S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
₹(S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
N/S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
N/S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
N/S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
N/S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
代[S	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
代TS	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
·	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
MFTS	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE SION SERVICE DESCRIPTION TRANS SPECI ATP+4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00 ***** **** PARTS	57.02 %+96 4545 57.00 119.95			
MFTS	CUSTONER REGUL CHANGE FLUTD PERFORM CUSTON PERFORM AUTOW CHANGE FLUTD PRS98-77 5 B5013 1 24643; 1 521187	ESTS AUTOMATION MID FILTER MER REQUESTED ATIC TRANSMISS AND FILTER 27 157-AA 24-AC 29	SERVICE DESCRIPTION TRANS SPECIA ATF-4 GASKET 01 2 FILTER VA 2	AL 1004003 1170001 30B # ;	JOB # 2 TOTAL 2 TOTAL LABOR 8	T PRICE- 57.00	57.00 			

Copy of Repair Invoice for CAIRS 13356717



Customer calling seeking assistance with the repair of her vehicle.
Customer states that the radiator fan on the radiator fan module exploded and damaged her radiator, two parts of her power steering, and the radiator itself. Writer called dealer 62359 and spoke with Marshall, Marshall advised that the plastic fan itself did indeed disintegrated causing damage to the power steering and the radiator. Marshall then stated that he has seen the fans come apart before, but not this violently. Marshall also advised that the there was evidence that the vehicle had been running very hid prior to the incident. Customer is the first owner of the vehicle and only owns this vehicle. Marshall also stated that the customer has not maintained a complete service history with dealer 63269. Writer advised customer that DainnerChrysler with not

Copy of CAIRS 13419481



5190 Highway 278 East Covington, GA 30014 770-786-2271 SALES • SERVICE • PARTS



www. walkerharrisautos.com

						rrisautos	Stanton Control of the Control of th
						l c	ŰE N
	100-00						
	102 JEEP G CHER, LAR GRY						
MILES I							
72	505 72510 05/10/02						
SEE AUSO							
(1)	CHECK FOR ANTIFREEZE LEAK.??	die die					
	REPLACED THE RADIATOR AND FAN AND CONDENSOR	Labor	(2)	Α.	96	528.00	
	MODULE: THERMOSTAT AND GASHET: FAN RELAY; POWER STEEING PUMP AND PULLEY; EVACUATED AND	52079428AD 52079489AB	(RADIATO: (SHROUD)	K)	1	184.80 28.39	
	THOUSENESS MITE A TO CHEMONY AND PARTY AND ADDRESS MITE	53010258AB	(PULLEY)		1	15.41	
	FREON AND HAD TO DO FURTHER A/C REFAIR; SEE	52079528AB 52028186AB	(FAN) (THRMOST	ו ייים	1 1	269.55	
	I the	53020547AC	(GASKET)	n. 1 ,	1	6.23	
	FREON AND HAD TO DO FURTHER A/C REPAIR; SEE CONDITION 2 This is far four forming a part COOLING	5066386AA	(COCLANT)	2	25.00	
	result mying a	4854033AB 4707286AF	(BELT) (RELAY)		1	28.98 59.90	
	a Corre	4741716	(O RING)		2	B.40	
	This is four	55116560 AF	(LINE)		1	77.97	
	1 Miles and	4885974AD 5012981AA	(VALVE) (O RING)		1	25,00	
	CD*	4885802AA	(O RING)		1	1.49	
		4796565	(O RING)		1	2.00	
		Total Labor Total Parts					528.0 735.8
	(03-9803 TSMITH-)	Total Repair					
,~,	PERFORMANCE TESTED THE A/C SYSTEM AND FOUND THE H-VALVE AND DRIFE STOPPED UP: REPLACED	Labor		A	39	214.50	
	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONENTS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-)	Labor Total Labor Total Repai:					
	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONENTS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK	Total Labor		, ,			214.5
	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-)	Total Labor Total Ropal:	r (Interna	L)			CUSTOMER.
	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-) EXTENDED TO THE TOTAL STATE OF THE TOTAL STA	Total Labor Total Repair	WC .00 7 .00 7 .00 7	42.50	Labor		214.5
Ne	THE H-VALVE AND DRIER STOPPED UP: REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-) EXT Service JUL '05 Lube-Oil-Filter DISCLAIMER OF WARRANTIES WE APPROPRIES	Total Labor Total Repair Total Repair	WG .00 7 .00 7 .00 7 .00	42.50 35.86	Labor Parts Sublet		214.5
Ne	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-) EXACT SERVICE JUL '05 Lube-Oil-Filter DISCLAIMER OF WARRANTIES DISCLAIMER OF WARRANTIES DISCLAIMER OF WARRANTIES DISCLAIMER OF WARRANTIES SERVEY(COMPLETED TO SERVEY) SERVE	Total Labor Total Ropal: RECIATE THE ITUNITY TO DU NOW AND	WC .00 7 .00 7 .00 7	42.50 35.86 .00	Labor Parta Sublet Haz.Wa	iste,Sh	214.5
Nearly was	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-) EXACT SERVICE JUL '05 Lube-Oil-Filter DISCLAIMER OF WARRANTIES DISCLAIMER OF WARRANTIES DISCLAIMER OF WARRANTIES DISCLAIMER OF WARRANTIES DISCLAIMER OF BOTH THE SERVICE OF T	Total Labor Total Repair Total Repair	WC .00 7 .00 7 .00 .00 .00 .00 .00 .00 .00	42.50 35.86 .00 .00 78.36	Labor Parts Sublet Haz. Wa Oil/Gr Total	iste,Sh	214.5 CUSTOMHC . 0 . 0 . 0 . 0 . 0
Ne.	THE H-VALVE AND DRIER STOPPED UP: REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-) axt Service JUL '05 Lube-Oil-Filter WE APPLY COMPONENTS OF WARRANTIES CHRYSLER OF WA	Total Labor Total Ropal: Total Ropal: TUTURITY TO DU NOW AND FUTURE	WC .00 7.00 7.00 7.00 .00 .00 .00 .00 .00	42.50 35.86 .00 .00 .00 .00 .00 .00 .00 .00	Labor Parts Sublet Haz.Wa Oil/Gr	iste,Sh	214.5
Ne Any was an analysis of materials of mater	THE H-VALVE AND DRIER STOPPED UP; REPLACED BOTH THESES COMPONETS AND RECHARGED THE COMPLETE SYSTEM TO CHRYSLER SPECS AND ALL ROAD TESTED OK (03-9803 TSMITH-) EXTENSION OF THE PROPERTY OF TH	Total Labor Total Ropal: Total Ropal: TUTURITY TO DU NOW AND FUTURE	WC .00 7.00 7.00 7.00 .00 .00 .00 .00 .00	42.50 35.86 .00 .00 .00 .00 .00 .00 .00 .00	Labor Parts Sublet Haz.Wa Oil/Gr Totul Tax	iste,Sh	214.5 CUSTOMEC . 00 . 00 . 00 . 00 . 00 . 00

Copy of Repair Invoice for CAIRS 1341948