



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 06-020
Date Opened: 05/23/2006
Principal Investigator: Robert Young
Subject: Motorcycle Stalling

Manufacturer: Yamaha Motor Corporation, USA
Products: 2004-5 Yamaha R1 and FZ6 Motorcycles
Population: 44455 (Estimated)

Problem Description: Tip-out stalling

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	23	0	23
Crashes/Fires:	3	0	3
Injury Incidents:	2	0	2
# Injuries:	2	0	2
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	0	2	2

*Description Of Other: EWR Field Reports

Action: Open a Preliminary Evaluation

Engineer: Bob Young

Date: 05/23/2006

Div. Chief: Richard Boyd

Date: 05/23/2006

Office Dir.: Kathleen C. DeMeter

Date: 05/23/2006

Summary: Operators report the motorcycle stalls when "rolling off the throttle" (while approaching a stop, for example) allegedly due to a faulty Throttle Position Sensor (TPS).

*To Yamaha
5-30-06
ly*

*GV
5/31/06*