

	A	B	C	D	E	P	Q	R	S
1	<u>GM's assessment</u>	<u>Build date</u>	<u>Odi_Id</u>	<u>Descr</u>	<u>Incident_Dt</u>	<u>Model</u>	<u>Model_Yr</u>	<u>Vin</u>	<u>Failure_Mileage</u>
2	NO VIN. VOQ did not mention if the timing chain failed while driving or while parked. Vehicle was in service approx. 6 years with 33,000 miles at reported incident date.	NO VIN	10149376	TIMING CHAIN FAILURE AT 33,000 MILES. *NM	7-Jan-06	LS1	2000		33000
3	Not original owner. VOQ shows purchase date of 4/02. Vehicle was in service 4.5 years with 51,950 miles at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	5/25/2001	10149274	1) THE CAR WAS DRIVEN TWO BLOCKS FROM HOME TO BRING A	24-Dec-05	L200	2001	1G8JU52F21Y	51950
4	Not original owner. VOQ shows purchase date of 8/05. Vehicle was in service 4 years with 61,000 miles at reported incident date. GM record shows the vehicle had extended warranty coverage of 60 month/ 60,000 miles starting 11/01. GM record shows customer received partial reimbursement from GM Saturn for repair not performed dealer (see Notes)	11/9/2001	10147664	DT: THE CONTACT STATED WHEN STOPPING AT A RED LIGHT, THE VEHICLE DIED.	12-Jan-06	ERIES WAC	2002	1G8JT84F22Y	61000
5	NO VIN.	NO VIN	10148627	2002 SATURN L200 STOPPE	24-Nov-05	L200	2002		28800
6	Not original owner. VOQ shows purchase date of 3/03. Vehicle was in service 3.75 years with 58,896 miles at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	10/10/2001	10144931	2002 L200 SATURN : TIMING CHAIN FAILURE, SATURN BULLETI	8-Aug-05	L200	2002	1G8JU54F02Y	58896
7	DUPLICATE see 10143174	DUPLICATE	10144271	FAX FM (KS) REQUEST	1-Nov-05	L-SERIES	2001		

	A	B	C	D	E	P	Q	R	S
8	DUPLICATE see 10143174	DUPLICATE	10142499	I HAVE A 2001 SATURN L-	8-Nov-05	ERIES SED	2001	1G8JU52F01Y	69000
9	Not original owner. VOQ shows purchase date of 2/04. Vehicle was in service 5 years with 69,000 miles at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	12/7/2000	10143174	I HAVE A 2001 SATURN L-SERIES, 2.2L ENGINE . I WAS DRIVING UNDER 30 MPH,ENGINE	8-Nov-05	ERIES SED	2001	1G8JU52F01Y	69000
10	Original owner. Vehicle was in service 5 years with 25,994 miles at reported incident date. Consumer recognized the rough idle was a problem and sought repair. Vehicle was driveable. Timing chain did not break. GM record shows the vehicle had extended warranty coverage of 48 month/ 50,000 miles starting on 3/04. There is no record of this repair or any related repair in the GM warranty system.	3/16/2000	10142770	DT: THE CONSUMER STATED THAT HER VEHICLE EXPERIENCED ROUGH IDLE.	29-Jul-05	LS	2000	1G8JR52F6YY	25994
11	Not original owner. VOQ shows purchase date of 6/04. Vehicle was in service 4.5 years with 52,250 miles at reported incident date. There is no record of extended warranty coverage or this repair or any related repair in the GM warranty system.	1/30/2001	10142297	ON OCTOBER 1, 2005 WILL DRIVING HOME, MY CAR STOPPE	2-Oct-05	L200	2001	1G8JU52F11Y	52250
12	Not original owner. VOQ shows purchase date of 7/02. Vehicle was in service 5.75 years with 73,500 miles at reported incident date. 60 month/ 60,000mile extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	9/15/1999	10133450	2000 SATURN LW-1 TIMING CHAIN BROKE ON THE VEHICLE.***NO ANSWER	13-Jun-05	ERIES WAC	2000	1G8JU82F1YY	73500

	A	B	C	D	E	P	Q	R	S
13	Not original owner. VOQ shows purchase date of 7/04. Vehicle was in service 4 years with 54,000 miles at reported incident date. This repair and a repair that may be related were in the GM warranty system. See Notes. No extended warranty coverag	2/9/2001	10127208	DT: THE CONSUMER WAS DRIVING THE VEHICLE WHEN HE	29-Jun-05	L200	2001	1G8JU52F21Y	54000
14	NO VIN.	NO VIN	10130462	THE TIMING CHAIN ON MY	26-Jul-05	L200	2001		75534
15	NO VIN.	NO VIN	10130504	TIMING CHAIN BREAKS PREMA	28-Jul-05	L200	2003		32000
16	NO VIN.	NO VIN	10129780	I WAS DRIVING ON CALIFO	16-Jul-05	ERIES SED	2000		69000
17	Not original owner. VOQ shows purchase date of 3/04. Vehicle was in service 4.5 years with 45,529 miles at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	1/22/2001	10128706	THE TIMING CHAIN ON MY 2001 SATURN L200 SNAPPED AT 45,000	6-Jun-05	L200	2001	1G8JU52F61Y	45529
18	Vehicle was in service 5 years with unknown mileage at reported incident date. A repair that may be related was found in the GM warranty system. See Notes. No extended warranty coverage on record.	4/11/2000	10127846	I OWN A 2000SA TURN LS1 WHILE DRIVING ON THE HIGHWAY MY CAR JUST BLEW	28-Apr-05	LS1	2000	1G8JU52F3YY	
19	Vehicle was in service 4 years with unknown mileage at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	5/21/2001	10127056	DT: THE TIMING CHAIN BROKE FOR THIS VEHICL	21-Jun-05	L-SERIES	2001	1G8JU52F21Y	

	A	B	C	D	E	P	Q	R	S
20	NO VIN.	NO VIN	10127045	WHILE DRIVING HOME FROM WORK MY	23-Jun-05	L200	2002		51500
21	Original owner. Vehicle was in service 4.5 years with 53,000 miles at reported incident date. No extended warranty coverage. GM record shows customer received partial reimbursement from GM Saturn for repair done at 53,327 miles. (see Notes)	9/26/2001	10126994	DRIVING DOWN A 4-LANE HIGHWAY AT 60 MPH THE ENGINE JUST QUIT RUNNING. THERE WERE NO	18-Jun-05	L200	2002	1G8JU54FX2Y	53000
22	Not original owner. VOQ shows purchase date of 9/03. Vehicle was in service 4.75 years with 49,050 miles at reported incident date. No extended warranty coverage. There is no record of this repair or any related repair in the GM warranty system.	9/20/1999	10126428	1. NO WARNING OF FAILURE E 2. TIMING CHAIN 3. REPLAC	20-Jun-05	LS1	2000	1G8JU52F9YY	49050
23	Vehicle was in service 5 years with 52,424 miles at reported incident date. No extended warranty coverage. There is no record of this repair or any related repair in the GM warranty system.	8/21/2000	10125864	STARTED VEHICLE AND LEFT GAS STATION WHEN THE ENGINE	15-Jun-05	L200	2001	1G8JU52F11Y	52424

	A	B	C	D	E	P	Q	R	S
24	Not original owner. VOQ shows purchase date of 1/02. Vehicle was in service 4.75 years with 63,000 miles at reported incident date. GM record shows customer received partial reimbursement from GM Saturn for repair done at 67,159 miles. (see Notes)	10/27/1999	10125476	WAS DRIVING THE CAR WHEN THE ENGINE QUIT AND ALL POWER WAS LOST. MECHANIC	11-Jun-05	L-SERIES	2000	1G8JU82F9YY	63000
25	Not original owner. VOQ shows purchase date of 2/05. Vehicle was in service 5 years with 107,000 miles at reported incident date. No extended warranty coverage.	6/26/2000	10124414	DT: TIMING CHAIN BROKE. FOUND INFORMATION ON	1-Jun-05	L-SERIES	2000	1G8JU82F6YY	107000
26	Vehicle was in service 5.5 years with unknown mileage at reported incident date. No extended warranty service coverage. There is no record of this repair or any related repair in the GM warranty system.	10/1/1999	10117087	WHILE DRIVING CONSUMER HEARD A LOUD POP	22-Mar-05	L-SERIES	2000	1G8JT52F0YY	
27	NO VIN.	NO VIN	10115682	WHILE DRIVING AT 65 MPH	10-Mar-05	LS	2001		36000
28	Original owner. Vehicle was in service 3.75 years with 30,000 miles at reported incident date. No extended warranty service coverage. There is no record of this repair or any related repair in the GM warranty system.	5/30/2001	10113766	AFTER MAKING A LEFT TURN VEHICLE FELT AS IF IT WAS	8-Mar-05	L200	2001	1G8JU52F01Y	30000
29	Original owner. Vehicle was in service 3.5 years with 53,772 miles at reported incident date. No extended warranty service coverage. There is no record of this repair or any related repair in the GM warranty system.	7/7/1999	10112117	TIMING CHAIN WENT ON MY 2000 SATURN LS JUST AT FIVE YEARS WITH	28-Jan-03	LS	2000	1G8JS52F8YY	53772

	A	B	C	D	E	P	Q	R	S
30	DUPLICATE see 10112117	DUPLICATE	10112953	THE VEHICLE WOULD	13-Dec-04	LS	2000	PLEASE PROVIDE	53000
31	Vehicle was in service 4 years with 57,000 miles at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	10/13/1999	10054190	WHILE DRIVING 45 MPH THE VEHICLE'S ENGINE DIED.	12-Oct-03	L-SERIES	2000	1G8JU52F1YY	57000
32	Not original owner. VOQ shows purchase date of 7/02. Vehicle was in service 2.75 years with 48,000 miles at reported incident date. No extended warranty coverage on record. There is no record of this repair or any related repair in the GM warranty system.	12/8/2000	10047912	WHILE DRIVING AT 65 MPH AND WITHOUT ANY WARNING, THE VEHICLE	9-Nov-03	LS	2001	1G8JU52F51Y	48000
33	NO VIN. Complaint sounds electrical in nature. Does not state that the vehicle stalled due to a timing chain issue.	NO VIN	10045937	TIMING CHAIN TENSOR FAILED.	31-Oct-03	L200	2001		
34	Original owner. Vehicle was in service 1 year with 48,157 miles at the reported incident date. No extended warranty coverage on record. This repair was recorded in the GM warranty system. See Notes.	9/18/2000	754647	DRIVING DOWN THE HIGHWAY BETWEEN 60	12-Nov-01	L200	2001	1G8JU52F71Y	

	U
1	<u>Notes</u>
2	
3	
4	CUSTOMER STATES THAT ENGINE WILL NOT START-TOWED TO INDEPENDENT JIMMY'S SERVICE.ORIGINAL OWNERS REQUEST FOR ASSISTANCE WAS DENIED JAN.06. SATURN RECONSIDERED ON 2/08/05, OFFER OF \$500 REIMBURSEMENT ISSUED
5	
6	
7	

	U
8	
9	
10	
11	
12	

	U
13	J0518: 'CONFIRMED ENGINE CRANKS BUT WILL NOT START. PERFORMED COMPRESSION TEST.3 CYLINDERS HAD NO COMPRESSION.REMOVED CAM COVER AND FOUND TIMING CHAIN BROKEN AND VALVES
14	
15	
16	
17	
18	FOR SES LIGHT AND LACK OF POWER. REPLACE D FAILING DIS MODULE AND MELTED CATLITIC CONVERTER AND O2 SENSOR, PIECES OF CATALITIC CONVERTER CLOGG ED INTERMEDIATE PIPE AND MUFFLER.ROAD TESTED FOR CORRECTION. DIS CAUSED ALL OTHER
19	

	U
20	
21	At 53,327 miles, labor code J0518: 'REIMBURSEMENT TO THE CUSTOMER FOR \$1 148.55 FOR THE REPLACEMENT OF THE TIMING CHAIN AND THE CYLINDER H EAD. THIS IS A ONE TIME OFFER, REMEMBER, CHANGE OI L AND FILTER EVERY 3,000 MILES OR 3 MONTHS AND WE RECOMMEND TH
22	
23	

	U
24	At 67,159 miles, labor code J1840: 'FOUND NECESSARY TO REPLACE CAR WITH USED ENGINE AND VP CUSTOMER 300.00 TOWARDS REPAIRS CASE NUMBER 1-16638728 TINA CUSTOMER MAINTED ALL SERVICES COPIES,VP CUSTOMER OF 300.00 TO
25	
26	
27	
28	
29	

	U
30	
31	
32	
33	
34	J0820: 'C/S ENG STALLED W/DRIVING. FND ENG CRANKED TOO FAS T AS IF NO COMPRESSION. PERF COMP TEST/ALL CYLS 0 PSI. REMOVE CAM COVER/FND BROKEN T/CHAIN. VALVES