

Q.7. Produce copies of all service, warranty, and other documents that relate to, or may relate to, the alleged defect in the subject vehicles, that Mitsubishi has issued to dealers, regional or zone offices, field offices, fleet purchasers, or other entities. This includes, but is not limited to, bulletins, advisories, informational documents, training documents, and other documents and communications, with the exception of standard shop manuals. Also include the latest draft copy of any communication that Mitsubishi is planning to issue within the next 120 days.

A.7. Copies of the following applicable documents are provided in this mailing:

- ◆ SR-01-008REVII
- ◆ SR-01-008REV
- ◆ SR-01-008
- ◆ ATIN-01-SR-010

Q.8 through Q.10. - MMNA will provide these responses on or before August 24, 2006.

Q.11. Produce one of each of the following:

- a. Exemplar sample of each design version of the subject component
- b. Field return sample of the subject component exhibiting the subject failure mode
- c. Any kits that have been released, or developed by, Mitsubishi for use in service repairs to the subject component/assembly which relate, or may relate, to the alleged defect in the subject vehicles.

A.11. **Even though there are four different part numbers for the accumulator, there are in fact only two designs. The first part number MR527718 was the original part number and was established in our system on 28 January 2000. The second part number MR977411 was established in our system on 18 May 2001 and was the same as the first part number, however an O-ring was included, making it a kit. The third part number MR977223 was a design change to the diaphragm and was developed for the recall. The fourth part number 4630A011 is the same physical design as MR977223; however the warning label attached to the accumulator was changed to include the Arabic language along with the other languages already on the label. A cross-sectional drawing showing the differences in design between the old and the countermeasure parts will be provided in our response to Q.10, which will be provided on or before August 24, 2006.**

- a. **Part numbers MR527718, MR977411 and MR977223 are no longer available as they have all been superseded by part number 4630A001. A sample of that design is being sent under separate cover.**
- b. **A failed part number MR527718 is also being sent under separate cover. This part was returned from the field and was originally installed on one of the subject vehicles.**
- c. **See A.11 above.**

Q.12. State the number of each of the following that Mitsubishi has sold that may be used in the subject vehicles by component name, part number (both service and engineering/production), model and model year of the vehicle in which it is used and month/year of sale (including the cut-off date for sales, if applicable):

- a. Subject components; and
- b. Kits that have been released, or developed, by Mitsubishi for use in service repairs to the subject component/assembly.

For each component part number, provide the supplier's name, address, and appropriate point of contact (name, title, and telephone number). Also identify by make, model and model year, any other vehicles of which Mitsubishi is aware of that contain the identical component, whether in production or in service, and the applicable dates of production or service usage.