



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 07-013
Date Opened: 03/12/2007
Principal Investigator: Ali Motamedamin
Subject: Fuel Pump Module Leaks Gasoline

Manufacturer: General Motors Corp.
Products: 2002-2003 Chevrolet Trailblazer, EXT, GMC Envoy, XL, XUV
Population: 818,763 (ESTIMATED)

Problem Description: Fuel Leaks From Corroded Fuel Pump Module.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	16	0	0
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	0	0	0

*Description of Other:

Action: Open A Preliminary Evaluation.

Engineer: Ali Motamedamin *AM*

Date: 03/12/2007

Div. Chief: Thomas Z. Cooper

Date: 03/12/2007

Office Dir.: Kathleen C. DeMeter

Date: 03/12/2007

Summary: ODI has received reports alleging that the fuel pump module (fuel sending unit) corrodes and leaks fuel. The module is located in the fuel tank and its top is exposed to atmosphere. Complainants report both smelling gasoline odor and observing fuel dripping from the tank.

ODI has opened this investigation to further examine the issue.