



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 07-056
Date Opened: 11/14/2007
Principal Investigator: Bob Young
Subject: Fuel Leak
Prompted by: Owner report / IE07-085

Manufacturer: Hyosung Motors America Inc.
Products: 2006 Hyosung "GV650" Motorcycles
Population: 2,000 (Estimated)

Problem Description: Fuel leak from tank seam

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	1	0	1
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	0	0	0

*Description of Other:

Action: Open this PE

Engineer: Bob Young

Date: 11/14/2007

Div. Chief: Richard Boyd

Date: 11/14/2007

Office Dir.: Kathleen C. DeMeter

Date: 11/14/2007

Summary: ODI received a vehicle owner questionnaire (VOQ) alleging a Hyosung GV650 leaked fuel from a fuel tank seam. After a Hyosung dealer replaced the tank, fuel again leaked from the motorcycle.

To learn more about this issue, and Hyosung's response to it, we are opening this PE.

Resume faxed to Hyosung, 11-15-07 @ 10:45AM