



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 08-043
Date Opened/Closed: 7/17/2008 / 8/8/2008
Principal Investigator: *Bob Young*
Subject: Motorcycle Stalling
Prompted by: Owner reports / IE08-068

Manufacturer: Harley-Davidson Motor Company
Products: MY 2008 FL and FX-Series
Population: 47,579

Problem Description: Engine stalls while underway due to cracked fuel filter housing.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	8	0	8
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	1	0	1

Description of Other: Web-based forum postings

Action: Harley recall (08V-357). Close this PE.

Engineer: *Bob Young*

Date: 8/8/2008

Div. Chief: *Richard Boyd*

Date: 8/8/2008

Office Dir.: *Kathleen C. DeMeter*

Date: 8/8/2008

Summary: The subject fuel filter housing (p/n 62229-08) cracks, resulting in sudden engine stall due to unregulated fuel pressure. Harley-Davidson has modified the housing with a new part number...62229-08A. Shortly after opening this PE, ODI received Harley's Defect Notification Report indicating that the subject vehicles were being recalled to install the new fuel filter housing. With that recall, received prior to release of our information request, this investigation is concluded.

Resume E-mailed to HD, 8-8-2008 @ ~ 1:30P