



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**

## ODI RESUME

Investigation: EA08-025  
Date Opened: 11-21-2008  
Principal Investigator: *Bob Young*  
Subject: Motorcycle Stalling - Electrical  
Prompted by: PE08-048

Manufacturer: Yamaha Motor Corporation, USA  
Products: MY 2006-2007 Yamaha FJR1300 motorcycles  
Population: 6,200 (Estimated)

Problem Description: Engine stalls while underway due to alleged ignition switch failure

### FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	14	31	45
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	1	0	1

\*Description of Other: Web forum postings

Action: Upgrade this PE to EA08-025

Engineer: *Bob Young* Date: 11/21/2008  
Div. Chief: *Richard Boyd* Date: 11/21/2008  
Office Dir.: *Kathleen C. DeMeter* Date: 11/21/2008

**Summary:** ODI is aware of at least 45 allegations of FJR1300 engine stalling while underway due to an ignition switch failure. In some instances, cycling the switch will allow re-start. FJRforum.com has numerous threads alleging the same issue.

To gather more focused information about this subject, we are upgrading PE08-048 to EA08-025.

Resume E-mailed to Yamaha, 11-21-2008 @ ~ 5:00P