



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 08-020
Date Opened: 3/20/2008
Principal Investigator: *Bob Young*
Subject: Stalling
Prompted by: Owner report / IE07-130

Manufacturer: Piaggio Group Americas, Inc.
Products: MY 2007 Moto Guzzi Norge
Population: 200 (Estimated)

Problem Description: Engine stalls when main fuse blows due to short in low beam headlight circuit

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	1	0	1
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	1	0	1

*Description of Other: Web-forum postings

Action: Open this PE.

Engineer: *Bob Young*

Date: 3/20/2008

Div. Chief: *Richard Boyd*

Date: 3/20/2008

Office Dir.: *Kathleen C. DeMeter*

Date: 3/20/2008

Summary: We have a VOQ alleging that a MY 2007 Moto Guzzi "Norge" model motorcycle stalled when the main fuse blew due to an alleged short in the low beam headlight circuit. This issue is also the subject of numerous web forum posts.

To learn more about this issue, we are opening this PE.

Resume sent by email to Piaggio, 3-21-08 @ 9:15A