



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 08-043
Date Opened: 7/17/2008
Principal Investigator: *Bob Young*
Subject: Motorcycle Stalling
Prompted by: Owner reports / IE08-068

Manufacturer: Harley-Davidson Motor Company
Products: MY 2008 FL and FX-Series
Population: Confidential

Problem Description: Engine stalls while underway due to cracked fuel filter housing.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	8	0	8
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	1	0	1

Description of Other: Web-based forum postings

Action: Open a Preliminary Evaluation.

Engineer: *Bob Young*

Date: 7/17/2008

Div. Chief: *Richard Boyd*

Date: 7/17/2008

Office Dir.: *Kathleen C. DeMeter*

Date: 7/17/2008

Summary: Fuel filter housing (p/n 62229-08) cracks, resulting in sudden engine stall due to unregulated fuel pressure. Harley-Davidson has modified the housing with a new part number...62229-08A.

Resume E-mailed to HD, 7-21-08 @ 1:30P

