

Document Name	Number of parts returned	Number of parts analyzed	Test description	Document Location
Consolidated.pdf	65	65	Checking for leaking SCDS.	Appendix K, NON-CONF ENGINEERING REVIEW, Bates range PE08-035 0032-0033
Review.pdf	Various	Various	Summary of testing, warranty claims, and field reports.	Appendix L, Tab B: CONF BUS INFO ROOT CAUSE, Bates range PE08-035 0590-0604
Windstar Switch Xrays 81196.pdf	19	19	X-Rays of switches from the field.	Appendix L, Tab D, CONF BUS INFO TEST RESULTS, Bates range PE08-035 0622-0635