

25635 Mound Road Warren, Michigan 48092-3499 (586) 753-3326 FAX (586) 753-3335


Facsimile Cover Sheet

DaimlerChrysler Vehicle Investigation Report (VIR)

وسيناه فقد مناوسي

Owne	Transmitting pages.				
EAA No: DF01- 5000	If transmission not complete, please				
	call the above phone number.				
CAIR No: 0059198					
	•				
To: Dee farm	From: Tina Martin				
Phone No:	From: Tina Martin				
	Date Faxed: 4-20				
Fax No: 845-339-510(a)	Due Date:				
	53.01				
Please acknowledge promptly by FAX or phone.	and the second second				
Panelint of CAID and A	W				
Receipt of CAIR and Accepting case for investigation	XYESNO DATE 4/19/02				
	-7				
Fou County of District	<u> </u>				
Fax Coversheet for DaimlerChrysler (Se	rvice Associate Use Only)				
(also tax to EAA for c	losure)				
Closure Date: DalmlerChrysle	er Fax Number: 248-512-8748				
4/30/02-					
Number of pages (including cover)					
TO:	•				
[] Dannie (240) 644 7664					
	lartell (248) 944-7038				
☐ Bott (248) 944-7056	usalia (248) 944-7149				
☐ Gilbert (248) 944-7037 ☐ P	orterfield (248) 944-7134				
	(240) 544-7 154				
Comments: / / / p = / - A					
Comments: / HSPEC/ED	4/30/02				
REPORT FAXED T					
METONI / PRED 3	· VCX 9/30/02				
t and yet, by planting to the second					
	aun				
	DAREL				
•					
	OF				
	PACE				

PAGE. 03



APR 30 2002 20:57

20:57

. .

<u>...</u>.

Additional information for Cair# 9959198 Mr. Scott Walton

Inspection of primary hood latch revealed no defect. Release cable works to standards and lock assy. locks firm.

Secondary latch shows signs of corrosion and salt deposits. Latch binds and sticks in open position.

Please take note that this is a snowplow vehicle.

Inspection of engine compartment revealed large deposits of salt on top of left exhaust manifold. Spark plug ports filled with salt. Engine wire harnesses filled with salt. Exhaust manifold and bolts severely corroded.

Brake lines to ABS and master cyl.severely corroded.

Large rodent nest under right side of intake manifold.

Oil level over 2qts low.

Coolant reservoir is empty.

Trans.fluid is cloudy and smells burned.

Other than the above mentioned items, general condition of the interior and exterior of this vehicle are good.

No service records available

My comment about the body estimate. Damage to hood is minor and can be repaired. Slight nicks to left and right rear corners of hood. Hinges are bent and need replacement. Secondary latch should be replaced due to corrosion. No other damage to vehicle.

Best regards; Dee Baum EAA-IC 845-339-5106

Der 4/3./02

9959198

MALTBIE'S CHEVROLET, INC. BOX 311 GLENS FALLS ROAD LAKE GEORGE, NY 12845

PHONE: (518) 668-5736 FAX: (518) 668-9567

NY REG.# R3570023

CD LOG NO 716-1 DATE 04/26/02

SHOP:

MALTBIE CHEVROLET

ADDRESS: ROUTE 9

CITY STATE: LAKE GEORGE, NY

ZIP: 12845-

OWNER: ADDRESS:

CITY STATE: LAKE GEORGE, NY

ZIP: 12845-

POINT OF IMPACT: 3

*=USER-ENTERED VALUE

EC=REPLACE ECONOMY

TE=PARTL REPL PRICE

N=ADDITIONAL LABOR

AA=APPEAR ALLOWANCE

LIC#: BODY COLOR: RED

CONDITION: EXCL

STATE: NY

VIN: MILEAGE:

INSP DATE:

CONTACT:

PHONE 1:

HOME PHONE:

FAX:

ACCING CIL#:

E≂REPLACE OEM

EU=REPLACE SALVAGE ET=PARTL REPL LABOR

L=REFINISH CG=CHIPGUARD

RI=R&I ASSEMBLY

RP=RELATED PRIOR

37,551

04/26/02

(518)668-5736

(518) 668-9567

DRU URE

NG=REPLACE NAGS EP=REPLACE PXN

IT=PARTIAL REPAIR BR=BLEND REFINISH

3B7KF26Z9YM1

SB=SUBLET

P=CHECK

UP=UNRELATED PRIOR

2000 DODGE RAM 250 SLT 2DOOR STANDARD CAB 8CYL GASOLINE 5.9

CODE: N8183B/B OPTNS K/24FZBACDH

OPTIONS:

I=REPAIR

TT=TWO-TONE

TWO-STAGE - EXTERIOR SURFACES

4-WHEEL DRIVE POWER DOOR LOCKS TILT STEERING WHEEL

CRUISE CONTROL

TWO-STAGE - INTERIOR SURFACES HEATED REMOTE CONTROL MIRRORS

POWER WINDOWS AIR CONDITIONING

OP	GDE	MC	DESCRIPTION		MFG. PART NO.	PRICE	AJ%	B&	HOURS R
E	0083		PANEL, HOOD	•	55075923AD	625.00			1.5 1
L	0083	09	PANEL, HOOD		REFINISH	·			6.2 4
RI	0343		DEFLECTOR, HOOD		R&I ASSEMBLY				0.3 1
E	0095		HANDLE, HOOD FRONT		55275195	9.35			0.3 1
E	0088		LATCH, HOOD PANEL		55275379	31.35			$0.2\tilde{1}$
E	0087		CATCH, HOOD SAFETY		55076367AB	6.90			1
E	0084	01	HINGE, HOOD PANEL	LT	55076271AC	76.50			0.2 1
L	0084		HINGE, HOOD PANEL	LŢ	REFINISH				0.4 4
E	0085	01	HINGE, HOOD PANEL	RТ	55076270AC	76.50			
L	0085		HINGE, HOOD PANEL		REFINISH	76.50			0.2 1
L	M16			L'I					0.4 4
יד	1110		COLOR BLEND		REFINISH				1.5*4*

,	9	4	5	y	1	9	8

2000	DODGE	RAM	250	SLT	2D00R	STANDARD	CAB
CD L	og nő i	716-1	•				

I	M17	COVER CAR EXTERIOR	SUBLET REPAIR	5.00*	0.3*1*
EC	M60	HAZARD. WSTE. REM.	ECONOMY PART	3.00*	*1*
N	M66	COLOR, SAND & BUFF	ADDNL LABOR OPERA		1.0*1*

14 ITEMS

MC MESSAGE(S)

01 CALL DEALER FOR EXACT PART NUMBER / PRICE

09 INCLUDES 0.6 HOURS MAJOR PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS OTHER PARTS PAINT MATERIAL PARTS TOTAL	,				825.60 3.00 153.00 981.60
TAX ON PARTS & MATERIAL	@			7.000%	68.71
LABOR 1-SHEET METAL	RATE 40.00	REPLACE	HRS 2.4	REPAIR HRS	148.00
2-mech/elec 3-frame 4-refinish	50.26		٥		
5-PAINT MATERIAL LABOR TOTAL	40.00 18.00		8.5		340.00
TAX ON LABOR SUBLET REPAIRS		0	,	7.000%	488.00 34.16 5.00
TAX ON SUBLET TOWING STORAGE		@		7.000%	0.35

GROSS TOTAL 1,577.82

NET TOTAL 1,577.82

ADP SHOPLINK U6489 ES CD LOG 716-1 DATE 04/26/02 12:32:26AM R6.2 CD 04/02 PXN:N/00/00/00 CUM:/// HOST LOG COPYRIGHT 2000, AUTOMATIC DATA PROCESSING, INC.

1.8 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.



Reference No.: 9959198 V.I.N.: 3B7KF26Z9YM

Dear

This will acknowledge your concern about the incident that occurred to your 2000 Dodge Ram truck.

Naturally, we were sorry to learn of this incident and the costly damage that occurred to your vehicle. At your request, DaimlerChrysler Motors Corporation provided for an independent inspector to examine your vehicle. DaimlerChrysler Motors Corporation feels that the expense of this inspection is in the best interest of you, our customer, and the Corporation, in our efforts to properly evaluate serious concerns such as yours.

The inspection involved a thorough examination of your vehicle and the photographing of all critical areas. It is the conclusion of this investigation that there was no manufacturing responsibility associated with this incident. Therefore, we must respectfully decline participation with any costs associated with this incident.

When an insurance company has paid a claim, the rights of recovery rest with them. Should they feel that there is a manufacturing responsibility with regard to their loss, they may subrogate which would include your deductible.

Thank you for this opportunity to address your inquiry.

Sincerely,

D. M. Bennis Special Investigations (248) 944-7036

DMB/kat