
## DaimlerChrysler

DaimlerChrysler Motors Corporation

June 13, 2002



Reference No.: 10098735

V.I.N.: 3B7HC12Y31G

Dear 1

This will further acknowledge contact to DaimlerChrysler Motors Corporation regarding your 2001 Dodge Ram 1500 pickup club cab.

Naturally, we were sorry to learn of the incident described to us during the initial contact. However, we have had the opportunity to review the inspection report and must inform you that we are not led to believe that the incident was due to a manufacturing responsibility. Therefore, we must respectfully decline any assistance associated with this incident.

Based on this information, we can only suggest that you refer this matter to your insurance carrier. Should they feel a manufacturing responsibility exists, they have full subrogation rights under the terms of your policy.

Thank you for allowing us the opportunity to review this matter with you.

Sincerely,

Linda Hutson Grzelka Special Investigations (248) 944-7089

sh

Owner: 🕀

JIM PRICE CHEUY



28635 Mound Road Warren, Michigan 48092-3499 (586) 753-3326 FAX (586) 753-3335

## Facsimile Cover Sheet DaimlerChrysler Vehicle Investigation

·	
Project No. DAIM-0001	CAIR No.:
10098735	
TO: Harald Aasland	FROM: Tina
Martin	
. •	/
Fax No.: COCC	Date Sent: 6-
10-02	
·	DUE DATE:
. <del>6-13-02</del>	

\*PLEASE-ACKNOWLEDGE PROMPTLY BY FAX OR EMAIL

\*Receipt of CAIR and Accepting case for investigation?
Yes No

6/11/02 Date: 0

Coversheet for DaimlerChrysler (Service Associate Use Only)

FALED 6(11/02

(Also fax or email to EAA for closure)

\*Closure Date: Daimler Chrysler Fax
No.: 248-512-8748


Bott (248) 944-7056 Susalla (248) 944-7149

-Gilbert (248) 944-7037 Porterfield (248) 944-7134


Comments:

434 817 1863 P.03/07

JUN-12-2002 14:02 JIM PRICE CHEUY







Picture List		
1.	l <sup>‡</sup> ront	
2.	Front/Passenger side corner	
3.	Passenger side	
4.	Passenger side/Rear corner	
5.	Rear	
6.	Rear/Driver side corner	
7.	Driver side	
8.	Driver side/Front corner	
9.	HOOD DAMAGE LEFT REAR CORNER	
10.	" " Right " "	
11.	CRACKED WINDSHIELD	
12.	RIGHT WIPER ARM TOUCHING REAR OF HOOD	
13.	SECONDARY HOOD LATCH HITTING BEHIND OPENING	
14.	MISALIGNMENT SEEN FROM RH FRONT FENDER	
15.	HOW HOD LATCH HOOK WAS FOUND AFTER INCIDENT	
16.	CONNECTING ROD WAS FOUND DISCONNECTED LIKE THIS	
17.		
18.		
19.		
20.		
21.		
22.		
23.		
24.		
	•	