



This photos is at a weird angle but the tech had to twist the camera to get the shot. This connector is the one we ask the techs to tape and add the tie strap. The connector is stressed and stretched when the wheel is extended to the full out telescopic position. The technicians are adding an extra inch of wire to correct it.