

VIN	MODEL-YEAR	DATE-MFG	DATE-IN-SVC	ST-DEALER	CODE-DLR	DATE-RO	NUM-RO	MILEAGE	CODE-PNC	NUM-PART1	QTY-PART1	DESC-PART1	COMM-CUST	COMM-TECH
JNKAY41E33 M [REDACTED]	2003	10/30/2002	8/2/2003	WA	70507	9/2/2004	0162301	22320	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES THAT THE AIR BAG LIGHT IS ON. SOP PART IS HERE	CODE B1134 L.H. SIDE MODULE OPEN REPLACED L.H. SIDE AIR BAG
JNKAY41E13 M [REDACTED]	2003	12/10/2002	4/13/2003	CA	70101	8/30/2004	9378502	53123	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT FLASHING	SUBLET TO HENRY'S FOR SIDE AIRBAG INSTALL PO#87882
JNKAY41E83 M [REDACTED]	2003	11/8/2002	1/27/2003	NY	71014	8/27/2004	9854801	29512	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIRBAG LIGHT FLASHING SEE SOP	CODE B1134 PRESENT (LH SIDE AIR BAG MODULE) REPLACE LH AIR BAG MODULE AND CLEAR CODE. NO OTHER DTC PRESENT.
JNKAY41EX3 M [REDACTED]	2003	10/21/2002	12/14/2002	SC	70202	8/26/2004	6870201	23695	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG WARNING ON SOP IN	INTERNAL FAILURE OF LH SIDE AIR BAG MODULE REPLACED AIR BAG

JNKAY41E13 M [REDACTED]	2003	1/31/2003	12/5/2003	CA	70112	8/25/2004	4457701	8125	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT IS FLASHING, SOP HERE.	OPEN CIRCUIT. REPLACED DRIVERS SIDE AIR BAG MODULE (THORNTONS)
JNKAY41E33 M [REDACTED]	2003	9/17/2002	9/22/2003	FL	70046	8/24/2004	7449501	26769	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT CAME ON MODULE WAS FAULTY SOP IN STOCK	SIDE MODULE LH OPEN REPLACED LH SIDE MODULE
JNKAY41E73 M [REDACTED]	2003	10/22/2002	7/31/2003	OH	70216	8/23/2004	4854303	21403	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THAT THE AIR BAG LIGHT IS ON (SOP)	RAN CONSULT RECIEVED B1134 REPLACED LEFT SIDE AIR BAG MODULE

INFORMATION Redacted PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

JNKAY41EX3 M [REDACTED]	2003	12/18/2002	12/13/2003	NV	70215	8/21/2004	4513601	6655	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS ON.	SOP LEFT FRONT SIDE MODULE REPLACE INTERNAL OPEN CIRCUIT SIDE MODULE OPEN B1134
JNKAY41E03 M [REDACTED]	2003	10/22/2002	8/6/2003	GA	70045	8/21/2004	5667703	21883	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS FLASHING	LH SIDE MODULE/OPE N B1134/REPLA CED L.F. SEAT SIDE MODULE TO RESOLVE INCIDENT/SO RRY FOR ANY INCONVIENCE S FOR GUEST
JNKAY41E13 M [REDACTED]	2003	7/31/2002	11/5/2002	NJ	70214	8/20/2004	8829501	24102	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT IS ON	DRIVER SEAT AIR BAG MODULE BAD. REPLACE DRIVER SEAT SIDE AIR BAG

JNKAY41E63 M [REDACTED]	2003	1/24/2003	7/31/2003	FL	73051	8/20/2004	2273301	7786	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT IS FLASHING.	FOUND LEFT SEAT AIRBAG MALFUNCTION. REPLACED AIRBAG
JNKAY41E93 M [REDACTED]	2003	10/15/2002	2/15/2003	CA	70496	8/20/2004	0368201	11476	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	OWNER STATES SUPPLEMENTAL AIR BAG LIGHT ON	VERIFY LIGHT ON, ISOLATE TO DRIVES SIDE AIR BAG REPLACED DRIVERS SIDE AIR BAG,CLEAR CODES,CHECK OPERATION
JNKAY41E23 M [REDACTED]	2003	10/24/2002	9/27/2003	TN	70234	8/18/2004	6895402	15899	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT IS ON	FOUND L/H AIR BAG MODULE OPEN REPLACE L/H AIR BAG MODULE
JNKAY41E33 M [REDACTED]	2003	10/18/2002	10/27/2003	PA	71028	8/16/2004	8472001	13147	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIRBAG LIGHT ON, SOP L SIDE AIRBAG IEZZI	INTERNAL PROBLEM IN L/SIDE AIR BAG MODULE IN SEAT. REPLACED AIR BAG MODULE IN SEAT.

JNKAY41E53 M [REDACTED]	2003	10/1/2002	11/30/2002	NJ	70021	8/16/2004	9619801	17210	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/R INSTALL SOP (AIBAG) L	FOUND FAULT CODE B1134 FOUND FAULTY AIR BAG MODULE REPLAACED FAULTY AIR BAG MODULE
JNKAY41E93 M [REDACTED]	2003	12/21/2002	2/20/2003	UT	71085	8/12/2004	6692301	21375	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIR BAG LIGHT ON	REPLACE A SIDE AIR BAG DRIVERS SEAT
JNKAY41EX3 M [REDACTED]	2003	11/8/2002	11/21/2003	NY	70017	8/11/2004	9861601	9340	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CAR WAS TOWED IN FOR AIR BAG LIGHT ON	INTERNAL FALURE IN LH SEAT AIR BAG. INSTALL NEW LH FRONT SEAT AIR BAG ASSEMBLY AND CLEAR CODES.

JNKAY41E03 M [REDACTED]	2003	10/7/2002	6/28/2003	NC	71042	8/10/2004	4882201	16643	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THAT THE SUP. AIR BAG LIGHT IS ON SOP IS IN	VERIFIED COMPLAINT AIR BAG LIGHT ON.CAUSE:RE TREV CODE LEFT BAG DEFECTIVE.C ORRECTION: REPLACE SEAT BAG RESET COMPUTER AND
JNKAY41E23 M [REDACTED]	2003	8/27/2002	6/30/2003	VA	70224	8/10/2004	6126201	17288	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THERE IS AN AIR BAG LAMP ON SOP IN	INSTALL NEW SIDE AIR BAG LH FRONT
JNKAY41E33 M [REDACTED]	2003	2/11/2003	4/11/2003	AL	71239	8/9/2004	4219601	30965	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG WARNING LIGHT ON	AIRBAG MODULE ON L/S HAS ELECT OPEN REPLACE AIRBAG MODULE

JNKAY41E43 M [REDACTED]	2003	10/22/2002	10/24/2003	NJ	71252	8/9/2004	0915702	12335	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT IS ON	FOUND DRIVERS SEAT AIRBAG TO HAVE INTERNAL FAULT REPLACED AIRBAG
JNKAY41E53 M [REDACTED]	2003	7/29/2002	10/7/2002	FL	71047	8/6/2004	4342004	17449	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT ON - CRAIG CHECKED SAT - NECESSARY TOP ORDER MODULE ASSY-SIDE AIR - WILL ARRIVE TUES FOR INSTALL	RAN CONSULT, CODE: B1134, LH SIDE AIRBAG MODULE WITH OPEN CIRCUIT, REPLACED LEH SIDE AIRBAG MODULE & CLEARED LIGHT

JNKAY41E93 M [REDACTED]	2003	11/19/2002	6/16/2003	OK	70487	8/6/2004	1458001	18242	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT IS ON	DIAG FOUND LEFT SIDE AIRBAG MODULE INTERNAL FAILURE.REP LACEDLEFT AIRBAG MODULE.OPE RATING TO SPECS.RO 121632
JNKAY41E83 M [REDACTED]	2003	8/7/2002	12/8/2002	CA	71094	8/5/2004	8416702	20575	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES THE AIRBAG WARNING LIGHT HAS COME ON.	INTERNAL FAILURE IN THE LEFT SIDE AIR BAG MODULE REPLACED THE LEFT SIDE AIR BAG MODULE. THANK YOU.
JNKAY41E83 M [REDACTED]	2003	12/19/2002	11/28/2003	CA	71238	8/5/2004	8753001	13935	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S THE AIR BAG LIGHT IS FLASHING SOP IN	AIR BAG MODULE OPEN CIRCUIT REPLACED MODULE

JNKAY41E93 M [REDACTED]	2003	12/20/2002	7/31/2003	OH	70231	8/3/2004	9200701	13958	98830	K8EHACR900		MODULE ASSY-SIDE AIR BAG FR 1 LH	CUSTOMER STATES AIR BAG WARNING LIGHT IS ON.	FOUND THE LEFT SIDE AIR BAG MODULE HAS AN OPEN CIRCUIT. I REMOVED THE DRIVERS SEAT AND REPLACED THE SIDE AIR BAG MOD
JNKAY41EX3 M [REDACTED]	2003	12/23/2002	11/28/2003	TX	70403	8/2/2004	8028301	6068	98830	K8EHACR900		MODULE ASSY-SIDE AIR BAG FR 1 LH	AIR BAG LIGHT ON	RAN TEST WITH CONSULT FOUND CODE B1134 REPLACED LEFT HAND AIR BAG MODULE

JNKAY41E53 M [REDACTED]	2003	10/24/2002	3/25/2003	CA	71094	8/2/2004	8407004	5578	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT IN DASH IS ON	INTERNAL FAILURE IN THE LEFT FRONT SIDE AIR BAG MODULE REPLACED THE AIR BAG MODULE AND CLEARED THE CODE
JNKAY41E53 M [REDACTED]	2003	12/23/2002	3/7/2003	VA	71035	8/2/2004	4338501	15031	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES HER TRUNK WONT OPEN, AIR BAG LIGHT IS FLASHING,	AIR BAG MODULE IS NOT SENDING ELECTRICAL SIGNALS TO ECM REPLACED MODULE
JNKAY41EX3 M [REDACTED]	2003	11/7/2002	10/23/2003	TN	70934	7/29/2004	30397A	6631	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	RPL AIR BAG MODULE	WARNING LIGHT
JNKAY41EX3 M [REDACTED]	2003	11/28/2002	10/18/2003	FL	73051	7/28/2004	2202602	9444	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT FLASHING	SIDE MODULE CODE LH REPLACED LEFT FRONT SEAT AIRBAG ASSEMBLY

JNKAY41E13 M [REDACTED]	2003	12/19/2002	3/11/2003	NY	70016	7/28/2004	0542201	28618	98830	K8EHMCR900	1	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMER STATES THAT THE AIR BAG LIGHT IS ON.INSTALL S/O AIR BAG	CHECKED WITH CONSULT RT SIDE SEAT AIR BAG MODULE FAULTY R/R RT SIDE SEAT AIR BAG MODULE
JNKAY41E63 M [REDACTED]	2003	10/26/2002	2/27/2003	NY	70017	7/28/2004	9803002	31628	98830	K8EHMCR900	1	MODULE ASSY-SIDE AIR BAG FR,RH	C/STATES THAT NAVIGATION SCREEN POPS UP AND STATED CALL FOR ROAD SIDE ASSISTANCE FOR AIR BAGS.	PERFORMED DIAG TEST FOUND OPEN CODE B1134 REPLACED SIDE MODULE AIR BAG

JNKAY41E43 M [REDACTED]	2003	1/21/2003	8/26/2003	LA	71229	7/27/2004	8381402	18693	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S THE AIR BAG LIGHT COMES ON WHILE DRIVING **SEE HISTORY**	DIAG W/ CONSULT FOUND DTC B1134 SIDE MODULE LH, OPEN IN LEFT SIDE MODULE//REP L LEFT SIDE AIR BAG MODU, CLEARED CODES
JNKAY41E53 M [REDACTED]	2003	2/5/2003	10/4/2003	NV	70215	7/26/2004	4383701	14809	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT ON	FOUND INTERNAL FAILURE IN LEFT SIDE A/B MODULE REPLACE A/B MODULE
JNKAY41E83 M [REDACTED]	2003	8/5/2002	8/30/2003	TX	71077	7/26/2004	2615701	25036	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT IS ON	DRIVER'S SIDE SEAT MODULE CODE FOR OPEN CIRCUIT FOUND REPLACED DRIVER'S SIDE SEAT MODULE

JNKAY41E43 M [REDACTED]	2003	8/2/2002	10/18/2002	TN	70234	7/21/2004	6810901	27778	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT IS FLASHING CUST DROP OFF AT 9:30AM/ NO LOANER	PERFORMED CONSULT DIAG/FOUND CODE L/H AIR BAG MODULE OPEN REPLACE L/H SIDE AIR BAG MODULE
JNKAY41E03 M [REDACTED]	2003	1/30/2003	10/31/2003	NJ	70025	7/20/2004	17601	5500	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIRBAG WARNING LIGHT IS ON	CODE B1134, REPLACED LH MODULE TESTED OK
JNKAY41E53 M [REDACTED]	2003	11/1/2002	8/22/2003	NH	70503	7/20/2004	0517601	8469	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES THAT AIRBAG WARNING LIGHT IS ON.	CONFIRMED COMPLAINT,O BSERVED THROUGH CONSULT CODE B1134 FOR L SIDE AIR BAG MODULE,REP LACE LEFT SIDE AIRBAG MODULE.

JNKAY41E93 M [REDACTED]	2003	11/13/2002	6/30/2003	NC	71042	7/20/2004	4787501	16359	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THAT THE AIRBAG LIGHT IS BLINKING	TESTED SYSTEM FOUND CODE FOR L/H SIDE AIRBAG REPLACED L/S SIDE AIRBAG
JNKAY41E83 M [REDACTED]	2003	12/3/2002	1/9/2004	NY	70012	7/19/2004	7054301	4640	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST. STATES: AIR BAG WARNING LIGHT ON. SIDE AIR BAG MODULE ON ORDER, RECEIVED.	TESTED WITH CONSULT - FAILURE IN SIDE AIR BAG MODULE- UNABLE TO RE-SET - REPLACED L/F SIDE AIR BAG MODULE
JNKAY41EX3 M [REDACTED]	2003	11/30/2002	7/23/2003	NC	72040	7/13/2004	6758001	24975	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES THE AIRBAG LIGHT IS ON	DIAG LAST VISIT/DIAG AGAIN/X2 DIAG!!/B1134 OPEN B1134/DIAG/R EPLACE SIDE MODULE/ERA SE CODE USING CVCONSULT

JNKAY41E03 M [REDACTED]	2003	11/6/2002	1/15/2003	AZ	70482	7/12/2004	6040601	17754	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT IS ON	VERIFIED LEFT SIDE AIRBAG CODE DUE TO OPEN CIRCUT IN AIR BAG MODULE, OHMS CHECKED MODULE FOUND OPEN CIRCUT TO EXSIST
JNKAY41E03 M [REDACTED]	2003	10/15/2002	8/21/2003	NJ	70024	7/8/2004	3635401	5149	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST/STATES AIR BAG LIGHT BLINKING (2 DAYS) LOANER # 19	PERFORM CONSULT DIAG, L/SIDE AIR BAG MODULE OPEN (B1134) REPLACED L/SIDE AIR BAG MODULE IN L/FRT SEAT
JNKAY41E33 M [REDACTED]	2003	12/5/2002	12/13/2003	NY	71015	7/8/2004	1974301	9504	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT IS ON. INSTALL SOP PART	REPLACED LEFT SIDE AIR BAG MODULE.

JNKAY41E23 M [REDACTED]	2003	10/25/2002	10/18/2003	OH	70216	7/6/2004	4785802	8217	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THAT THE AIR BAG LIGHT IS ON	RAN CONSULT AND RECIEVED P1134 REPLACED AIR BAG MODULE AND HARNESS LEFT SIDE
JNKAY41E13 M [REDACTED]	2003	12/6/2002	7/22/2003	IL	70062	7/3/2004	3874401	26678	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C STATES THE AIR BAG LIGHT IS FLASHING (HISTORY)	SIDE MODULE FAILURE REPLACED SIDE AIR BAG MODULE
JNKAY41E23 M [REDACTED]	2003	10/28/2002	10/22/2003	CA	70499	6/30/2004	1044701	9924	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	OWNER REPORTS AIR BAG LIGHT WAS ON. INSTALL SOP.	OPEN CIRCUIT IN DRIVER SEAT AIR BAG REPLACE DRIVERS SEAT SIDE AIR BAG

JNKAY41E13 M [REDACTED]	2003	10/19/2002	8/20/2003	FL	71050	6/28/2004	0738501	9761	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIRBAG WARNING LIGHT FLASHING	DIAGNOSTIC INSPECTION FINDS CODE B1134, OPEN CIRCUIT LH/SIDE AIRBAG.REPL ACED LH/SIDE AIRBAG MODULE ASSEMBLY
JNKAY41E23 M [REDACTED]	2003	1/14/2003	2/26/2003	NM	71241	6/28/2004	4360101	37886	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT ON. SOP	FOUND OPEN CIRCUIT AT LEFT AIRBAG MODULE REPLACED MODULE
JNKAY41E23 M [REDACTED]	2003	10/10/2002	3/5/2003	NJ	70214	6/24/2004	8625603	32201	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIR BAG LIGHT IS ON-SOP PART	DRIVER SEAT AIR BAG CODES SET REPLACE DRIVER SEAT AIR BAG ASSEMBLY.

JNKAY41E23 M [REDACTED]	2003	12/21/2002	9/9/2003	GA	70045	6/23/2004	5382304	10123	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C.S/ THAT THE SRS LIGHT IS FLASHING	HAS CODE B1134 IN MEMORY. LEFT SIDE MODULE IS OPEN. REPLACE LEFT SIDE MODULE IN DRIVER'S SEAT.
JNKAY41E73 M [REDACTED]	2003	1/24/2003	10/27/2003	AZ	70482	6/21/2004	5968202	14280	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT IS FLASHING SOP PART IS HERE	VERIFIED AIR BAG LIGHT FLASHING FOUND CODE B1134 FOR LEFT SIDE MODULE OPEN
JNKAY41E83 M [REDACTED]	2003	10/4/2002	12/31/2002	TX	70236	6/21/2004	6667201	32332	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES THE AIR BAG LIGHT IS ON	RAN SELF DIAGNOSTICS WITH CONSULT AND DTC B1134 WAS STORED IN MEMORY DUE TO OPEN CIRCUIT IN LH SIDE AIR BAG MODULE.REP LA

JNKAY41E53 M [REDACTED]	2003	8/5/2002	2/24/2003	MI	70310	6/18/2004	6732001	15529	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S THE AIR BAG LIGHT	FOUND DRIVER SIDE SEAT SIDE AIR BAG SHORTED NECESSARY TO REPLACE SIDE AIR BAG MODULE
JNKAY41E53 M [REDACTED]	2003	12/17/2002	9/14/2003	CA	70504	6/18/2004	0327601	8799	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIRBAG LIGHT ALWAYS ON	DRIVERS SIDE AIRBAG MODULE SHOWS OPEN HARNESS CONN ALL FINE REPLACED AIRBAG MODLUE
JNKAY41E93 M [REDACTED]	2003	8/28/2002	10/21/2002	IN	70059	6/17/2004	7870401	31051	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES SEAT BELT MALFUNTION WARNING ON	REPLACED AIR BAG MODULE

JNKAY41E63 M [REDACTED]	2003	11/1/2002	12/23/2002	GA	70498	6/16/2004	1272202	27135	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES THAT THE AIR BAG LIGHT IS ON, PLEASE CHECK.	SIDE MODULE LH HAS OPEN CIRCUIT (B1134) REPLACED LH SIDE SRS MODULE.
JNKAY41E63 M [REDACTED]	2003	10/24/2002	12/30/2002	CA	70101	6/15/2004	8889902	27918	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CHECK AIR BAG LIGHT WAS ON -- INSTALL SOP AIR BAG	AIR BAG LIGHT ON PO#86749 REPLACED DRIVER SIDE MODUAL - SUBLET TO HENRYS UPHOLSTRY
JNKAY41E13 M [REDACTED]	2003	12/18/2002	7/12/2003	NJ	70024	6/11/2004	3496201	12928	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIRBAG LIGHT ON (SOP)	CONFIRMED AIRBAG DTC B1134 SIDE MODULE LH iOPEN ^J , REPLACED LH SIDE MODULE
JNKAY41E93 M [REDACTED]	2003	8/26/2002	3/29/2003	GA	70247	6/10/2004	2337301	18245	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES SRS WARNING LIGHT IS ON	FOUND D/S AIRBAG MODULE OPEN CIRCUIT REPLACED AIRBAG MODULE

JNKAY41E93 M [REDACTED]	2003	11/6/2002	2/28/2003	CA	71238	6/10/2004	8546901	28967	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS ON. CHK FOR SOP.	INTERNAL FAILURE. REPLACED DRIVERS AIR BAG.
JNKAY41E73 M [REDACTED]	2003	12/18/2002	1/28/2003	AZ	70082	6/9/2004	3511902	16820	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT IS ON	CONSULT SHOWS L SIDE AIRBAG MODULE OPEN-B1134 REPL L SIDE AIRBAG MODULE
JNKAY41EX3 M [REDACTED]	2003	12/24/2002	11/30/2003	NY	70017	6/8/2004	9629501	8242	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	C/STATES THAT THE AIR BAG LIGHT IS ON SOP PARTS ORDERED LAST SERVICE	AIR BAG LIGHT IS ON FOR SIDE MODULE REPLACED AIR BAG IN SEAT

JNKAY41E53 M [REDACTED]	2003	1/21/2003	8/31/2003	NC	71042	6/1/2004	4574001	12409	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LAMP FLASHING ON VEHICLE CHECK AND ADVISE	CONFIRMED CUSTOMER COMPLAINT. FOUND PAST DIAGNOSIS STORED TROUBLE CODE FOR LH SIDE MODULE OPEN. WIRING AND CONNECTION S
JNKAY41EX3 M [REDACTED]	2003	8/29/2002	2/14/2003	IL	70062	5/28/2004	3718401	18818	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C STATES THE AIRBAG LIGHT IS ON.	SIDE MODUKE LH OPEN REPL MODULE
JNKAY41E43 M [REDACTED]	2003	9/12/2002	8/31/2003	MD	71481	5/26/2004	2430801	8050	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS ON	CODE FOR AIR BAG MODULE REPLACE AIR BAG MODULE

JNKAY41E43 M [REDACTED]	2003	10/1/2002	11/30/2002	NJ	70214	5/24/2004	8515601	15785	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIR BAG LIGHT IS ON	DRIVER SEAT AIR BAD HAS OPEN CIRCUIT STORED REPLACE DRIVER SEAT AIR BAG, CLEAR CODES.
JNKAY41E73 M [REDACTED]	2003	10/25/2002	7/22/2003	NC	71042	5/24/2004	4540601	15532	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUT STATES AIR BAG LIGHT IS ON	DEFECTIVE PART/FAILUR E AND OPEN CIRCUIT FROM LF SIDE AIR BAGMODULE CAUSING AIR BAG LIGHT TO CAME ON. CONSULT CODE B1134.
JNKAY41E63 M [REDACTED]	2003	9/13/2002	11/30/2002	TN	72233	5/21/2004	5547601	18849	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT ON	LEFT FRONT SEAT SIDE AIR BAG MODULE MALFUNCTION REPLACED AIR BAG MODULE

JNKAY41E13 M [REDACTED]	2003	11/11/2002	7/15/2003	OH	70231	5/17/2004	8911501	10834	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THE AIRBAG LIGHT IS FLASHING	FOUND THE LEFT SIDE MODULE OPEN. I REMOVED THE SEAT AND REPLACED THE MODULE TO RESOLVE THE I
JNKAY41E13 M [REDACTED]	2003	12/6/2002	7/22/2003	IL	70062	5/4/2004	3600101	23509	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C STATES THE AIRBAG LIGHT IS FLASHING	LEFT SIDE AIR BAG MOD. OPEN CODE. REPLACE DRIVERS SEAT SIDE AIR BAG. MODULE.
JNKAY41E73 M [REDACTED]	2003	12/18/2002	7/31/2003	NJ	71023	5/4/2004	6756101	12843	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LITE ON	LH SIDE MODUALE OPEN.REPLA CE L/F SIDE AIR BAG MODUALE

JNKAY41E13 M [REDACTED]	2003	12/23/2002	10/13/2003	AZ	70482	5/3/2004	5776301	7029	98830	K8EHACR900		MODULE ASSY-SIDE AIR BAG FR 1 LH	C/S AIR BAG LIGHT SUPPLIMENT AL	VERIFIED INTERNAL FALIURE IN DRIVERS SEAT SIDE AIR BAG MODULE. REPLACED DRIVERS SEAT SIDE AIR BAG MODULE FOR CODE B1134.
JNKAY41E03 M [REDACTED]	2003	7/26/2002	11/16/2002	NY	70221	4/26/2004	8127901	23744	98830	K8EHACR900		MODULE ASSY-SIDE AIR BAG FR 1 LH	CUSTOMER STATES THE AIR BAG LIGHT IS ON SEEHISTORY AND REPORT	LEFT DRIVERS SIDE SEAT MODULE FAILING CONTROL UNIT BAD REPLACE SIDE MODULE

JNKAY41E43 M [REDACTED]	2003	11/6/2002	3/24/2003	SC	71423	4/22/2004	2920401	15983	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES, SRS LIGHT IS ON	PERFORMED SRS DIAGNOSTIC FOUND SIDE MODULE LH OPEN B1134 SENT TO TRIM SHOP FOR SIDE MODULE LH REPLACEMEN T
JNKAY41E43 M [REDACTED]	2003	12/3/2002	6/30/2003	AZ	70082	4/22/2004	3266502	23246	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CST CHILD AIR BAG POPS UP, HAPPEN AT 23000	DTC B1134-L SIDE AIRBAG MODULE.FOL LOW DIAG PROCEDURE PG SRS-29,L SIDE AIRBAG MDULE OPEN,REPL L AIRBAG MODULE,CON TROL UN

JNKAY41E53 M [REDACTED]	2003	7/30/2002	5/31/2003	GA	70045	4/21/2004	5122705	27326	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT FLASHING... ALSO WARNING FOR OIL CHANGE	B1134 STORED LEFT SIDE AIR BAG MODULE REPLACE LEFT SIDE AIR BAG MODULE
JNKAY41E33 M [REDACTED]	2003	11/5/2002	5/25/2003	CA	70112	4/20/2004	3957501	16785	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT IS ON.	OPEN CIRCUIT. REPLACED LEFT SIDE AIR BAG MODULE.
JNKAY41E93 M [REDACTED]	2003	11/13/2002	9/25/2003	CT	70006	4/20/2004	8309001	15285	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LITE IS ON	DIAG OPEN IN DRV SIDE AIR BAG CUST STATES LITE CAME ON AFTERVAC UNDER SEAT.REMOV E DRV SEAT AND CUSHION REPL AIR BAG

JNKAY41E03 M [REDACTED]	2003	10/18/2002	10/25/2003	VA	71035	4/15/2004	3821901	5077	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LAMP IS ON (SOP)	TECH. FOUND SIDE AIR BAG MODULE WITH INTERNAL FAILURE TECH. REPLACED SIDE AIR BAG MODULE- RETESTED OK AT THIS TIME
JNKAY41E03 M [REDACTED]	2003	10/23/2002	4/14/2003	MA	70001	4/13/2004	4400101	10292	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT ON, LEFT AIR BAG SIDE MODULE NEEDS REPLACEMENT...S.O.P.	OPEN CIRCUIT IN LEFT SIDE AIR BAG MODULE REPLACE LH SIDE AIR BAG MODULE

JNKAY41E73 M [REDACTED]	2003	11/15/2002	5/16/2003	NJ	70024	4/5/2004	3106103	13260	98830	K8EHMCR900	1	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES AIR BAG LIGHT FLASHING ON DASH - ALSO ON NAV SCREEN 'SUPPLEMEN TAL AIR BAG'	FOUND FAULT FOR SIDE AIR BAG.FOUND OPEN CIRCUIT. DTC=B1129.R EPLACED PASS FRONT SIDE AIR BAG.
JNKAY41E43 M [REDACTED]	2003	10/25/2002	11/3/2003	NY	70017	4/3/2004	9418901	3923	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/STATES THAT THE AIR BAG LIGHT IS FLASHING.	FOUND SIDE MODULE LEFT SIDE OPEN INSTALL NEW LEFT SIDE AIR BAG MODULE CLEAR CODES
JNKAY41E53 M [REDACTED]	2003	10/1/2002	11/16/2002	CA	71238	4/1/2004	8316103	23669	98830	K8EHMCR900	1	MODULE ASSY-SIDE AIR BAG FR,RH	C/S THE AIR BAG LIGHT IS ON---SOP IN	PASSENGERS AI BAG MODULE SHORTED OUT REPLACED PASSENGERS SIDE AIR BAG MODULE & RESET

JNKAY41E83 M [REDACTED]	2003	9/14/2002	12/30/2002	GA	71304	3/26/2004	5277401	26785	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES SRS LIGHT STAYS ON-- ADVISE--	LH SIDE AIR BAG HAS FAILED REPLACED DRIVER SEAT SIDE AIR BAG
JNKAY41E83 M [REDACTED]	2003	10/17/2002	5/30/2003	NV	70215	3/22/2004	3856901	6191	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E93 M [REDACTED]	2003	9/10/2002	11/9/2002	CA	70112	3/22/2004	3836601	12802	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E43 M [REDACTED]	2003	8/9/2002	10/18/2002	CA	70492	3/19/2004	2348901	40060	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E83 M [REDACTED]	2003	10/24/2002	8/21/2003	NJ	70024	3/8/2004	2954401	8199	98830	K8EHMCR900	1	MODULE ASSY-SIDE AIR BAG FR,RH		
JNKAY41E93 M [REDACTED]	2003	12/2/2002	8/18/2003	OH	71055	2/24/2004	7641801	16065	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E33 M [REDACTED]	2003	1/6/2003	4/11/2003	NJ	70021	2/17/2004	9081401	14753	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E53 M [REDACTED]	2003	10/25/2002	12/8/2003	CA	71107	2/10/2004	6611301	5965	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		

JNKAY41E93 M [REDACTED]	2003	11/25/2002	2/20/2003	NJ	70024	1/29/2004	2744702	17610	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41EX3 M [REDACTED]	2003	9/10/2002	7/31/2003	AL	71239	1/28/2004	3964701	8597	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E53 M [REDACTED]	2003	10/25/2002		GA	70498	1/28/2004	0997801	12014	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41EX3 M [REDACTED]	2003	12/4/2002	2/7/2003	FL	70052	1/20/2004	2576301	12381	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41EX3 M [REDACTED]	2003	8/8/2002	8/20/2003	PA	72029	1/13/2004	8717001	7545	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E23 M [REDACTED]	2003	12/20/2002	6/16/2003	FL	71050	1/13/2004	0184901	4795	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E13 M [REDACTED]	2003	12/6/2002	7/22/2003	IL	70062	1/9/2004	3102101	12512	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E43 M [REDACTED]	2003	11/14/2002	2/27/2003	CT	70006	1/5/2004	7990501	15000	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		
JNKAY41E73 M [REDACTED]	2003	7/25/2002	10/18/2002	LA	71229	1/5/2004	7586001	17724	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH		

JNKAY41EX3 M [REDACTED]	2003	8/27/2002	12/14/2002	IL	70062	12/23/2003	3042101	16439	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C STATES AIRBAG WARNING LIGHT IS ON. PART IN.	AIRBAG WARNING LIGHT ON SHORT IN LEFT SIDE AIRBAG. REPLACED AIRBAG.
JNKAY41E33 M [REDACTED]	2003	10/3/2002	2/20/2003	PA	70508	12/12/2003	0143701	15068	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIR BAG LIGHT ON	USING CONSULT FOUND D/S SIDE IMPACT AIRBAG OPEN CODE. REPLACED DRIVERS FRONT SIDE IMPACT AIRBAG&CLE ARED CODES.
JNKAY41E13 M [REDACTED]	2003	12/16/2002	4/23/2003	WI	71065	12/11/2003	0760501	9489	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG WARNING ON	SIDE-MODULE OPEN-AIR BAG LT ON R&R PASS. SIDE IMPACT AIR BAG MODULE

JNKAY41E53 M [REDACTED]	2003	11/9/2002	3/14/2003	MA	70001	12/10/2003	3894701	11225	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES THE AIR BAG LIGHT IS ON	OPEN CIRCUIT IN LEFT SIDE AIR BAG MODULE REPLACE LH SIDE AIR BAG MODULE
JNKAY41E53 M [REDACTED]	2003	10/25/2002		GA	70498	11/26/2003	0889701	10376	98830	K8EHMCR900	0	MODULE ASSY-SIDE AIR BAG FR,RH	CLIENT STATES AIR BAG LIGHT ON	TESTED SYSTEM, FOUND CODE B1134 (LH SIDE MODULE OPEN) LOOKEDUND ER SEAT/ CONNECTOR WASN'T FULLY PLUGGED IN. ROAD TESTED C


JNKAY41E03 M [REDACTED]	2003	11/4/2002	2/17/2003	GA	70044	11/10/2003	8116101	10297	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES THAT THE AIRBAG LIGHT IS FLASHING. VERIFY AND ADVISE SEE HISTORY	INSTALLED LEFT SIDE AIRBAG MODULE AS PER PREVIOUS DIAGNOSIS.N OTES ON PREVIOUS RO WERE CHANGED IMPROPERLY.
JNKAY41E13 M [REDACTED]	2003	12/23/2002	10/13/2003	AZ	70482	10/29/2003	5002201	846	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES SRS INDICATOR ON	VERIFIED SRS LIGHT FLASHING, DTC B1134 IN PAST, (DRIVERS IDE BAG OPEN, INSPECTED SRS HARNES FOR DAMAGE AND NONE WAS LOC

JNKAY41E73 M [REDACTED]	2003	8/9/2002	1/24/2003	NJ	70025	10/24/2003	9217101	8908	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIRBAG LIGHT IS ON, INSTALL SOP	CODE B1134 (L/H SIDE AIRBAG MODULE), PULLED CODE PREVIOUS SVC REPLACED LEFT HAND SIDE AIR BAG
JNKAY41E23 M [REDACTED]	2003	10/30/2002	4/4/2003	IL	71119	10/20/2003	7237301	9100	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIRBAG LIGHT IS ON--- SOP PARTS	SIDE AIR BAG MODULE (LH) OPEN REPLACED SIDE AIR BAG MODULE
JNKAY41E33 M [REDACTED]	2003	10/18/2002		GA	70498	10/3/2003	0788501	780	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIR BAG LIGHT ON	SIDE MODULE LH iOPEN- ^J IS STORED IN CONTROL UNIT REPLACED SIDE MODULE LH

JNKAY41E33 M [REDACTED]	2003	10/3/2002	2/20/2003	PA	70508	9/30/2003	50101	12990	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	CLIENT STATES AIR BAG LIGHT IS ON CHECK AND REPORT	CK CONSULT CODES B1134 SIDE MODULE LH OPEN RWEPLACED DEFECTIVE LS AIRBAG AND CONTROL UNIT
JNKAY41E13 M [REDACTED]	2003	8/23/2002	11/17/2002	OK	70075	9/22/2003	7565001	9295	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT ON CK AND ADVISE	FAULTY AIR BAG MODULE REPLACE AIR BAG MODULE
JNKAY41E13 M [REDACTED]	2003	8/23/2002	11/17/2002	OK	70075	9/4/2003	7523401	8921	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT IS FLASHING CK AND ADVISE	LEFT SIDE AIR BAG FAULTY DIAGNOSE AND REPLACE LEFT SIDE AIR BAG
JNKAY41E13 M [REDACTED]	2003	10/21/2002	12/26/2002	FL	73033	9/4/2003	3245902	16320	98830	K8EHACR900		1	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT ON PLEASE FIX	HAD CODE FOR LF SIDE AIRBAG MODULE REPLACED LF SIDE AIRBAG MODULE.

JNKAY41E23 M [REDACTED]	2003	8/8/2002	10/30/2002	MA	70001	9/4/2003	3477001	18373	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES THAT AIR BAG LIGHT IS ON PART IS IN	TESTED AND FOUND CODE FOR FAULTY LEFT SIDE AIR BAG MODULE REPLACED AIR BAG MODULE AND TESTED OK.
JNKAY41E03 M [REDACTED]	2003	7/26/2002	11/16/2002	NY	70221	7/2/2003	7363701	8611	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT IS ON SOP	DRIVER SIDE MODULE FAILING REPLACE MODULE AIR BAG IN SEAT
JNKAY41E73 M [REDACTED]	2003	7/25/2002	10/18/2002	FL	73051	7/2/2003	0912505	11739	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG MODULE INOPERATIVE	THE AIR BAG MODULE LIGHT WAS ON, RUN THE DTC RESULT CODE WAS B1134 SIDE MODULE LH OPEN, REPLACE THE RIGHT FRONT AIR BAG

JNKAY41E23 M [REDACTED]	2003	7/27/2002	11/27/2002	OK	70075	5/20/2003	7255302	32007	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT FLASHING CK AND ADVISE	LEFT SIDE AIR BAG MODULE FAULTY DIAGNOSE AND REPLACE AIR BAG MODULE
JNKAY41E03 M [REDACTED]	2003	8/27/2002	3/29/2003	FL	71047	4/5/2003	2033701	2650	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIRBAG LIGHT IS ON & BLINKING	RAN CONSULT, SHOWS OPEN IN LEFT SIDE AIRBAG MODULE ASSEMBLY REPLACED LEFT SIDE AIRBAG MODULE ASSEMBLY
JNKAY41E73 M [REDACTED]	2003	7/25/2002	10/18/2002	FL	72051	4/3/2003	0602001	9008	98830	K8EHACR900	1	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIRBAG WARNING LIGHT IN INSTUMENT CLUSTER ON ALSO WARNING ON DISPLAY SCREEN	AIR BAG LIGHT IS ON DUE TO CODE B1134. REPLACED L. SIDE SEATAIR BAG AND CLEARED CODE. SEE PRINT OUT



* NLCR9027305174 *



* NLAR1032075011 *


VIN	MODEL-YEAR	COD E-NML-PROD	DATE-MFG	DATE-IN-SVC	ST-DEALER	CODE-DLR	DATE-RO	NUM-RO	MILEAGE	CODE-PNC	NUM-PART1	QTY-PART1	DESC-PART1	COMM-CUST	COMM-TECH
JNKBF01A73M [REDACTED]	2003.0	F50	08/27/2002	10/27/2003	FL	71050	03/16/2005	1605301	43621	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES SRS AIRBAG LIGHT FLASHING, SPECIAL ORDER PART	DIAGNOSTIC INSPECTION FINDS DTC B1129 RH SIDE OPEN CIRCUIT REPLACED RH SIDE AIRBAG MODULE, RETESTED, OK
JNKBF01A73M [REDACTED]	2003.0	F50	02/22/2003	12/26/2003	CA	70090	03/07/2005	9177701	26058	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	INSTALL SOP AIR BAG MODULE. PART NOW IN STOCK.	L/H AIR BAG MODULE CODE PRESENT REPLACED L/H SIDE MODULE, CLEARED CODE
JNKBF01A63M [REDACTED]	2003.0	F50	10/24/2002	06/08/2003	CA	70101	03/04/2005	0524802	27081	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CHECK AIR BAG LIGHT IS ON	MODUAL FAILURE REPLACED RIGHT SIDE AIR BAG MODUAL
JNKBF01A43M [REDACTED]	2003.0	F50	08/24/2002	07/16/2003	CA	71105	02/25/2005	0458001	32439	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	AIR BAG LIGHT FLASHING ON, ON DASH, REPORT NEEDS	RIGHT FRONT SIDE AIR BAG INTERNAL FAILURE REPLACED FAILED RIGHT FRONT SIDE AIR BAG MODULE
JNKBF01AX3M [REDACTED]	2003.0	F50	12/12/2002	06/10/2004	CA	72319	02/12/2005	3755301	33638	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	C/S: AIRBAG LIGHT IS ON	CODE P1129 SIDE MODULE RH INTERNAL FAILURE RPL AIR BAG MOLDUE
JNKBF01A93M [REDACTED]	2003.0	F50	11/16/2002	06/17/2003	CA	70101	02/09/2005	0388701	41644	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMER STATES THE AIR BAG IS FLASHING	REPLACED R AIR BAG MODULE PO#89760
JNKBF01A63M [REDACTED]	2003.0	F50	06/23/2003	10/09/2003	NY	71014	01/25/2005	0264201	37510	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS ON SEE SOP	FOUND CODE FOR L/S SEAT AIR BAG MODULE REPLACED L/S MODULE AND CLEARED CODES
JNKBF01AX3M [REDACTED]	2003.0	F50	06/05/2003	02/28/2004	VA	71035	01/19/2005	5145601	20111	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT WAS ON (SPECIAL ORDERED PART)	LEFT FRONT (DRIVER) SIDE AIR BAG MALFUNCATION REPLACED SIDE AIR BAG MODULE & REPROGRAMMED ECU
JNKBF01A33M [REDACTED]	2003.0	F50	05/23/2003	10/03/2003	GA	70493	01/17/2005	3164001	17526	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT IS ON, INSPECT SEE HISTORY	LF SIDE AIRBAG MODULE INTERNAL MALFUNCTION;REPLACED AIRBAG RESET AIRBAG MODULE.
JNKBF01A73M [REDACTED]	2003.0	F50	02/26/2003	07/11/2003	FL	73051	01/17/2005	2829701	23499	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES SRS LIGHT IS ON	AIR BAG LIGHT IS ON DUE TO CODE B1134. REPLACED L. SIDE AIR BAG MODULE AND CLEARED CODE. RETESTED O.K SEE PRINT OUT
JNKBF01A23M [REDACTED]	2003.0	F50	10/09/2002	09/11/2003	LA	71264	01/10/2005	1659701	53869	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	AIR BAG LIGHT ON, S/O PART IN.	OPEN CIRCUIT LEFT SEAT SIDE MODULE. REMOVED LEFT SEAT AND REPLACED SIDE AIR BAG MODULE AND HARNESS.


JNKBF01A23M [REDACTED]	2003.0	F50	02/21/2003	07/17/2003	NJ	70211	01/04/2005	0404403	26899	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	INSTALL AIR BAG- SOP	INSTALLED SOP AIR BAG MOD
JNKBF01A33M [REDACTED]	2003.0	F50	10/10/2002	01/29/2004	NY	70016	01/04/2005	1212501	17365	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	C/S AIRBAG LIGHT IS ON	RT SEAT BAG OPEN R/R R SEAT AIR BAG
JNKBF01A63M [REDACTED]	2003.0	F50	11/15/2002	09/10/2003	CT	72007	01/03/2005	8626301	26575	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	C/S AIR BAG LIGHT IS FLASHING	R0 SIDE MODULE OPEN B1129 REPLACED RH SIDE MODULE AIR BAG RESET CONSULT OK
JNKBF01A73M [REDACTED]	2003.0	F50	11/18/2002	02/09/2003	CA	70492	12/22/2004	3432901	24544	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMER STATES THAT THE AIR BAG LIGHT IS ON,INSTALL S-O PARTS	REPLACED RIGHT FRONT AIR BAG
JNKBF01A93M [REDACTED]	2003.0	F50	10/31/2002	12/22/2003	CA	70499	12/16/2004	1500201	24934	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	OWNER REPORTS AIR BAG LIGHT STARTED FLASHING. CHECK AND ADVISE.	DTC B1129 / INTERNAL MALFUNCTION RIGHT SEAT AIR BAG REPLACE RIGHT SIDE AIR BAG MODULE
JNKBF01A23M [REDACTED]	2003.0	F50	08/24/2002	01/18/2004	CA	70112	12/07/2004	4832501	11112	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMER STATES AIRBAG LIGHT IS FLASHING WHEN DRIVING	TECHNICIAN FOUND PASSENGER SIDE AIRBAG TO BE FAULTY REPLACED PASSENGER SIDE AIRBAG (SUBLET)
JNKBF01A73M [REDACTED]	2003.0	F50	06/24/2003	05/31/2004	NJ	71023	12/03/2004	7280601	9462	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S AUR BAG LITE ON S.O.P	CODE: SIDE MODULE (LH) OPEN iB1134 J . LH MODULE INTERNAL FAILURE. REPLACED FT L/H MODULE AND ERASED CODE
JNKBF01A53M [REDACTED]	2003.0	F50	08/07/2002	12/04/2002	CA	70492	11/20/2004	3299101	43039	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CIENT REPORTS AIR BAG LIGHT IS ON....SOP	LEFT HAND AIR BAG MODULE INTERNAL FAILURE REPLACED LEFT HAND AIR BAG MODULE
JNKBF01A63M [REDACTED]	2003.0	F50	11/20/2002	01/22/2003	OH	70216	11/15/2004	4975901	18240	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES AIR LITE IS FLASHING (SOP)	RAN CONSULT RECEIVED B1129 RH SIDE MODULE OPEN REPLACED RT SIDE AIR BAG MODULE
JNKBF01A93M [REDACTED]	2003.0	F50	12/07/2002	01/18/2003	CA	71115	11/09/2004	3731302	32431	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST REP AIR BAG LIGHT IS ON, PLEASE CHECK AND ADVISE.	DTC B1129 AIR BAG SIDE MODULE R/H (OPEN) REPL R/H AIR BAG SIDE MODULE
JNKBF01A73M [REDACTED]	2003.0	F50	06/19/2003	01/23/2004	NJ	70024	11/08/2004	4354901	21689	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIRBAG LIGHT ON	FOUND CONSULT CODE B1134 LH SIDE MODULE OPEN REPLACED L/S FRONT AIRBAG MODULE CLEARED CODE
JNKBF01A23M [REDACTED]	2003.0	F50	04/04/2003	06/30/2003	NY	70012	11/06/2004	7378401	4304	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES: CHECK AIR BAG SYSTEM - LIGHT ON DASH NOTE: PART ORDERED/IN	TESTED WITH CONSULT - CODE REPLACED L/F SIDE AIR BAG MODULE
JNKBF01A73M [REDACTED]	2003.0	F50	10/15/2002	12/07/2002	FL	70049	11/02/2004	8867101	38698	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMER STATES AIR BAG WARNING LIGHT IS ON. PART IS IN TECH17	FOUND CODE B1129 SIDE MODULE OPEN,INTERNAL FAILURE IN RH SIDE MODULE,REPLACED,RESET LIGHT RETEST OK


JNKBF01A23M [REDACTED]	2003.0	F50	11/11/2002	01/24/2003	FL	70052	10/14/2004	3362602	25859	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES AIR BAG LIGHT ON	DTC B1129 SIDE MODULE OPEN CIRCUIT. REPLACE RIGHT FRONT SEAT AIR BAG ASSEMBLY.
JNKBF01A63M [REDACTED]	2003.0	F50	02/19/2003	06/30/2003	NJ	70025	10/07/2004	0278801	16637	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIRBAG LIGHT IS ON, INSTALL SOP	INSTALLED DRIVER'S SIDE AIRBAG MODULE, TESTED SYSTEM, ALL OK
JNKBF01AX3M [REDACTED]	2003.0	F50	02/19/2003	02/24/2004	CA	70101	10/04/2004	9598301	11860	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S THE AIR BAG LIGHT IS FLASHING SOP IN PARTS	REPLACED DRIVERS SIDE SEAT AIRBAG PO#88252
JNKBF01A63M [REDACTED]	2003.0	F50	06/16/2003	08/29/2003	NJ	70025	10/04/2004	0266101	8152	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S THAT THE AIRBAG LIGHT IS ON, INSTALL SOP	REPLACED SOP L/F SEAT SIDE MODULE.
JNKBF01A03M [REDACTED]	2003.0	F50	11/01/2002	11/19/2003	GA	70044	09/27/2004	9522301	23916	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	C/S THE SRS/AIR BAG LIGHT IS ON/FLASHING-INSTALL SOP	CONSULT CODE FOR RIGHT AIRBAG SIDE MODULE. REPLACED FOR OPENCIRCUIT TO CORRECT.
JNKBF01A23M [REDACTED]	2003.0	F50	01/15/2003	06/16/2003	NY	71014	09/15/2004	9901301	24733	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS A FLASHING ATT L/S SEAT	FOUND CODE SIDE MODULE AIR BAG MODULE OPEN INSTALED L/H AIR BAG MODULE . NO MORE AIR BAG LIGHT . NO COD
JNKBF01A33M [REDACTED]	2003.0	F50	02/21/2003	11/09/2003	GA	70045	08/25/2004	5683302	19491	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT FLASHING, PART HERE	B1134 L.F. SEAT SIDE A/B MODULE OPEN CIRCUIT/REPLACED L.F. SEAT A/B MODULE TO RESOLVE INCIDENT/SORRY FOR ANY INCONVIENCE
JNKBF01A33M [REDACTED]	2003.0	F50	08/30/2002	01/23/2003	NY	70012	08/18/2004	7146801	24835	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMER STATES: CHECK AIR BAG LIGHT ON DASH	FOUND SIDE MODULE RH OPEN 2ND INCIDENT.FOUND AIR BAG SIDE MODULE INTERNAL FAILURE.REPLACED RH SIDE MODULE TO REPAIR.
JNKBF01A23M [REDACTED]	2003.0	F50	02/20/2003	06/25/2003	TN	70234	08/12/2004	6876201	19930	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES AIR BAG LIGHT IS ON/LH MODULE PART HERE 8/9/04	INSTALLED PREVIOUSLY ORDERED SOP PART. ALL OK AT THIS TIME.
JNKBF01A53M [REDACTED]	2003.0	F50	04/04/2003	01/28/2004	NC	71042	08/11/2004	4888501	10407	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUST STATES THAT THE AIR BAG LIGHT IS ON	CONSULT CODE B1134-LH SIDE MODULE OPEN-DIAGNOSED AND REPLACED DRIVERS SIDE MODULE/HARNESS ASSY-INTERNAL WIRING
JNKBF01A33M [REDACTED]	2003.0	F50	10/26/2002	03/22/2003	FL	73051	07/27/2004	2199202	19521	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES SRS LIGHT IS ON	AIR BAG LIGHT IS ON DU ETO CODE B1129. REPLACED R. SIDE SEATAIR BAG. CLEARED CODE AND RETESTED. SEE PRINT OUT


JNKBF01A43M [REDACTED]	2003.0	F50	06/23/2003	10/31/2003	NY	71015	07/22/2004	2036101	9529	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT FLASHES. PART SPECIAL ORDERED IN STOCK.	INTERNAL FAILURE OF THE LEFT SIDE AIR BAG MODULE. PREVIOUSLYDIAGNOSED ON INVOICE 18938. REPLACED MODULE TO RECTIFY.
JNKBF01A03M [REDACTED]	2003.0	F50	10/11/2002	02/26/2003	FL	71050	07/15/2004	0797701	25171	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES AIRBAG LIGHT FLASHING	DIAGNOSTIC INSPECTION FINDS DTC B1081, REPLACED R/F SEATBELTPRETENSIONER, AND R/F AIRBAG IN SEAT
JNKBF01A23M [REDACTED]	2003.0	F50	11/14/2002	01/23/2003	CT	70006	07/14/2004	8557602	30018	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	C/S SIR LIGHT IS ON	SOP PASS AIR BAG FOUND OPEN CIRCUIT IN PASS SIDE AIR BAG AT CONNECTOR UNDER SEAT PINS WERE LOOSE CODE B1129.COMPLETED
JNKBF01A33M [REDACTED]	2003.0	F50	02/14/2003	01/16/2004	NV	70215	07/09/2004	4308901	4132	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUSTOMER STATES AIR BAG LIGHT IS ON.SOP IN	CODE FOR LEFT SIDE MODULE GRND-SHRT STORED {B1136} REPLACED SIDE MODULE ASSY
JNKBF01A33M [REDACTED]	2003.0	F50	06/27/2003	11/23/2003	GA	70044	06/15/2004	9053201	7230	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S THE AIRBAG LIGHT IS FLASHING	B1134. LH SIDE AIR BAG MODULE(OPEN) REPLACED LH SIDE AIR BAG MODULE
JNKBF01A83M [REDACTED]	2003.0	F50	11/27/2002	02/27/2003	NY	70221	05/27/2004	8217801	22339	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUSTOMERSTATES AIRBAG LIGHT IS ON PARTSARE IN STOCK	CODE FOR R/S SIDE AIR BAG REMOVE SEAT AND DISASSEMBLE AND REPLACE AIR BAG
JNKBF01A53M [REDACTED]	2003.0	F50	06/24/2003	09/30/2003	MO	71067	05/17/2004	9644101	9421	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	CUST. STATES, AIR BAG LIGHT IS ON.	INT. FAILURE CHECKED WITH CONSULT. REPLACED LEFT AIR BAG MODULE.
JNKBF01A03M [REDACTED]	2003.0	F50	10/19/2002	01/09/2003	CA	72321	04/29/2004	3071502	25525	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CLIENT SAYS THAT AIR BAG WARNING LIGHT IS ON, PLS CK.	R/F SIDE AIR BAG MODULE HAS OPEN CIRCUIT REPLACED RF SIDE AIR BAG MODULE, RESET AIR BAG LIGHT
JNKBF01A73M [REDACTED]	2003.0	F50	10/22/2002	01/30/2003	NY	70017	04/08/2004	9436001	14065	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	C/STATES THAT THE AIR BAG LIGHT KEEPS FLASHING.	FOUND RIGHT SIDE AIR BAG MODULE OPEN INSTALL NEW RIGHT SIDE AIR BAG MODULE
JNKBF01A33M [REDACTED]	2003.0	F50	02/27/2003	08/04/2003	CT	70006	03/10/2004	8184601	8760	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	C/S AIR BAG LIGHT, CODE B1134 IN SYSTEM AND SIDE MODULE ORDERED LAST VISIT	CODE B1134 CHECKED WIRING AND CONNECTRORS--OK MODULE OPEN REPLACED LEFT HAND SIDE AIR BAG MODULE
JNKBF01A73M [REDACTED]	2003.0	F50	09/05/2002	03/27/2003	PA	72029	03/08/2004	8857401	10692	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CLIENT STATES VEHICLE TOWED IN AIR BAG LIGHT ON	R/S AIR BAG MODULE OPEN REPLACE RF/S AIR BAG MODULE CLEAR CODES
JNKBF01A83M [REDACTED]	2003.0	F50	11/16/2002	03/22/2003	CA	71107	02/05/2004	6597201	7511	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	RECHECK AIR BAG LIGHT ON AFTER REPAIR	CODE P1129 SIDE MODULE RH CHECK HARNESS,REPLACE RIGHT SIDE MODULE,CLEAR CODE

JNKBF01A13M	2003.0	F50	07/01/2003	12/31/2003	TX	71077	01/16/2004	1452101	611	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	AIRBAG LIGHT IS ON	TEST & SELF DIAG RESULTS REVEAL OPEN CIRCUIT IN LEFT SIDE MODULE. REPLACED MODULE TO RESOLVE.
JNKBF01A63M	2003.0	F50	11/15/2002	01/30/2003	NJ	71213	01/05/2004	6221101	19200	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES AIR BAG LIGHT IS ON	FAULT CODE RH SIDE AIR BAG MODULE OPEN REPLACED SIDE AIR BAG MODULE
JNKBF01A83M	2003.0	F50	02/24/2003		AL	70073	10/07/2003	5149001	3855	98830	K8EHAAR100	1.00	MODULE ASSY-SIDE AIR BAG FR LH	AIR BAG LIGHT IS ON	CONSULT TESTED, LEFT SIDE AIR BAG MODULE HAS OPEN CIRCUIT TOTAL (0.9) RQ36AA/0.7/HC/62/RQ666A/0.2 CONSULT TESTED AND
JNKBF01A33M	2003.0	F50	10/17/2002		MI	70206	06/05/2003	1760001	279	98830	K8EHMAR100	1.00	MODULE ASSY-SIDE AIR BAG FR,RH	CUST STATES AIR BAG LIGHT ON 318077	B1129. SIDE MOD RH OPEN REPLACE AIR BAG









³ For M45, the prediction is at SINCAP impact speed of 38.5 mph. The injury values would be expected to be even lower at the FMVSS No. 214 test speed of 33.5 mph.

