



American Honda Motor Co., Inc.
1919 Torrance Boulevard
Torrance, CA 90501-2746
Phone (310) 783-2000

August 5, 2008

NVS-212mjl
PE08-026

Mr. Thomas Z. Cooper, Chief
Vehicle Integrity Division
Office of Defects Investigation
U.S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, DC 20590

Dear Mr. Cooper:

Please find enclosed the exemplar samples as requested in question 25.

25. Produce two of each of the following:

- a. Exemplar samples of each design version of the subject components;
- b. Field-returned samples of the subject components exhibiting the subject failure mode;
- c. Any kits and software changes (including patches, modifications, and reflashes) that have been released, or developed, by Honda for use in service repairs to the subject component/assembly which relate, or may relate, to the alleged defect in the subject vehicles; and
- d. The owner's manuals for MY 2005 through 2007 Honda Odyssey vehicles.

Response:

| a. Exemplar Samples | | |
|---------------------|-------------|------------------|
| | Drawing no. | Manufacture Date |
| 1. | A611 | 8/04, 10/04 |
| 2. | A612-C1 | 2/06 |
| 3. | A612 | 9/06, 6/07 |
| 4. | A710 | 3/08 |

| b. Field-returned Samples | | |
|---------------------------|-------------|------------------|
| | Drawing no. | Manufacture Date |
| 1. | A611 | 8/04 |
| 2. | A612-C1 | 1/06 |
| 3. | A612-C1 | 2/06 |
| 4. | A612 | 9/06 |

- c. Honda has not released or developed any kits or software changes.

Sincerely,

AMERICAN HONDA MOTOR CO., INC.

William R. Willen
Managing Counsel
Product Regulatory Office

WRW:nis

Enclosures